

**A site investigation  
into building airtightness  
from external wall insulation**

3 house types from  
the Clients stock

for:  
The client

December 2015 v3  
Year/Job Number: 2014 118  
Written: KP  
Checked: MR

3 Admirals Hard, Plymouth, PL1 3RJ, U.K.  
Tel +44 (0)1752 542 546 Email [info@peterwarm.co.uk](mailto:info@peterwarm.co.uk)  
WARM COMPANY (SW) LIMITED Reg 7676841  
Directors: Sally Godber, Sue Johns, Mike Roe, Peter Warm.  
Member, Association for Environment Conscious Building  
Passivhaus Trainers and Certifiers

**Disclaimer:**

This document has been prepared by WARM for sole use of the client detailed above in accordance with generally accepted consultancy principles, the budget for fees and the terms of reference agreed between WARM and the client.

Any information provided by third parties and referred to herein has not been checked or verified by WARM, unless otherwise expressly stated in the Report. WARM accepts no responsibility for misinformation or inaccurate information supplied by any third party as part of this assessment.

No third party may rely upon this document (in whole or in part) without the prior and express written agreement of WARM.

WARM has set out where we have made assumptions, if the reader disagrees with any statement, or finds any other information contained within this report to be inaccurate, WARM request that the writer is informed immediately.

## Introduction

This report has been commissioned by The Client, in order to assess the airtightness of 3 existing house construction types both before and after external insulation works are carried out, comprising 3 non-traditional building systems. The three dwellings chosen for testing were:

- House A - BISF
- House B - Laing Easiform
- House C - NoFines

All three dwellings are currently occupied, and have been fitted with uPVC double glazing.

The initial report has been updated to include the results after the insulation was installed. The results of the three tests are listed below, with an illustrated commentary on each house type discussing the main issues. An appendix contains detailed information about each test and documents the individual leakage points.

Air tightness testing was carried out using a fan mounted in a frame in the building entrance door. Air flow rates and pressures are then measured to determine the air change rate in the building at a standard internal pressure of 50 Pa. Tests were carried out in accordance with the general principles of Passivhaus technical standards.



Door fan installation at House A

## Results

The following results show the air change rate (ACH) within the buildings as tested. For compassion building regulations require a *maximum* ACH of approximately 10.0 ACH, with most designs achieving around 6 ACH. Passivhaus standards require a maximum of 0.6 ACH, an order of magnitude lower.

Results pre and post External Wall Insulation (EWI):

| House                | Pre EWI  | Post EWI | Change |
|----------------------|----------|----------|--------|
| House A              | 16.8 ACH | 14.0 ACH | -10%   |
| House B              | 7.7 ACH  | 11.1 ACH | +45%   |
| House C <sup>1</sup> | 26.9 ACH | 22.7 ACH | -15%   |

Note 1: Depressurisation only as too leaky for Pressurisation test to pressurise.

## Conclusions

- Clearly the EWI has had only a random effect on the airtightness of the buildings
- The results are all discouraging (apart from the significant appearance improvement)
  - The air changes rates are all massive. Unsurprising therefore that most occupants had sealed up their extract fans in Kitchen and Bathroom – extract fans are really unnecessary as these leakage rates.
  - What is further worrying is that the EWI installation has in fact made airtightness routes inaccessible. How will draught-proofing work be carried out now?
  - The extensive air leakage will of course negate most of the savings from the insulation, as it has been effectively bypassed by the large air leakage

## Recommendations


The work leads to a situation where money has been spent on insulation in a way that hampers any further improvement work.

It is recommended that :

- the roll out of EWI across the stock is reviewed and at least some form of air testing/draught proofing work initiated before a building is classed as suitable for EWI.
- a review is made of the standards being used for retrofit: 2.5” of insulation is really wasting the cost of the external render.

## Commentary


### House A



The airtight barrier in this house is currently provided by the plasterboard face to the walls and ceilings.

Air leakage is apparent at the window reveals; at the wall to ground junction; internal wall vents in bedrooms; the stair to wall junction and the wall to roof junction. Including the 'Outhouse' area in the airtightness and insulation strategy is essential, given that the residents use this space as part of their home. The before and after test results show a marginal reduction in air leakage.

## House B



Cast concrete cavity construction is by its nature likely to be the most airtight of the 3 types tested. The most significant leaks were through services penetrations and probably the intermediate floor, likely to be caused at the point where floor joists are cast into the inner leaf of the concrete. However, given that the outhouse area forms a regularly used part of the house, airtightness in this should be addressed of the dwelling. (see photographs in Appendix for further details).


The before and after test results indicate that the air leakage has actually increased since the initial test. It is not clear why this has occurred.



### House C



While we could undertake depressurisation tests, it was not possible to pressurise the house to 50Pa with our fan. We abandoned the test at this point as one of the residents was unwell with chest problems, and even with heating on the fan test was cooling the house to an uncomfortable level. While earlier No-fines houses were wet plastered internally, these later ones have an internal lining which appears to be consist of plasterboard on battens. Therefore there is essentially a cavity behind the concrete. Significant leakage through the intermediate floor shows that this cavity is not well sealed from the outside. Without further examination it is not possible to say definitively where these leaks originate from.



Given the airflow felt through a socket on an internal wall it is possible that the wall to roof junctions play an important role. The very high air leakage in this house would certainly limit the effectiveness of any external insulation unless the detailing of the insulation is carefully considered at the window reveals, at the wall to ground junction and the wall to roof junction. However BRE guidance (Williams 1991) suggests that there is an intentional drainage slot at the base of the No-fines wall which needs to be maintained, so the strategy does need some thought.

The before and after test results show a marginal reduction in air leakage.

3 house types from  
the Clients stock

## Sources of illustrations

Building Research Station (1986) The British Iron & Steel Federation steel framed house Building Research Establishment

Currie RJ (1988) The Structural Condition of Wimpey No-fines low rise dwellings Building Research Establishment

Reeves BR & Martin GR (1989) The Structural Condition of Wimpey No-fines low rise dwellings Building Research Establishment

Williams AW (1991) The Renovation of no-fines housing BRE Press

## Appendix

### Notes: House A

BISF steel frame house, replacement windows, and original render/cladding. 'Outhouse' used as part of dwelling. No complaints of mould growth, occasional condensation in kitchen, but only when cooking very large meals. Occupiers like fresh air so door often open. Most trickle vents open on arrival.

Currently the only airtightness line in the walls and roof seems to be the plasterboard. Services etc go through it. If the top and base of walls remain unsealed after insulation the entire house will still leak.


### Ground floor

|                                                                                                                                                           |                                                                                       |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| <b>Sockets/switches</b><br>Leakage was noted from all the sockets and switches in the house                                                               |    |
| <b>Plumbing behind kitchen sink</b><br>A draught could be felt coming from the kitchen sink cupboard. This is likely to be from the plumbing penetrations |  |
| <b>Gas pipe vent in kitchen</b><br>This gas pipe venting was installed during the refit of the kitchen                                                    |   |
| <b>Window reveal in lounge</b><br>Air appeared to be coming in through the                                                                                |                                                                                       |



|                                                                                                                                                                                      |                                                                                     |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| <p>damaged reveal, which may be due to corrosion in the steelwork.</p>                                                                                                               |   |
| <p><b>Switches and trunking by front door</b><br/>Despite being surface mounted, air could be felt both from in and around the switches and the trunking</p>                         |   |
| <p><b>Disused gas pipework</b><br/>The disconnected pipe appears to run to the outside of the building, where it must also be disconnected, and does not appear to be capped off</p> |  |
| <p><b>Within electricity cupboard</b><br/>There was significant airflow within the cupboard. This appears to be related to the electric cable entry</p>                              |                                                                                     |

|                                                                                                                                                                                       |                                                                                      |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| <p><b>Behind stairs</b></p> <p>The plasterboard appears to stop somewhere behind the steel stair construction, allowing significant airflow at this point. Access very difficult.</p> |    |
| <p><b>Outhouse</b></p>                                                                                                                                                                |                                                                                      |
| <p><b>Wall vents</b></p> <p>2 vents within the main wall of the house which are open to the outhouse area but do not appear to connect to the interior</p>                            |   |
| <p><b>Doorframe</b></p> <p>Around the top of the steel doorframe within the outhouse area</p>                                                                                         |  |
| <p><b>First Floor</b></p>                                                                                                                                                             |                                                                                      |
| <p><b>Bath panel/plumbing</b></p> <p>Leakage was noted at the plumbing penetrations and from behind the bath panel</p>                                                                |  |

|                                                                                                                                                                                                    |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| <p><b>Plasterboard damage</b><br/>A gap in the plasterboard leaked significantly</p>                                                                                                               |   |
| <p><b>Intermediate floor</b><br/>Lightweight carpet upstairs lifted during the depressurisation test, showing a significant leakage path through the wall construction into the floor cassette</p> |  |
| <p><b>Wall Vents</b><br/>Uncontrolled vents in bedrooms into the wall cavity. There is significant air flow through these. They were temporarily sealed during the tests.</p>                      |  |

**Notes: House B**

Laing Easiform house, with uPVC replacement windows and doors. 'Outhouse' used as part of dwelling. Bathroom extract fan and front bedroom ventilator both taped over by tenant to avoid draughts.

A significant part of the leakage through the outhouse. Note that previously completed insulation works locally do not appear to have addressed this area.


**Ground Floor**

|                                                                                                                                                              |                                                                                       |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| <p><b>Phone point</b><br/>The telephone sockets were leaky, suggesting poor sealing of the telephone cable entry</p>                                         |    |
| <p><b>Cable</b><br/>This cable was very poorly sealed. Control over 3<sup>rd</sup> party works is important in avoiding unwanted leakage</p>                 |    |
| <p><b>By boiler</b><br/>This is likely to be from the gas pipe penetration or from another services penetration hidden behind the built-in kitchen units</p> |  |

### Outhouse

#### Roof to wall junction

This junction is not sealed, with gaps between the corrugated asbestos roofing and the rendered blockwork wall



#### External view of the same area



#### An insulated house nearby


The asbestos roofing has been left in situ, and there is a cold bridge where the roofing meets the main house wall. The corrugated roofing junction with the outhouse wall does not appear to have been made airtight, and the insulation stops short of the roof both at the top (main house) and bottom (outhouse)



### First Floor

#### Intermediate floor

Where floor coverings were absent a small amount of leakage could be felt through the gaps between floorboards





|                                                                                                                                                                                                                                                      |                                                                                      |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| <p><b>Switch (on internal wall) and ceiling roses</b><br/>The switch was leaky, suggesting that the internal stud wall is open to the loft space<br/>Additionally, leakage was noted at ceiling roses, which is to be expected</p>                   |   |
| <p><b>Lintel</b><br/>A leak was noted where the lintel surface decoration was damaged, which may suggest that the lintel itself is damaged somehow, or that the internal plaster has come loose and the hole behind communicates with the cavity</p> |    |
| <p><b>Built in cupboard</b><br/>The corner of this built in cupboard in the front bedroom was leaky</p>                                                                                                                                              |  |
| <p><b>Windows</b><br/>Some of the windows had slight leaks where either the opening sashes did not seal fully or glazing unit beading was not sealing fully</p>                                                                                      |  |



**Notes: House C**

No-fines rendered concrete house, with plasterboard walls internally (presumably with studwork and a void behind), no later than 1970s (dated from Digimap). Occupants note that house is very leaky, including the kitchen, front door and some windows, and that it never feels warm. No access to two cupboards off hall, so unsure if leaks in there.

Unable to pressurise successfully with our fan kit, indicating a very high high leakage rate.

**Ground floor**


|                                                                                                                                                                                                                                                                       |                                                                                      |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| <b>Front door</b><br>Not tested by us (as the back door was too small for our fan) but with this door closed and at atmospheric pressure significant leakage could be felt on the lock side of the door.                                                              |   |
| <b>Behind built in kitchen units</b><br>Significant airflow could be felt through all the kitchen cupboards and drawers both on the external and party wall, as well as from around the washing machine. Air could also be felt behind the cooker (on the party wall) |  |
| <b>Kitchen Sockets</b><br>All sockets were leaky, including one on an internal wall                                                                                                                                                                                   |  |

|                                                                                                                                                                                            |                                                                                     |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| <p><b>Under vivarium in dining room</b><br/>Air could be felt coming from under the vivarium. This may have been from a socket on the external wall or from the wall to floor junction</p> |   |
| <p><b>Internal to external wall junction</b><br/>The junction of the internal wall and external wall was leaky</p>                                                                         |   |
| <p><b>Window in dining room</b><br/>This was quite leaky. Other ground floor windows appeared to be ok</p>                                                                                 |  |

## First Floor

|                                                                                                                                          |                                                                                      |
|------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| <p><b>Sockets</b><br/>First floor sockets were leaky, indicating that the void behind the dry lining is providing a path for airflow</p> |  |
|------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|

|                                                                                                                                                                                           |                                                                                      |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| <p><b>Windows</b></p> <p>Some windows were leaky, particularly the one in the wet room. This room was reported to be particularly draughty by the tenants</p>                             |    |
| <p><b>Loft hatch frame</b></p> <p>The loft hatch was well sealed, but where the frame meets the ceiling there was a leak. There were also leaks at cracks in the plasterboard ceiling</p> |    |
| <p><b>Boxing in wet room</b></p> <p>Leaks could be felt at the junction between the wall finish and wet room floor. This room was reported to be particularly draughty by the tenants</p> |   |
| <p><b>Soil pipe</b></p> <p>Air leakage was noted at the soil pipe. This runs into the adjacent room (ie the soil pipe runs parallel to the external wall)</p>                             |  |

|                                                                                                                                                                                                                             |                                                                                     |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| <p><b>Old overflow</b><br/>Although this was filled with foam externally, leakage was felt through the old disconnected toilet overflow</p>                                                                                 |   |
| <p><b>Intermediate floor</b><br/>There was a large amount of leakage through the intermediate floor cassette, felt strongly where floorboards were exposed. The lino in the WC lifted during the depressurisation test.</p> |  |

### External Photographs

|                                                                                                                                                                        |                                                                                       |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| <p><b>Ventilators in external wall</b><br/>These ventilators, the purpose of which is unclear, are likely to add significantly to the airflow through the building</p> |  |
| <p><b>Kitchen extract cowl</b><br/>There are no flaps to this cowl to reduce airflow when the fan is not running</p>                                                   |   |



3 house types from  
the Clients stock

|                                                                                                                                                                                                                                                                                             |                                                                                     |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| <p><b>Render stop line</b></p> <p>At the back of the render stop line the no-fines concrete could be felt exposed in places, providing a potential leak path due to voids within the no-fines material. However, according to the BRE there is supposed to be drainage at this location</p> |   |
| <p><b>Eaves vents</b></p> <p>Eaves ventilation appears to have been fitted. It is likely that this ventilation connects with the void behind the dry lining</p>                                                                                                                             |  |