INDEPENDENT

BATTERY CERTIFICATE



CERTIFICATE NUMBER: 71BE9EE4-4CD5-43AF-AE4E-955D0458E2A2

VEHICLE

BRAND: Tesla


MODEL: Model 3 - 82,1 kWh


MILEAGE: 77,243 km

VIN: 5YJ3E7EB2MF969422

DATE AND TIME: 30.09.2025, 15:49:27

EXECUTED BY: Carla AB





Battery Management System (BMS)

Battery Sensor

Battery Measurements - warning detected

Battery Cell Voltages

Vehicle Communication



EVALUATION

WARNING! - SIGNIFICANT ISSUES DETECTED


During the detailed battery diagnosis with the AVILOO FLASH Test, anomalies were detected that require monitoring or inspection. For Details scan the QR code.

For assistance, please contact AVILOO Customer Management.

horas Reiser

Dr. Marcus Berger, CEO





SENSORS

Voltage Sensor	✓
Current Sensor	~
Temperature Sensors	~
Cell Voltage Sensors	✓

 WLTP
 Typical
 Individual

 Current:
 513-576km
 411km
 367km

 New:
 547-614km
 438km
 391km

		Value	Status
ВМЗ	BMS State of Charge (SoC)*:	14%	
	SoC calculation accuracy:		~
	BMS State of Health (SoH)*:	87%	
	SoH calculation accuracy:		✓

AVILOO Box connected.

FLASH Test started.

Vehicle detected.

Starting data acquisition.

Finished data acquisition.

Analyzing data.

Analysis completed.

MEASUREMENTS Min Max Delta Status 16.5°C 1.0°C **Battery Temperature** 17.5°C Cell Voltage 3.440V 3.494V 54mV Pack Voltage 334.3V Average Current -2.6A

CELL VOLTAGES DIAGRAM

20 14 1 - 20 21 - 40 3.489 3.492 3.494 41 - 60 61 - 80 3 493 3.493 3.492 3.493 3.492 3.493 3.493 3.494 3.492 3.493 3.493 3.493 3.493 3.492 3.492 3.492 3.491 3.490 3.490 3.491 3.491 3.490 3.490 3,490 3,490 3.491 81 - 96

MIN 3.440 3.447 3.454 3.460 3.467 3.474 3.481 3.487 3.494 MAX

MESSAGES

71BE9EE4-4CD5-43AF-AE4E-955D0458E2A2

It has been determined that there is a significant discrepancy between the highest and lowest charged cells, as illustrated in the cell voltage table above. This can be attributed to a prolonged period where the battery was not charged to 100%, or alternatively, an issue with battery balancing. In order to troubleshoot, please ensure the vehicle is fully charged and allow it to sit undisturbed for several hours. Then, please run the FLASH Test again to assess if the deviation has reduced. If the deviation has reduced, please repeat the process. If the deviation persists, please take your vehicle to a workshop or contact AVILOO Customer Management for further assistance.

^{*}The values shown here were not calculated by AVILOO but correspond to the values read out from the battery management system (BMS) and were calculated by the manufacturer. AVILOO therefore assumes no liability for their accuracy.