

Operating Manual



RS 1111-UT RS 1114-UT

Stock number: 205-0961 Stock number: 205-0965











Table of contents

1	About this documentation	4
1.1	Purpose of the document	4
1.2	Legal notices	4
1.3	Further information	4
2	Safety	5
2.1	Explanation of safety symbols	
2.2	Foreseeable misuse	5
2.3	Safety instructions	6
2.4	Intended use	6
3	The product at a glance	7
3.1	The RS 1100 barometer series	7
3.2	Display elements	7
3.3	Operating elements	8
3.4	Connections	9
4	Operation	10
4.1	Opening the configuration menu	10
4.2	Open the adjustment menu	12
5	Measurement Basics	13
5.1	Vacuum measurements	13
5.2	Special functions	14
5.2.1	പ്പെL Tare function	14
5.2.2	RVr 0:02 / RVr 0:05 / RVr 0: 10	14
6	Operation and maintenance	15
6.1	Operating and maintenance notices	15
6.2	Battery	15
6.2.1	Battery indicator	15

Manufacturer 22



9 1



About this documentation

1.1 Purpose of the document

- This document is intended as a quick reference option.

1.2 Legal notices

This document is entrusted to the recipient for personal use only. Any impermissible transfer, duplication, translation into other languages or excerpts from this operating manual are prohibited.

The manufacturer assumes no liability for print errors.

1.3 Further information

Software version of the product:

V1.1 or later

For the exact product name, refer to the type plate on the rear side of the product.



2 Safety

2.1 Explanation of safety symbols

⚠ DANGER

This symbol warns of imminent danger, which can result in death, severe bodily injury, or severe property damage in case of non-observance.

↑ CAUTION

This symbol warns of potential dangers or harmful situations, which can cause damage to the device or to the environment in case of non-observance.

NOTE

This symbol indicates processes, which can have a direct influence on operation or can trigger an unforeseen reaction in case of non-observance.

2.2 Foreseeable misuse

The fault-free function and operational safety of the product can only be guaranteed if applicable safety precautions and the device-specific safety instructions for this document are observed

If these notices are disregarded, personal injury or death, as well as property damage can occur.

⚠ DANGER

Incorrect area of application!

In order to prevent erratic behaviour of the product, personal injury and property damage, the product must be used exclusively as described in the chapter Description in the operating manual.

- The product is not suitable for use in explosion-prone areas!
- The product must not be used for diagnostic or other medical purposes on patients!
- For measurements requiring devices that are subject to authorisation or special approvals, this product is not a substitute for such products and can only be used as an aid in preparatory or comparison measurements!





2.3 Safety instructions



NOTE

This product does not belong in children's hands!

2.4 Intended use

The device measures the absolute pressure in the air, clean water or in non-corrosive/non-ionising gases. A direct measurement of the environmental pressure can take place or the measurement pressure is taken with a suitable hose connected to the port. Relative measurements can also be conducted with the integrated special function add.

Applications include:

RS 1111

RS 1114

Barometric measurements (e.g. weather)

Barometric measurements (e.g. weather)

Vacuum measurements (down to 0.0 hPa abs., negative pressure via hose or even with complete device evacuation)

Vacuum measurements (down to 0 hPa abs., negative pressure via hose or even with complete device evacuation)

Pneumatic measurements (up to 14000 hPa abs. or 14 bar abs.)

The pressure connection is made at the supplied interchangeable pressure connection ports with suitable hoses.

The device must only be used under the conditions and for the purposes for which it was designed.

It must be handled with care and used according to the technical data (do not throw, strike, etc.). Suitable measures must be used to protect the pressure connections and be protected from dirt.



NOTE

Complete evacuation see Vacuum measurements [13].



The product at a glance

3.1 The RS 1100 barometer series







Front view

3.2 Display elements

Display

Battery indicator Evaluation of the battery status

Unit display Display of the units or Min/Max/Hold information

text

Measurement of the current pressure or value for

min/max/hold

#BBB# Auxiliary display Measurement of the current pressure in

Min/Max/Hold mode





3.3 Operating elements



On / Off button

Press briefly Switch on the product

Activate / deactivate lighting

Long press Switch off the product

Reject changes in a menu



Up / Down button

Press briefly Display of the min/max value

Change value of the selected parameter

Long press Reset the min/max value of the current measure-

ment

Both simultaneously Rotate display, overhead display





Press briefly Freeze measurement (Hold)

Return to measurement display

Call up next parameter

Long press, 2s Start menu configuration, Ears appears in the

display

Close menu, changes are saved

Long press, 4s Depending on the selected special function: Activa-

tion of the Tare function null or rapid measurement

with mean value RVr

3.4 Connections

Universal connection Interchangeable pressure connection via G1/8"

thread.





- 4 Operation
- 4.1 Opening the configuration menu
- 1. Press the Function key for 2 seconds to open the Configuration menu.
- 2. ConF appears in the display. Release the Function key.

Parameter	Values	Meaning
Display unit		
Uni E		
	hРа	
	mbar	
	bar	(only at RS 1114)
	P51	
	mm X ն	
Activatable spe	ecial functions	
	null	Tare function available
	AVR 0:02 / AVR 0:05 / AVR 0: 10	Rapid measurement with mean value over 2 s / 5 $^{\prime}$ / 10 s activatable
Measuring rate)	
rREE		Selection of the measurement speed
	SLo	Slow
	FRSE	Fast

s



Nautical norm correction

SER!

Inactive, display measured air pressure directly nn

Active, display air pressure compensated to sea 455

level

Height above sea level in m for correction -500 9000 Ri Fi

Shut-off time

POFF

No automatic shut-off oFF

חחיכו

0:15 0:30 1:00 4:00 Automatic shut-off after a selected time in hours and minutes, during which no buttons have been

pressed

Backlight

1. FF

Backlight deactivated oFF

0:15 0:30 1:00 4:00 Automatic shut-off of the backlight after a selected

time in minutes and seconds, during which no

buttons have been pressed

No automatic shut off of the backlight nn

Factory settings

In E

Use current configuration no

YES Reset product to factory settings. In EdonE appears

in the display





4.2 Open the adjustment menu

- 1. The product is switched off
- 2. Press and hold the Down button.
- 3. Press the *On/Off button* to switch on the product.
- Release the On/Off button after 1 second and then the Down button in order to call up the adjustment menu. The display shows the first parameter.

Parameter	Values	Meaning
Zero point corr	ection: offset	
Pr.oF		
	0.00	No offset
	-50.0 50.0	Offset active (in hPa – at RS 1111)
	-500 500	Offset active (in hPa – at RS 1114)
Gradient corre	ction: slope	
Pr.SL		
	0.00	No slope
	-5.00 5.00	Slope active (in %)

Formula:

Zero point correction: Displayed value = measured value – offset

Gradient correction: Display = (measured value - offset) * (1 + slope / 100)



5 Measurement Basics

↑ CAUTION

Air pressure at port variant UT!

With higher pressures greater than 1 bar, the hoses must be secured to prevent unintended loosening. Suitable hose clamps are used for this purpose.

6x1 mm PVC. Up to 5 bar rel., vacuum-suitable!
6x1 mm PE. Up to 10 bar rel., vacuum-suitable!
6x1 mm PUR. Up to 9 bar rel., vacuum-suitable!





5.1 Vacuum measurements

The device is especially suitable to measure rough vacuum via the pressure port very fast. But if the complete device is evacuated the following has to be considered:

↑ CAUTION

Damage possible by fast complete evacuation!

Due to the water tight construction a complete evacuation of the device may degrade water protection. The keypad/display screen may break loose. If the device should still be used for this application, the following options are available:

 Remove the o-ring of the battery compartment! The Instrument then is no more water protected! Changing battery.





5.2 Special functions

With the special functions that can be selected via the *Configuration menu*, the device can be optimised for special measuring tasks.

After it is switched on, the device starts up in standard measuring mode, the relevant special function is started by pressing and holding the *Function key* for 4 s.

5.2.1 null Tare function

The special function Func null has been selected in the configuration menu.

The display can be zeroed by pressing the *Function key* for 4 s. If the tare function is activated, null blinks in the lower display. The tare function can be reset by pressing the *Function key* again for 4 s.

NOTE

The tare function is independent of the zero point correction accessible via the settings menu.

5.2.2 RVr 0:02 / RVr 0:05 / RVr 0: 10

Fast measurement with mean value over 2 s / 5 s / 10 s

Mean value mode for measurement of heavily fluctuating pressures.

In the Configuration mode, a special function RVr 0:02, RVr 0:05 or RVr 0:00 has been selected.

By pressing and holding the *Function key* for 4 s. the measurement with mean value can be activated.

The different mean value times of 2, 5 or 10 seconds can be selected depending on the requirement.

The first parameter is shown in the auxiliary display.

If the Tare function is activated when called up, this special function RVr can be reset by pressing and holding the *Function key* for 4 s. In order to reactivate the Tare, the special function must be switched in the configuration menu.



6 Operation and maintenance

6.1 Operating and maintenance notices

NOTE

Pressure connections must be protected from soiling.

6.2 Battery

6.2.1 Battery indicator

If the empty frame in the battery display blinks, the batteries are depleted and must be replaced. However, the device will still operate for a certain length of time.

If the BAT display text appears in the main display, the battery voltage is no longer adequate for operation of the product. The battery is fully depleted.

6.2.2 Changing battery

⚠ DANGER

Danger of explosion!

Using damaged or unsuitable batteries can generate heat, which can cause the batteries to crack and possibly explode!

- Only use high-quality and suitable alkaline batteries!

↑ CAUTION

Damage!

If the batteries have different charge levels, leaks and thus damage to the product can occur.

- Use new, high-quality batteries!
- Do not use different types of batteries!
- Remove depleted batteries and dispose of them at a suitable collection point.





NOTE

This symbol indicates processes, which can have a direct influence on operation or can trigger an unforeseen reaction in case of non-observance.

NOTE

Read the following handling instructions before replacing batteries and follow them step by step.

If disregarded, the product could be damaged or the protection from moisture could be diminished



- 1. Unscrews the Phillips screws (A)and remove the cover.
- Carefully replace the two Mignon AA batteries (B). Ensure that the polarity is correct! It must be possible to insert the batteries in the correct position without using force.
- The O-ring (C) must be undamaged, clean and positioned at the intended depth. In order to facilitate assembly and avoid damage, a suitable grease can be applied.
- Fit the cover on evenly. The O-ring must remain at the intended depth!
- 5. Tighten the Phillips screws (A).



7 Error and system messages

Display	Meaning	Possible causes	Remedy
	Calculation not possible	Measurement data acquisition is run- ning	Waiting for data collection
No display,	Battery depleted	Battery depleted	Replace battery
unclear characters	System error	Error in the product	Send in for repair
or no re- sponse when but- tons are pressed	Product is defective	Product is defective	
ЬЯŁ	Battery depleted	Battery depleted	Replace battery
bAt Lo	Battery depleted	Battery depleted	Replace battery
Err.l	Measuring range exceeded	Measurement too high	Stay within allowable measurement range
		Product is defective	Send in for repair
Err.2	Measuring range is undercut	Measurement too low	Stay within allowable measurement range
		Product is defective	Send in for repair
535 Err	System error	Error in the product	Switch product on/off
			Replace batteries
			Send in for repair





8 Technical data

8.1 RS 1111

Measuring range		0.0 1700.0 hPa (mbar) abs.
		0.00 25.00 PSI abs.
		0.0 1300 mmHg (Torr) abs.
Accuracy		< ± 2 hPa typical (at T: 5 30 °C)
		± 1,5 % FSS max
Measuring cycle	е	FR5E: approx. 25 measurements per second
		5Lo: approx. 2.5 measurements per second
Overload		3000 hPa abs.
Pressure connection		1 hose connection, interchangeable with G1/8 universal port
Display		3-line segment LCD, additional symbols, illuminated (adjustable white, permanent illumination)
Standard function		Min/Max/Hold
		Auto-power-Off function / if activated, switches the product off automatically
Additional functions		null: Tare function
		RVr: Averaging over 2 s / 5 s / 10 s
Calibration		Zero point and gradient adjustment
Housing		Break-proof ABS housing
	Protection rating	IP67
	Dimensions L*W*H [mm] and weight	108 * 54 * 28 mm without pressure connector 140 g, incl. battery



Operating conditions		-20 to 50 °C; 0 to 95 % r.h. (short-term condensation possible)
Storage temperature		-20 to 70 °C
Current supply		2*AA battery (included in the scope of delivery)
	Current require- ment/ Battery life	approx. 1 mA (slow measurement SLO) Operating time approx. 3000 h
	Battery indicator	4-stage battery status indicator,
		Charge indicator for low charge level: "BAT LO"
Auto-power-OFF function		The device switches off automatically if this is activated
Directives and standards		The devices conform to the following Directives of the Council for the harmonisation of legal regulations of the Member States: 2014/30/EU EMC Directive
		2011/65/EU RoHS
		Applied harmonised standards:
		EN 61326-1:2013 Emission limits: class B Immunity according to table 1 Additional errors: < 1 % FS
		EN 50581:2012
		The device is intended for mobile use and/or stationary operation in the scope of the specified operating conditions without further limitations.





8.2 RS 1114

Measuring range		0 14000 hPa (mbar) abs.	
		0.00 199.99 PSI abs.	
		0 10500 mmHg (Torr) abs.	
Accuracy		< ± 0.1 % MW respectively ± 0.02 % FSS typical (at T: 5 30 °C)	
		± 0.5 % MW ± 0.1 % FSS max.	
Measuring cycle	Э	FR5E: approx. 25 measurements per second	
		5Lo: approx. 2.5 measurements per second	
Overload		20000 hPa abs.	
Pressure connection		1 hose connection, interchangeable with G1/8 universal port	
Display		3-line segment LCD, additional symbols, illuminated (adjustable white, permanent illumination)	
Standard function	on	Min/Max/Hold	
		Auto-power-Off function / if activated, switches the product off automatically	
Additional functions		null: Tare function	
		RVr: Averaging over 2 s / 5 s / 10 s	
Calibration		Zero point and gradient adjustment	
Housing		Break-proof ABS housing	
	Protection rating	IP67	
	Dimensions L*W*H [mm] and weight	108 * 54 * 28 mm without Pressure connector 140 g, incl. battery	
Operating conditions		-20 to 50 °C; 0 to 95 % r.h. (short-term condensa-	



		tion possible)
Storage temperature		-20 to 70 °C
Current		2*AA battery (included in the scope of delivery)
supply	Current require- ment/ Battery life	approx. 0.6 mA (slow measurement SLO) Operating time approx. 5000 h
	Battery indicator	4-stage battery status indicator,
		Charge indicator for low charge level: "BAT LO"
Auto-power-OFF function		The device switches off automatically if this is activated
Directives and standards		The devices conform to the following Directives of the Council for the harmonisation of legal regulations of the Member States:
		2014/30/EU EMC Directive
		2011/65/EU RoHS
		Applied harmonised standards:
		EN 61326-1:2013 Emission limits: class B Immunity according to table 1 Additional errors: < 1 % FS
		EN 50581:2012
		The device is intended for mobile use and/or stationary operation in the scope of the specified operating conditions without further limitations.





9 Service

9.1 Manufacturer

If you have any questions, please do not hesitate to contact us:

Contact

RS Components Limited

Birchington Road

Corby

Northamptonshire

NN17 9RS

WEE/GF0002ZR

