



education

Department:
Education
REPUBLIC OF SOUTH AFRICA

**NATIONAL
SENIOR CERTIFICATE**

GRADE 12

MECHANICAL TECHNOLOGY

MARCH 2009

MEMORANDUM

MARKS: 200

This memorandum consists of 17 pages.

QUESTION 1: MULTIPLE CHOICE QUESTIONS
(Learning Outcome 3: Assessment Standards 1 – 9)

1.1	B	✓ (1)
1.2	D	✓ (1)
1.3	C	✓ (1)
1.4	B	✓ (1)
1.5	D	✓ (1)
1.6	A	✓ (1)
1.7	C	✓ (1)
1.8	B	✓ (1)
1.9	D	✓ (1)
1.10	D	✓ (1)
1.11	C	✓ (1)
1.12	A	✓ (1)
1.13	B	✓ (1)
1.14	A	✓ (1)
1.15	D	✓ (1)
1.16	C	✓ (1)
1.17	B	✓ (1)
1.18	C	✓ (1)
1.19	D	✓ (1)
1.20	A	✓ (1)
		[20]

QUESTION 2: FORCES AND SYSTEMS AND CONTROL
(Learning Outcome 3: Assessment Standards 6 and 8)

2.1 STRESS AND STRAIN (Young's modulus)

2.1.1 Calculate the diameter of the pin.

$$\text{Stress } (\sigma) = \frac{\text{Force (F)}}{\text{Area (A)}}$$

$$A = \frac{100 \times 10^3}{204 \times 10^6}$$

$$= 0,49 \times 10^{-3} \text{ m}^2$$

$$\text{But Area} = \frac{\pi d^2}{4}$$

$$d = \sqrt{\frac{4A}{\pi}}$$

$$= \sqrt{\frac{4 \times 0,49 \times 10^{-3}}{\pi}}$$

$$= \sqrt{0,624 \times 10^{-3}}$$

$$= 0,025 \text{ m}$$

$$d = 25 \text{ mm}$$

✓

✓

✓

✓

✓

✓

(6)

2.1.2 Calculate the strain induced in the pin.

$$E = \frac{\sigma}{\varepsilon}$$

$$\varepsilon = \frac{\sigma}{E}$$

$$= \frac{204 \times 10^6}{210 \times 10^9}$$

$$= 0,97 \times 10^{-3}$$

✓

✓

✓

(3)

2.1.3 Calculate the change in length of the pin.

$$\varepsilon = \frac{\Delta L}{OL}$$

$$\Delta L = \varepsilon \times OL$$

$$= (0,97 \times 10^{-3}) \times (110)$$

$$= 0,11 \text{ mm}$$

✓

✓

✓

(3)

2.1.4 Type of stress induced in the pin

Compressive stress ✓ (1)

2.1.5 Effect the load has on the pin

The load will shorten the length of the pin

The new length = (110 – 0,11) mm ✓
= 109,89 mm ✓ (3)

2.1.6 Effect when using brass

The length of the brass pin will be shortened more than the mild steel pin. ✓

Young's modulus of elasticity will be less than mild steel because it is a softer material. ✓ (2)

2.2 BELT DRIVES**2.2.1 Calculate the mass of the belt.**

Mass per metre = Area × Length × Density
= (thickness × width) × (length) × (density) ✓
= (0,005 × 0,28) × (1) × (1) × 10³ ✓
= 1,40 kg/m ✓ (3)

2.2.2 Calculate the belt speed.

Belt speed (V) = $\frac{\pi(D+t) \times N}{60}$
= $\frac{\pi(0,34 + 0,005) \times 2000}{60}$ ✓
= 36,14 m/s ✓ (3)

2.2.3 Calculate the power to drive the belt system.

$$P = \frac{2\pi NT}{60}$$

$$\text{but } T = F \times r$$

$$= 400 \text{ N} \times 0,17 \text{ m}$$

$$= 68 \text{ Nm}$$

$$P = \frac{2 \times \pi \times 2000 \times 68}{60}$$

$$= 14241,89 \text{ W}$$

$$= 14,24 \text{ kW}$$

✓

✓

✓

✓

(4)

2.2.4 The thicker belt

The thicker belt will result in reducing the speed of the pulley because of its weight.

✓✓

(2)

2.3 FRICTION**2.3.1 Calculate the torque applied.**

$$\text{Torque} = \mu W n R$$

$$= 0,35 \times 3,4 \times 10^3 \times 2 \times 0,1$$

$$= 238 \text{ Nm}$$

✓

✓

(2)

2.3.2 Calculate the power transmitted.

$$\text{Power} = \frac{2\pi NT}{60}$$

$$= \frac{2 \times \pi \times 3\ 200 \times 238}{60}$$

$$= 79,75 \text{ kW}$$

✓

✓

✓

(3)

2.4 HYDRAULIC PRESS**2.4.1 Calculate the diameter of Piston A.***First calculate the volume of cylinder B.* ✓

$$V_B = \text{Area}_B \times \text{Stroke length}_B$$

$$= \frac{\pi \times D_B^2}{4} \times L_B$$

$$= \frac{\pi \times (0,18)^2}{4} \times 0,012$$
 ✓

$$= 0,305 \times 10^{-3} \text{ m}^3$$
 ✓

$$\text{But, } V_A = V_B$$

$$\therefore A_A \times L_A = V_B$$
 ✓

$$A_A \times 0,06 = 0,305 \times 10^{-3}$$
 ✓

$$A_A = \frac{0,305 \times 10^{-3}}{0,06}$$

$$= 5,08 \times 10^{-3} \text{ m}^2$$
 ✓

$$A_A = \frac{\pi D_A^2}{4}$$

$$D_A^2 = \frac{5,08 \times 10^{-3} \times 4}{\pi}$$
 ✓

$$D_A = \sqrt{6,47 \times 10^{-3}}$$
 ✓

$$D_A = 0,80 \text{ m}$$

$$= 80 \text{ mm}$$
 ✓ (9)

2.4.2 Calculate the pressure exerted on Piston A.

$$\text{Pressure at A} = \frac{F_A}{A_A}$$

$$P_A = \frac{550}{5,08 \times 10^{-3}}$$
 ✓

$$= 108,268 \times 10^3 \text{ Pa}$$

$$= 108,27 \text{ kPa}$$
 ✓ (2)

2.4.3 Calculate the force exerted on Piston B.

NOTE: Pressure at A is equal to Pressure at B

$$P_B = P_A$$

$$P_B = \frac{F_B}{A_B}$$

$$\begin{aligned} F_B &= 108,268 \times 10^3 \times A_B \\ &= 108,268 \times 10^3 \times 25,45 \times 10^{-3} \\ &= 2755,42 \text{ N} \\ &= 2,76 \text{ kN} \end{aligned}$$

✓

✓

✓

✓

(4)
[50]

QUESTION 3: TOOLS AND EQUIPMENT
Learning Outcome 3: Assessment Standard 2

3.1 METAL ARC GAS SHIELDED WELDING

- | | | |
|------------------------|---|-----|
| 1. Regulator | ✓ | |
| 2. Gun cable | ✓ | |
| 3. Welding gun / torch | ✓ | |
| 4. Earth cable | ✓ | |
| 5. Power cable | ✓ | |
| 6. Wire feed control | ✓ | |
| 7. Gas cylinder | ✓ | (7) |

3.2 ABBREVIATION MAGS/MIGS

<i>Metal Arc Gas Shielded /Metal Inert Gas Shielded</i>	✓	(1)
---	---	-----

3.3 GAS USED IN MAGS/MIGS WELDING

<i>Argon</i>		
<i>Carbon dioxide</i>	✓	
<i>Helium</i>		
<i>Oxygen</i>	(Any 2) ✓	(2)

3.4 DETERMINE CYLINDER LEAKAGES

- | | | |
|--|--------|------|
| • Listen at the carburetor for a hissing noise | ✓ | |
| ➤ Valve is leaking | ✓ | |
| • Listen at the exhaust pipe for a hissing noise | ✓ | |
| ➤ Exhaust valve is leaking | ✓ | |
| • Listen for a hissing noise in the dipstick hole | ✓ | |
| ➤ Piston ring is worn | ✓ | |
| • Remove the filler cap on the tappet cover and listen for a hissing noise | ✓ | |
| ➤ Rings are worn | ✓ | |
| • If you see bubbles in the radiator water, | | |
| ➤ The cylinder head gasket is blown | (10) ✓ | (10) |

[20]

QUESTION 4: MATERIALS
(Learning Outcome 3: Assessment Standard 3)

4.1 MATERIALS

- 4.1.1** *A non-ferrous alloy is a metal that has a combination of two or more non-ferrous metals, which are melted together to form one alloy.* ✓
✓ (2)
- 4.1.2** *Composites are materials that are made up of two or more different materials put together.* ✓
✓ (2)

4.2 ENGINEERING MATERIALS

	PROPERTIES	USES
4.2.1 White metal	<i>Any TWO of the following:</i> <ul style="list-style-type: none"> • <i>Low friction</i> ✓ • <i>Low melting</i> ✓ • <i>Casts well</i> ✓ 	<i>Any TWO of the following:</i> <ul style="list-style-type: none"> • <i>Big-end bearings</i> ✓ • <i>Main bearings</i> ✓ • <i>Bearings for electrical machines</i> ✓

(4)

4.2.2 Vanadium	<i>Any TWO of the following:</i> <ul style="list-style-type: none"> • <i>Wear resistant</i> ✓ • <i>Fatigue resistant</i> ✓ • <i>Makes steel stronger</i> ✓ 	<i>Any TWO of the following:</i> <ul style="list-style-type: none"> • <i>Crankshafts</i> ✓ • <i>Connecting rods</i> ✓ • <i>Gears</i> ✓ • <i>Vehicle axles</i> ✓ • <i>Steering components</i> ✓
---------------------------------	---	---

(4)

4.2.3 Nylon	<i>Any TWO of the following:</i> <ul style="list-style-type: none"> • <i>Needs no lubrication</i> ✓ • <i>Can withstand a lot of shock</i> ✓ • <i>No maintenance</i> ✓ • <i>Light in weight</i> ✓ • <i>Easy to machine</i> ✓ 	<i>Any TWO of the following:</i> <ul style="list-style-type: none"> • <i>Fan blades</i> ✓ • <i>Bearings</i> ✓ • <i>Gears</i> ✓ • <i>Trolley wheels</i> ✓ • <i>Bolts and nuts</i> ✓
------------------------------	--	---

(4)

4.3 BRASS

- *It is resistant against corrosion.* ✓
 - *It is ductile and malleable.* ✓
 - *Can be polished to give a good shine.* ✓
 - *It is softer than mild steel and easy to machine.* ✓
- (4)
[20]

QUESTION 5: SAFETY, TERMINOLOGY AND JOINING METHODS
(Learning Outcome 3: Assessment Standards 1, 4 and 5)**5.1 LATHE MACHINE – SAFETY**

- *Clamp work piece solidly.* ✓
- *Use the correct size tool and work-holding device for the job.* ✓
- *Get an assistant when working with heavy chucks, attachments and work piece.* ✓
- *Make sure that all guards are in place before you operate the machine.* ✓
- *Stop the machine before making measurements or adjustments.* ✓
- *Do not attempt to remove chips with your hand. Use a brush or short stick.* ✓
- *Remove neck tie, wrist watch and jewelry.* ✓
- *Always remove the key from the chuck.* ✓
- *Wear apron and safety goggles when working on a lathe.* ✓
- *Tools must not be placed on the lathe ways.* (any 5 x 1 = 5) ✓ (5)

5.2 METAL ARC GAS SHIELDED SAFETY OR METAL INERT GAS WELDING SAFETY

- *The work area must be well ventilated because of toxic gases.* ✓
- *The work area must be well illuminated.* ✓
- *Wear flameproof gauntlet, gloves, flameproof apron or leather, asbestos or other non-flammable materials, because of hot sparks.* ✓
- *Do not use gloves to carry hot metal, use a pair of pliers.* ✓
- *Use fire-resistant leggings and safety boots to protect legs and feet.* ✓
- *When performing overhead welding, the operator must use the face shield and helmet.* (any 4 x 1 = 4) ✓ (4)

5.3 MILLING CUTTERS

- 5.3.1** *Plain helical cutter* ✓ (1)
- 5.3.2** *Side and face cutter* ✓ (1)
- 5.3.3** *Slotting cutter* ✓ (1)
- 5.3.4** *Dove tail cutter* ✓ (1)
- 5.3.5** *Slot drill* ✓ (1)

5.4 INDEXING

<i>INDEX PLATE HOLE CIRCLES</i>											
<i>Side 1</i>	24	25	28	30	34	37	38	39	41	42	43
<i>Side 2</i>	46	47	49	51	53	54	57	58	59	62	66

<i>STANDARD CHANGE GEARS</i>										
24 x 2	28	32	40	44	48	56	64	72	86	100

5.4.1 Indexing:

Use $A = 86$ and $n=87$

$$\text{Indexing} = \frac{40}{A} = \frac{40}{87} \Rightarrow \text{no calculation possible} \quad \checkmark$$

choose $A = 86$

$$\begin{aligned} \text{Indexing} &= \frac{40}{A} && \checkmark \\ &= \frac{40}{86} \\ &= \frac{20}{43} && \checkmark \end{aligned}$$

i.e. no full turns and 20 holes in a 43 hole circle plate (3)

5.4.2 Change gears:

$$\begin{aligned} \frac{Dr}{Dv} (\text{Gear ratio}) &= (A/N - n) \times \frac{40}{A/N} && \checkmark \\ &= (86 - 87) \times \frac{40}{86} && \checkmark \\ &= -1 \times \frac{40}{86} && \checkmark \\ & && \checkmark \\ \frac{Dr}{Dv} &= -\frac{40}{86} && \checkmark \\ & && \checkmark \end{aligned}$$

(6)

5.4.3 Meaning of positive (+) and negative (-) signs

If the sign is positive (+) when determining change gears, the rotation of the index plate will be in the same direction of rotation of the crank handle. ✓
✓

If the sign is negative (-) when determining change gears, the rotation of the index plate will be in the opposite direction of rotation of the crank handle. ✓
✓

(4)

5.5 Calculate the feed on a milling machine.

$$D = \frac{80}{1000}$$

$$= 0,08 \text{ m} \quad \checkmark$$

$$V = \pi DN$$

$$N = \frac{V}{\pi D}$$

$$= \frac{25}{\pi \times 0,08}$$

$$= 99,47 \text{ r/min} \quad \checkmark$$

$$f = f_i \times T \times N$$

$$= 0,04 \times 16 \times 99,47$$

$$= 63,66 \text{ mm/min} \quad \checkmark$$

$$= 64 \text{ mm/min} \quad \checkmark \quad (6)$$

5.6 LIQUID DYE PENETRANT

- *Clean the surface to be tested.* ✓
- *A liquid dye penetrant is sprayed onto the clean surface.* ✓
- *Allow a short time for the dye to penetrate the weld joint.* ✓
- *Use a cloth to remove excess dye on the weld.* ✓
- *Wash the surface and allow to dry thoroughly.* ✓
- *Use a developer and spray on the surface which brings out the colour in the dye penetrant that has penetrated into the cracks or pinholes.* ✓ (6)

5.7 DESTRUCTIVE TESTS ON A WELDED JOINT

- *To check whether proper welding procedures were followed during the welding process.* ✓
- *To check for visual weld defects.* ✓ (2)

5.8 WELDING DEFECTS (any 3 x 3 = 9)

WELD DEFECT	CAUSES	CORRECTION METHOD
<i>Poor appearance ✓</i>	<p><i>Any ONE of the following:</i></p> <ul style="list-style-type: none"> • <i>Current too high or too low ✓</i> • <i>Incorrect use of electrode ✓</i> • <i>Faulty electrode ✓</i> 	<p><i>Any ONE of the following</i></p> <ul style="list-style-type: none"> • <i>Adjust current to required amperage ✓</i> • <i>Check the procedure of welding ✓</i> • <i>Change the electrode or use dry electrode ✓</i>
<i>Weld crater ✓</i>	<p><i>Any ONE of the following:</i></p> <ul style="list-style-type: none"> • <i>Current too high ✓</i> • <i>Improper welding technique ✓</i> • <i>Electrode too small ✓</i> 	<p><i>Any ONE of the following:</i></p> <ul style="list-style-type: none"> • <i>Use lower current ✓</i> • <i>Use proper welding technique ✓</i> • <i>Use correct electrode ✓</i>
<i>Slag inclusion ✓</i>	<p><i>Any ONE of the following:</i></p> <ul style="list-style-type: none"> • <i>Included angle too narrow ✓</i> • <i>Rapid chilling ✓</i> • <i>Weld temperature too low ✓</i> • <i>High viscosity of molten metal ✓</i> 	<p><i>Any ONE of the following:</i></p> <ul style="list-style-type: none"> • <i>Preheat metal ✓</i> • <i>Remove slag from previous run weld ✓</i> • <i>Increase the included angle ✓</i>
<i>Porous weld ✓</i>	<p><i>Any ONE of the following:</i></p> <ul style="list-style-type: none"> • <i>Speed too fast ✓</i> • <i>Current too low ✓</i> • <i>Insufficient puddling time ✓</i> • <i>Faulty electrode ✓</i> • <i>High sulphur or other impurities in metal ✓</i> • <i>Impaired base metal ✓</i> • <i>Short arc with exception of low hydrogen and stainless ✓</i> 	<p><i>Any ONE of the following:</i></p> <ul style="list-style-type: none"> • <i>Use correct current ✓</i> • <i>Hold a long arc ✓</i> • <i>Use low hydrogen electrodes ✓</i> • <i>Check for impurities in base metal ✓</i> • <i>Allow for sufficient puddling time for gases to escape ✓</i> • <i>Weave the weld ✓</i> • <i>Use correct electrode for the job ✓</i>

WELD DEFECT	CAUSES	CORRECTION METHOD
<i>Incomplete penetration ✓</i>	<p><i>Any ONE of the following:</i></p> <ul style="list-style-type: none"> • <i>Speed too fast ✓</i> • <i>Joint design faulty ✓</i> • <i>Electrodes too large ✓</i> • <i>Current too low ✓</i> 	<p><i>Any ONE of the following:</i></p> <ul style="list-style-type: none"> • <i>Use correct current to obtain desired penetration ✓</i> • <i>A weld slowly ✓</i> • <i>Calculate the electrode penetration properly ✓</i> • <i>Select correct electrode according to welding groove ✓</i> • <i>Leave enough free space at the bottom of the weld ✓</i>
<i>Undercutting ✓</i>	<p><i>Any ONE of the following:</i></p> <ul style="list-style-type: none"> • <i>Faulty electrode manipulation ✓</i> • <i>Current too high ✓</i> • <i>Arc length too long ✓</i> • <i>Speed of weld too fast ✓</i> 	<p><i>Any ONE of the following:</i></p> <ul style="list-style-type: none"> • <i>Use a uniform weave in butt welding ✓</i> • <i>Do not use a too large electrode ✓</i> • <i>Avoid excessive weaving ✓</i> • <i>Current to be moderate and weld slowly ✓</i> • <i>Hold the electrode at a safe distance from the vertical plane when making a horizontal fillet weld ✓</i>

(any 3 x 3 = 9)

(9)
[50]

QUESTION 6: MAINTENANCE AND TURBINES
(Learning Outcome 3: Assessment Standards 7 and 9)

6.1 EFFECTIVENESS OF A CUTTING FLUID AS COMPARED TO OIL

- *It prevents the shavings or metal chips from sticking and fusing to the cutting tool* ✓
- *It will carry away the heat generated by the turning process* ✓
- *It flushes away shavings/metal chips* ✓
- *It improves the quality of the finish of the turned surface* ✓ (4)

6.2 CORROSION AND RUST RESISTANCE OF OIL

- *It is the ability of oil to displace water from the metal allowing the oil to coat the surfaces.* ✓
- *It also has the alkaline reaction to neutralise combustion acid thus preventing corrosion.* ✓ (2)

6.3 REASONS FOR OIL CHANGE

- *Formation of gum, acids and lacquer may be left by the combustion of the fuel.* ✓
- *Oil loses its viscosity after a while due to excessive heat transfer which results in reduction of lubricating efficiency.* ✓
- *Metal particles deposit in the oil due to metal and metal contact.* ✓ (3)

6.4 DRAINING AND FILLING DIFFERENTIAL OIL PROCEDURE

- *Run the vehicle first so that the rear axle oil is warm, so that it drains easily.* ✓
- *Place a drain tray that can hold all the oil removed.* ✓
- *Clean the area around the drain and filler plug.* ✓
- *Remove the filler plug this will allow oil to flow easily and fast.* ✓
- *Remove the drain plug/plate and allow oil to drain into the tray.* ✓
- *Wash drain and filler plugs.* ✓
- *Fit new washers to both the drain and filler plugs.* ✓
- *Replace the drain plug.* ✓
- *Fill the oil until it just trickles out of the filler hole.* ✓
- *Replace filler plug.* ✓
- *Wipe off surplus oil.* ✓ (11)

6.5 BLOWER**6.5.1 Type of blower**

Centrifugal blower ✓ (1)

6.5.2 Labels

1. *Air inlet* ✓
2. *Air outlet* ✓
3. *Impeller* ✓
4. *Fins* ✓ (4)

6.5.3 Advantages of the supercharger

- *Increases the output power of the engine.* ✓
- *A smaller engine fitted with a centrifugal blower delivers the same power as a larger engine.* ✓
- *It eliminates lack of oxygen above sea level.* ✓
- *Increases the volumetric efficiency of the engine.* ✓
- *With the aid of the intercooler both the power and the torque output of the engine are increased.* ✓ (3)
(any 3 x 1)

6.6 PURPOSES OF A SUPERCHARGER.

Any TWO of the following:

- *The supercharger fills the cylinder with an increased pressure that is higher than atmospheric pressure* ✓
- *The compression pressure in the cylinder is increased.* ✓
- *The volumetric efficiency of the engine is increased.* (any 2 x 1 = 2) ✓ (2)

6.7 USES OF A SUPERCHARGER

Any TWO of the following:

- *Used in high performance cars.* ✓
- *Aircraft engines to overcome loss of power owing to height above sea level.* ✓
- *Heavy vehicles and earth moving equipment.* (any 2 x 1 = 2) ✓ (2)

6.8 OPERATION OF THE TURBOCHARGER

- *The energy at which the exhaust gases that rushes out the exhaust are wasted* ✓
- *This hot expanding gases from the engine is routed in the direction of the turbine wheel through a scroll like housing,* ✓
- *In this manner the turbine wheel is enabled to spin at very high speeds.* ✓
- *The gases are then channeled out of the housing and wheel assembly into the normal exhaust system.* ✓
- *As the turbine wheel spins, it turns a common shaft, which in turn spins the other fan called the impeller.* ✓
- *The impeller and its scroll housing acts as a compressor drawing air or air and fuel mixture in through the inlet compressing and delivering it through the output port.* ✓
- *The induction passage then transfers the air/fuel mixture into the cylinders under pressure.* ✓
- *This boost pressure delivered to the cylinders increases the volumetric efficiency of the engine, as well as the engine performance.* ✓ (8 [40])

TOTAL: 200