



basic education

Department:
Basic Education
REPUBLIC OF SOUTH AFRICA

**NATIONAL
SENIOR CERTIFICATE**

GRADE 12

MECHANICAL TECHNOLOGY

NOVEMBER 2010

MEMORANDUM

MARKS: 200

This memorandum consists of 18 pages.

QUESTION 1: MULTIPLE CHOICE QUESTIONS

- 1.1 D ✓ (1)
- 1.2 C ✓ (1)
- 1.3 B ✓ (1)
- 1.4 D ✓ (1)
- 1.5 D ✓ (1)
- 1.6 B ✓ (1)
- 1.7 C ✓ (1)
- 1.8 A ✓ (1)
- 1.9 D ✓ (1)
- 1.10 B ✓ (1)
- 1.11 D ✓ C (1)
- 1.12 D ✓ (1)
- 1.13 D ✓ (1)
- 1.14 A ✓ (1)
- 1.15 D ✓ (1)
- 1.16 B ✓ (1)
- 1.17 B ✓ (1)
- 1.18 C ✓ (1)
- 1.19 A ✓ (1)
- 1.20 B ✓ (1)

[20]

QUESTION 2: FORCES, SYSTEMS AND CONTROL**2.1 HYDRAULICS****2.1.1 Calculate the fluid pressure in the system:**

$$A_B = \frac{\pi D^2}{4} \quad \text{or } A_B = \pi r^2 \quad \checkmark$$

$$= \frac{\pi(0.1)^2}{4} \quad \checkmark$$

$$= 7,85 \times 10^{-3} \text{ m}^2$$

$$P = \frac{F_B}{A_B} \quad \checkmark$$

$$= \frac{150 \times 10^3}{7,85 \times 10^{-3}} \quad \checkmark$$

$$= 19,108 \text{ MPa}$$

$$= 19,11 \text{ MPa} \quad \checkmark \quad (4)$$

2.1.2 Calculate the force on piston A:

$$A_A = \frac{\pi D^2}{4} \quad \checkmark$$

$$= \frac{\pi(0,025)^2}{4} \quad \checkmark$$

$$= 0,49 \times 10^{-3} \text{ m}^2$$

$$F_A = P \times A_A \quad \checkmark$$

$$= \frac{150 \times 10^3}{7,85 \times 10^{-3}} \times 0,49 \times 10^{-3} \quad \checkmark$$

$$= 9363,9 \text{ N}$$

$$= 9,36 \text{ kN} \quad \checkmark \quad (4)$$

2.1.3 Calculate force F:

$$F \times 0,48 = 9363,9 \times 0,08 \quad \checkmark \checkmark$$

$$F = \frac{9363,9 \times 0,08}{0,48} \quad \checkmark$$

$$= 1560,65 \text{ N} \quad \checkmark \quad (4)$$

2.2 STRESS AND STRAIN**2.2.1 Calculate the maximum stress in part C:**

$$\begin{aligned}
 A_C &= \frac{\pi D^2}{4} && \checkmark \\
 &= \frac{\pi(0,05)^2}{4} && \checkmark \\
 &= 1,96 \times 10^{-3} \text{ m}^2 && \checkmark \\
 \\
 \sigma_C &= \frac{F}{A_C} && \checkmark \\
 &= \frac{12 \times 10^3}{1,96 \times 10^{-3}} \\
 &= 6,12 \times 10^6 \text{ Pa} \\
 &= 6,12 \text{ MPa} && \checkmark \quad (5)
 \end{aligned}$$

2.2.2 Calculate the strain in part A:

$$\begin{aligned}
 E &= \frac{\sigma_A}{\varepsilon_A} \\
 \varepsilon_A &= \frac{\sigma_A}{E} && \checkmark \\
 \text{BUT} \\
 \sigma_A &= \frac{F}{A_A} && \checkmark \\
 \sigma_A &= \frac{F \times 4}{\pi(D_A)^2} && \checkmark \\
 &= \frac{12 \times 10^3 \times 4}{\pi(0,1)^2} && \checkmark \\
 &= 1,527 \times 10^6 \text{ Pa} && \checkmark \\
 &= 1,53 \text{ MPa} \\
 \\
 \varepsilon_A &= \frac{\sigma_A}{E} && \checkmark \\
 &= \frac{1,53 \times 10^6}{108 \times 10^9} \\
 &= 0,014 \times 10^{-3} \quad \text{or} \quad 0.00001414 && \checkmark \quad (7)
 \end{aligned}$$

ALTERNATIVELY**2.2.2 Calculate the strain in part A:**

$$\begin{aligned} \sigma_A \times A_A &= \sigma_C \times A_C && \checkmark \\ \sigma_A &= \frac{\sigma_C \times A_C}{A_A} && \\ \sigma_A &= \frac{\sigma_C \times (D_C)^2}{(D_A)^2} && \checkmark \\ &= \frac{\sigma_C \times (50)^2}{(100)^2} && \checkmark \\ &= \frac{\sigma_C}{2^2} && \\ &= \frac{6,12 \times 10^6}{4} && \checkmark \\ \sigma_A &= 1,53 \times 10^6 \text{ Pa} && \checkmark \\ \varepsilon_A &= \frac{\sigma_A}{E} && \\ &= \frac{1,53 \times 10^6}{108 \times 10^9} && \checkmark \\ &= 0,014 \times 10^{-3} && \checkmark \quad (7) \end{aligned}$$

2.3 BELT DRIVE**Calculate power transmitted:**

$$\frac{T_1}{T_2} = 2,5$$

$$T_2 = \frac{T_1}{2,5}$$

$$= \frac{300}{2,5}$$

$$T_2 = 120 \text{ N}$$

$$P = (T_1 - T_2)\pi Dn$$

$$= (300 - 120) \times \pi \times 0,6 \times 7,2$$

$$= 2442,9 \text{ Watt}$$

$$= 2,44 \text{ kW}$$

OR

$$P = (T_1 - T_2)\pi Dn$$

$$= (300 - 120)\pi \times 0,432 \times 10$$

$$= 2442,9 \text{ Watt}$$

$$= 2,44 \text{ kW}$$

√

√

√

√

√√

√

O**R**

√

√√

√

(7)

2.4 GEAR DRIVE**2.4.1 Calculate the number of teeth on the final gear D:**

$$\frac{\text{Product of number of teeth on driven gears}}{\text{Product of number of teeth on driver gears}} = \frac{N_{DR}}{N_{DN}}$$

$$\frac{80 \times T_D}{30 \times 20} = \frac{480}{90}$$

$$T_D = \frac{480 \times 30 \times 20}{90 \times 80}$$

$$= 40 \text{ Teeth}$$

√

√

√

√

(4)

2.4.2 The gear ratio of the system:

$$\begin{aligned}
 \text{Gear ratio} &= \frac{\text{Product of number of teeth on driven gears}}{\text{Product of number of teeth on driver gears}} && \checkmark \\
 &= \frac{80 \times 40}{30 \times 20} && \checkmark \\
 &= 5,3 : 1 && \checkmark \\
 &\text{OR} && \checkmark \\
 \text{Gear ratio} &= \frac{N_{\text{input}}}{N_{\text{output}}} && \mathbf{O} \\
 &= \frac{480}{90} && \mathbf{R} \\
 &= 5,3 : 1 && \checkmark
 \end{aligned}$$

(3)

2.5 WHEEL AND AXLE**2.5.1 Calculate the mechanical advantage of the system:**

$$\begin{aligned}
 MA &= \frac{\text{Load}}{\text{Effort}} && \checkmark \\
 &= \frac{1800}{100} && \checkmark \\
 &= 18 && \checkmark
 \end{aligned}$$

(3)

2.5.2 Calculate the velocity ratio of the system:

$$\begin{aligned}
 VR &= \frac{2D}{d_2 - d_1} && \checkmark \\
 &= \frac{2 \times 0,3}{0,15 - 0,12} \quad \text{or} \quad VR = \frac{600}{30} && \\
 &= 20 : 1 && \checkmark
 \end{aligned}$$

(2)

2.5.3 Calculate the mechanical efficiency of the system:

$$\begin{aligned}
 \eta &= \frac{MA}{VR} \times 100 && \\
 &= \frac{18}{20} \times 100 && \checkmark \\
 &= 90\% && \checkmark
 \end{aligned}$$

(2)

2.6 CLUTCH**2.6.1 Calculate the torque transmitted by the clutch:**

$$\begin{aligned} T &= \mu W n R && \checkmark \\ &= 0,4 \times 3 \times 10^3 \times 2 \times \left(\frac{0,25}{2} \right) && \checkmark \\ &= 300 Nm && \checkmark \quad (3) \end{aligned}$$

2.6.2 Calculate the power transmitted:

$$\begin{aligned} P &= \frac{2 \pi N T}{60} && \checkmark \\ &= \frac{2 \pi \times 3000 \times 300}{60} \\ &= 94,247 \times 10^3 W \quad \text{or} \quad 94247,78 \text{ Watt} \\ &= 94,25 kW && \checkmark \quad (2) \end{aligned}$$

[50]

QUESTION 3: TOOLS AND EQUIPMENT

3.1 **VOLTMETER** is connected in parallel with a circuit. ✓
AMMETER is connected in series with a circuit. ✓ (2)

3.2 Metal Arc Gas Shielded/Metal Inert Gas Shielded ✓✓ (2)

3.3 **USES OF A MULTI-METER:**

- Direct current measurement (DC) ✓
- Alternating current measurement (AC) ✓
- Diode and continuity measurement ✓
- Battery measurement ✓
- Resistance measurement ✓
- Temperature measurement ✓
- Transistor test ✓
- Direct current voltage measurement ✓

(Any 2 x 1)

3.4 **COMPRESSION TEST**

3.4.1 **Reasons for compression test:**

- **Valve clearances** ✓
- Leaking exhaust valve ✓
- Leaking cylinder head gasket ✓
- Worn rings ✓
- Worn cylinders ✓
- Worn piston ✓
- Leaking inlet valve. ✓
- **Loose cylinder head bolt**
- **Cracked cylinder head**
- **Cracked piston**

(Any 4 x 1)

3.4.2 **Dry compression test:**

- Run engine until normal operating temperature is reached. ✓✓
- Air cleaner to be removed and jam the choke and throttle valve in the open position, to allow maximum air to enter the combustion chamber. ✓✓
- Disconnect the primary coil lead to prevent spark. ✓
- Clean area around spark plug and the screw the pressure gauge into the spark plug hole. ✓✓
- Crank the engine until the gauge stops rising. ✓
- Test all the cylinders and compare the readings to the manufacturer's specifications. ✓✓ (10)

[20]

QUESTION 4: MATERIALS

4.1 PROPERTIES OF STAINLESS STEEL:

- It has a shiny appearance due to chromium oxide film applied to the surface √
- It has good resistance to corrosion due to a high chrome content. √ (2)

4.2 SCREW DRIVER:

Reason: The material is too brittle. √

Support: A brittle material is the one that fractures with little or no deformation √ (2)

4.3 HAMMER:

Material B is the toughest. √√

Reason: Toughness is measured by the amount of energy needed to break the material. The higher the swing height of the hammer the higher the toughness of the material. √√ (4)

4.4 ELECTRICAL CABLE:

Polyvinylchloride (PVC) and Polythene (Polyethylene) √√

Reasons: They soften on heating and can be moulded into shape. √
On cooling they harden. √ (4)

4.5 NON-FERROUS ALLOYS:

A non-ferrous alloy is a metal that has a combination of two or more non-ferrous metals which are melted together to form one non-ferrous alloy. √

Example: Brass; Bronze; White metal; duralumin and solder (only one example) √ (2)

4.6

Process	Composition	Uses
Silver soldering	They are alloys of copper, zinc and silver, tin and lead √	They are used to produce strong ductile joints in copper, brass and in jewellery work √
Brazing	They make use of zinc copper alloys	They are used to produce strong ductile joints in ferrous metals. √

(4)

4.7 CARBON STEEL:

- Low carbon steel – 0,25% carbon or
 Medium carbon steel – 0,5 % carbon or
 High carbon steel – 1% carbon Select only ONE answer (2 x 1) (2)

[20]

QUESTION 5: SAFETY, TERMINOLOGY AND JOINING METHODS

5.1 BEAM BENDING TESTER:

- Make sure the object to be tested is firmly secured √
 - Make sure that all the holding devices are fitted properly √
 - Check components of a tester for wear √
 - Check for leaks at the hydraulic pump ram. √
 - Make sure the area around tester is clean and free from oil and grease √
- (Any 4 x 1) (4)

5.2 CENTRE LATHE:

- **Personal safety**
 - Do not operate the machine until you are certain you know the procedures √
 - Make sure that the machine is clean and safe to use √
 - Clamp work piece firmly/securely √
 - Choose the correct cutting tool and holding device for the job √
 - Make sure that all guards are in place before you operate the machine √
 - Remove the chuck key from the chuck before starting the machine √
 - Make sure the area around the lathe is free from oil, grease and any scrap metal. √
- (Any 4 x 1) (4)

5.3 OIL AND GREASE are highly flammable under high pressure in the presence of oxygen. √
√ (2)

5.4 METHODS OF INDEXING:

- Direct indexing/Rapid indexing √
 - Simple indexing √
 - Angular indexing √
 - Differential indexing √
- (4)

5.5 FEED IN MILLIMETRE PER MINUTE:

$$\begin{aligned}
 D &= \frac{100}{1000} && \checkmark \\
 &= 0,1m && \\
 v &= \pi DN && \\
 N &= \frac{v}{\pi D} && \checkmark \\
 &= \frac{40}{\pi \times 0,1} && \checkmark \\
 &= 127,32 \text{ r/min} && \checkmark \\
 \text{feed} &= f_1 \times T \times N && \checkmark \\
 &= 0,09 \times 24 \times 127,32 && \\
 &= 275,01 \text{ mm/min} && \checkmark \quad (6)
 \end{aligned}$$

5.6 GEARS**5.6.1 Calculate the module of the small gear:**

$$\begin{aligned}
 m &= \frac{PCD}{T} && \\
 &= \frac{48,75}{39} && \checkmark \\
 &= 1,25 \text{ mm} && \checkmark \quad (2)
 \end{aligned}$$

5.6.2 Calculate the outside diameter of the big gear:

$$\begin{aligned}
 \text{Outside diameter} &= m(T + 2) && \checkmark \\
 &= 1,25(63 + 2) \text{ or } && \checkmark \quad (2) \\
 &= 81,25 \text{ mm} && \\
 OD &= PCD + 2m && \\
 &= m \times T + 2m && \\
 &= 1,25 \times 63 + 2,5 && \\
 &= 78,75 + 2,5 && \\
 &= 81,25 \text{ mm} &&
 \end{aligned}$$

5.6.3 Calculate the PCD of the big gear:

$$\begin{aligned}
 PCD &= m \times T && \checkmark \\
 &= 1,25 \times 63 && \checkmark \\
 &= 78,75 \text{ mm} && \quad (2)
 \end{aligned}$$

5.6.4 Calculate the dedendum of the big gear:

$$\begin{aligned}
 \text{Dedendum} &= 1,157 \times m \\
 &= 1,157 \times 1,25 \\
 &= 1,446 \text{ mm} \\
 &= 1,45 \text{ mm}
 \end{aligned}$$

√
√ (2)

OR

$$\begin{aligned}
 \text{Dedendum} &= 1,25 \times m \\
 &= 1,25 \times 1,25 \\
 &= 1,56 \text{ mm}
 \end{aligned}$$

OR
√
√ (2)

5.6.5 The centre distance Y

$$\begin{aligned}
 \text{Distance } Y &= \frac{\text{PCD big gear} + \text{PCD small gear}}{2} \\
 &= \frac{78,75 + 48,75}{2} \\
 &= 63,75 \text{ mm}
 \end{aligned}$$

√
√
√ (3)

5.7 WELDING DEFECTS

5.7.1 Cracks:

Causes:

- Atmospheric pollution
 - Wrong welding technique
 - Dirty or wet electrodes / corroded MIG wire
 - Wrong electrode
 - Stressed weld
 - Faulty weld joint preparation
 - Cooling rate too fast
 - Craters present
- √
√
√
√
√
√
√
√
(Any 2 x 1) (2)

Corrective measures:

- Use low hydrogen electrode.
 - Increase the temperature of the parts to be welded.
 - Fill craters with welding material.
 - Use the correct welding current settings.
- √
√
√
√
(Any 1 x 1) (1)

5.7.2 **Slag inclusion:**

Causes:

- Rapid chilling √
 - Repeating a weld without removing the previous slag √
 - Weld temperature is too low √
 - High viscosity of the molten metal √
 - Included angle is too small √
- (Any 2 x 1) (2)

Corrective measures:

- Remove slag from the previous weld run. √
 - Increase the preparation angle. √
- (Any 1 x 1) (1)

5.8 **NON-DESTRUCTIVE TESTS:**

- Liquid dye penetrant √
 - Ultrasonic √
 - X-ray √
 - Sound test √
 - Hardness test √
 - Visual inspection √
- (Any 3 x 1) (3)

5.9 **INDEXING**

5.9.1 **Calculate the required indexing:**

$$\begin{aligned}
 \text{Indexing} &= \frac{40}{n} \\
 &= \frac{40}{60} && \sqrt{} \\
 &= \frac{2}{3} \\
 &= \frac{2}{3} \times \frac{8}{8} && \sqrt{} \\
 &= \frac{16}{24} \\
 \text{No full turns, and 16 holes on the 24 hole circle} &&& \sqrt{\sqrt{}} \quad (4)
 \end{aligned}$$

Other hole circles can also be allowed

5.9.2 Calculate the required change gears:

$$\begin{aligned} \frac{Dr}{Dv} &= (A-n) \times \frac{40}{A} \\ &= (60-63) \times \frac{40}{60} & \text{OR } &= \frac{-120}{60} \\ &= -\frac{3 \times 2}{3} & &= \frac{-2}{1} & \checkmark \\ &= \frac{-2}{1} \times \frac{24}{24} & &= \frac{-2}{1} \times \frac{24}{24} & \checkmark \\ &= \frac{-48}{24} & &= \frac{-48}{24} \\ & \text{Drive gears has 48 teeth and Driven gear has 24} & & & \checkmark\checkmark \quad (4) \end{aligned}$$

5.9.3 Direction of rotation of the index plate in relation to the index crank:

The index plate rotates in the opposite direction of the crank. (- sign) $\checkmark\checkmark$ (2)

Anti clockwise or left

[50]

QUESTION 6: MAINTENANCE AND TURBINES

6.1 CUTTING FLUIDS:

- Carry away the heat generated by machining process. ✓
 - Acts as a lubricant. ✓
 - Prevents the chips/swarf from sticking and fusing to the cutter teeth. ✓
 - Improve quality of the finish of machine surface. ✓
 - To keep the cutting tool cool. ✓
 - To obtain a higher cutting speed. ✓
 - It gives the cutting tool a longer lifespan. ✓
 - Does not rust the machine. ✓
 - Helps to wash away the chips/swarf of the metal being removed from the work piece, thus keeping the cutting edge of the cutting tool clean. ✓
- (Any 4 x 1) (4)

6.2 VEHICLE SERVICE

6.2.1 Functions of an oil:

- It lubricates ✓
 - Provide cooling and control temperature ✓
 - It acts as a seal ✓
 - Reduce engine noise ✓
 - Prolong engine life ✓
 - It absorbs shocks and vibrations ✓
 - Cleans the inside of the engine ✓
- (Any 3 x 1) (3)

6.2.2 Draining and filling oil for differential unit:

- Run the vehicle so that the rear axle oil is warm, so that it drains easily. ✓
 - Keep a drain tray that can hold all the oil at hand. ✓
 - Clean area around the drain and filler plug. ✓
 - Remove filler plug this will allow the oil to flow easily and fast. ✓
 - Remove the drain plug using a correct spanner and allow oil to drain into the tray. ✓
 - Allow all the oil to drain out. ✓
 - Wash the drain and filler plug. ✓
 - Fit new washers to both the drain and filler plugs. ✓
 - Replace the drain plug. ✓
 - Fill oil using oil from a plastic dispenser. ✓
 - Fill the oil until the oil just trickles out of the filler hole. ✓
 - Do not overfill the rear axle because this can cause the side shaft seals to fail ✓
 - Replace filler plug and wipe off surplus oil ✓
- (13)

6.3 BLOWER

6.3.1 Centrifugal blower √ (1)

6.3.2 Components

- 1. Air inlet √
- 2. Air outlet √
- 3. Impeller √
- 4. Fins √ (4)

6.3.3 Operation:

- This blower can be driven mechanically by means of a belt drive from the crank shaft or by means of exhaust gases moving through to the exhaust manifold √
- The shaped fins on the impeller move the air around to the outer edge of the impeller into the housing. √
- In doing so, the moving fins leave a low pressure behind it. √
- Air, under atmospheric pressure, rushes in to fill the low pressure at the centre of the impeller. √
- The impeller rotates so fast that a continuous movement of air is present which now builds up a pressure as it is thrown at the rim of the edge. √ (5)

6.4 SUPER CHARGER

6.4.1 Advantages of a supercharger:

- More power is obtained compared to an engine with a similar capacity without a supercharger √
 - Supercharged engines are more economical per given kilowatt output. √
 - Less fuel is used compared to engine mass. √
 - Power loss is eliminated above sea level. √
- (Any 3 x 1) (3)

6.4.2 **Disadvantages of a supercharger:**

- A small amount of power is lost in order to drive the supercharger because it uses the engine power to drive it ✓
- Higher fuel consumption if the power generated is not fully used, as in the case of passenger vehicles ✓
- Due to the compression of the air this results in an increase in air temperature causing a decrease in the density of the inlet charge. ✓
- The lifespan of the engine is decreased because of higher cylinder pressure, which increases the load on the engine components. ✓

(Any 3 x 1) (3)

6.5 **FUNCTION OF STEAM TURBINE:**

- Steam turbines are operated by using steam that generates kinetic energy ✓
- This generates rotational motion which is mechanical energy. ✓ (2)

6.6 **TURBINE USES:**

- To power generators which generate large amounts of electricity. ✓
- To power ship propulsion. ✓ (2)

[40]

TOTAL: 200