

SYNTec

Mill Machine Program Manual

By: SYNTec

Date: 2010/7/15

Version: 8.13

版本更新記錄

項次	更改內容紀錄	更改日期	作者	更改後版本
01	初版定稿	2001/07/01		V8.6
02	修正 G87 規格說明	2006/04/21	賴春億	V8.7
03	修正 G84 規格說明	2006/05/09	林昀暉	V8.8
04	修正 G73~G89 Z,R 引數規格說明	2006/05/25	賴春億	V8.9
05	修正 G65 G66 G67 規格說明	2006/07/18	賴春億	V8.10
06	修正 G50 G51 範例 修正 Page59 說明----重覆次數引數 L 為 K	2006/10/12	賴春億	V8.11
07	新增 G05, G06.2 規格說明	2008/11/17	王芝峰	V8.12
08	修改圖片 並與中文手冊同步	2010/4/20	陳弘真	V8.13

Contents

1	G Function Description.....	1
1.1	G code list	1
1.2	G code description.....	3
1.2.1	G00: POSITIONING	3
1.2.2	G01: LINEAR INTERPOLATION.....	4
1.2.3	G02/G03: CIRCULAR INTERPOLATION.....	6
1.2.4	G02/G03: HELICAL INTERPOLATION.....	10
1.2.5	G04: Dwell.....	12
1.2.6	G05: High Speed & High Precision Interpolation.....	13
1.2.7	G09/G61: EXACT STOP	15
1.2.8	G10: PROGRAMMABLE DATA INPUT	16
1.2.9	G15/G16 POLAR COORDICATES COMMAND MODE	17
1.2.10	G17/G18/G19: PLANE SELECTION.....	21
1.2.11	G28: RETURE TO REFERENCE POSITION.....	22
1.2.12	G29: RETURE FROM REFERENCE POSITION	23
1.2.13	G30: 2 nd , 3 rd and 4 th REFERENCE POSTION RETURE	24
1.2.14	G31: SKIP FUNCTION.....	25
1.2.15	G33: THREAD INTERPOLATION	27
1.2.16	G40/G41/G42: CUTTER COMPENSTAION	29
1.2.17	G43/G44/G49: TOOL LENGTH COMPENSATION	36
1.2.18	G51/G50: SCALING	39
1.2.19	G51.1/G50.1: PROGRAMMABLE MIRROR IMAGE.....	41
1.2.20	G52: LOCAL COORDINATE SYSTEM	45
1.2.21	G53: MACHINE COORDICATE SYSTEM SELECTION.....	48
1.2.22	G54...G59.9: WORKPIECE COORDICATE SELECTION	50
1.2.23	G64: CUTTING MODE	52
1.2.24	G65: SIMPLE CALL.....	53
1.2.25	G66/G67: MACRO CALL.....	54
1.2.26	G68/G69: COORDINATE ROTATION	55
1.2.27	G70/G71: UNIT SETTING OF INCH/METRIC SYSTEM.....	58
1.2.28	Cycle perform function:	59
1.2.29	G73: HIGH SPEED PECK DRILL CYCLE	61
1.2.30	G74: LEFT HAND TAPING CYCLE	63
1.2.31	G76: FINE BORING CYCLE.....	65
1.2.32	G81: DRILLING CYCLE.....	68

1.2.33	G82: DRILLING CYCLE OF DWELL ON THE HOLE BOTTOM	70
1.2.34	G83: PECK DRILL CYCLE.....	72
1.2.35	G84: TAPPING DRILLING CYCLE	74
1.2.36	G85: DRILLING CYCLE.....	78
1.2.37	G86: HIGH SPEED DRILLING CYCLE	80
1.2.38	G87: FINE BORING CYCLE OF BACK SIDE.....	82
1.2.39	G88: FINE BORING CYCLE OF HALF AUTOMATION.....	85
1.2.40	G89: BORING CYCLE OF DWELL ON THE HOLE BOTTOM 87	
1.2.41	G90/G91: ABSOLUTE/INCREMENT COMMEND	89
1.2.42	G92: SETTING OF WORK COORDINATE SYSTEM.....	90
1.2.43	G94/G95: FEED UNIT SETTING	91
1.2.44	G96/G97: CONSTANT LINEAR VELOCITY CONTROL ON SURFACE	92
1.2.45	G134: CIRCUMFERENCE HOLE CYCLE	93
1.2.46	G135: ANGULAR STRAIGHT HOLE CYCLE	94
1.2.47	G136: ARC TYPE HOLE CYCLE	95
1.2.48	G137.1: CHESS TYPE HOLE CYCLE	96
1.2.49	Tool Function: T Code Command.....	97
1.2.50	Spindle Speed Function: S Code Command	97
1.2.51	Feed Function: F Code Command.....	97
2	M Code Description:.....	98

1 G Function Description

1.1 G code list

G code	Function	PS.	Item	Function name	PS.
G00	Positioning		G64	Cutting mode	
G01	Linear interpolation		G65	Marco call	※
G02	Circular interpolation /Helical interpolation (CW)		G66	Marco modal call	※
G03	Circular interpolation /Helical interpolation (CCW)		G67	Marco modal call cancel	※
G04	Dwell ,exact stop		G68	Coordinate rotation	
G05	High speed and high precision interpolation		G69	Coordinate rotation cancel	
G09	Exact stop		G70	Inch perform	
G10	Programmable data input		G71	Mm perform	
G15	Polar coordinates command cancel		G73	Peck drilling cycle	
G16	Polar coordinates command		G74	Counter tapping cycle	
G17	X-Y plane selection		G76	Fine boring cycle	
G18	Z-X plane selection		G80	Canned cycle cancel	
G19	Y-Z plane selection		G81	Drilling cycle	
G28	Return to reference position		G82	Drilling cycle of dwell on the hole bottom	
G29	Return from reference position		G83	Peck drilling cycle	
G30	2 nd ,3 rd and 4 th reference position return		G84	Tapping cycle	
G31	Skip function		G85	Drilling cycle	
G33	Thread cutting		G86	High speed drilling cycle	
G40	Cutter compensation cancel		G87	Fine boring cycle of back side	
G41	Cutter compensation left		G88	Fine boring cycle of half automation	
G42	Cutter compensation right		G89	Boring cycle of dwell on the hole bottom	
G43	Tool length compensation + direction		G90	Absolute command	
G44	Tool length compensation - direction		G91	Increment command	
G49	Tool length compensation cancel		G92	Setting of work coordinate system	
G50	Scaling		G94	Feed per minute(mm/min.)	

G51	Scaling cancel		G95	Feed per rotation (mm/rev.)	
G50.1	Programmable mirror image cancel		G96	Constant linear velocity control on surface	
G51.1	Programmable mirror image		G97	Constant linear velocity control on surface cancel	
G52	Local coordinate system setting		G98	Return to initial point in canned cycle	
G53	Machine coordinate system setting		G99	Return to R point in canned cycle	
G54	Workpiece coordinate system 1 selection		G134	Circumference hole cycle	
G59	Workpiece coordinate system 6 selection		G135	Angular straight hole cycle	
G61	Exact stop mode		G136	Arc type hole cycle	
			G137.1	Chess type hole cycle	

- SYNTEC 900M G code uses RS274D standards, and the only differences with FANUC 0M are G70, G71 respective to G20, G21.

1.2 G code description

1.2.1 G00: POSITIONING

Command form:

G00 X____Y____Z____ ;


X、Y、Z: Specified point

Description:

each axles move to appointed point in no interpolation status, X、Y、Z is the final position, use G90/G91 to design absolute or increment value.

<Notice>: the movement mode can decide by parameter #411
(0: linear, 1: each axle move in max speed independently)

PIC:



Program description:

1. first way(absolute): G90 G00 X90.0 Y40.0 ;

//use difference value between appointed point and zero point to do straight interpolation to appointed point

2. second way(increment): G91 G00 X70.0 Y20.0 ;

// use difference value between appointed point and initial point to do straight interpolation to appointed point

1.2.2 G01: LINEAR INTERPOLATION

Command form:

G01 X__Y__Z__ F__ ;


X、Y、Z: Specified point

F: Speed of tool feed (feed rate) (mm/min)

Description:


G01 do straight interpolation, and it depends on working program, it can use G90/G91 to decide absolute or increment mode, use the speed of tool feed that "F" provide, to appointed position.

Example 1:



1. absolute command: G90 G01 X90.0 Y40.0 ;
//do linear interpolation from zero point to the specified point(90,40)
2. increment command: G91 G01 X70.0 Y20.0 ;
// the tool does linear interpolation X + 70 and Y + 20 to specified point

Example 2: processing example



Program description:

1. absolute way:

```
N001 G00 X0.0 Y0.0 Z10.0 ; //positioning to above of P0
N002 G90 G01 Z-10.0 F1000 ; //straight interpolation to bottom of
workpiece, speed 1000mm/min
N003 Y38.0 ; //P0 → P1
N004 X20.0 Y45.0 ; //P1 → P2
N005 X55.0 ; //P2 → P3
N006 Y10.0 ; //P3 → P4
N007 X45.0 Y0.0 ; //P4 → P5
N008 X0.0 ; //P5 → P0
N009 G00 Z10.0 ; //positioning back to above of P0
N010 M30 ; //program end
```

2. increment way

```
N001 G00 X0.0 Y0.0 Z10.0 ; //positioning to above of P0
N002 G91 G01 Z-20.0 F1000 ; //straight interpolation to bottom of
workpiece, speed 1000mm/min
N003 Y38.0 ; //P0 → P1
N004 X20.0 Y7.0 ; //P1 → P2
N005 X35.0 ; //P2 → P3
N006 Y-35.0 ; //P3 → P4
N007 X-10.0 Y-10.0 ; //P4 → P5
N008 X-45.0 ; //P5 → P0
N009 G00 Z20.0 ; //positioning back to above of P0
N011 M30 ; //program end
```

1.2.3 G02/G03: CIRCULAR INTERPOLATION

Command form:

1. X-Y plane circular interpolation:

$$G17 \left\{ \begin{array}{l} G02 \\ G03 \end{array} \right\} X - Y - \left\{ \begin{array}{l} R - \\ I - J - \end{array} \right\} F - ;$$

2. Z-X plane circular interpolation:

$$G18 \left\{ \begin{array}{l} G02 \\ G03 \end{array} \right\} X - Z - \left\{ \begin{array}{l} R - \\ I - K - \end{array} \right\} F - ;$$

3. Z-X plane circular interpolation

$$G19 \left\{ \begin{array}{l} G02 \\ G03 \end{array} \right\} Y - Z - \left\{ \begin{array}{l} R - \\ J - K - \end{array} \right\} F - ;$$

X, Y, Z: Specified point

I, J, K: the vector value that starting point of arc to the center of a circle(center of a circle—starting point)

R: Radius of arc

F: Feed rate

G90/G91 decide absolute or increment


Description:

G02、G03 do circular interpolation according to appointed plane、coordinate system、size of arc and speed of interpolation, and the rotate direction decide by G02(CW)、G03(CCW). Description of the command format as below:


Setting Data		Command	Definition
1	Plane selection	G17	X-Y plane setting
		G18	X-Z plane setting
		G19	Y-Z plane setting
2	Direction	G02	Clockwise direction (CW)
		G03	Counterclockwise direction (CCW)
3	End position	G90	Two axes of X, Y, Z
		G91	Two axes of X, Y, Z Vector value from start point to end point
4	Distance from start point to center of circle	Two axes of I, J, K	Vector value from start of arc to center of circle
	Radius of arc	R	Radius of arc
5	Speed of feed (feedrate)	F	Feedrate along the arc

Example:

1. G02, G03 direction



2. I, J, K definition:



3. how to use R:


- ◆ When $\theta \leq 180$ degree, R is positive.

$$\left\{ \begin{array}{l} G 02 \\ G 03 \end{array} \right\} X - Y - R 25 .0;$$


- ◆ When $180 \text{ degree} < \theta < 360$ degree, R is negative.

$$\left\{ \begin{array}{l} G 02 \\ G 03 \end{array} \right\} X - Y - R - 25 .0;$$

- ◆ When $\theta = 360$ degree, only use **I**、**J**、**K**.



Program example 1:




```

G90 G00 X5500 Y4000;//positioning to start point of arc
G17 G90 G03 X1500 Y4000 I-3000 J-1000 F200;
//absolute command
(G17 G91 G03 X-4000 Y2000 I-3000 J-1000 F200;
//increment command)

```

Program example 2: (interpolate a full circle)



G90 G00 X0 Y0;
G02 I1000 F100; //interpolate a full circle

1.2.4 G02/G03: HELICAL INTERPOLATION

Command form:

(1)

$$G17 \left\{ \begin{array}{l} G02 \\ G03 \end{array} \right\} X_ Y_ \left\{ \begin{array}{l} R_ \\ I_ J_ \end{array} \right\} Z_ F_-;$$

X, Y: end position of arc ;

Z: end position of straight line ;

R: radius of arc ;

I, J: center position of arc ;

F: speed of tool feed(feed rate) ;

(2)

$$G18 \left\{ \begin{array}{l} G02 \\ G03 \end{array} \right\} X_ Z_ \left\{ \begin{array}{l} R_ \\ I_ K_ \end{array} \right\} Y_ F_-;$$

X, Z: end position of arc ;

Y: end position of straight line ;

R: radius of arc ;

I, K: center position of arc ;

F: speed of tool feed(feed rate) ;

(3)

$$G19 \left\{ \begin{array}{l} G02 \\ G03 \end{array} \right\} Y_ Z_ \left\{ \begin{array}{l} R_ \\ J_ K_ \end{array} \right\} X_ F_-;$$

Y, Z: end position of arc ;

X: end position of straight line ;

R: radius of arc ;

J, K: center position of arc ;

F: speed of tool feed(feed rate) ;

Description:


When the 3rd axis which is vertical to arc plane moves, G02/G03 is to be helical interpolation. The choice of helical interpolation is the same as circular interpolation. Helical interpolation uses G code(G17/G18/G19) to decide which plane to do circular interpolation.

G17 form: synchronously with arc of X-Y plane.

G18 form: synchronously with arc of Z-X plane.

G19 form: synchronously with arc of Y-Z plane.

Example:



Program description:

G17 G03 X0.0 Y1000.0 R1000.0 Z900.0 F600 ;

// synchronously with arc of X-Y plane (CCW), do helical interpolation
with feedrate 600mm/min

1.2.5 G04: Dwell

Command form:

$$G\ 04 \left\{ \begin{array}{c} X \ - \\ P \ - \end{array} \right\} ;$$

X: specific time (decimal point permitted 0.001~9999.999s)

P: specific time (decimal point not permitted)

Description:

By specifying a dwell, the execution of the next block is delayed by the specified time. In addition, a dwell can be specified to make an exact check in the cutting mode.

Program example:

G04 X2500;//delay 2.5 sec

G04 X2.5;//delay 2.5 sec

G04 P2500;//delay 2.5 sec

G04 P2.5;//delay 2 sec (decimal point not permitted)

1.2.6 G05: High Speed & High Precision Interpolation

Command form:

```
G05 P { 10000 }
      |   |
      |   1
      |   |
      |   2
      |   |
      |   3
      |   |
      |   4
      |   |
      |   5
      } ; // Start HSHP interpolation
```

```
G01 X__Y__Z__F__;
G02 X__Y__Z__R__;
G00 X__Y__Z__;
```

```
G05 P0; // Cancel HSHP interpolation
```

P: Multiple motion parameters

X, Y, Z: Specific coordinate point

F: Max feedrate (mm/min)


Description:

G05 provides one default parameter, P10000, and five other parameters, P1~P5, for users. Interpolation commands execute the mode of smoothing curve by processing program. G90/G91 decides absolute or increment mode. Feedrate is decided by F code for high speed & high precision interpolation.

Condition:

- On high speed & high precision interpolation (G05 P__) mode, M code and MPG simulation of negative direction are invalid.
- On high speed & high precision interpolation (G05 P__) mode, if cutter compensation(G40/G41/G42) and tool length compensation (G43/G44/G49) are used, the program can cancel G05 mode until G40/G41/G42 or G43/G44/G49 ending. It is not recommended to do that unless necessary.

Example:



G0 X3. Y4. Z0.

G05 P10000 //Start high speed & high precision interpolation

G01 X3.8 Y6.1 F5000.

X4.6 Y7.

X5.4 Y6.1

X6.1 Y4.

X6.9 Y1.9

X7.7 Y1.

X8.5 Y1.9

X9.3 Y4.

X10. Y6.1

G05 P0 // Cancel high speed & high precision interpolation

M30

1.2.7 G09/G61: EXACT STOP

Command form:

G09 X__ Y__ Z__ ;
G61 ;

X, Y, Z: position of exact stop

Description:


when cut the corner, because tool moves too fast or servo system delays, tool can not cut the exact shape of corner, but when you need to cut high precision rectangular, you can use G09 or G61 to make it, it slow down the tool when approach to corner, when reach to the specified position (in CNC parameter range), it will run the next block. G09 exact stop only effected in one block which has G09; G61 exact stop effected each cutting command (G01~G03) after G61, until G62 or G63 or G64 is specified.

Notice:

G01 check window: parameter 421-440

G00 check window: parameter 461-480

Example:



1.2.8 G10: PROGRAMMABLE DATA INPUT

Command form:

$$G10 \left\{ \begin{array}{l} L10 \\ L11 \\ L12 \\ L13 \end{array} \right\} P _ R _ ;$$

L10: for tool length(H) geometric compensation value

L11: for tool length(H) wear compensation value

L12: for tool diameter(D) geometric compensation value

L13: for tool diameter(D) wear compensation value

P: tool NO.


R: compensation value(data of tool length or tool diameter)

Description:

G10 command: it can directly use program command to enter tool compensation value.

In absolute mode (G90), value of G10 is the new compensation value; in increment mode (G91), value of G10 is the sum of the value of the moment with the new compensation value.

Example:



1.2.9 G15/G16 POLAR COORDINATES COMMAND MODE

Command form:

```
G 16 ;           //Start   polar   coordinate   mode
G __ X __ Y __
:
G 15 ;           //Cancel   polar   coordinate   command
```

} //Polar coordinate command

X: polar coordinate radius


Y: polar coordinate angle(“+” for CW, ”−” for CCW)

Description:


start polar coordinate mode in first line, G16 for polar coordinate command start, G15 for polar coordinate command cancel, it can use polar coordinate mode to enter position(radius and angle), G90/G91 can specify in it. First address is radius, second address is angle. Absolute or increment is decided by G90 or G91, G90 is absolute, G91 is increment, in absolute mode, the increase of radius or angle from origin point; in increment mode, angle or radius total from the last radius or angle.

Example:

1. when polar coordinate zero point is the same as working coordinate




- a. When angle is specified with an absolute command




- b. when angle is specified with an increment command

2. when polar coordinate zero point is in normal position




- a. When angle is specified with an absolute command



- b. when angle is specified with an increment command

Program example:



1. Absolute command:

```
N001 T1 S1000 M03 ;
//NO.1 tool(diameter 10 mm drill), spindle 1000rpm (CW)
N002 G17 G90 G16 ;
//X-Y plane, absolute mode, start polar coordinate mode
N003 G99 G81 Z-12.0 R2.0 F600 K0 ;
//do drilling cycle, depth 12mm, feedrate 600mm/min, back to R point
when finish
N004 X100.0 Y90.0 ;
//specified a distance 100mm, angle 90 degree(first hole)
N005 Y210.0 ;
//specified a distance 100mm and angle 210 degree, from the origin
point(second hole)
N006 Y330.0 ;
//specified a distance 100mm and angle 330 degree, from the origin
point(third hole)
N007 G15 G80 M05 ;
//polar coordinate mode cancel, cycle cancel, spindle stop
N008 M30 ; //program end
```

2. Increment command:

```
N001 T1 S1000 M03 ;
// NO.1 tool(diameter 10 mm drill), spindle 1000rpm (CW)
N002 G17 G90 G16 ;
// X-Y plane, absolute mode, start polar coordinate mode
N003 G99 G81 Z-12.0 R2.0 F600 K0 ;
// do drilling cycle, depth 12mm, feedrate 600mm/min, back to R point
when finish
N004 X100.0 Y90.0 ;
//specified a distance 100mm, angle 90 degree(first hole)
```

```
N005 G91 Y120.0 K2 ;
//increment command, angle totals 120 degree from last point (second
hole)
N006 Y120.0 ;
//increment command, angle totals 120 degree from last point (third
hole)
N007 G15 G80 M05 ;
// polar coordinate mode cancel, cycle cancel, spindle stop
N008 M30 ; //program end
```

1.2.10 G17/G18/G19: PLANE SELECTION

Command form:

G17; X-Y plane selection



G18; Z-X plane selection

G19; Y-Z plane selection

Description:

when use circular interpolation, tool radius compensation or polar coordinate command, need to use G17, G18, or G19 to set cutting plane and tell controller the working plane(default G17).

Example:



1.2.11 G28: RETURE TO REFERENCE POSITION

Command form:
G28 X__Y__Z__ ;

X, Y, Z: mid-point position (absolute value in G90 mode, increment value in G91 mode)


Description:

it can return to reference position or return to origin point, in order not to let the tool crush, it will use G00 mode to move from present position, it will move to the specified safety mid-point first and then return to origin point or reference point.

<Note> this command usually use in auto tool exchange. For safety, before doing G28, must cancel tool compensation

Example 1:

G90 **G28 X50.0 Y30.0;** //A→B→C, mid-point(50,30)



Example 2:

G28 X0; //only X axis return to reference point

G28 Y0; //only Y axis return to reference point

G28 Z0; //only Z axis return to reference point

1.2.12 G29: RETURE FROM REFERENCE POSITION

Command form:
G29 X__Y__Z__;


X, Y, Z: specified coordinate ; (absolute value in G90 mode, increment value in G91 mode)

Description:

G29 can let tool from reference point through mid-point to specified point after setting G28. Notice that G29 can not use alone, because G29 does not specify mid-point, G29 use the mid-point from G28, therefore, before do G29 must do G28 first.

Under G90, the specified point is the absolute coordinate; under G91, it is the increment distance from mid-point to specified point.

Example:



1. Absolute command:

N001 G90 G28 X20.0 Y30.0;
//A→B→C, mid-point(20,40), in absolute command mode
N002 M06;//change the tool
N003 **G29** X40.0 Y0.0;
// C→B→D, the specified point is absolute coordinate

2. Increment command:

N001 G91 G28 X20.0 Y40.0;
//A→B→C, mid-point(20,40), in increment command mode
N002 M06;//change the tool
N003 **G29** X40.0 Y-40.0;
//C→B→D, the specified position is the increment value from mid-point to specified point

1.2.13 G30: 2nd, 3rd and 4th REFERENCE POSITION RETURE

Command form:

G30 Pn X__ Y__ Z__ ;

X、Y、Z: mid-point coordinates ; (absolute value under G90, increment value under G91)

Pn: Specified reference point(parameter #2801 ~ #2860)

P1: mechanical origin point ;

P2: second reference point ;


P_: default is P2 ;

Description:

for the convenience that change tool and check, we use parameter to set a reference point to suitable position, it can let tool need not return to mechanical zero point, increase efficiency in changing the tool, the usage of this command is the same as G28 only expect returned point. Floating reference position return command, usually use in the position of automatically change the tool differ from the origin point. Movement mode G00.

<Notice> usually this command use in automatically change the tool, for safety, before do G30, need to cancel the tool compensation function.

Example:



Program description: presume tool is in A (60,10)

1. to second reference point

G30 P2 X75.0 Y25.0 ; //A→B→ 2nd reference point

2. to third reference point

G30 P3 X15.0 Y10.0 ; //A→C→ 3rd reference point

1.2.14 G31: SKIP FUNCTION


Command form:
G31 X__ Y__ Z__ F__;

X, Y, Z: specified point
F: feedrate

Description:

skip command use in a unknown program point, and it specify that point, when measurement runs into impede, when machine get skip signal, LADDER C BIT ON, G31 will record the present mechanical position and interrupt motion of G31, run next block.


Example 1: incremental command(G91)



Program description:

```
N001 G31 G91 X100.0 F100; //original motion until run into impede
N002 Y100.0; //use contact point to be opposite coordinate, change
path to specified position, it does not wait to the finished of front block
```


Example 2: absolute command for 1 axes(G90)



Program description:

```
N001 G31 G90 X200.0 F100; //original path until running into impede
N002 X200.0 Y100.0; //use zero point to be the relative coordinate to
change the path to the specified position, and it does not wait to the
finished of front block.
```

Example 3: absolute command for 2 axes(G90)



Program description:

```
N001 G31 G90 X100.0 F1000; // original path until running into
impede
N002 X130.0 Y70.0; // use zero point to be opposite coordinate to
change the path to specify position, it does not wait to the finished of
front block
```

1.2.15 G33: THREAD INTERPOLATION

Command form:
G33 Z__ F__ ;

Z: Absolute command (G90), coordinates of Z axis for end point;
Incremental command (G91), for length of thread in axis direction;
F: the thread of a screw (0.01mm);

Description:

When spindle turned, tool feeds in Z axis direction at the same time.
After repeating many times, there is inertia lag of the spindle rotation at
thread interpolation finishing. They will produce somewhat incorrect leads
at start and end points of a thread cut. In order to compensate this, thread
cutting length should be specified longer than required, in thread
interpolation, limit of spindle speed(R) is:

$$1 \leq \text{spindle speed } (R) \leq \frac{\text{Max feedrate}}{\text{thread lead}}$$

R: spindle speed(rpm)

Thread lead(F): mm or inch


Feedrate: mm/min or inch/min

Notes:

Max feedrate can be setting by parameter #405.

Acceleration and deceleration time of thread interpolation can be
setting by parameter #409.

Example:



Program form:

G33 Z10.0 F1.5 ;

//thread cutting at a pitch of 1.5mm, the end is at Z axis 10mm

1.2.16 G40/G41/G42: CUTTER COMPENSTAION

Command form:

$$\left\{ \begin{array}{l} G\ 41 \\ G\ 42 \end{array} \right\} \ X\ _{-}\ Y\ _{-}\ Z\ _{;}$$

G40 ;

G41: cutter compensation left.

G42: cutter compensation right.

G40: cutter compensation cancel.

X, Y: end coordinate of each axis.


D: code for specifying as the cutter compensation value.

Description:


In general, when the tool is moved, if tool center is cutting along the workpiece, and the tool radius is overcut. In cutter compensation, the tool moved, the tool path can be shifted by the radius of tool. It can let the shape which is after process is equal with layout. Therefore we can enter the size of layout, and match this function, to get the right size of workpiece, we can ignore tool radius in the program.

Example:


1. Cutter compensation:




2. Direction decision of cutter compensation:




Compensation value	Positive	Negative
G41	Compensation left	Compensation right
G42	Compensation right	Compensation left




a. G41-outline cut (CW)



b. G41-inline cut (CCW)



c. G42-outline cut (CCW)




d. G42-inline cut (CW)


3. cutter compensation of corner interpolation:

- When the corner: $90^\circ \leq \alpha < 180^\circ$


i. straight line → straight line




ii. straight line → arc




iii. arc → straight line




iv. arc → arc




- When corner $\alpha < 90^\circ$
- v. straight line → straight line




- vi. straight line → arc



- vii. arc → straight line




viii. arc → arc



Notes:


when process a fillister, if the width less than twice of tool, than system will send the alarm because of over cutting.




if under MDI mode, can not use cutter compensation.

G41/G42 and G40 can not be used with G02 and G03 in the same block, only can use with G00 and G01 in the same block.

when processing the step shape workpiece, if the step higher than workpiece radius ,then system will send alarm because of over cutting.



Program example:



Program description:

```

N001 T1 S1000 M03 ; //tool NO.1(diameter 10mm), spindle 1000rpm
(CW)
N002 G00 X0.0 Y0.0 Z10.0 ; //positioning above programmed zero
point
N003 M08 ; //open cutting liquid
N004 G90 G01 Z-10.0 F600 ; //linear interpolation to bottom of
workpiece, feedrate 600mm/min
N005 G42 Y24.0 D01 ; //cutter compensation left, program zero
point→A
N006 G03 X9.0 Y30.0 R10.0 ; //A→B circular interpolation (CCW)
N007 G02 X30.0 Y9.0 R15.0 ; //B→C circular interpolation (CW)
N008 G03 X30.0 Y-9.0 R10.0 ; //C→D circular interpolation (CCW)
N009 G02 X9.0 Y-30.0 R15.0 ; //D→E circular interpolation (CW)
N010 G03 X-9.0 Y-30.0 R10.0 ; //E→F circular interpolation (CCW)
N011 G02 X-30.0 Y-9.0 R15.0 ; //F→G circular interpolation (CW)
N012 G03 X-30.0 Y9.0 R10.0 ; //G→H circular interpolation (CCW)
N013 G02 X-9.0 Y30.0 R15.0 ; //H→M circular interpolation (CW)
N014 G03 X0.0 Y24.0 R10.0 ; //M→A circular interpolation (CCW)
N015 G00 Z10.0 ; //Z axis rise, return to start point
N016 G40 X0.0 Y0.0 ; //cutter interpolation cancel, return to start
point
N017 M09 ; //cutting liquid OFF

```

N018 M05 ; //spindle stop
N019 M30 ; //program end

1.2.17 G43/G44/G49: TOOL LENGTH COMPENSATION

Command form:

$$\left\{ \begin{array}{l} G\ 43 \\ G\ 44 \end{array} \right\} \ Z\ _- \ H\ _- ;$$

G49 ;

G43: compensation along positive direction ;

G44: compensation along negative direction ;

G49: compensation cancel ;

Z: Z axis end coordinates ;

H: tool number ;

Description:

when use machine to process each workpieces, there are many tools that we use, and the length of each tool is different, during programming, after change the tool the difference between tool length will make Z axis direction have errors, tool length compensation(G43/G44) is used to Z axis position compensation and to correct the difference between tool length.

Compensation value setting:

(consult “milling machine controller manual”)


First way:

use manual that let the tool go down from machine zero point of Z axis until it touch the surface of workpiece, enter the distance to tool setup in operation interface and do this for each tools. Set the number of tool in H value of program command form.

Second way:



choose a tool to be basis, in system operation interface do tool length adjust in work coordinates setting to G54 system, after that we can use it to be the difference between tools of basis tool, we can convert length of compensation.

Example:



Compensation value	Positive	Negative
G43	Positive direction	Negative direction
G44	Negative direction	Positive direction

Example:



Program description:

```

T1 S1000 M03 ; //use tool NO.1(diameter 20mm), spindle
1000rpm(CW)
G42 D01 ; //tool radius compensation right(D01=10)
G00 X10.0 Y5.0 Z15.0 ; //positioning above A point
G43 H01 ; //tool length compensation positive(H01=-10)
G01 Z-10.0 ; //linear interpolation to bottom of A point
X110.0 ; //A→B
Y85.0 ; //B→C
X90.0 Y105.0 ; //C→D
X50.0 ; //D→E
G02 X10.0 Y65.0 R40.0 ; //E→F
G01 Y5.0 ; //F→A

```

```
G00 Z15.0 ; //positioning return above A point  
G40 G49 ; //compensation cancel  
M05 ; //spindle stop  
M30 ; //program end
```

1.2.18 G51/G50: SCALING

Command form:

$$X - Y - Z - \left\{ \begin{array}{l} I - J - K - \\ P - \end{array} \right.$$

X, Y, Z: center coordinate value of scaling ;


I, J, K: scaling magnification for X axis Y axis and Z axis respectively ;

P: scaling magnification for X axis Y axis and Z axis are the same magnification ;

Description: G51 let the tool path magnify and reduce at our own choose.

G50: scaling cancel.

Example:



Program description:

```

N001 G00 X50.0 Y50.0 ; //positioning
N002 G51 X125.0 Y90.0 P0.5 ; //decide center of scaling X125,Y90
scaling magnification value 0.5, do scaling to steps N003~N009
N003 G01 Y70.0 F1000 ; //linear interpolation, feedrate 1000mm/min
N004      X100.0 Y150.0 ;
N005 G03 X150.0 I25.0 ; //circular interpolation, radius 25mm ;
N006 G01 X200.0 Y70.0 ; // linear interpolation
N007      Y50.0 ;
N008      X50.0 ;
N009 G00 X0.0 Y0.0 ; //return

```

```
N010 G50 ; //scaling cancel  
N011 M30 ; //program end
```

1.2.19 G51.1/G50.1: PROGRAMMABLE MIRROR IMAGE

Command form:

G51.1 X__Y__Z__;

G50.1;//programmable mirror image cancel

X, Y, Z: mirror point (axis) coordinate value.

Description:

when cut symmetry shape, we only need one program between left side or right side, and use this function we can process another side. G51.1 specify point(position) and axis of symmetry for producing a mirror image

if there is only one axis specify mirror image on specified plane, circular 、 tool length compensation or the direction of coordinate rotation or direction of compensation, all of those execute reverse.


because of this function use in part coordinates, when counter reset or work coordinates change, center of mirror image is changed.


G28, G30 in programmable mirror image, before the mid-point , programmable mirror image is effective, after the mid-point, programmable mirror image is not execute.

execute G29 in programmable mirror image, that is effective to mirror image of mid-point.

Note:

Execute mirror image cancel out of the center point, absolute value can not match with mechanical position, as the below PIC (this status continues until executing G90 、 G28 or G30). If you specify the center of mirror image again in the absolute static status, it will be specified to a unable expect position. Please use absolute positioning after mirror image cancel.



Example 1:

Program description:


```

N001 T1 S1000 M03 ; //use tool NO. 1, 1000rpm(CW)
N002 M98 H100 ; //execute sub-program
N003 G51.1 X60.0 ; //execute programmable mirror image that
symmery axis X=60
N004 M98 H100 ; // execute sub-program
N005 G50.1 ; //programmable mirror image cancel
N006 G51.1 Y55.0 ; //execute programmable mirror image that
symmery axis Y=55
N007 M98 H100 ; // execute sub-program
N008 G50.1 ; // programmable mirror image cancel
N009 M05 ; //spindle stops
N010 M30 ; //program ends

N100 ; //sub-program list
G00 X60.0 Y55.0 ; //positioning to specified point
G01 Y75.0 ; //linear interpolation to O point
X80.0 ; //O→A
X120.0 ; //A→B
Y105.0 ; //B→C
X80.0 Y95.0 ; //C→D
Y75.0 ; //D→A
M99 ; //sub-program ends

```

Example 2: processing example



Program description: process a trough that flower shaped

```

N001 T1 S1000 M03 ; //tool No.1(diameter 10mm), 1000rpm(CW)
N002 G41 D01 ; //set cutter compensation left of tool No.1(D01 = 5)
N003 M98 H100 ; //execute sub-program
N004 G51.1 X0.0 ; //execute programmable mirror image at symmery
axis X=0
N005 M98 H100 ; //execute sub-program
N006 G50.1 ; //programmable mirror image cancel
N007 G51.1 X0.0 Y0.0 ; // execute programmable mirror image at
symmery point X=0, Y=0
N008 M98 H100 ; // execute sub-program
N009 G50.1 ; // programmable mirror image cancel
N010 G51.1 Y0.0 ; // execute programmable mirror image at symmery
axis Y=0
N011 M98 H100 ; // execute sub-program
N012 G50.1 ; // programmable mirror image cancel
N013 G40 ; //cutter compensation cancel
N014 M05 ; //spindle stops
N015 M30 ; //program ends

```

Sub-program

```

N100 ; sub-program list
G00 X58.0 Y0.0 Z10.0 ; //positioning to the above of starting position
G01 Z-10.0 ; //linear interpolation to bottom of workpiece
G03 X49.36 Y7.9744 R8.0 ;//circular interpolation(CCW), radius 8mm
G03 X40.5415 Y29.2641 R50.0 ;// circular interpolation(CCW), radius
50mm
G03 X29.2641 Y40.5415 R8.0 ; // circular interpolation(CCW), radius
8mm

```

```
G03 X7.9744 Y49.36 R50.0 ; // circular interpolation(CCW), radius  
50mm  
G03 X0.0 Y58.0 R8.0 ; // circular interpolation(CCW), radius 50mm  
G00 Z10.0 ; //positioning to above of end point  
M99 ; //sub-program end, continue to execute main program
```

1.2.20 G52: LOCAL COORDINATE SYSTEM

Command form:

G52 X__ Y__ Z__ ;


X、Y、Z: coordinate values


Description:

specify a work coordinate system(G54~G59), when workpiece need to set another coordinate system, that coordinate system is local coordinate system.

G52 X0.0 Y0.0 Z0.0: cancel the coordinate system

Coordinate system:



Example:**Program description:**

```

N001 T1 S1000 M03 ; //tool No.1(diameter 10mm), spindle 1000rpm
(CW)
N002 G54 X0.0 Y0.0 Z0.0 ; //specify work coordinate (G54)
N003 G00 X90.0 Y15.0 Z10.0 ; //positioning to above of specified
position
N004 G43 H01 ; //tool length compensation (tool No.1)
N005 G99 G81 Z-15.0 R2.0 F1000 ; //execute drilling cycle, stop at R
point when return, feedrate 1000mm/min, drill 1st hole
N006 X110.0 ; //drill 2nd hole
N007 X100.0 Y65.0 ; //drill 3rd hole
N008 G80 ; //cancel cycle
N009 M05 ; //spindle stops
N010 G28 X0.0 Y0.0 Z10.0 ; //reference point return, X0.0,Y0.0,Z10.0
to be center point
N011 T2 M06 S1000 M03 ; //execute tool exchange(tool No.2 diameter
10mm), after finishing, spindle start to turn, 1000rpm(CW)
N012 G52 X30.0 Y30.0 Z0.0 ; //specify local coordinate zero point to
the work coordinate (G54) of X40.0,Y40.0,Z0.0(geometry center of
workpiece)
N013 G00 X0.0 Y0.0 Z10.0 ; //positioning to local coordinate
X0.0,Y0.0,Z10.0(above the hole)
N014 G01 Z-12.0 ; //linear interpolation to bottom of the hole
N015 G17 G41 D02 ; //cutter compensation left (tool No.2)
N016 G91 X20.0 ; //specify to use increment to interpolation
N017 Y10.0 ;
N018 X-10.0 ;
N019 Y10.0 ;
N020 X-20.0 ;

```

```
N021 Y-10.0 ;
N022 X-10.0 ;
N023 Y-20.0 ;
N024 X10.0 ;
N025 Y-10.0 ;
N026 X20.0 ;
N027 Y10.0 ;
N028 X10.0 ;
N029 Y10.0 ;
N030 G90 G00 Z10.0 ; //specify to use absolute positioning
N031 G52 X0.0 Y0.0 Z0.0 ; //cancel local coordinate
N032 G40 M05 ; //cancel compensation, spindle stops
N033 M30 ; //program ends
```

1.2.21 G53: MACHINE COORDINATE SYSTEM SELECTION

Command form:

G53 X__ Y__ Z__ ;

X: move to specify machine coordinate of X position.

Y: move to specify machine coordinate of Y position.

Z: move to specify machine coordinate of Z position.


Description:

Machine origin point is the fixed origin point when factory build the CNC machine, this coordinate system is fixed ; when G53 is specified tool will move to the specified position on machine coordinate, when tool returns to machine zero point(0,0,0), this point is the origin point of machine coordinate system.

<Notes>:

1. G53 only effective in specified block ;
2. G53 only effective absolute mode(G90), not effective in increment mode(G91) ;
3. before specify G53, must cancel related cutter compensation ,tool length compensation or position compensation ;
4. before use G53 to set coordinate system, must set coordinate system on the basement of reference return position by manual.

Example:



Program description:

```
N001    G92 X-200.0 Y-100.0 ; //specify to basic coordinate system
N002    G54 G90 X100.0 Y200.0 ; //to specified postion on
          workpiece coordinate system
N003    G53 X300.0 Y100.0 ; //to specified position on machine
```

coordinate system
N004 X300.0 Y0 ;
//because of G53 only effective in one block, this block continue G54
to the specified position on workpiece coordinate system
N005 G52 X300.0 Y200.0 ; //set local coordinate to specified
position on workpiece coordinate system
N006 X0.0 Y0.0 ;

1.2.22 G54...G59.9: WORKPIECE COORDICATE SELECTION

Command form:

```

    { G 54
    | G 55
    | G 56
    | G 57
    | G 58
    | G 59      X _ Y _ Z _;
    | G 59 .1
    | G 59 .2
    | :
    | :
    | :
    | G 59 .9
  
```

G54: 1st workpiece coordinate system

:

:

G59: 6th workpiece coordinate system

G59.1: 7th workpiece coordinate system

:

:

G59.9: 15th workpiece coordinate system

X, Y, Z: move to specified position on setting workpiece system ;


Description:

In general when we operate numerical machine, if there are many workpieces on the machine, we can use workpiece coordinate system G54 to G59 six G codes G59.1~G59.9 to present 15 different coordinate systems, it is convenient to specify each workpiece position on machine coordinate, and it is more convenient to our processed. Use parameter #3229 to 「 disable workpiece coordinate system 」 (0: enable; 1: disable).

※G54.....G59.9 settings:

“setting workpiece coordinate system” in operation interface, setup G54 ...G59.9 by each other. (consult ”milling machine controller operation manual”)

Example:



1.2.23 G64: CUTTING MODE

Command form:
G64;

Description:

G64 is similar to G09, G61 in usage, NC use smooth cutting face mode to cut. This mode does not decelerate and stop between G61 and reverse cutting feed block, the mode will continue to execute next block. G64 can be canceled by G61, G62, G63.

Command name	G code	range	description
Exact stop	G09	Only effective in block with G09.	When tool decelerate to the end of path. The precision will have error in the corner when the tool turns a corner. We use G09 to control the error.
Exact stop	G61	G61 is effective until we set G62、G63、G64.	G61 is similar to G09. The difference is G61 effective until we set G62, G63, or G64.
Cutting mode	G64	G64 is effective until we set G61、G62、G63.	Tool does not decelerate on the end of path, and continue to execute next path after to specified point.

1.2.24 G65: SIMPLE CALL

Command form:

G65 P__ L__ ;

P: number of the program to call ;

L: repetition count ;

Description:

After calling macro, P__ is called to execute and L__ indicates repeating times. But it is enable only in the block with G65.

Example:

G65 P10 L20 X10.0 Y10.0

//Call sub-program O0010 continuously 20 times, and set X=10.0 and Y=10.0 into sub-program.

1.2.25 G66/G67: MACRO CALL

Command form:

G66 P__ L__ ; macro call

G67 ; macro call cancel

P: number of the program to call ;

L: repetition count ;

Description:

After G66 is called, P__ is called to execute and L__ indicates repeating times. If there is a moving block, G66 block will be executed again after moving block ends until using G67 to cancel it.

Example:

G91

G66 P10 L2 X10.0 Y10.0 //repeat twice calling sub-program O0010 and set X=10.0 and Y=10.0 into sub-program.

X20.0 //Move to position X=20.0. After moving, call G66 P10 L2 X10.0 Y10.0.

Y20.0 //Move to position Y=20.0. After moving, call G66 P10 L2 X10.0 Y10.0.

G67 //Cancel macro call mode.

1.2.26 G68/G69: COORDINATE ROTATION

Command form:

(G17) G68 X_ Y_ R_; // start coordinate rotation
 (G18) G68 Z_ X_ R_;
 (G19) G68 Y_ Z_ R_;

G69; // Disable coordinate rotation

X_, Y_, Z_: absolute coordinate of center of rotation
 R_: angle of rotation


Description

After coordinate rotation start, all movement command will rotate with rotation center, so the geometric figure rotate a angle. Rotation center only effective in absolute command, if all command is increment, the actual rotation center is the starting point of path.

Example 1:

```

G54 X0 Y0 F3000.;
G16;                                // start polar coordinates
G90 G00 X50. Y9.207 R8.;           // positioning to strating point
M98 H100;                            // first process
G68 X0 Y0 R90.;                   // coordinate rotates 90°
M98 H100;                            // second process
G68 X0 Y0 R180.;                  // coordinate rotates 180°
M98 H100;                            // third process
G68 X0 Y0 R270.;                  // coordinate rotates 270°
M98 H100;                            // fourth process
G69;                                 // coordinate rotation cancel
G15;                                 // polar coordinate cancel
M02;                                 // main program end
N100                                 // orbit sub-program start
G90 G01 X50. Y9.207 R8.;
G03 X50. Y80.793. R50.;
G03 X50. Y99.207 R8.;
M99;                                 // orbit sub-program return
    
```



Example 2:

```


G54 X0 Y0 F3000. ; // start polar coordinate
G16; // positioning to starting point
G90 G00 X50. Y9.207 R8.; // first process
M98 H100; // coordinate rotates 45°
G68 X0 Y0 R45.; // second process
M98 H100; // coordinate rotates 90°
G68 X0 Y0 R90.; // thied process
M98 H100; // fourth process
G68 X0 Y0 R135.; // coordinate rotates 135°
M98 H100; // fifth process
G68 X0 Y0 R180.; // coordinate rotates 180°
M98 H100; // sixth process
G68 X0 Y0 R225.; // coordinate rotates 225°
M98 H100; // seventh process
G68 X0 Y0 R270.; // coordinate rotates 270°
M98 H100; // eighth process
G68 X0 Y0 R315.; // coordinate rotates 315°
M98 H100; // coordinate rotates cancel
G69; // polar coordinate cancel
G15;
G00 X-80. Y0. // process first "flower"
M98 H200; // process first "flower"

```

```

G51.1 Y-40.; // symmetry axis Y-40.
M98 H200; // process second "flower"
G50; // mirror image cancel
G90 G81 Z-20. R2. F1000. K0; // start G81 drilling cycle
G134 X0 Y0 I75. J30. K6; // circumference hole cycle
G137.1 X60. Y-60. I20. J-20. P3 K3; // chess type hole cycle
G80; // drilling cycle cancel
M02; // main program end
N100 // orbit sub-program
G90 G01 X50. Y9.207;
G03 X50. Y35.793 R50.;
G03 X50. Y54.207 R8.;
M99; // sub-program return
N200 // sub-program start (flower)
G90 G00 X-70. Y10.;
G91 G03 X-20. R10.;
G03 Y-20. R10.;
G03 X20. R10.;
G03 Y20. R10.;
M99; // sub-program return(flower)

```



1.2.27 G70/G71: UNIT SETTING OF INCH/METRIC SYSTEM

Command form:

G70;

G71;

Description:

G70: inch system

G71: metric system

After change inch/metric system, origin offset value of workpiece coordinate, tool data, system parameter, and reference point, all of that is still correct. System will deal the change of unit automatically. After change inch/metric system, item below will change as follow:

- Coordinate, unit of speed
- increment JOG unit
- MPG JOG unit

Decimal Point Input

When parameter is inputted by decimal point input, will to be the common measurement unit, mm, inch, sec...etc., if input by whole number, it will to be the Min unit that system default, μm , ms...etc.

example:

- decimal point: 00.00
- whole number: 0000

1.2.28 Cycle perform function:

G Code	Cutting	Bottom of the hole	Escape	Application
G73	Intermittent cutting feed	----	Speedy movement	High speed peck drill cycle
G74	Cutting feed	After stopping, spindle rotate clockwise	Cutting feed	Left hand taping cycle
G76	Cutting feed	Spindle location stop and offset a displacement value	Speedy movement	Fine boring cycle
G80	----	----	----	Cycle cancel
G81	Cutting feed	----	Speedy movement	Drilling cycle
G82	Cutting feed	Dwell	Speedy movement	Drilling cycle of dwell on the hole bottom
G83	Intermittent cutting feed	----	Speedy movement	Peck drill cycle
G84	Cutting feed	Spindle reverse after dwell	Cutting feed	Tapping drilling cycle
G85	Cutting feed	----	Cutting feed	Drilling cycle
G86	Cutting feed	Spindle dwell	Speedy movement	Boring cycle
*G87	Cutting feed	Spindle rotate CW	Speedy movement	Fine boring cycle of back side
*G88	Cutting feed	Spindle stop after dwell	Manual movement	Fine boring cycle of half automation
G89	Cutting feed	Dwell	Cutting feed	Boring cycle of dwell on the hole bottom

Fixed cycle address and meaning:

Address	Address meaning
G	Selection of fixed cycle
X	Selection position of drilling point(increment or absolute)
Y	Selection position of drilling point(increment or absolute)
Z	Selection position of hole bottom(increment or absolute)
P	Dwell time when hole is in the bottom
Q	Cutting value in G73、G83, or specified movement value (increment) in G76、G87
R	Selection of R position (absolute or increment)
F	Selection of federate
K	Specify fixed cycle times 0~999

G17, G18, and G19 can set axis of drilling, list as below:

G Code	Plane	Axis of drilling
G17	X-Y plane	Z axis
G18	Z-X plane	Y axis
G19	Y-Z plane	X axis

Return to R point:

When tool perform to the bottom of the hole, the tool can return to initial position or R point. And that is decided by G98/G99, G98 is back to initial position, G99 is back to R point.

Number of repeats K:


If we want to perform many holes in the same distance, we can specify number of repeats K, range of K 0~9999, but the first hole need to use increment mode(G91) to specify, or it will repeat drilling in the same place.

When K=0, drilling data will be set, X, Y movement command cannot be executed in block, drilling can not be execute too.

Cancel cycle:

G80 or G code of 01 group(G00/G01/G02/G03...etc.) can cancel cycle.

Increment (G91)/ absolute(G90) mode:



1.2.29 G73: HIGH SPEED PECK DRILL CYCLE

Command form:

G73 X__Y__Z__R__Q__F__K__ ;

X_or Y_: hole position data (absolute/increment)

Z_:

G91: the distance from the bottom of the hole to point Z (directional)

G90: program position of point Z

R_:

G91: the distance from initial level to R point level (directional)

G90: program position of point R

Q_: depth of cut for each cutting feed (increment and positive, minus will be ignore)


F_: feedrate

K_: number of repeats (movement of repeats and action of drilling, G91 increment effective)


X, Y, Z, R can use G90/G91 to decide absolute or increment

PIC:

G 98



G 99



Description:

1. use G00 to move to specified (X,Y) when performance start
2. use G00 to reach specified R point.
3. use G01 to interpolate a distance Q at the present depth
4. use G00 to return a distance d (CNC parameter 4002)
5. repeat drilling hole until reach the Z point
6. use G00 to return initial point(G98) or programmable R point(G99)

Notes:

1. d distance is defined in CNC parameter No.4002.
2. before using G73, please use M Code let the drill start to turn.
3. if M Code and G73 are specified in the same block ,this M Code only executes in the first time of positioning in that block, when K is used to specify numbers of times, this M Code is executed for the first only, for the second hole and subsequent holes, the M Code is not executed.
4. G73 is module G Code ,when use G73 once ,it is effectively always ,we only give the (X,Y) in the next line of program ,then controller will start to drill of (X,Y).
5. this module G code ,use G80 to cancel ,or G00 ,G01,G02,G03 or other cycle this G code will be canceled automatically.

Condition:

1. Before drilling axis be changed, Canned Cycle must be canceled first.
2. If a Block is not included movement command of any axes (X, Y, Z), then drilling can not be executed.
3. The data that Q and R specified, only be set in the block we execute drilling, it can not be set in the block we do not execute drilling.
4. G Code group 01 and G73 can not be specified in the same block, or G73 Canned Cycle will be cancel.
5. In Canned Cycle, tool length compensation (G41/G42/G40)will be ignored.

Program example:

```
F1000. S500;  
M03; // start the drill to turn CW  
G90;  
G00 X0. Y0. Z10.; // positioning to initial point  
G17;  
G90 G99;  
//set the R point, Z point and hole 1, cutting rate 2.0  
G73 X5. Y5. Z-10. R-5. Q2.;  
X15.; // hole 2  
Y15.; // hole 3  
G98 X5.; // hole 4, and return to initial point  
X10. Y10. Z-20.; // hole 5, and set new Z point be -20  
G80;  
M05; // stop drill  
M02;
```

1.2.30 G74: LEFT HAND TAPING CYCLE

Command form:

G74 X__Y__Z__R__P__F__K__ ;

X_ or Y_: coordinates of holes (absolute/increment)

Z_:

G91: the distance from the bottom of the hole to point Z (directional)

G90: program position of point Z

R_:

G91: the distance from initial level to R point level (directional)

G90: program position of point R


P_: dwell time (s)

F_: feedrate

K_: number of repeats (repeat movement and drilling, G91 is effective)

X, Y, Z, R: use G90/91 to decide absolute or increment

PIC:



Description:

1. use G00 to move to specified(X,Y) when start to perform
2. use G00 to specified point R.
3. use G01 to reach the bottom of the hole ,point Z
4. dwell P(s) then reverse the drill
5. use G01 raise to point R
6. dwell P(s) then reverse the drill
7. use G00 to raise to initial point (G98) or programmable point R(G99)

tapping pitch / feed rate reduce:

- G94: $F \text{ (mm/min)} = S \text{ (RPM)} * P \text{ (mm/rev)}$
- G95: $F \text{ (mm/rev)} = P \text{ (mm/rev)}$
- G74: when performing, feedrate(F), spindle RPM(S), they are not controlled by turning switch(fixed at 100%)

Notes:

1. before G74, use M Code let drill start to rotate CCW
2. if M Code and G74 are specified in the same block ,this M Code only executes in the first time of positioning in that block
3. when K is used to specify numbers of times, this M Code is executed for the first only, for the second hole and subsequent holes, the M Code is not executed. G74 is module G Code ,it is always effective when we use once ,we only specify (X,Y) in next line of program ,controller will execute drilling at (X,Y)
4. this module G code ,use G80 to cancel ,when program run into G00 , G01, G02 , G03 or other cycle ,this module G code will be canceled automatically,
5. because there is a little time when spindle CW to CCW in tapping ,please use P add dwell in G code

Condition:

1. before drilling axis be changed, Canned Cycle must be canceled first.
2. if the Block does not include movement command of any axes (X, Y, Z), then drilling will not be executed.
3. data that R specified only be set in blocks of executing drilling, it can not be set in blocks of no executing drilling.
4. G code 01 group and G74 can be specified in the same block, or G74 Canned Cycle will be canceled.
5. in Canned Cycle, tool length compensation(G41/G42/G40) will be ignored.

Program example:

```
F1000. S500;  
G90;  
G00 X0. Y0. Z10.; // positioning to initial point  
G17;  
M04; // start drill to rotate CCW  
G90 G99;  
//specify point R 、 point Z and hole 1 coordinate values, dwell 2 s  
G74 X5. Y5. Z-10. R-5. P2.;  
X15.; // hole 2  
Y15.; // hole 3  
G98 X5.; // hole 4, and set to return to initial point  
X10. Y10. Z-20.; // hole 5, and set new point Z to be -20.  
G80;  
M05; // drill stops  
M02;
```

1.2.31 G76: FINE BORING CYCLE

Command form:

G76 X__Y__Z__R__Q__P__F__K__ ;

X__ or Y__: hole position data (absolute/increment position)

Z__:

G91: the distance from the bottom of the hole to point Z (directional)

G90: program position of point Z

R__:

G91: the distance from initial level to R point level (directional)

G90: program position of point R

Q__: shift amount at the bottom of the hole (positive, negative will be ignored)

P__: dwell time at the bottom of the hole (s)


F__: feedrate

K__: number of repeats (repeat moving and drilling ,G91 is effective)



X, Y, Z, R is absolute or increment mode, decided by G90/G91

PIC:

G 98



G 99



Oriented Spindle Stop(OSS)

Description:

1. use G00 to move tool to specified (X, Y) point, when performance start
2. use G00 reach the specified R point(not include spindle positioning)
3. use G01 reach point Z at the bottom of the hole, dwell P(s) and spindle positioning and stop the drill
4. shift q distance
5. use G00 raise to initial point (G98) or programmable point R (G99)
6. drill reverse start

※ alarm:

- Q is a Modal Value that requests in G76 cycle, we must specify this Q value carefully, because it also use in G73/G83.
- OSS(Oriented Spindle Stop) direction is decided by parameter No. 4020:

Parameter 4020	OSS direction
0	+X
1	-X
2	+Y
3	-Y

Note:

1. before G76, use M Code let drill start to rotate CW.
2. if M Code and G76 are specified in the same block ,this M Code only executes in the first time of positioning in that block
3. when K is used to specify numbers of times, this M Code is executed for the first only, for the second hole and subsequent holes, the M Code is not executed.
4. G76 is module G Code ,it is always effective when we use once ,we only specify (X,Y) in next line of program ,controller will execute drilling at (X,Y)
5. this module G code ,use G80 to cancel ,when program run into G00, G01, G02 , G03 or other cycle ,this module G code will be canceled automatically.

Condition:

1. before drilling axis be changed, Canned Cycle must be canceled first.
2. if the Block does not include movement command of any axes (X, Y, Z), then drilling will not be executed.
3. Q must be specified a positive value. If Q is negative value ,it will be thought to be a positive value (absolute value), data that Q and R specified only be set in drilling blocks, it will not be set in not drilling blocks.
4. G Code group 01 and G76 can not be specified in the same block, or G76 Canned Cycle cancel.
5. in Canned Cycle, tool length compensation (G41/G42/G40)will be ignore.

Program example:

```
F1000. S500;  
M03; // start drill rotate CW  
G90;  
G00 X0. Y0. Z10.; // position to initial point  
G17;  
G90 G99;  
//specify point R、point Z and hole 1, shift amount at bottom of hole2.0,  
dwell time 5 s  
G76 X5. Y5. Z-10. R-5. Q2. P5.;  
X15.; // hole 2  
Y15.; // hole 3  
G98 X5.; // hole 4, and return to initial point  
X10. Y10. Z-20.; // hole 5, and specify the new point Z to be -20.0  
G80;  
M05; // drill stops  
M02;
```

1.2.32 G81: DRILLING CYCLE

Command form:

G81 X__Y__Z__R__F__K__ ;

X_ or Y_: hole position data (absolute/increment position)

Z_:

G91: the distance from the bottom of the hole to point Z (directional)

G90: program position of point Z

R_:

G91: the distance from initial level to R point level (directional)


G90: program position of point R

F_: feed rate

K_: number of repeats (repeat moving and drilling, G91 is effective)

X, Y, Z, R is absolute or increment mode, decided by G90/G91

PIC:



Description:

1. use G00 to positioning to specified (X,Y) when start to perform
2. use G00 to reach specified point R.
3. use G01 to reach point Z the bottom of the hole
4. use G00 to raise to initial point(G98) or program point R(G99)

Note:

1. before G81, use M Code to let drill start to rotate.
2. if M Code and G81 are specified in the same block ,this M Code only executes in the first time of positioning in that block,
3. when K is used to specify numbers of times, this M Code is executed for the first only, for the second hole and subsequent holes, the M Code is not executed.

Condition:

1. before drilling axis be changed, Canned Cycle must be canceled first.
2. if the Block does not include movement command of any axes (X, Y, Z), then drilling will not be executed.
3. data R specified only be set in drilling block, it will not be set in not drilling block.
4. G Code group 01 and G81 can not be specified in the same block, or G76 Canned Cycle cancel.
5. in Canned Cycle, tool length compensation (G41/G42/G40)will be ignore.

Program example:

```
F1000. S500;  
G90;  
G00 X0. Y0. Z10.; // positioning to initial point  
G17;  
G90 G99; //setting point R 、 point Z and hole 1  
G81 X5. Y5. Z-10. R-5.;  
X15.; // hole 2  
Y15.; // hole 3  
G98 X5.; // hole 4, and return to initial point  
X10. Y10. Z-20.; // hole 5, and set new point Z to be -20  
G80;  
M02;
```

1.2.33 G82: DRILLING CYCLE OF DWELL ON THE HOLE BOTTOM

Command form:

G82 X__Y__Z__R__P__F__K__ ;

X__ or Y__: hole position data (absolute/increment mode)

Z__:

G91: the distance from the bottom of the hole to point Z (directional)

G90: program position of point Z

R__:

G91: the distance from initial level to R point level (directional)

G90: program position of point R

P__: dwell time at the bottom of the hole (s)


F__: feed rate

K__: number of repeats (repeat moving and drilling, G91 is effective)


X, Y, Z, R is absolute or increment mode, decided by G90/G91

PIC:

G 98



G 99



Description:

1. use G00 to positioning to specified (X,Y) when start to perform
2. use G00 to reach specified point R.
3. use G01 to reach point Z the bottom of the hole
4. dwell P (s)
5. use G00 raise to initial point(G98) or program point R(G99)

Notes:

1. before G82, use M Code to let drill start to rotate.
2. if M Code and G82 are specified in the same block ,this M Code only executes in the first time of positioning in that block
3. when K is used to specify numbers of times, this M Code is executed for the first only, for the second hole and subsequent holes, the M Code is not executed

Condition:

1. before drilling axis changes, Canned Cycle must be canceled first.
2. if the Block does not include movement command of any axes (X, Y, Z), then drilling will not be executed.
3. data R specified only be set in drilling block, it will not be set in not drilling block.
4. G Code group 01 and G82 can not be specified in the same block, or G76 Canned Cycle cancel.
5. in Canned Cycle, tool length compensation mode(G41/G42/G40) will be ignored.

Program example:

```
F1000. S500;  
G90;  
G00 X0. Y0. Z10.; // positioning to initial point  
G17;  
M03; // start drill to rotate CW  
G90 G99;  
//specified point R 、 point Z and hole 1, dwell time 2 s  
G82 X5. Y5. Z-10. R-5. P2.;  
X15.; // hole2  
Y15.; // hole3  
G98 X5.; // hole4, and return to initial point  
G80;  
M05; // drill stops  
M02;
```

1.2.34 G83: PECK DRILL CYCLE

Command form:

G83 X__Y__Z__R__Q__F__K__ ;

X__ or Y__: hole position data (absolute/increment mode)

Z__:

G91: the distance from the bottom of the hole to point Z (directional)

G90: program position of point Z

R__:

G91: the distance from initial level to R point level (directional)

G90: program position of point R

Q__: the feed depth (increment and positive value; negative value is neglected)

P__: dwell time at the bottom of the hole(s)


F__: feed rate

K__: number of repeats (repeat moving and drilling, G91 is effective)


X, Y, Z, R is absolute or increment mode, decided by G90/G91

PIC:

G 98



G 99



Description:

1. use G00 to positioning to specified (X,Y) when start to perform
2. use G00 to reach specified point R.
3. use G01 to interpolate a distance Q at the present depth
4. use G00 raise to point R of workpiece interface.
5. use G00 reach a distance "d" that opposite to the present depth(parameter 4002)
6. use G01 to interpolate a distance Q at the present depth

7. use G00 raise to point R of workpiece interface.
8. repeat performing until the bottom of the hole point Z
9. use G00 raise to initial point (G98) or program point R(G99)

Notes:

1. peck drill of returning tool value “d” ,it is specified by CNC parameter No.4002.
2. before using G83, use M Code let the drill to rotate first.
3. if M Code and G83 are specified in the same block ,this M Code only executes in the first time of positioning in that block
4. when K is used to specify numbers of times, this M Code is executed for the first only, for the second hole and subsequent holes, the M Code is not executed.

Condition:

1. before drilling axis changes, Canned Cycle must be canceled first.
2. if the Block does not include movement command of any axes (X, Y, Z), then drilling will not be executed
3. data Q and data R specified only be set in drilling block, it will not be set in not drilling block.
4. G Code group 01 and G83 can not be specified in the same block, or G76 Canned Cycle cancel.
5. in Canned Cycle, tool length compensation mode (G41/G42/G40) will be ignored.

Program example:

```
F1000. S500;  
M03; // start drill to rotate CW  
G90;  
G00 X0. Y0. Z10.; // positioning to initial point  
G17;  
G90 G99; // specify point R, point Z and hole 1, cutting federate 3.0  
G83 X5. Y5. Z-10. R-5. Q3.;  
X15.; // hole2  
Y15.; // hole3  
G98 X5.; // hole4, and return to initial point  
G80;  
M05; // drill stops  
M02;
```

1.2.35 G84: TAPPING DRILLING CYCLE

Command form:

G84 X__Y__Z__R__P__Q__F__K__ ;

X_ or Y_: hole position data (absolute/increment mode)

Z_:

G91: the distance from the bottom of the hole to point Z (directional)

G90: program position of point Z

R_:

G91: the distance from initial level to R point level (directional)

G90: program position of point R

P_: dwell time at the bottom of the hole(s)

Q_: the feed depth (increment and positive value; negative value is neglected)

F_: feed rate

K_: number of repeats (repeat moving and drilling, G91 is effective)


X, Y, Z, R is absolute or increment mode, decided by G90/G91.

PIC:

Type I: None argument Q

G 98


G 99



Description:


1. use G00 to positioning to specified (X, Y) when start to perform
2. use G00 to reach specified point R
3. use G01 to reach point Z the bottom of the hole
4. dwell P(s) and reverse the drill
5. use G01 to raise to point R
6. dwell P(s) and reverse the drill
7. use G00 to raise to initial point(G98) or program point R(G99)

TYPE II : High Speed Peck Tapping (Custom Parameter No.4001= 1)



Description:

1. use G00 to positioning to specified (X,Y) when start to perform
2. use G00 to reach specified point R
3. use G01 to interpolate a distance Q at the present depth
4. After dwell P(s), use G01 to reach a distance “d” that opposite to the present depth (set by parameter 4002).
5. After dwell P(s), use G01 to interpolate a distance Q at the present depth.
6. After dwell P(s), use G01 to reach a distance “d” that opposite to the present depth (set by parameter 4002).
7. Repeat the above action until reaching the bottom of the hole, point Z.
8. Dwell P(s) and reverse the tap. Then use G01 to rise to point R (G99).
9. Dwell P(s) and reverse the tap. Then G00 to rise to initial point (G98).

TYPE III: General Peck Tapping (Custom Parameter No.4001= 0)**Description:**

1. Use G00 to positioning to specified (X, Y) when start to perform.
2. Use G00 to reach specified point R.
3. Use G01 to interpolate a distance Q at the present depth.
4. Dwell P(s) and reverse the tap. Then use G01 to reach point R.
5. Dwell P(s) and reverse the tap. Then use G01 to interpolate a distance "Q" relative to the depth of present hole.
6. Dwell P(s) and reverse the tap. Then use G01 to reach point R.
7. Repeat the above action until reaching the bottom of the hole, point Z.
8. Dwell P(s) and reverse the tap. Then use G01 to rise to point R (G99).
9. Dwell P(s) and reverse the tap. Then use G00 to rise to initial point (G98).

tapping pitch/perform speed, reduce :

- G94: perform speed(F mm/min) = spindle rotate rate(S RPM) * pitch(P mm/rev)
- G95: perform speed(F mm/rev) = pitch(P mm/rev)
- G84: when performing, perform speed(F) spindle rotate rate(S), they are not controlled by turning switch(fix 100%)

Notes:

1. before using G84, use M Code to let the drill rotate CCW
2. if M Code and G84 are specified in the same block ,this M Code only executes in the first time of positioning in that block
3. when the K is used to specify numbers of repeats, this M Code is executed in the first hole only. G84 is module G Code ,it is always effective when we use once ,we only specify (X,Y) in next line of program ,controller will execute drilling at (X,Y)
4. this module G Code ,will be canceled when G80 command ,or we command G00 ,G01,G02,G03 or other cycle G code ,this module G code will be canceled automatically
5. because there is a period of time that spindle from CW to CCW at tapping , please command P to dwell a period of time

Condition:

1. before drilling axis changes, Canned Cycle must be canceled first.
2. if the Block does not include movement command of any axes (X, Y, Z), then drilling will not be executed.
3. data R specified only be set in drilling block, it will not be set in not drilling block.
4. G Code group 01 and G84 can not be specified in the same block, or G76 Canned Cycle cancel.
5. in Canned Cycle, tool length compensation mode (G41/G42/G40) will be ignored.

Program example:

```
F1000. S500;  
G90;  
G00 X0. Y0. Z10.; // positioning to initial point  
G17;  
M03; // start drill to rotate CW  
G90 G99;  
//specify point R 、 point Z and hole1  
G84 X5. Y5. Z-10. R-5.;  
X15.; // hole2  
Y15.; // hole3  
G98 X5.; // hole4, and return to initial point  
G80;  
M05; // drill stops  
M02;
```

1.2.36 G85: DRILLING CYCLE

Command form:

G85 X__Y__Z__R__F__K__ ;

X_ or Y_: hole position data (absolute/increment mode)

Z_:

G91: the distance from the bottom of the hole to point Z (directional)

G90: program position of point Z

R_:

G91: the distance from initial level to R point level (directional)

G90: program position of point R

P_: dwell time at the bottom of the hole(s)


F_: feed rate

K_: number of repeats (repeat moving and drilling, G91 is effective)


X, Y, Z, R is absolute or increment mode, decided by G90/G91.

PIC:

G98



G99



Description:

1. use G00 to positioning to specified (X,Y) when start to perform
2. use G00 to reach specified point R.
3. use G01 to reach point Z the bottom of the hole,
4. G01 command to raise to point R
5. G00 command to raise to initial point(G98) or program point R(G99)

Notes:

1. before G85 command, use M Code to let the spindle rotate.
2. if M Code and G85 are specified in the same block ,this M Code only executes in the first time of positioning in that block.
3. when K is used to specify numbers of times, this M Code is executed for the first only, for the second hole and subsequent holes, the M Code is not executed.

Condition:

1. before drilling axis changes, Canned Cycle must be canceled first.
2. if the Block does not include movement command of any axes (X, Y, Z), then drilling will not be executed.
3. data R specified only be set in drilling block, it will not be set in not drilling block.
4. G Code group 01 and G85 can not be specified in the same block, or G76 Canned Cycle cancel.
5. in Canned Cycle, tool length compensation mode (G41/G42/G40) will be ignored.

Program example:

```
F1000. S500;  
G90;  
G00 X0. Y0. Z10.; // positioning to initial point  
G17;  
M03; // start drill to rotate CW  
G90 G99;  
//specify point R 、point Z and hole 1  
G85 X5. Y5. Z-10. R-5.;  
X15.; // hole2  
Y15.; // hole3  
G98 X5.; // hole4, and return to initial point  
G80;  
M05; // drill stops  
M02;
```

1.2.37 G86: HIGH SPEED DRILLING CYCLE

Command form:

G86 X__Y__Z__R__F__K__ ;

X_or Y_: hole position data (absolute/increment mode)

Z_:

G91: the distance from the bottom of the hole to point Z (directional)

G90: program position of point Z

R_:

G91: the distance from initial level to R point level (directional)

G90: program position of point R

P_: dwell time at the bottom of the hole (s)


F_: feed rate

K_: number of repeats (repeat moving and drilling, G91 is effective)

X, Y, Z, R is absolute or increment mode, decided by G90/G91


PIC:

G98



Drill stops

G99



Drill stops

Description:

1. use G00 to positioning to specified (X,Y) when start to perform
2. use G00 to reach specified point R.
3. use G01 to reach point Z the bottom of the hole,
4. use G00 to raise to initial point (G98) or program point R(G99)

Notes:

1. before using G86, use M Code to let the drill to rotate.
2. if M Code and G86 are specified in the same block ,this M Code only executes in the first time of positioning in that block
3. when K is used to specify numbers of times, this M Code is executed for the first only, for the second hole and subsequent holes, the M Code is not executed.

Condition:

1. before drilling axis changes, Canned Cycle must be canceled first.
2. if the Block does not include movement command of any axes (X, Y, Z), then drilling will not be executed.
3. data R specified only be set in drilling block, it will not be set in not drilling block.
4. G Code group 01 and G86 can not be specified in the same block, or G76 Canned Cycle cancel.
5. in Canned Cycle, tool length compensation mode (G41/G42/G40) will be ignored.

Program example:

```
F1000. S500;  
G90;  
G00 X0. Y0. Z10.; // positioning to initial point  
G17;  
M03; // start drill to rotate CW  
G90 G99;  
//specify point R 、point Z and hole 1  
G86 X5. Y5. Z-10. R-5.;  
X15.; // hole2  
Y15.; // hole3  
G98 X5.; // hole4, and return to initial point  
G80;  
M05; // drill stops  
M02;
```

1.2.38 G87: FINE BORING CYCLE OF BACK SIDE

Command form:

G87 X__Y__Z__R__Q__P__F__K__ ;

X__ or Y__: hole position data (absolute/increment position)

Z__:

G91: the distance from the bottom of the hole to point Z (directional)

G90: program position of point Z

R__:

G91: the distance from initial level to R point level (directional)

G90: program position of point R

Q__: shift amount at the bottom of the hole (positive, negative will be ignored)

P__: dwell time at the bottom of the hole (s)



F__: feedrate

K__: number of repeats (repeat moving and drilling, G91 is effective)

X, Y, Z, R is absolute or increment mode, decided by G90/G91

PIC:

G98, G99



Oriented Spindle Stop(OSS) PIC

Description:

1. use G00 to positioning to specified (X,Y) when start to perform
2. after OSS stops ,use the direction that parameter 4020 specify ,and shift amount a Q distance in reverse direction
3. use G00 to reach specified point R, shift amount a Q distance,
4. drill rotate CW.
5. G01 command to raise to point Z
6. after dwell P(s) and shift amount a Q distance in reverse direction
7. G00 command to raise to initial point
8. after drill rotate CW and shift amount a Q distance.

※Alarm:

- Q is a Modal Value that request in G87 cycle. This Q value must be specified carefully because it is also used in G73/G83 cycle.
- OSS(Oriented Spindle Stop) direction is decided by parameter No. 4020:

Parameter 4020	OSS direction
0	+X
1	-X
2	+Y
3	-Y
4	+Z
5	-Z

Notes:

1. before G87 command, use M Code to let the spindle rotate.
2. if M Code and G87 are specified in the same block , this M Code only executes in the first time of positioning in that block
3. when K is used to specify numbers of times, this M Code is executed for the first only, for the second hole and subsequent holes, the M Code is not executed.

Condition:

1. before drilling axis changes, Canned Cycle must be canceled first.
2. if the Block does not include movement command of any axes (X, Y, Z), then drilling will not be executed.
3. Q must be specified to a positive value. If Q were a negative value, it will be specified to positive value (absolute value), data Q and data R specified only be set in drilling block, it will not be set in not drilling block.
4. G Code group 01 and G87 can not be specified in the same block, or G76 Canned Cycle cancel.
5. in Canned Cycle, tool length compensation mode (G41/G42/G40) will be ignored.

```
Program example:  
F1000. S500;  
G90;  
G00 X0. Y0. Z10.; // positioning to initial point  
G17;  
G90 G99;  
M03; // start drill to rotate CW  
//specify point R 、 point Z and hole 1, shift amount 5.0, dwell time 4.0s  
G87 X5. Y5. Z10. R-30. Q5. P4.;  
X15.; // hole2  
Y15.; // hole3  
G80;  
M05; // drill stops  
M02;
```

1.2.39 G88: FINE BORING CYCLE OF HALF AUTOMATION

Command form:

G88 X__Y__Z__R__P__F__K__ ;

X_ or Y_ : hole position data (absolute/increment position)

Z_ :

G91: the distance from the bottom of the hole to point Z (directional)

G90: program position of point Z

R_ :

G91: the distance from initial level to R point level (directional)

G90: program position of point R

P_ : dwell time at the bottom of the hole (s)


F_ : feedrate

K_ : number of repeats (repeat moving and drilling, G91 is effective)


X, Y, Z, R is absolute or increment mode, decided by G90/G91

PIC:

G98



G99



※

for positioning by manual.

Description:

1. use G00 to positioning to specified (X,Y) when start to perform
2. use G00 to reach specified point R.
3. use G01 to reach point Z the bottom of the hole,
4. drill stops after dwell P(s),
5. make the tool out of workpiece in manual mode and reset
6. use G01 to move to point R
7. use G00 to raise to initial point(G98) or program point R(G99)
8. drill rotate CW.

Notes:

1. before G88 command, use M Code to let drill start to rotate first.
2. if M Code and G88 specify in the same block ,this M Code only executes once when the first time positioning in that block
3. when K is used to specify numbers of times, this M Code is executed for the first only, for the second hole and subsequent holes, the M Code is not executed.

Condition:

1. before drilling axis changes, Canned Cycle must be canceled first.
2. if the Block does not include movement command of any axes (X, Y, Z), then drilling will not be executed.
3. data R specified only be set in drilling block, it will not be set in not drilling block.
4. G Code group 01 and G88 can not be specified in the same block, or G76 Canned Cycle cancel.
5. in Canned Cycle, tool length compensation mode (G41/G42/G40) will be ignored.

Program example:

```
F1000. S500;  
G90;  
G00 X0. Y0. Z10.; // positioning to initial point  
G17;  
M03; // start drill to rotate CW  
G90 G99;  
//specify point R 、 point Z and hole1, dwell 2.0s  
G88 X5. Y5. Z-10. R-5. P3.;  
X15.; // hole2  
Y15.; // hole3  
G98 X5.; // hole4, and return to initial point  
G80;  
M05; // drill stops  
M02;
```

1.2.40 G89: BORING CYCLE OF DWELL ON THE HOLE BOTTOM

Command form:

G89 X__Y__Z__R__P__F__K__;

X__ or Y__: hole position data (absolute/increment position)

Z__:

G91: the distance from the bottom of the hole to point Z (directional)

G90: program position of point Z

R__:

G91: the distance from initial level to R point level (directional)

G90: program position of point R


P__: dwell time at the bottom of the hole (s)

F__: feedrate

K__: number of repeats (repeat moving and drilling, G91 is effective)

X, Y, Z, R is absolute or increment mode, decided by G90/G91.

PIC:



Description:

1. use G00 to positioning to specified (X,Y) when start to perform
2. use G00 to reach specified point R.
3. use G01 to reach point Z the bottom of the hole
4. dwell P (s)
5. use G01 to raise to point R
6. use G00 to raise to initial point (G98) or program point R(G99)

Notes:

1. before G89 command, use M Code to let the drill start to rotate.
2. if M Code and G89 are specified in the same block ,this M Code only executes in the first time of positioning in that block
3. when K is used to specify numbers of times, this M Code is executed for the first only, for the second hole and subsequent holes, the M Code is not executed.

Condition:

1. before drilling axis changes, Canned Cycle must be canceled first.
2. if the Block does not include movement command of any axes (X, Y, Z), then drilling will not be executed.
3. data R specified only be set in drilling block, it will not be set in not drilling block.
4. G Code group 01 and G89 can not be specified in the same block, or G76 Canned Cycle cancel.
5. in Canned Cycle, tool length compensation mode (G41/G42/G40)will be ignored.

Program example:

```
F1000. S500;  
G90;  
G00 X0. Y0. Z10.; // positioning to initial point  
G17;  
M03; // start drill to rotate CW  
G90 G99;  
//specify point R 、point Z and hole1, dwell 2.5s  
G89 X5. Y5. Z-10. R-5. P2.5;  
X15.; // hole2  
Y15.; // hole3  
G98 X5.; // hole4, and return to initial point  
G80;  
M05; // drill stops  
M02;
```

1.2.41 G90/G91: ABSOLUTE/INCREMENT COMMAND

Command form:

G90;


G91;

Description:

G90: absolute command.

G91: incremental command.

PIC:



Description:

1. first way(absolute): G90 G00 X90.0 Y40.0 ;
//use the different distance from specified point to program zero point, to linear interpolation to specified point
2. second way(increment): G91 G00 X70.0 Y20.0 ;
//use the different distance from specified point to starting point, to linear interpolation to specified point

1.2.42 G92: SETTING OF WORK COORDINATE SYSTEM

Command form:


G92 X__ Y__ Z__;

X、Y、Z: set the position that work coordinate system(G92) in programmable coordinate system

Description:

When we design the program, we must set another program coordinate zero point, we can use G92 to set a new coordinate system at this time, this command is set a new zero point of coordinate system when the tool is in any position, after setting tool will start to perform at this point, absolute command is computed by this new coordinate system.

PIC:



Format: G92 X20.0 Y15.0 Z20.0 ;

1.2.43 G94/G95: FEED UNIT SETTING


Command form:

G94 F__;


G95 F__;

Description: this command set the unit of feedrate of F__ function (tool move distance per unit time or move distance per revolution) ; G94 is feed value per minute, unit: mm/min, inch/min, G95 is feed value per revolution, unit: mm/rev, inch/rev.

PIC:



G94. feed per minute(mm/min or inch/min)



G95. feed per revolution(mm/rev or inch/rev)

1.2.44 G96/G97: CONSTANT LINEAR VELOCITY CONTROL ON SURFACE

Command form:

G96 S__ ; constant linear velocity control on surface: ON

G97 S__ ; constant linear velocity control on surface: OFF

Description:

G96 specify the surface speed (relative speed between the tool and workpiece), G97 command can cancel G96 command, it also can specify spindle speed ; in performance, use the tool in different radius, but we need surface speed in a fixed value, we can use G96 S__ to control surface speed ; if you do not mind how big is the diameter of tool when perform, and we fix the spindle speed, we can use G97 S__ to control spindle speed, follow the formula:

$$V = \frac{\pi DN}{1000}$$

V: surface speed, it can use G96 to specify to fixed value, unit M/MIN or FEET/MIN.

D: diameter of tool, unit mm

N: spindle speed, it can use G97 to specify to fixed value, unit RPM.

Example 1:

spindle surface speed fixed:

G92 S2000; //use G92 to restrict spindle max revolution

G96 S130 M03; //for interpolation speed is 130 m/min

Notes: G92 always used with G96, it restricts max revolution of spindle, example is tool NO.2 diameter 10mm, then:

$$N = \frac{1000 \times 130}{\pi \times 10} = 4140 \text{ rpm}$$

Through G92 the spindle max revolution is 2000rpm, in order to prevent spindle revolution too big、centrifugal too big, workpiece is not tight with the machine, so some accident will happen ; so we use G92 to match G96 in some times

Example 2:

spindle revolution fixed: G97 S1300 M03 ;

//for spindle keep 1300 rev/min

1.2.45 G134: CIRCUMFERENCE HOLE CYCLE

Command form:

G134 X__ Y__ I__ J__ K__ ;

X, Y: center position of circumference hole, effective by G90/G91.

I: radius of circle(r), unit is specified by G70/G71, must in positive value.


J: angle of initial drilling hole.

K: number of holes. Range 1~9999, can not be zero. It is specified positive when CCW, negative when CW.

Description:

Use the point between X axis and angle ,start to make the circle in n parts, n holes. The point is on the circle that center is specified (X,Y) and the radius is r.

Example:



Program description:

```

G92 X500.0 Y100.0 ; //set absolute zero point coordinate system
G91 G81 Z-10.0 R5.0 K0 F200 ;
//execute drilling cycle, feedrate 200mm/min, depth 10 mm, and return
to initial point when finish
G134 X200.0 Y100.0 I100.0 J20.0 K6 ;
//execute circumference hole cycle, X=200mm,Y=100mm drill the first
hole, radius 100mm, starting angle 20° , 6 holes
G80 ; //cancel cycle
G90 G0 X0.0 Y0.0 ; //return to the system zero point

```

1.2.46 G135: ANGULAR STRAIGHT HOLE CYCLE

Command form:

G135 X__ Y__ I__ J__ K__ ;

X, Y: starting position, effective by G90/G91.


I: interval, unit is specified by G70/G71, if it is negative then use starting point to be the center and drill holes in symmetry direction.

J: angle of horizontal, CCW is positive.

K: number of holes, include starting point, range 1~9999.

Example:

Use the interval to drill n holes in the direction that X axis and a angle, the starting point is specified (X, Y)



Program description:

```

G91 ; //use increment mode
G81 Z-10.0 R5.0 K0 F100 ;
//execute drill cycle, feedrate 100mm/min, depth of each hole 10 mm,
//return to starting point when finish
G135 X200.0 Y100.0 I100.0 J30.0 K5 ;
//execute angular straight hole cycle, X=200mm,Y=100mm be starting
position, interval 100mm, angle with horizontal 30° , 5 holes

```

1.2.47 G136: ARC TYPE HOLE CYCLE

Command form:

G136 X__ Y__ I__ J__ P__ K__ ;

X, Y: center coordinate of arc, effective by G90/91.

I: radius of arc, unit is specified by G70/G71, present in positive value.

J: angle of the first drilling hole, positive in CCW.


P: interval of angle, positive in CCW.

K: number of holes.

Description:

Use the point make between X axis and a angle to be starting point ,and drill a hole every angular. The hole is drilling in the arc that specified (X,Y) is center and “r” is radius.

Example:



G91 ; //use incremental mode

G81 Z-10.0 R5.0 K0 F100 ;

//execute drilling cycle, cutting feedrate 100mm/min, depth of each holes 10 mm, and return the initial point

G136 X300.0 Y100.0 I300.0 J10.0 P15000 K6 ;

//execute arc type hole cycle, X=300mm,Y=100mm to be the center of the arc, radius 300mm, starting angle value10° , interval angle15° , 6 holes

1.2.48 G137.1: CHESS TYPE HOLE CYCLE

Command form:

G137.1 X__ Y__ I__ P__ J__ K__ ;

X, Y: coordinates of starting point, effective by G90/91.

I: X axis interval, unit is decided by G70/G71, if the interval value is positive ,then go through positive direction from starting point, if it is negative ,then go through negative direction.

P: interval of X axis direction, range 1~9999.


J: interval of Y axis direction

K: number of Y axis direction, range 1~9999.

Description:

The starting point is specified (X,Y), we get the interval at horizontal direction of X axis, and drill nx chess type holes. We get the interval at horizontal direction of Y axis, and drill ny chess type holes.

Example:



G91 ; //use incremental mode

G81 Z-10.0 R5.0 K0 F20 ;

//execute drilling cycle, cutting feedrate 20mm/min, depth of each hole 10 mm, then return to initial point

G137.1 X300.0 Y-100.0 I50.0 P10 J100.0 K8 ;

//execute chess type hole cycle, X = 300mm,Y = -100mm to be strating point, X axis interval is 50mm, number of the hole is 10, Y axis interval is 100mm, number of the hole is 8

1.2.49 Tool Function: T Code Command

Command form:

T __

Description:

Tool function is also called T function, it is used to choose tools, we usually use it to change tool with M06, we can auto do tool exchange according to the number of the tools.

Example:

T03 M06; //for change to tool No.3

1.2.50 Spindle Speed Function: S Code Command

Command form:

S __

Description:

S function is spindle speed command, specify spindle rev/min (RPM) or constant linear velocity, it is specified by G96/G97.

Example:

G96 S150 M03; //constant linear velocity on surface, 150 m/min

G97 S500 M03; //keep 500 rev/min

1.2.51 Feed Function: F Code Command

Command form:

F __

Description:

When interpolate workpiece, the only speed we specify to tool in the program, is called feedrate. There is two to specify the feedrate (G94/G95). If we use G94, F300 is for 300 mm/min. If we use G95, F0.5 is for 0.5mm/rev.

Example:

G94 G01 X100.0 Y100.0 F300;
//linear interpolation, feedrate is 300mm/min
G95 G01 X100.0 Y100.0 F0.5;
//linear interpolation, feedrate is 0.5mm/rev

2 M Code Description:

Ancillary function is used to control machine function ON or OFF. The description is as below:

M function table

M Code	Function
M00	Program dwell
M01	Selectivity program dwell
M02	End program
M03	Spindle rotate(CW)
M04	Spindle rotate(CCW)
M05	Spindle stop
M06	Tool exchange
M08	Coolant liquid ON
M09	Coolant liquid OFF
M19	Spindle positioning, let spindle stop at a specified position
M30	Program end, return to starting point
M98	Call the sub-program
M99	From sub-program return to main program

1. M00: Program dwell

When CNC executes M00 command, the spindle will stop to rotate, feed will dwell, cutting oil will stop, it is convenient to size check and compensate for operator ; we can specify the program is dwell or not by "M00 cancel switch" on the interface.

2. M01: Selectivity program dwell

M01 is similar to M00 ; but M01 is controlled by "selectivity stop" ; when the switch is ON, M01 is effective, program dwell ; when the switch is OFF, then M01 is not effective.

3. M02: program end

when there is M02 command in the end of main program. When CNC executes this command, machine will stop, if we need to execute the program again, we must click "RESET", and then click "program start".

4. M03: spindle rotate (CW)

M03 command can let the spindle rotate CW, it can use with S function, spindle can rotate CW in specified speed.

5. M04: spindle rotate (CCW)

M04 command can let the spindle rotate CCW

6. M05: spindle stop

M05 command can let spindle stop, when you want to change the gear or change the rotate direction, must use M05 to stop the spindle before we change the gear or change the rotate direction.

7. M06: tool exchange

M06 command can execute tool exchange, this command does not include tool selection, it must use with T__function.

8. M08/M09: coolant liquid ON/OFF

M08 command for coolant liquid ON, M09 for OFF

9. M19: spindle positioning stop

M19 command let spindle positioning on a specified corner

10. M30: program end

M30 command for program ends, when program execute M30 command, will action stops, and the memory will return to the initial of the program.

11. M98/M99: sub-program control

sub-program is parameter which has fixed perform method or be executed usually, we prepare first and put it into memory, when we need to use, we can call by main program. We use M98 to call the sub-program and use M99 to end that.

Command form:

M98 P__ H__ L__; //Sub-program called

P is specified number of program(when we ignore P, it specify the program itself, and it is only used in memory perform or MDI perform)
H is the number of ranking in specified program.

L is the number of repeats that sub-program executes.

M99 P__; //Sub-program end

P is the line number that returns to main program after sub-program ends.

Milling machine parameter description:

NO.	Description	Range	Unit	Operation description
4002	Drilling cycle return tool value	[0,99999999]	LIU	LIU Min input unit, this unit is effective by G70/G71.
4010	Percentage of perform feed depth on perform cycle plant	[1,100]		Percentage of perform feed depth to tool diameter on perform cycle
4020	Boring spindle stop direction	[0,3]		XY work plan 0:X+,1:X-,2:Y+,3:Y- ZX work plan 0:Z+,1:Z-,2:X+,3:X- YZ work plan 0:Y+,1:Y-,2:Z+,3:Z-