

JBM CAMPLLONG S.L.U. - 54904

Telefónica Tech TheThinX Test Report

| | |
|---------------------------|--|
| Addressed to: | JBM CAMPLLONG S.L.U. |
| Manufacturer: | JBM CAMPLLONG S.L.U. |
| Device Type: | End Device |
| Model: | 54904 |
| Module: | Y7080E |
| Technology: | NB-IoT |
| Device SW Version: | V0.2 |
| Module SW Version: | 2212B07Y7080E-240506 |
| Photo: |  |

As a result of TheThinX service, **JBM CAMPLLONG S.L.U. - 54904** end device, in its V0.2 version, have been found important issues as a result of TheThinX pre-testing service.

These issues may affect some device functionality.

JBM CAMPLLONG S.L.U. should deliver to Telefónica a solution plan to solve open issues.

Index

| | |
|---|-----------|
| 1. Tested Version | 3 |
| 2. Testing result | 4 |
| 3. Scope of testing | 5 |
| 4. Device Test Environment | 6 |
| a. Software items..... | 6 |
| b. Hardware and Firmware items..... | 6 |
| c. Other Materials..... | 6 |
| 5. Test Procedure..... | 7 |
| a. Test Bench | 7 |
| b. Architecture | 7 |
| c. Configuration process..... | 7 |
| 6. Test Report..... | 8 |
| a. General Description..... | 8 |
| b. Device Performance Information | 9 |
| c. IoT Device Control Information | 10 |
| 8. Disclaimers..... | 12 |
| ANNEX I: TheThinX Results | 13 |
| a. Service Delivery Results..... | 13 |
| b. Possible Network Impact Results | 14 |
| ANNEX II: Testing Details | 15 |
| a. Tested versions (Device under Testing) | 15 |
| b. History of testing..... | 15 |
| c. Bug tracking | 15 |
| ANNEX III: Document Version..... | 16 |
| ANNEX IV: Test Historical | 17 |
| ANNEX V: Telefonica bug Priority definition..... | 18 |



1. Tested Version

| | Device under Testing |
|-------------------|-----------------------------------|
| Model version | 54904 |
| SW/FW version | V0.2 |
| HW version | V01 |
| Module Model | Y7080E |
| Module FW version | 2212B07Y7080E-240506 ¹ |
| Chipset Model | XY1100 |

Table 1. Software Test Environment

¹ Latest SW version validated by Telefónica IoT & Big Data TECH (https://okapi.telefonica.com/iot_modules/).



2. Testing result²

As a result of testing service TheThinX, Telefonica has tested **JBM CAMPLLONG S.L.U. - 54904** device with the result of several non-blocking issues, with testing concluding in a total of **9** bugs.

Summarizing, this document records all the issues found, and Telefonica strongly recommends solving, as soon as possible, all issues defined as:

- “P2-High” issues (1) because they may affect the device functionality.
- “P3-Medium” issues (2) because they might affect the device functionality.
- “P4-Low” issues (6) are related to those features to take into account. Telefonica's recommendation is to solve them to achieve important product improvements.

It is important to point out that:

- Device Behaviour:
 - DuT follows Telefonica’s recommended retry and reboot scheme for V16 Traffic Beacons.
- SWAP functionality is not in the scope of testing.
- FOTA update is not in the scope of testing.
- DuT does not handle ACK reception.

² Please, refer to Annex V for more detailed information about bug priority.



3. Scope of testing

The testing of **JBM CAMPLLONG S.L.U. – 54904** has been executed using Telefónica Country and specific laboratory mobile communications network and infrastructure as and Global Kite Platform as the Telefonica managed connectivity platform.

The testing dates have been:

- Start of Testing: 25/08/2025
- End of testing: 01/09/2025

The testing scope has been based on the following testing blocks:

| General testing |
|-----------------------|
| General |
| Communication |
| Device Behaviour |
| Remote upgrade |
| Protocols |
| Stability |
| Device management |
| Physical |
| Power |
| Kite compatibility |
| Device identification |
| Use case specific |
| Specific tests |

Table 2. Software Test Environment



4. Device Test Environment

a. Software items

The software engineering environment shall be according to the following configuration:

| Tool | Description |
|------------------------------|---|
| CMW500 | Wideband Radio Communication Tester |
| Chrome | Web navigator |
| MobaXterm | AT analysis |
| Interoperability Test Center | SIM logs analysis |
| Word | Word processing and document creation |
| Otii | Energy optimization of battery-driven devices tool. |

Table 3. Software Test Environment

b. Hardware and Firmware items

The Hardware and Firmware engineering environment shall be according to the following configuration:

| Tool | Description |
|-----------------|--|
| M2M SIM Card | M2M SIM Card |
| CMW500 | Wideband Radio Communication Tester |
| JBM 5904 | Device Under Test |
| Comprion reader | SIM card reader |
| Otii | Energy optimization of battery-driven devices tool |

Table 4. Hardware Test Environment

c. Other Materials

External power supply.



5. Test Procedure

a. Test Bench




Figure 1. Simplified Test Bench

b. Architecture



Figure 2. Simplified Architecture of test bench

c. Configuration process

This section describes the steps to get to the previous initialization state.

Commissioning: Not provided.



6. Test Report

TheThinX has tested the JBM CAMPLLONG S.L.U. - 54904 in TheThinX laboratories. The results of the tests are following:

a. General Description

| | Device under Testing |
|-------------------|----------------------|
| Manufacturer | JBM CAMPLLONG S.L.U. |
| Date | 02/09/2025 |
| Model | 54904 |
| S/N, IMEI | 861269084697050 |
| FW Device Version | V0.2 |
| Technology | NB-IoT |
| FW Module Version | 2212B07Y7080E-240506 |

Table 5. General Description



b. Device Performance Information

| | | Device under Testing |
|---|---|---|
| Use Case | | Beacon signalling light with geolocation for safety in road traffic |
| Device Name³ | | 54904 |
| 3GPP Release | | 14 |
| PDP context opening/activation time | | 4 |
| Messages | Purpose⁴ | Update location |
| | Number/Day⁵ | Depend on the use case |
| | Upload/Download⁶ | 1 Up / 1 Down |
| | Payload size (Bytes)⁷ | 77 or 125 bytes up / 17 bytes down |
| | Message Size (Bytes)⁸ | 119 or 167 bytes up / 59 bytes down |
| Estimated Monthly Data Usage (Bytes)⁹ | | Depend on the use case |
| Consumption in a communication cycle | | 0.46 Wh |
| Avg. current drain | | 204 mA |
| Test Cases not applicable by DuT | | 7 |
| Blocked Test Cases | | 5 ¹⁰ |
| Executed Test Cases | | 69 |
| Total Test Cases | | 115 |

Table 6. Device Performance Information

³ DeviceName: Device Name collected in the SRF.

⁴ Msg/Purpose: Purpose of communication from the device (for example, water measurements, location data, etc).

⁵ Msg/NumberDay: Number of communications per day.

⁶ Msg/UpDown: Number of Up and Down messages in a communication (for example, 2 Up, 1 Down).

⁷ Msg/Payload: Number of bytes sent.

⁸ Msg/PayloadFinal: Msg/Payload with headers depending on the communication protocol.

⁹ Data Usage: Calculation of data that KITE would show monthly.

¹⁰ TCs blocked due to bug 155387 [Regional] Not retry policy when ACK is missing, SIM Card not available for TC-DVCTC-IOTAP-005c and missing messages between the network and the device for TC-MIPLF-PRFTC-031j and TC-MIPLF-PRFTC-032i



c. IoT Device Control Information

| | Device Under testing |
|---|----------------------|
| Collect device capabilities | Yes |
| Reset device | Yes |
| Error case. MO SMS restricted. | Yes |
| IMEI | Yes |
| Location | No |
| Signal Strength | No |
| Radio Technology supported | No |
| Radio Technology in use | No |
| Battery Level | No |
| Check device capability when DuT switched OFF | Yes |
| Check IMEI during PSM state | NA |
| Check IMEI during eDRX state | NA |

Table 7. IoT Device Control Information



7. Highlights of the testing

- Testing has finished with 9 bugs: 1 bug with priority P2 (High), 2 bugs with priority P3 (Medium) and 6 bugs with priority P4 (Low/Notification).
- Please refer to ANNEX II: Testing Details for more detailed information about testing results.



8. Disclaimers

- This report describes the tests executed on a given device under testing and the results of these tests.
- The report does not mean nor imply approval nor rejection of the solution. It neither implies that other devices of this class, not even the same device, will behave the same in later tests or situations.
 - Telefónica does not commit to arrive to a certain result derived from these tests.
- This report refers only to the version tested by Telefonica.
- This report refers only to the setup (device, communications and platform) employed.
- This report does not have any effect on any functionality not tested.
- In any case, the device under testing shall fulfil Telefonica requirements according to TDDC (Telefonica Device Design Council).
- Telefonica will not be responsible of any damage or loss provoked by the device under testing.

Best Regards,

José Rubén García Muñoz

On behalf of:
Technology & Integration | TheThinX
Telefónica IoT & Big Data TECH

Alberto Ramos Pérez

On behalf of:
Technology & Integration | TheThinX
Telefónica IoT & Big Data TECH



ANNEX I: TheThinX Results

a. Service Delivery Results

| Bug ID | Priority ¹¹ | Description | Business Impact | Recommendation |
|--------|------------------------|---|---|---|
| 155439 | P4 | Bands reported by the device and by the SRF do not match | The SRF may cause confusion regarding device configuration or usage | The manufacturer should fix this information in SRF |
| 155441 | P4 | The IoT Device Control functionality fails to collect the following device capability from Telefonica IoT platform: Location. | From Telefonica IoT platform will not be able to obtain the device capabilities | Manufacturer should provide a solution to support this functionality. |
| 155423 | P4 | Device does not support RPM parameters. | Device cannot be monitored remotely | Only informative issue. |
| 155440 | P4 | Service Request Form provided is not fulfilled with technical details | The SRF may cause confusion regarding device configuration or usage | The manufacturer should fix this information in SRF |
| 156127 | P4 | Updated state diagram not provided. | The different steps programmed in the device in case of success or failure during its operation are unknown | The manufacturer should provide an updated state diagram. |

Table 8. Service delivery results

¹¹ The meaning of Priority is included in ANNEX V: Telefonica bug Priority definition.



b. Possible Network Impact Results


| Test Case | Priority ¹² | Description | Network Impact | Recommendation |
|------------------|------------------------|--|--|--|
| 156126 | P2 | When the device is connected under roaming conditions, it remains attached for a short period of time but reboots before transmitting the protocol A frame. This behaviour occurs repeatedly in a loop. | The continuous re-attachments to the network generate unnecessary signalling traffic, which can lead to signalling channel congestion, especially when multiple devices exhibit the same behaviour under roaming conditions. |  Best_practices_beacon_V_16_V1.4_EN.pc |
| 155446 155447 | P3 | The device always registers to the network in a synchronized way. There is a slight offset between devices but it is always the same and not random. | In some network problems the devices communicate at the same time. As this kind of device is typically deployed in high densities it will certainly cause saturation in the base stations signalling channel. | |
| 155387 | P4 | The device does not implement a retry policy when not receiving an ACK. The device still working with normal behaviour and does not perform any reboot. | The device continues operating even when data transmission with ACK is failing. It does not change the retry interval nor perform a reboot to recover the service as quickly as possible. | |

Table 9. Possible network impact results

¹² The meaning of Priority is included in ANNEX V: Telefonica bug Priority definition.



ANNEX II: Testing Details

a. Tested versions (Device under Testing)

- Model: 54904
- SW version: V0.2



JBM - 54904 - ES -
ALL - (VERSION_SW_



JBM_54904_pretesti
ng_V02_logs.rar

b. History of testing


| | End of Testing date | SW versions | Final Report |
|-------------------------------|--------------------------------|-------------|--|
| 1st Testing | 1 st August 2025 | V0.1 |  Global Telefonica TheThinX Report_JBI |
| 2nd Testing | 1 st September 2025 | V0.2 | |

Table 10. History of testing

c. Bug tracking

| Bug ID | Summary | Status | Details |
|--|--|-------------------|--|
| 155412 | The device sends location data after losing GPS coverage | CLOSED INVALID | - Fixed in this additional testing with SW version: V0.2 |
| 155424 | Device enables and configures the extended protocol configuration options (ePCO) | CLOSED FIXED | - Fixed in this additional testing with SW version: V0.2 |
| 155442 | The device is not able to detect when SIM card is removed | CLOSED FIXED | - Fixed in this additional testing with SW version: V0.2 |
| 155443 155444 155445 | The device does not reboot after receiving Attach Reject with cause #3 #7 #6 | CLOSED FIXED | - Fixed in this additional testing with SW version: V0.2 |
| 155448 155449 155477 155478 155479 155480 | The device does not reboot after receiving Detach Request with cause #7 | CLOSED FIXED | - Fixed in this additional testing with SW version: V0.2 |

Table 11. Bug Tracking



ANNEX III: Document Version

| Version | Date | Author | Reviewed Impact | Change | Change Description |
|---------|------------|-------------|-----------------|--------|--------------------|
| 1.0 | 10/09/2025 | Emilio Mira | | | Opening Version |

Table 12. Document version



ANNEX IV: Test Historical

The historical test follows the document below:



Test_Historical.xlsx

| | Result |
|--|----------------------|
| Manufacturer | JBM CAMPLLONG S.L.U. |
| Model | 54904 |
| Debug Changes¹³ | 0 |
| Debug Time¹⁴ | 0 hours |
| Debug Time Average¹⁵ | 0 hours |

Table 13. Test history

¹³ Debug Changes: Number of times manufacturer support was required.

¹⁴ Debug Time: Total time it took the manufacturer to answer to support.

¹⁵ Debug Time Average: Debug Time divided by Debug Changes.



ANNEX V: Telefonica bug Priority definition

| Telefónica bug Priority | | Severity | Highlight | Description | Examples |
|-------------------------|---------|--------------|--|--|--|
| P1 | Highest | Critical | Most important: showstopper, blocking. | DuT can NOT be approved with this bug. | Bug is blocking device running or product tests or security and there is no workaround. DuT is not presenting mandatory certificates/documents. DuT behaviour is affecting network or other service users. |
| P2 | High | Medium | Very important, but not showstopper. | DuT's vendor must deliver a "solution plan": when it will be fixed. Telefonica will decide what to do then. | Bug is blocking device running or product tests or security and there is uneasy workaround. |
| P3 | Medium | Low | Should be solved. | DuT's vendor should provide a solution but a wontfix is acceptable. Solution is less priority than P2 bug. | Bug is blocking device running or product tests or security but there is easy workaround. Bug is affecting secondary feature. |
| P4 | Low | Notification | Something to highlight. | Something to consider for the future. The only difference between P3 and P4 is that the P3's is preferred to be solved before the P4's. | Improvement or inconvenience to consider. DuT behaviour is not following Telefonica device behaviour recommendations. |

Telefónica bug Severity

Severity field is in practice not considered for Telefonía to avoid the possibility of giving contradictory messages between the Priority and Severity fields

Please feel free to ignore it.

The default value is Critical, Medium, Low or Notification for bugs of priorities P1, P2, P3 and P4, respectively, but the testers could change it.

Table 14. Bug priority definition

