At the Repair Bench – NanoVNA Touch Screen – June 2023

One recent Saturday afternoon, one of our fellow club members had cause to use the club's NanoVNA for some new equipment testing. Unfortunately, when he tried to operate the unit, the touch-screen feature was not working, and in fact, it seemed that the menu system was completely inoperative. I decided to bring it home with me to make the required repairs.

The club's NanoVNA is the H4 (Figure 1) variant which, at the time, was loaded with the DiSlord version 1.1.01 firmware dated 30 December 2021. While the firmware was most likely not the cause of the problem, as the unit had been working fine for a long while, I did notice that



the firmware was about a year and a half old, which is a lifetime by today's electronic equipment standards. I slated it for a firmware update as a part of the repair.

In testing the NanoVNA quite thoroughly, I found that occasionally, I could get the menu system to operate via the multi-function control (MFC) wheel on the unit's top edge, after which the touch screen would occasionally operate until the next power-off. However, it was not consistent enough to say that this would be a usable work-around, so I kept on digging for an answer.

I opened up the unit and disconnected the battery and the touch screen ribbon cable. I then reseated the ribbon cable, reconnected the battery, and powered up the device. No change was evident, with the touch screen and menu system operating the same as it had before the disconnects.

A few more words about the actual behavior would seem appropriate at this point. If I was able to get the menu system to launch using the MFC wheel, it was then possible to navigate the menu using the stylus via the touch screen. It was even possible to re-launch the menu system via the touch screen, until the unit was powered off. Then the problem re-asserted itself and it was pot luck as to whether or not the menus would open via the MFC.

I turned to that giant reference resource called the internet for some help, and I came across an obscure reference in a forum somewhere – I never noticed where – that made mention of



Figure 2 - Threshold setting

NanoVNA stability. This seemed to fit, so I looked some more into that concept – stability and how to control it. What I found was that the default settings for the DiSlord firmware versions are set to slightly overclock the NanoVNA. I decided to slow it down a little bit and see what happens.

The clock speed of the NanoVNA is controlled by a firmware value called *Threshold*, which is set to 300.000100MHz by default. The *Threshold* setting is found under *Config* > *Expert Settings*. I decided to set it down to 290MHz. *Voilá*! The touch screen now behaved

normally in every regard! I figured that I had resolved this issue, though I still did not understand

what had happened, or specifically why it spontaneously stopped working after operating for so long, but I chose not to worry about that at this point.

I next went about performing a firmware upgrade on the NanoVNA. This is a simple operation that is done using the STMicroelectronics DfuSe software. I had the software (Figure 3) installed on my PC already, so all that I needed to do was to download the newest DiSlord firmware file in the commonly-used .dfu firmware format. That filename is NanoVNA.H4.v1.2.20.dfu which indicates that the firmware is version 1.2.20, dated 12 March 2023. The various firmware files can be downloaded from https://github.com/DiSlord/NanoVNA-D/releases under the Assets listing.

To update the firmware in the NanoVNA, the device must be placed into DFU mode. Start out by launching the

STM Device in DFU Mode			~		cation Mode:	DFU Mode:	
 Supports Uplo Supports Down Can Detach 	ad nload	Manifestation Accelerated I	tolerant Jpload (ST)	Procu Ver	ct ID:	Procuct ID	DF11
Enter DFU mode/HID detach			e DFU mode			2200	
octions							
Select <u>T</u> arget(s):	Target Id	Name			Available Sectors	(Double Click	for more
	00	Internal Flash			128 sectors		
	01	Option Bytes			1 sectors		
File:		i	File: Vendor ID:		Targets in fi	e:	
Transforred data	eine S	F	Procuct ID:		_		
indiministration under	O KB(O Buter) of O KB(O Buter)		Version:				
O V P(O Putera) of	o volo pàtes		Verify after	downl	oad		
0 KB(0 Bytes) of			Optimize L	pgrade	duration (Remov	/e some FFs)	
0 KB(0 Bytes) of	n						

Figure 3 - DfuSe utility interface

STMicro DfuSe software and connecting the NanoVNA to the PC via an appropriate USB cable. Then, put the NanoVNA into DFU mode by holding down the MFC wheel while powering up the unit. Note that the screen will remain black in DFU mode, but the STMicro DfuSe software should indicate that the NanoVNA is connected and accessible. The net step is to use the *Choose* button in the DfuSe software to open the *.dfu* firmware file. The software will show

Course I Internet	Vendor ID:	0483	Targets in file: 00 ST
Puoose".	Procuct ID:	0000	
Transferred data size	Version	0000	
Operation duration 00:00:00	Chgose	Upgråde	duration (Remove some FFs) Upgrade <u>V</u> erify

Figure 4 - Firmware loaded in DfuSe

(Figure 4) that the firmware file was successfully loaded into the utility and that it is ready for upload to the device. Upload that file to the device by clicking the *Upgrade* button. Once the upgrade is completed as indicated in the software (Figure 5), power off the NanoVNA and disconnect it from the PC.

The interesting thing about this repair is that post-upgrade of the firmware, that new firmware *Threshold* setting was once

again set to 300.000100MHz... but the unit was operating properly and with many more menu options than it had before.

OK – so slowing the clock speed solved the initial touch screen response issue in the old firmware. Of that there is no doubt. As a result, I feel comfortable suggesting that as a solution for anyone who may encounter a similar issue with the touch screen on a NanoVNA H4 and needs an immediate fix.

t ID: 0000 00 ST
ifu after download
imize Upgrade duration (Remove some FFs) gose Upgrade Verify
rade successful !

Figure 3 - Firmware update successful

I also feel comfortable recommending the firmware upgrade to DiSlord version 1.2.20, as I have now installed and tested it extensively, and everything works as it should. Some of the new features include the ability to save a calibration set to the SD card, enter a custom name for any image file saved to the SD card (or simply check the *Autoname* check box to avoid having to enter a name – it will default to a date and time format naming convention). The new firmware allows loading an image from the SD card into the display, and there is also a *Pause Sweep* and *Resume Sweep* capability now. There are several changes to the *Calibrate* menu item as well as to several other menu items. This new firmware version is feature-rich and is well worth installing.

Having explored the new menu items and capabilities of the NanoVNA H4 under DiSlord firmware 1.2.20, I am happy to report that all of the new features work well, and are for the most part self-explanatory or very intuitive. This makes these new features easy to use without needing any type of documentation for them. I like the new firmware so much that I also installed it onto my personal H4 unit.

See you next month...

