

7225 Highview Rd Port Hardy, BC V0N2P0

PREPARED FOR:

GLENN JOHNSON DAVE MCCULLOUGH

INSPECTION DATE:

Monday, March 14, 2016

PREPARED BY:

Andrew Philliskirk AScT, CHIP





Philliskirk Enterprises 8895 Darwin Street Chilliwack, BC V2P 6W7

(604) 219-2591

www.philliskirk.com andrew.philliskirk@gmail.com

7225 Highview Rd, Port Hardy, BC March 14, 2016

SUMMARY ROOFING **EXTERIOR** STRUCTURE **HEATING PLUMBING** INTERIOR REFERENCE

Note: For the purpose of this report the building is considered to be facing North.

Scope of Inspection:

I have performed an inspection of the Property in accordance with the attached Applied Science Technologists and Technicians of British Columbia Property Inspectors (ASTTBC PI) Standards of Inspection approved by the Applied Science Technologists and Technicians of British Columbia.

The Inspection was limited to a visual inspection performed by direct observation of existing conditions reasonably apparent at the time of inspection in accordance with the Standards of Inspection and Scope of Inspection.

The following is a summary of the "Report of the Inspection" which outlines potentially significant issues from a cost or safety standpoint. This section is provided as a courtesy and cannot be considered a substitute for reading the entire report. Please read the complete document.

Priority Maintenance Items

Roofing

General

 This modified bitumen roofing is most likely the second roof this building has had since it was built in the 1980's. It is nearing the end of its' useful life and should be replaced soon. Being subjected to many years of sunlight without a UV protective coating has cracked the membrane in several locations. There has been extensive patch work all over the roof. The flashings will need to be replaced when the roof is replaced as they are very rusted.

Exterior

General

• The exterior of the building hasn't been cleaned for a while. Because of the marine environment here in Port Hardy excessive organic growth has built up on the siding, decks and many other surfaces. Some of the building materials could deteriorate due to the trapped moisture. The building needs to be cleaned and exposed wood painted or sealed to protect it.

Structure

General

• The block walls have been subject to years of exposure to the weather. They have suffered from many wet-freeze cycles causing spalling. The deteriorated masonry poses a structural and possibly a safety hazard. It should be reviewed by a qualified stone mason to see if it is structurally sound. It may just need repointing, re-sealing (paint) and ensuring that adequate weep holes exist.

Some outer deck framing was spongy and may need replacing soon. The guard rail pickets should be checked out by a carpenter to ensure they are adequately attached.

7225 Highview Rd, Port Hardy, BC March 14, 2016

SUMMARY ROOFING **EXTERIOR** STRUCTURE **HEATING PLUMBING** INTERIOR REFERENCE

Electrical

General

• During the inspection it was raining outside. The electrical room had a steady flow of water running underneath the main cabinets causing the the metal cabinets to rust along the bottom. The water flowed into the room adjacent where a sump pump was set up to extract the water.

The perimeter drainage beside these panels needs to be looked at to see what is wrong. A drainage company should be brought in to review the performance of the perimeter drainage and figure out where the water is coming from and how to stop it. They could send a video camera down the drainage lines to look for problems like blockages.

Once the water ingress has been stopped a certified electrical professional should be brought in to assess these cabinets for safety.

Plumbing

General

• This building has separate water heaters in each unit. There are too many installation errors and omissions regarding these water tanks to list separately. The amateurish work leads me to believe that the installations were performed by unqualified installers. There are many safety and flood hazards that need to be rectified as soon as possible. A qualified plumber should be brought in to review and bring each tank up to code. The higher than usual pressure should be reduced by installing a pressure regulator right after the main shutoff valve.

Interior

General

 Some of the windows showed signs of excessive condensation which appeared to be coming from the interior of the units. The cause is usually high humidity in the suites in conjunction with lack of heat and ventilation to the windows (ie. heavy curtains blocking air flow and preventing heat from reaching the glass). The moisture is causing condensation on the window frames which is running down and puddling on the window sills. The sills are starting to deteriorate and may need to be replaced. As this was only a visual inspection I could not tell if the wall framing below the sills were affected by the water. If a sill is getting replaced the studs should be checked while the framing is visible.

The window frames showed signs of organic matter building up and should be cleaned up with chlorine/bleach and water solution to prevent re-occurrence.

This concludes the Summary section.

The remainder of the report describes each of the building's systems and also details any recommendations I have for improvements. Limitations that restricted the inspection are included as well.

The suggested time frames for completing recommendations are based on the limited information available during a pre-purchase home inspection. These may have to be adjusted based on the findings of specialists.

Home Improvement - ballpark costs

7225 Highview Rd, Port Hardy, BC March 14, 2016

SUMMARY ROOFING STRUCTURE ELECTRICAL PLUMBING REFERENCE

Description

Flat roofing material:

• Modified bitumen

The flat roof material appears to be a modified bitumen roll roofing.

Probability of leakage: • High

Recommendations

General

1. • This modified bitumen roofing is most likely the second roof this building has had since it was built in the 1980's. It is nearing the end of its' useful life and should be replaced soon. Being subjected to many years of sunlight without a UV protective coating has cracked the membrane in several locations. There has been extensive patch work all over the roof. The flashings will need to be replaced when the roof is replaced as they are very rusted.

FLAT ROOFING \ Modified bitumen

2. Condition: • Near end of life expectancy

Implication(s): Chance of water damage to contents, finishes and/or structure

3. Condition: • Cracked

Implication(s): Chance of water damage to contents, finishes and/or structure





1. Surface cracks, splitting


2. Surface cracks, splitting

4. Condition: • Patched

Implication(s): Chance of water damage to contents, finishes and/or structure

7225 Highview Rd, Port Hardy, BC March 14, 2016

REFERENCE PLUMBING SUMMARY ROOFING STRUCTURE ELECTRICAL





3. Patched

5. Condition: • No UV protection (paint, granules, etc.)

Implication(s): Chance of water damage to contents, finishes and/or structure

7225 Highview Rd, Port Hardy, BC March 14, 2016


SUMMARY ROOFING STRUCTURE REFERENCE



4. No UV Protection

6. Condition: • Ponding

Implication(s): Chance of water damage to contents, finishes and/or structure | Chance of movement



SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING PLUMBING INTERIOR REFERENCE





6. Ponding

5. Ponding

FLAT ROOF FLASHINGS \ Wear or damage

7. Condition: • Rust

Implication(s): Chance of water damage to contents, finishes and/or structure





7. Rust **8.** Rust

7225 Highview Rd, Port Hardy, BC

March 14, 2016

PLUMBING SUMMARY ROOFING STRUCTURE REFERENCE EXTERIOR

Description

Gutter & downspout material:

• <u>Aluminum</u>



9. Aluminum

• Plastic



10. Plastic

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING PLUMBING INTERIOR REFERENCE

Gutter & downspout type: • Integral/built-in

Gutter & downspout discharge:

• Below grade



11. Below grade



12. Below grade

Lot slope:

Away from building



13. Away from building

• Towards building

7225 Highview Rd, Port Hardy, BC

Report No. 1013, v.5

SUMMARY PLUMBING INTERIOR ROOFING STRUCTURE ELECTRICAL EXTERIOR

March 14, 2016



14. Towards building

Wall surfaces - masonry:

• Block



15. *Block*

Wall surfaces and trim:

• Metal siding

REFERENCE

7225 Highview Rd, Port Hardy, BC

March 14, 2016

SUMMARY ROOFING

EXTERIOR

STRUCTURE

HEATING

PLUMBING

INTERIOR

REFERENCE



16. Metal siding

Driveway:

Asphalt



17. Asphalt

Walkway:

• Concrete

7225 Highview Rd, Port Hardy, BC

SUMMARY ROOFING EXTERIOR

STRUCTURE ELECTRICAL

March 14, 2016

PLUMBING

INTERIOR

REFERENCE



18. Concrete

Exterior steps: • Concrete

Balcony: Wood



19. Wood

Patio: • Concrete Fence: • Wood

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING PLUMBING INTERIOR REFERENCE

Recommendations

General

8. • The exterior of the building hasn't been cleaned for a while. Because of the marine environment here in Port Hardy excessive organic growth has built up on the siding, decks and many other surfaces. Some of the building materials could deteriorate due to the trapped moisture. The building needs to be cleaned and exposed wood painted or sealed to protect it.

WALLS \ Metal siding

9. Condition: • <u>Discolored</u>Implication(s): Cosmetic defects



20. Discolored



22. Discolored



21. Metal siding



23. Discolored

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING PLUMBING INTERIOR REFERENCE

WALLS \ Brick, stone and concrete

10. Condition: • Masonry deterioration

Implication(s): Weakened structure | Chance of structural movement



24. Missing, ineffective weep holes or flashings



25. Masonry deterioration

EXTERIOR GLASS \ Glass (glazing)

11. Condition: • Excess condensation

Implication(s): Chance of damage to finishes and structure



26. Excess condensation

LANDSCAPING \ Walkway

12. Condition: • Uneven (trip hazard)


Implication(s): Physical injury

7225 Highview Rd, Port Hardy, BC

Report No. 1013, v.5

PLUMBING SUMMARY REFERENCE EXTERIOR STRUCTURE ELECTRICAL

March 14, 2016





27. Uneven (trip hazard)

LANDSCAPING \ General

13. Condition: • Siding too close to grade


Implication(s): Chance of water entering building | Weakened structure | Rot | Insect damage

7225 Highview Rd, Port Hardy, BC

Report No. 1013, v.5

SUMMARY REFERENCE PLUMBING EXTERIOR STRUCTURE

March 14, 2016





28. Siding too close to grade

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING PLUMBING INTERIOR REFERENCE

Description

Configuration: • <u>Slab-on-grade</u>

Foundation material: • Poured concrete

Floor construction: • Joists

Exterior wall construction: • Wood frame • Masonry

Roof and ceiling framing: • Not visible

Party walls: • Masonry

Recommendations

General

14. • The block walls have been subject to years of exposure to the weather. They have suffered from many wet-freeze cycles causing spalling. The deteriorated masonry poses a structural and possibly a safety hazard. It should be reviewed by a qualified stone mason to see if it is structurally sound. It may just need repointing, re-sealing (paint) and ensuring that adequate weep holes exist.

Some outer deck framing was spongy and may need replacing soon. The guard rail pickets should be checked out by a carpenter to ensure they are adequately attached.

WALLS \ Solid masonry walls

15. Condition: • Masonry deteriorating

Implication(s): Weakened structure | Chance of structural movement



29. Masonry deterioration

16. Condition: • Efflorescence

Implication(s): Cosmetic defects | Weakened structure

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING PLUMBING INTERIOR REFERENCE

17. Condition: • Mortar deteriorating

Implication(s): Weakened structure | Chance of structural movement



30. Masonry deterioration

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING PLUMBING INTERIOR REFERENCE

Description

Service entrance cable and location: • Underground copper

Service size: • 400 Amps (240 Volts)

Main disconnect/service box rating: • 400 Amps

Main disconnect/service box type and location: • Breakers - utility room

Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI): • GFCI - bathroom

Recommendations

General

18. • During the inspection it was raining outside. The electrical room had a steady flow of water running underneath the main cabinets causing the the metal cabinets to rust along the bottom. The water flowed into the room adjacent where a sump pump was set up to extract the water.

The perimeter drainage beside these panels needs to be looked at to see what is wrong. A drainage company should be brought in to review the performance of the perimeter drainage and figure out where the water is coming from and how to stop it. They could send a video camera down the drainage lines to look for problems like blockages.

Once the water ingress has been stopped a certified electrical professional should be brought in to assess these cabinets for safety.



31.



32.

DISTRIBUTION SYSTEM \ Wiring - damaged or exposed

19. Condition: • Exposed on walls or ceilings

Implication(s): Electric shock

ROOFING SUMMARY

STRUCTURE ELECTRICAL

PLUMBING

INTERIOR

REFERENCE



33. Exposed on walls or ceilings



34. Exposed on walls or ceilings



35. Exposed on walls or ceilings



36. Exposed on walls or ceilings

HEATING Report No. 1013, v.5

7225 Highview Rd, Port Hardy, BC March 14, 2016

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING PLUMBING INTERIOR REFERENCE

Description

General: • Each unit has individual baseboard heaters with zone controls. They seem to be performing as they should.

Fuel/energy source:

• Electricity

Baseboards in each unit.

System type: • Electric baseboard heaters

Approximate age: • 36 years

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING PLUMBING INTERIOR REFERENCE

Description

Water supply source:

Public



37. Public

Service piping into building: • Copper Supply piping in building: • Copper

Main water shut off valve at the: • Utility room Water flow and pressure: • Above average

Water heater fuel/energy source:

• Electric
In each unit -

Recommendations

General

20. • This building has separate water heaters in each unit. There are too many installation errors and omissions regarding these water tanks to list separately. The amateurish work leads me to believe that the installations were performed by unqualified installers. There are many safety and flood hazards that need to be rectified as soon as possible. A qualified plumber should be brought in to review and bring each tank up to code. The higher than usual pressure should be reduced by installing a pressure regulator right after the main shutoff valve.

SUPPLY PLUMBING \ Pressure regulator

21. Condition: • Required due to high supply water presssure


There is no visible pressure regulator in the utility room. The water pressure was over 100psi and should be reduced to prevent possible leaks.

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING PLUMBING INTERIOR REFERENCE

Implication(s): Chance of damage to contents, finishes and/or structure | Damage to equipment

Task: Improve





39. Required due to high supply water presssure

38. Typical for neighborhood

22. Condition: • Static water pressure should not exceed 80 psi

Implication(s): Chance of water damage to contents, finishes and/or structure | Damage to equipment

WATER HEATER \ Tank

23. Condition: • Wobbly or not stable

This tank in the laundry room needs to be seismically restrained.

Implication(s): Damage to equipment | No hot water

7225 Highview Rd, Port Hardy, BC March 14, 2016

STRUCTURE REFERENCE SUMMARY ROOFING PLUMBING



40. Wobbly or not stable

24. Condition: • Safety pan and drain defect

Implication(s): Chance of water damage to contents, finishes and/or structure | Damage to equipment

WATER HEATER \ Temperature/pressure relief valve

25. Condition: • Water Heater missing vacume relief valve.


Implication(s): The tank may be crushed from vacuum if Water Main is shut off and a valve opened.

26. Condition: • Discharge tube too short

Implication(s): Scalding

7225 Highview Rd, Port Hardy, BC March 14, 2016

SUMMARY ROOFING STRUCTURE **PLUMBING** REFERENCE





41. Discharge tube too short

27. Condition: • Missing temperature protection


Implication(s): Steam explosion

WATER HEATER \ Isolating valve/Cold water shut-off valve

28. Condition: • Missing

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING PLUMBING INTERIOR REFERENCE

Implication(s): Increased maintenance costs



FIXTURES AND FAUCETS \ Hose bib or bibb

29. Condition: • Leak or drip

Implication(s): Chance of water damage to contents, finishes and/or structure

7225 Highview Rd, Port Hardy, BC March 14, 2016

SUMMARY STRUCTURE ELECTRICAL HEATING INTERIOR REFERENCE ROOFING PLUMBING



42. Leak or drip

7225 Highview Rd, Port Hardy, BC ROOFING **PLUMBING** INTERIOR REFERENCE

March 14, 2016

Recommendations

General


30. • Some of the windows showed signs of excessive condensation which appeared to be coming from the interior of the units. The cause is usually high humidity in the suites in conjunction with lack of heat and ventilation to the windows (ie. heavy curtains blocking air flow and preventing heat from reaching the glass). The moisture is causing condensation on the window frames which is running down and puddling on the window sills. The sills are starting to deteriorate and may need to be replaced. As this was only a visual inspection I could not tell if the wall framing below the sills were affected by the water. If a sill is getting replaced the studs should be checked while the framing is visible.

The window frames showed signs of organic matter building up and should be cleaned up with chlorine/bleach and water solution to prevent re-occurrence.

WINDOWS \ Glass (glazing)

31. Condition: • Excess condensation

Implication(s): Chance of condensation damage to finishes and/or structure



7225 Highview Rd, Port Hardy, BC March 14, 2016

REFERENCE SUMMARY ROOFING PLUMBING STRUCTURE INTERIOR



43. Excess condensation

APPLIANCES \ Washing machine

32. Condition: • Inoperative Two machines out of service.

Implication(s): Equipment inoperative



44. Inoperative

APPLIANCES \ Dryer

33. Condition: • Dryer vent material not smooth wall Implication(s): Equipment ineffective | Fire hazard

7225 Highview Rd, Port Hardy, BC March 14, 2016

SUMMARY ROOFING PLUMBING REFERENCE STRUCTURE INTERIOR



45. Dryer vent material not smooth wall

34. Condition: • Screen on vent termination Dryer vents stuck open. Entry point for vermin. Implication(s): Equipment ineffective | Fire hazard



46. Screen on vent termination

END OF REPORT

REFERENCE LIBRARY

Report No. 1013, v.5

7225 Highview Rd, Port Hardy, BC March 14, 2016

SUMMARY

ROOFING

STRUCTURE ELECTRICAL

PLUMBING

REFERENCE

The links below connect you to a series of documents that will help you understand your home and how it works. These are in addition to links attached to specific items in the report.

Click on any link to read about that system.

- 01. ROOFING, FLASHINGS AND CHIMNEYS
- 02. EXTERIOR
- 03. STRUCTURE
- 04. ELECTRICAL
- 05. HEATING
- 06. COOLING/HEAT PUMPS
- 07. INSULATION
- 08. PLUMBING
- 09. INTERIOR
- 10. APPLIANCES
- 11. LIFE CYCLES AND COSTS
- 12. SUPPLEMENTARY

Asbestos

Radon

Urea Formaldehyde Foam Insulation (UFFI)

Lead

Carbon Monoxide

Mold

Household Pests

Termites and Carpenter Ants

- 13. HOME SET-UP AND MAINTENANCE
- 14. MORE ABOUT HOME INSPECTIONS





HOME INSPECTION CONTRACT					
CLIENT:					(THE "CLIENT"
ADDRESS:					
CLIENT:					
ADDRESS:					
BENEFICIARY:					
ADDRESS:					
INSPECTOR:					
INSPECTOR		LICENSE#			ASTTBC PI NO.
DOING BUSINESS AS:					
Property:					
ADDRESS OF PROPERTY TO BE INSPECTED					
DATE OF INSPECTION	TIME				
Fees:					
BASIC FEE:	\$				
MISC, FEE:	\$				
GST#:	\$				
PST#:	\$		-		
TOTAL:	S				
This Agreement, made and entered into on this the purpose of a pre purchase inspection. The repo	day of ort format will co	, 20 nsist of	in a full 1	, B.C. by	the above named Clients for
This Agreement contains terms which limit the this Agreement.	liability of the I	nspecto	r. Plea	se read ca	refully before executing
In executing this Agreement, you, the Client, acknown entirety and, should you choose to do so, to obtain immediately below and returning this Agreement to	independent lega				
CLIENT (please print) CLIENT (p.	lease print)		ī	BENEFICIARY	(please print)
CLIENT (signature) CLIENT (st					





TERMS AND CONDITIONS GOVERNING THIS AGREEMENT

Scope of Services

- 1.1 The Inspector will perform an inspection of the Property in accordance with the attached Applied Science Technologists and Technicians of British Columbia Property Inspectors (ASTTBC PI) Standards of Inspection approved by the Applied Science Technologists and Technicians of British Columbia (the 'Inspection'). ASTTBC PI is established under the provisions of the Applied Science Technologists and Technicians (ASTT) Act, to represent the professionally Certified House and Property Inspectors in British Columbia.
- 1.2 The Inspection shall be limited to a visual inspection performed by direct observation of existing conditions reasonably apparent at the time of inspection in accordance with the Standards of Inspection and Scope of Inspection.
- 1.3 Following the Inspection, the Inspector will provide the Client with a Report of the Inspection (the 'Report').

2. Limitation of Liability

This section contains the limitations upon any liability that may be imposed in law upon the Inspector arising from the professional services provided to you by that Inspector. Please read carefully.

- 2.1 Any and all actions, causes of action, contracts, demands or claims, whether in contract, negligence, or otherwise known to law, which you may have arising out of services provided to you by the Inspector, hereinafter referred to as a "Claims" or "Claim", shall be regarded as a single claim subject to the further limitations of liability set out below.
- 2.2 The liability of the Inspector, whether in contract, tort (including negligence) or other cause of action known to law shall be limited to the lesser amount of \$50,000 or the amount of our professional liability insurance in effect as at the date of the Claim being made known to us and only to the extent that such insurance is available to satisfy the Claim. If this limit of liability is insufficient for your purposes, the Inspector would be pleased to discuss with you a different limit which, if greater than \$50,000, may result in our charging a higher fee.
- 2.3 If the Inspector is incorporated, you expressly agree that you will not bring any proceedings in any arbitration or court of any jurisdiction advancing any Claim against our professional staff and employees.
- 2.4 You expressly agree that any liability the Inspector may have to you shall not be joint and several with any other person, but shall be several only, and limited to the percentage or degree of the Inspector's fault in proportion to the fault or wrongdoing of all persons who contributed to the loss arising from the Claim.





- 2.5 The Inspector's liability for all Claims you may have or bring in connection with the professional services rendered or arising out of or ancillary to this Agreement shall absolutely cease to exist after a period of two (2) years from the date of:
 - a) Performance of the Inspection;
 - b) Delivery to you of our Inspector's Report;
 - c) Suspension or abandonment of this Agreement; or
 - d) Termination of the Inspector's services pursuant to this Agreement,

whichever shall occur first, regardless of whether you were aware of the potential for making a Claim against the Inspector within that period. Following the expiration of the aforesaid period, you agree that you shall make no Claim against the Inspector, the Inspector shall have no liability to you, and you shall not bring any proceedings of any kind known to law against the Inspector.

2.6 The intellectual material amassed from the Inspections is the property of the Inspector. The Report shall be prepared for the Client's information only and may not be used or relied upon by any other person unless that person is specifically named in this Agreement as a beneficiary of the Report, in which case the Report may also be used by the additional beneficiary named. The Client agrees to maintain the confidentiality of the Report and reasonably protect the Report from distribution to any other person. If the Client directly or indirectly causes the Report to be distributed to any other person, the Client shall indemnify, defend, and hold the Inspector harmless against the claim of any third party.

3. No Warranty

3.1 The Inspection does not constitute a warranty, an insurance policy or a guarantee of any kind.

4. Dispute Resolution

- 4.1 In the event of any Claim arising under this Agreement, the Client shall immediately give notice in writing to the Inspector of all particulars of the Claim and shall give the Inspector all reasonable opportunity to inspect the Property and, where appropriate, resolve the matters in dispute.
- 4.2 The Client acknowledges that any failure on the Client's part to give timely notice of all particulars of the Claim will deprive the Inspector of the opportunity to reasonably investigate and, where appropriate, resolve the Claim. In the event that the Inspector is prejudiced by the Client's failure to give notice of the Claim in accordance with Section 4.1 of this Agreement, then the Client expressly waives any right to recover from the Inspector any losses arising from the Claim.
- 4.3 Any dispute between the Inspector and the Client, except those for non-payment of fees, that in any way, directly or indirectly, arise out of, or relate to this Agreement or to the interpretation of this Agreement, the scope of the services provided to the Client, the Report or any other matter involving the services performed by the Inspector, shall, upon either party's election, be resolved in accordance with the British Columbia Commercial Arbitration Act (the 'Act'), by a single arbitrator appointed in accordance with the Act.



5. Other Provisions

- 5.1 Payment in full is due upon the completion of the Inspection and prior to delivery of the Report.
- 5.2 The validity or unenforceability of any provision in this Agreement shall not affect or impair the validity or enforceability of any other provision. The remainder of this Agreement shall remain in full force and effect.
- 5.3 This Agreement contains the entire agreement between the parties, and shall be binding upon and enforceable by the parties, their heirs, executors, administrators, successors and assigns.
- 5.4 The Client agrees to obtain permission from the seller permitting deactivation of the distribution portion of the electrical panel so that the cover may be safely removed by the Inspector to inspect the interior.
- 5.5 The Client shall ensure the Inspector has access to the property; that a designated party provides security for the property during the inspection process and that someone responsible for the property will ensure that the property is secured upon the Inspector's departure.
- 5.6 This Agreement shall be construed in accordance with, and governed by, the laws of British Columbia.
- 5.7 Where required, the singular shall be read in the plural, and the gender the masculine or feminine.
- 5.8 Time shall be of the essence of this Agreement, save as otherwise specified in this Agreement.





ASTTBC PI STANDARDS OF INSPECTION

Part 1: Glossary (CONTAINS ITALICIZED WORDS IN THIS DOCUMENT)

ASTTBC & ASTTBC P1: ASTTBC - The Applied Science Technologists and Technicians of British Columbia (see

http://www.asttbc.com/ for more information). ASTTBC is the certifying body for the members of ASTTBC PI. Applied Science Technologists and Technicians of British Columbia Property Inspectors

(see www.asttbcpi.org for more information).

COMMON AREA(S): In condominium and some cooperative housing projects, the areas not owned by an individual owner of

the condominium or cooperative residence, but shared by all owners, either by percentage interest or owned by the management organization. Common areas may include recreation facilities, outdoor space, parking, landscaping, fences, laundry rooms and all other jointly used space. Management is by a homeowners' association or cooperative board, which collects assessments from the owners and pays for upkeep, some insurance, maintenance and reserves for replacement of improvements in the common

areas.

DIRECT OBSERVATION: Observation within arm's length.

INSPECTED UNIT: (Relating to Multi-Family Dwellings) - Individual suite, apartment, or unit being inspected. Does not

include any common area(s).

INSPECTOR: Members of ASTTBC PI having the appropriate technical training, experience, knowledge, and

qualifications and who have been certified by ASTTBC with the designations of Certified House Inspector

(CHI) or Certified Property Inspector (CPI).

MULTI-FAMILY DWELLING: Building or group of buildings on a single lot arranged or designed for occupancy by two or more

families, with separate housekeeping and cooking facilities for each and where the individual family units have unique legal addresses. A house with a legal suite is **NOT** considered a Multi-Family Dwelling. The Multi-Family Dwelling usually refers to a condominium but can also refer to buildings under the control

of a Housing Cooperative, Single Owner Rental Apartment Complexes, etc.

QUALIFIED TRADES PERSON: A certified and licensed professional in their field (Plumbers, Carpenters, Electricians, etc.).

REGISTERED PROFESSIONAL: Individuals who are registered members of the Professional Engineers and Geoscientists of BC

(APEGBC) or the Architectural Institute of BC (MAIBC) or Applied Science Technologist - AScT

(ASTTBC) or Certified Technician - CTech (ASTTBC).

SPECIALIST: Individuals having the appropriate technical training, experience, knowledge, and qualifications for

obtaining a provincial license or trade qualification or; a REGISTERED PROFESSIONAL practicing

within their area of specialization.

VISUAL INSPECTION: Observation without the use of any specialized tools or equipment.

Readily accessible: In the sole determination of the inspector, visually observable and able to be examined without requiring

destructive measures; without risk to the inspector or others; without risk of damage to any item of personal or real property; without requiring the inspector to move, remove, damage, or disturb any wall, floor, ceiling, or window coverings; or any interior or exterior claddings or finish treatments; to move, remove, damage, disturb, climb upon, climb over, or straddle any item of personal property; to move, remove, damage, or disturb any landscape elements; or to interrupt the business of occupants, and not requiring disassembly or the use of any special protective clothing or special tools or equipment"





Part 2: Limitations of the Inspection

- The Inspection is a VISUAL INSPECTION performed by DIRECT OBSERVATION of existing conditions at the time of inspection and shall be conducted by a CERTIFIED HOUSE INSPECTOR PROVISIONAL (CHI-P); CERTIFIED HOUSE INSPECTOR (CHI) or CERTIFIED PROPERTY INSPECTOR (CPI) (identified as the INSPECTOR in the rest of this document) acting in accordance to this ASTTBC PI Standards of Inspection approved by ASTTBC.
- The Inspectors with <u>CHI-P and CHI designations</u> are limited to the inspection of single-family dwellings, duplexes, individual
 townhouse units, single units in apartment buildings and multi-family complexes up to a four units which shall commensurate
 with their level of certification, qualification, experience and knowledge. Inspectors with a <u>CPI designation</u> can inspect all
 residential properties as well as commercial, industrial or investment real estate property.
- 3. The Inspection is of a general nature and not that of a SPECIALIST. A SPECIALIST serves to provide additional analysis and opinion of adverse conditions or defects identified, beyond the scope of the inspection. CLIENTS SHOULD BE AWARE OF THE LIMITATIONS OF THIS INSPECTION AND ARE ENCOURAGED TO CAREFULLY CONSIDER ANY RECOMMENDATIONS FOR FURTHER INVESTIGATION, READ AND UNDERSTAND ALL PERTINENT STRATA REPORTS, DOCUMENTS, MINUTES, AND RECORDS, AND SEEK ANY FURTHER INVESTIGATION OR CLARIFICATION PRIOR TO PURCHASE.
- The INSPECTOR shall NOT offer warranties or guarantees of any kind for any building system or component.
- The ASTTBC PI Standards of Inspection does NOT cover or require the INSPECTOR to identify or report on the presence of asbestos, radon gas, lead paint, urea formaldehyde, toxic or flammable chemicals, and/or soil contamination.
- The INSPECTOR is NOT required to perform any calculations or analyze any part of the building or components relating to
 design, engineering or architectural concepts, including, but not limited to the strength and adequacy, methods, materials, the
 efficiency of any system or component or compliance with any regulatory requirements, laws or bylaws.
- The INSPECTOR is NOT required to locate, confirm, verify, or comment on property lines, borders and markers or any easements, right of ways, restrictions which may or may not exist against the subject property, buildings, dwelling or dwelling unit.
- The INSPECTOR shall NOT comment on life expectancy, but may however offer an opinion based on the typical life cycle of a system or component.
- The INSPECTOR is NOT required to provide cost estimates, quotations or comment on construction techniques and shall NOT
 advertise, or promote an individual contractor or person for any repairs, modifications, or improvements necessary.
- 10. The INSPECTOR is NOT required to dismantle any item or assembly to gain visible access, or move personal items, furniture, equipment, plant life, soil, ice or snow, insulation, or other debris, which obstructs access or visibility for the inspection. The Inspection Report shall identify by description (and photograph if possible) the obstruction that restricted visual inspection.
- 11. The INSPECTOR shall NOT perform any task, enter any area, or disturb any existing condition where, in the INSPECTOR's judgment, damage could result, specialized safety equipment is required, or the safety of the INSPECTOR is endangered.

 The Inspection Report will contain a description (and photograph where possible) to confirm the presence of these conditions.
- 12. The INSPECTOR shall NOT comment on any system that is mechanically or electrically disconnected, including any equipment that is in the off position or is otherwise not operational. The Inspection Report will provide a limited description (if possible) of the system condition that prevented inspection.
- The INSPECTOR shall NOT accept compensation, financial or otherwise, from more than one interested party for the same service without the consent of all interested parties.
- The INSPECTOR shall NOT directly or indirectly offer, advertise or promote any other professional services relating to the advertising, sale, appraisal, or lending, of the subject building or property.
- 15. The INSPECTOR shall provide the Client a copy of the Engagement Contract, the Standards of Inspection and the Scope of Inspection in adequate time to review and approval prior to the Inspection. The Inspector shall not begin the inspection until the Client has communicated approval of the document.
- 16. The Inspector shall retain a copy of the Engagement Contract, the Standards of Inspection and the Scope of Inspection for his records that has been signed and initialed by the Clients.





Part 3: Scope of Inspection

Special Limitations to Scope:

- In the case of MULTI-FAMILY DWELLINGS, it is the Client's responsibility to arrange access to all building COMMON AREAS
 requiring inspection. The INSPECTOR will not inspect any secured COMMON AREA(S) unless permission has been granted and
 access provided by an authorized building representative (Property Manager, Caretaker, Council Member, etc.).
- Any component not directly identified on the individual INSPECTED UNIT as part of title and is generally believed in the real estate
 industry, as being maintained by the STRATA is defined as part of the COMMON AREA. The inspection of COMMON AREAS
 - a) is limited to a cursory review of easily accessible COMMON AREAS appropriate in the circumstance and subject to any limitations; and
 - terms or conditions established by the recognized building representative. Identification of what is UNIT ENTITLEMENT and what is COMMON AREA is not the responsibility of the Inspector.

	An Inspector is <u>REQUIRED</u> to Inspect and Report on:	An Inspector is NOT REQUIRED to Inspection and Report on:
ROOFING	<u> </u>	
SINGLE FAMILY	Roofing components and roof coverings Roof penetrations and flashings Roof drainage components, including gutters and downspouts Chimneys Report on any observed evidence of current/past water penetration and/or condensation	Accessories that do not make up part of the roof system, such as lightning arrestor systems, antennae, solar heating systems
Multi-Family/Strata	As per single family dwellings except for those components located in COMMON AREAS outside of the INSPECTED UNIT Offer comments only of a general nature based on a limited observation of accessible roofing components located in COMMON AREAS outside of the INSPECTED UNIT	As per single family and; Roofing components (inc. chimneys) contained in a COMMON AREA not directly attributable to, and of sole use by the INSPECTED UNIT Observe and report evidence of water penetration that is beyond the interior of the INSPECTED UNIT
EXTERIOR	Ada A	
SINGLE FAMILY	Exterior wall surfaces, eaves and trim Doors, windows and flashings Garages and carports All entrances such as porches, decks, balconies, including stairs, guards and railings Observe and report on the impact of lot grading, landscaping, retaining walls, walkways, and driveways on the building. Test the operation of power operated garage door openers, including the stop and automatic - reverse function	Seasonal accessories such as removable storm windows, storm doors, screens and shutters. Storage sheds, yard fencing, and other structures not related to the building Any items or facilities not directly related to the building structure, such as recreational rooms, swimming pools, saunas, hot tubs, tennis courts, etc. Ground and soil conditions





	An Inspector is REQUIRED to Inspect and Report on:	An Inspector is NOT REQUIRED to Inspection and Report on:
Multi-Family/Strata	As per single family dwellings except for those components located in COMMON AREAS outside of the INSPECTED UNIT Offer comments only of a general nature based on a limited observation of accessible exterior components located in COMMON AREAS outside of the INSPECTED UNIT	As per single family and; Any Exterior component contained in a COMMON AREA not directly attributable to, and of sole use for the INSPECTED UNIT
STRUCTURE	The state of the s	
SINGLE FAMILY	Foundations and Framing Attics & Roof structure Crawl Spaces Adverse conditions in interior walls, ceilings, and floors	Observe and report on any evidence of water penetration, condensation, or mould Observe and report any evidence of deterioration from insects, rot or fire Observe and report as to the adequacy of any structural component or system
MULTI-FAMILY/STRATA	As per single family dwellings except for those components located in COMMON AREAS outside of the INSPECTED UNIT Offer comments only of a general nature based on a limited observation of accessible structural components located in COMMON AREAS outside of the INSPECTED UNIT	As per single family and; Any Structural component contained in a COMMON AREA not directly attributable to, and of sole use for the INSPECTED UNIT
Insulation & Ventil	ATION	
SINGLE FAMILY	Insulation and vapour barrier in accessible attics, crawl spaces and unfinished basements Ventilation of attics and unheated crawlspaces	Concealed insulation, air and vapour barrier systems
Multi-Family/Strata	As per single family dwellings except for those components located in COMMON AREAS outside of the INSPECTED UNIT Offer comments only of a general nature based on a limited observation of accessible insulation and ventilation components located in COMMON AREAS outside of the INSPECTED UNIT	As per single family and; Any Insulation and Ventilation component contained in a COMMON AREA not directly attributable to, and of sole use for the INSPECTED UNIT





		An Inspector is <u>NOT REQUIRED</u> to Inspection and Report on:		
ELECTRICAL.				
SINGLE FAMILY	Service entrance cable and location Main service panel and auxiliary panels Panel & Branch circuit over-current protection and system grounding Branch circuit wiring Amperage and voltage ratings of main service panel	Secondary wiring systems such as security systems, low voltage wiring, telephone wiring, cable television wiring, etc. Insert or remove fuses, or operate circuit breakers. Provide or remove power for equipment		
	Inspect inside panels with readily accessible and removable panel covers designed for homeowner access Randomly select and operate a representative number of permanently installed light fixtures and outlets Outlets noted above are to be checked for polarity and grounding All exterior outlets and those within five feet of plumbing fixtures will be checked for polarity and grounding Verify presence and test the operation of ground fault circuit interrupters and arc-fault breakers	An Inspector is not to remove a circuit panel cover in the main or any auxiliary panels unless they have received permission from the owner to do so and have safely de-energized the system by means of the main breaker or are wearing appropriate personal protective equipment		
Multi-Family/Strata	As per single family dwellings except for those components located in COMMON AREAS outside of the INSPECTED UNIT and not including the testing of smoke detectors Offer comments only of a general nature based on a limited observation of accessible electrical components located in COMMON AREAS outside of the INSPECTED UNIT	As per single family and; Any Electrical component contained in a COMMON AREA not directly attributable to, and of sole use for the INSPECTED UNIT Test the operation smoke detectors forming part of a fire suppression system subject to annual inspection and certification by others Remove a circuit panel cover in the main or auxiliary panels where the INSPECTED UNIT does not contain a main breaker to safely deenergize the electrical system in the INSPECTE UNIT		





	An Inspector is REQUIRED to Inspect and Report on:	An Inspector is NOT REQUIRED to Inspection and Report on:		
HEATING, MECHANIC	AL VENTILATION & COOLING SYSTEMS (PERMANENT)	y Installed)		
SINGLE FAMILY	Heating and Cooling distribution systems, including where applicable fans, flue piping, vents, chimneys, dampers, pumps, supports, filters, ducts, piping, registers, radiators, and convectors Heat Recovery Ventilators The presence of manufacturer's built-in safety controls The presence of heating source in each room. Test systems using the thermostat or other similar standard operating controls Operate the individual exhaust fan ventilation systems Will recommend to Client to have any gas appliance present serviced by a licensed gas Contractor ASAP if documentation cannot be presented showing the unit has been serviced in the last calendar year	Commence of the Commence of th		
Multi-Family/Strata	As per single family dwellings except for those components located in COMMON AREAS outside of the INSPECTED UNIT Offer comments only of a general nature based on a limited observation of accessible Heating and Cooling systems located in COMMON AREAS outside of the INSPECTED UNIT	As per single family and; Any Heating & Cooling system component contained in a COMMON AREA not directly attributable to, and of sole use for the INSPECTED UNIT		
PLUMBING				
SINGLE FAMILY	Main water supply piping into dwelling and any distribution piping, pipe supports, and any leaks in above piping systems Fixtures, faucets, and isolating valves Drain, waste and vent piping, pipe supports and insulation Hot Water heaters, including if present, fuel supply piping, flue piping, vents, chimneys, and verify the precence of required safety devices Interior sumps and pumps	Any item or facilities not directly related to the plumbing such as swimming pools, saunas, hot tubs, solar systems, etc. Any Water-treatment devices Automatic air vents Foundation drainage system and yard piping. Irrigation or fire sprinkler systems Observe the quantity and quality of water supply, and whether public or private Observe outdoor waste disposal systems located on the property or determine whether public or private		





	An Inspector is <u>REQUIRED</u> to Inspect and Report on:	An Inspector is NOT REQUIRED to Inspection and Report on:
	PLUMBING CONTINUED: Water volume and pressure should be tested by opening the faucets to obtain a reasonable flow of one or more fixtures simultaneously, and at various locations in the dwelling Water drainage should be tested by draining one or more fixtures simultaneously, and at various locations in the dwelling Observe and report on the presence of crossconnections that could contaminate the potable water.	Operate any valve other than those used on a regular or daily basis by an /the occupant lgnite or extinguish pilot lights, change settings, or conditions on equipment
Multi-Family/Strata	As per single family dwellings except for those components located in COMMON AREAS outside of the INSPECTED UNIT Offer comments only of a general nature based on a limited observation of accessible Plumbing components located in COMMON AREAS outside of the INSPECTED UNIT	As per single family and; Any Plumbing component contained in a COMBAON AREA not directly attributable to, and of sole use for the INSPECTED UNIT
INTERIOR		
SINGLE FAMILY	Floors, walls, ceilings, and trims Fire separating walls and party walls Stairs, guards, and railings Solid fuel burning appliances, including fireplaces and wood stoves Observe and report on the presence of smoke/heat/CO detectors and/or fire sprinklers Observe the condition of permanently installed counters and cabinets Randomly select and operate, where reasonably accessible, a representative number of doors and windows Observe and report on any evidence of water penetration and condensation	Treatments such as paint, wallpaper, carpeting, blinds, drapes, and other similar treatments Kitchen, bathroom, and laundry appliances Ignite or extinguish fires Observe fireplace insert installation Also see Exterior excluded seasonal accessories and excluded accessory buildings
Multi-Family/Strata	As per single family dwellings except for those components located in COMMON AREAS outside of the INSPECTED UNIT and not including the testing of smoke & heat detectors Offer comments only of a general nature based on a limited observation of accessible Interior components located in COMMON AREAS outside of the INSPECTED UNIT	As per single family and; Any Interior component contained in a COMMON AREA not directly attributable to, and of sole use for the INSPECTED UNIT Test the operation of smoke/heat/CO detectors and/or fire sprinklers