



Your Inspection Report

11554 136 Street
Surrey, BC V3R 3C2

PREPARED FOR:

KEN MAYO
RIZWAN SYED

INSPECTION DATE:

Thursday, July 21, 2016

PREPARED BY:

Andrew Philliskirk



Philliskirk Enterprises
41750 Bowman Road
Abbotsford, BC V2R 5G8

(604) 219-2591

www.philliskirk.com
andrew.philliskirk@gmail.com

Note: For the purpose of this report the building is considered to be facing **West**.

This Summary outlines potentially significant issues from a cost or safety standpoint. This section is provided as a courtesy and cannot be considered a substitute for reading the entire report. Please read the complete document.

[Priority Maintenance Items](#)

Roofing

General

- There has been a new asphalt shingle roof installed fairly recently. As seen from the attic, the roof has been patched where the old chimney came through and where the extension was added. The rafters and ridge boards in these areas have been weakened. This patchwork in conjunction with the weakened structure will impact life of the new roof. The step flashings on the lower section of roof, over the porch, have not been tucked under the siding or tucked under the shingles. These need to be fixed as soon as possible as it poses an immediate water ingress problem. The siding should have been cut back to allow the flashings to tuck underneath. There are no drip edge flashings, gutters or downspouts installed. In the winter months the water will simply pour over the edge, create a puddle where it hits the ground, and splash onto the wall. This will be an annoyance as it will splash on the walls and anything close to the house and could deteriorate the siding and structure over time. There are no penetrations through the roof for plumbing vents. After the plumbing vents have been installed a qualified roofing contractor should be brought in, to install boots around the vents, fix the flashings and install gutters and downpipes.

Exterior

General

- The back deck has been poorly constructed. It is a safety hazard as it stands now and should not be used until made safe by a qualified carpenter or contractor. It has been attached to the house using only wood screws. The best way is to through-bolt the ledger to the rim joist of the house. The main beam has no bracing to prevent it from toppling over. The deck is tilting away from the house. The guardrails and banisters are missing pickets which pose a falling hazard. This is an unsafe arrangement that needs to be addressed. A carpenter or contractor should be brought in to fix these issues so this deck is safe to use. The siding has been patched together using at least four different materials. The vinyl siding is coming away from the building in areas. There needs to be some time spent installing appropriate drip flashings and caulking by a contractor.

Structure

General

- This house is very old - the buyers have disclosed the age to be about a hundred years old. It has gone through many renovations and has had at least one major addition. Based on the amateurish work around the rest of the house it is unlikely that permits were pulled for the work or that it has been inspected. This may be an insurance issue. Some of the exterior framing will be compromised by the wood-soil contact. The roof framing is showing signs of sagging and has deteriorated in locations. The floor joists on the main floor are undersized by today's standards. The basement appears to be a living space but should not be lived in. The ceiling height is well below minimum standards and the windows are too small for egress. The foundation has signs of shifting and settling.

Electrical

General

- The electrical system has been upgraded to a 200Amp service. This is more than adequate power for this size of dwelling. The circuits are poorly labeled. There are many abandoned wires throughout the house which could pose a shock or fire hazard. The main ground wire has corroded through and is no longer functioning as is should which could pose a shock hazard. The GFCI circuits may not protect as they should until ground continuity is corrected and verified. The old knob and tube wiring has been removed and poses no hazard. The installation of the new service would have required a permit and possible inspection. There should be records available from the BC Safety Authority. A certified electrician should be brought in to perform an all aspect review of all the wiring, bring it up to code and make it safe.

Heating

General

- The heating systems of this house have used different fuel/energy sources over the decades. There is evidence that there used to be a fireplace way back before the addition. There may have been a period of oil heating after that but there is no visible evidence. If there was an oil tank it should have been removed. This is done under strict guidelines, for environmental reasons, and there would be records of it. If no records are found, an expert should be brought in to determine if there is still a tank that needs to be removed. This may be an insurance restriction. There is an abandoned gas service indicating that natural gas was utilized for a while then discontinued. The current system is solely electric baseboard heaters.

Insulation and Ventilation

General

- The attic space is not sufficiently vented. There needs to be soffit and roof vents installed. They work in conjunction to keep the attic space vented. There is a big heap of fiberglass batts in the attic that needs to be spread out and installed correctly. There has been other types of insulation used over the years. There appears to be small granules that may be left over from a vermiculite or similar granule product. A specialized removal may be required if there is any asbestos in the leftover dust. A specialist should be consulted. This could pose an air quality/safety issue.

Plumbing

General

- The plumbing in this building has not been done by qualified people. The garden hoses used for connecting the hot water tank must be replaced as soon as possible to prevent flooding. The abandoned hoses in other locations should be investigated further by a plumber. The pressure measured at two locations were 50 and 80 psi. This is a huge variance. There may be issues with the pressure regulator. There are no apparent vents coming up through the roof. Sewer gasses may be able to enter the house if proper P-traps and vents aren't installed. The sink drainage for the basement kitchen sink is not functional. The waste water from this house likely goes to a septic tank then a field out back, to the east. These are underground and not a part of a home inspection. A septic specialist should be brought in to find the tank and the field. Depending on usage the tank will need to be drained every few years. The original system was designed for a tiny house a long time ago. Now that this house is being used as a six bedroom dwelling the septic system may not be able to keep up and may need upgrading or frequent emptying. The septic field may lie under the gravel which is used as a parking lot. Heavy machinery might do damage to the field.

SUMMARY

11554 136 Street, Surrey, BC July 21, 2016

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Interior

General

- The interior finishes don't necessarily reflect the condition of the house. There has been a lot of amateurish work to the house which may have covered up potential issues. The holes through the walls in the basement needs to be addressed. The visible organic matter needs to be cleaned and prevented from re-occurrence. The flooring needs to be made safe from trip hazards. The wallboard needs to be completed for air quality purposes.

This concludes the Summary section.

The remainder of the report describes each of the home's systems and also details any recommendations we have for improvements. Limitations that restricted our inspection are included as well.

The suggested time frames for completing recommendations are based on the limited information available during a pre-purchase home inspection. These may have to be adjusted based on the findings of specialists.

[Home Improvement - ballpark costs](#)

ROOFING

11554 136 Street, Surrey, BC July 21, 2016

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Description

Sloped roofing material:

- [Asphalt shingles](#)



1. Asphalt shingles



2. Asphalt shingles

Sloped roof flashing material:

- Metal



3. Metal Flashings

Probability of leakage:

- High
- Side wall flashings need to be sealed.

Limitations

General: • The inspection was limited to the edge of the building as there were no gutters to rest a ladder against to access the upper portion of the roof. Even if there were gutters, the weakened structure would have been unsafe to walk on.

Inspection performed: • From roof edge • From the ground

Recommendations

General

1. • There has been a new asphalt shingle roof installed fairly recently. As seen from the attic, the roof has been patched where the old chimney came through and where the extension was added. The rafters and ridge boards in these areas have been weakened. This patchwork in conjunction with the weakened structure will impact life of the new roof. The step flashings on the lower section of roof, over the porch, have not been tucked under the siding or tucked under the shingles. These need to be fixed as soon as possible as it poses an immediate water ingress problem. The siding should have been cut back to allow the flashings to tuck underneath. There are no drip edge flashings, gutters or downspouts installed. In the winter months the water will simply pour over the edge, create a puddle where it hits the ground, and splash onto the wall. This will be an annoyance as it will splash on the walls and anything close to the house and could deteriorate the siding and structure over time. There are no penetrations through the roof for plumbing vents. After the plumbing vents have been installed a qualified roofing contractor should be brought in, to install boots around the vents, fix the flashings and install gutters and downpipes.



4. Flashings not properly installed



5. Patched where chimney used to come through




6. Patched at addition

SLOPED ROOF FLASHINGS \ Roof/sidewall flashings

2. Condition: • [No step or counter flashings](#)

Implication(s): Chance of water damage to contents, finishes and/or structure



3. Condition: • [Siding not cut back](#)


Implication(s): Chance of water damage to contents, finishes and/or structure

4. Condition: • [Step flashings not set into shingles properly](#)

Implication(s): Chance of water damage to contents, finishes and/or structure

5. Condition: • [No kickout flashing](#)


Implication(s): Chance of water damage to contents, finishes and/or structure



SLOPED ROOF FLASHINGS \ Drip edge flashings

6. Condition: • [Missing](#)

Implication(s): Chance of water damage to contents, finishes and/or structure



Description

Gutter & downspout material: • No gutters or downspouts

Lot slope:

- [Away from building](#)



7. Away from building

- [Towards building](#)



8. Towards building

Wall surfaces - wood:

- [Boards](#)

EXTERIOR

11554 136 Street, Surrey, BC July 21, 2016


- SUMMARY
- ROOFING
- EXTERIOR**
- STRUCTURE
- ELECTRICAL
- HEATING
- INSULATION
- PLUMBING
- INTERIOR
- REFERENCE



9. Siding Materials



10. Siding Materials



11. Siding Materials



12. Siding Materials

Driveway:

- Gravel

EXTERIOR

11554 136 Street, Surrey, BC July 21, 2016

Report No. 1016, v.2

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

INSULATION

PLUMBING

INTERIOR

REFERENCE



13. Gravel

Deck:

- Wood



14. Wood Deck at Back

Porch:

- Wood

EXTERIOR

11554 136 Street, Surrey, BC July 21, 2016

Report No. 1016, v.2

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

INSULATION

PLUMBING

INTERIOR

REFERENCE



15. Wood Front Porch

Exterior steps:

- Wood



16. Wood Staircase - Front Door

Limitations

General: • There has been recent painting of most of the exterior. As such it is hard to assess the condition of the exterior components.

Inspection limited/prevented by:

• New finishes/paint/trim

There has been recent renovations and painting of all the exterior siding.

Exterior inspected from: • Ground level

Recommendations

General

7. • The back deck has been poorly constructed. It is a safety hazard as it stands now and should not be used until made safe by a qualified carpenter or contractor. It has been attached to the house using only wood screws. The best way is to through-bolt the ledger to the rim joist of the house. The main beam has no bracing to prevent it from toppling over. The deck is tilting away from the house. The guardrails and banisters are missing pickets which pose a falling hazard. This is an unsafe arrangement that needs to be addressed. A carpenter or contractor should be brought in to fix these issues so this deck is safe to use. The siding has been patched together using at least four different materials. The vinyl siding is coming away from the building in areas. There needs to be some time spent installing appropriate drip flashings and caulking by a contractor.




17. Unsafe Deck - Do not Use.

ROOF DRAINAGE \ Downspouts

8. Condition: • [Missing](#)


Implication(s): Chance of water damage to contents, finishes and/or structure



WALLS \ Soffits and fascia

9. Condition: • [Vents missing, ineffective](#)


Implication(s): Chance of condensation damage to finishes and/or structure | Material deterioration



EXTERIOR

11554 136 Street, Surrey, BC July 21, 2016

- SUMMARY
- ROOFING
- EXTERIOR**
- STRUCTURE
- ELECTRICAL
- HEATING
- INSULATION
- PLUMBING
- INTERIOR
- REFERENCE



18. Missing Soffit Vents



19. Missing Soffit Vents

WALLS \ Wood siding


10. Condition: • The rodents have chewed right through both walls.



20. Rodent damage to wall

11. Condition: • [Too close to grade](#)

Implication(s): Chance of water damage to contents, finishes and/or structure | Material deterioration | Rot | Insect damage



21. Too close to grade

WALLS \ Vinyl siding

12. Condition: • [Buckled or wavy](#)

Implication(s): Cosmetic defects | Chance of water damage to contents, finishes and/or structure

EXTERIOR

11554 136 Street, Surrey, BC July 21, 2016

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

INSULATION

PLUMBING

INTERIOR

REFERENCE



22. Vinyl siding buckling and pulling away

WALLS \ Fiber cement siding

13. Condition: • [Missing paint or caulking](#)

Implication(s): Cosmetic defects | Chance of water damage to contents, finishes and/or structure



23. Missing paint or caulking

EXTERIOR GLASS \ Glass (glazing)

14. Condition: • [Cracked](#)

Implication(s): Cosmetic defects




24. Cracked

EXTERIOR GLASS \ Exterior drip caps

15. Condition: • [Missing](#)

Implication(s): Chance of water damage to contents, finishes and/or structure





25. Missing Drip Edge

DOORS \ Doors and frames

16. Condition: • [Damage](#)

Implication(s): Cosmetic defects | Chance of damage to finishes and structure | Poor security

PORCHES, DECKS, STEPS, PATIOS AND BALCONIES \ Columns

17. Condition: • [Leaning](#)

Implication(s): Weakened structure | Chance of movement




26. Leaning

PORCHES, DECKS, STEPS, PATIOS AND BALCONIES \ Handrails and guards

18. Condition: • [Spindles too far apart](#)

Implication(s): Fall hazard



27. Spindles too far apart



28. Spindles too far apart

PORCHES, DECKS, STEPS, PATIOS AND BALCONIES \ General

19. Condition: • Unsafe

Implication(s): Physical injury

EXTERIOR

11554 136 Street, Surrey, BC July 21, 2016

Report No. 1016, v.2

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

INSULATION

PLUMBING

INTERIOR

REFERENCE



29. Unsafe Beam



30. Screwed not bolted



31. Unsafe

20. Condition: • Poorly built

Implication(s): Weakened structure

Description

Configuration: • [Basement](#)

Foundation material:

• [Poured concrete](#)



32. Poured concrete

Floor construction: • [Joists](#)

Exterior wall construction: • [Wood frame](#)

Roof and ceiling framing: • Roof repairs or additions



33. Roof extended

Roof and ceiling framing:

- [Rafters/roof joists](#)



34. Rafters/roof joists



35. Rafters/roof joists

Limitations

Attic/roof space: • Entered but access was limited

Percent of foundation not visible: • 95 %

Not included as part of a building inspection: • The inspection was a visual inspection only. Most of the framing could not be seen so I can not comment on the condition of most of the wall structure. There was no signs of water but it was hot and dry on the day of the inspection and had not rained the days prior.

Not included as part of a building inspection: • Visible mold evaluation is not included in the building inspection report

Recommendations


General

21. • This house is very old - the buyers have disclosed the age to be about a hundred years old. It has gone through many renovations and has had at least one major addition. Based on the amateurish work around the rest of the house it is unlikely that permits were pulled for the work or that it has been inspected. This may be an insurance issue. Some of the exterior framing will be compromised by the wood-soil contact. The roof framing is showing signs of sagging and has deteriorated in locations. The floors joists on the main floor are undersized by today's standards. The basement appears to be a living space but should not be lived in. The ceiling height is well below minimum standards and the windows are too small for egress. The foundation has signs of shifting and settling.

FOUNDATIONS \ Foundation

22. **Condition:** • [Settled](#)

Implication(s): Chance of structural movement




36. Settled

37. Settled

23. Condition: • Typical minor cracks

Implication(s): Chance of water entering building



24. Condition: • [Typical minor settlement](#)

25. Condition: • [Lateral movement](#)

These cracks should be caulked, to prevent insects and rodents getting into the house, and monitored for further lateral movement.

Implication(s): Weakened structure



38. Lateral movement

26. Condition: • [Wood/soil contact](#)

Implication(s): Weakened structure

FLOORS \ Joists

27. Condition: • Undersized floor joists are below today's minimum code.



39. Floor joists undersized

ROOF FRAMING \ Rafters/trusses

28. Condition: • [Rot, fire or insect damage](#)


Implication(s): Weakened structure | Chance of structural movement




40. Rot/fire damage to roofing

29. Condition: • [Ridge sagging](#)

Implication(s): Weakened structure | Chance of structural movement





41. Ridge sagging

Description

Service entrance cable and location:

- [Overhead](#)



42. Overhead



43. Overhead

Service size: • [200 Amps \(240 Volts\)](#)

Main disconnect/service box type and location: • [Breakers - basement](#)

Number of circuits installed: • 24

Distribution panel rating: • [200 Amps](#)

Distribution panel type and location:

- [Breakers - basement](#)



44. Breakers - basement

Distribution wire material and type:

- [Copper - non-metallic sheathed](#)
- [Copper - knob and tube](#)

Abandoned



45. Copper - knob and tube



46. Copper - knob and tube

Type and number of outlets (receptacles): • [Grounded - upgraded](#)


Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI):

- [GFCI - bathroom](#)




47. GFCI - bathroom

- [GFCI - basement](#)



48. GFCI - basement

- [GFCI - kitchen](#)



49. GFCI - kitchen

Limitations

General: • The testing of lights was limited because some of the light fixtures were missing or not working. There was no power to the south-east corner bedroom on the main floor so testing was limited.

Inspection limited/prevented by:

- Storage



50. Storage

Recommendations

General

30. • The electrical system has been upgraded to a 200Amp service. This is more than adequate power for this size of dwelling. The circuits are poorly labeled. There are many abandoned wires throughout the house which could pose a shock or fire hazard. The main ground wire has corroded through and is no longer functioning as is should which could pose a shock hazard. The GFCI circuits may not protect as they should until ground continuity is corrected and verified. The old knob and tube wiring has been removed and poses no hazard. The installation of the new service would have required a permit and possible inspection. There should be records available from the BC Safety Authority. A certified electrician should be brought in to perform an all aspect review of all the wiring, bring it up to code and make it safe.

SERVICE BOX, GROUNDING AND PANEL \ System grounding

31. Condition: • [Corroded ground wire](#)

Implication(s): Electric shock




51. Ground wire corroded

SERVICE BOX, GROUNDING AND PANEL \ Distribution panel

32. Condition: • [Double taps](#)

Implication(s): Fire hazard



ELECTRICAL

11554 136 Street, Surrey, BC July 21, 2016

Report No. 1016, v.2

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL



HEATING

INSULATION

PLUMBING

INTERIOR

REFERENCE




52. Double taps

53. Double taps

DISTRIBUTION SYSTEM \ Wiring - damaged or exposed

33. Condition: • [Exposed on walls or ceilings](#)

Implication(s): Electric shock



54. Exposed wiring

55. Exposed wiring





56. Exposed wiring

DISTRIBUTION SYSTEM \ Wiring - installation

34. Condition: • [Loose connections](#)

Implication(s): Electric shock | Fire hazard | Interruption of electrical service





57. Loose connections

35. Condition: • [Abandoned wire](#)

Implication(s): Electric shock



58. Abandoned wire



59. Abandoned wire

DISTRIBUTION SYSTEM \ Lights


36. Condition: • [Inoperative](#)

Implication(s): Inadequate lighting

DISTRIBUTION SYSTEM \ Outlets (receptacles) - number or location

37. Condition: • [Above electric baseboard heaters](#)

Implication(s): Increased fire hazard



60. Above electric baseboard heaters

DISTRIBUTION SYSTEM \ Smoke detectors

38. Condition: • Missing
Implication(s): Fire hazard



61. *Removed smoke detector*




62. *Removed smoke detector*

Description

Fuel/energy source: • [Electricity](#)

System type:

- Electric baseboard heaters



63. Electric baseboard heaters

Recommendations

General

39. • The heating systems of this house have used different fuel/energy sources over the decades. There is evidence that there used to be a fireplace way back before the addition. There may have been a period of oil heating after that but there is no visible evidence. If there was an oil tank it should have been removed. This is done under strict guidelines, for environmental reasons, and there would be records of it. If no records are found, an expert should be brought in to determine if there is still a tank that needs to be removed. This may be an insurance restriction. There is an abandoned gas service indicating that natural gas was utilized for a while then discontinued. The current system is solely electric baseboard heaters.




64. Abandoned Gas Service

Description

Attic/roof insulation material:

- [Glass fiber](#)



65. Glass fiber

Attic/roof insulation amount/value: • Not determined

Attic/roof ventilation: • [None found](#)

Attic/roof air/vapor barrier:

- [None found](#)



66. None found

Limitations

Attic inspection performed: • By entering attic, but access was limited

Recommendations

General

40. • The attic space is not sufficiently vented. There needs to be soffit and roof vents installed. They work in conjunction to keep the attic space vented. There is a big heap of fiberglass batts in the attic that needs to be spread out and installed correctly. There has been other types of insulation used over the years. There appears to be small granules that may be left over from a vermiculite or similar granule product. A specialized removal may be required if there is any asbestos in the leftover dust. A specialist should be consulted. This could pose an air quality/safety issue.

ATTIC/ROOF \ Insulation

41. Condition: • [Gaps or voids](#)

Implication(s): Increased heating and cooling costs | Reduced comfort



67. Gaps or voids



68. Gaps or voids


ATTIC/ROOF \ Roof vents

42. Condition: • [Missing](#)

Implication(s): Chance of condensation damage to finishes and/or structure

Recommended amount of attic ventilation

the total vent area is often recommended to be 1/300 of the floor space of the attic




69. Missing Roof Vents

ATTIC/ROOF \ Hatch

43. Condition: • [Not insulated and not weatherstripped](#)

Implication(s): Chance of condensation damage to finishes and/or structure | Increased heating and cooling costs | Reduced comfort



Description


Water supply source: • Public

Service piping into building: • [Plastic](#)

Supply piping in building: • [Plastic](#)

Main water shut off valve at the:

• Front of the basement



70. Main Water Shutoff

Water flow and pressure:

• [Typical for neighborhood](#)

This is quite a discrepancy in pressure.



71. Water Pressure 80psi




72. Water Pressure 50psi

Tank capacity: • 189 liters

Water heater approximate age:

• 17 years

Model number: JW50SDE1 **Serial number:** U0502 536252



73. Water Heater Specs

Water heater failure probability: • [High](#)

Waste and vent piping in building: • [ABS plastic](#)

Floor drain location: • None found

Limitations

Items excluded from a building inspection: • Well • Water quality • Septic system • Isolating/relief valves & main shut-off valve • Concealed plumbing • Tub/sink overflows • Water treatment equipment • Water heater relief valves are not tested • The performance of floor drains or clothes washing machine drains

Recommendations

General

44. • The plumbing in this building has not been done by qualified people. The garden hoses used for connecting the hot water tank must be replaced as soon as possible to prevent flooding. The abandoned hoses in other locations should be investigated further by a plumber. The pressure measured at two locations were 50 and 80 psi. This is a huge variance. There may be issues with the pressure regulator. There are no apparent vents coming up through the roof. Sewer gasses may be able to enter the house if proper P-traps and vents aren't installed. The sink drainage for the basement kitchen sink is not functional. The waste water from this house likely goes to a septic tank then a field out back, to the east. These are underground and not a part of a home inspection. A septic specialist should be brought in to find the tank and the field. Depending on usage the tank will need to be drained every few years. The original system was designed for a tiny house a long time ago. Now that this house is being used as a six bedroom dwelling the septic system may not be able to keep up and may need upgrading or frequent emptying. The septic field may lie under the gravel which is used as a parking lot. Heavy machinery might do damage to the field.

SUPPLY PLUMBING \ Supply piping in building

45. Condition: • [Non-standard material](#)

Implication(s): Chance of water damage to contents, finishes and/or structure | Reduced system life expectancy | No water



74. Non-standard material

WATER HEATER \ Hot/cold piping

46. Condition: • Garden hose used for hot water tank.

Implication(s): These hoses are not designed for continuous pressure and high heat applications. There is risk of bursting and flooding. The hoses themselves may leach harmful heavy metals into the drinking water. They should be replaced with rated potable water lines.




75.

WATER HEATER \ Temperature/pressure relief valve

47. Condition: • [Discharge tube missing](#)

Implication(s): Scalding




76. Discharge tube missing

WATER HEATER \ Isolating valve/Cold water shut-off valve

48. Condition: • [Missing](#)

Implication(s): Increased maintenance costs




WASTE PLUMBING \ Drain piping - installation

49. Condition: • These plastic pipes appear to be abandoned. They were likely the old drainage lines before the house was lifted.

Implication(s): They pose an insect or rodent entry risk and make it hard to weatherproof the siding in these locations. They should be removed or capped inside the wall and sealed up.



77. Abandoned Drain Pipes



78. Abandoned Drain Pipes

WASTE PLUMBING \ Traps - performance

50. Condition: • S-Trap

Implication(s): May allow sewer gases to enter the building.



79. S-Trap

51. Condition: • [Missing](#)

Implication(s): Sewer gases entering the building



80. No Visible P-Trap

WASTE PLUMBING \ Venting system

52. Condition: • [Missing](#)

Implication(s): Sewer gases entering the building

PLUMBING

11554 136 Street, Surrey, BC July 21, 2016

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

INSULATION

PLUMBING

INTERIOR

REFERENCE



81. Missing



82. Missing

FIXTURES AND FAUCETS \ Basin, sink and laundry tub

53. Condition: • Sink drain inoperative. This unusual installation seems to defies gravity.



83. Flow of Drain



84. Flow of Drain

FIXTURES AND FAUCETS \ Hose bib or bibb

54. Condition: • [Inoperative](#)

Implication(s): Equipment inoperative



85. Hose Bib Inoperative

Description

Major floor finishes:

- [Carpet](#)



86. Carpet

- [Laminate](#)



87. Laminate




88. Laminate

INTERIOR


11554 136 Street, Surrey, BC July 21, 2016

- SUMMARY
- ROOFING
- EXTERIOR
- STRUCTURE
- ELECTRICAL
- HEATING
- INSULATION
- PLUMBING
- INTERIOR**
- REFERENCE



89. Laminate

- [Concrete](#)



90. Laminate



91. Concrete

- Tile



92. Concrete



93. Tile



94. Tile

Major wall and ceiling finishes:

- [Plaster/drywall](#)




95. Gypsum Ceilings

- [Gypsum board](#)


Windows:

- [Sliders](#)



96. *Sliders*

- [Awning](#)



97. *Awning*

- Vinyl
- Aluminum

Glazing: • [Single](#) • [Double](#)

Bathroom ventilation: • Exhaust fan

Limitations

Not included as part of a building inspection: • Carbon monoxide detectors • Security systems and intercoms • Central vacuum systems • Cosmetic issues • Appliances • Perimeter drainage tile around foundation, if any

Appliances: • Appliances are not inspected as part of a building inspection

Basement leakage: • Cannot predict how often or how badly basement will leak • Storage in basement limited inspection

Recommendations


General

55. • The interior finishes don't necessarily reflect the condition of the house. There has been a lot of amateurish work to the house which may have covered up potential issues. The holes through the walls in the basement needs to be addressed. The visible organic matter needs to be cleaned and prevented from re-occurrence. The flooring needs to be made safe from trip hazards. The wallboard needs to be completed for air quality purposes.

FLOORS \ General

56. Condition: • [Loose or missing pieces](#)

Implication(s): Cosmetic defects | Trip or fall hazard



98. *Tile*

57. Condition: • [Trip hazard](#)


Implication(s): Physical injury

WALLS \ General

58. Condition: • Damaged

Implication(s): Cosmetic defects

Common locations for water damage



99. Damaged

WINDOWS \ Glass (glazing)

59. Condition: • [Cracked](#)

Implication(s): Cosmetic defects | Physical injury



100. Cracked

DOORS \ Doors and frames

60. Condition: • [Damage](#)

Implication(s): Cosmetic defects



101. Damage

61. Condition: • [Loose or poor fit](#)

Implication(s): Chance of damage to finishes and structure


EXHAUST FANS \ Exhaust duct

62. Condition: • [Not insulated in unconditioned space](#)

Implication(s): Chance of condensation damage to finishes and/or structure

63. Condition: • [Poor termination location](#)

Implication(s): Chance of condensation damage to finishes and/or structure



64. Condition: • [Not vented to exterior](#)

Implication(s): Chance of condensation damage to finishes and/or structure



102. Bathroom Fan Exhausting into attic space

END OF REPORT

The links below connect you to a series of documents that will help you understand your home and how it works. These are in addition to links attached to specific items in the report.

Click on any link to read about that system.

» 01. ROOFING, FLASHINGS AND CHIMNEYS

» 02. EXTERIOR

» 03. STRUCTURE

» 04. ELECTRICAL

» 05. HEATING

» 06. COOLING/HEAT PUMPS

» 07. INSULATION

» 08. PLUMBING

» 09. INTERIOR

» 10. APPLIANCES

» 11. LIFE CYCLES AND COSTS

» 12. SUPPLEMENTARY

Asbestos

Radon

Urea Formaldehyde Foam Insulation (UFFI)

Lead

Carbon Monoxide

Mold

Household Pests

Termites and Carpenter Ants

» 13. HOME SET-UP AND MAINTENANCE

» 14. MORE ABOUT HOME INSPECTIONS