

Montreal, May 6, 2019

IMPORTANT SAFETY NOTICE

Steerer Module on Electron Pro 2016-2019



Subject

This Safety Notice applies only to the **Steerer Module** originally supplied with the **Argon 18 Electron Pro** and used when the bike is assembled in drop bar configuration.



Safety Issue

Under extreme riding conditions or set-up, a crack may develop at the base of the steerer module and ultimately lead to part failure. **Therefore, no Electron Pro should be ridden in drop bar configuration using the originally supplied steerer module until a replacement part is provided by Argon 18.** This does not affect Electron Pro bikes assembled with the pursuit handle bar.

Replacement Program

To fix this issue, Argon 18 will replace, free of charge, all affected steerer modules with a new, more robust part. This new replacement steerer module should become available for shipping between May 24 and May 31, 2019.

The replacement part will be shipped promptly via express courier:

- to Argon 18 retailers in North America who have sold the Electron Pro.
- to Regional Distributors elsewhere in the world who will then forward the parts to their retailers who have sold the Electron Pro.

All original steerer modules will need to be replaced with the new part. Installation of the new part needs to be done as per instructions provided in the Electron Pro frame assembly guides. Once replaced, the original part should be discarded.

For additional information or questions regarding this Safety Notice, please contact:

- Your retailer (if in North America)
- Your retailer or Argon 18's Regional Distributor (if outside North America)

Thank you for your support.

Technical Service Department
Argon 18