



Date: **Sunday, 01st May 2022**

Time: **11.45 hrs**

Subject: **COC COMMUNICATION Nr 8**

Document No: **3.10**

From: The Clerk of the Course

To: All Competitors

Number of pages: 1

Attachments: 0

The team of GEOTRAQ, have been investigating a lot last night what could have been the reason that so many radio signals were sent and received on yesterday's stages.

In order to avoid what happened yesterday, it's mandatory to install the device according to Instruction Manual provided.

Please, read the manual and watch the video to understand how the 4 buttons of the ComBox shall be operated we realize that buttons for overtaking and danger were pressed randomly but the common case was when a danger signal was received the competitors answered by pressing the blue button that started an overtake procedure, what is incorrect.

Moreover, we identified some competitors from all classes from bike to car that they have wrapped the whole enclosure of the ComBox with numerous zip ties that caused the operating buttons to be pressed permanently, so even that there is a time out in the firmware, the devices were sending nonstop signals, blocking the system and overloading the network. (see the picture to see that bad installation).

Luis GONZALEZ
Clerk of the Course

