
Choice of suitable cuts for different materials.

At least three teeth should be engaged at one time.



Coarse cut





Fine cut