



# MUV MARKETPLACE SDN BHD (253263-U)

Lot 3, Jalan 6/3, Kawasan Perindustrian Seri Kembangan, 43300 Seri Kembangan, Selangor.  
Tel: 03-8947 6888 Fax No: 03-8947 6880

## VEHICLE INSPECTION REPORT

|                        |                           |                  |                          |
|------------------------|---------------------------|------------------|--------------------------|
| Registration Number    | <b>W5494R</b>             | Vehicle Location | -                        |
| Vehicle Model          | <b>SUPRIMA S PREMIUM</b>  | Colour           | <b>Blue</b>              |
| Engine Type            | <b>Petrol</b>             | Year Made        | <b>2014</b>              |
| Engine Capacity (C.C.) | <b>1561</b>               | Mileage (KM)     | <b>126973</b>            |
| Gearbox Type           | <b>Automatic</b>          | Assessment Date  | <b>27/02/2020</b>        |
| Type of Usage          | <b>Individual Private</b> | Body Type        | <b>Hatchback</b>         |
| Engine Number          | <b>S4PHTY1794</b>         | Chassis Number   | <b>PL1CR6LDREG004022</b> |
| Key Set                | <b>1</b>                  |                  |                          |

## INSPECTION SUMMARY


| Inspection area | Rating | Page | Inspection area | Rating | Page |
|-----------------|--------|------|-----------------|--------|------|
| Exterior        | C      | 2    | Gearbox         | -      | 4    |
| Structure       | -      | -    | Undercarriage   | -      | 4    |
| Interior        | B      | 3    | Electrical      | A      | 4    |
| Engine          | -      | 3    | Flooded Rating  | -      | -    |

## VEHICLE HISTORY


### Comments:

-

Structure (Bottom View)



Exterior (Top View)



**Legend:** ● NA ● Defect ● Normal

Disclaimer: Our inspection report are based on what is seen and heard by our inspectors at the time of inspection. We do not guarantee or warranty any physical deterioration or mechanical/technical failures or defects which arise after the date of inspection. No judgement is made to the internal components of engine, transmission, driveline, electrical or any other systems that require dismantling to diagnose. Our inspection report does not cover the authentication of the components or specification of the vehicle. The mileage is reported as per the readings on the odometer and MUV provides no guarantee to the actual mileage of the vehicle.

## EXTERIOR

|    |  |   |    |   |   |
|----|--|---|----|---|---|
| 1  | Front Skirt                                | N/A   | 32 | Spare Tyre Brand, Size and Year Make      | Dunlop T135/70D16                         |
| 2  | Front Bumper                               | Replaced  | 33 | Rear Trunk                                | Dented (below 3cm), Scratched (above 6cm) |
| 3  | Front Reinforcement                        | Normal  | 34 | Rear Lighting Panel                       | Normal                                    |
| 4  | Front Grille                               | Normal  | 35 | Rear Reinforcement                        | Normal                                    |
| 5  | Front Bonnet                               | Dented (below 3cm), Scratched (above 6cm), Broken / Damaged / Cracked, Rusted & Corrosion, Re-sprayed | 36 | Rear Bumper                               | Normal                                    |
| 6  | Headlamp (Right)                           | Normal  | 37 | Rear Skirt                                | N/A                                       |
| 7  | Hazard/Signal Lamp (Right)                 | Normal  | 38 | Rear Combination Lamp (Right)             | Normal                                    |
| 8  | Headlamp (Left)                            | Normal  | 39 | Rear Combination Lamp (Left)              | Normal                                    |
| 9  | Hazard/Signal Lamp (Left)                  | Normal  | 40 | Rear Windscreen                           | Normal                                    |
| 10 | Front Windscreen                           | Stone Chip  | 41 | Rear Left Fender                          | Dented (below 3cm), Scratched (above 6cm) |
| 11 | Front Right Fender                         | Scratched (above 6cm)   | 42 | Rear Left Tyre Tread                      | 60 mm                                     |
| 12 | Front Right Tyre Tread                     | 68 mm   | 43 | Rear Left Tyre Brand, Size and Year Make  | Goodyear 215/45R17                        |
| 13 | Front Right Tyre Brand, Size and Year Make | Goodyear 215/45R17  | 44 | Left D-pillar                             | Normal                                    |
| 14 | Side Mirror (Right)                        | Normal  | 45 | Left C-pillar                             | Normal                                    |
| 15 | Right A-pillar                             | Normal  | 46 | Rear Left Door                            | Dented (below 3cm), Scratched (3cm - 6cm) |
| 16 | Front Right Door                           | Dented (below 3cm), Scratched (above 6cm)   | 47 | Rear Left Door Window                     | Normal                                    |
| 17 | Front Right Door Window                    | Normal  | 48 | Left Quarter Glass                        | Normal                                    |
| 18 | Right B-pillar                             | Normal  | 49 | Left B-pillar                             | Normal                                    |
| 19 | Right Side Sill                            | Normal  | 50 | Left Side Skirt                           | N/A                                       |
| 20 | Right Side Skirt                           | N/A   | 51 | Left Side Sill                            | Normal                                    |
| 21 | Rear Right Door                            | Dented (below 3cm), Scratched (above 6cm)   | 52 | Front Left Door                           | Dented (below 3cm), Scratched (above 6cm) |
| 22 | Rear Right Door Window                     | Normal  | 53 | Front Left Door Window                    | Normal                                    |
| 23 | Right Quarter Glass                        | Normal  | 54 | Left A-pillar                             | Normal                                    |
| 24 | Right C-pillar                             | Normal  | 55 | Front Left Fender                         | Normal                                    |
| 25 | Right D-pillar                             | Normal  | 56 | Front Left Tyre Tread                     | 65 mm                                     |
| 26 | Rear Right Fender                          | Normal  | 57 | Front Left Tyre Brand, Size and Year Make | Goodyear 215/45R17                        |
| 27 | Rear Right Tyre Tread                      | 65 mm   | 58 | Side Mirror (Left)                        | Normal                                    |
| 28 | Rear Right Tyre Brand, Size and Year Make  | Goodyear 215/45R17  | 59 | Roof Top                                  | Normal                                    |
| 29 | Rear Right Cargo Panel                     | N/A   | 60 | Antenna                                   | Damaged                                   |

30 Rear Left Cargo Panel N/A

61 Vehicle Paint Condition -

31 Spare Tyre Tread 80 mm

Additional comments:

-Need touch up.  
-Front windscreen stone chipped.  
-Front section impact.

Exterior rating

C

## INTERIOR

|    |                         |        |    |   |                            |
|----|-------------------------|--------|----|---|----------------------------|
| 1  | Dashboard               | Normal | 18 | Seat Belt (Rear Left)                           | Normal                     |
| 2  | Audio System            | Normal | 19 | Seat Adjustment (Right)                         | Manual                     |
| 3  | Navigation              | Normal | 20 | Seat Adjustment (Left)                          | Manual                     |
| 4  | Speaker (Right)         | Normal | 21 | Seat (Front Right)                              | Leather, Worn Out, Damaged |
| 5  | Speaker (Left)          | Normal | 22 | Seat (Front Left)                               | Leather                    |
| 6  | Front Console Box       | Normal | 23 | Seat (Rear Right)                               | Leather                    |
| 7  | Floor Console Box       | Normal | 24 | Seat (Rear Left)                                | Leather                    |
| 8  | Armrest                 | Normal | 25 | Steering Wheel                                  | Normal                     |
| 9  | Door Panels (Front)     | Normal | 26 | Gear Knob / Lever                               | Normal                     |
| 10 | Door Panels (Rear)      | Normal | 27 | Central Door Lock (Front Right)                 | Normal                     |
| 11 | Headrest (Front Right)  | Normal | 28 | Central Door Lock (Front Left)                  | Normal                     |
| 12 | Headrest (Front Left)   | Normal | 29 | Central Door Lock (Rear Right)                  | Normal                     |
| 13 | Headrest (Rear Right)   | Normal | 30 | Central Door Lock (Rear Left)                   | Normal                     |
| 14 | Headrest (Rear Left)    | Normal | 31 | Tonneau Cover                                   | Normal                     |
| 15 | Seat Belt (Front Right) | Normal | 32 | Sunroof / Moonroof / Convertible Top / Hard Top | N/A                        |
| 16 | Seat Belt (Rear Right)  | Normal | 33 | Immobilizer                                     | Normal                     |
| 17 | Seat Belt (Front Left)  | Normal |    |   |                            |

Additional comments:

-driver seat damage.  
-interior need cleaning

Interior rating

**B**

## ENGINE

|   |                 |        |   |                              |                     |
|---|-----------------|--------|---|------------------------------|---------------------|
| 1 | Battery         | Normal | 4 | Engine Idle Condition        | Rough Idle, Vibrate |
| 2 | Engine Belting  | Normal | 5 | Engine Running / Temperature | Normal              |
| 3 | Engine Starting | Normal |   |                              |                     |

Additional comments:

-Engine oil leaking

Engine rating

-

## GEARBOX

|   |                        |        |   |                             |        |
|---|------------------------|--------|---|-----------------------------|--------|
| 1 | Gearbox Shifting (A/T) | Normal | 4 | Paddle Shifter / Sport Mode | Normal |
| 2 | Gearbox Shifting (M/T) | N/A    | 5 | 4WD Operation               | N/A    |
| 3 | Clutch Operation (M/T) | N/A    |   |                             |        |

Additional comments:

Gearbox rating

## UNDERCARRIAGE

|   |   |        |   |                 |        |
|---|---|--------|---|-----------------|--------|
| 1 | Shock Absorber /Absorber Mounting (Front) | Normal | 3 | Brake Operation | Normal |
| 2 | Shock Absorber /Absorber Mounting (Rear)  | Normal |   |                 |        |

Additional comments:

Chassis rating

## ELECTRICAL

|   |                             |        |    |                         |                             |
|---|-----------------------------|--------|----|-------------------------|-----------------------------|
| 1 | Power Windows (Front Right) | N/A    | 9  | Boot                    | Manual                      |
| 2 | Power Windows (Rear Right)  | Normal | 10 | Parking Sensor          | Normal                      |
| 3 | Power Windows (Rear Left)   | Normal | 11 | Camera - Front & Rear   | N/A                         |
| 4 | Power Windows (Front Left)  | Normal | 12 | Meters & Gauges         | Normal                      |
| 5 | A/C System                  | Normal | 13 | Warning light (Gearbox) | Normal                      |
| 6 | Washer                      | Normal | 14 | Warning light (Chassis) | ABS warning light always ON |
| 7 | Wiper                       | Normal | 15 | Warning light (Engine)  | Normal                      |
| 8 | Sliding Door                | Normal |    |                         |                             |

Additional comments:

Electrical rating

Test drive comments: