



# MUV MARKETPLACE SDN BHD (253263-U)

Lot 3, Jalan 6/3, Kawasan Perindustrian Seri Kembangan, 43300 Seri Kembangan, Selangor.  
Tel: 03-8947 6888 Fax No: 03-8947 6880

## VEHICLE INSPECTION REPORT

Registration Number	<b>WYB4119</b>	Vehicle Location	-
Vehicle Model	<b>SAGA 1.3 FLX STANDARD (M)</b>	Colour	<b>Brown</b>
Engine Type	<b>Petrol</b>	Year Made	<b>2013</b>
Engine Capacity (C.C.)	<b>1332</b>	Mileage (KM)	<b>99378</b>
Gearbox Type	<b>Manual</b>	Assessment Date	<b>28/02/2020</b>
Type of Usage	<b>Individual Private</b>	Body Type	<b>Sedan</b>
Engine Number	<b>S4PETL5597</b>	Chassis Number	<b>PL1BT3SNRDB372147</b>
Key Set	<b>1</b>		

## INSPECTION SUMMARY


Inspection area	Rating	Page	Inspection area	Rating	Page
Exterior	C	2	Gearbox	-	4
Structure	-	-	Undercarriage	-	4
Interior	A	3	Electrical	A	4
Engine	-	3	Flooded Rating	-	-

## VEHICLE HISTORY


Comments:

-

Structure (Bottom View)



Exterior (Top View)



Legend: ● NA ● Defect ● Normal

Disclaimer: Our inspection report are based on what is seen and heard by our inspectors at the time of inspection. We do not guarantee or warranty any physical deterioration or mechanical/technical failures or defects which arise after the date of inspection. No judgement is made to the internal components of engine, transmission, driveline, electrical or any other systems that require dismantling to diagnose. Our inspection report does not cover the authentication of the components or specification of the vehicle. The mileage is reported as per the readings on the odometer and MUV provides no guarantee to the actual mileage of the vehicle.

## EXTERIOR

1	Front Skirt	Normal	32	Spare Tyre Brand, Size and Year Make	
2	Front Bumper	Scratched (above 6cm)	33	Rear Trunk	Normal
3	Front Reinforcement	Normal	34	Rear Lighting Panel	Normal
4	Front Grille	Normal	35	Rear Reinforcement	Normal
5	Front Bonnet	Scratched (above 6cm)	36	Rear Bumper	Scratched (above 6cm)
6	Headlamp (Right)	Normal	37	Rear Skirt	Normal
7	Hazard/Signal Lamp (Right)	Normal	38	Rear Combination Lamp (Right)	Normal
8	Headlamp (Left)	Normal	39	Rear Combination Lamp (Left)	Normal
9	Hazard/Signal Lamp (Left)	Normal	40	Rear Windscreen	Normal
10	Front Windscreen	Normal	41	Rear Left Fender	Scratched (above 6cm)
11	Front Right Fender	Scratched (above 6cm)	42	Rear Left Tyre Tread	3 mm
12	Front Right Tyre Tread	3 mm	43	Rear Left Tyre Brand, Size and Year Make	Leao, 175/70/R13
13	Front Right Tyre Brand, Size and Year Make	Leao, 175/70/R13	44	Left D-pillar	N/A
14	Side Mirror (Right)	Normal	45	Left C-pillar	Normal
15	Right A-pillar	Normal	46	Rear Left Door	Scratched (above 6cm)
16	Front Right Door	Scratched (above 6cm)	47	Rear Left Door Window	Normal
17	Front Right Door Window	Normal	48	Left Quarter Glass	Normal
18	Right B-pillar	Normal	49	Left B-pillar	Normal
19	Right Side Sill	Normal	50	Left Side Skirt	Normal
20	Right Side Skirt	Normal	51	Left Side Sill	Normal
21	Rear Right Door	Scratched (above 6cm)	52	Front Left Door	Scratched (above 6cm)
22	Rear Right Door Window	Normal	53	Front Left Door Window	Normal
23	Right Quarter Glass	Normal	54	Left A-pillar	Normal
24	Right C-pillar	Normal	55	Front Left Fender	Scratched (above 6cm)
25	Right D-pillar	N/A	56	Front Left Tyre Tread	3 mm
26	Rear Right Fender	Scratched (above 6cm)	57	Front Left Tyre Brand, Size and Year Make	Leao, 175/70/R13
27	Rear Right Tyre Tread	3 mm	58	Side Mirror (Left)	Normal
28	Rear Right Tyre Brand, Size and Year Make	Leao, 175/70/R13	59	Roof Top	Normal
29	Rear Right Cargo Panel	Normal	60	Antenna	Normal
30	Rear Left Cargo Panel	Normal	61	Vehicle Paint Condition	1 Layer Paint
31	Spare Tyre Tread	0 mm			

Additional comments:

1 layer paint.

Exterior rating

Power door lock malfunction.  
Engine oil leaking.

**C**

## INTERIOR

1	Dashboard	Normal	18	Seat Belt (Rear Left)	Normal
2	Audio System	Normal	19	Seat Adjustment (Right)	Normal
3	Navigation	N/A	20	Seat Adjustment (Left)	Normal
4	Speaker (Right)	Normal	21	Seat (Front Right)	Normal
5	Speaker (Left)	Normal	22	Seat (Front Left)	Normal
6	Front Console Box	Normal	23	Seat (Rear Right)	Normal
7	Floor Console Box	Normal	24	Seat (Rear Left)	Normal
8	Armrest	N/A	25	Steering Wheel	Normal
9	Door Panels (Front)	Normal	26	Gear Knob / Lever	Normal
10	Door Panels (Rear)	Normal	27	Central Door Lock (Front Right)	Normal
11	Headrest (Front Right)	Normal	28	Central Door Lock (Front Left)	Normal
12	Headrest (Front Left)	Normal	29	Central Door Lock (Rear Right)	Normal
13	Headrest (Rear Right)	Normal	30	Central Door Lock (Rear Left)	Normal
14	Headrest (Rear Left)	Normal	31	Tonneau Cover	Normal
15	Seat Belt (Front Right)	Normal	32	Sunroof / Moonroof / Convertible Top / Hard Top	N/A
16	Seat Belt (Rear Right)	Normal	33	Immobilizer	Normal
17	Seat Belt (Front Left)	Normal			

Additional comments:

Interior rating

**A**

## ENGINE

1	Battery	Normal	4	Engine Idle Condition	Normal
2	Engine Belting	Normal	5	Engine Running / Temperature	Normal
3	Engine Starting	Normal			

Additional comments:

Engine rating

-

## GEARBOX

1	Gearbox Shifting (A/T)	Normal	4	Paddle Shifter / Sport Mode	Normal
2	Gearbox Shifting (M/T)	Normal	5	4WD Operation	Normal
3	Clutch Operation (M/T)	Normal			

Additional comments:

Gearbox rating

## UNDERCARRIAGE

1	Shock Absorber /Absorber Mounting (Front)	Normal	3	Brake Operation	Normal
2	Shock Absorber /Absorber Mounting (Rear)	Normal			

Additional comments:

Chassis rating

## ELECTRICAL

1	Power Windows (Front Right)	Normal	9	Boot	Normal
2	Power Windows (Rear Right)	Normal	10	Parking Sensor	Normal
3	Power Windows (Rear Left)	Normal	11	Camera - Front & Rear	Normal
4	Power Windows (Front Left)	Normal	12	Meters & Gauges	Normal
5	A/C System	Normal	13	Warning light (Gearbox)	Normal
6	Washer	Normal	14	Warning light (Chassis)	Normal
7	Wiper	Normal	15	Warning light (Engine)	Normal
8	Sliding Door	N/A			

Additional comments:

Electrical rating

Test drive comments: