



MUV MARKETPLACE SDN BHD (253263-U)

Lot 3, Jalan 6/3, Kawasan Perindustrian Seri Kembangan, 43300 Seri Kembangan, Selangor.
Tel: 03-8947 6888 Fax No: 03-8947 6880

VEHICLE INSPECTION REPORT

Registration Number	WBL7040	Vehicle Location	-
Vehicle Model	COROLLA 1.3 (M)	Colour	Silver
Engine Type	Petrol	Year Made	1987
Engine Capacity (C.C.)	1295	Mileage (KM)	461266
Gearbox Type	Manual	Assessment Date	09/03/2020
Type of Usage	Individual Private	Body Type	Sedan
Engine Number	2E0941767	Chassis Number	EE909000368
Key Set	1		

INSPECTION SUMMARY


Inspection area	Rating	Page	Inspection area	Rating	Page
Exterior	C	2	Gearbox	-	4
Structure	-	-	Undercarriage	-	4
Interior	B	3	Electrical	B	4
Engine	-	3	Flooded Rating	-	-

VEHICLE HISTORY


Comments:

-

Structure (Bottom View)



Exterior (Top View)



Legend: ● NA ● Defect ● Normal

Disclaimer: Our inspection report are based on what is seen and heard by our inspectors at the time of inspection. We do not guarantee or warranty any physical deterioration or mechanical/technical failures or defects which arise after the date of inspection. No judgement is made to the internal components of engine, transmission, driveline, electrical or any other systems that require dismantling to diagnose. Our inspection report does not cover the authentication of the components or specification of the vehicle. The mileage is reported as per the readings on the odometer and MUV provides no guarantee to the actual mileage of the vehicle.

EXTERIOR

1	Front Skirt	N/A	32	Spare Tyre Brand, Size and Year Make	Dunlop 175/70R13
2	Front Bumper	Dented (below 3cm), Scratched (above 6cm), Broken / Damaged / Cracked, Rusted & Corrosion, Repaired	33	Rear Trunk	Dented (below 3cm), Scratched (above 6cm), Broken / Damaged / Cracked, Rusted & Corrosion
3	Front Reinforcement	Normal	34	Rear Lighting Panel	Normal
4	Front Grille	Normal	35	Rear Reinforcement	Normal
5	Front Bonnet	Dented (below 3cm), Scratched (above 6cm), Broken / Damaged / Cracked, Rusted & Corrosion	36	Rear Bumper	Dented (below 3cm), Scratched (above 6cm), Broken / Damaged / Cracked, Rusted & Corrosion
6	Headlamp (Right)	Normal	37	Rear Skirt	N/A
7	Hazard/Signal Lamp (Right)	Normal	38	Rear Combination Lamp (Right)	Scratched, Damaged
8	Headlamp (Left)	Normal	39	Rear Combination Lamp (Left)	Normal
9	Hazard/Signal Lamp (Left)	Normal	40	Rear Windscreen	Normal
10	Front Windscreen	Normal	41	Rear Left Fender	Dented (below 3cm), Scratched (above 6cm), Broken / Damaged / Cracked, Rusted & Corrosion
11	Front Right Fender	Scratched (above 6cm), Rusted & Corrosion	42	Rear Left Tyre Tread	30 mm
12	Front Right Tyre Tread	40 mm	43	Rear Left Tyre Brand, Size and Year Make	Dunlop 175/70R13
13	Front Right Tyre Brand, Size and Year Make	Silverstone 175/70R13	44	Left D-pillar	Normal
14	Side Mirror (Right)	Normal	45	Left C-pillar	Normal
15	Right A-pillar	Rusted & Corrosion, Repaired	46	Rear Left Door	Dented (below 3cm), Scratched (above 6cm), Rusted & Corrosion
16	Front Right Door	Dented (below 3cm), Scratched (above 6cm), Broken / Damaged / Cracked, Rusted & Corrosion, Repaired	47	Rear Left Door Window	Normal
17	Front Right Door Window	Normal	48	Left Quarter Glass	Normal
18	Right B-pillar	Normal	49	Left B-pillar	Normal
19	Right Side Sill	Normal	50	Left Side Skirt	N/A
20	Right Side Skirt	N/A	51	Left Side Sill	Normal
21	Rear Right Door	Dented (below 3cm), Scratched (above 6cm), Broken / Damaged / Cracked, Rusted & Corrosion	52	Front Left Door	Dented (below 3cm), Scratched (above 6cm), Rusted & Corrosion
22	Rear Right Door Window	Normal	53	Front Left Door Window	Normal
23	Right Quarter Glass	Normal	54	Left A-pillar	Normal

24	Right C-pillar	Normal	55	Front Left Fender	Dented (above 6cm), Scratched (above 6cm), Broken / Damaged / Cracked, Rusted & Corrosion
25	Right D-pillar	Normal	56	Front Left Tyre Tread	40 mm
26	Rear Right Fender	Dented (below 3cm), Scratched (above 6cm), Broken / Damaged / Cracked, Rusted & Corrosion, Repaired	57	Front Left Tyre Brand, Size and Year Make	Silverstone 175/70R13
27	Rear Right Tyre Tread	30 mm	58	Side Mirror (Left)	Normal
28	Rear Right Tyre Brand, Size and Year Make	Dunlop 175/70R13	59	Roof Top	Dented (below 3cm), Scratched (above 6cm), Broken / Damaged / Cracked, Rusted & Corrosion
29	Rear Right Cargo Panel	N/A	60	Antenna	Normal
30	Rear Left Cargo Panel	N/A	61	Vehicle Paint Condition	2 Layer Paint
31	Spare Tyre Tread	50 mm			

Additional comments:

-wholebody need repaint.
-rear trunk impact.

Exterior rating

C

INTERIOR

1	Dashboard	Damaged, Scratched	18	Seat Belt (Rear Left)	Normal
2	Audio System	Normal	19	Seat Adjustment (Right)	Manual
3	Navigation	N/A	20	Seat Adjustment (Left)	Manual
4	Speaker (Right)	Normal	21	Seat (Front Right)	Fabric, Worn Out, Damaged
5	Speaker (Left)	Normal	22	Seat (Front Left)	Fabric, Worn Out
6	Front Console Box	Normal	23	Seat (Rear Right)	Fabric
7	Floor Console Box	Normal	24	Seat (Rear Left)	Fabric, Stain Mark
8	Armrest	Scratched, Damaged	25	Steering Wheel	Normal
9	Door Panels (Front)	Normal	26	Gear Knob / Lever	Normal
10	Door Panels (Rear)	Normal	27	Central Door Lock (Front Right)	Normal
11	Headrest (Front Right)	Normal	28	Central Door Lock (Front Left)	Normal
12	Headrest (Front Left)	Normal	29	Central Door Lock (Rear Right)	Normal
13	Headrest (Rear Right)	Normal	30	Central Door Lock (Rear Left)	Normal
14	Headrest (Rear Left)	Normal	31	Tonneau Cover	N/A
15	Seat Belt (Front Right)	Normal	32	Sunroof / Moonroof / Convertible Top / Hard Top	N/A
16	Seat Belt (Rear Right)	Normal	33	Immobilizer	N/A
17	Seat Belt (Front Left)	Normal			

Additional comments:

-Interior need cleaning.
-head liner dirty.

Interior rating

B

ENGINE

1	Battery	Normal	4	Engine Idle Condition	Rough Idle, Vibrate, Idling Unstable
2	Engine Belting	Normal	5	Engine Running / Temperature	Normal
3	Engine Starting	Normal			

Additional comments:

-engine oil badly leaking

Engine rating

-

GEARBOX

1	Gearbox Shifting (A/T)	N/A	4	Paddle Shifter / Sport Mode	N/A
2	Gearbox Shifting (M/T)	Normal	5	4WD Operation	N/A
3	Clutch Operation (M/T)	Normal			

Additional comments:

-

Gearbox rating

-

UNDERCARRIAGE

1	Shock Absorber /Absorber Mounting (Front)	Leaking,Damaged	3	Brake Operation	Normal
2	Shock Absorber /Absorber Mounting (Rear)	Leaking,Damaged			

Additional comments:

-Engine oil badly leaking.

Chassis rating

-

ELECTRICAL

1	Power Windows (Front Right)	Normal	9	Boot	Manual
2	Power Windows (Rear Right)	N/A	10	Parking Sensor	N/A
3	Power Windows (Rear Left)	N/A	11	Camera - Front & Rear	N/A
4	Power Windows (Front Left)	Normal	12	Meters & Gauges	Normal
5	A/C System	Not Cold	13	Warning light (Gearbox)	Normal
6	Washer	Malfunction	14	Warning light (Chassis)	Normal
7	Wiper	Normal	15	Warning light (Engine)	Normal
8	Sliding Door	N/A			

Additional comments:

-aircold not cold

Electrical rating

B

Test drive comments:

-Engine vibrate & noise
-noise from piston engine .