



# MUV MARKETPLACE SDN BHD (253263-U)

Lot 3, Jalan 6/3, Kawasan Perindustrian Seri Kembangan, 43300 Seri Kembangan, Selangor.  
Tel: 03-8947 6888 Fax No: 03-8947 6880

## VEHICLE INSPECTION REPORT

|                        |                           |                  |                          |
|------------------------|---------------------------|------------------|--------------------------|
| Registration Number    | <b>WSP1496</b>            | Vehicle Location | -                        |
| Vehicle Model          | <b>VIOS S 1.5 (A)</b>     | Colour           | <b>Black</b>             |
| Engine Type            | <b>Petrol</b>             | Year Made        | <b>2009</b>              |
| Engine Capacity (C.C.) | <b>1497</b>               | Mileage (KM)     | <b>299800</b>            |
| Gearbox Type           | <b>Automatic</b>          | Assessment Date  | <b>09/03/2020</b>        |
| Type of Usage          | <b>Individual Private</b> | Body Type        | <b>Sedan</b>             |
| Engine Number          | <b>1NZX898369</b>         | Chassis Number   | <b>PN153HY9307050238</b> |
| Key Set                | <b>1</b>                  |                  |                          |

## INSPECTION SUMMARY


| Inspection area | Rating | Page | Inspection area | Rating | Page |
|-----------------|--------|------|-----------------|--------|------|
| Exterior        | D      | 2    | Gearbox         | -      | 4    |
| Structure       | -      | -    | Undercarriage   | -      | 4    |
| Interior        | A      | 3    | Electrical      | A      | 4    |
| Engine          | -      | 3    | Flooded Rating  | -      | -    |

## VEHICLE HISTORY


### Comments:

-

Structure (Bottom View)



Exterior (Top View)



**Legend:** ● NA ● Defect ● Normal

Disclaimer: Our inspection report are based on what is seen and heard by our inspectors at the time of inspection. We do not guarantee or warranty any physical deterioration or mechanical/technical failures or defects which arise after the date of inspection. No judgement is made to the internal components of engine, transmission, driveline, electrical or any other systems that require dismantling to diagnose. Our inspection report does not cover the authentication of the components or specification of the vehicle. The mileage is reported as per the readings on the odometer and MUV provides no guarantee to the actual mileage of the vehicle.

## EXTERIOR

|    |  |                        |    |   |                        |
|----|--|------------------------|----|---|------------------------|
| 1  | Front Skirt                                | N/A                    | 32 | Spare Tyre Brand, Size and Year Make      |                        |
| 2  | Front Bumper                               | Scratched (3cm - 6cm)  | 33 | Rear Trunk                                | N/A                    |
| 3  | Front Reinforcement                        | Scratched (3cm - 6cm)  | 34 | Rear Lighting Panel                       | Normal                 |
| 4  | Front Grille                               | Scratched (3cm - 6cm)  | 35 | Rear Reinforcement                        | Normal                 |
| 5  | Front Bonnet                               | Scratched (3cm - 6cm)  | 36 | Rear Bumper                               | Scratched (3cm - 6cm)  |
| 6  | Headlamp (Right)                           | Yellowish              | 37 | Rear Skirt                                | N/A                    |
| 7  | Hazard/Signal Lamp (Right)                 | Normal                 | 38 | Rear Combination Lamp (Right)             | Normal                 |
| 8  | Headlamp (Left)                            | Yellowish              | 39 | Rear Combination Lamp (Left)              | Normal                 |
| 9  | Hazard/Signal Lamp (Left)                  | Normal                 | 40 | Rear Windscreen                           | Normal                 |
| 10 | Front Windscreen                           | Normal                 | 41 | Rear Left Fender                          | Scratched (3cm - 6cm)  |
| 11 | Front Right Fender                         | Scratched (3cm - 6cm)  | 42 | Rear Left Tyre Tread                      | 0 mm                   |
| 12 | Front Right Tyre Tread                     | 0 mm                   | 43 | Rear Left Tyre Brand, Size and Year Make  | Continental, 195/60R15 |
| 13 | Front Right Tyre Brand, Size and Year Make | Continental, 195/60R15 | 44 | Left D-pillar                             | N/A                    |
| 14 | Side Mirror (Right)                        | Normal                 | 45 | Left C-pillar                             | Scratched (below 3cm)  |
| 15 | Right A-pillar                             | Scratched (below 3cm)  | 46 | Rear Left Door                            | Scratched (3cm - 6cm)  |
| 16 | Front Right Door                           | Scratched (3cm - 6cm)  | 47 | Rear Left Door Window                     | Normal                 |
| 17 | Front Right Door Window                    | Normal                 | 48 | Left Quarter Glass                        | Normal                 |
| 18 | Right B-pillar                             | Scratched (below 3cm)  | 49 | Left B-pillar                             | Scratched (below 3cm)  |
| 19 | Right Side Sill                            | Scratched (3cm - 6cm)  | 50 | Left Side Skirt                           | Scratched (3cm - 6cm)  |
| 20 | Right Side Skirt                           | Scratched (3cm - 6cm)  | 51 | Left Side Sill                            | Scratched (3cm - 6cm)  |
| 21 | Rear Right Door                            | Scratched (3cm - 6cm)  | 52 | Front Left Door                           | Scratched (3cm - 6cm)  |
| 22 | Rear Right Door Window                     | Normal                 | 53 | Front Left Door Window                    | Normal                 |
| 23 | Right Quarter Glass                        | Normal                 | 54 | Left A-pillar                             | Scratched (below 3cm)  |
| 24 | Right C-pillar                             | Scratched (below 3cm)  | 55 | Front Left Fender                         | Scratched (3cm - 6cm)  |
| 25 | Right D-pillar                             | N/A                    | 56 | Front Left Tyre Tread                     | 0 mm                   |
| 26 | Rear Right Fender                          | Scratched (3cm - 6cm)  | 57 | Front Left Tyre Brand, Size and Year Make | Continental, 195/60R15 |
| 27 | Rear Right Tyre Tread                      | 0 mm                   | 58 | Side Mirror (Left)                        | Normal                 |
| 28 | Rear Right Tyre Brand, Size and Year Make  | Continental, 195/60R15 | 59 | Roof Top                                  | Scratched (3cm - 6cm)  |
| 29 | Rear Right Cargo Panel                     | Normal                 | 60 | Antenna                                   | Normal                 |
| 30 | Rear Left Cargo Panel                      | Normal                 | 61 | Vehicle Paint Condition                   | 1 Layer Paint          |
| 31 | Spare Tyre Tread                           | 0 mm                   |    |   |                        |

Additional comments:

Exterior rating



## INTERIOR

|    |                         |        |    |   |          |
|----|-------------------------|--------|----|---|----------|
| 1  | Dashboard               | Normal | 18 | Seat Belt (Rear Left)                           | Normal   |
| 2  | Audio System            | Normal | 19 | Seat Adjustment (Right)                         | Normal   |
| 3  | Navigation              | N/A    | 20 | Seat Adjustment (Left)                          | Normal   |
| 4  | Speaker (Right)         | Normal | 21 | Seat (Front Right)                              | Normal   |
| 5  | Speaker (Left)          | Normal | 22 | Seat (Front Left)                               | Normal   |
| 6  | Front Console Box       | Normal | 23 | Seat (Rear Right)                               | Normal   |
| 7  | Floor Console Box       | Normal | 24 | Seat (Rear Left)                                | Normal   |
| 8  | Armrest                 | Normal | 25 | Steering Wheel                                  | Worn Out |
| 9  | Door Panels (Front)     | Normal | 26 | Gear Knob / Lever                               | Normal   |
| 10 | Door Panels (Rear)      | Normal | 27 | Central Door Lock (Front Right)                 | Normal   |
| 11 | Headrest (Front Right)  | Normal | 28 | Central Door Lock (Front Left)                  | Normal   |
| 12 | Headrest (Front Left)   | Normal | 29 | Central Door Lock (Rear Right)                  | Normal   |
| 13 | Headrest (Rear Right)   | Normal | 30 | Central Door Lock (Rear Left)                   | Normal   |
| 14 | Headrest (Rear Left)    | Normal | 31 | Tonneau Cover                                   | Normal   |
| 15 | Seat Belt (Front Right) | Normal | 32 | Sunroof / Moonroof / Convertible Top / Hard Top | N/A      |
| 16 | Seat Belt (Rear Right)  | Normal | 33 | Immobilizer                                     | Normal   |
| 17 | Seat Belt (Front Left)  | Normal |    |   |          |

Additional comments:

Interior rating

**A**

## ENGINE

|   |                 |        |   |                              |        |
|---|-----------------|--------|---|------------------------------|--------|
| 1 | Battery         | Normal | 4 | Engine Idle Condition        | Normal |
| 2 | Engine Belting  | Normal | 5 | Engine Running / Temperature | Normal |
| 3 | Engine Starting | Normal |   |                              |        |

Additional comments:

Engine rating

-

## GEARBOX

|   |                        |        |   |                             |        |
|---|------------------------|--------|---|-----------------------------|--------|
| 1 | Gearbox Shifting (A/T) | Normal | 4 | Paddle Shifter / Sport Mode | Normal |
| 2 | Gearbox Shifting (M/T) | N/A    | 5 | 4WD Operation               | Normal |
| 3 | Clutch Operation (M/T) | Normal |   |                             |        |

Additional comments:

Gearbox rating

## UNDERCARRIAGE

|   |   |        |   |                 |        |
|---|---|--------|---|-----------------|--------|
| 1 | Shock Absorber /Absorber Mounting (Front) | Normal | 3 | Brake Operation | Normal |
| 2 | Shock Absorber /Absorber Mounting (Rear)  | Normal |   |                 |        |

Additional comments:

Chassis rating

## ELECTRICAL

|   |                             |        |    |                         |        |
|---|-----------------------------|--------|----|-------------------------|--------|
| 1 | Power Windows (Front Right) | Normal | 9  | Boot                    | Normal |
| 2 | Power Windows (Rear Right)  | Normal | 10 | Parking Sensor          | Normal |
| 3 | Power Windows (Rear Left)   | Normal | 11 | Camera - Front & Rear   | N/A    |
| 4 | Power Windows (Front Left)  | Normal | 12 | Meters & Gauges         | Normal |
| 5 | A/C System                  | Normal | 13 | Warning light (Gearbox) | Normal |
| 6 | Washer                      | Normal | 14 | Warning light (Chassis) | Normal |
| 7 | Wiper                       | Normal | 15 | Warning light (Engine)  | Normal |
| 8 | Sliding Door                | N/A    |    |                         |        |

Additional comments:

Electrical rating

Test drive comments: