



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.aspenfieldservices.com/api/attachments/get/8cPPGGZpKxqdmfAr8/full_report_0068218_8cPPGGZpKxqdmfAr8.pdf?view

NOTE: By clicking above, you will be redirected to Aspen Field Services.

Inspection Details	
Year	2019
Make	Bobcat
Model	T590
Date of Inspection	03/05/2024
Location of Inspection	5875 State Street , Bettendorf, IA, 52722, USA
Serial Number	ALJU30285
Cylinders	See Notes
Engine Hours	2,352
EMS Warning Lights	No Active Warnings
Travel Control	No Damages Observed
Operator's Seat	See Notes
Mirrors	N/A
Radio	No
A/C	No
Steering Wheel	N/A



Inspection Details Cont'd	
Pedals	No Damages Observed
Floorboard	No Damages Observed
Power Mirrors	No
Heated Mirrors	No
Switches and Controls	No Damages Observed
Steps	See Notes
Handrails	No Damages Observed
Oil Dipstick	Good Level / Dark Color
Engine Compartment	See Notes
Exhaust	No Damages Observed
Axles	N/A
Deluxe Instrumentation	No
Backup Camera	No
ROPS	No Damages Observed
Front Lights	No Damages Observed
Rear Lights	See Notes
Left Track Condition	See Notes
Left Track Brand	Could Not Be Located
Left Track Size	Could Not Be Located
Left Track Tread Depth Measurement	1"
Right Track Condition	See Notes
Right Track Brand	Could Not Be Located
Right Track Size	Could Not Be Located
Right Track Tread Depth Measurement	1"
Attachments - Bucket	No Damages Observed
Comments	The unit runs and drives. The site confirmed that the lights are operational. The left taillight lens is damaged at the bottom. The rear work lights are absent. The headliner in the cab seems to be drooping at the rear. The material on the operator's seat is torn. The upper engine enclosure at the rear appears to be bent and has a dent in the screen. The engine oil is dark in color. The bucket steps are bent. The left track appears to be loose. The sprockets on both sides are worn out. The lift cylinder is leaking. The right sprocket appears to be oily, indicating a leak from the final drive. The tilt cylinders appear to be oily and possibly leaking.

Inspection Details Cont'd

Aspen Field Services



Front Left / Attachments - Bucket / 03-06-2024



Front / Attachments - Bucket / Front Lights / 03-05-2024

Aspen Field Services



Front Right / Attachments - Bucket / 03-05-2024



Rear Left / 03-05-2024

Aspen Field Services



Rear / Rear Lights / 03-05-2024



Rear Right / 03-05-2024

Aspen Field Services



Right / 03-05-2024



Left / 03-05-2024

Aspen Field Services



S/N: ALJU30285 / 03-05-2024



Engine Hours: 2,352 / 03-05-2024

Aspen Field Services



EMS Warning Lights / 03-05-2024



Interior Condition / ROPS / Handrails / Operator's Seat / 03-05-2024

Aspen Field Services



Switches and Controls / 03-05-2024



Switches and Controls / 03-05-2024

Aspen Field Services



Switches and Controls / 03-05-2024



Switches and Controls / 03-05-2024

Aspen Field Services



Switches and Controls / Travel Control / 03-05-2024




Switches and Controls / Travel Control / 03-05-2024

Aspen Field Services



Floorboard / Pedals / 03-05-2024



Engine Compartment / 03-05-2024

Aspen Field Services



Engine Compartment / Exhaust / 03-05-2024



Oil Dipstick / 03-05-2024

Aspen Field Services



Steps / 03-05-2024



Steps / 03-05-2024

Aspen Field Services



Left Track Condition / 03-05-2024



Left Track Condition / 03-05-2024

Aspen Field Services



Left Track Condition / 03-05-2024



Left Track Condition / 03-05-2024

Aspen Field Services



Left Track Tread Depth Measurement / 03-05-2024



Right Track Condition / 03-05-2024

Aspen Field Services



Right Track Condition / 03-05-2024



Right Track Condition / 03-05-2024

Aspen Field Services



Right Track Condition / 03-05-2024



Right Track Tread Depth Measurement / 03-05-2024

Aspen Field Services



Cylinders / 03-05-2024



Cylinders / 03-05-2024

Aspen Field Services



Cylinders / 03-05-2024



Cylinders / 03-05-2024