




Inspection Detail				
	Client:	CloudStore		
	Inspected by:			
	Location of Inspection:	1116 MN-23, Pipestone, MN 56164		
	Phone No / Email:	+1 507 820 1720 / nonapplicable@gmail.com		
	Date of Inspection:	6/19/2024	Job#:	8688u58jk
	Year:	2019	Make:	Komatsu
	Model:	PC138US	VIN:	KMTPC261JJA052547

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Inspection Details

Observations / Comments

The Front and Rear Lights are not operational. The bucket is missing. The rear counterweight has paint scratches on it. Both of the tracks appear to be loose. The unit is showing a warning for the fan control system abnormality on the dash at the time of inspection. The headliner and roof panel are stained. The armrests on the operator seat are worn. The bottom aftermarket seat cover is coming off. The left foot pedal pad cover is missing. The front right sheet metal panel is dented and the paint is missing. The right center sheet metal cover is bent and dented. The rear right compartment door panel is bent and dented. The front right step is bent. The engine coolers appear to be dirty. The tie-down loops on the sides of the blade appear to be broken off. The blade lift cylinder shields appear to be missing on top of the cylinders. The rubber track shoes have cuts and gouges in them. Some of the track link pins are starting to show wear. The coolant is low in the reservoir. The front right grab handle appears to be bent. The front left lower sheet metal below the cab appears to be bent.

Unit Information

Engine Hours:	3,747	EMS Warning Lights:	Yes
----------------------	-------	----------------------------	-----

Interior Details

Interior Condition:	No Damages Observed	Operator's Seat:	See Notes	Radio:	Yes
A/C:	Yes	Hand Controls:	No Damages Observed	Pedals:	See Notes
Floorboard:	No Damages Observed	Power Mirrors:	No	Heated Mirrors:	No
Switches and Controls:	No Damages Observed	Cab Mirror:	N/A	Back-Up Camera:	Yes

Exterior Details

Mirrors:	No Damages Observed	Steps:	See Notes	Handrails:	See Notes
Exhaust Pipe:	No Damages Observed	ROPS:	No Damages Observed	Undercarriage:	Good Condition
Front Lights:	See Notes	Rear Lights:	See Notes	Engine Serial Plate:	Obstructed
Bucket:	No	Bucket Condition:	N/A	Bucket Cylinder Condition:	No Damages Observed
Blade:	N/A	Blade Condition:	No Damages Observed	Blade Cylinder Condition:	No Damages Observed
Thumb:	No	Thumb Condition:	NA	Thumb Cylinder Condition:	NA
Swing Tower Cylinder:	No	Swing Tower Cylinder Condition:	NA	Stick Cylinder:	Yes
Boom Cylinder:	Yes	Boom Cylinder Condition:	Good Condition	Additional Cylinders:	Yes
Additional Cylinders Condition:	Good Condition	Additional Cylinders Name:	Hydraulic Coupler Cylinder		
Attachment Type:	Blade	Attachment Condition:	No Damages Observed		

Engine Details

Engine Compartment:	See Notes	Oil Dipstick:	Good Level / Good Color
----------------------------	-----------	----------------------	-------------------------

Tracks

Right Track Condition:	See Notes	Right Track Brand:	Obstructed	Right Track Size:	Obstructed
Right Track Tread Depth Measurement:	2.75"	Right Track-Idler:	No Damages Observed	Right Track-Sprocket:	No Damages Observed
Right Track Rollers:	No Damages Observed				
Left Track Condition:	No Damages Observed	Left Track Brand:	Bridgestone	Left Track Size:	Obstructed
Left Track Tread Depth Measurement:	2.75"	Left Track-Idler:	No Damages Observed	Left Track-Sprocket:	No Damages Observed
Left Track Rollers:	No Damages Observed				

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Front Left



Front Right



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Front



Rear Left



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Rear Right



Rear



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Left



Right




Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Serial Number:KMTPC261JJA052547



ROPS Serial Number: CT18527799




Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Engine Hours: 3,747 / EMS Warning Lights / Backup Camera



Deluxe Instrumentation



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Interior Condition / Handrails



Interior Condition / Handrails



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Operator's Seat



ROPS



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Radio



A/C / Switches and Controls



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Switches and Controls



Switches and Controls



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Switches and Controls



Switches and Controls



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Switches and Controls



Hand Controls



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Pedals / Floorboard



Handrails



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Handrails



Steps



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Steps



Mirrors



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Undercarriage



Undercarriage



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Undercarriage



Undercarriage



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Engine Compartment



Engine Compartment




Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Engine Compartment




Oil Dipstick



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Engine Information

Exhaust Pipe

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Attachment - Blade



Attachment - Blade



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Hydraulic Coupler Cylinder



Hydraulic Coupler Cylinder



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Blade Cylinder Condition



Blade Cylinder Condition



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Bucket Cylinder Condition



Boom Cylinder



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Boom Cylinder



Stick Cylinder



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Hydraulic Coupler Cylinder



Left Track Condition / Left Track Rollers



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Left Track Condition



Left Track - Sprocket



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Left Track - Idler



Left Track Condition



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Left Track Condition



Left Track Brand



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Left Track Condition



Left Track Tread Depth Measurement



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Right Track Condition



Right Track Condition



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Right Track - Sprocket



Right Track - Idler



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Right Track - Rollers



Right Track Condition



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Right Track Condition



Right Track Condition



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Right Track Tread Depth Measurement



Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.