## TECHNICAL PARAMETER

| Signal | Range | Precision | Number | Error |
|---|---|---|---|---|
| Voltage (V) | 0~10V | 0.01mV | Output | ±0.02% |
| Voltage (V) | 0~24V | 0.01mV | Output | ±0.02% |
| mA (I) | 0~20mA | 0.01μA | Output | ±0.02% |
| mA (I) | 4~20mA | 0.01μA | Output | ±0.02% |
| Resistance (Ω) | 0~400Ω | 0.01Ω | Output | ±0.02% |
| Resistance (Ω) | 0~4000Ω | 0.1Ω | Output | ±0.02% |
| Thermocouple (℃) | B (0~1820℃) | 0.01℃ | Output | ±0.02% |
| Thermocouple (℃) | E (-100~1000℃) | 0.01℃ | Output | ±0.02% |
| Thermocouple (℃) | J (-100~1200℃) | 0.01℃ | Output | ±0.02% |
| Thermocouple (℃) | K (-100~1372℃) | 0.01℃ | Output | ±0.02% |
| Thermocouple (℃) | N (-100~1300℃) | 0.01℃ | Output | ±0.02% |
| Thermocouple (℃) | R (-50~1768℃) | 0.01℃ | Output | ±0.02% |
| Thermocouple (℃) | S (-50~1768℃) | 0.01℃ | Output | ±0.02% |
| Thermocouple (℃) | T (-100~400℃) | 0.01℃ | Output | ±0.02% |
| RTD | PT100 (-200~850℃) | 0.01℃ | Output | ±0.02% |
| RTD | PT1000 (-200~850℃) | 0.01℃ | Output | ±0.02% |

| Output Signal | Input Signal |
|---|---|
| Voltage: 0~24V | Voltage: 0~30V |
| Current: 0~24mA | Current: 0~30mA |
| Frequency: 0~1MHz | Frequency/PWM: 0~1MHz |
| Pulse: 0~65535 | Pulse: 0~65535 |
| Resistance: 0~4000Ω | Resistance: 0~4000Ω |
| RTD: PT100/PT1000 | RTD: PT100/PT1000 |
| Thermocouple: B/E/J/K/N/R/S/T | Thermocouple: B/E/J/K/N/R/S/T |

**Extended Function**

- Support HART communication protocol, can read and write HART instrument parameters
- Support 24V loop power supply, can directly power the transmitter
- Support 24V loop power supply, can directly power the transmitter

## VARIETY OF SIGNALS WITH YOU

/ UP TO 100,000 OR 15 SETS OF DATA CAN BE RECORDED /