Release Notes

Public Release

Version 1.0.11	
Features	• Added front panel timeout feature. The front panel display will turn off after 30 seconds of non-use. Pressing a button on the front panel will awaken the unit.
Bug Fixes	• None
Known Issues	• None

Previous Releases

Version 1.0.09	
Features	• If communication with the DHCP server is lost, the unit will automatically switch to Auto IP mode.
Bug Fixes	• Fixed an issue where Preset 4 was not properly saving the routing settings.
Known Issues	• None

Version 1.0.00
• Factory Firmware