IMPORTANT: the firmware update cycle can take up to 10 minutes, and the device may reboot twice during update process.

Public Release

Version 1.0.0	
Features	Initial Firmware Release
Bug Fixes	
Known Issues	• Certain USB hubs, when connected to a device port on the AT-USB-EX350-KIT, can cause the unit to incorrectly report device connectivity status on the web UI. This does not affect the functionality of the AT-USB-EX350-KIT. This has only been seen in isolated cases, and a work-around is to use a hub from a different manufacturer. • When accessing the web UI using the Mozilla Firefox® browser, refreshing the web page can cause the the AT-USB-EX350-KIT login page to be displayed. In this case, it is recommended to use a different browser, such as Google Chrome™, to avoid this issue. • Repeatedly sending the UsbInfo.Get API call to the AT-USB-EX350-KIT can cause USB 3.0 devices to disconnect and reconnect. Users are advised not to poll this command regularly as it can cause connectivity issues.