Release Notes

IMPORTANT: the firmware update cycle can take up to 10 minutes, and the device may reboot twice during update process.

Public Release

Version 1.1.7	
Features	• The built-in dongle firmware updated to 1.1.8
Bug Fixes	• Fixed—The built-in default guide screen picture has a typo. • Fixed—Occasional the built-in soft AP name is incorrect.
Know Issues	• No Known Issues

Previous Releases

Version 1.1.5	
Bug Fixes	• Solve the problem of being unable to log in via SSH
Know Issues	• No Known Issues
Version 1.1.4	
Bug Fixes	• Resolve the issue of MixerMute and InputMute not being effective • Fix the issue of IPDHCP on when there is no DHCP server and the device does not have a local link • Resolve the issue of being unable to log in to web pages after restoring factory settings • Fixed the issue of automatic reconnection when switching from one DHCP service network to another. • First login prompt to change password. • API Command missing • SSL/HTTPS Certificates • Unit stops working in DHCP mode after IPDHCP off / on / sta; no DHCP Discover frames sent. • Dante Command reporting wrong number • Signal presence not reported in WebUI or APIGAIN does not self-assign a link-local IP when DHCP is unavailable • GAIN-M won't get DHCP IP after Factory Reset • GAIN keeps old DHCP lease after moving to a new VLAN • IP address is not being reported correctly • IP Mode — I have raised the static IP related question in Jira; the requirements need to be confirmed. • Change P/N on login page • Change Logo
Know Issues	• No Known Issues
Version 1.0.0	
Features	• Factory Firmware