Release Notes

Public Release

Version 1.0.03	
Features	• N/A
Bug Fixes	• Addressed HDCP period mismatch with certain older AVR repeater outputs.
Known Issues	• Extenders are not fully compatible with AT-UHD-CAT series of Distribution Amplifiers over HDMI due to their short DDC timing constraints. This results in a prolonged delay before handshaking is established, due to constant HPD and DDC retries. • When changing channels on a DirecTV C61 Genie Mini Client, the AT-HDR-EX-70-2PS may fail to sync, resulting in a black frame, no signal message, or snow present on the display.

Previous Releases

Version 1.0.02 - TX	
Features	• N/A
Bug Fixes	• Extender no longer reports Dolby Vision 4K@60 as supported, resulting in a black screen. *Dolby Vision 4K@30 **is** supported.
Known Issues	• N/A

Version 1.0.02 - RX	
Features	• N/A
Bug Fixes	• Fixed negotiation issues with ViewSonic PC monitors. • Improved support for displays where slow response time resulted in long delays for video.
Known Issues	• N/A

Version 1
• Factory Firmware