Release Notes

Public Release

Version 1.0.16	
Features	• N/A
Bug Fixes	• Improved switching time and handshaking. • Fixed compatibility with 2018 Samsung displays (e.g. NU6xxx, NU7xxx, QxF series). • Fixed an issue where using the DirecTV C61K-700 source would produce an output resolution of 1600x720p when viewing 720p60 10-bit channels.
Known Issues	• Extenders are not fully compatible with AT-UHD-CAT-series of distribution amplifiers over HDMI, due to short DDC timing constraints. This results in prolonged delay before handshaking is established caused by constant HPD and DDC retries. • The DirecTV C61K-700 set-top box, when connected to certain models of LG displays, produces random “snow”, when changing channels.

Previous Releases

Version 1.0.04	
Features	• N/A
Bug Fixes	• Fixed an issue where changing channels, using the DirecTV C61 or HR54, resulted in a permanent black frame, no signal message, or snow on the display. • Fixed an issue where, after an extended period of time, a signal drop was encountered when using the DirecTV C61 or HR54 as a source.
Known Issues	• Extenders are not fully compatible with AT-UHD-CAT series of Distribution Amplifiers over HDMI due to their short DDC timing constraints. This results in a prolonged delay before handshaking is established, due to constant HPD and DDC retries.

Version 1.0.03	
Features	• N/A
Bug Fixes	• Addressed HDCP period mismatch with certain older AVR repeater outputs.
Known Issues	• Extenders are not fully compatible with AT-UHD-CAT series of Distribution Amplifiers over HDMI due to their short DDC timing constraints. This results in a prolonged delay before handshaking is established, due to constant HPD and DDC retries. • When changing channels on a DirecTV C61 Genie Mini Client, the AT-HDR-EX-70-2PS may fail to sync, resulting in a black frame, no signal message, or snow present on the display.

Version 1.0.02 - TX	
Features	• N/A
Bug Fixes	• Extender no longer reports Dolby Vision 4K@60 as supported, resulting in a black screen. *Dolby Vision 4K@30 **is** supported.
Known Issues	• N/A

Version 1.0.02 - RX	
Features	• N/A
Bug Fixes	• Fixed negotiation issues with ViewSonic PC monitors. • Improved support for displays where slow response time resulted in long delays for video.
Known Issues	• N/A

Version 1
• Factory Firmware