Release Notes

Public Release

Version 1.0.1	
Features	• Added support for AT-OME-CS31-SA-C. • General improvements. • Add mute toggle option to the API method `AudioOutputMute.Set`. • Added support for mDNS. • Update to Valens Firmware 7.5.23. • Added 21:9 internal EDID(s): » 2560x1080 » 3440x1440 » 5120x2160
Bug Fixes	• Updated the API method `DisplayCtrlOperation.Set`. Update to Velocity 2.8.1 for support. • Resolved an issue in which the API method `DisplayCtrlCmd.Set` would not execute. • Resolved an audio drop issue with certain LG displays. • Resolved an issue where certain USB peripherals would not turn on if USB VBUS is set to Always On.
Known Issues	• Compatibility with OME-SW21-TX-WPC to come in a future firmware release. • Velocity display database to be added in a future firmware release. • Audio Mixer: Mono Balanced Input only outputs to 1 Channel on Amp Output. • In rare instances, if the unit is set to DHCP, the IP address will change after a reboot or factory reset.

Previous Releases

Version 1.0.0
• Factory firmware