Release Notes

Public Release

Version 1.5.1	
Features	• Updated HDBaseT to version 7.5.21 • Added support for the OCS-900 occupancy sensor. • Added option to toggle HDMI +5V on the HDMI Output. • Added support for 21:9 aspect ratio EDID formats.
Bug Fixes	• Resolved issue where HDCP sync was lost after a power cycle. • Fixed issue where TCP Proxy would stop functioning over time. • Fixed problem preventing configuration files from downloading and loading properly. • Resolved CEC compatibility issues with certain display models. • Increased character limits for Display Control fields.
Known Issues	• None

Previous Releases

Version 1.5.0	
Features	• Update to Valens Firmware 7.5.4.
Bug Fixes	• Improvements to UI Language. • Various WebUI updates. • Improved robustness of Web GUI with respect to specific security scanning software. • Fixed an issue where hex character “0xFF” was doubled when being sent. • Improved stability of IP/RS-232 Display Control Methods. • Improved stability and compatibility with OME-TX21-WP-E. • Fixed an issue where relay feedback would erroneously default after power loss. • Fixed an issue where EDID would erroneously default after power loss.

Version 1
• Factory firmware.