Release Notes

Public Release

Version 1.2.3	
Features	• Added variable substitution support • LG Web OS Driver • Osiris Driver • Two-way variable drivers from velocity
Bug Fixes	• None
Known Issues	• None

Previous Releases

Version 1.2.2	
Features	• New drivers: » Hall Versa 4k Driver Support » Hall Osiris Support
Bug Fixes	• None
Known Issues	• None

Release Notes

Version 1.2.1	
Features	• Added variable and command support for AT-OME-SW-21-TX, AT-PRO-5MX-810, and AT-USB-EX-350 drivers. • Introduced an optional interstitial passcode to secure the Settings page for enhanced unit security. • New drivers: Hall Technologies HT-OSIRIS-DSP1, Hall Technologies HT-Ranger2, and TeamConnect Ceiling Medium (TCC M).
Bug Fixes	• None
Known Issues	• None

Version 1.2.0	
Features	• Factory reset now sets Button 4 and Button 8 LEDs to green. • Increased the font size of numbers on the lock screen for improved readability. • Updated lock icon design. • Updated sleep icon design.
Bug Fixes	• Button text and icons now render independently for smoother feedback and status updates. • Page transitions now animate smoothly instead of flickering. • Network status correctly resets to DHCP when the unit is restored to factory settings.
Known Issues	• None

Version 1.1.1	
Features	• Added error monitoring tool. • Expanded logging support in API Mode. • Firmware version is now shown on the e-ink QR home page. • Macros are now limited to a maximum of 250 items.
Bug Fixes	• Button 1 LEDs function correctly in test mode. • Passcode functionality has been corrected. • E-ink display no longer shows a grey screen after reboot. • AT-VKP-8E now reliably controls AT-OME-CS31 over RS-232 without errors.
Known Issues	• None

Version 1.1.0	
Features	• Local Mode: » Updated background design. » Timeout status is now visible in the local web UI. » Timeout can be reset to 20 minutes directly from the local web UI. • Configuration files can now be downloaded in Local Mode. • Gateway Mode has been renamed to API Mode.
Bug Fixes	• None
Known Issues	• None

Version 1	
• Factory Firmware	