BERGMANN
ARCHITECTS ENGINEERS PLANNERS

PHASE I ENVIRONMENTAL SITE ASSESSMENT
APA Headquarters Feasibility Study – Phase I ESA
3 Main Street, Saranac Lake, New York



Bergmann

280 E. Broad Street Suite 200
Rochester, NY 14604

585.232.5135
www.bergmannpc.com

Project Number: 23010004G

Issued: August 16, 2023

TABLE OF CONTENTS

EXECUTIVE SUMMARY **4**

1.0 INTRODUCTION **7**

1.1 Property Overview 7
1.2 Purpose and Scope of Services 7
1.3 Significant Assumptions 8
1.4 Limitations, Deviations, and Special Terms and Conditions 8

2.0 USER PROVIDED INFORMATION **10**

2.1 Recorded Land Title Records 10
2.2 Reason for Performing this Phase I ESA 10

3.0 PHYSICAL SETTING **11**

4.0 RECORDS REVIEW **12**

4.1 Aerial Photographs, Sanborn Maps and Topographic Maps 12
4.2 Local Street Directories 13
4.3 United States Environmental Protection Agency 14
4.4 New York State Department of Environmental Conservation (NYSDEC) 14
4.5 New York State Department of Health (NYSDOH) 14
4.6 Franklin County Clerk's Office 14
4.7 Franklin County Department of Health 14
4.8 Village of Saranac Lake Clerk's Office 14
4.9 Saranac Lake Fire Department Fire 16
4.10 Utilites 16
4.10.1 Municipal Water/Water Wells 16
4.10.2 Sanitary Sewer/Septic System 16
4.10.3 Heat Source 16
4.11 Petroleum Bulk Storage (PBS) Systems 16
4.11.1 Underground Storage Tanks (USTs) 16
4.11.2 Aboveground Storage Tanks (ASTs) 17
4.12 Previous Environmental Reports 17
4.13 Environmental Liens, Activity and Use Limitations, and Government Institutional and Engineering Controls 17

5.0 INTERVIEW **18**

6.0 SUMMARY OF HISTORICAL USE **19**

7.0 SUBJECT PROPERTY RECONNAISSANCE **20**

7.1 Subject Property Observations 20
7.2 Current Operations 20

8.0 ADJOINING PROPERTIES **21**

9.0 REGULATORY RECORDS REVIEW **22**

9.1 Environmental Listings 23

10.0 BUSINESS ENVIRONMENTAL RISK CONSIDERATIONS **37**

10.1 Asbestos Containing Building Materials 37

10.2 Lead Based Paint 37
10.3 Indoor Air Quality 37
10.4 Lead in Drinking Water 37
10.5 Environmental Regulatory Compliance 37
10.6 Vapor Encroachment 37
10.7 Cultural, Historic, and Archeological Resources 37
10.8 Wetlands and Surface Waters 38
10.9 Threatened, Endangered, and Other Protected Species 38
10.10 Wildlife Sanctuaries and Other Natural Resource Preserves 38
10.11 Biological Agents 39
10.12 Mold 39
10.13 Potential PCB and Mercury Containing Materials 39
10.14 Potential CFC-Containing Equipment 39
10.15 Tritium Exit Signage 39

11.0 FINDINGS, OPINIONS AND CONCLUSIONS 40

11.1 Significant Data Gaps 40
11.2 Recognized Environmental Conditions (RECs) 40
11.3 Controlled Recognized Environmental Conditions (CREC) 40
11.4 Historical Recognized Environmental Conditions (HRECs) 40
11.5 Business Environmental Risk Considerations (BERS) 40
11.6 Recommendations 41
11.7 Statement of Compliance 42

12.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS 43

Figures

Figure 1: Site Location Map
Figure 2: Aerial Location Map

Photographs

Site Photographs taken during the Site Reconnaissance Visit.

Appendices

Appendix A: USGS Topographic Maps

Appendix B: Aerial Photographs

Appendix C: Phase I ESA Site Observation Notes and Field Site Map

Appendix D: Interview Questionnaire

Appendix E: Sanborn Fire Insurance Map Search

Appendix F: FOIL Request Letters and Response Package

Appendix G: EDR Database Search Report

Appendix H: Additional Documentation

Appendix I: Resumes of Authors

EXECUTIVE SUMMARY

Bergmann was retained by the New York State Office of General Services (OGS) at the request of the New York State Adirondack Park Agency (NYS APA) to conduct a Phase I Environmental Site Assessment (ESA) of an existing property located at 3 Main Street, Village of Saranac Lake, New York. This Phase I ESA was conducted in accordance with (1) the United States Environmental Protection Agency (USEPA) Standards and Practices for All Appropriate Inquiries {(AAI), 40 CFR Part 312} and (2) guidelines established by the American Society for Testing and Materials (ASTM) in the *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process / Designation E1527-21* (ASTM Standard Practice E1527-21).

The Phase I ESA for the Subject Property represents a product of Bergmann's professional expertise and judgment in the environmental consulting industry. This report is certified to, can be relied upon by, and has been prepared for the exclusive use of the following entities: Bergmann; NYS Adirondack Park Agency; New York State Office of General Services (NYSOGS); and its Successors and/or assigns and their respective successors, assigns, affiliates, and subsidiaries.

Reasonably ascertainable records reviewed as part of this Phase I ESA documented the use of the Subject Property back to 1898 – the earliest topographic map. The Subject Property consists of one (1) tax parcel and encompasses a total of 3.46 acres. Bergmann did not identify any Significant Data Gaps during the completion of this Phase I ESA.

Bergmann has performed this Phase I ESA in conformance with the scope and limitations of ASTM Practice E1527-21 and as outlined in an agreement with NYS APA.

Recognized Environmental Conditions (RECs)

A Recognized Environmental Condition (REC), as defined in the ASTM Standard, is an environmental condition where (1) the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment. A de minimis condition is not a recognized environmental condition. Bergmann identified the following RECs in connection with the Subject Property:

- Standard and other historical sources were able to document that the Subject Property was utilized historically by electric and railway companies from 1903 until 1986.
    - There is the potential that polychlorinated biphenyls (PCBs) were used on the Subject Property as a component of electrical equipment, including but not limited to transformers and switches.
    - Additionally, semi-volatile organic compounds (SVOCs) may have been used as a component in rail ties that may have been present at the site.
- A corroded pipe was noted in the basement of the historical building located on the Subject Property. The corroded pipe is likely from an oil leak via a suspect former tank and/or PCBs. Bergmann personnel recommends wipe test sampling be done to determine contaminant of concern.
- Three (3) Underground Storage Tanks (USTs) were listed in a compliance letter provided by the Village of Saranac Lake and EDR. One (1) tank was listed as closed/removed and listed as an HREC. The former location of this closed/removed UST is unknown. The following active tanks are listed below:
    - One (1) 2000-gallon gasoline UST (Tank #104249 Tank ID# 002) installed on 12/01/1967, no tank status or closure date reported, but is presumed to be still active, and associated with the on-site generator. The location of this UST is unknown, but is presumed to be within the vicinity of the generator on site.
    - One (1) 8000-gallon #2 fuel oil UST (Tank# 109435; Tank ID# 003) installed on 11/01/1994, no tank status or closure date reported. The location of this UST is unknown, and was not identified during the subsurface investigation performed by Bergmann.

Historical Recognized Environmental Conditions (HRECs)
A Historic Recognized Environmental Condition (HREC), as defined in the ASTM Standard, is an environmental condition that in the past would have been identified as REC but has been adequately addressed and therefore no longer represents a HREC. Bergmann identified one (1) HREC in association with the Subject Property.

- One (1) 8000-gallon #2 fuel oil UST used for on-site consumption (Tank #104248; ID# 001) closed/removed on 11/01/1994.

Controlled Recognized Environmental Conditions (CRECs)

A Controlled Recognized Environmental Condition (CREC), as defined in the ASTM Standard, is a REC resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority (for example, as evidenced by issuance of a no further action letter or equivalent, or meeting risk-based criteria established by regulatory authority), with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls (for example, property use restrictions, activity and use limitations, institutional controls, or engineering controls). Bergmann has not identified CRECs in association with the Subject Property.

Business Environmental Risk Considerations (BERs)
Although not required by the ASTM E1527-21 standard, based on standard industry practices, Bergmann has attempted to identify Business Environmental Risk (BER) considerations for the Subject Property. Bergmann has identified the following BERS in connection with the Subject Property:

- The IPaC resource list identified that the federally endangered Northern long-eared bat (*Myotis septentrionalis*) and candidate species Monarch Butterfly (*Danaus plexippus*) may occur within the Subject Property.
- Past UST and property uses may have impacted subsurface soils and groundwater, therefore, indoor air quality on the Subject Property in present and future buildings (if constructed) is considered a BER at this time. Testing indoor air was not part of the Scope of Services for this Phase I ESA. It is unknown if there are any existing indoor air quality issues at the historical buildings and/or structures located on the Subject Property.
- Propane tanks and a rusted and stained 55-gallon drum were noted adjoining the Property immediately to the northeast, off-site.
- Based on a desktop review, it is noted that Ampersand Bio, LLC, a 2017 occupant of the Subject Property, was determined to be involved in the development and manufacturing of immunoassay kits. These kits appear to be comprised of human, canine, hamster, and mouse DNA, and it is likely that small quantities of refrigerants, acids, organic solvents, organic substances and stains were utilized in their manufacture at the Subject Property. However, no evidence of spills, contamination, or improper storage of these chemicals has been identified.
- The National Register of Historic Places (NRHP) and Cultural Resource Information System (CRIS) were reviewed for properties within Ulster County, New York that may be impacted by the Project. Two (2) historic buildings and one (1) historic building were listed on the Subject Property: Paul Smiths Electric Light and Power and Railroad Company (USN number: 03347.000121; NR number: 90NR00509) – constructed in 1909. Lake Flower Dam (USN number: 03347.000246), constructed in 1938. Municipal Building and Pumping Station (USN number: 03347.000229), constructed in 1903.

  Four (4) historic buildings were located east of the Subject Property, off-site. One (1) listed Cottage (USN number: 03347.000054) located 17 Maple Hill Road, Saranac Lake, New York. One (1) listed cottage (USN number: 03347.000067) located at 13 Riverside Drive, Saranac Lake, New York. One (1) listed cottage (USN

number: 03347.000068) located at 25 Riverside Drive, Saranac Lake, New York. One (1) listed cottage (USN number: 03347.000069), name Magill Cottage, located at 74 Kiwassa Road, Saranac Lake, New York.

One historic building district is located north of the Subject Property off-site: Berkeley Square Historic District (USN number: 03347.000228). One (1) eligible building is located approximately 0.13 miles west of the Subject Property, off-site. The village of Saranac Lake, noted north of the Subject Property, had several listings of historic buildings. A map of the full listings is provided in Appendix H – Additional Documentation.

Table of Critical Dates

Final Report Issuance Date	06/6/2025
Date of Interview of Past and Present Owners and Occupants Identified in Section 5.0	07/19/2023
Date of Recorded Environmental Lien and AUL Search	07/22/2023
Date of Visual Inspection of Subject and Adjoining Properties	07/20/2023
Earliest Date of Interviews, Record Reviews, and Inspections	07/20/2023
180-day Update Required	01/15/2024
Report Viability Date	07/19/2024

*The Table of Critical Dates provides a summary of key milestones in the preparation of this Phase I ESA, in accordance with ASTM E1527-21. This table is intended to document the timing of essential components of the assessment, including the site reconnaissance, interviews, records review, and report issuance. These dates are critical for determining the validity period of the ESA, which is 180 days from the earliest of these components. Accurate tracking of these dates ensures compliance with regulatory and industry standards and supports the timely use of the ESA in property transactions, financing, or other due diligence activities.

1.0 INTRODUCTION

This Phase I ESA was conducted in accordance with (1) the United States Environmental Protection Agency (USEPA) Standards and Practices for All Appropriate Inquiries {(AAI), 40 CFR Part 312} and (2) guidelines established by the American Society for Testing and Materials (ASTM) in the *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process / Designation E1527-21* (ASTM Standard Practice E1527-21).

The Phase I ESA for the property located at 3 Main Street, Village of Saranac Lake, New York herein after referred to as the "Subject Property". This Phase I ESA represents the product of Bergmann's professional expertise and judgment in the environmental consulting industry. This report is certified to, can be relied upon by, and has been prepared for the exclusive use of the following entities: Bergmann; New York State Adirondack Park Agency (NYS APA), NYS OGS, and their respective successors, assigns, affiliates, and subsidiaries. Bergmann acknowledges that these parties may rely on the contents and conclusions presented in this report. Unless stated otherwise in writing, Bergmann makes no other warranty, representation, or extension of reliance upon the findings of this report to any other entity or third party.

1.1 PROPERTY OVERVIEW

The Subject Property (Tax ID# 458.21-2-1) is located at 3 Main Street, Saranac Lake, Franklin County, New York, 12983, on which Saranac Lake Police Department, Franklin County Nurses, and Franklin County Hydroelectric are situated.

Address	Tax Parcel ID	Subject Property Acreage
3 Main Street, Saranac Lake, New York	458.21-2-1	2.18 acres

Figure 1 – Site Location Map shows the Subject Property on Topographic Map. Figure 2 – Aerial Location Map shows the property boundary over satellite imagery. Topographic Maps from USGS are presented in Appendix A – USGS Topographic Maps. Topographic maps indicate the geographic features of the Subject Property and surrounding area. Aerial photographs of the Subject Property and surrounding properties are presented in Appendix B – Aerial Photographs. Any mention of the "Subject Property" in this Phase I ESA report will refer to the 2.18 acres of the Tax Parcel associated with 3 Main Street, Saranac Lake, New York.

1.2 PURPOSE AND SCOPE OF SERVICES

The Phase I Environmental Site Assessment (ESA) practice, established by the American Society for Testing and Materials (ASTM) Standard Practice E1527-21 and the United States Environmental Protection Agency (USEPA) All Appropriate Inquiries (AAI) Final Rule 40 CFR Part 312, is intended for use on a voluntary basis by parties who wish to assess the environmental condition of real estate taking into account commonly known and reasonably ascertainable information. The practice permits a User to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner, or bona fide prospective purchaser limitations (i.e., landowner liability protections or LLPs) on Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) liability.

The scope of services performed by Bergmann is consistent with the general specifications outlined in ASTM E1527-21 and 40 CFR Part 312. In general, the scope of services for this project included:

- Review environmental database search to identify sites in federal and state records that are potentially characterized by environmental liabilities within the recommended ASTM search radius as described in Section 4;
- Review available historical aerial photographs, USGS topographic maps, tax maps, plat maps, atlases, local street directories, and Sanborn® Fire Insurance Maps to obtain information relative to the historical usage of the Site;

- Conduct a Site visit, interview appropriate Site personnel and adjacent property owners, and record pertinent observations related to potential environmental impacts at the Site;
- Contact government authorities, including the New York State Department of Environmental Conservation (NYSDEC) to obtain any records on file associated with the property; local environmental and health departments, and local municipalities to obtain available Site-specific information, including legal descriptions, tax and title information, and locations of municipal services;
- Prepare a report that provides a Site description, summary of records reviewed, and observations noted of the environmental conditions at the Site, and an opinion as to the presence of potential Recognized Environmental Conditions (RECs);
- The performance of a Subject Property site visit and recording pertinent observations related to potential environmental impacts at the Subject Property; and
- Review of local street directories, City Directory Image Report, Sanborn® Fire Insurance Maps, Environmental Lien and AUL Search, and Tax Maps.

1.3 SIGNIFICANT ASSUMPTIONS

Pursuant to ASTM Standard Practice E1527-21, Bergmann assumes that the information provided by all sources and parties, including the User, is accurate and complete, except where obvious inconsistencies or inaccuracies were identified.

While this report provides an overview of potential current and historical RECs, the ESA is limited by the availability of information at the time of the assessment. It is possible that unreported disposal of waste or illegal activities impairing the environmental status of the property may have occurred which could not be identified. The conclusions and recommendations regarding the RECs that are presented in this report are based on a Scope of Work authorized by the Client.

Freedom of Information Law (FOIL) requests were submitted to the following agencies:

- New York State Department of Environmental Conservation (NYSDEC)
- New York State Department of Health (NYSDOH)
- Franklin County Department of Health
- Franklin County Clerk
- Village of Saranac Lake Clerk
- Saranac Lake Volunteer Fire Department

At the time of this report, the requested information has not been received from the following agencies:

- New York State Department of Environmental Conservation (NYSDEC)
- New York State Department of Health (NYSDOH)
- Franklin County Department of Health
- Saranac Lake Volunteer Fire Department

If any additional information from the above-listed agencies is received, it will be forwarded in a Letter of Addendum and this report will be amended, should the information reveal additional and pertinent findings.

1.4 LIMITATIONS, DEVIATIONS, AND SPECIAL TERMS AND CONDITIONS

Relationship of the Purchase Price to the Value of the Property

Bergmann was not provided with the purchase price of the Subject Property or with information relative to the value of the property, or if the property was not contaminated. This Phase I ESA assumes that the user/prospective property owner will consider the relationship of the purchase price relative to the fair market value of the property and consider

whether or not the difference in purchase price and fair market value is due to the presence of releases or threatened releases of hazardous substances.

Due to changing environmental regulatory conditions and potential on-site or adjacent activities occurring after this assessment, the client may not presume the continuing applicability to the subject property of the conclusions in this assessment for more than 180 days after the report's issuance date, per ASTM Standard Practice E1527-21.

Limitations

No sampling or testing of media such as soil, soil gas, surface water and groundwater, suspect asbestos containing material, radon, mold, or lead-based paint was conducted during this assessment. Pending FOIL requests are considered a non-significant limitation at this time.

2.0 USER PROVIDED INFORMATION

The ASTM Standard defines a User as "*the party seeking to use Practice* E1527 *to complete an Environmental Site Assessment of the Subject Property. A user may include, without limitation, a potential purchaser of Subject Property, a potential tenant of Subject Property, an owner of the Subject Property, a lender, or a property manager*." The User has specific obligations for completing a successful application of this practice as outlined in Section 6 of the ASTM Standard Practice E1527-21.

2.1 RECORDED LAND TITLE RECORDS

Bergmann was not provided a land title for review.

2.2 REASON FOR PERFORMING THIS PHASE I ESA

According to the User, this Phase I ESA was conducted as part of environmental due diligence related to the future requirements as part of the future lease of the Subject Property.

3.0 PHYSICAL SETTING

PHYSICAL SETTING INFORMATION FOR THE SUBJECT PROPERTY AND SURROUNDING AREA		SOURCE
Topography (Refer to Figure 1 for an excerpt of the Topographic Map)		
Elevation	Approximately 1528 feet above mean sea level	United States Geological Survey Division (U.S.G.S.) 7.5-Minute Topographic Map of Saranac Lake, NY Quadrangle, 2019
Geographic Gradient	General North	
Nearest Surface Water	Saranac River	
General Soil Characteristics:		
Soil Type	Adams loamy fine sand and Becket fine sandy loam	United States Department of Agriculture, EDR Environmental Data Resources Inc. (EDR) Report, Web Soil Survey (WSS)
Description	Class C – slow infiltration rates. Soils with layers impeding downward movement of water. Soils with moderately fine or fine textures.	
Geology	>60 inches	EDR Environmental Data Resources, Inc. (EDR) Report
Oil and Gas Wells		
Current Oil and Gas Wells on the Subject Property	None known	EDR Environmental Data Resources, Inc. (EDR) Report
Historical Oil and Gas Wells on the Subject Property	None known	

4.0 RECORDS REVIEW

Bergmann reviewed reasonably ascertainable records to identify obvious uses of the Subject Property from the present, back to the property's obvious first developed use, or back to 1940, whichever is earlier. Reasonably ascertainable records reviewed as part of this Phase I ESA documented the use of the Subject Property back to 1898 – the earliest topographic map of the Subject Property obtained by Bergmann.

4.1 AERIAL PHOTOGRAPHS, SANBORN MAPS AND TOPOGRAPHIC MAPS

Aerial Photographs

Bergmann reviewed reasonably ascertainable aerial photographs for the Subject Property. Aerial photographs from 2019, 2015, 2011, 2008, 1994, 1985, 1976, 1953 and 1942 were purchased from Environmental Data Resources, Inc. (EDR).

1942-1985: The aerial photographs from 1942 to 1985 are poor quality and make it difficult to discern if changes were made to the Subject Property and adjoining properties. The maps look relatively unchanged. The Village of Saranac Lake primarily consists of commercial and residential properties. Wooded area noted to the south and west/northwest of the Subject Property

1994-2019: Subject Property and Adjoining properties remain relatively unchanged compared to the previous aerial photographs from 1942 to 1985.

Copies of relevant Historic Aerial Photographs are provided in Appendix B.

Sanborn Maps:

Bergmann reviewed reasonably ascertainable Sanborn® Fire Insurance Maps for the Subject Property. Maps from 1894, 1899, 1903, 1908, 1916, 1924, 1931, 1945, and 1965 were obtained in this report. A copy of the EDR Sanborn Map is provided as Appendix E – Historic Sanborn Map Report. The following documents the Sanborn map review:

1894: T. Dewey Grist sawmill listed as hydropower with no heat, light, or fire apparatus was listed on the Subject Property. A grocery store, dwelling, and warehouse (internal components stored in warehouse unknown) were also listed in the southeast corner of the Subject Property. A lumber yard adjoined the Property to the east, across west main street, off site. Village of Saranac Lake north of the Subject Property, off site.

1899: Map relatively unchanged between 1894 and 1899. The grocery store was listed as abandoned on the 1899 map. An icehouse was listed on the Sanborn map in the southeast corner of the Subject Property, west of the sawmill. Village of Saranac Lake north of the Subject Property, off site. Two shingled roof, concrete structures are listed in the same area of the Subject Property. The Village of Saranac Lake is relatively unchanged.

1903: Saranac Lake Light, Heat, and Power Company appears to have been converted from the sawmill. The abandoned grocery store was listed as a dwelling, the warehouse was listed as storage, and the icehouse was listed as a shed. One new shingle roof, concrete structure listed in the Subject Property. The Village of Saranac Lake is relatively unchanged. Adjoining the Subject Property to the east is a lumber building, office, dwelling, and boat house.

1908: Subject Property relatively unchanged. The power company is now listed as Paul Smith's Light, Power, and Railway Company. Two dynamos and three water wheels are listed in Paul Smith's Light, Power, and Railway Company building. One new shingle roof, concrete structure listed in the Subject Property. The Village of Saranac Lake is relatively unchanged.

1916: Subject Property relatively unchanged. Shed behind dwelling removed from Property. The Village of Saranac Lake is relatively unchanged. A lumber company that was adjoining the Property to the east is now listed as storage.

1924: Subject Property relatively unchanged. One shingle roof concrete structure removed from Sanborn map. More dwellings and businesses listed in the village of Saranac Lake, outside the Subject Property. The office is no longer listed east of the Subject Property, off-site. Storage building adjoining the Property to the east is removed from the 1924 Sanborn map and listed as a dwelling.

1931: One shed, dwelling, and storage structure are no longer listed on the Subject Property. The second storage building listed as "to be removed" on Sanborn Map. More development occurs in the Village of Saranac Lake, off site. A dwelling is listed adjoining the Subject Property immediately to the west, off site. The only building adjoining the Property to the east of the Subject Property off site is a dwelling, the rest of the buildings removed from the property.

1945: Second storage building removed. A one stone wall well house is listed on the Subject Property, west of Paul Smith's Light, Power, and Railway Company. A shop and storage building listed west of the well house, on the Subject Property. The village of Saranac Lake is relatively unchanged although some development has occurred. All buildings were removed from the property east of the Subject Property, off-site.

1965: Subject Property and adjoining properties are relatively unchanged.

Topographic Maps:

The Subject Property is located on United States Geological Society (USGS) topographic maps for 1904, 1955, 1978, 1979, 1999, 2013, 2016, and 2019. Adjoining properties are also indicated on these maps. These maps indicate the geographic features of the Subject Property and surrounding area. Based on the information gathered from these maps, the railroad tracks to the west of the Property are illustrated in maps from 1902 until 1999. The former railroad track route is indicated as a roadway from the 2013 map until 2019, the most recent topographic map of the area. Indications of the current building structures on the Subject Property are not shown in the 2013, 2016, and 2019 map.

Copies of relevant Historic Topographic maps are provided in Appendix A.

4.2 LOCAL STREET DIRECTORIES

EDR provided local street directories of the Target Street for 1992, 1995, 2000, 2005, 2010, 2014, 2017, and 2020. The Subject Property was listed in the 2005, 2010, and 2017 City Directory records purchased from EDR. Surrounding properties listed include commercial and residential uses. Based on a desktop review, it is noted that the listed occupant from 2017, Ampersand Bio, LLC, was determined to be involved in the development and manufacturing of immunoassay kits. These kits appear to be comprised of human, canine, hamster, and mouse DNA, and it is likely that small quantities of refrigerants, acids, organic solvents, organic substances and stains were utilized in their manufacture at the Subject Property. Refer to Appendix H – Additional Documentation.

Year	Listed Property Owner(s)
2005	Saranac Lake Village, The Brown Dog Café & Wine Bar
2010	Franklin County Public Health, Franklin County Social Services, Municipal Garage, Saranac Lake Community Development, Sarace Lake Treasures Office, Saranac Lake Village Manager
2017	Ampersand Bio LLC Lori

4.3 UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Bergmann reviewed the United States Environmental Protection Agency (EPA) Envirofacts online database in lieu of a FOIL request. After a review of this database, no relevant environmental record was obtained for the Subject Property.

4.4 NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION (NYSDEC)

Bergmann submitted a request for environmental information with respect to the Subject Property to the NYSDEC via the Online FOIL request System on July 25, 2023. As of the issuance date of this ESA, FOIL documentation has not been received back from NYSDEC. If Bergmann receives relevant documents from the Office that reveal new and pertinent findings relative to the Property, a Letter of Addendum to this report will be submitted to the NYS APA detailing the new findings. Refer to Appendix F - FOIL Request Letters

4.5 NEW YORK STATE DEPARTMENT OF HEALTH (NYSDOH)

Bergmann submitted a request for environmental information with respect to the Subject Property to the NYSDOH via the Online FOIL request System on July 25, 2023. As of the issuance date of this ESA, FOIL documentation has not been received back from NYSDOH. If Bergmann receives relevant documents from the Office that reveal new and pertinent findings relative to the Property, a Letter of Addendum to this report will be submitted to the NYS APA detailing the new findings. Refer to Appendix F - FOIL Request Letters

4.6 FRANKLIN COUNTY CLERK'S OFFICE

Bergmann submitted a request for environmental information with respect to the Subject Property to the Franklin County Clerk's Office. On July 25, 2023, Bergmann received a response from Kip Cassavaw, Franklin County Clerk, stating that Franklin County Clerk's Office are public records and physical records are kept in the office. Mr. Cassavaw also stated that the requested documentation records would be with the NYSDEC, the Town of Harrietstown, or the Village of Saranac Lake. Refer to Appendix F - FOIL Request Letters

4.7 FRANKLIN COUNTY DEPARTMENT OF HEALTH

Bergmann submitted a request for environmental information with respect to the Subject Property to the Franklin County Department of Health Office. As of the issuance date of this ESA, FOIL documentation has not been received back from Franklin County Department of Health. If Bergmann receives relevant documents from the Office that reveal new and pertinent findings relative to the Property, a Letter of Addendum to this report will be submitted to the NYS APA detailing the new findings. Refer to Appendix F - FOIL Request Letters

4.8 VILLAGE OF SARANAC LAKE CLERK'S OFFICE

Bergmann submitted a request for environmental information with respect to the Subject Property to the village of Saranac Lake Clerk's Office. On July 25, 2023, Bergmann received a response from Amanda Hopf, the Village Clerk with a Petroleum Storage Compliance Letter for the Subject Property.

The compliance letter noted two (2) tanks, tank #003 and tank #004 located on the Subject Property. Tank #003 is listed as a 2,000-gallon #2 fuel oil underground storage tank included vaulted with no access for inspection installed on 11/01/1994. Tank #004 is listed as a 165-gallon diesel aboveground storage tank (no contact – i.e., legs, saddle, cradle, etc.) installed on 08/30/2013. The facility information report listed on page 2 of the provided documentation of two (2) additional tanks located within the Subject Property. Tank #001 is listed as an 8,000-gallon #2 fuel oil underground storage tank included vaulted with no access for inspection and was closed on 11/01/1994. Tank #002 is listed as a 2,000-gallon gasoline underground storage tank included vaulted with no access for inspection was installed on 12/01/1967 and no closure date was reported. Tanks #003 and #004 owners are listed as the Village of Saranac Lake. Ownership for tanks #001 and #002 was not listed.

Ms. Hopf forwarded the request to the Department of Public Works Superintendent and Code Enforcement Officer.

DPW Superintendent Dustin Martin provided the following documentation:

- One (1) Petroleum Bulk Storage Application from July 2022 with a hand drawn map of the PBS location on the Subject Property.
- One (1) State Pollutant Discharge Elimination System (SPDES) Discharge Permit #NY-0256536, DEC #5-1546-00351/00002 for the 3 Main Street Building Heat Pump. SPDES permit effective from 06/01/2021 through 05/31/2026. A Monitoring Location Map detailing the heat pump intake, outfall, and heat pump discharge locations provided in the attachment.
- One (1) corrosion protection testing document completed on 09/22/2021. The corrosion protection testing was awarded a pass.

The Code Enforcement Officer Chris McClatchie provided the following documentation:

- One (1) Parcel History Map for the Subject Property with information from June 19, 2009, to July 5, 2023. Pertinent listings include:

Date(s)	Transaction	Description
11/24/2010-10/18/2011	Common repair, alteration, addition	BP-2010-119 – Water plant insulation and electrical work permit
03/16/2012-08/08/2012	Common repair, alteration, addition	BP-2012-014 Temporary permit application for interior demolition, HVAC, windows and doors, and elevator rehab.
04/05/2012-09/28/2012	Common repair, alteration, addition	BP-2012-021 - Completed permit for alterations to existing building including interior non-loadbearing partitions, fire alarm system, electrical, and plumbing.
10/01/2014	Permit application and permit for blasting	2014-001 - drill and blast trench rock for reconstruction of sewer. Drill a 3" hole on a 4' by 4' staggering pattern. Prime blast holes with high explosives and brought to the proper load depth using blasting agents or emulsion depending on dryness/wetness of blast hole. Preform blasting using detonators, extra gelatin dynamite and blast agents. All blasting done by a qualified person. All work is done in accordance with safety plan, specifications, drawings, and agreed upon by VSL engineer AES northeast.
05/29/2015	Land use text amendment	2015-DA01 – Amendment to Flood Damage Prevention Law. Withdrawn.

Date(s)	Transaction	Description
11/20/15-12/31/15	Floodplain Deviation Permit	FDP-2015-002 – removal of existing stone retaining wall with precast blocking retaining wall in accordance with submitted plans and NYS building codes.

Refer to Appendix F - FOIL Request Letters for provided documentation.

4.9 SARANAC LAKE VOLUNTEER FIRE DEPARTMENT

Bergmann submitted a request for environmental information regarding the Subject Property to the Saranac Lake Volunteer Fire Department. As of the issuance date of this ESA, FOIL documentation has not been received back from Saranac Lake Volunteer Fire Department. If Bergmann receives relevant documents from the Office that reveal new and pertinent findings relative to the Property, a Letter of Addendum to this report will be submitted to the NYS APA detailing the new findings. Refer to Appendix F - FOIL Request Letters

A copy of the report is included in Appendix D – FOIL Requests and Responses.

4.10 UTILITIES

4.10.1 Municipal Water/Water Wells

An active police department, County Nurses, and Franklin County Hydro Electric are present on the Subject Property. The buildings are attached to municipal water.

4.10.2 Sanitary Sewer/Septic System

Bergmann personnel observed a sanitary sewer system on the Subject Property during the Site Reconnaissance.

4.10.3 Heat Source

The Subject Property currently operates as a police department, Franklin County Nurses, and Franklin County Hydro Electric. The heat source for the Subject Property is fuel oil provided by the 2,000-gallon UST.

4.11 PETROLEUM BULK STORAGE (PBS) SYSTEMS

4.11.1 Underground Storage Tanks (USTs)

Documentation provided by the landowner and the reasonably attainable resources indicate the presence of two (2) underground storage tanks on the Subject Property.

- Tank #003 is listed as a 2,000-gallon #2 fuel oil underground storage tank, included vaulted with no access for inspection installed on 11/01/1994.
- Tank #002 is listed as a 2,000-gallon gasoline underground storage tank, included vaulted with no access for inspection was installed on 12/01/1967 and no closure date was reported.

One (1) additional UST was indicated in the Petroleum Storage Compliance Letter. Tank #001 is listed as an 8000-gallon #2 fuel oil underground storage tank, included vaulted with no access for inspection and was closed on 11/01/1994. Prior to redevelopment, a Phase II ESA is recommended to determine if any contaminants are present on site.

4.11.2 Aboveground Storage Tanks (ASTs)

Bergmann received a response from Amanda Hopf, the Village Clerk with a Petroleum Storage Compliance Letter for the Subject Property. The Compliance Letter listed tank #004 is listed as a 165-gallon diesel aboveground storage tank (no contact – i.e., legs, saddle, cradle, etc.) installed on 08/30/2013.

Three (3) propane tanks were observed on the Subject Property during the Site Reconnaissance. Two propane tanks adjoined the Subject Property off-site. No staining, discoloration, or leaking was noted at the time of the Site Reconnaissance.

4.12 PREVIOUS ENVIRONMENTAL REPORTS

No previous environmental reports were provided to Bergmann during the completion of this Phase I ESA. A Wetland Delineation Report was prepared in July 2023 by Bergmann personnel and was submitted under a different cover.

4.13 ENVIRONMENTAL LIENS, ACTIVITY AND USE LIMITATIONS, AND GOVERNMENT INSTITUTIONAL AND ENGINEERING CONTROLS

Environmental Liens and/or Activity and Use Limitations were not identified for the subject property, according to a search and documents provided by EDR. A copy of the Environmental Lien and AUL Search Report is included in Appendix H – Additional Documentation.

5.0 INTERVIEW

Bergmann conducted a Phase I ESA interview with Dustin Martin, Superintendent of Public Works for the Village of Saranac Lake on July 19, 2023. Bergmann was informed of the following details regarding the Property:

- The building was built in 1927. Prior to the construction of the residential building, the land had two (2) single family residential buildings on the property.
- The Property Manager is unaware of any tanks, spills, or any events that may provide environmental hazards to the Subject Property.
- There are no Environmental Cleanup Liens against the Subject Property.
- There are no known chemicals, past or present, used at the Property as well as no known spills, chemical releases, and/or environmental cleanups.

A representative of The Adirondack Park Agency completed a User Questionnaire for the Property on July 19, 2023. The following details were provided by The Adirondack Park Agency:

- The Adirondack Park Agency noted that there are no Environmental Cleanup liens against the Property/Study Area.
- The Adirondack Park Agency noted that there are no Activity and Use Limitations (AULs) that are implemented at the Property/Study Area.
- The Adirondack Park Agency does not have specialized knowledge or experience related to the Property/Study Area.
- The Adirondack Park Agency does not know of chemicals, part or present, used at the Property/Study Area as well as no known spills, chemical releases and/or environmental cleanups.

A copy of the completed questionnaires are included in Appendix D – Interview Questionnaires

6.0 SUMMARY OF HISTORICAL USE

Standard and other historical sources were able to document that the Subject Property was utilized historically as an Electric Company from 1903 until 1986. The 1894 and 1899 Sanborn Maps indicated that the Subject Property operated as T. Dewy Grist Sawmill. No fire apparatus, power, water, heat, lights, or electricity were present at the Subject Property at this time. The 1894 Sanborn map indicated the Subject Property had a grocery store, that was then vacant in the following 1899 map. The building was built in 1903 and operated as Saranac Lake Electrical company until bought by Paul Smith in 1907. In 1927, Paul Smith's son, Phelp Smith constructed the present office building. The building operated as Paul Smith's Electric, Light, and Power and Railroad Company from 1927 until 1966. In 1966, the Subject Property continued to operate as an electric company, under Niagara Mohawk ownership until 1986, when the Village of Saranac Lake acquired the Property.

Currently, the Subject Property primary operations include Saranac Lake Police Department, Franklin County Nurses, Department of Social Services, and Village of Saranac Lake Hydroelectric. Adjoining properties include residential properties, commercial properties, and wooded land. Documentation provided by the Village of Saranac Lake Clerk included historical and present documentation of three (3) USTs and one (1) AST on the Subject Property. The 1894-1899 Sanborn maps listed a sawmill, grocery store, dwelling, and warehouse on the Subject Property. The 1903 Sanborn map listed Saranac Lake Light, Heat, and Power Company on the Subject Property; the sawmill was not identified/listed on this map. The 1908 Sanborn Map listed the Power company as Paul Smith's Light, Power, and Railway Company. Two (2) dynamos and three (3) water wheels are listed in Paul Smith's Light, Power, and Railway Company building. In the 1945 Sanborn Map, one (1) stone wall well house was listed on the Subject Property. A shop and storage building listed west of the well house, on the Subject Property. The Subject Property, Village of Saranac Lake, and Properties east of the Subject Property have historical buildings and structures listed on the National Register of Historic Places (NRHP) and Cultural Resource Information System (CRIS).

Based on a review of the EDR Street Directories and a desktop review, it is noted that the listed occupant from 2017, Ampersand Bio, LLC, was determined to be involved in the development and manufacturing of immunoassay kits. These kits appear to be comprised of human, canine, hamster, and mouse DNA, and it is likely that small quantities of refrigerants, acids, organic solvents, organic substances, and stains were utilized in their manufacture at the Subject Property.

7.0 SUBJECT PROPERTY RECONNAISSANCE

7.1 SUBJECT PROPERTY OBSERVATIONS

Category	Feature	Observed
Buildings	Elevators	**Yes**
	Air Compressors	No
	Incinerators	No
	Waste Treatment Systems	No
	Presses/Stamping Equipment	No
	Press Pits	No
	Hydraulic Lifts or In-ground hoists	No
	Paint Booth	No
	Plating Tanks	No
	Lathes, Screw Machines, etc.	No
Aboveground Chemical or Other Waste Storage or Waste Streams	Aboveground Storage Tanks (ASTs)	**Yes**
	Drums, Barrels and/or Containers > 5 gallons	**Yes**
	Chip Hoppers	No
	Hazardous or Petroleum Waste Streams	No
Underground Chemical or Waste Storage, Drainage or Collection Systems	Underground Storage Tanks	Yes
	Fuel Dispensers	No
	Sumps or Cisterns	No
	Dry Wells	No
	Oil/Water Separators	No
	Floor Drains, Trench Drains, etc.	**Yes**
	Pipeline Markers	**Yes**
Exterior Observations	Stressed Vegetation	No
	Stained Soil or Pavement	No
	Pad or Pole Mounted Transformers and/or Capacitors	**Yes**
	Soil Piles of Unknown Origin	No
	Exterior Dumpsters with Staining	No
	Leachate or Other Waste Seeps	No
	Trash, Debris, and/or Other Waste Materials	No
	Uncontrolled Dumping or Disposal Areas	No
	Surface Water Discoloration, Sheen or Free Product	No
	Strong, Pungent or Noxious Odors	No
	Storm water retention or detention ponds	No
	Pits, Ponds, Lagoons	No

7.2 CURRENT OPERATIONS

The Subject Property consists of Saranac Police Department, a parking lot, a dam, a small park, wooded land, and commercial office building. The buildings located on the Subject Property are listed as historic buildings on the Cultural Resources Information System (CRIS).

8.0 ADJOINING PROPERTIES

The following paragraphs provide information about the adjoining properties obtained through review of reasonably ascertainable information.

North of the Subject Property
Adjoining the Subject Property to the north are route 3 and the Village of Saranac Lake beyond.

West of the Subject Property
Adjoining the Subject Property to the west are Pelkey Lane, residential properties, wooded land, Petrova Elementary School beyond.

South of the Subject Property
Adjoining the Subject Property to the south are Lake Street and wooded land.

East of the Subject Property
Adjoining the Subject Property to the east are Main Street and Lake Flower.

9.0 REGULATORY RECORDS REVIEW

Regulatory database searches were conducted for the Subject Property as part of the scope of this Phase I ESA. The regulatory database search was conducted by EDR, a nationally recognized database search service, contracted by Bergmann.

Regulatory database searches were conducted for the subject property as part of the scope of this Phase I ESA. The regulatory databases searched include the following:

- Environmental Data Resources Inc. (EDR) report dated July 14, 2023.
- Review of the US EPA web-based Envirofacts Database, dated July 25, 2023.
- Review of the NYSDEC web-based environmental databases, dated July 25, 2023.

The database searches were conducted at or beyond the radii established by the Federal All Appropriate Inquiries (AAI) Rule and/or ASTM E1527-21 which ever was greater, for all parts of the subject property. The most recent EDR database reviewed for this Phase I ESA is included in Appendix E – EDR Database Search Report.

A summary of the major environmental databases searched is provided below. The dates of the environmental databases were the most recent releases as of June 21st, 2023, EDR environmental database review. Reviews were further supplemented with a search using the Federal USEPA Envirofacts web-based databases. July 14, 2023, web-based Petroleum Bulk Storage (PBS)/ Chemical Bulk Storage (CBS)/ Major Oil Storage Facility (MOSF) registries and the NYSDEC Spills Event web-based database and findings are summarized below:

Table 1

Source Reviewed	Agency[1]	ASTM Minimum Search Distance (AMSD)	Recent Date of Record Update[2]
Federal NPL List	US EPA	1.0 miles	05/17/2023
Federal Proposed NPL	US EPA	1.0 miles	05/17/2023
Federal De-listed NPL List	US EPA	1.0 miles	05/17/2023
Federal CERCLIS List	US EPA	0.5 miles	05/30/2023
Federal CERCLIS-NFRAP List	US EPA	0.5 miles	05/17/2023
Federal RCRA CORRACTS List	US EPA	1.0 miles	03/20/2023
Federal RCRA Generators List	US EPA	0.25 miles	03/20/2023
Federal ERNS List	US EPA	Target Property	05/30/2023
CERCLA Lien	US EPA	Target Property	05/17/2023
Federal Institutional/Engineering Controls	USEPA	0.5 miles	05/02/2023
State/Tribal Inactive Hazardous Waste Sites	NYSDEC	0.5 miles	04/24/2023
Solid Waste Facility/Landfill Sites	NYSDEC	0.5 miles	06/21/2023
State/Tribal Registered Storage Tank Lists	NYSDEC	0.25 miles	04/24/2023
State/Tribal Leaking Storage Tanks	NYSDEC	0.5 miles	07/14/2023
State Spills Inventory	NYSDEC	0.5 miles	02/09/2023
State/Tribal VCP Sites	NYSDEC	0.5 miles	04/24/2023
State/Tribal Brownfield Sites	NYSDEC	0.5 miles	04/24/2023

1. US EPA – United States Environmental Protection Agency
   a. NYSDEC – New York State Department of Environmental Conservation
2. Record updates are based on the database records reported in the Environmental Database Search conducted on July 14, 2023. The referenced dates are the most recent government releases as of the July 2023 database review.

9.1 ENVIRONMENTAL LISTINGS

Bergmann's review of the referenced databases also considered the potential or likelihood of contamination from adjoining and nearby sites. To evaluate which of the adjoining and nearby sites identified in the regulatory database report present an environmental risk to the subject property, Bergmann considered the following criteria:

- The type of database on which the site is identified.
- The topographic position of the identified site relative to the Subject Property.
- The direction and distance of the identified site from the Subject Property.
- Local soil conditions in the Subject Property area.
- The known or inferred groundwater flow direction in the Subject Property area.
- The status of the respective regulatory agency-required investigation(s) of the identified site, if any.
- Surface and subsurface obstructions and diversions (e.g., buildings, roads, sewer systems, utility service lines, rivers, lakes, and ditches) located between the identified site and the Subject Property.

Subject Property was identified in the database review that may present recognized environmental concerns (RECs). 93 properties were identified within the search radius of ¼ mile of the Subject Property, the closest 39 listings, present on the western side of the Saranac River and may potentially impact the Subject Property, are summarized in the table below. A full list of EDR results can be found in Appendix E – EDR Database Search Report

Table 2

Identified Environmental Listings

Location	Address	Database(s)	Description & Report Summary
Saranac River from Drain	Main Street, Saranac Lake, NY	NY SPILLS	**Location:** 0 ft/0/0 mi. E of the Subject Property **Spill Incident #:** 09945094 **Spill Cause/source:** Human error/commercial industrial **Spill Date:** 08/04/1999 **Spill Close Date**: 08/04/1999 **Description:** Caller reports sheen/odors entering river through 48 storm drain behind Little Italy. Investigated and determined that NTS pumping contaminated water into storm drain vs sanitary drain. RH corrected the situation. Cleanup does not meet standard, false. This is not considered a REC based on age and nature of the spill.
Town Hall	Main Street, Saranac Lake, NY	NY SPILLS	**Location:** 0 ft/0/0 mi. E of the Subject Property **Spill Incident #:** 8909365 **Spill Cause/source:** Unknown/unknown **Spill Date:** 12/27/1989 **Spill Close Date**: 12/27/1989 **Description:** Report of gas odors/petro in boiler room. No petro on the floor, appears to be water and coal dust. No action taken. Cleanup meets standard, true. This is not considered a REC based on age and nature of the spill.

Location	Address	Database(s)	Description & Report Summary
Parnell Shoe Salon	Main Street, Saranac Lake, NY	LTANKS SPILLS	**Location:** 0 ft/0/0 mi. E of the Subject Property **NY SPILLS** **Spill Incident #:** 0345061 **Spill Cause/source:** Unknown/unknown **Spill Date:** 08/20/2003 **Spill Close Date**: 12/22/2003 **Description:** DOT upgrading storm sewer lines and disturbing outfall behind Little Italy. Material being collected/contained as possible but minor sheen is escaping. Advised caller of situation, contractor preventing release as possible. Spill closed. Cleanup does not meet standard, false. This is not considered a REC based on age and nature of the spill. **LTANKS** **Spill Incident #:** 9300339 **Spill Cause/source:** Tank Failure/Commercial/Industrial **Spill Date:** 04/07/1993 **Spill Close Date**: 04/0/1993 **Description:** Store clerk noticed oil odor. Full tank not used. Bucket placed under tank. Contacted owner and advised to empty tank asap. No further DEC action unless tank fails in interim. Tank has been leaking for over five days. Minor spill, owner to clean up and pump out tank. 2-gallons of petroleum spilled. Cleanup does not meet standard, false. This is not considered a REC based on age and nature of the spill.
Lake Flower Bridge	Main Street, Saranac Lake, New York	SPILLS	**Location:** 0 ft/0/0 mi. E of the Subject Property **NY SPILLS** **Spill Incident #:** 0345061 **Spill Cause/source:** Unknown/unknown **Spill Date:** 01/16/1991 **Spill Close Date**: 05/29/1991 **Description:** 15-gallons of petroleum oil on surface water, along shoreline on Riverside Drive. Sorbents given to contractor, told to clean up/ Free product still in lake next day (1/17). Cleanup met standards true. This spill is not considered a REC.
Saranac Lake S.L.	Main Street (Quonset Hut Bld), Saranac Lake, New York	SPILLS	**Location:** 0 ft/0/0 mi. E of the Subject Property **NY SPILLS** **Spill Incident #:** 9402274 **Spill Cause/source:** Unknown/unknown **Spill Date:** 05/15/1994 **Spill Close Date**: 05/16/1994 **Description:** Fisherman observed an unknown amount of oil in river coming from storm sewer system. Minor sheen entering into storm culvert from parking area. No other problems found. Cleanup does not meet standard, false.

Location	Address	Database(s)	Description & Report Summary
Saranac Lake S.L. (continued)	Main Street (Quonset Hut Bld), Saranac Lake, New York	SPILLS	This spill is not considered a REC based on the nature, extent, and age of the spill.
Lalande Property	4 Dorsey Street, Saranac Lake, New York	FINDS	**Location:** 0 ft/ 0.0 mi. WSW of the Subject Property. **Registry ID:** 110019596800
Village of Saranac Lake	3 Main Street, Saranac Lake, New York	UST SPILLS	**Location:** Subject Property **UST** **ID/Status:** 5-416703/Active **Site type**: Municipality **Expiration date:** 10/02/2027 **Site ID:** 39482 **Tank Number/ID**: 104248; 001 **Tank Status**: Closed/removed. **Capacity**: 8000-gallon **Date opened:** unknown. **Date closed**: 11/01/1994. **Registered**: True **Location**: Underground **Material**: 0001 **Substance**: #2 fuel oil (on-site consumption) **Tank Number/ID**: 104249; 002 **Tank Status**: Not reported. **Capacity**: 2000-gallon **Date opened:** 12/01/1967. **Registered**: True **Location**: Underground **Material**: 0009 **Substance**: gasoline **Tank Number/ID**: 109435; 003 **Tank Status**: Not reported. **Capacity**: 8000-gallon **Date opened:** 11/01/1994. **Registered**: True **Location**: Underground **Material**: 0001 **Substance**: #2 fuel oil (on-site consumption) **Date Test:** 06/15/2015 **Tanks are considered a REC. Phase II ESA is recommended.** **Spills** **Spill Incident #:** 9802463 **Spill Cause/Source:** Traffic accident/passenger vehicle **Spill Date:** 05/26/1998 **Spill Close Date**: 05/26/1998 **Description:** Truck went into river spilling gas into water – unknown amount of oil into Surface Water. The cleanup did not meet standard, false.

Location	Address	Database(s)	Description & Report Summary
Village of Saranac Lake (continued)	3 Main Street, Saranac Lake, New York	UST SPILLS	Not considered a REC based on nature, extent, and age of spill. **Spill Incident #:** 9210815 **Spill Cause/Source:** Equipment failure; commercial/industrial **Spill Date:** 05/26/1998 **Spill Open/Close Date**: 12/17/1992 **Description:** 13-gallon spill, no discharge into river and no further action awarded. Cleanup did not meet standard. Not considered a REC based on nature, extent, and age of spill.
Saranac River	Route 3, Saranac Lake, New York	SPILLS	**Location:** Adjoining Subject Property to the north. **Spill Incident #:** 0145138 **Spill Cause/Source:** Deliberate; Institutional/educational/govt **Spill Date:** 02/15/2002 **Spill Close Date**: 02/19/2002 **Description:** Caller reported Village of Saranac Lake dumped snow into river. LM spoke with Lt. Bill Crain regarding concern. Lt. found out that VK was on site during the day. The village had a water main break. No dumping of snow occurred. Cleanup did not meet standard, false. Spill not considered a REC, based on nature, extent, and age of spill.
Pump Station @ Nimo Route 86	Route 86, Saranac Lake, New York	SPILLS	**Location:** 81 ft/ 0.015 mi. NNW **Spill Incident #:** 9111614 **Spill Cause/Source:** Deliberate; Institutional/educational/govt **Spill Date:** 02/10/1992 **Spill Close Date**: 02/11/1992. **Description:** Sewage overflowing pump station, running across road and into lake, response taken by DOW, no action by spill response. Cleanup meets standard, true. Spill not considered a REC, based on nature, extent, and age of spill.
Saranac River Rt. 3 Toward Boomingdale, Saranac Lake, NY	Rt. 3. Toward Boomingdale, Saranac Lake, New York	SPILLS	**Location:** 81 ft/ 0.015 mi. NNW **Spill Incident #:** 9801448 **Spill Cause/Source:** unknown **Spill Date:** 05/03/1998 **Spill Close Date**: 12/01/1998. **Description:** Unknown amount of unknown material. Sheen on the river, unknown where it is coming from. Cleanup complete. Cleanup did not meet standard, false. Spill is not considered a REC based on nature, extent, and age of spill.

Location	Address	Database(s)	Description & Report Summary
Storm Sewer Outfall Lapan HWY, Rt. 3., Saranac Lake, New York	Lapan Hwy, Rt. 3, Saranac Lake, New York	SPILLS	**Location:** 81 ft/ 0.015 mi. NNW **Spill Incident #:** 9310574 **Spill Cause/Source:** unknown **Spill Date:** 11/29/1993 **Spill Close Date**: 04/23/1999. **Description:** Strong petroleum odors coming from storm sewer at the new hydraulic jump storm sewer outfall. Unknown source. Unknown amount of petroleum. Cleanup did not meet standard. Spill is not considered a REC based on nature, extent, and age of spill.
Behind Pump Station	River Street, Saranac Lake, New York	SPILLS	**Location:** 81 ft/ 0.015 mi. NNW **Spill Incident #:** 9705049 **Spill Cause/Source:** unknown **Spill Date:** 07/27/1997 **Spill Close Date**: 09/18/1998 **Description:** Sheen in river, fire department on scene, DEC requested. Cleanup did not meet standard, false. Spill is not considered a REC based on nature, extent, and age of spill.
Lapan Highway Bridge	Lapan Highway, Saranac Lake, New York	SPILLS	**Location:** 81 ft/ 0.015 mi. NNW **Spill Incident #:** 9202680 **Spill Cause/Source:** unknown **Spill Date:** 06/03/1992 **Spill Close Date**: 06/03/1992 **Description:** Sheen reported. Identified as pine pollen and foam from upstream dam. No further action requested. Cleanup meets standard, true. Spill is not considered a REC based on nature, extent, and age of spill.
Saranac River	Route 3, Saranac River	SPILLS	**Location:** 81 ft/ 0.015 mi. NNW **Spill Incident #:** 9514240 **Spill Cause/Source:** Human error; passenger vehicle **Spill Date:** 02/05/1996 **Spill Close Date**: 02/07/1996 **Description:** Snowmobile went through ice ½ mile north of Saranac Lake F&G club in 7ft of water. Unknown amount of waste oil/used oil (petroleum) in surface water. Cleanup did not meet standard, false. Spill is not considered a REC based on nature, extent, and age of spill.

Location	Address	Database(s)	Description & Report Summary
Saranac Lake Off Dorsey	St Bridge Municipal Lot Saranac Lake, NY	SPILLS	**Location:** 141 ft/ 0.027 mi. NNW **Spill Incident #:** 0300692 **Spill Cause/Source:** Human Error **Spill Date:** 04/19/2003 **Spill Close Date**: 04/21/2003 **Description:** A fire extinguisher was observed in the river. The fire extinguisher was found to not to be leaking. The spill was closed. This listing is not considered a REC due to the nature of the spill.
In Lake Flower Off	14 Kiwassa Road Saranac Lake, NY	SPILLS	**Location:** 188 ft/ 0.036 mi. ESE **Spill Incident #:** 1009429 **Spill Cause/Source:** Traffic Accident **Spill Date:** 12/03/2010 **Spill Close Date**: 12/03/2010 **Description:** A car drove off of the road and into the lake. The vehicle was removed from the water, and it appeared that no fluids were released. The spill was closed. This listing is not considered a REC due to the nature of the spill.
Chapin Residence	22 Kiwassa Road Saranac Lake, NY	LTANKS	**Location:** 421 ft/ 0.080 mi. ESE **Spill Incident #:** 0308360 **Spill Cause/Source:** Tank Failure **Spill Date:** 11/07/2022 **Spill Close Date**: 07/15/2003 **Description:** A tank was pulled, and contamination was found. 10 tons of #2 fuel oil contaminated soil was excavated and disposed of. No further action was determined necessary. This listing is considered an HREC, due to the nature of the listing and its distance from the Subject Property.
Saranac River	Dorsey Street Saranac Lake, NY	LTANKS	**Location:** 494 ft/ 0.094 mi. NNW **Spill Incident #:** 8605567 **Spill Cause/Source:** Tank Failure **Spill Date:** 12/02/1986 **Spill Close Date**: 08/01/1988 **Description:** A sheen was observed in the river, with oil and rust observed coming out of a stormline next to the bank office building. A leaking #2 fuel oil UST was determined to be the source of the spill. The tank was replaced with a new one. The spill was cleaned up and closed, with no further action necessary. This listing is not considered an REC, due to the nature of the listing and that the location of the UST is on the opposite side of the river from the Subject Property.

Location	Address	Database(s)	Description & Report Summary
87 Lake Street	87 Lake Street	SPILLS	**Location:** 546 ft/ 0.103 mi. WSW **Spill Incident #:** 1400270 **Spill Cause/Source:** Housekeeping **Spill Date:** 04/08/2014 **Spill Close Date**: 05/20/2015 **Description:** A report of stained soils present as a result of waste/used oil spilled from auto repair business operating on premises. Cleanup was not done to standard. Spill was closed. This listing is considered an HREC, due to the nature of the listing and its distance from the Subject Property.
Daring Residence	5 Sumner Place Saranac Lake, NY	LTANKS	**Location:** 1043 ft/ 0.198 mi. N **Spill Incident #:** 9845097 **Spill Cause/Source:** Tank Failure **Spill Date:** 03/12/1999 **Spill Close Date**: 04/19/1999 **Description:** Two (2) 275-gallon #2 fuel oil AST's were found in the basement. One (1) was found to be leaking. The tanks were pumped out and replaced, with cleanup completed by the fuel supplier. The spill was not cleaned up to standard. This listing is not considered a REC, due to the sites distance, age, and down gradient location from the Subject Property.
Saranac Lake CSD – Petrova Middle School	141 Petrova Ave Saranac Lake, NY	AST UST AIRS RCRA	**Location:** 1054 ft/ 0.200 mi. W **AIRS** **DECID:** 5164600348 **Issue Date:** 10/15/2015 **Expired Date**: 10/14/2025 **Permit Status:** Issued **Issue Date:** 08/24/2011 **Expired Date:** 10/14/2025 **Permit Status:** Expired **NY MANIFEST** **Trans1 State ID:** NYD986980753 **Trans2 State ID:** NJ0000027193 **Generator Ship Date**: 12/03/2009 **Trans2 Recv Date:** 12/11/2009 **TSD Site Recv Date:** 12/14/2009 **Generator EPA ID:** NYD987014651 **Description:** Four (4) drums of 275 kilograms of 2-propen-1-ol (or) Allyl Alcohol **AST** **ID/Status:** 5-230006/Active **Site type**: School **Expiration date:** 07/10/2027 **Site ID:** 39048

Location	Address	Database(s)	Description & Report Summary
Saranac Lake CSD – Petrova Middle School (continued)	141 Petrova Ave Saranac Lake, NY	AST UST AIRS RCRA	**Tank Number/ID**: 110134; 005 **Tank Status**: In service **Capacity**: 500-gallon **Install Date:** 08/01/1996 **Registered**: True **Location**: Aboveground **Material**: Gasoline/Ethanol **Tank Number/ID**: 235131; 007 **Tank Status**: Closed - Removed **Capacity**: 10-gallon **Install Date:** 06/01/1996 **Closure Date:** 09/12/2022 **Registered**: True **Location**: Aboveground **Material**: #2 Fuel Oil **UST** **ID/Status:** 5-230006/Active **Site type**: School **Expiration date:** 07/10/2027 **Site ID:** 39048 **Tank Number/ID**: 102685; 001 **Tank Status**: Closed - Removed **Capacity**: 3,000-gallon **Install Date:** Not reported **Closure Date:** 08/01/1992 **Registered**: True **Location**: Underground **Material**: Gasoline **Tank Number/ID**: 102686; 002 **Tank Status**: Closed - Removed **Capacity**: 2,000-gallon **Install Date:** 12/01/1979 **Closure Date:** 08/01/1996 **Registered**: True **Location**: Underground **Material**: Gasoline **Tank Number/ID**: 102684; 003 **Tank Status**: Closed - Removed **Capacity**: 15,000-gallon **Install Date:** 12/01/1969 **Closure Date:** 08/01/1996 **Registered**: True **Location**: Underground **Material**: #2 Fuel Oil **Tank Number/ID**: 102687; 004 **Tank Status**: Closed - Removed **Capacity**: 2,000-gallon **Install Date:** 12/01/1969 **Closure Date:** 08/01/1996 **Registered**: True

Location	Address	Database(s)	Description & Report Summary
Saranac Lake CSD – Petrova Middle School (continued)	141 Petrova Ave Saranac Lake, NY	AST UST AIRS RCRA	**Location**: Underground **Material**: #2 Fuel Oil **Tank Number/ID**: 110135; 006 **Tank Status**: In Service **Capacity**: 12,000-gallon **Install Date:** 08/01/1996 **Registered**: True **Location**: Underground **Material**: #2 Fuel Oil **RCRA** **EPA ID:** NYD987014651 **Description:** Conditionally Exempt Small Quantity Generator of ignitable waste and benzene. Conditionally Exempt Small Quantity Generator for the years 1992 and 2009. Historic non generator for the years 2006, 2007. No violations or evaluations found. This listing is not considered a REC, due to the listings nature and distance from the Subject Property.
Key Bank of New York	55 Broadway Street Saranac Lake, NY	UST	**Location:** 1164 ft/ 0.220 mi. N **UST** **ID/Status:** 5-600238 / Unregulated/Closed **Site type**: Other **Site ID:** 40468 **Tank Number/ID**: 109063; 001 **Tank Status**: Closed - Removed **Capacity**: 8,000-gallon **Install Date:** Not reported **Closure Date:** 09/01/1994 **Registered**: True **Location**: Underground **Material**: #2 fuel oil This listing is not considered a REC, due to the listings nature, down gradient location, and distance from the Subject Property.
Adirondack Daily Enterprise	61 Broadway	RCRA	**Location:** 1294 ft/ 0.245 mi. N **EPA ID:** NYN008014193 **Description:** Verified non-generator. Conditionally Exempt Small Quantity Generator for the year 2005. Verified non-generator for the years 2006 and 2007. One compliance evaluation inspection in 2004. This listing is not considered a REC, due to the nature of the listing and its distance from the Subject Property.

Location	Address	Database(s)	Description & Report Summary
North Star Industries	71 Petrova Avenue Saranac Lake, NY	LTANKS	**Location:** 1321 ft/ 0.250 mi. W **Spill Incident #:** 9608722 **Spill Cause/Source:** Tank Failure **Spill Date:** 10/14/1996 **Spill Close Date**: 10/16/1996 **Description:** A #2 fuel oil tank had a bad gauge line, and failed a tank test. The tank was excavated and retested. The spill was closed. This listing is not considered a REC, due to the spills nature, age, and distance from the Subject Property.
Broadway Properties	60-62 Broadway Saranac Lake, NY	LTANKS	**Location:** 1327 ft/ 0.251 mi. N **Spill Incident #:** 9007621 **Spill Cause/Source:** Tank Test Failure **Spill Date:** 10/12/1990 **Spill Close Date**: 12/04/1990 **Description:** An 8000-gallon #2 fuel oil tank had a tank test fail. The tank was removed, and an encountered 1000-gallon tank was abandoned. Excavation was found to be free of product with negligible contaminated soil. Spill was cleaned up to standard and closed. This listing is not considered a REC, due to the spills nature, age, and distance from the Subject Property.
29 Williams Street	29 Williams Street Saranac Lake, NY	LTANKS	**Location:** 1327 ft/ 0.251 mi. NNW **Spill Incident #:** 0012844 **Spill Cause/Source:** Tank Overfill **Spill Date:** 03/05/2001 **Spill Close Date**: 03/05/2001 **Description:** A #2 fuel oil tank was overfilled, and approximately 1 gallon was spilled. The spill was cleaned up, but not to standard, and closed. This listing is not considered a REC, due to the spills nature, age, and distance from the Subject Property.
North Star Industries	71 Petrova Avenue Saranac Lake, NY	LTANKS	**Location:** 1349 ft/ 0.255 mi. W **Spill Incident #:** 8911602 **Spill Cause/Source:** Tank Overfill **Spill Date:** 03/07/1990 **Spill Close Date**: 03/07/1990 **Description:** A #2 fuel oil overfilled approximately 15 gallons when the tank contents were misgauged during a delivery. The tank overfilled onto blacktop at the rear of the building. The spill was cleaned up to standard and closed. **Spill Incident #:** 9712367 **Spill Cause/Source:** Tank Overfill **Spill Date:** 02/04/1998

Location	Address	Database(s)	Description & Report Summary
North Star Industries (continued)	71 Petrova Avenue Saranac Lake, NY	LTANKS	**Spill Close Date**: 02/05/1998 **Description:** A #2 fuel oil overfilled approximately 1 gallon. The fuel oil sprayed over snow, which was shoveled up and removed. The spill was cleaned up, but not to standard, and the spill was closed. This listing is not considered a REC, due to the quantity, age, and distance of the spills from the Subject Property.
Casier's – Old Tank	Bloomingdale St Saranac Lake, NY	LTANKS	**Location:** 1633 ft/ 0.309 mi. N **Spill Incident #:** 9901135 **Spill Cause/Source:** Tank Failure **Spill Date:** 04/29/1999 **Spill Close Date**: 05/17/1999 **Description:** A leaking 1,000 gallon UST was discovered during excavation. A minor amount of contaminated soil was excavated and disposed of, with no further action deemed necessary. The spill was cleaned up, but not to standard, and closed. This listing is not considered a REC, due to the spills nature, quantity, age, downgradient location, and distance from the Subject Property.
Stewarts	Bloomingdale Road & Depot Saranac Lake, NY	LTANKS	**Location:** 1675 ft/ 0.317 mi. N **Spill Incident #:** 9312279 **Spill Cause/Source:** Tank Overfill **Spill Date:** 01/19/1994 **Spill Close Date**: 01/19/1994 **Description:** Approximately 8 gallons of gasoline was spilled onto pavement. The spill was cleaned up by the fire department, but not to standard. The spill was closed. This listing is not considered a REC, due to the spills nature, quantity, age, downgradient location, and distance from the Subject Property.
Stewarts Shop #35, 242	Bloomingdale Road Ave Saranac Lake, NY	LTANKS	**Location:** 1685 ft/ 0.319 mi. N **Spill Incident #:** 9112342 **Spill Cause/Source:** Tank Overfill **Spill Date:** 03/04/1992 **Spill Close Date**: 09/11/2002 **Description:** A 4,000-gallon unleaded gasoline tank failed, causing a gross leak. The tank was pumped out. A groundwater treatment and soil vapor extraction system was installed and operated at the site, with exhaust fans installed in nearby structures (Adirondack Daily Enterprise, JC Penney, and storm sewer). Monitoring wells were installed. Contamination was determined to be decreasing, with the site closed out with satisfactory cleanup being completed.

Location	Address	Database(s)	Description & Report Summary
Stewarts Shop #35, 242 (continued)	Bloomingdale Road Ave Saranac Lake, NY	LTANKS	This listing is not considered a REC, due to the spills age, downgradient location, satisfactory closure, and distance from the Subject Property.
Petrova Ave School	Petrova Ave Saranac Lake, NY	LTANKS	**Location:** 1706 ft/ 0.323 mi. W **Spill Incident #:** 9107092 **Spill Cause/Source:** Tank Failure **Spill Date:** 10/02/1991 **Spill Close Date**: 10/02/1991 **Description:** Approximately 5 gallons of #2 fuel oil were spilled to grass near a vent pipe during a delivery. The spill was cleaned up to standard and closed. This listing is not considered a REC, due to the spills size, age, and distance from the Subject Property.
Mrs. Kelting	174 Lake Street Saranac Lake, NY	LTANKS	**Location:** 1714 ft/ 0.325 mi. WSW **Spill Incident #:** 9509800 **Spill Cause/Source:** Tank Overfill **Spill Date:** 11/07/1995 **Spill Close Date**: 11/07/1995 **Description:** A #2 fuel oil tank spilled approximately 10 gallons of oil onto a cement floor. The spill was cleaned up, but not to standard. The spill was closed. This listing is not considered a REC, due to the spills quantity, age, and distance from the Subject Property.
In Front of Rusty Nail	Broadway Saranac Lake, NY	LTANKS	**Location:** 1840 ft/ 0.348 mi. NNW **Spill Incident #:** 9945033 **Spill Cause/Source:** Tank Failure **Spill Date:** 05/13/1999 **Spill Close Date**: 05/14/1999 **Description:** Two (2) #2 fuel oil tanks – 1000 gallons and 500 gallons in capacity, with contaminated soil was discovered while DOT was excavating in front of Rusty Nail. Tanks and contaminated soil were removed, but not to standard. The spill was closed. This listing is not considered a REC, due to the spills nature, age, down-gradient location, and distance from the Subject Property.
Rusty Nail	Broadway Saranac Lake, NY	LTANKS	**Location:** 1845 ft/ 0.349 mi. NNW **Spill Incident #:** 8910180 **Spill Cause/Source:** Tank Failure **Spill Date:** 01/22/1990 **Spill Close Date**: 01/24/1990 **Description:** A 275 gallon #2 fuel oil AST ruptured, spilling fuel to a basement floor, exiting out of a floor drain into the Saranac River. Dye testing was

Location	Address	Database(s)	Description & Report Summary
Rusty Nail (continued)	Broadway Saranac Lake, NY	LTANKS	completed, and material was cleaned up. Spill was cleaned up to standard and was closed. This listing is not considered a REC, due to the spills nature, age, down-gradient location, and distance from the Subject Property.
Durfee Residence	2 Fairview Avenue Saranac Lake, NY	LTANKS	**Location:** 2007 ft/ 0.380 mi. NW **Spill Incident #:** 9205763 **Spill Cause/Source:** Tank Overfill **Spill Date:** 08/18/1992 **Spill Close Date**: 08/19/1992 **Description:** A #2 fuel oil tank spilled due to a leak occurring in the bottom of a tank due to corrosion, which leaked into a basement area. A residence noticed odors and contacted Agway, who responded, pumped out tank, wiped product off cement. DEC did not require response. This listing is not considered a REC, due to the spills quantity, age, and distance from the Subject Property.
Shelly Vancour Residence	340 Glenwood Drive Saranac Lake, NY	LTANKS	**Location:** 2153 ft/ 0.408 mi. S **Spill Incident #:** 0485104 **Spill Cause/Source:** Tank Overfill **Spill Date:** 11/01/2004 **Spill Close Date**: 11/05/2004 **Description:** A #2 fuel oil tank was overfilled, and 1 gallon of fuel spilled into the basement. The spill was cleaned up and closed. This listing is not considered a REC, due to the spills quantity, age, and distance from the Subject Property.
Meth Lab Cleanup	155 Broadway Apt 3, Saranac Lake, New York	SPILLS	**Location:** 2163 ft/ 0.41 mi. N of Subject Property **Spill Incident #:** 1305742 **Spill Cause/Source:** Deliberate; Commercial/Industrial **Spill Date:** 08/29/2013 **Spill Close Date**: 12/13/2013 **Material FA/name:** unknown hazardous material **Description:** Meth lab cleanup, NFA required. The cleanup did not meet standard, false. This spill is not considered a REC based on the down gradient location and distance of the spill from the Subject Property.

After a review of the NYS Spill Incidents Database Search, Bergmann identified thirty-six (36) closed spills, within the closest 39 listings of the EDR environmental listings list, within a radius of ½ mile of the Subject Property, on the western side of the Saranac River.

The EDR Radius Report Environmental listings listed 93 listings within ¼ mile of the Subject Property. These Spill environmental listings do not represent RECs based on the nature and location to the Subject Property.

Three (3) closed USTs were listed within ¼ mile of the Subject Property, and three (3) USTs were listed as on the Subject Property. One (1) of the three (3) USTs listed on the Subject Property (Tank Number/ID: 104248; 001) was listed as closed/removed on 11/01/1994 is identified as an HREC.

The two (2) remaining UST tanks (Tank numbers: 104249; 109435| Tank ID: 003; 0004) were listed as installed as of 11/01/1994 and 12/01/1967, respectively. No closure dates or tank statuses were provided in the EDR report and/or PBS database listings. These two (2) tanks are identified as RECs.

A full list of EDR results can be found in Appendix E – EDR Database Search Report.

10.0 BUSINESS ENVIRONMENTAL RISK CONSIDERATIONS

Although not required by the ASTM E1527-21 standard, based on standard industry practices, Bergmann has attempted to identify Business Environmental Risk (BER) considerations for the Subject Property. Bergmann has identified BERs in connection with the Subject Property.

10.1 ASBESTOS CONTAINING BUILDING MATERIALS

An asbestos containing materials (ACM) survey was not conducted as part of this Phase I ESA. Bergmann recommends an ACM survey to be conducted prior to any renovation or construction in accordance with applicable federal, state, and local regulations.

10.2 LEAD BASED PAINT

A Lead-Based paint (LBP) survey was not conducted as part of this Phase I ESA. Bergmann recommends an LBP survey to be conducted prior to any renovation or construction in accordance with applicable federal, state, and local regulations.

10.3 INDOOR AIR QUALITY

New buildings are contemplated with the construction of the Project, therefore, indoor air quality on the Subject Property in future buildings is considered a BER at this time. Testing indoor air was not part of the Scope of Services for this Phase I ESA. It is unknown if there are any existing indoor air quality issues at the historical building located on the Subject Property.

10.4 LEAD IN DRINKING WATER

Testing for lead contamination in drinking water was not part of this Phase I ESA. It is unknown if there are any existing lead impacts to drinking water at the historical building located on the Subject Property. The property is serviced by a municipal potable water source.

10.5 ENVIRONMENTAL REGULATORY COMPLIANCE

Bergmann did not identify any documentation or observe any items related to violations of environmental regulations at the Subject Property.

10.6 VAPOR ENCROACHMENT

A vapor encroachment survey was not conducted as part of this Phase I ESA.

10.7 CULTURAL, HISTORIC, AND ARCHEOLOGICAL RESOURCES

The National Register of Historic Places (NRHP) and Cultural Resource Information System (CRIS) were reviewed for properties within Franklin County, New York that may be impacted by the Project.

Three (3) historic building were listed on the Subject Property:

- Paul Smiths Electric Light and Power and Railroad Company (USN number: 03347.000121; NR number: 90NR00509) – constructed in 1909.
- Lake Flower Dam (USN number: 03347.000246), constructed in 1938.
- Municipal Building and Pumping Station (USN number: 03347.000229), constructed in 1903.

Four (4) historic buildings were located east of the Subject Property, off-site.

- One (1) listed Cottage (USN number: 03347.000054) located 17 Maple Hill Road, Saranac Lake, New York
- One (1) listed cottage (USN number: 03347.000067) located at 13 Riverside Drive, Saranac Lake, New York.
- One (1) listed cottage (USN number: 03347.000068) located at 25 Riverside Drive, Saranac Lake, New York.

- One (1) listed cottage (USN number: 03347.000069), name Magill Cottage, located at 74 Kiwassa Road, Saranac Lake, New York.

One historic building district is located north of the Subject Property off-site:

- Berkeley Square Historic District (USN number: 03347.000228)

One (1) eligible building is located approximately 0.13 miles west of the Subject Property, off-site. The village of Saranac Lake, noted north of the Subject Property, had several listings of historic buildings. A map of the full listings is provided in Appendix H – Additional Documentation.

10.8 WETLANDS AND SURFACE WATERS

The NYSDEC Environmental Resource Mapper online application was reviewed to determine the presence of wetlands on or around the Subject Property. Based on the information obtained through the application, one riverine wetland, which corresponds to the Saranac River, was located on the Subject Property.

Review of the available Adirondack Park Agency (APA) Wetland mapping indicated there are no APA Wetlands mapped within the Study Area.

The FEMA Flood Hazard Layer Map for Franklin County, New York was reviewed. The Flood Insurance Rate Map (FIRM) (Panel #3602730001C) indicated that the entire Study Area is located within Zone X – "Area of Minimal Flood Hazard" and zone AE – "Base flood elevations determined". A desktop review of the available USFWS NWI digital data indicated that the Study Area is located within the Saranac River Watershed (HUC 04150406). There is one (1) riverine (R2UBH) NWI mapped feature within the Study Area (refer to Appendix H – Additional Documentation).

10.9 THREATENED, ENDANGERED, AND OTHER PROTECTED SPECIES

A review of the US Fish and Wildlife Service Information for Planning and Consultation (IPaC) application was conducted to determine the presences or absence of threatened, endangered, and other protected species, and critical habitat on the subject property.

Based on the review, federally threatened and endangered species are expected to occur within the Property. The resource list indicates that the endangered Indiana Bat (*Myotis sodalist*), the federally threatened Northern Long-eared Bat (*Myotis septentrionalis*), and the Monarch Butterfly (*Danaus plexippus*) may occur within the Subject Property. No critical habitats were located on or near the subject property (refer to Appendix H – Additional Documentation).

Consultation with the New York Natural Heritage Program (NYNHP) is not required for the Project.

The Property was reviewed in the New York State Department of Environmental Conservation (NYSDEC) Environmental Resource Mapper (ERM). According to the ERM, the Property is not located within a NYSDEC Rare Plants and Rare Animals layer. Consultation with the New York Natural Heritage Program (NYNHP) is not required for the Project.

10.10 WILDLIFE SANCTUARIES AND OTHER NATURAL RESOURCE PRESERVES

No wildlife sanctuaries or other natural resource preserves are present on or near the subject property.

10.11 BIOLOGICAL AGENTS

Biological agents were not observed during the Site reconnaissance.

10.12 MOLD

Mold was not observed during Site Reconnaissance.

10.13 POTENTIAL PCB AND MERCURY CONTAINING MATERIALS

Bergmann observed three (3) pole mounted transformers on the Subject Property during the site reconnaissance. No evidence for the existence of Mercury Containing Materials on the Subject Property was observed during the site reconnaissance.

10.14 POTENTIAL CFC-CONTAINING EQUIPMENT

Bergmann did not observe a potential for CFC-containing equipment on the Subject Property during the site reconnaissance.

10.15 TRITIUM EXIT SIGNAGE

Tritium Exit Signs were observed during the site reconnaissance visit to the Subject Property.

11.0 FINDINGS, OPINIONS AND CONCLUSIONS

11.1 SIGNIFICANT DATA GAPS

Bergmann has not identified significant data gaps associated with the completion of this Phase I ESA.

11.2 RECOGNIZED ENVIRONMENTAL CONDITIONS (RECS)

Bergmann identified the following RECs in connection with the Subject Property:

- Standard and other historical sources were able to document that the Subject Property was utilized historically by electric and railway companies from 1903 until 1986.
    - There is the potential that polychlorinated biphenyls (PCBs) were used on the Subject Property as a component of electrical equipment, including but not limited to transformers and switches.
    - Additionally, semi-volatile organic compounds (SVOCs) may have been used as a component in rail ties that may have been present at the site.
- A corroded pipe was noted in the basement of the historical building located on the Subject Property. The corroded pipe is likely from an oil leak via a suspect former tank and/or PCBs. Bergmann personnel recommends wipe test sampling be done to determine contaminant of concern.
- Three (3) Underground Storage Tanks (USTs) were listed in a compliance letter provided by the Village of Saranac Lake and EDR. One (1) tank was listed as closed/removed and listed as an HREC. The former location of this closed/removed UST is unknown. The following active tanks are listed below:
    - One (1) 2000-gallon gasoline UST (Tank #104249 Tank ID# 002) installed on 12/01/1967, no tank status or closure date reported, but is presumed to be still active, and associated with the on-site generator. The location of this UST is unknown, but is presumed to be within the vicinity of the generator on site.
    - One (1) 8000-gallon #2 fuel oil UST (Tank# 109435; Tank ID# 003) installed on 11/01/1994, no tank status or closure date reported. The location of this UST is unknown, and was not identified during the subsurface investigation performed by Bergmann.

11.3 CONTROLLED RECOGNIZED ENVIRONMENTAL CONDITIONS (CREC)

Bergmann has not identified any CRECs in association with the Subject Property during this Phase I ESA.

11.4 HISTORICAL RECOGNIZED ENVIRONMENTAL CONDITIONS (HRECS)

Bergmann has identified one (1) HRECs in association with the Subject Property during this Phase I ESA:

- One (1) 8000-gallon #2 fuel oil UST used for on-site consumption (Tank #104248; ID# 001) closed/removed on 11/01/1994.

11.5 BUSINESS ENVIRONMENTAL RISK CONSIDERATIONS (BERS)

Although not required by the ASTM E1527-21 standard, based on standard industry practices, Bergmann has attempted to identify Business Environmental Risk (BER) considerations for the Subject Property. Bergmann has identified the following BERS in connection with the Subject Property:

- The IPaC resource list identified that the federally endangered Northern long-eared bat (*Myotis septentrionalis*) and candidate species Monarch Butterfly (*Danaus plexippus*) may occur within the Subject Property.

- Past UST and property uses may have impacted subsurface soils and groundwater, therefore, indoor air quality on the Subject Property in present and future buildings (if constructed) is considered a BER at this time. Testing

indoor air was not part of the Scope of Services for this Phase I ESA. It is unknown if there are any existing indoor air quality issues at the historical buildings and/or structures located on the Subject Property.

- Propane tanks and a rusted and stained 55-gallon drum were noted adjoining the Property immediately to the northeast, off-site.

- Based on a desktop review, it is noted that Ampersand Bio, LLC, a 2017 occupant of the Subject Property, was determined to be involved in the development and manufacturing of immunoassay kits. These kits appear to be comprised of human, canine, hamster, and mouse DNA, and it is likely that small quantities of refrigerants, acids, organic solvents, organic substances and stains were utilized in their manufacture at the Subject Property. However, no evidence of spills, contamination, or improper storage of these chemicals has been identified.
- The National Register of Historic Places (NRHP) and Cultural Resource Information System (CRIS) were reviewed for properties within Ulster County, New York that may be impacted by the Project. Two (2) historic buildings and one (1) historic building were listed on the Subject Property: Paul Smiths Electric Light and Power and Railroad Company (USN number: 03347.000121; NR number: 90NR00509) – constructed in 1909. Lake Flower Dam (USN number: 03347.000246), constructed in 1938. Municipal Building and Pumping Station (USN number: 03347.000229), constructed in 1903.

  Four (4) historic buildings were located east of the Subject Property, off-site. One (1) listed Cottage (USN number: 03347.000054) located 17 Maple Hill Road, Saranac Lake, New York. One (1) listed cottage (USN number: 03347.000067) located at 13 Riverside Drive, Saranac Lake, New York. One (1) listed cottage (USN number: 03347.000068) located at 25 Riverside Drive, Saranac Lake, New York. One (1) listed cottage (USN number: 03347.000069), name Magill Cottage, located at 74 Kiwassa Road, Saranac Lake, New York.

  One historic building district is located north of the Subject Property off-site: Berkeley Square Historic District (USN number: 03347.000228). One (1) eligible building is located approximately 0.13 miles west of the Subject Property, off-site. The village of Saranac Lake, noted north of the Subject Property, had several listings of historic buildings. A map of the full listings is provided in Appendix H – additional documentation.

11.6 RECOMMENDATIONS

- Based on the Recognized Environmental Conditions (RECs) identified as part of this Phase I ESA, a Phase II Environmental Site Assessment is recommended to be performed for the Subject Property to determine if past UST and property uses have impacted the subsurface soils and groundwater.

- Past UST and property uses may have impacted subsurface soils and groundwater, therefore, indoor air quality on the Subject Property in present and future buildings (if constructed) is considered a BER at this time. Testing indoor air was not part of the Scope of Services for this Phase I ESA. It is unknown if there are any existing indoor air quality issues at the historical buildings and/or structures located on the Subject Property. If subsurface VOC-related impacts are discovered during a Phase II ESA investigation, Bergmann would recommend that indoor air quality sampling be performed in the current building present at the Subject Property.

- A corroded pipe was noted in the basement of the historical building located on the Subject Property. The corroded pipe is likely from an oil leak via a suspect former tank and/or PCBs. Wipe test sampling is recommended to determine contaminant of concern.

- If future development occurs on the Property, development should avoid impact to the federally endangered Northern Long-eared Bat (*Myotis septentrionalis*) that may occur on the Subject Property.

- If future development involves removal or relocation of ASTs, USTs, and other features identified during historical review such removal/relocation requires completion pursuant to all applicable federal, state, and local regulations.


- asbestos containing materials (ACM), Lead-Based Paint, and PCB-Caulk survey was not conducted as part of this Phase I ESA. Bergmann recommends an ACM, LBP, and PCB-Caulk survey to be conducted prior to any renovation or construction in accordance with applicable federal, state, and local regulations.

11.7 STATEMENT OF COMPLIANCE

We have performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM Practice ASTM E1527-21 for the Subject Property located at 161 Colonial Drive, Kingston, Ulster County, New York. Any exceptions to, or deletions from, this practice are described in Section 1.4 of this report. This assessment has revealed evidence of Recognized Environmental Conditions connected with the property. This report is certified to, can be relied upon by, and has been prepared for the exclusive use of the following entitiesBergmann; NYS Adirondack Park Agency; New York State Office of General Services (NYSOGS) and their respective successors, assigns, affiliates, and subsidiaries. The named entities above can convey this report to an affiliate, related entity, subsidiary, lender, title insurer, regulatory/city agency or current property owner(s) and their agents, but further dissemination to other parties or persons requires prior written approval from Bergmann.

12.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS

We declare that, to the best of our professional knowledge and belief, we meet the definition of *Environmental Professional* as defined in §312.10 of 40 CFR 312 and we have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. We have developed and performed all the appropriate inquires in conformance with the standards and practices set forth in 40 CFR Part 312.



Mary K. Legawiec, MSc

Environmental Scientist

Phase I ESA Author/Site Reconnaissance



Ariadna Cheremeteff

Bergmann Regional Discipline Leader, Environmental

Phase I ESA QA/QC Reviewer

FIGURES

Adirondack Park Agency Headquarters Feasibility Study Project


STUDY AREA LOCATION MAP

Fig. 1

2,000 Feet

N

Village of Saranac Lake, Franklin County, New York



BERGMANN

Adirondack Park Agency Headquarters Feasibility Study Project

AERIAL IMAGERY MAP

Fig. 2

100 Feet

N

Village of Saranac Lake, Franklin County, New York



PHOTOGRAPHS

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023




Photograph 1: View of Subject Property from west, facing east-southeast.



Photograph 2: powerline and transformer noted on Subject Property near southwest boundary.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023



Photograph 3: View of southwest property, picture taken from parking lot.



Photograph 4: Powerline and transformer along southern boundary.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023




Photograph 5: Historic building, police station, hydropower station, dam located near eastern Property Boundary, on-site.



Photo 6: View of Historic building from front, along Main Street.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023



Photograph 7: Dam adjoining historic building, on Property.



Photograph 8: Residential apartment adjoining the Subject Property, off-site.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023




Photograph 9: Foot bridge and path intersecting Property of Saranac River, from south to north.



Photograph 10: View of Subject Property, from north facing south.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023




Photograph 11: View from northern boundary, facing north, off-site.



Photograph 12: Facing southeast from northwest.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023




Photograph 13: Foot path along western boundary.




Photograph 14: Northwest corner of property facing east.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023



Photograph 15: Northwest of property along west boundary.



Photograph 16: West boundary facing east.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023




Photograph 17: Residential properties adjoining west boundary off site.



Photograph 18: Residential property along west boundary, off site.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023



Photograph 19: Power lines along western boundary, off site.



Photograph 20: Intersection of south and west boundary, facing east.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023




Photograph 21: Power line along south boundary.



Photograph 22: View from southern boundary, facing north.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023




Photograph 23: View from southern boundary, facing east.




Photograph 24: View from southern boundary, facing north.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023



Photograph 25: Transformer at southeast corner of Property, on site.




Photograph 26: Transformer at southeast corner of Property.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023



Photograph 27: Facing east, off site, from eastern boundary.




Photograph 28: Testing laboratory, on site.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023



Photograph 29: Dam access doors adjoining, off site.




Photograph 30: Footbridge.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023




Photograph 31: Discharge culvert pipes.



Photograph 32: Bench within park area.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023



Photograph 33: NYS Environmental Protection Fund marked building.



Photograph 34: Two transformers, on site.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023




Photograph 35: Facing east from eastern boundary.




Photograph 36: Facing east from eastern boundary.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023




Photograph 37: Basement, interior of building.



Photograph 38: Basement access at building.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023




Photograph 39: Elevator mechanical in building.



Photograph 40: Interior of building.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023



Photograph 41: Interior of building.




Photograph 42: Interior of building.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023




Photograph 43: Third floor, interior of building.



Photograph 44: Third floor, interior of building.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023




Photograph 45: Fourth floor, interior of building.




Photograph 46: Roof of building.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023




Photograph 47: Interior of hydro unit.



Photograph 48: Access manhole, interior of hydro unit.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023




Photograph 49: Bucket, interior of hydro unit.




Photograph 50: Interior of hydro unit.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023




Photograph 51: Office space.




Photograph 52: Office space, second floor.

APA HQ – 3 Main Street, Saranac Lake, New York - Phase I ESA
Site Visit Photographs 07.20.2023



Photograph 53: Office space, second floor.



Photograph 54: Water and electrical inlet.

APPENDIX A:

USGS TOPOGRAPHIC MAPS

APA HQ - Phase I ESA
13 Main Street
Saranac Lake, NY 12983

Inquiry Number: 7391856.4
July 17, 2023

EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

07/17/23

Site Name:

APA HQ - Phase I ESA
13 Main Street
Saranac Lake, NY 12983
EDR Inquiry # 7391856.4

Client Name:

Bergmann Associates
280 East Broad Street, Suite 200
Rochester, NY 14604
Contact: Mary K Legawiec

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by Bergmann Associates were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:

P.O.# TBD

Project: APA HQ - Saranac Lake Phase

Coordinates:

Latitude:	44.324429 44° 19' 28" North
Longitude:	-74.132928 -74° 7' 59" West
UTM Zone:	Zone 18 North
UTM X Meters:	569136.87
UTM Y Meters:	4908273.02
Elevation:	1529.30' above sea level

Maps Provided:

2019	1902
2016	
2013	
1999	
1979	
1978	
1955	
1904	

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2019 Source Sheets



Saranac Lake
2019
7.5-minute, 24000



McKenzie Mountain
2019
7.5-minute, 24000

2016 Source Sheets



Saranac Lake
2016
7.5-minute, 24000



McKenzie Mountain
2016
7.5-minute, 24000

2013 Source Sheets




Saranac Lake
2013
7.5-minute, 24000



McKenzie Mountain
2013
7.5-minute, 24000

1999 Source Sheets



Saranac Lake
1999
7.5-minute, 25000
Aerial Photo Revised 1976

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1979 Source Sheets




Saranac Lake
1979
7.5-minute, 25000
Aerial Photo Revised 1976

1978 Source Sheets




Saranac Lake
1978
7.5-minute, 25000
Aerial Photo Revised 1976

1955 Source Sheets



Saranac Lake
1955
15-minute, 62500
Aerial Photo Revised 1953

1904 Source Sheets




Saranac
1904
15-minute, 62500

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.


1902 Source Sheets



Saranac
1902
15-minute, 62500

Historical Topo Map

2019



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Saranac Lake, 2019, 7.5-minute
E, McKenzie Mountain, 2019, 7.5-minute

SITE NAME: APA HQ - Phase I ESA
ADDRESS: 13 Main Street
Saranac Lake, NY 12983
CLIENT: Bergmann Associates

N

Historical Topo Map

2016



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Saranac Lake, 2016, 7.5-minute
E, McKenzie Mountain, 2016, 7.5-minute

SITE NAME: APA HQ - Phase I ESA
ADDRESS: 13 Main Street
Saranac Lake, NY 12983
CLIENT: Bergmann Associates

N

Historical Topo Map

2013



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Saranac Lake, 2013, 7.5-minute
E, McKenzie Mountain, 2013, 7.5-minute

SITE NAME: APA HQ - Phase I ESA
ADDRESS: 13 Main Street
Saranac Lake, NY 12983
CLIENT: Bergmann Associates

N

Historical Topo Map

1999



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Saranac Lake, 1999, 7.5-minute

SITE NAME: APA HQ - Phase I ESA
ADDRESS: 13 Main Street
Saranac Lake, NY 12983
CLIENT: Bergmann Associates

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Saranac Lake, 1979, 7.5-minute

SITE NAME: APA HQ - Phase I ESA
ADDRESS: 13 Main Street
Saranac Lake, NY 12983
CLIENT: Bergmann Associates

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Saranac Lake, 1978, 7.5-minute

SITE NAME: APA HQ - Phase I ESA
ADDRESS: 13 Main Street
Saranac Lake, NY 12983
CLIENT: Bergmann Associates

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Saranac Lake, 1955, 15-minute

SITE NAME: APA HQ - Phase I ESA
ADDRESS: 13 Main Street
Saranac Lake, NY 12983
CLIENT: Bergmann Associates

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Saranac, 1904, 15-minute

SITE NAME: APA HQ - Phase I ESA
ADDRESS: 13 Main Street
Saranac Lake, NY 12983
CLIENT: Bergmann Associates

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Saranac, 1902, 15-minute

SITE NAME: APA HQ - Phase I ESA
ADDRESS: 13 Main Street
Saranac Lake, NY 12983
CLIENT: Bergmann Associates

N

APPENDIX B:

AERIAL PHOTOGRAPHS

APA HQ - Phase I ESA

13 Main Street

Saranac Lake, NY 12983

Inquiry Number: 7391856.11

July 19, 2023

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

07/19/23

Site Name:

APA HQ - Phase I ESA
13 Main Street
Saranac Lake, NY 12983
EDR Inquiry # 7391856.11

Client Name:

Bergmann Associates
280 East Broad Street, Suite 200
Rochester, NY 14604
Contact: Mary K Legawiec

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	*Scale*	*Details*	*Source*
2019	1"=500'	Flight Year: 2019	USDA/NAIP
2015	1"=500'	Flight Year: 2015	USDA/NAIP
2011	1"=500'	Flight Year: 2011	USDA/NAIP
2008	1"=500'	Flight Year: 2008	USDA/NAIP
1994	1"=500'	Acquisition Date: May 14, 1994	USGS/DOQQ
1985	1"=500'	Flight Date: May 24, 1985	USDA
1976	1"=500'	Flight Date: May 13, 1976	USGS
1953	1"=500'	Flight Date: April 24, 1953	USGS
1942	1"=500'	Flight Date: October 02, 1942	USGS


When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.


INQUIRY #: 7391856.11
YEAR: 2019
= 500'
N
EDR



INQUIRY #: 7391856.11
YEAR: 2015
= 500'
N
EDR



INQUIRY #: 7391856.11
YEAR: 2011
= 500'
N
EDR


INQUIRY #: 7391856.11
YEAR: 2008
= 500'
N
EDR


INQUIRY #: 7391856.11
YEAR: 1994
= 500'
N
EDR


INQUIRY #: 7391856.11
YEAR: 1985
= 500'
N
EDR


INQUIRY #: 7391856.11
YEAR: 1976
= 500'
N
EDR


INQUIRY #: 7391856.11
YEAR: 1953
= 500'
N
EDR



INQUIRY #: 7391856.11

YEAR: 1942

= 500'

N

EDR

APPENDIX C:

SITE OBSERVATION NOTES AND FIELD MAP

BERGMANN
ARCHITECTS ENGINEERS PLANNERS

SITE OBSERVATIONS
(Confidential and Private)

Job No.: 23 0100049 Date: 07/20/2023 Assessor Name: M.Legawiec

Property Address: 3 East Main Street, Saranac Lake, New York

(Provide a sketch of the property at a minimum)

Persons Present/Title/Tenure: M. Legawiec – Environmental Scientist
J. Hill – Project Manager
D. Plante – APA

Locality: (Circle one)
Urban, Suburban, Rural
Highly, Moderately, Lightly - Developed
Industrial, Commercial, Agricultural, Residential, Wooded, Fallow, Vacant

No. of acres: _____ Frontage: _____ Depth: _____ Zoning: _____

GROUND SURFACES:

Fill materials: yes/no/type None observed
Debris/Dumping: yes/no/type None observed
Spills/Staining: yes/no None observed
Stressed Vegetation: yes/no None observed
Odors: yes/no None observed
Pools of Liquid: yes/no Saranac river runs through site, dam present.
Pits/Ponds/Lagoons: yes/no None observed
Wastewater discharge: yes/no None observed
Sheen (location): None observed
Trees _____ Landscaping _____ Green Area _____

UTILITIES:

Transformers: number: three (3) transformer
Location on property: adjoining police station / SE area of subject property
(Pole-mounted) or pad-mounted
Client owned or utility owned – unknown
Suspect PCB-containing equipment: yes / (no) / unknown

Utility services by:

Natural gas: _____
Electric: _____
Telephone: _____
Sewer: Sanitary-sewering at Date of Connection: _____
Septic: _____ Location on Property: _____
Water" _____ Date of Connection: _____
Well: _____ Location on Property: _____

BUILDING:

Job Number: 2301000 49

BERGMANN
ARCHITECTS ENGINEERS PLANNERS

No. of stories multi Square Foot _____
Age of Construction c 1909
Additions _____

Structure:
block/poured concrete yes brick _____
steel _____ wood/stick _____
siding (type) _____
flat / peaked roof flat condition good

Current Heating System: _____
Past Heating System: _____
Floor drains: yes / no discharge point: _____
Sump pumps: yes / no discharge point _____
Catch basins: yes / no discharge point _____
Dry wells: yes / no discharge point _____

Current on-site operations: police station, nurses, village at saranac
Past on-site operations: lake, businesses.

ASBESTOS:

Was asbestos evaluated as part of this assessment? Yes No
Does the age of the building suggest the presence of asbestos? (Yes) No
Has the building been renovated? Yes No - partially. see phase I ESA - village of saranac lake foil response.

Floor materials:
_____ 9" x 9"
_____ Rolled vinyl flooring
_____ 12" X 12"
_____ stair treads

Ceiling tiles:
_____ 1' x 1'
_____ 2' x 4'
_____ 2' x 2'
_____ Spray-on

Drywall/Plaster _____
Pipe Wrap _____
Base Cove _____
Roofing _____

TSI _____
Boiler TSI _____
Transite _____

Condition of materials: uneven

WASTES

Job Number: 23010004g

Solid: type
container
collector

Recycling: type
container and location
collector

Other: type
container and location
collector

type
container and location
collector

PERMITS (air, water, etc.):
(copies available)

EQUIPMENT:
none. Porta johns + propane tanks noted on subject property. Dam + hydro facility noted on subject property.

ADJOINING PROPERTIES:
(Photo's)
North: Rte 3, village of Saranac consisting of commercial businesses.
South: Lake Street + wooded land beyond.
East: Main Street + Saranac Inn
West: Pelkey Lane, residential properties, wooded land, Petrova elementary school beyond.

GENERATORS OR COMPRESSORS (fuel source; spills)

STORAGE TANKS: None Observed

Job Number: 23010004g

AST/UST's
(Get copies of plans for tank location.)

(USTs)

	Capacity	Product	Location on Property
Tank 1	2000 -gallon	heating oil tank	on subject property - EAST UST
Tank 2	8000 - gallon	#2 fuel oil	on subject property - EAST
Tank 3			

Staining, Stressed or Dead Vegetation no

Odors Detected no

Tanks Registered yes

(Copies of registrations available)

Any tanks removed from the property unknown

Contractor/date

HAZARDOUS MATERIALS: None Observed

Stored on-site _____ Used on-site _____

MSDS on-site yes / no

List materials (type, size of containers, spills, odors, etc.)
rusted 55-gallon drum, outside of RES property to the NE, off-site. unknown if spilled, some exterior staining observed.

Evidence of Spillage/Leakage:

ADDITIONAL NOTES:

Signature of Assessor: Mary K. Legawiec

Job Number: J 3010049

APPENDIX D:

INTERVIEW QUESTIONNAIRE

Phase I Environmental Site Assessment
User Questionnaire

Site Name: Adirondack Park Agency HQ – Saranac Lake Study

Site Location: 3 Main Street, Saranac Lake, New York

The following questions aretaken from the ASTM 1527-13 Standard Practice for Phase I Environmental Site Assessments and must be answered in order to qualify for the Landowner Liability Protections ("LLPs") under the federal Comprehensive Environmental Response Compensation and Liability Act, otherwise known as "CERCLA" or the Superfund law. ***Note that the completion of this form, by itself, does not automatically qualify one for any of the three LLPs, all of which have additional eligibility criteria. Note further that state and local government agencies will often have their own, independent source of environmental liability not covered by any of the LLPs.***

Please provide an answer to each question or attach pertinent information and identify a number for each attachment.

1. Are you aware of any environmental cleanup liens against the *property* that are filed or recorded under federal, tribal, state or local law?

☑ No ☐ Yes (Describe or attach information) Attachment No. _____

_____

_____

2. Are you aware of any Activity and Use Limitations (AULs), such as engineering controls (e.g. engineered caps, foundations, liners, treatment methods, etc. in use to prevent contamination from migrating to surrounding areas), land use restrictions or institutional controls (e.g. administrative measures restricting groundwater use, construction, or property use) that are in place at the site and/or have been filed or recorded in a registry under federal, tribal, state or local law?

☑ No ☐ Yes (Describe or attach information) Attachment No. _____

_____

_____

B

3. As the user of the Phase I Environmental Site Assessment, do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business?

☐ No ☑ Yes (Describe or attach information) Attachment No. _____

4. a. Does the purchase price being paid for this property reasonably reflect the fair market value of the property?

☐ No ☐ Yes (Describe or attach information) Attachment No. _____

4. b. If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the *property*?

☐ No ☐ Yes (Describe or attach information) Attachment No. _____

5. Are you aware of commonly known or reasonably ascertainable information about the property that would help the environmental professional to identify conditions indicative of releases or threatened releases? For example, as User,

(a) Do you know the past uses of the property? ☐ No ☑ Yes (Describe or attach information) Attachment No. Pauls smith electris and railroad

B

(b) Do you know of specific chemicals that are present or once were present at the property?

☑ No ☐ Yes (Describe or attach information) Attachment No. _____

_____

_____

(c) Do you know of spills or other chemical releases that have taken place at the property?

☑ No ☐ Yes (Describe or attach information) Attachment No. _____

_____

_____

(d) Do you know of any environmental cleanups that have taken place at the property?

☑ No ☐ Yes (Describe or attach information) Attachment No. _____

_____

_____

6. As the User of the Phase I Environmental Site Assessment, based on your knowledge and experience related to the property are there any obvious indicators that point to the presence or likely presence of contamination at the property?

☑ No ☐ Yes (Describe or attach information) Attachment No. _____

_____

_____

_____

Signature (Project) Manager

_____

Printed Name

_____

Date

B

BERGMANN
ARCHITECTS ENGINEERS PLANNERS

Interview Form

Bergmann Project #

Site Name APA HQ - Saranac Lake
Site Location 3 Main Street
Saranac Lake, Franklin County, New York

Interviewee Dustin Martin **Date** 7/19/2023
Connection to subject property superintendent of public works

Asked the interviewee to answer in "good faith and to the extent of their knowledge".

Ownership From: Village of Saranac Lake To: NYS APA

Previous Owners? Paul Smiths Electric and Railroad

Occupants or operations onsite? Saranac Lake Police Department, Franklin County Nurses, Franklin County, Hydro electric

Site Use hydro electric unit, police department and rental space.

Site History

Any evidence or past use of hazardous substances or petroleum products used or stored on the property? no

Pits, Lagoons or Ponds.	Y or (N)	Pools of Liquid	Y or (N)
Stained Soils	Y or (N)	Odors	Y or (N)
Stressed Vegetation	Y or (N)	Stains or Corrosion	(Y) or N - basement of building
Solid Waste	Y or (N)	PCB's	Y or (N)
Waste Water	Y or N	Storage Tanks	(Y) or N - propane
Wells	Y or N	Drums	Y or (N)
Septic System	Y or N	Drains or Sumps	Y or (N)

Adjoining property uses? (gas station...) res properties, saranac lake, wooded land
(past uses)

Haz Substances or Petrol potential to migrate onto the subject property? no

Materials/Drums buried onsite? 2000 Gallon burried fuel oil tank on site still used for heating. Cathodic protection is tested annually for this tank.

Previous use of the property? no

Environmental Cleanup Liens? No

Any known spills/emergency response? No

Misc:

APPENDIX E:

SANBORN FIRE INSURANCE MAP SEARCH

APA HQ - Phase I ESA

13 Main Street

Saranac Lake, NY 12983

Inquiry Number: 7391856.3

July 18, 2023

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

07/18/23

Site Name:

APA HQ - Phase I ESA
13 Main Street
Saranac Lake, NY 12983
EDR Inquiry # 7391856.3

Client Name:

Bergmann Associates
280 East Broad Street, Suite 200
Rochester, NY 14604
Contact: Mary K Legawiec

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Bergmann Associates were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 0D31-4F57-8044

PO # TBD

Project APA HQ - Saranac Lake Phase I

Maps Provided:

1965
1945
1931
1924
1916
1908
1903
1899
1895

Sanborn® Library search results

Certification #: 0D31-4F57-8044

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Bergmann Associates (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.


Copyright 2023 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.


Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1965 Source Sheets



Volume 1, Sheet 7
1965



Volume 1, Sheet 16
1965



Volume 1, Sheet 2
1965

1945 Source Sheets



Volume 1, Sheet 2
1945



Volume 1, Sheet 7
1945



Volume 1, Sheet 16
1945


1931 Source Sheets



Volume 1, Sheet 7
1931



Volume 1, Sheet 2
1931



Volume 1, Sheet 16
1931

1924 Source Sheets



Volume 1, Sheet 5
1924




Volume 1, Sheet 4
1924

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1916 Source Sheets



Volume 1, Sheet 7
1916



Volume 1, Sheet 5
1916

1908 Source Sheets



Volume 1, Sheet 6
1908



Volume 1, Sheet 4
1908

1903 Source Sheets




Volume 1, Sheet 4
1903



Volume 1, Sheet 3
1903

1899 Source Sheets



Volume 1, Sheet 2
1899



Volume 1, Sheet 4
1899

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.


1895 Source Sheets



Volume 1, Sheet 2
1895

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # 0D31-4F57-8044



Site Name:	APA HQ - Phase I ESA
Address:	13 Main Street
City, ST, ZIP:	Saranac Lake, NY 12983
Client:	Bergmann Associates
EDR Inquiry:	7391856.3
Order Date:	07/18/2023
Certification #	0D31-4F57-8044
Copyright	1965

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 2
Volume 1, Sheet 16
Volume 1, Sheet 7

0 Feet 150 300 600

N


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 0D31-4F57-8044

Site Name:	APA HQ - Phase I ESA
Address:	13 Main Street
City, ST, ZIP:	Saranac Lake, NY 12983
Client:	Bergmann Associates
EDR Inquiry:	7391856.3
Order Date:	07/18/2023
Certification #	0D31-4F57-8044
Copyright	1945

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 16
Volume 1, Sheet 7
Volume 1, Sheet 2

0 Feet 150 300 600

N





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 0D31-4F57-8044

Site Name:	APA HQ - Phase I ESA
Address:	13 Main Street
City, ST, ZIP:	Saranac Lake, NY 12983
Client:	Bergmann Associates
EDR Inquiry:	7391856.3
Order Date:	07/18/2023
Certification #	0D31-4F57-8044
Copyright	1931

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 16
Volume 1, Sheet 2
Volume 1, Sheet 7

0 Feet 150 300 600

N

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # 0D31-4F57-8044



Site Name: APA HQ - Phase I ESA
Address: 13 Main Street
City, ST, ZIP: Saranac Lake, NY 12983
Client: Bergmann Associates
EDR Inquiry: 7391856.3
Order Date: 07/18/2023
Certification #: 0D31-4F57-8044
Copyright 1924

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 4
Volume 1, Sheet 5

0 Feet 150 300 600

N


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 0D31-4F57-8044

Site Name:	APA HQ - Phase I ESA
Address:	13 Main Street
City, ST, ZIP:	Saranac Lake, NY 12983
Client:	Bergmann Associates
EDR Inquiry:	7391856.3
Order Date:	07/18/2023
Certification #	0D31-4F57-8044
Copyright	1916

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 5
Volume 1, Sheet 7

0 Feet 150 300 600

N


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 0D31-4F57-8044


River
MAIN
LIVERY
HOTEL EMPIRE
RIVER
RIVERSIDE INN
Flume
Saranac River
DAM
IRON BRIDGE
Lake Flower
PAUL SMITH LIGHT, POWER & RAILWAY CO.
LAKE
MAPLE
LUMBER
Storage
Bakery
Printing Ex
Drugs
Boarding
Jewelry Store
Tel. Off.
Ice Ho.
Sal.
Vac.
Gro.
Barber
Hall 2d
Hall 3d
Ice Ho. Pd
Storing 2d
Storing 3d
Wood Ho. Pd
Wood Ho. 2d
Wood Ho. 3d
Wood Ho. Pd Storing 2d
Wood Ho. Pd Storing 3d
Wood Ho. 2d Storing 3d
Wood Ho. 3d Storing 3d
Wood Ho. Pd Storing 2d Storing 3d
Wood Ho. 2d Storing 2d Storing 3d
Wood Ho. 3d Storing 2

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # 0D31-4F57-8044



Site Name:	APA HQ - Phase I ESA
Address:	13 Main Street
City, ST, ZIP:	Saranac Lake, NY 12983
Client:	Bergmann Associates
EDR Inquiry:	7391856.3
Order Date:	07/18/2023
Certification #	0D31-4F57-8044
Copyright	1903

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 3
Volume 1, Sheet 4

0 Feet 150 300 600

N

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # 0D31-4F57-8044



Site Name:	APA HQ - Phase I ESA
Address:	13 Main Street
City, ST, ZIP:	Saranac Lake, NY 12983
Client:	Bergmann Associates
EDR Inquiry:	7391856.3
Order Date:	07/18/2023
Certification #:	0D31-4F57-8044
Copyright	1899

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 4
Volume 1, Sheet 2

0 Feet 150 300 600

N

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # 0D31-4F57-8044

Site Name:	APA HQ - Phase I ESA
Address:	13 Main Street
City, ST, ZIP:	Saranac Lake, NY 12983
Client:	Bergmann Associates
EDR Inquiry:	7391856.3
Order Date:	07/18/2023
Certification #	0D31-4F57-8044
Copyright	1895

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 1, Sheet 2

N

APPENDIX F:

FOIL REQUESTS AND RESPONSES

BERGMANN
ARCHITECTS ENGINEERS PLANNERS

July 25, 2023

Records Access Office
New York State Department of Health
Empire Plaza, Corning Tower
State Street
Albany, NY 12203

Re: Freedom of Information Request

Dear Sir or Madam:

Bergmann has been retained to conduct a Phase I Environmental Site Assessment on the property below. Bergmann requests copies of environmental files, records, and memoranda concerning the following properties:

3 East Main Street
Saranac Lake, New York
Tax Parcel No.: 458.21-2-1

This information should include: 1) past and present aboveground and/or underground storage tank registration(s); 2) reported spills or releases of hazardous substances; 3) generation, storage, treatment, or disposal of hazardous substances; 4) past and present groundwater, surface water, and soil investigations and/or remediation; 5) environmental permits/violations; and 6) Environmental Liens or Activity Use Limitations (AULs).

We would prefer to receive any documents electronically in PDF format. Once notified of your findings we will gladly pay copying costs associated with the documents we require.

Please let us know if you can accommodate this request in an expedient manner.

Please email if you have any questions.

Very truly yours,
Bergmann

Mary K. Legawiec
Environmental Scientist, BERGMANN
mlegawiec@bergmannpc.com

BERGMANN
ARCHITECTS ENGINEERS PLANNERS

July 25, 2023

Franklin County Department of Health
355 West Main Street
Malone, NY 12953

Re: Freedom of Information Request

Dear Sir or Madam:

Bergmann has been retained to conduct a Phase I Environmental Site Assessment on the property below. Bergmann requests copies of environmental files, records, and memoranda concerning the following properties:

3 East Main Street
Saranac Lake, New York
Tax Parcel No.: 458.21-2-1

This information should include: 1) past and present aboveground and/or underground storage tank registration(s); 2) reported spills or releases of hazardous substances; 3) generation, storage, treatment, or disposal of hazardous substances; 4) past and present groundwater, surface water, and soil investigations and/or remediation; 5) environmental permits/violations; and 6) Environmental Liens or Activity Use Limitations (AULs).

We would prefer to receive any documents electronically in PDF format. Once notified of your findings we will gladly pay copying costs associated with the documents we require.

Please let us know if you can accommodate this request in an expedient manner.

Please email if you have any questions.

Very truly yours,
Bergmann

Mary K. Legawiec
Environmental Scientist, BERGMANN
mlegawiec@bergmannpc.com

BERGMANN
ARCHITECTS ENGINEERS PLANNERS

July 25, 2023

Kip Cassavaw, County Clerk
355 West Main Street, Suite 248
P.O Box 70
Malone, NY 12953

Re: Freedom of Information Request

Dear Sir or Madam:

Bergmann has been retained to conduct a Phase I Environmental Site Assessment on the property below. Bergmann requests copies of environmental files, records, and memoranda concerning the following properties:

3 East Main Street
Saranac Lake, New York
Tax Parcel No.: 458.21-2-1

This information should include: 1) past and present aboveground and/or underground storage tank registration(s); 2) reported spills or releases of hazardous substances; 3) generation, storage, treatment, or disposal of hazardous substances; 4) past and present groundwater, surface water, and soil investigations and/or remediation; 5) environmental permits/violations; and 6) Environmental Liens or Activity Use Limitations (AULs).

We would prefer to receive any documents electronically in PDF format. Once notified of your findings we will gladly pay copying costs associated with the documents we require.

Please let us know if you can accommodate this request in an expedient manner.

Please email if you have any questions.

Very truly yours,
Bergmann

Mary K. Legawiec
Environmental Scientist, BERGMANN
mlegawiec@bergmannpc.com

BERGMANN
ARCHITECTS ENGINEERS PLANNERS

July 25, 2023

Saranac Lake Village Clerk
39 Main Street. 2nd floor
Saranac Lake, NY 12983

Re: Freedom of Information Request

Dear Sir or Madam:

Bergmann has been retained to conduct a Phase I Environmental Site Assessment on the property below. Bergmann requests copies of environmental files, records, and memoranda concerning the following properties:

3 East Main Street
Saranac Lake, New York
Tax Parcel No.: 458.21-2-1

This information should include: 1) past and present aboveground and/or underground storage tank registration(s); 2) reported spills or releases of hazardous substances; 3) generation, storage, treatment, or disposal of hazardous substances; 4) past and present groundwater, surface water, and soil investigations and/or remediation; 5) environmental permits/violations; and 6) Environmental Liens or Activity Use Limitations (AULs).

We would prefer to receive any documents electronically in PDF format. Once notified of your findings we will gladly pay copying costs associated with the documents we require.

Please let us know if you can accommodate this request in an expedient manner.

Please email if you have any questions.

Very truly yours,
Bergmann

Mary K. Legawiec
Environmental Scientist, BERGMANN
mlegawiec@bergmannpc.com

BERGMANN
ARCHITECTS ENGINEERS PLANNERS

July 25, 2023

Saranac Lake Volunteer Fire Department
100 Broadway
Saranac Lake, NY 12983

Re: Freedom of Information Request

Dear Sir or Madam:

Bergmann has been retained to conduct a Phase I Environmental Site Assessment on the property below. Bergmann requests copies of environmental files, records, and memoranda concerning the following properties:

3 East Main Street
Saranac Lake, New York
Tax Parcel No.: 458.21-2-1

This information should include: 1) past and present aboveground and/or underground storage tank registration(s); 2) reported spills or releases of hazardous substances; 3) generation, storage, treatment, or disposal of hazardous substances; 4) past and present groundwater, surface water, and soil investigations and/or remediation; 5) environmental permits/violations; and 6) Environmental Liens or Activity Use Limitations (AULs).

We would prefer to receive any documents electronically in PDF format. Once notified of your findings we will gladly pay copying costs associated with the documents we require.

Please let us know if you can accommodate this request in an expedient manner.

Please email if you have any questions.

Very truly yours,
Bergmann

Mary K. Legawiec
Environmental Scientist, BERGMANN
mlegawiec@bergmannpc.com

BERGMANN
ARCHITECTS ENGINEERS PLANNERS

July 25, 2023

Records Access Office
New York State Department of Environmental Conservation
625 Broadway
Albany, NY 12233

Re: Freedom of Information Request

Dear Sir or Madam:

Bergmann has been retained to conduct a Phase I Environmental Site Assessment on the property below. Bergmann requests copies of environmental files, records, and memoranda concerning the following properties:

3 East Main Street
Saranac Lake, New York
Tax Parcel No.: 458.21-2-1

This information should include: 1) past and present aboveground and/or underground storage tank registration(s); 2) reported spills or releases of hazardous substances; 3) generation, storage, treatment, or disposal of hazardous substances; 4) past and present groundwater, surface water, and soil investigations and/or remediation; 5) environmental permits/violations; and 6) Environmental Liens or Activity Use Limitations (AULs).

We would prefer to receive any documents electronically in PDF format. Once notified of your findings we will gladly pay copying costs associated with the documents we require.

Please let us know if you can accommodate this request in an expedient manner.

Please email if you have any questions.

Very truly yours,
Bergmann

Mary K. Legawiec
Environmental Scientist, BERGMANN
mlegawiec@bergmannpc.com

VILLAGE OF SARANAC LAKE

FREEDOM OF INFORMATION LAW (FOIL) REQUEST

[This form language is optional but may enhance your use of the Freedom of Information Law. You may choose to utilize certain portions that are most applicable to your request. You may cut and paste the entire form into an email, read all provisions, and delete and/or modify those that do not apply.]

Dear Records Access Officer:

(1) Please mail/ email the following records if possible [include as much detail about the record as possible, such as relevant dates, names, descriptions, etc.]:

(2) Please advise me of the appropriate time during normal business hours for inspecting the following records prior to obtaining copies [include as much detail about the records as possible, including relevant dates, names, descriptions, etc.]:

(3) Please inform me of the cost of providing paper copies of the records.

(4) If the requested records cannot be mailed/ emailed to me due to the volume of records identified in response to my request, please advise me of the actual cost of copying all records onto a CD or floppy disk.

(5) If my request is too broad or does not reasonably describe the records, please contact me via mail/ email so that I may clarify my request, and when appropriate inform me of the manner in which records are filed, retrieved or generated.

If it is necessary to modify my request, and an mail/ email response is not preferred, please contact me at the following telephone number: _____.

If for any reason any portion of my request is denied, please inform me of the reasons for the denial in writing and provide the name, address/ email address of the person or body to whom an appeal should be directed.

Name:

Address [if records are to be mailed]

OR

Email [if records are to be emailed]

VILLAGE OF SARANAC LAKE

FREEDOM OF INFORMATION LAW (FOIL)
REQUEST FORM

APPLICATION FOR PUBLIC ACCESS TO RECORDS

To: RECORDS ACCESS OFFICER

Fee: $.25 per page _____

Please indicate amount fee should not exceed

Name: _____

Address: _____

Phone: _____

Email: _____

I HEREBY APPLY FOR THE FOLLOWING RECORD:

_____

_____

_____

_____

_____

_____

NOTICE: You have a right to appeal a denial of this application to the head of this agency who must fully explain the reasons for such denial in writing within seven days of receipt of this appeal.

I HEREBY APPEAL:

Signature: _____ *Date:* _____

AGENCY USE ONLY

Approved ____ Denied ____ Record is not maintained by this agency ____

Record of which this agency is Legal Custodian cannot be found ____

Date of Notice of Cost: _____ Time Needed for Research: _____

Date of Payment: _____ Estimated Date of Readiness: _____

Prepared by (Signature): _____

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

Office of Environmental Quality, Region 5
1115 State Route 86, PO Box 296, Ray Brook, NY 12977
P: (518) 897-1241 I F: (518) 897-1245
www.dec.ny.gov

February 19, 2016

Mr. John Sweeney
Village Manager
Village of Saranac Lake
manager@saranaclakeny.gov

Re: Petroleum Bulk Storage (PBS) Program Site
Inspection -6NYCRR Parts 612-614
PBS# 5-416703, Inspection #41832
Village of Saranac Lake
3 Main Street
Saranac Lake, NY 12983

Dear Mr. Sweeney:

The Department has reviewed the application received on January 25, 2016 along with the January 29, 2016, February 4, 2016, and February 16, 2016 emails submitted by Mr. Dora regarding the Department's May 13, 2015 Notice of Violation and follow up responses of September 29, 2015, January 5, 2016 and January 21, 2016. Please note the new regulations as of October 11, 2015 found on our website at http://www.dec.ny.gov/regulations/98151.html.

UST TANK # 003

As-built Plans – [Section 613-3.1(b) (4) (ii)] – The as-built plan submitted was missing labels on the two circles. The first one is current labeled with a dimension of 26'-9" and then we have the little circle inside the big circle which should have a label of fill port on it. Please make these corrections to the as-built.

The application submitted was processed; enclosed is the current certificate and facility information report (FIR). Please remember to sign the certificate and post it at the facility, replacing the outdated one.

The Department has determined that except for the item listed above, the information provided satisfactorily demonstrates that the facility has returned to

compliance. Please contact me with any questions at 518-897-1241 or by email at Benjamin.Hankins@dec.ny.gov.

Sincerely,

Benjamin Hankins
Environmental Engineer 1
NYSDEC, Region 5

BH:pm

Enclosures: PBS certificate
PBS FIR

ec: Jeff Dora, dpw1@aranaclakeny.gov

PBS Number
5-416703

New York State Department of Environmental Conservation
PETROLEUM BULK STORAGE CERTIFICATE

625 Broadway, 11th Floor, Albany, NY 12233-7020 Phone: 518-402-9553

Region 5 NYSDEC - PBS Unit
Route 86, P.O. Box 296
Ray Brook, NY 12977-0296
(518) 897-1241

TANK NUMBER	TANK LOCATION	DATE INSTALLED	TANK TYPE	PRODUCT STORED	CAPACITY (GALLONS)	
003	Underground including vaulted with no access for inspection	11/01/1994	Fiberglass Coated Steel	#2 fuel oil (on-site consumption)	2,000	
004	Aboveground - No Contact (on saddles, legs, rack, cradle, etc.)	08/30/2012	Plastic	diesel	165	*

*** Aboveground tanks require monthly visual inspections and may need documented internal inspections as described in 6 NYCRR Section 613-4.3**

FACILITY NAME AND ADDRESS :
VILLAGE SARANAC LAKE
3 MAIN STREET
SARANAC LAKE, NY 12983

Class B (Daily On-Site) Operator: JEFF DORA

Emergency Contact Name: JEFF DORA
Emergency Contact Phone Number: (518) 354-0595

ISSUED BY: Acting Commissioner Basil Seggos
PBS NUMBER: **5-416703**
DATE ISSUED: 01/04/2013
EXPIRATION DATE : 10/02/2017
FEE PAID: $300.00

FACILITY (PROPERTY) OWNER:
VILLAGE SARANAC LAKE
39 MAIN STREET
SARANAC LAKE, NY 12983

Tank Owner Name:
Same as Property Owner

Facility Phone Number
(518) 891-4160

MAILING CORRESPONDENCE:
VILLAGE MANAGER
VILLAGE SARANAC LAKE
39 MAIN STREET
2ND FLOOR, SUITE 9
SARANAC LAKE, NY 12983

As the owner of this facility and/or the tanks at this facility, the receipt, posting, and use of this certificate is an acknowledgement that I am responsible to the extent required by law for ensuring that this facility is in compliance with all regulations for the bulk storage of petroleum including those regarding equipment requirements, inspections, handling procedures, recordkeeping, registration requirements, providing advanced notice to the Department of major changes to a tank system, spill reporting, and all other applicable requirements. Violations may be punishable as a criminal offense and/or a civil violation in accordance with applicable state and federal law.

This registration certificate must be kept current and conspicuously posted at this facility at all times. Posting must be at the tank, at the entrance of the facility, or the main office where the storage tanks are located.

Spills must be reported to the DEC within two hours (1-800-457-7362).

Signature of Facility Owner/Authorized Representative Date

Printed Name and Title of Facility Owner/Authorized Representative

Print Date: 2/16/2016

THIS REGISTRATION CERTIFICATE IS NON -TRANSFERABLE

PBS # : 5-416703

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
Petroleum Bulk Storage Program
Facility Information Report

Printed : 2/16/2016 pbsfacrpt_foil.rpt

Site Information

VILLAGE SARANAC LAKE
3 MAIN STREET
SARANAC LAKE, NY 12983

Site Phone: (518) 891-4160
Town: Harrietstown County: Franklin
Class B (On-Site) Operator: JEFF DORA
Class A (Primary) Operator:
Emergency Contact: JEFF DORA

Tax Map Information

Boro/Sec.: 458.21
Block: 2
Lot: 1

Site Owner Information

VILLAGE SARANAC LAKE
39 MAIN STREET
SARANAC LAKE, NY 12983

(518) 891-4150
Owner Type : Local Government

Mail Correspondent Information

VILLAGE SARANAC LAKE
39 MAIN STREET
2ND FLOOR, SUITE 9
SARANAC LAKE, NY 12983

ATTN: VILLAGE MANAGER

(518) 891-4150

Authorized Representative: JOHN M. SWEENEY
Emergency Phone: (518) 354-0595

Site Status : Active Reg Expires : 10/02/2017 Cert Printed: 02/16/2016 Total Active Tanks : 2 Last Inspected: 04/30/2015
Site Type: Municipality (Incl. Waste Water Treatment Cert Issued: 01/04/2013 Total Active Capacity : 2,165 Inspected By: Benjamin Hankins

(2) Tank No	(3) Tank Loc	(4) Status	(5) Date Install	(5) Date Closed	(6) Capacity (gals)	(7) Product	(8) Tank Type	(9) Tank IP	(10) Tank EP	(11) Tank SC	(12) Tank LD	(13) Tank OP	(14) Tank SP	(15) Tank Disp	(16) Pipe Loc	(17) Pipe Type	(18) Pipe EP	(19) Pipe SC	(20) Pipe LD	(21) UDC	Next Tank Test	Next Line Test	Tank Owner
003	5	1	11/01/1994		2,000	0001	04	00	02 04	04	02	05	01	05	03	10	00	00	09				VILLAGE SARANA
004	3	1	08/30/2012		165	0008	07	00	05	12	02	04	05 00	02	01	10	00	00	09				VILLAGE SARANA
001	5	3		11/01/1994	8,000	0001	01	00	00	00	00	00		02	00	02	00						
002	5	6	12/01/1967		2,000	0009	01	00	00	00	00	00		02	00	02	00						

(See Reverse Side or Last Page for Code Keys)

PETROLEUM BULK STORAGE APLICATION - SECTION B - TANK INFORMATION - CODE KEYS

Action (1)

1. Initial Listing
2. Add Tank
3. Close/Remove Tank
4. Information Correction
5. Recondition/Repair/Reline Tank

Tank Location (3)

1. Aboveground-contact w/soil
2. Aboveground-contact w/ impervious barrier
3. Aboveground on saddles, leggs, stilts, rack or cradle
4. Tank 10% or more below ground
5. Underground including vaulted with no access for inspection
6. Aboveground in Subterranean Vault w/access for inspections

Status (4)

1. In-service
2. Out-of-service
3. Closed-Removed
4. Closed- In Place
5. Tank converted to Non-Regulated use

D. Delivery Prohibited

Products Stored (7)

Heating Oils: On-Site Consumption

0001. #2 Fuel Oil
0002. #4 Fuel Oil
0259. #5 Fuel Oil
0003. #6 Fuel Oil
0012. Kerosene
0591. Clarified Oil
2711. Biodiesel (Heating)
2642. Used Oil (Heating)

Heating Oils: Resale/ Redistribution

2718. #2 Fuel Oil
2719. #4 Fuel Oil
2720. #5 Fuel Oil
2721. #6 Fuel Oil
2722. Kerosene
2723. Clarified Oil
2724. Biodiesel (Heating)

Motor Fuels

0009. Gasoline
2712. Gasoline/Ethanol
0008. Diesel
2710. Biodiesel
0011. Jet Fuel
1044. Jet Fuel (Biofuel)
2641. Aviation Gasoline

Lubricating/Cutting Oils

0013. Lube Oil
0015. Motor Oil
1045. Gear/Spindle Oil
0010. Hydraulic Oil
0007. Cutting Oil
0021. Transmission Fluid
1836. Turbine Oil
0308. Petroleum Grease

Oils Used as Building Materials

2626. Asphaltic Emulsions
0748. Form Oil

Petroleum Spirits

0014. White/Mineral Spirits
1731. Naptha

Mineral/Insulating Oils

0020. Insulating Oil (e.g., Transformer, Cable Oil)
2630. Mineral Oil

Waste/Used/Other Oils

0022 Waste/Used Oil
9999. Other-Please list:*

Crude Oil

0006. Crude Oil
0701. Crude Oil Fractions

Tank Type (8)

01. Steel/Carbon Steel/Iron
02. Galvanized Steel Alloy
03. Stainless Steel Alloy
04. Fiberglass Coated Steel
05. Steel Tank in Concrete
06. Fiberglass Reinforced Plastic (FRP)
07. Plastic
08. Equivalent Technology
09. Concrete
10. Urethane Clad Steel
99. Other-Please list:*

Internal Protection (9)

00. None
01 Epoxy Liner
02. Rubber Liner
03. Fiberglass Liner (FRP)
04. Glass Liner
99. Other-Please list:*

External Protection (10/18)

00. None
01. Painted/Asphalt Coating
02. Original Sacrificial Anode
03. Original Impressed Current
04. Fiberglass
05. Jacketed
06. Wrapped (Piping)
07 Retrofitted Sacrificial Anode
08. Retrofitted Impressed Current
09. Urethane
99. Other-Please list:*

Tank Secondary Containment (11)

00. None
01. Diking (AST Only)
02. Vault (w/access)
03. Vault (w/o access)
04. Double-Walled (UST Only)
05. Synthetic Liner
06. Remote Impounding Area
07. Excavation Liner
09. Modified Double-Walled (AST Only)
10. Impervious Underlayment (AST Only)**
11. Double Bottom (AST Only)**
12. Double-Walled (AST Only)
99. Other - Please List:*

Tank Leak Detection (12)

00. None
01. Interstitial Electronic Monitoring
02. Interstitial Manual Monitoring
03. Vapor Well
04. Groundwater Well
05. In-Tank System (Auto Tank Gauge)
06. Impervious Barrier/Concrete Pad (AST Only)
07. Statistical Inventory Reconciliation (SIR)
08. Weep holes in vaults with no access for inspection.
99. Other-Please list:*

Overfill Protection (13)

00. None
01. Float Vent Valve
02. High Level Alarm
03. Automatic Shut-Off
04. Product Level Gauge (AST)
05. Vent Whistle
99. Other-Please list:*

Spill Prevention (14)

00. None
01. Catch Basin
99. Other-Please list:*

Pumping/Dispensing Method (15)

00. None
01. Presurized Dispenser
02. Suction Dispenser
03. Gravity
04. On-Site Heating System (Suction)
05. On-Site Heating System (Supply/Return)
06. Tank-Mounted Dispenser
07. Loading Rack/Transfer Pump

Piping Location (16)

00. No Piping
01. Aboveground
02. Underground/On-ground
03. Aboveground/Underground Combination

Piping Type (17)

00. None
01. Steel/Carbon Steel/Iron
02. Galvanized Steel
03. Stainless Steel Alloy
04. Fiberglass Coated Steel
05. Steel Encased in Concrete
06. Fiberglass Reinforced Plastic (FRP)
07. Plastic
08. Equivalent Technology
09. Concrete
10. Copper
11. Flexible Piping
99. Other-Please list:*

Piping Secondary Containment (19)

00. None
01. Diking (Aboveground Only)
02. Vault (w/access)
04. Double-Walled (Underground Only)
06. Remote Impounding Area
07. Trench Liner
12. Double-Walled (Aboveground Only)
99. Other - Please List:*

Pipe Leak Detection (20)

00. None
01. Interstitial Electronic Monitoring
02. Insterstitial Manual Monitoring
03. Vapor Well
04. Groundwater Well
07. Pressurized Piping Leak Detector
09. Exempt Suction Piping
10. Statistical Inventory Reconciliation (SIR)
99. Other-Please list:*

Under Dispenser Containment (UDC) (21)

Check Box if Present _____

* If other, please list on a separate sheet including tank number,

** Each of these codes must be combined with code 01 or 06 to meet compliance requirements.

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

Division of Environmental Permits, Region 5
1115 State Route 86, PO Box 296, Ray Brook, NY 12977-0296
P: (518) 897-1234 | F: (518) 897-1394
www.dec.ny.gov

Sent Via Email Only

April 21, 2021

Village of Saranac Lake
39 Main Street
Saranac Lake, NY 12983

Re: Facility: Chesterfield Water Treatment Facility
SPDES No. NY 025 6536
DEC No. 5-1646-00351/00002
Chesterfield (T), Essex County

Dear Honorable Rabideau:

Enclosed is your State Pollutant Discharge Elimination System (SPDES) Permit and associated conditions. Please refer to Permit Conditions for appropriate effluent limits, monitoring requirements, and other conditions.

The Department maintains authority regarding the terms of this permit in accordance with 6 NYCRR 750. This regulation may be accessed from the internet at the Department's website at: http://www.dec.ny.gov/regs/2485.html. If you do not have website access, you may obtain a paper copy of the regulation at the above address and phone number.

If you should have any questions concerning any aspect of this permit, please contact Kelly Duval of our Regional Water Quality staff at (518) 897-1241.

Any questions regarding the annual SPDES fee should be addressed to the Regulatory Fee Determination Unit at (800) 225-2566.

Sincerely,

Erin L. Burns
Deputy Regional Permit Administrator

ELB:RAS
Enclosure

ec: Rob Streeter, RWM
Kelly Duval, DEC Water
Cheri Jamison, BWP Permit Coordinator
Marlene Martin, DOH
EPA Region II
NEIWPCC

NEW YORK STATE OF OPPORTUNITY | Department of Environmental Conservation

State Pollutant Discharge Elimination System (SPDES) DISCHARGE PERMIT

SIC Code:	**9111**	NAICS Code:	**92110**	SPDES Number:	**NY 0256536**
Discharge Class (CL):	**04**			DEC Number:	**5-1646-00351/00002**
Toxic Class (TX):	**N**			Effective Date (EDP):	**06/01/2021**
Major-Sub Drainage Basin:	**10 - 03**			Expiration Date (ExDP):	**05/31/2026**
Water Index Number:	**C-15 (Portion 6)**	Item No.:	**830-61**	Modification Dates (EDPM):	
Compact Area:	**NEIWPCC**				

This SPDES permit is issued in compliance with Title 8 of Article 17 of the Environmental Conservation Law of New York State and in compliance with the Clean Water Act, as amended, (33 U.S.C. '1251 et.seq.)

PERMITTEE NAME AND ADDRESS					
Name:	**Village of Saranac Lake**	Attention:	**Clyde Rabideau, Mayor** **John Sweeney, Manager**		
Street:	**39 Main Street**				
City:	**Saranac Lake**	State:	**NY**	Zip Code:	**12983**
Email:	**mayorrabideau@saranaclakeny.gov** **manager@saranaclakeny.gov**	Phone:	**(518)891-4150**		

is authorized to discharge from the facility described below:

FACILITY NAME, ADDRESS, AND PRIMARY OUTFALL														
Name:	**3 Main St. Building Heat Pump**													
Address / Location:	**3 Main Street**											County:	**Franklin**	
City:	**Saranac Lake**						State:	**NY**				Zip Code:	**12983**	
Facility Location:		Latitude:	**44**	°	**19**	’	**27**	” N	& Longitude:	**74**	°	**07**	’	**55** ” W
Primary Outfall No.:	**001**	Latitude:	**44**	°	**19**	’	**28**	” N	& Longitude:	**74**	°	**07**	’	**55** ” W
Wastewater Description:	**Noncontact cooling water**		Receiving Water:		**Saranac River**		NAICS:	**92110**			Class:	**C(T)**		

in accordance with: effluent limitations; monitoring and reporting requirements; other provisions and conditions set forth in this permit; and 6 NYCRR Part 750-1 and 750-2.

This permit and the authorization to discharge shall expire on midnight of the expiration date shown above and the permittee shall not discharge after the expiration date unless this permit has been renewed or extended pursuant to law. To be authorized to discharge beyond the expiration date, the permittee shall apply for permit renewal not less than 180 days prior to the expiration date shown above.

DISTRIBUTION:
Rob Streeter, RWM
Kelly Duval, DEC Water
Cheri Jamison, CO BWP
Marlene Martin, DOH
EPA Region II
NEIWPCC

Permit Administrator:	Erin L. Burns		
Address:	1115 St Route 86, PO Box 296, Ray Brook, NY 12977		
Signature:	Erin L. Burns	Date:	04/21/2021

Contents

DEFINITIONS FOR PERMIT LIMITS, LEVELS AND MONITORING TERMS 3
PERMIT LIMITS, LEVELS AND MONITORING 4
SPECIAL CONDITIONS 4
DISCHARGE NOTIFICATION REQUIREMENTS 5
MONITORING LOCATIONS 6
GENERAL REQUIREMENTS 7
RECORDING, REPORTING AND ADDITIONAL MONITORING REQUIREMENTS 8

DEFINITIONS FOR PERMIT LIMITS, LEVELS AND MONITORING TERMS

TERM	DEFINITION
7-Day Geo Mean	The highest allowable geometric mean of daily discharges over a calendar week.
7-Day Average	The average of all daily discharges for each 7-days in the monitoring period. The sample measurement is the highest of the 7-day averages calculated for the monitoring period.
12-Month Rolling Average (12 MRA)	The current monthly value of a parameter, plus the sum of the monthly values over the previous 11 months for that parameter, divided by 12.
30-Day Geometric Mean	The highest allowable geometric mean of daily discharges over a calendar month, calculated as the antilog of: the sum of the log of each of the daily discharges measured during a calendar month divided by the number of daily discharges measured during that month.
Action Level	Action level means a monitoring requirement characterized by a numerical value that, when exceeded, triggers additional permittee actions and department review to determine if numerical effluent limitations should be imposed.
Compliance Level / Minimum Level	A compliance level is an effluent limitation. A compliance level is given when the water quality evaluation specifies a Water Quality Based Effluent Limit (WQBEL) below the Minimum Level. The compliance level shall be set at the Minimum Level (ML) for the most sensitive analytical method as given in 40 CFR Part 136, or otherwise accepted by the Department.
Daily Discharge	The discharge of a pollutant measured during a calendar day or any 24-hour period that reasonably represents the calendar day for the purposes of sampling. For pollutants expressed in units of mass, the 'daily discharge' is calculated as the total mass of the pollutant discharged over the day. For pollutants with limitations expressed in other units of measurement, the 'daily discharge' is calculated as the average measurement of the pollutant over the day.
Daily Maximum	The highest allowable Daily Discharge.
Daily Minimum	The lowest allowable Daily Discharge.
Effective Date of Permit (EDP or EDPM)	The date this permit is in effect.
Effluent Limitations	Effluent limitation means any restriction on quantities, quality, rates and concentrations of chemical, physical, biological, and other constituents of effluents that are discharged into waters of the state.
Expiration Date of Permit (ExDP)	The date this permit is no longer in effect.
Instantaneous Maximum	The maximum level that may not be exceeded at any instant in time.
Instantaneous Minimum	The minimum level that must be maintained at all instants in time.
Monthly Average	The highest allowable average of daily discharges over a calendar month, calculated as the sum of each of the daily discharges measured during a calendar month divided by the number of daily discharges measured during that month.
Outfall	The terminus of a sewer system, or the point of emergence of any waterborne sewage, industrial waste or other wastes or the effluent therefrom, into the waters of the State.
Range	The minimum and maximum instantaneous measurements for the reporting period must remain between the two values shown.
Receiving Water	The classified waters of the state to which the listed outfall discharges.
Sample Frequency / Sample Type / Units	See NYSDEC's "DMR Manual for Completing the Discharge Monitoring Report for the SPDES" for information on sample frequency, type and units.

PERMIT LIMITS, LEVELS AND MONITORING

OUTFALL	LIMITATIONS APPLY	RECEIVING WATER	EFFECTIVE	EXPIRING
001	All year	Saranac River	06/01/2021	05/31/2026

PARAMETER	EFFLUENT LIMITATION					MONITORING REQUIREMENTS				FN
	Type	Limit	Units	Limit	Units	(minimum) Sample Frequency	Sample Type	Location		
								Inf.	Eff.	
Flow	Monthly Average	Monitor	GPD			2 per month	Meter or gauge		X	1
Temperature	Daily Maximum	70	ºF			2 per month	Grab or sensor		X	1

FOOTNOTES:

1. Monitoring data shall be recorded and five years of data be maintained.

SPECIAL CONDITIONS

The discharge of refrigerants, antifreeze, lubrication oils, corrosion inhibitors and any other type of treatment chemical in water that is discharged through outfall 001 to the receiving water is prohibited.

DISCHARGE NOTIFICATION REQUIREMENTS

(a) The permittee shall install and maintain identification signs at all outfalls to surface waters listed in this permit, unless the Permittee has obtained a waiver in accordance with the Discharge Notification Act (DNA). Such signs shall be installed before initiation of any discharge.

(b) Subsequent modifications to or renewal of this permit does not reset or revise the deadline set forth in (a) above, unless a new deadline is set explicitly by such permit modification or renewal.

(c) The Discharge Notification Requirements described herein do not apply to outfalls from which the discharge is composed exclusively of storm water, or discharges to ground water.

(d) The sign(s) shall be conspicuous, legible and in as close proximity to the point of discharge as is reasonably possible while ensuring the maximum visibility from the surface water and shore. The signs shall be installed in such a manner to pose minimal hazard to navigation, bathing or other water related activities. If the public has access to the water from the land in the vicinity of the outfall, an identical sign shall be posted to be visible from the direction approaching the surface water.

The signs shall have **minimum** dimensions of eighteen inches by twenty-four inches (18" x 24") and shall have white letters on a green background and contain the following information:

N.Y.S. PERMITTED DISCHARGE POINT

SPDES PERMIT No.: NY_____

OUTFALL No. :____

For information about this permitted discharge contact:

Permittee Name: _____

Permittee Contact: _____

Permittee Phone: ( ) - ### - ####

OR:

NYSDEC Division of Water Regional Office Address:

NYSDEC Division of Water Regional Phone: ( ) - ### -####

(e) Upon request, the permittee shall make available electronic or hard copies of the sampling data to the public. In accordance with the RECORDING, REPORTING AND ADDITIONAL MONITORING REQUIREMENTS page of your permit, each DMR shall be maintained (either electronically or as a hard copy) on record for a period of five years.


(f) The permittee shall periodically inspect the outfall identification sign(s) in order to ensure they are maintained, are still visible, and contain information that is current and factually correct. Signs that are damaged or incorrect shall be replaced within 3 months of inspection.

(g) If the permittee believes that any outfall which discharges wastewater from the permitted facility meets any of the DNA waiver criteria, notification must be made to the Department's Bureau of Water Permits. Provided there is no objection by the Department, a sign for the involved outfall(s) are not required. This notification must include the facility's name, address, telephone number, contact, permit number, outfall number(s), and reason why such outfall(s) is waived from the requirements of discharge notification. The Department may evaluate the applicability of a waiver at any time and take appropriate measures to assure that the ECL and associated regulations are complied with.

MONITORING LOCATIONS

The permittee shall take samples and measurements, to comply with the monitoring requirements specified in this permit, at the locations(s) specified below:

Effluent: at any point between the heat pump discharge and outfall 001



GENERAL REQUIREMENTS

A. The regulations in 6 NYCRR Part 750 are hereby incorporated by reference and the conditions are enforceable requirements under this permit. The permittee shall comply with all requirements set forth in this permit and with all the applicable requirements of 6 NYCRR Part 750 incorporated into this permit by reference, including but not limited to the regulations in paragraphs B through H as follows:

B. General Conditions

1.	Duty to comply	6 NYCRR 750-2.1(e) & 2.4
2.	Duty to reapply	6 NYCRR 750-1.16(a)
3.	Need to halt or reduce activity not a defense	6 NYCRR 750-2.1(g)
4.	Duty to mitigate	6 NYCRR 750-2.7(f)
5.	Permit actions	6 NYCRR 750-1.1(c), 1.18, 1.20 & 2.1(h)
6.	Property rights	6 NYCRR 750-2.2(b)
7.	Duty to provide information	6 NYCRR 750-2.1(i)
8.	Inspection and entry	6 NYCRR 750-2.1(a) & 2.3

C. Operation and Maintenance

1.	Proper Operation & Maintenance	6 NYCRR 750-2.8
2.	Bypass	6 NYCRR 750-1.2(a)(17), 2.8(b) & 2.7
3.	Upset	6 NYCRR 750-1.2(a)(94) & 2.8(c)

D. Monitoring and Records

1.	Monitoring and records	6 NYCRR 750-2.5(a)(2), 2.5(a)(6), 2.5(c)(1), 2.5(c)(2), & 2.5(d)
2.	Signatory requirements	6 NYCRR 750-1.8 & 2.5(b)

E. Reporting Requirements

1.	Reporting requirements for non-POTWs	6 NYCRR 750-2.5, 2.6, 2.7, &1.17
2.	Anticipated noncompliance	6 NYCRR 750-2.7(a)
3.	Transfers	6 NYCRR 750-1.17
4.	Monitoring reports	6 NYCRR 750-2.5(e)
5.	Compliance schedules	6 NYCRR 750-1.14(d)
6.	24-hour reporting	6 NYCRR 750-2.7(c) & (d)
7.	Other noncompliance	6 NYCRR 750-2.7(e)
8.	Other information	6 NYCRR 750-2.1(f)

F. Sludge Management

The permittee shall comply with all applicable requirements of 6 NYCRR Part 360.

G. SPDES Permit Program Fee

The permittee shall pay to the Department an annual SPDES permit program fee within 30 days of the date of the first invoice, unless otherwise directed by the Department, and shall comply with all applicable requirements of ECL 72-0602 and 6 NYCRR Parts 480, 481 and 485. Note that if there is inconsistency between the fees specified in ECL 72-0602 and 6 NYCRR Part 485, the ECL 72-0602 fees govern.

H. Water Treatment Chemicals (WTCs)

New or increased use and discharge of a WTC requires prior Department review and authorization. At a minimum, the permittee must notify the Department in writing of its intent to change WTC use by submitting a completed *WTC Notification Form* for each proposed WTC. The Department will review that submittal and determine if a SPDES permit modification is necessary or whether WTC review and authorization may proceed outside of the formal permit administrative process. The majority of WTC authorizations do not require SPDES permit modification. In any event, use and discharge of a WTC shall not proceed without prior authorization from the Department. Examples of WTCs include biocides, coagulants, conditioners, corrosion inhibitors, defoamers, deposit control agents, flocculants, scale inhibitors, sequestrants, and settling aids.

1. WTC use shall not exceed the rate explicitly authorized by this permit or otherwise authorized in writing by the Department.
2. The permittee shall maintain a logbook of all WTC use, noting for each WTC the date, time, exact location, and amount of each dosage, and, the name of the individual applying or measuring the chemical. The logbook must also document that adequate process controls are in place to ensure that excessive levels of WTCs are not used.
3. The permittee shall submit a completed WTC Annual Report Form each year that they use and discharge WTCs. This form shall be submitted in electronic format and attached to either the December DMR or the annual monitoring report required below. The *WTC Notification Form and WTC Annual Report Form* are available from the Department's website at: http://www.dec.ny.gov/permits/93245.html

RECORDING, REPORTING AND ADDITIONAL MONITORING REQUIREMENTS

A. The monitoring information required by this permit shall be retained for a period of at least five years from the date of the sampling for subsequent inspection by the Department or its designated agent.

B. Annual SPDES Monitoring Reports: An annual report shall be submitted to the Department by February 1st each year. The report shall summarize information for January to December of the previous year and shall be submitted **electronically** utilizing the SPDES Annual Report Form available on the Department's website.

Electronic submission of the Annual Report shall be submitted to the Regional Water Manager at the email address below: *(please specify Division of Water as recipient, and indicate county and name of facility in email subject line)*

fax.rayb.eq@dec.ny.gov
Department of Environmental Conservation
Regional Water Manager, Region 5
232 Golf Course Road, Warrensburg, New York, 12885-1172 Phone: (518) 623-1200

C. Monitoring and analysis shall be conducted using sufficiently sensitive test procedures approved under 40 CFR Part 136, unless other test procedures have been specified in this permit.

D. More frequent monitoring of the discharge(s), monitoring point(s), or waters of the State than required by the permit, where analysis is performed by a certified laboratory or where such analysis is not required to be performed by a certified laboratory, shall be included in the calculations and recording of the data on the corresponding DMRs.

E. Calculations which require averaging of measurements shall utilize an arithmetic mean unless otherwise specified in this permit.

F. Unless otherwise specified, all information recorded on the DMRs shall be based upon measurements and sampling carried out during the most recently completed reporting period.

G. Any laboratory test or sample analysis required by this permit for which the State Commissioner of Health issues certificates of approval pursuant to section 502 of the Public Health Law shall be conducted by a laboratory which has been issued a certificate of approval. Inquiries regarding laboratory certification should be directed to the New York State Department of Health, Environmental Laboratory Accreditation Program.

CK Tank And Line Testing, LLC

3836 STATE ROUTE 85
WESTERLO, NY 12193
518-756-3439
cktanktesting@gmail.com

Invoice # 2587

Date: 9-22-21

Service Performed at	Bill To (if different)
SARANAC LAKE POLICE DEPT. 3 MAIN ST. SARANAC LAKE, NY 12983	VILLAGE OF SARANAC LAKE 39 MAIN ST. SUITE 9 SARANAC LAKE, NY 12983
Phone:	Phone:
PO# / Customer Order #:	Terms:

QTY	Work Performed Description:	Unit Price	Total Price
1	CORROSION PROTECTION TEST ON 2,000 GAL. UNDERGROUND FUEL OIL STORAGE TANK		380.00


Thank You!

Total Labor	$ 380.00
Total Material	$ —
Tax %	$ —
Travel/Mileage	$
Total Amount Due	$ 380.00

CORROSION PROTECTION TESTING FORM
UNDERGROUND STORAGE TANK (UST)

Facility Name VILLAGE OF SARANAC LAKE
Address POLICE DEPT.
3 MAIN ST.
SARANAC LAKE, NY 12985

(UST) Facility ID# 5-416703
Test Date 9-22-21



PLAN Test Locations
N.T.S.(1, 2, 3)
Note: Minimum Test Locations

Testing Company
CK Tank & Line Testing, LLC
3836 State Route 85
Westerlo, NY 12193
Phone (518) 756-3439
cktanktesting@gmail.com

Equipment used to test: High Impedence Volt Meter and Copper Sulfate Electrode and Associated Test Leads

Sacrificial or Impressed System (circle one) N/A - Not Applicable

RESULTS SYSTEM No. 003 PRODUCT #2 FUEL OIL SIZE 2,000 GAL

Test Locations	1	2	3	4	5	6	7	8	9	10	11
Reading -MV	-1070	-1049	-1046	-1059	-1069	-1067	-1063	-1042	-1044		-1066
Native Voltage											
Instant Off											
Polarization (Mv)											

Corrosion Protection: TANK (PASS or FAIL or N/A) Circle - PIPING TANK (PASS or FAIL or N/A) Remote

RESULTS SYSTEM No. PRODUCT SIZE

Test Locations	1	2	3	4	5	6	7	8	9	10	11
Reading											
Native Voltage											
Instant Off											
Polarization (Mv)											

Corrosion Protection: TANK (PASS or FAIL or N/A) Circle - PIPING TANK (PASS or FAIL or N/A) Remote

Comments / Recommendations:

I hereby certify I am a qualified cathodic protection tester who has an understanding of the principles and measurements of all common types of techniques used to prevent corrosion of a metal surface by making that surface the cathode of an electrochemical cell as applied to buried piping and tank systems.

Name of tester (print): Chris Parks

Signature: Chris Parks Date: 9-22-21

Attach any additional information

Mary Legawiec

From: Kip Cassavaw <Kip.Cassavaw@franklincountyny.gov>
Sent: Tuesday, July 25, 2023 2:57 PM
To: Mary Legawiec
Cc: Foil; Jessica Pryce; Lynn Humphries
Subject: FW: FOIL Request - 3 East Main Street, Saranac Lake
Attachments: Franklin County Request.docx

Follow Up Flag: Follow up
Flag Status: Flagged

This message originated from outside your organization

Good Afternoon,

I am in receipt of your FOIL request dated July 25, 2023 and received via email in this office on July 25, 2023.

The records in the Franklin County Clerk's Office are indexed by name and NOT location, therefore any request for records based upon an address cannot be completed. Also, please not that the records in the Franklin County Clerk's Office are public records and are therefore not subject to FOIL. You can come into the office anytime between the hours of 8 am and 4 pm, Monday thru Friday, and search the records on the computers or in the index books.

With that being said, I believe the records that you are searching for would be with the New York State Department of Environment Conservation, the Town of Harrietstown or the Village of Saranac Lake.

Please accept this email as my office's response to your FOIL request and should you have any further questions, please let me know.

Kip Cassavaw
Franklin County Clerk
355 West Main Street, Suite 248
PO Box 70
Malone, NY 12953

From: Mary Legawiec <mlegawiec@BERGMANNPC.com>
Sent: Tuesday, July 25, 2023 12:29 PM
To: Kip Cassavaw <Kip.Cassavaw@franklincountyny.gov>
Subject: FOIL Request - 3 East Main Street, Saranac Lake

WARNING - This email was sent from outside of this organization. Take care when opening links or attachments from external sources.

Good afternoon Mr. Cassavaw,

Attached please find a FOIL request for a Property located at 3 East Main Street, Saranac Lake, New York. Please reach out if you have any questions.

Thank you,

Mary Legawiec, MSc | Environmental Scientist
585.498.7820 | mlegawiec@bergmannpc.com

BERGMANN
Architects | Engineers | Planners
280 E Broad Street #200, Rochester, NY 14604
www.bergmannpc.com

Bergmann has joined Colliers Engineering & Design!

Village of Saranac Lake

Parcel History

01/01/1950 - 07/24/2023
Tax Map #: 458.21-2-1
Owners: Village Of Saranac Lake
Zoning: E2

Address	Date	Transaction	Transaction Type	Status	Description
1-3 Main St	06/15/09	Permit Application	Temporary Sign	Issued	2009-S04 | Chamber 4th - 5th of July Activities Sandwich Board Sign placed in NBT Triangle, Pine St., Urgent Care, Riverside Park, Berkley Square, & Church St. Vets Memorial on 6/15/09. To be removed 07/06/09.
1-3 Main St	06/15/09	Inspection	Condition 1	Passed Electrical	
1-3 Main St	07/06/09	Closed Permit	Temporary Sign	Closed	2009-S04 | Chamber 4th - 5th of July Activities Sandwich Board Sign placed in NBT Triangle, Pine St., Urgent Care, Riverside Park, Berkley Square, & Church St. Vets Memorial on 6/15/09. To be removed 07/06/09.
1-3 Main St	07/06/09	Inspection	Final Inspection	<None>	
1-3 Main St	09/30/09	Permit Application	Temporary Sign	Issued	2009-S14 | Pumpkin Fest Sandwich Boards at: Pine & Rte. 3, Rte. 86 & Trudeau Rd., NBT Bank Triangle, Rte. 3 & Rte. 30, Donnelly Corner, & Rte. 186 & Airport Rd. until 10/11/09.
1-3 Main St	10/12/09	Closed Permit	Temporary Sign	Closed	2009-S14 | Pumpkin Fest Sandwich Boards at: Pine & Rte. 3, Rte. 86 & Trudeau Rd., NBT Bank Triangle, Rte. 3 & Rte. 30, Donnelly Corner, & Rte. 186 & Airport Rd. until 10/11/09.
1-3 Main St	11/18/09	Permit Application	Temporary Sign	Issued	2009-S22 | 1 each 3' x 4' Sandwich sign at NBT Triangle.
1-3 Main St	12/07/09	Closed Permit	Temporary Sign	Closed	2009-S22 | 1 each 3' x 4' Sandwich sign at NBT Triangle.
1-3 Main St	12/09/09	Permit Application	Temporary Sign	Issued	2009-S27 | 5 Banners throughout the Village for 1st Night from 12/14/09 - 01/04/10.
1-3 Main St	01/04/10	Closed Permit	Temporary Sign	Closed	2009-S27 | 5 Banners throughout the Village for 1st Night from 12/14/09 - 01/04/10.
1-3 Main St	07/27/10	Permit Application	Temporary Sign	Issued	Temp-2010-008 | Temporary Sign- Riverside Park Denny Park William Morris Park NBT Triangle July 24 to August 6

Village of Saranac Lake

Parcel History

Address	Date	Transaction	Transaction Type	Status	Description
1-3 Main St	08/30/10	Permit Application	Temporary Sign	Issued	Temp-2010-011 | Temporary Signage, Ampersand/Broadway,Riverside Park,NBT Bank triangle,Church/Bloomingdale Ave Todd Smith/7444 Gallery, 28 Depot St
1-3 Main St	09/07/10	Closed Permit	Temporary Sign	Closed	Temp-2010-011 | Temporary Signage, Ampersand/Broadway,Riverside Park,NBT Bank triangle,Church/Bloomingdale Ave Todd Smith/7444 Gallery, 28 Depot St
1-3 Main St	09/30/10	Closed Permit	Temporary Sign	Closed	Temp-2010-008 | Temporary Sign- Riverside Park Denny Park William Morris Park NBT Triangle July 24 to August 6
1-3 Main St	11/24/10	Permit Application	Comm Repair, Alt, Add	Issued	BP-2010-119 | Water Plant Insulation and electrical work
1-3 Main St	01/26/11	Inspection	Insulation Inspection	Passed Inspection	
1-3 Main St	06/29/11	Project	Site Plan	Approved with	2011-P008 | Special Use permit to operate a Bio-Science business at 3 Main Street.
1-3 Main St	10/18/11	Inspection	Final Inspection	Passed Inspection	
1-3 Main St	10/18/11	Completed Permit	Comm Repair, Alt, Add	Completed	BP-2010-119 | Water Plant Insulation and electrical work | Certificate of Occupancy #BP-2010-119
1-3 Main St	03/16/12	Permit Application	Comm Repair, Alt, Add	Issued	BP-2012-014 | TEMPORARY PERMIT issued pending finalization of paperwork. Permit expires September 7, 2012 Interior Demolition, HVAC, Windows and doors, Elevator rehab
1-3 Main St	04/05/12	Permit Application	Comm Repair, Alt, Add	Issued	BP-2012-021 | - Alterations to existing building -interior non-loadbearing partitions - fire -alarm system -electrical -plumbing
1-3 Main St	07/09/12	Inspection	HVAC Inspection	Passed Inspection	
1-3 Main St	07/10/12	Inspection	Special Inspection	Passed Inspection	

Village of Saranac Lake

Parcel History

Address	Date	Transaction	Transaction Type	Status	Description
1-3 Main St	07/19/12	Inspection	Framing Inspection	Passed Inspection	
1-3 Main St	07/19/12	Inspection	Plumbing Inspection	Passed Inspection	
1-3 Main St	07/19/12	Inspection	Special Inspection	Passed Inspection	
1-3 Main St	07/30/12	Inspection	Final Electrical Inspection	Passed Inspection	
1-3 Main St	08/08/12	Inspection	Final Electrical Inspection	Passed Inspection	
1-3 Main St	08/08/12	Inspection	Plumbing Inspection	Passed Inspection	
1-3 Main St	08/08/12	Inspection	Final Inspection	Passed Inspection	
1-3 Main St	08/08/12	Temporary Permit	Comm Repair, Alt, Add	Temporary	BP-2012-014 | TEMPORARY PERMIT issued pending finalization of paperwork. Permit expires September 7, 2012 Interior Demolition, HVAC, Windows and doors, Elevator rehab | Expires 09/08/2012
1-3 Main St	08/08/12	Inspection	Final Inspection	Passed Inspection	
1-3 Main St	08/08/12	Inspection	HVAC Inspection	Passed Inspection	
1-3 Main St	09/28/12	Completed Permit	Comm Repair, Alt, Add	Completed	BP-2012-021 | - Alterations to existing building -interior non-loadbearing partitions - fire -alarm system -electrical -plumbing | Certificate of Occupancy #BP-2012-021
1-3 Main St	11/08/12	Permit Application	Temporary Sign	Issued	Temp-2012-031 | Temporary Signs Banners- Morris Park & Ampersand Park December 10 to January 10
1-3 Main St	01/24/13	Closed Permit	Temporary Sign	Closed	Temp-2012-031 | Temporary Signs Banners- Morris Park & Ampersand Park December 10 to January 10
1-3 Main St	12/09/13	Permit Application	Temporary Sign	Issued	Temp-2013-024 | Temporary Signs: Ampersand Park, William Morris Park, Petrova Bridge First Night December 9 to January 9, 2014

Village of Saranac Lake

Parcel History

Address	Date	Transaction	Transaction Type	Status	Description
1-3 Main St	10/01/14	Permit Application	Blasting	Issued	2014-001 | Drill and blast trench rock for the reconstruction of the sewer. Drill a 3" hole on a 4' x 4' staggered pattern. Prime blast holes with high explosives and brought to the proper load depth using blasting agents or emulsion depending on dryness/wetness of blast hole. Perform blasting using detonators, extra gelatin dynamite and blasting agent. Initiate blast electronically. Blasting mats will be used. Load weights will vary by hole depth from 1.0 lbs per delay up to 5.0 lbs per delay. Holes will be stemmed to the top with #1 crushed stone. All blasting is to be done by a qualified person who has a valid licensed to handle explosives. All work is to be done accordance with the safety plan, specifications, drawings and as agreed upon by the VSL Engineer AES Northeast. Blasting will take place on 10/8/2014 & 10/9/2014 between 8:00AM to 4:00PM. Siren shall be sounded prior to each blast.
1-3 Main St	10/01/14	Permit	Blasting	Open	2014-001 | Drill and blast trench rock for the reconstruction of the sewer. Drill a 3" hole on a 4' x 4' staggered pattern. Prime blast holes with high explosives and brought to the proper load depth using blasting agents or emulsion depending on dryness/wetness of blast hole. Perform blasting using detonators, extra gelatin dynamite and blasting agent. Initiate blast electronically. Blasting mats will be used. Load weights will vary by hole depth from 1.0 lbs per delay up to 5.0 lbs per delay. Holes will be stemmed to the top with #1 crushed stone. All blasting is to be done by a qualified person who has a valid licensed to handle explosives. All work is to be done accordance with the safety plan, specifications, drawings and as agreed upon by the VSL Engineer AES Northeast. Blasting will take place on 10/8/2014 & 10/9/2014 between 8:00AM to 4:00PM. Siren shall be sounded prior to each blast. | Expires 11/01/2014

Village of Saranac Lake

Parcel History

Address	Date	Transaction	Transaction Type	Status	Description
1-3 Main St	05/29/15	Project	Land Use Text Amendment	Withdrawn	2015-DA01 | Amendment to Flood Damage Prevention Law
1-3 Main St	11/20/15	Permit Application	Floodplain Dev. Permit	Issued	FDP-2015-002 | Removal of existing stone retaining wall with precast block retaining wall in accordance with submitted plans and NYS Building Codes.
1-3 Main St	12/31/15	Completed Permit	Floodplain Dev. Permit	Completed	FDP-2015-002 | Removal of existing stone retaining wall with precast block retaining wall in accordance with submitted plans and NYS Building Codes. | Certificate of Compliance #FDP-2015-002
1-3 Main St	01/02/18	Closed Permit	Temporary Sign	Closed	Temp-2013-024 | Temporary Signs: Ampersand Park, William Morris Park, Petrova Bridge First Night December 9 to January 9, 2014
1-3 Main St	10/08/19	Permit Application	Comm Repair, Alt, Add	Issued	BP-2019-105 | Conversion of office space aas per submitted plans. All work to be completed in accordance with the Uniform Code.
1-3 Main St	10/08/19	Permit	Comm Repair, Alt, Add	Open	BP-2019-105 | Conversion of office space aas per submitted plans. All work to be completed in accordance with the Uniform Code. | Expires 01/08/2021
1-3 Main St	07/04/23	Permit Application	Fireworks	Issued	Fireworks-2023-003 | Fireworks display to be set off from lot 4 riverstreet in the village of Saranac Lake
1-3 Main St	07/05/23	Inspection	Final Inspection	Passed Inspection	
1-3 Main St	07/05/23	Closed Permit	Fireworks	Closed	Fireworks-2023-003 | Fireworks display to be set off from lot 4 riverstreet in the village of Saranac Lake

PBS Number:
5-416703

Section B - Tank Information

(Please use the key located on the last page to complete each item/column)

Registration Expiration Date:
10/2/2022

(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)	(14)	(15)	(16)	(17)	(18)	(19)	(20)	(21)
Action	Tank Number	Tank Location	Status	Installation, out-of-service, or Permanent ClosureDate (mm/dd/yyyy) **Application will be returned if blank**	Capacity (Gallons)	Product Stored (If Gasoline w/ethanol or Biodiesel, list % additive) %	Tank Type	Tank Internal Protection	Tank External Protection	Tank Secondary Containment	Tank Leak Detection	Tank Overfill Prevention	Tank Spill Prevention	Pumping/Dispensing Method	Piping Location	Piping Type	Piping External Protection	Piping Secondary Containment	Piping Leak Detection	Under Dispenser Containment (UDC) (Check box if present)
	003	5	1	11/1/1994	2,000	0001	04	00	02 04	04	02	05	01	05	03	10	05	00	00	☐
	004	3	1	8/30/2012	165	0008	07	00	05	12	02	04 05	00	02	01	10	00	00	00	☐

Note: If you need to add tanks to your registration, write them in using blank lines above. Attach additional sheets as needed.
Blank Section B is available at http:/www.dec.ny.gov/docs/remediation_hudson_pdf/pbsrenewal.pdf

New York State Department of Environmental Conservation
Division of Environmental Remediation

Petroleum Bulk Storage Application

Pursuant to the Environmental Conservation Law: Article 17, Title 10; and
Regulations 6 NYCRR Part 613 and 6 NYCRR Subpart 374-2

(Please Type or Print Clearly and Complete All Items for Sections A, B & C)

PBS Number:
5-416703

Return Completed Form & Fees To:
NYSDEC Region 5
P.O. Box 296
1115 State Route 86
Ray Brook, NY 12977-0296
(518) 897-1241

Expiration Date: 10/02/2022

Section A - Facility/Property Owner/Contact Information

Transaction Type: 5

1) Initial/New Facility
2) Change of Ownership
3) Tank Installation, Closing, or Repair
4) Information Correction
5) Renewal

FACILITY

Facility Name: VILLAGE SARANAC LAKE

Tax Map: Borough/Section 458; Block 2; Lot 1

Facility Address (Physical Address, No P.O. Boxes): 3 MAIN STREET

Facility Address (cont.):

City: SARANAC LAKE

State: NY ZIP Code: 12983

County: Franklin

Township or City: Harrietstown

Facility Phone Number: (518) 891-4160

Facility Operator: DUSTIN MARTIN

TYPE OF PETROLEUM FACILITY (Check only one)

- [ ] 01=Storage Terminal/Petrol. Distributor
- [ ] 02=Retail Gasoline Sales
- [ ] 03=Other Retail Sales
- [ ] 04=Manufacturing
- [ ] 05=Utility
- [ ] 06=Trucking/Transportation/Fleet
- [ ] 07=Apartment/Office Building
- [ ] 08=School
- [ ] 09=Farm
- [ ] 10=Private Residence
- [ ] 11=Airline/Air Taxi/Airport
- [ ] 12=Chemical Distributor
- [x] 13=Municipality
- [ ] 15=Railroad
- [ ] 25=Auto Service/Repair (No Gasoline
- [ ] 28=Cemetery/Memorial
- [ ] 26=Religious (Church, Synagogue, Mosque, Temple, etc.)
- [ ] 27=Hospital/Nursing Home/Health Care
- [ ] 52=Marina
- [ ] 53=Nuclear Power Plant
- [ ] 99=Other (Specify):

Emergency Contact Name: DUSTIN MARTIN

Emergency Telephone Number: (518) 354-0595

NOTE:

Fill in Property Owner information here....>>>

Indicate Tank Owner in Section C.

OWNER

Facility (Property) Owner (from Deed): VILLAGE SARANAC LAKE

Facility Owner Address (Street and/or P.O. Boxes): 39 MAIN STREET

City: SARANAC LAKE

State: NY ZIP Code: 12983

Owner Telephone Number: (518) 891-4150

Type of Owner (check only one):

- 1 [ ] Private Resident
- 2 [ ] State Government
- 3 [x] Local Government
- 4 [ ] Federal Government
- 5 [ ] Corporate/Commercial/Other

I hereby certify, under penalty of law, that all of the information provided on this form is true and correct. False statements made herein may be punishable as a criminal offense and/or a civil violation in accordance with applicable state and federal law.

Name of Property Owner or Authorized Representative: Dustin Martin

Amount Enclosed: $300.00

Title: DPW Superintendent

Signature:

Date: 7/22/2022

Official Use Only
Date Received: ___/___/___
Date Processed: ___/___/___
Amount Received: $_____
Reviewed By: _____

Rev. 6/26/2019

CORRESPONDENCE

(Please keep this information up to date.)

Facility Contact Person Name: VILLAGE MANAGER

Contact Person Company Name: VILLAGE SARANAC LAKE


Address: 39 MAIN STREET

Address (cont.): 2ND FLOOR, SUITE 9

City/State/ZIP Code: SARANAC LAKE, NY 12983

Tel. Number: (518) 891-4150

eMail Address: MANAGER@SARANACLAKENY.GOV



1-3 Main Street 2000 Gallon Underground storage Tank
Village of Saranac Lake (2/12 Inc)

APPENDIX G:

EDR DATABASE SEARCH REPORT

APA HQ - Phase I ESA
13 Main Street
Saranac Lake, NY 12983

Inquiry Number: 7391856.8
July 17, 2023

EDR Building Permit Report

Target Property and Adjoining Properties

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

EDR Building Permit Report: Search Documentation

7/17/23

Site Name:
APA HQ - Phase I
13 Main Street
Saranac Lake, NY

EDR Inquiry # 7391856.8

Client Name:
Bergmann Associates
280 East Broad Street, Suite
Rochester, NY 14604

Contact: Mary K Legawiec

Search Documentation

DATA GAP

The complete collection of Building Permit data available to EDR has been searched, and as of 7/17/23, EDR does not have access to building permits in the city where your target property is located (Saranac Lake, NY).

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED ORIMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THEMAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALLRISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OFERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL,INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLYLIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risklevels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providingany facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by anenvironmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to beconstrued as legal advice.

Copyright 2017 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EDR BUILDING PERMIT REPORT

About This Report

The EDR Building Permit Report provides a practical and efficient method to search building department records for indications of environmental conditions. Generated via a search of municipal building permit records gathered from more than 1,600 cities nationwide, this report will assist you in meeting the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

Building permit data can be used to identify current and/or former operations and structures/features of environmental concern. The data can provide information on a target property and adjoining properties such as the presence of underground storage tanks, pump islands, sumps, drywells, etc., as well as information regarding water, sewer, natural gas, electrical connection dates, and current/former septic tanks.

ASTM and EPA Requirements

ASTM E 1527-13 lists building department records as a "standard historical source," as detailed in § 8.3.4.7: "Building Department Records - The term building department records means those records of the local government in which the property is located indicating permission of the local government to construct, alter, or demolish improvements on the property." ASTM also states that "Uses in the area surrounding the property shall be identified in the report, but this task is required only to the extent that this information is revealed in the course of researching the property itself."

EPA's Standards and Practices for All Appropriate Inquires (AAI) states: "§312.24: Reviews of historical sources of information. (a) Historical documents and records must be reviewed for the purposes of achieving the objectives and performance factors of §312.20(e) and (f). Historical documents and records may include, but are not limited to, aerial photographs, fire insurance maps, building department records, chain of title documents, and land use records."

Methodology

EDR has developed the EDR Building Permit Report through our partnership with BuildFax, the nation's largest repository of building department records. BuildFax collects, updates, and manages building department records from local municipal governments. The database now includes 30 million permits, on more than 10 million properties across 1,600 cities in the United States.

The EDR Building Permit Report comprises local municipal building permit records, gathered directly from local jurisdictions, including both target property and adjoining properties. Years of coverage vary by municipality. Data reported includes (where available): date of permit, permit type, permit number, status, valuation, contractor company, contractor name, and description.

Incoming permit data is checked at seven stages in a regimented quality control process, from initial data source interview, to data preparation, through final auditing. To ensure the building department is accurate, each of the seven quality control stages contains, on average, 15 additional quality checks, resulting in a process of approximately 105 quality control "touch points."

For more information about the EDR Building Permit Report, please contact your EDR Account Executive at (800) 352-0050.

EDR® Environmental Data Resources Inc

BUILD FAX PROPERTY HISTORY

APA HQ - Phase I ESA
13 Main Street
Saranac Lake, NY 12983

Inquiry Number: 7391856.5
July 17, 2023

The EDR-City Directory Image Report

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available business directory data at approximately five year intervals.

RECORD SOURCES

The EDR City Directory Report accesses a variety of business directory sources, including Haines, InfoUSA, Polk, Cole, Bresser, and Stewart. Listings marked as EDR Digital Archive access Cole and InfoUSA records. The various directory sources enhance and complement each other to provide a more thorough and accurate report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer.

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

Year	*Target Street*	*Cross Street*	*Source*
2020	☑	☐	EDR Digital Archive
2017	☑	☐	Cole Information
2014	☑	☐	Cole Information
2010	☑	☐	Cole Information
2005	☑	☐	Cole Information
2000	☑	☐	Cole Information
1995	☑	☐	Cole Information
1992	☑	☐	Cole Information

FINDINGS

TARGET PROPERTY STREET

13 Main Street
Saranac Lake, NY 12983

Year	*CD Image*	*Source*
MAIN ST		
2020	pg A1	EDR Digital Archive
2017	pg A2	Cole Information
2014	pg A4	Cole Information
2010	pg A6	Cole Information
2005	pg A8	Cole Information
2000	pg A11	Cole Information
1995	pg A13	Cole Information
1992	pg A15	Cole Information

FINDINGS

CROSS STREETS

No Cross Streets Identified

City Directory Images

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MAIN ST 2020

1	PLAYERS SPORTS BAR
	SARANAC LAKE VILLAGE POLICE
2	SECTION 8 HOUSING ASSISTANCE
12	LITTLE ITALY INC
17	NORTH STAR CHEM DEPENDENCY
23	JOSEPH HADLOCK
	LITTLE ITALY
38	R E HANPETER ARCHITECT
	R E HANPETER-ARCHITECT
	THOMAS P WARD RL EST
	WIRELESS ZONE-VERIZON AUTH
39	ASSESSOR'S OFFICE
	FRANKLIN COUNTY NY DMV
	HARRIETSTOWN ZONING DEPT
	NEW YORK VETERANS AFFAIRS DIV
	SARANAC LAKE TREASURER'S OFC
	SARANAC LAKE VILLAGE OFFICE
	TOWN CLERK
	TOWN OF HARRIETSTOWN
40	SARANAC LAKE DISC LIQUORS INC
42	AMY PAGE
	COMPASS PRINTING PLUS
	KELLY SCHMIDT
43	ATM
	G CARVER RICE FURNITURE
	GAIL RICE
	RICE FURNITURE
48	JOHN JOINER
49	SARANAC LAKE DISC LIQUORS INC
51	OWL'S NEST PIZZERIA
52	ADIRONDACK ARTISTS GUILD
	ADIRONDACK CENTER FOR WRITING
	AMPERSOUND
53	ATM
	GRIZLE T'S LLC
55	BLUE MOON CAFE
57	AYRES REALTY INC

Target Street	Cross Street	Source
✓	-	Cole Information

MAIN ST 2017

2	SECTION
	VILLAGE OF SARANAC LAKE
3	AMPERSAND BIO LLC LORI
15	CHINA CITY
17	ACTIVE MOTIF
	FRANKLIN COUNTY COMMUNITY SERVICES
	NORTH STAR CHEMICAL DEPENDENCY & PRE
18	GOOD THINGS
23	LAVOY, EVELYN
	LITTLE ITALY PIZZERIA
	PARKER, SEAN
27	LITTLE ITALY PIZZERIA INC
30	COUNTY OF FRANKLIN
	TOWN OF HARRIETSTOWN
	VILLAGE OF SARANAC LAKE
33	LAKE PLACID CHRISTMAS COMPANY
38	E HANPETER R AIAARCHITECT
39	TOWN OF HARRIESTOWN
	VILLAGE OF SARANAC LAKE
40	SARANAC LAKE DISCOUNT LIQUORS INC
42	COMPASS PRINTING PLUS
	SANFORD, GEOFFREY
43	RICE FURNITURE
46	BLUE MOON CAFE
47	RICE FURNITURE & FLOORING
48	WATERHOLE MUSIC LOUNGE LLC
51	EASTERN MOUNTAIN SPORTS
	OWLS NEST PIZZERIA
52	ADIRONDACK ARTISTS GUILD
	AMPERSOUND
53	GRIZLES TS
	GRIZLETS LLC
	MINNIE, JASON H
55	BLUE MOON CAFE
	GAP OUTLET
57	AYRES INSURANCE AGENCY INC
	AYRES REALTY INC
59	BAUMANN, JEREMY O
	WILCOX, MARGARET A
	WOLF, STEPHEN H
60	SARANAC LAKE ABSTRACT CO
61	CANDY MAN HOMEMADE ADIRONDACK CHOCOL
	UNITED STATES POSTAL SERVICEUSPS
63	BELLEVILLE & ASSOCIATES
	JUDIS COMPUTER SUPPORT
	SZE, PAK T
65	CHINA JADE
	EDWARD JONES
	SEARS
67	ADIRONDACK BANK

Target Street	Cross Street	Source
✓	-	Cole Information

MAIN ST 2017 (Cont'd)

67	ADIRONDACK ECONOMIC DEVELOPMENT CORP
	ADIRONDACK FINANCIAL SERVICES CORP
	ANCA
	WORKFORCE DEVELOPMENT INSTITUTE
68	EDWARD JONES
	SALON MIRAGE DAY SPA & FITNESS
69	SALON MIRAGE DAY SPA & FITNESS
72	BASS
74	DOWNHILL GRILL
	VAN HEUSEN CORP
75	SARANAC LAKE VOLUNTARY HEALTH ASSN I
77	DEDERICK, NANCY Q
78	LIZ COMPANY LLC
80	CLARK, EMILY
	DEPALMA, JOSEPH
	GORGAS, HANNAH
	LAFOUNTAIN, BRITNEY
81	BLUE LINE SPORT SHOP
	HOMEWARD BOUND
	JAMES E MAHER ATTY
82	BLUE LINE SPORT SHOP
83	ADIRONDACK EYE CENTER
	MCSWEENEY ORTHODONTICS
84	IB HUNT AGENCY
85	BELLEVILLE & ASSOCIATES INC
86	DUNCAN WINTER MD
	ROCKEFELLER, WILLIAM
	SURGICAL EYE CARE
90	GRANVILLE A SMALL DDS
	HEVERLY, MARY
	STARBUCKS COFFEE
	TRILAKES CETER FOR DENTISTRY
100	ADIRONDACK HISTORY ROOM
	SARANAC LAKE FREE LIBRARY

Target Street	Cross Street	Source
✓	-	Cole Information

MAIN ST 2014

2	FRANKLIN COUNTY GOVERNMENT
	RULES BASED MEDICINE
	SARANAC LAKE VILLAGE OF
	SARANAC LAKE VILLAGE OFFICIALS & DEP
	SECTION EIGHT HOUSING ASSISTANCE
7	HARVEY, JOAN A
9	DECLERQUE, STACY
10	SARANAC LAKE VILLAGE OFFICIALS & DEP
17	ACTIVE MOTIF
	FRANKLIN COUNTY COMMUNITY SERVICES
19	BLOCH, JEFFREY
23	LAVOY, EVELYN
	LITTLE ITALY PIZZERIA
	MCCARTHY, SIR R
30	FRANKLIN COUNTY GOVERNMENT
	STATE OF NEW YORK
	TOWN OF HARRIETSTOWN
33	BELAHANT, NICHOLAS
34	RICE, GAIL R
38	R E HANPETER AIAARCHITECT
	WARD THOMAS P RL EST
39	SARANAC LAKE VILLAGE OF
40	SARANAC LAKE DISCOUNT LIQUORS INCORP
42	COMPASS PRINTING PLUS
	HUYCK, JEFFREY M
	OWLS NEST PIZZA PARLOR
	SANFORD, GEOFFREY
43	RICE FURNITURE
46	BLUE MOON CAFE
47	RICE FLOORING
	ROTHE, SEAN F
52	ADIRONDACK ARTISTS GUILD
	AMPERSOUND
53	GRIZLETS LLC
54	CHARRON, CHERRIE
57	AYRES INSURANCE AGENCY INCORPORATED
59	OWENS, JAMES
	WARDEN, LAURA A
	WILCOX, MARGARET A
60	CANTWELL, WILLIAM W
	SARANAC LAKE ABSTRACT COMPANY
61	POST OFFICE PHARMACY
62	OCCUPANT UNKNOWN,
63	DUMAS, LUKE R
	JONES, JAMIE L
	SAY REAL ESTATE
	SZE, HUNG
64	JENKINS, GIGI F
65	CHINA JADE
	NORIS VILLAGE MARKET INCORPORATED

Target Street	Cross Street	Source
✓	-	Cole Information

MAIN ST 2014 (Cont'd)

67	ADIRONDACK BANK
	ADIRONDACK ECONOMIC DEVELOPMENT CORP
	ADIRONDACK FINANCIAL SERVICES CORPOR
	ANCA
	WORKFORCE DEVELOPMENT INSTITUTE
68	EDWARD JONES FINANCIAL ADVISOR MA
69	SALON MIRAGE DAY SPA & FITNESS
74	DOWNHILL GRILL
75	SARANAC LAKE VOLUNTARY HEALTH ASSOCI
76	FORTUNE STUDIO
77	BERRUS, MICHELLE R
	BODAH, CHRISTINE E
78	LIZ COMPANY LLC
79	FINNIGAN T F MENS OUTFITTER
80	LAFOUNTAIN, BRITNEY
	MILLER, KEN M
	SEYMOUR, ROBERT D
81	BLUE LINE SPORT SHOP
	MAHER JAMES E ATTY
83	MCGILL JOHN DDS MS PC
84	IB HUNT AGENCY
86	SURGICAL EYE CARE
90	DR ROGER NEILL
	GREENIER, DAVID L
	SMALL GRANVILLE A DDS
	TRI LAKES CENTER FOR DENTISTRY
91	ZIMNY, FREDERIC W
93	SARANAC LAKE CENTRAL SCHOOL DISTRICT
100	ADIRONDACK HISTORY ROOM
	HOTEL SARANAC
	SARANAC LAKE FREE LIBRARY
102	HOUGH, ERNEST

Target Street	Cross Street	Source
✓	-	Cole Information

MAIN ST 2010

1	SARANAC LAKE POLICE JUSTICE
3	FRANKLIN COUNTY PUBLIC HEALTH
	FRANKLIN COUNTY SOCIAL SVC
	MUNICIPAL GARAGE
	SARANAC LAKE COMMUNITY DEVMNT
	SARANAC LAKE TREASURERS OFC
	SARANAC LAKE VILLAGE MANAGER
7	HARVEY, JOAN A
9	DECLERQUE, STACY
10	SARANAC LAKE WATER DEPT
17	CITIZEN ADVOCATES INC
	NORTH STAR BEHAVIOR HEALTH SVC
19	BLOCH, JEFFREY
23	HUBER, JASON R
	YELLE, BRANDON M
25	WILSON FARMS XPRESS
26	HARE, BRIAN R
27	LITTLE ITALY PIZZERIA INC
30	PLUMADORE, JAN B
	TOWN CLERK
33	BELAHANT, NICHOLAS
34	BAKER, RICE
38	CIGARETTE WAREHOUSESARANAC LK
	GREAT CAMPLAUNDRY
39	ASSESSORS OFFICE
	FRANKLIN COUNTY MOTOR VEHICLE
	HARRIETSTOWN BUILDING DEPT
	HARRIETSTOWN REHAB PROGRAM
	HARRIETSTOWN TOWN SUPERVISOR
	HARRIETSTOWN ZONING DEPT
	HUD PROGRAM
	NEW YORK VETERANS AFFAIRS DIV
	SUPERINTENDENT OF HIGHWAYS
40	SARANAC LAKE DISCOUNT LIQUORS
42	COMPASS PRINTING PLUS
	HUYCK, JEFFREY
	OWLS NEST PIZZA PARLOR
43	RICE FURNITURE
	WATERHOLE
47	PLANNED PARENTHOOD
	RICE FLOORING
	TANZINI, GREGORY L
52	ADIRONDACK ARTISTS GUILD
	BOREALIS COLOR
	HANCOCK, CHARLES A
53	GRIZLE TS LLC
54	CHARRON, CHERRIE
55	BLUE MOON CAFE
56	DEROSE, RALPH
	GUINN, ERIC

Target Street	Cross Street	Source
✓	-	Cole Information

MAIN ST 2010 (Cont'd)

56	MANDIGO, JOE M
	MOSES, CARLOS
59	BEAULIEU, ROBERT P
	LAPIERRE, STACEY A
	VAUGHN, STACEY
60	NICASTRO, CHARLES J
62	OCCUPANT UNKNOWN,
63	COMPUTER SUPPORT
	CURTIS, STEPHANIE
64	GILE, MICHAEL
65	CHINA JADE
	EDWARD JONES
	SEARS HOMETOWN STORE
67	ADIRONDACK BANK
	ADIRONDACK FINANCIAL SVC CORP
	ADIRONDACK NORTH COUNTRY ASSN
68	NORIS VILLAGE MARKET INC
69	SALON MIRAGE DAY SPA & FITNESS
70	GEORGEANNE GAFFNEY CUSTOM
	SARANAC LAKE VOLUNTARY HEALTH
76	FORTUNE STUDIO
77	MILLER, KEN M
78	LIZ CO LLC
79	FINNIGANS
80	MOORE, JOHN P
	WATSON, AMANDA
81	BLUE LINE SPORT LLC
	MAHER JAMES E
	MAHER, JAMES J
	US MARINE CORPS
82	ADIRONDACK CLOCK WORKS
83	JOHN MC GILL PC
	MCGILL, JOHN
	Y GALLERY
84	I B HUNT AGENCY
85	BELLEVILLE & ASSOC
	SEPULVEDA, ANGELO
86	ADIRONDACK EYE CTR
89	GREENIER, DAVID L
90	TRILAKES CTR FOR DENTISTRY
91	ZIMNY, FREDERIC W
100	HOTEL SARANAC
102	HOUGH, ERNEST

Target Street	Cross Street	Source
✓	-	Cole Information

MAIN ST 2005

1	FAR MORS KIDS
	MOUNT PISGAH SKI AREA
	ONE MAIN INC
	SARANAC LAKE POLICE DEPARTMENT
2	FRANKLIN CO DEPT SOCIAL SERVICES
3	SARANAC LAKE VILLAGE
	THE BROWN DOG CAFE & WINE BAR
10	DARRAH COOPER JEWELERS
	FRANKLIN COUNTY COMMUNITY SERVICE
11	RUTHIES RUN
13	WATER EDGE
14	SOUP STONE CAFE THE
15	CHINA CITY
17	NORTH STAR INDUSTRIES
21	JIMMYS 21
23	MAGRO, PAOLO
25	SUGAR CREEK STORES
	TOPS MARKET INC
26	NICE N EASY GROCERY SHOPPE
30	MOUNTAINEER RUGBY
	SARANAC LAKE AREA CHAMBER OF COMMERC
	TOWN OF HARRIETSTOWN
	VETERANS AFFAIRS
33	SIR SPEEDY
34	BAKER, RICE
	KANE RESTAURANT GROUP
	RICE FURNITURE
38	CIGARETTE WAREHOUSE OF SARANAC LAKE
	MOUNTAIN GIFT AND POWDER CO
	SARANAC LAKE DISCOUNT LIQUORS
39	HARRIETTS TOWN
	THE SARANAC LAKE AREA CHAMBER OF COM
	TOWN OF HARRIETSTOWN
42	OWLS NEST PIZZA PARLOR
	SIR SPEEDY PRINTING CENTER
43	WATERHOLE NO 3
44	SNUFFYS PUB
45	BURNAH, MARVIN
46	COLD RIVER COFFEE CO INC
	FLETCHER, JEFFREY C
47	DARRING, BRUCE R
	KELLER, DEBRA
	ONEILL, VALERIE
	R E HANPETER AIA ARCHITECT
	ROTHE, SEAN
48	AYRES REALTY INC
50	LAPOINT, DAVID J
51	RICHARDS FREEYSTYLE CUISINE
52	POST OFFICE PHARMACY
	TANZINI, GREGORY

Target Street	Cross Street	Source
✓	-	Cole Information

MAIN ST 2005 (Cont'd)

53	PERSICO RICHARD A
	ULASEWICZ PATRICIA M
54	CHARRON, CHERRIE
55	BLUE MOON CAFE
56	DODD, STEVEN
	DUSETT, MICHELE
	FOLEY, BARBARA A
	GREEN, CLINTON
	MOSES, CARLOS
	NIEZNALSKI, PATRICIA
	PIROZZI, DOMINIC
	SAUVEUR, JOHN
	SEARS, SAMARA
	STOCKI, JOHN
	WILSON, NATHANIEL
58	CHINA JADE
59	CASEY, CHRISTINE
	GRIFFIN BRADNEY
	LEWIS, JOAN M
	RAUCH, NED
	STEPHENSON, WILLIAM
60	ADIRONDACK ECONOMIC DEVELOPMENT CORP
	NICASTRO & CANTWELL
	SARANAC LAKE ABSTRACT CO
63	MANDIGO, JOE M
64	BLING
65	BLING
	EDWARD JONES
	EDWARD, JONES
	MERRILL L THOMAS INC
	NORIS VILLAGE MARKET INC
	POLITI ROBERT T
	SEARS ROEBUCK CO
68	DANCE OF LIGHT
	RANDIG, ALYSSA
	SALON MIRAGE DAY SPA & FITNESS CENTE
69	MEYERS GIFTS
70	SARANAC LAKE VOLUNTARY HEALTH ASSN I
71	FORTUNE STUDIO
72	GETAWAY SARANAC LAKE YOUTH CENTER
74	ADIRONDACK ARTIST GUILD
	GETAWAY SARANAC LAKE USED CENTER INC
	REID, MARYLOU
75	HENGST, WILLY N
	MATHERS, R S
	ROCHELLE, D
76	BALISCIANO, PHILIP
	DISCOVERIES INC
	PHILIP TOWN BARBER & STYLE
	VICTORY BOUND

Target Street	Cross Street	Source
✓	-	Cole Information

MAIN ST 2005 (Cont'd)

77	MILLER, KEN
78	ADIRONDACK CHURCH OF NAZARENE
	FINNIGAN, T F
	LIZ CO LLC
	T F FINNIGAN INC
80	MOORE, JOHN P
	RAFUSE, JASON
	ROMPS, DEVIN
82	BLUE LINE SPORT SHOP INC
	FEEL THE STEEL TOO
	JAMES E MAHER
	MAHER, JAMES
	THE COIN DEN
83	ADIRONDACK EYEWEAR INC
	BEN & JERRYS ICE CREAM
	SMITH, STEPHEN
	WINTER DUNCAN FORBES
84	LONG, JOHN
	THOMPSON, KIRA
86	SURGICAL EYE CARE
89	GREENIER, DAVID
	NEILL, ROGER W
94	CORVO RESTAURANT
	NINETY FOUR MAN ST SRNC CORP
100	ADRNDCK ROOM OF THE SRNCK LAKE
	HOTEL SARANAC
	SARANAC LAKE FREE LIBRARY

Target Street	Cross Street	Source
✓	-	Cole Information

MAIN ST 2000

2	FRANKLIN COUNTY DEPARTMENT OF SOCIAL SVCES
	FRANKLIN COUNTY NURSING SVCE
	SARANAC LAKE VILLAGE OFFICIALS & DEPARTMENTS COMMUNITY DEVE
	SARANAC LAKE VILLAGE OFFICIALS & DEPARTMENTS PLC DEPARTMENT
	SARANAC LAKE VILLAGE OFFICIALS & DEPARTMENTS VILLAGE CLERKS
	SARANAC LAKE VILLAGE OFFICIALS & DEPARTMENTS VILLAGE CODES E
	SECTION 8 HOUSING ASSISTANCE
10	FRANKLIN CNTY GOVERNMENT FRANKLIN CNTY COMMUNITY SERVICES
	NORTH STAR INDUSTRIES BEHAVIORAL HEALTH SERVICES
	SARANAC LAKE VILLAGE OFFICIALS & DEPARTMENTS WATER DEPARTMEN
12	BARBONI, JEFFREY W
	BLAUM, MARK
	FEIL, L M
	STAVES, C
	TAICNER, CYNTHIA A
	WARD, FRANCIS X
25	SUGAR CREEK STORES
30	CHAMBER OF COMMERCE OF SARANAC LAKE
	COMMUNITY ACTN AGENCY OF FRANKLIN CNTY INCORPORATED SARANAC
	FRANKLIN COUNTY DEPARTMENT OF MOTOR VEHICLE
	NEW YORK STATE DIVISION OF VETERANS AFFAIRS
	NORTHERN ADIRONDACK BOARD OF REALTORS
	POLICE DEPARTMENT
	SARANAC LAKE AREA CHAMBER O
	SARANAC LAKE POLICE DEPARTMENT
	SARANAC LAKE VILLAGE OFFICIALS & DEPARTMENTS PLC JSTC
	TOWN OF HARRIETSTOWN
	TOWN OF HARRIETSTOWN ASSESSORS OFFICE
	TOWN OF HARRIETSTOWN TOWN CLERK
	TWN OF HARRIETSTOWN TWN JSTC & TWN SUPVSR
33	SIR SPEEDY PRINTING CENTER
34	RICE FURNITURE
38	CIGARETTE WAREHOUSE INCORPORATED
	HANPETER, RICHARD E
	R E HANPETER AIA ARCHITECT
	WARD THOMAS P REAL ESTATE
40	SARANAC LAKE DISCOUNT LIQUORS INCORPORATED
42	OWLS NEST PIZZA PARLOR
43	WATERHOLE NO 3
44	SNUFFY'S PUB
45	SALON MIRAGE
46	BLUE MOON CAFE
	COLD RIVER COFFEE COMPANY INCORPORATED
47	PLANNED PARENTHOOD NORTHERN ADIRONDACK
49	BARKEATER BICYCLES
52	BEVILACQUA CARL
	POST OFFICE PHARMACY
60	ADIRONDACK BANK
	CANTWELL WILLIAM W ATTORNEY
	NICASTRO CHARLES J ATTORNEY

Target Street	Cross Street	Source
✓	-	Cole Information

MAIN ST 2000 (Cont'd)

60	SARANAC LAKE ABSTRACT COMPANY
68	HEALTH DEN FITNESS CENTER
69	MEYERS
70	MARINE MIDLAND BANK
	SARANAC LAKE VOLUNTARY HEALTH ASSOCIATION INCORPORATED
71	FORTUNE STUDIO
73	SARANAC LAKE JEWELERS
74	NORTH COUNTRY ARTIST GUILD
	NORTH COUNTRY ORIGINALS
75	BIRTHRIGHT
	CONLEY, SEAN
	DAVIS, BRYAN
	DEDERICK, MICHAEL P
	PARKER, J
	RIVERA, AVIS
	WILCOX, E E
76	CHRISTINAS PLACE
	PHILIP TOWN BARBER & STYLE
77	COIN DEN THE
78	FINNIGAN, T F
79	HUNT B AGENCY
80	DRAGON, ANDREA F
	MOORE, JOHN P
82	BLUE LINE SPORT SHOP
	MAHER JAMES E ATTORNEY
	NORTH WOODS ENGINEERING
	OCCUPANT UNKNOWN,
	WHISHER JEFFREY INSURANCE
83	ADIRONDACK EYE CENTER
	ADIRONDACK OPTICAL CENTER
	MCGILL JOHN DDS MS PC
	WINTER DUNCAN FORBES MD
	WINTER, DUNCAN F
84	TURN A ROUND
89	AUSTIN, J
	NEILL ROGER W DMD GENERAL DENTIST
94	CORVO RESTRNT
100	SARANAC LAKE FREE LIBRARY

Target Street	Cross Street	Source
✓	-	Cole Information

MAIN ST 1995

2	FRANKLIN COUNTY DEPT OF SOCIAL SERVICESS
	FRANKLIN COUNTY NURSING SVCE
	FRANKLIN COUNTY PROBATION OFCSS
	SARANAC LAKE VILLAGE OFFICIALS & DEPTS-COMMUNITY DEVELOPMENT
	SARANAC LAKE VILLAGE OFFICIALS & DEPTS-VILLAGE MANAGERR
	SECTION 8 HOUSING ASSISTANCE
10	FRANKLIN COUNTY COMMUNITY SERVICES
	NORTH STAR SUBSTANCE ABUSE SVCES
	SARANAC LAKE VILLAGE OFFICIALS & DEPTS-VILLAGE CLERK'S OFCC
	SARANAC LAKE VILLAGE OFFICIALS & DEPTS-WATER DEPTT
25	SUGAR CREEK STORES
	WESTERN UNION-TO PICK UP OR SEND MONEY TRANS-SUGAR CREEK
30	CHAMBER OF COMMERCE OF SARANAC LAKE
	COMMUNITY ACTION AGENCY OF FRANKLIN COUNTY INCORPORATED, SAR
	FRANKLIN COUNTY DEPT OF MOTOR VEHICLESS
	HARRIETSTOWN TOWN OF HUD PROGRAMM
	HARRIETSTOWN TOWN OF-ASSESSOR'S OFCC
	NYS DIV OF VETERANS AFFAIRSS
	PLUMADORE, JAN H, JUSTICE SUPREME COURT
	POLICE DEPTT
	SARANAC LAKE AREA CHAMBER OF COMMERCE
	SARANAC LAKE VILLAGE OFFICIALS & DEPTS-POLICE DEPTT
	SARANAC LAKE VILLAGE OFFICIALS & DEPTS-POLICE JUSTICEE
	TOWN OF HARRIETSTOWN-TOWN CLERKK
	TOWN OF HARRIETSTOWN-TOWN JUSTICE & TOWN SUPERVISORR
33	LOCKROW'S OFFICE SUPPLIES
	SIR SPEEDY PRINTING CENTER
	TECH OFFICE PRODUCTS
34	RICE FURNITURE
38	MAYFLOWER TRANSIT AGENCY
	OLYMPIC MOVING & STORAGE CO INC
	SARANAC LAKE DISCOUNT LIQUORS INC
	WARD, THOMAS P, RL EST
40	HANPETER, RICHARD E, ARCHT
	PETER, DROWN TRAVEL
	R E HANPETER AIA-ARCHITECT
42	OWL'S NEST PIZZA PARLOR
43	WATERHOLE NO 3
44	SNUFFY'S PUB
45	SALON MIRAGE
46	GIFT CORNER THE
	YUM YUM TREE THE
47	PLANNED PARENTHOOD-NORTHERN ADIRONDACK
48	AYRES INSURANCE AGENCY INC, INS
	AYRES REALTY INC/BETTER HOMES & GARDENS
49	BARKEATER BICYCLES
50	CHRISTIAN SCHOOLS OF KARATE
52	BEVILACQUA, CARL
	POST OFC PHARMACY
54	TOWNE BARBER & STYLE

Target Street	Cross Street	Source
✓	-	Cole Information

MAIN ST 1995 (Cont'd)

58	CHINA JADE
60	ADIRONDACK BANK FSB
	CANTWELL, WILLIAM W, ATTY
	NICASTRO & CANTWELL, ATTYS
	NICASTRO, CHARLES J, ATTY
65	NEWBERRY J J CO
67	SARANAC LAKE FLORIST
68	HEALTH DEN FITNESS CENTER
69	MEYER'S
70	MARINE MIDLAND BANK-BRANCH OFFICES-SARANAC LAKE
	SARANAC LAKE VOLUNTARY HEALTH ASSN INC
71	FORTUNE STUDIO
72	GETAWAY SARANAC LAKE YOUTH CENTER
73	SARANAC LAKE JEWELERS
75	BIRTHRIGHT
76	CHRISTINA'S PLACE
	HAIRLINES
77	CLOTHES CLOSET THE
78	FINNIGAN, T F, MEN'S OUTFITTER
79	HUNT I B AGENCY, INS & RL EST
82	BLUE LINE SPORT SHOP
	MAHER, JAMES E, ATTY
83	RENTAVISION INC
84	TURN A ROUND
89	NEILL, ROGER W, DMD
93	PAUL SMITHS TRAVEL AGENCY OF PAUL SMITHS COLLEGE
94	CORVO RESTRNT
100	SARANAC LAKE FREE LIBRARY

Target Street	Cross Street	Source
✓	-	Cole Information

MAIN ST 1992

2	FRANKLIN COUNTY DEPT OF SOCIAL SERVICES
	FRANKLIN COUNTY NURSING SVCE
	FRANKLIN COUNTY PROBATION OFC
	SARANAC LAKE VILLAGE OFFICIALS & DEPTS-COMMUNITY DEVELOPMENT
	SARANAC LAKE VILLAGE OFFICIALS & DEPTS-VILLAGE MANAGER
	SECTION 8 HOUSING ASSISTANCE
10	FRANKLIN COUNTY COMMUNITY SERVICE
	NORTH STAR SUBSTANCE ABUSE SVCES
	SARANAC LAKE VILLAGE OFFICIALS & DEPTS-VILLAGE CLERK'S OFC
	SARANAC LAKE VILLAGE OFFICIALS & DEPTS-WATER DEPT
12	BICKFORD, JAMES J
	IVIMEY, WILLIAM H
	KNAPP, CHRISTOPHER
	VELAZQUEZ, SUSAN
25	SUGAR CREEK STORES, NO 307
30	ADIRONDACK ECONOMIC DEVELOPMENT CORP
	CHAMBER OF COMMERCE OF SARANAC LAKE
	FRANKLIN COUNTY DEPT OF MOTOR VEHICLES
	HARRIETSTOWN TOWN OF HUD PROGRAM
	HARRIETSTOWN TOWN OF-ASSESSOR'S OFC
	HARRIETSTOWN TOWN OF-TOWN CLERK & TOWN SUPERVISOR
	HARRIETSTOWN TOWN OF-TOWN JUSTICE
	NYS DIV OF VETERANS AFFAIRS
	PLUMADORE, JAN H, JUSTICE SUPREME COURT
	POLICE DEPT
	SARANAC LAKE AREA CHAMBER OF COMMERCE
	SARANAC LAKE VILLAGE OFFICIALS & DEPTS-POLICE DEPT
	SARANAC LAKE VILLAGE OFFICIALS & DEPTS-POLICE JUSTICE
33	ATLAS, DAN
	MOLNAR, JAE
	SEARS ROEBUCK AND CO
34	RICE FURNITURE
38	SARANAC LAKE DISCOUNT LIQUORS INC
	WARD, THOMAS P, RL EST
40	PETER, DROWN TRAVEL
42	OWL'S NEST PIZZA PARLOR
43	ALLEN, WILLIAM
	WATERHOLE NO 3
44	PARENT, CHANCE
	ZEH, GREGORY
45	NORTH COUNTRY ORIGINALS
46	GIFT CORNER THE
	YUM YUM TREE THE
47	PLANNED PARENTHOOD-NORTHERN ADIRONDACK
49	BESSETTE, JAMES P, ATTY
	FISCHER HUGHES & BESSETTE, LAW OFFICES
	GORDON, TAMMY L, ATTY
	HUGHES, BRYAN J, ATTY
	MAC NEILL, GLENN, ATTY
	MULDOWNEY, JOHN J, ATTY

Target Street	Cross Street	Source
✓	-	Cole Information

MAIN ST 1992 (Cont'd)

50	DIBIASIE, M
	GONYEA, VICTOR & KATHLEEN
	LAKE PLACID DESIGNS INC
	LEWIS, JOAN
	MAJERUS, TED
	OLMSTEAD, K
52	BEVILACQUA, CARL
	POST OFC PHARMACY
54	TOWNE BARBER & STYLE
56	BAKER, LYNN
	BAKER, WAYNE
	DE GRACE, NICK
	FADDEN, CHARLEEN
58	CHINA JADE
60	ADIRONDACK BANK A FEDERAL SAVINGS BANK
	CANTWELL, WILLIAM W, ATTY
	FEDERAL SAVINGS BANK
	NICASTRO & CANTWELL, ATTYS
	NICASTRO, CHARLES J, ATTY
	NOVA GRAPHICS
65	NEWBERRY J J CO
67	SARANAC LAKE FLORIST
68	HEALTH DEN FITNESS CENTER
69	MEYER'S DRUGS
70	MARINE MIDLAND BANK NA-BRANCH OFFICES-SARANAC LAKE
	SARANAC LAKE VOLUNTARY HEALTH ASSN INC
73	SARANAC LAKE JEWELERS
75	BIRTHRIGHT
	LEIES, ANNA
	MOODY, CYNTHIA
	STACEY, EARL, JR
76	CHRISTINA'S PLACE
	HAIRLINES
77	LAMY, LEO
78	FINNIGAN, T F, MEN'S OUTFITTER
79	HUNT I B AGENCY, INS & RL EST
80	BLAISE, ERIC
82	BLUE LINE SPORT SHOP
	PARNELL SHOE SALON
84	KENT, A
	STEVENS, JOHN
89	LARSEN, ALFRED R
	LAVALLEY, S L
	NEILL, ROGER W, DMD
	WOODS, HELEN
93	PAUL SMITHS TRAVEL AGENCY OF PAUL SMITHS COLLEGE
94	PONTIAC CLUB
100	SARANAC LAKE FREE LIBRARY
7212	GETAWAY SARANAC LAKE YOUTH CENTER

APA HQ - Phase I ESA
13 Main Street
Saranac Lake, NY 12983

Inquiry Number: 7391856.6
July 17, 2023

The EDR Property Tax Map Report

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

EDR Property Tax Map Report

Environmental Data Resources, Inc.'s EDR Property Tax Map Report is designed to assist environmental professionals in evaluating potential environmental conditions on a target property by understanding property boundaries and other characteristics. The report includes a search of available property tax maps, which include information on boundaries for the target property and neighboring properties, addresses, parcel identification numbers, as well as other data typically used in property location and identification.

NO COVERAGE

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2022 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

APA HQ - Phase I ESA
13 Main Street
Saranac Lake, NY 12983

Inquiry Number: 7391856.2s
July 17, 2023

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	267
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-7
Physical Setting Source Map Findings	A-8
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA) INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527 - 21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E2247 - 16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E1528 - 22) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

13 MAIN STREET
SARANAC LAKE, NY 12983

COORDINATES

Latitude (North):	44.3244290 - 44° 19' 27.94''
Longitude (West):	74.1329280 - 74° 7' 58.54''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	569138.9
UTM Y (Meters):	4908056.5
Elevation:	1528 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	14115916 SARANAC LAKE, NY
Version Date:	2019
East Map:	14115876 MCKENZIE MOUNTAIN, NY
Version Date:	2019

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20190727, 20190802
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
13 MAIN STREET
SARANAC LAKE, NY 12983

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	SARANAC RIVER FROM D	MAIN ST.	NY Spills	Lower	1 ft.
A2	TOWN HALL	MAIN STREET	NY Spills	Lower	1 ft.
A3	PARNELL SHOE SALON	MAIN STREET	LTANKS, NY Spills	Lower	1 ft.
A4	LAKE FLOWER BRIDGE	MAIN STREET	NY Spills	Lower	1 ft.
A5	SARANAC RIVER S.L.	MAIN ST.(QUONSET HUT	NY Spills	Lower	1 ft.
6	LALANDE PROPERTY - D	4 DORSEY ST	FINDS	Higher	1 ft.
A7	METH LAB CLEAN UP	1 MAIN STREET	NY Spills	Lower	3, 0.001,
A8	SARANAC LAKE VILLAGE	10 MAIN ST	RCRA NonGen / NLR, MANIFEST	Lower	42, 0.008, East
A9	SARANAC LAKE VILLAGE	10 MAIN ST.	NY Spills	Lower	42, 0.008, East
A10	VILLAGE SARANAC LAKE	3 MAIN STREET	UST, NY Spills	Lower	43, 0.008, ESE
B11	SARANAC RIVER	RT. 3	NY Spills	Higher	81, 0.015, NNW
B12	PUMP STATION @ NIMO	ROUTE 86	NY Spills	Higher	81, 0.015, NNW
B13	SARANAC RIVER	RT 3, TOWARD BOOMING	NY Spills	Higher	81, 0.015, NNW
B14	STORM SEWER OUTFALL	LAPAN HWY, RT. 3	NY Spills	Higher	81, 0.015, NNW
B15	BEHIND PUMP STATION	RIVER ST.	NY Spills	Higher	81, 0.015, NNW
B16	LAPAN HIGHWAY BRIDGE	LAPAN HIGHWAY	NY Spills	Higher	81, 0.015, NNW
B17	SARANAC RIVER	RT 3	NY Spills	Higher	81, 0.015, NNW
A18	AMERIGAS TRUCK	23 MAIN STREET	NY Spills	Lower	102, 0.019, ENE
A19	NONNA FINA	23 MAIN ST	EDR Hist Auto	Lower	102, 0.019, ENE
A20	WILSON FARMS XPRESS	25 MAIN STREET	UST, NY Spills	Lower	105, 0.020, ENE
A21	CASSIDY GERALD F	27 MAIN ST	EDR Hist Auto	Lower	109, 0.021, ENE
A22	SARANAC RIVER	SARANAC LAKE	NY Spills	Higher	132, 0.025, East
B23	SARANAC LAKE OFF DOR	ST BRIDGE-MUNICIPAL	NY Spills	Higher	141, 0.027, NNW
C24	SARANAC RIVER OUTFAL	RT 3/MAIN ST.	NY Spills	Lower	144, 0.027, NE
C25	OUTFALL BHND LITTLE	MAIN ST.	NY Spills	Lower	144, 0.027, NE
A26	SARANAC LAKE LF (V)	881 MCKENZIE ROAD 89	SWF/LF	Lower	184, 0.035, NE
A27	TOWN OF HARRIETSTOWN	39 MAIN ST	NY Spills	Lower	184, 0.035, NE
A28	7-ELEVEN 35225 (WILS	MAIN AND RIVER ST	NY Spills	Higher	184, 0.035, NE
D29	IN LAKE FLOWER OFF	14 KIWASSA RD	NY Spills	Higher	188, 0.036, SE
D30	IN LAKE FLOWER	OFF RIVERSIDE DRIVE	NY Spills	Higher	219, 0.041, ESE
C31	HARRIETSTOWN SANITAR		PFAS ECHO	Higher	239, 0.045, NE
E32	STORM SEWER OUTFALL	RIVER ST & ST BERNAR	NY Spills	Higher	240, 0.045, ENE
C33	BEHIND THE WATER HOL	MAIN STREET	NY Spills	Lower	242, 0.046, NNE
C34	TOWN HALL	30 MAIN ST	LTANKS, UST	Higher	243, 0.046, NE
C35	ST BERNARD'S CHURCH	ST BERNARD ST	LTANKS, NY Spills	Higher	244, 0.046, ENE
C36	ST BERNARD CHURCH	ST BERNARD ST	NY Spills	Higher	244, 0.046, ENE
C37	HARRIETSTOWN TOWN HA	MAIN ST	LTANKS	Higher	282, 0.053, NNE
C38	@ SARANAC LAKE TOWN	MAIN STREET	NY Spills	Higher	282, 0.053, NNE
E39	ATLANTIC STATION	14 RIVER ST/ST. BERN	NY Spills	Higher	297, 0.056, ENE

MAPPED SITES SUMMARY

Target Property Address:
13 MAIN STREET
SARANAC LAKE, NY 12983

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
E40	ATLANTIC REF. & MKTG	14 RIVER ST	UST	Higher	297, 0.056, ENE
E41	ATLANTIC SERVICE STA	14 RIVER ST	RCRA NonGen / NLR, FINDS, ECHO, MANIFEST	Higher	297, 0.056, ENE
C42	BETWEEN T HALL/RICE	MAIN STREET	NY Spills	Higher	301, 0.057, NNE
C43	COMMERCIAL BLDG	47 MAIN ST	NY Spills	Higher	317, 0.060, NNE
C44	PARKING LOT BETWEEN	42 MAIN ST	NY Spills	Higher	365, 0.069, NE
C45	SIR SPEEDY PRINTING	42 MAIN ST	RCRA NonGen / NLR	Higher	365, 0.069, NE
F46	HOYT TAXI SERVICE	53 MAIN ST	EDR Hist Auto	Higher	370, 0.070, NNE
E47	ATLANTIC GAS STATION	RIVER ST.	LTANKS	Higher	409, 0.077, ENE
48	CHAPIN RESIDENCE	22 KIWASSA RD	LTANKS	Higher	421, 0.080, ESE
49	SARANAC RIVER	DORSEY STREET	LTANKS	Higher	494, 0.094, NNW
F50	CHINA JADE	58 MAIN STREET	LTANKS	Higher	541, 0.102, NNE
51	87 LAKE STREET	87 LAKE STREET	NY Spills	Higher	546, 0.103, WSW
G52	ST. BERNARD'S CHURCH	ST. BERNARD ST	LTANKS, NY Spills	Higher	549, 0.104, ENE
G53	ST. BERNARD CHURCH	BERNARD ST.	NY Spills	Higher	549, 0.104, ENE
G54	ST. BERNARD'S CHURCH	CHURCH ST.(PRES.CHUR	NY Spills	Higher	549, 0.104, ENE
G55	ST BERNARDS CHURCH	ST BERNARD ST	LTANKS	Higher	549, 0.104, ENE
G56	ST. BERNARD'S CHURCH	BERNARD STREET	NY Spills	Higher	549, 0.104, ENE
G57	ST BERNARD'S CHURCH	ST BERNARDS STREET	NY Spills	Higher	549, 0.104, ENE
F58	ADIRONDACK BANK, FSB	60 MAIN ST	UST	Higher	556, 0.105, NNE
F59	ADIRONDACK BANK	60 MAIN STREET	LTANKS, AST	Higher	556, 0.105, NNE
F60	MEYER'S HALLMARK (AL	69 MAIN STREET	NY Spills	Higher	573, 0.109, NNE
61	VILLAGE SARANAC LAKE	3 MAIN STREET	AST	Lower	597, 0.113, North
62	MARINE MIDLAND BANK	70 MAIN ST	UST, NY Spills	Higher	622, 0.118, NNE
H63	ST BERNARD'S CHURCH	27 ST. BERNARD STREE	UST, AST	Higher	826, 0.156, ENE
64	RIVER STREET NICE N	111 RIVER STREET	UST, VCP, NY Spills	Higher	864, 0.164, East
I65	CLUB SARANAC	BROADWAY ST	LTANKS	Higher	879, 0.166, NNE
I66	FORMER ALICE'S REST.	BROADWAY STREET	LTANKS, NY Spills	Higher	886, 0.168, NNE
I67	MAURICES BUILDING	10 BROADWAY	UST	Higher	886, 0.168, NNE
H68	NY TELEPHONE COMPANY	CHURCH STREET	LTANKS	Higher	925, 0.175, ENE
I69	OXFORD MARKET BLDG	BROADWAY ST	LTANKS, NY Spills	Lower	932, 0.177, NNE
J70	HOTEL SARANAC	100 MAIN ST	AST	Higher	932, 0.177, NE
J71	HOTEL SARANAC	100 MAIN ST	UST	Higher	932, 0.177, NE
J72	MORGAN RESIDENCE	104 MAIN STREET	LTANKS, NY Spills	Higher	974, 0.184, NE
K73	PRIMETIME RESTAURANT	42 BROADWAY STREET	LTANKS, NY Spills	Lower	999, 0.189, North
74	DARING RESIDENCE	5 SUMNER PLACE	LTANKS	Higher	1043, 0.198, North
L75	SARANAC LAKE CSD - P	141 PETROVA AVE	AIRS, MANIFEST	Higher	1054, 0.200, West
L76	SARANAC LAKE CENTRAL	141 PETROVA AVENUE	AST	Higher	1054, 0.200, West
L77	SARANAC LAKE CSD - P	141 PETROVA AVE	RCRA-VSQG, FINDS, ECHO	Higher	1054, 0.200, West
L78	SARANAC LAKE CENTRAL	141 PETROVA AVENUE	UST	Higher	1054, 0.200, West

MAPPED SITES SUMMARY

Target Property Address:
13 MAIN STREET
SARANAC LAKE, NY 12983

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
M79	NORTH COUNTRY HOME S	37 CHURCH STREET	LTANKS	Higher	1101, 0.209, East
I80	28 BROADWAY	28 BROADWAY	AST	Lower	1115, 0.211, NNE
N81	TRUDEAU INSTITUTE IN	18-22 WOODRUFF ST	UST	Higher	1119, 0.212, NNE
O82	DECHANTAL APARTMENTS	60 CHURCH ST	UST	Higher	1125, 0.213, ENE
O83	VERIZON NEW YORK INC	48 CHURCH STREET	TANKS	Higher	1139, 0.216, ENE
N84	TRUDEAU INSTITUTE	15 WOODRUFF STREET	LTANKS	Lower	1152, 0.218, NNE
K85	KEY BANK OF NEW YORK	55 BROADWAY STREET	UST	Lower	1164, 0.220, North
N86	DR. BALKIEWICZ	WOODRUFF STREET	LTANKS	Lower	1177, 0.223, NNE
M87	NYNEX	26 CHURCH ST	NY Spills, RCRA NonGen / NLR, FINDS, ECHO,...	Higher	1203, 0.228, ENE
N88	BURNS NEWS AGENCY IN	28 WOODRUFF ST	LTANKS, UST, NY Spills	Higher	1217, 0.230, NNE
N89	RIVERSIDE PROPERTIES	28-30 WOODRUFF STREE	UST	Higher	1217, 0.230, NNE
M90	DECHANTAL APARTMENTS	20 CHURCH STREET	LTANKS	Higher	1243, 0.235, East
M91	DECHANTAL APTS. INC.	20 CHURCH STREET	LTANKS	Higher	1243, 0.235, East
P92	ADIRONDACK DAILY ENT	61 BROADWAY	RCRA NonGen / NLR	Higher	1294, 0.245, North
Q93	NORTH STAR INDUSTRIE	71 PETROVA AVENUE	LTANKS	Higher	1321, 0.250, West
94	29 WILLIAMS STREET	29 WILLIAMS ST	LTANKS	Higher	1327, 0.251, NNW
P95	BROADWAY PROPERTIES	60-62 BROADWAY	LTANKS, UST, NY Spills	Higher	1327, 0.251, North
Q96	NORTH STAR INDUSTRIE	PETROVA AVE	LTANKS	Higher	1349, 0.255, West
97	PMS OUTFALL INTO SAR	WOODRUFF ST.	LTANKS, NY Spills	Lower	1472, 0.279, NNE
98	TISSOT CONSTRUCTION	RT. 86	LTANKS	Higher	1628, 0.308, ENE
R99	CASIER'S - OLD TANK	BLOOMINGDALE ST	LTANKS	Higher	1633, 0.309, North
R100	STEWARTS	BLOOMINGDALE ROAD &	LTANKS	Higher	1675, 0.317, North
R101	STEWARTS SHOP #	BLOOMINGDALE AVE	LTANKS	Higher	1685, 0.319, North
102	PETROVA AVE SCHOOL	PETROVA AVE	LTANKS	Higher	1706, 0.323, West
103	MRS KELTING	174 LAKE ST	LTANKS	Higher	1714, 0.325, WSW
104	SCHNECK RESIDENCE	FRANKLIN AVE.	LTANKS	Higher	1754, 0.332, East
105	45 FRANKLIN AVE	45 FRANLKIN AVE	LTANKS	Higher	1827, 0.346, ENE
S106	IN FRONT OF RUSTY NA	BROADWAY	LTANKS	Higher	1840, 0.348, NNW
S107	SARANAC LAKE VILLAGE	MCKENZIE POND RD	ODI	Higher	1843, 0.349, North
S108	SARANAC LAKE LANDFIL	MCKENZIE POND ROAD	LTANKS, NY Spills	Higher	1843, 0.349, North
S109	RUSTY NAIL	BROADWAY STREET	LTANKS, NY Spills	Higher	1845, 0.349, NNW
110	MAINLINE GARAGE	LAKE FLOWER AVENUE	LTANKS, NY Spills	Higher	1946, 0.369, East
111	DURFEE RESIDENCE	2 FAIRVIEW AVENUE	LTANKS	Higher	2007, 0.380, NW
112	SARANAC LOFTS	120 BROADWAY	BROWNFIELDS	Higher	2115, 0.401, North
113	SHELLY VANCOUR RESID	340 GLENWOOD DRIVE	LTANKS	Higher	2153, 0.408, South
T114	PJ HYDE & SON	171 BROADWAY	LTANKS, NY Spills	Higher	2297, 0.435, NNW
T115	JOHN'S SUNOCO - FORM	172 BROADWAY ST.	LTANKS, NY Spills	Higher	2355, 0.446, NNW
116	DUPREE RESIDENCE	LAKE FLOWER AVE	LTANKS	Higher	2457, 0.465, ESE
U117	NO COUNTRY CHRISTIAN	212 LAKE FLOWER AV	LTANKS	Higher	2470, 0.468, ESE

MAPPED SITES SUMMARY

Target Property Address:
13 MAIN STREET
SARANAC LAKE, NY 12983

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
U118	MAIN LINE GARAGE	26 LAKE FLOWER AVENU	LTANKS	Higher	2488, 0.471, ESE
U119	MADDENS RENTAL PROPE	8 LAKE FLOWER AVE	LTANKS	Higher	2509, 0.475, ESE
120	BIG D	87 RIVERSIDE DRIVE	LTANKS	Higher	2519, 0.477, SE
121	SARANAC LAKE GAS CO.	PAYVILLE ROAD	DEL SHWS	Higher	4078, 0.772, ESE

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Lists of Federal Delisted NPL sites

Delisted NPL ---------- National Priority List Deletions

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE ---------- Superfund Enterprise Management System Archive

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS ---------- Corrective Action Report

Lists of Federal RCRA TSD facilities

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Lists of Federal RCRA generators

RCRA-LQG ---------- RCRA - Large Quantity Generators
RCRA-SQG ---------- RCRA - Small Quantity Generators

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROLS ---------- Institutional Controls Sites List

EXECUTIVE SUMMARY

Federal ERNS list

ERNS ---------- Emergency Response Notification System

Lists of state- and tribal hazardous waste facilities

SHWS ---------- Inactive Hazardous Waste Disposal Sites in New York State

Lists of state and tribal leaking storage tanks

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land
HIST LTANKS ---------- Listing of Leaking Storage Tanks

Lists of state and tribal registered storage tanks

FEMA UST ---------- Underground Storage Tank Listing
CBS UST ---------- Chemical Bulk Storage Database
MOSF UST ---------- Major Oil Storage Facilities Database
MOSF ---------- Major Oil Storage Facility Site Listing
CBS ---------- Chemical Bulk Storage Site Listing
CBS AST ---------- Chemical Bulk Storage Database
MOSF AST ---------- Major Oil Storage Facilities Database
INDIAN UST ---------- Underground Storage Tanks on Indian Land

State and tribal institutional control / engineering control registries

RES DECL ---------- Restrictive Declarations Listing
ENG CONTROLS ---------- Registry of Engineering Controls
INST CONTROL ---------- Registry of Institutional Controls

Lists of state and tribal voluntary cleanup sites

INDIAN VCP ---------- Voluntary Cleanup Priority Listing

Lists of state and tribal brownfield sites

ERP ---------- Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ---------- A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

SWTIRE ---------- Registered Waste Tire Storage & Facility List
SWRCY ---------- Registered Recycling Facility List
INDIAN ODI ---------- Report on the Status of Open Dumps on Indian Lands
DEBRIS REGION 9 ---------- Torres Martinez Reservation Illegal Dump Site Locations
IHS OPEN DUMPS ---------- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---------- Delisted National Clandestine Laboratory Register

US CDL ..... National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

HIST UST ..... Historical Petroleum Bulk Storage Database
HIST AST ..... Historical Petroleum Bulk Storage Database

Local Land Records

LIENS ..... Spill Liens Information
LIENS 2 ..... CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ..... Hazardous Materials Information Reporting System
NY Hist Spills ..... SPILLS Database
SPILLS 90 ..... SPILLS 90 data from FirstSearch
SPILLS 80 ..... SPILLS 80 data from FirstSearch

Other Ascertainable Records

FUDS ..... Formerly Used Defense Sites
DOD ..... Department of Defense Sites
SCRD DRYCLEANERS ..... State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ..... Financial Assurance Information
EPA WATCH LIST ..... EPA WATCH LIST
2020 COR ACTION ..... 2020 Corrective Action Program List
TSCA ..... Toxic Substances Control Act
TRIS ..... Toxic Chemical Release Inventory System
SSTS ..... Section 7 Tracking Systems
ROD ..... Records Of Decision
RMP ..... Risk Management Plans
RAATS ..... RCRA Administrative Action Tracking System
PRP ..... Potentially Responsible Parties
PADS ..... PCB Activity Database System
ICIS ..... Integrated Compliance Information System
FTTS ..... FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS ..... Material Licensing Tracking System
COAL ASH DOE ..... Steam-Electric Plant Operation Data
COAL ASH EPA ..... Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ..... PCB Transformer Registration Database
RADINFO ..... Radiation Information Database
HIST FTTS ..... FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS ..... Incident and Accident Data
CONSENT ..... Superfund (CERCLA) Consent Decrees
INDIAN RESERV ..... Indian Reservations
FUSRAP ..... Formerly Utilized Sites Remedial Action Program
UMTRA ..... Uranium Mill Tailings Sites
LEAD SMELTERS ..... Lead Smelter Sites
US AIRS ..... Aerometric Information Retrieval System Facility Subsystem
US MINES ..... Mines Master Index File
ABANDONED MINES ..... Abandoned Mines
ECHO ..... Enforcement & Compliance History Information
DOCKET HWC ..... Hazardous Waste Compliance Docket Listing

EXECUTIVE SUMMARY

UXO ---------- Unexploded Ordnance Sites
FUELS PROGRAM ---------- EPA Fuels Program Registered Listing
PFAS NPL ---------- Superfund Sites with PFAS Detections Information
PFAS FEDERAL SITES ---------- Federal Sites PFAS Information
PFAS TSCA ---------- PFAS Manufacture and Imports Information
PFAS RCRA MANIFEST ---------- PFAS Transfers Identified In the RCRA Database Listing
PFAS ATSDR ---------- PFAS Contamination Site Location Listing
PFAS WQP ---------- Ambient Environmental Sampling for PFAS
PFAS NPDES ---------- Clean Water Act Discharge Monitoring Information
PFAS ECHO FIRE TRAINING ---------- Facilities in Industries that May Be Handling PFAS Listing
PFAS PART 139 AIRPORT ---------- All Certified Part 139 Airports PFAS Information Listing
AQUEOUS FOAM NRC ---------- Aqueous Foam Related Incidents Listing
PFAS ---------- PFAS Contamination Site Location Listing
AIRS ---------- Air Emissions Data
COAL ASH ---------- Coal Ash Disposal Site Listing
DRYCLEANERS ---------- Registered Drycleaners
E DESIGNATION ---------- E DESIGNATION SITE LISTING
Financial Assurance ---------- Financial Assurance Information Listing
HSWDS ---------- Hazardous Substance Waste Disposal Site Inventory
LEAD ---------- Lead-based Paint Testing Results
SPDES ---------- State Pollutant Discharge Elimination System
VAPOR REOPENED ---------- Vapor Intrusion Legacy Site List
UIC ---------- Underground Injection Control Wells
COOLING TOWERS ---------- Registered Cooling Towers
MINES MRDS ---------- Mineral Resources Data System
PFAS TRIS ---------- List of PFAS Added to the TRI

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP ---------- EDR Proprietary Manufactured Gas Plants
EDR Hist Cleaner ---------- EDR Exclusive Historical Cleaners

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS ---------- Recovered Government Archive State Hazardous Waste Facilities List
RGA LF ---------- Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

EXECUTIVE SUMMARY

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal RCRA generators

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 03/06/2023 has revealed that there is 1 RCRA-VSQG site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SARANAC LAKE CSD - P	***141 PETROVA AVE***	***W 1/8 - 1/4 (0.200 mi.)***	***L77***	***156***
EPA ID:: NYD987014651				

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the SWF/LF list, as provided by EDR, and dated 03/31/2023 has revealed that there is 1 SWF/LF site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SARANAC LAKE LF (V)	881 MCKENZIE ROAD 89	NE 0 - 1/8 (0.035 mi.)	A26	48

Lists of state and tribal leaking storage tanks

LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the LTANKS list, as provided by EDR, and dated 02/06/2023 has revealed that there are 50 LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
TOWN HALL	***30 MAIN ST***	***NE 0 - 1/8 (0.046 mi.)***	***C34***	***57***
Spill Number/Closed Date: 9706973 / 1997-11-05				
Site ID: 186709				
Spill Date: 1997-09-11				
ST BERNARD'S CHURCH	***ST BERNARD ST***	***ENE 0 - 1/8 (0.046 mi.)***	***C35***	***60***
Spill Number/Closed Date: 9604012 / 1996-08-27				
Site ID: 331024				

Spill Date: 1996-06-17				
HARRIETSTOWN TOWN HA Spill Number/Closed Date: 0245048 / 2002-06-21 Site ID: 232048 Spill Date: 2002-06-21	MAIN ST	NNE 0 - 1/8 (0.053 mi.)	C37	64
ATLANTIC GAS STATION Spill Number/Closed Date: 8805328 / 1988-09-28 Site ID: 221831 Spill Date: 1988-09-20	RIVER ST.	ENE 0 - 1/8 (0.077 mi.)	E47	82
CHAPIN RESIDENCE Spill Number/Closed Date: 0308360 / 2003-12-03 Site ID: 299941 Spill Date: 2003-11-07	22 KIWASSA RD	ESE 0 - 1/8 (0.080 mi.)	48	83
SARANAC RIVER Spill Number/Closed Date: 8605567 / 1988-08-01 Site ID: 139351 Spill Date: 1986-12-02	DORSEY STREET	NNW 0 - 1/8 (0.094 mi.)	49	84
CHINA JADE Spill Number/Closed Date: 9304928 / 1993-07-15 Site ID: 160821 Spill Date: 1993-07-15	58 MAIN STREET	NNE 0 - 1/8 (0.102 mi.)	F50	86
ST. BERNARD'S CHURCH Spill Number/Closed Date: 9700694 / 1998-07-16 Site ID: 145119 Spill Date: 1997-04-16	***ST. BERNARD ST***	***ENE 0 - 1/8 (0.104 mi.)***	***G52***	***88***
ST BERNARDS CHURCH Spill Number/Closed Date: 9701419 / 1997-05-01 Site ID: 331025 Spill Date: 1997-05-01	ST BERNARD ST	ENE 0 - 1/8 (0.104 mi.)	G55	94
ADIRONDACK BANK Spill Number/Closed Date: 9601460 / 1996-05-03 Site ID: 62244 Spill Date: 1996-04-29	***60 MAIN STREET***	***NNE 0 - 1/8 (0.105 mi.)***	***F59***	***99***
CLUB SARANAC Spill Number/Closed Date: 9515930 / 1996-05-31 Site ID: 312196 Spill Date: 1996-03-05	BROADWAY ST	NNE 1/8 - 1/4 (0.166 mi.)	I65	129
FORMER ALICE'S REST. Spill Number/Closed Date: 9506484 / 2006-02-15 Site ID: 122398 Spill Date: 1995-05-01	***BROADWAY STREET***	***NNE 1/8 - 1/4 (0.168 mi.)***	***I66***	***130***
NY TELEPHONE COMPANY Spill Number/Closed Date: 9107797 / 1991-11-01 Site ID: 318731 Spill Date: 1991-10-22	CHURCH STREET	ENE 1/8 - 1/4 (0.175 mi.)	H68	134
MORGAN RESIDENCE Spill Number/Closed Date: 0208796 / 2002-12-03 Site ID: 168485 Spill Date: 2002-11-25	***104 MAIN STREET***	***NE 1/8 - 1/4 (0.184 mi.)***	***J72***	***145***
DARING RESIDENCE	5 SUMNER PLACE	N 1/8 - 1/4 (0.198 mi.)	74	150

Spill Number/Closed Date: 9845097 / 1999-04-19
Site ID: 251141
Spill Date: 1999-03-12

NORTH COUNTRY HOME S | 37 CHURCH STREET | E 1/8 - 1/4 (0.209 mi.) | M79 | 164
Spill Number/Closed Date: 8710155 / 1988-03-09
Site ID: 67978
Spill Date: 1988-03-03

BURNS NEWS AGENCY IN | 28 WOODRUFF ST | NNE 1/8 - 1/4 (0.230 mi.) | N88 | 183
Spill Number/Closed Date: 8702320 / 1992-10-01
Spill Number/Closed Date: 8603923 / 1986-11-01
Site ID: 219812
Site ID: 59704
Spill Date: 1987-06-22
Spill Date: 1986-09-16

DECHANTAL APARTMENTS | 20 CHURCH STREET | E 1/8 - 1/4 (0.235 mi.) | M90 | 194
Spill Number/Closed Date: 9110179 / 1992-02-04
Site ID: 174072
Spill Date: 1991-12-27

DECHANTAL APTS. INC. | 20 CHURCH STREET | E 1/8 - 1/4 (0.235 mi.) | M91 | 195
Spill Number/Closed Date: 0245039 / 2003-04-09
Site ID: 174071
Spill Date: 2002-06-11

NORTH STAR INDUSTRIE | 71 PETROVA AVENUE | W 1/4 - 1/2 (0.250 mi.) | Q93 | 200
Spill Number/Closed Date: 9608722 / 1996-10-16
Site ID: 274677
Spill Date: 1996-10-14

29 WILLIAMS STREET | 29 WILLIAMS ST | NNW 1/4 - 1/2 (0.251 mi.) | 94 | 201
Spill Number/Closed Date: 0012844 / 2001-03-06
Site ID: 145443
Spill Date: 2001-03-05

BROADWAY PROPERTIES | 60-62 BROADWAY | N 1/4 - 1/2 (0.251 mi.) | P95 | 202
Spill Number/Closed Date: 9007621 / 1990-12-04
Site ID: 235125
Spill Date: 1990-10-12

NORTH STAR INDUSTRIE | PETROVA AVE | W 1/4 - 1/2 (0.255 mi.) | Q96 | 207
Spill Number/Closed Date: 8911602 / 1990-03-07
Spill Number/Closed Date: 9712367 / 1998-02-05
Site ID: 238818
Site ID: 238820
Spill Date: 1990-03-07
Spill Date: 1998-02-04

TISSOT CONSTRUCTION | RT. 86 | ENE 1/4 - 1/2 (0.308 mi.) | 98 | 212
Spill Number/Closed Date: 0145038 / 2001-06-12
Site ID: 120228
Spill Date: 2001-06-11

CASIER'S - OLD TANK | BLOOMINGDALE ST | N 1/4 - 1/2 (0.309 mi.) | R99 | 213
Spill Number/Closed Date: 9901135 / 1999-05-17
Site ID: 76576
Spill Date: 1999-04-29

STEWARTS | BLOOMINGDALE ROAD & | N 1/4 - 1/2 (0.317 mi.) | R100 | 214
Spill Number/Closed Date: 9312279 / 1994-01-19

Site ID: 319324
Spill Date: 1994-01-19

STEWARTS SHOP #	BLOOMINGDALE AVE	N 1/4 - 1/2 (0.319 mi.)	R101	215
Spill Number/Closed Date: 9112342 / 2002-09-11				
Site ID: 182693				
Spill Date: 1992-03-04				
PETROVA AVE SCHOOL	PETROVA AVE	W 1/4 - 1/2 (0.323 mi.)	102	217
Spill Number/Closed Date: 9107092 / 1991-10-02				
Site ID: 238819				
Spill Date: 1991-10-02				
MRS KELTING	174 LAKE ST	WSW 1/4 - 1/2 (0.325 mi.)	103	218
Spill Number/Closed Date: 9509800 / 1995-11-07				
Site ID: 181770				
Spill Date: 1995-11-07				
SCHNECK RESIDENCE	FRANKLIN AVE.	E 1/4 - 1/2 (0.332 mi.)	104	219
Spill Number/Closed Date: 9515925 / 1996-03-04				
Site ID: 243136				
Spill Date: 1996-02-26				
45 FRANKLIN AVE	45 FRANLKIN AVE	ENE 1/4 - 1/2 (0.346 mi.)	105	221
Spill Number/Closed Date: 8808981 / 1989-10-04				
Site ID: 327366				
Spill Date: 1989-02-14				
IN FRONT OF RUSTY NA	BROADWAY	NNW 1/4 - 1/2 (0.348 mi.)	S106	222
Spill Number/Closed Date: 9945033 / 1999-05-14				
Site ID: 61852				
Spill Date: 1999-05-13				
SARANAC LAKE LANDFIL	***MCKENZIE POND ROAD***	***N 1/4 - 1/2 (0.349 mi.)***	***S108***	***223***
Spill Number/Closed Date: 9305475 / 1993-08-17				
Site ID: 193220				
Spill Date: 1993-07-31				
RUSTY NAIL	***BROADWAY STREET***	***NNW 1/4 - 1/2 (0.349 mi.)***	***S109***	***225***
Spill Number/Closed Date: 8910180 / 1990-01-24				
Site ID: 122388				
Spill Date: 1990-01-22				
MAINLINE GARAGE	***LAKE FLOWER AVENUE***	***E 1/4 - 1/2 (0.369 mi.)***	***110***	***228***
Spill Number/Closed Date: 8706905 / 1987-11-24				
Site ID: 287325				
Spill Date: 1987-06-10				
DURFEE RESIDENCE	2 FAIRVIEW AVENUE	NW 1/4 - 1/2 (0.380 mi.)	111	231
Spill Number/Closed Date: 9205763 / 1992-08-19				
Site ID: 329037				
Spill Date: 1992-08-18				
SHELLY VANCOUR RESID	340 GLENWOOD DRIVE	S 1/4 - 1/2 (0.408 mi.)	113	235
Spill Number/Closed Date: 0485104 / 2004-11-05				
Site ID: 333221				
Spill Date: 2004-11-01				
PJ HYDE & SON	***171 BROADWAY***	***NNW 1/4 - 1/2 (0.435 mi.)***	***T114***	***236***
Spill Number/Closed Date: 9209709 / 1995-12-18				
Spill Number/Closed Date: 9406734 / 1994-08-17				
Spill Number/Closed Date: 9407184 / 1994-08-26				
Spill Number/Closed Date: 9814305 / 1999-03-01				

Spill Number/Closed Date: 9903373 / 1999-07-08
*Additional key fields are available in the Map Findings section
Site ID: 74229
Site ID: 74233
Site ID: 74234
Site ID: 74240
Site ID: 74241
*Additional key fields are available in the Map Findings section
Spill Date: 1992-11-19
Spill Date: 1994-08-17
Spill Date: 1994-08-26
Spill Date: 1999-02-28
Spill Date: 1999-06-23
*Additional key fields are available in the Map Findings section

JOHN'S SUNOCO - FORM	***172 BROADWAY ST.***	***NNW 1/4 - 1/2 (0.446 mi.)***	***T115***	***253***
Spill Number/Closed Date: 8705769 / 1988-12-14 Site ID: 157299 Spill Date: 1987-10-08				
DUPREE RESIDENCE	LAKE FLOWER AVE	ESE 1/4 - 1/2 (0.465 mi.)	116	257
Spill Number/Closed Date: 9845038 / 1998-12-16 Site ID: 130116 Spill Date: 1998-10-01				
NO COUNTRY CHRISTIAN	212 LAKE FLOWER AV	ESE 1/4 - 1/2 (0.468 mi.)	U117	258
Spill Number/Closed Date: 9803041 / 1998-06-22 Spill Number/Closed Date: 9100066 / 1991-04-02 Site ID: 271172 Site ID: 176313 Spill Date: 1998-06-08 Spill Date: 1991-04-01				
MAIN LINE GARAGE	26 LAKE FLOWER AVENU	ESE 1/4 - 1/2 (0.471 mi.)	U118	261
Spill Number/Closed Date: 9406571 / 1996-08-22 Site ID: 106092 Spill Date: 1994-08-08				
MADDENS RENTAL PROPE	8 LAKE FLOWER AVE	ESE 1/4 - 1/2 (0.475 mi.)	U119	262
Spill Number/Closed Date: 9601576 / 1996-04-30 Site ID: 194449 Spill Date: 1996-04-30				
BIG D	87 RIVERSIDE DRIVE	SE 1/4 - 1/2 (0.477 mi.)	120	263
Spill Number/Closed Date: 9311945 / 1994-04-29 Site ID: 219724 Spill Date: 1994-01-04				

Lower Elevation	Address	Direction / Distance	Map ID	Page
PARNELL SHOE SALON	***MAIN STREET***	***0 - 1/8 (0.000 mi.)***	***A3***	***10***
Spill Number/Closed Date: 9300339 / 1993-04-07 Site ID: 310219 Spill Date: 1993-04-07				
OXFORD MARKET BLDG	***BROADWAY ST***	***NNE 1/8 - 1/4 (0.177 mi.)***	***I69***	***136***
Spill Number/Closed Date: 9004926 / 1994-01-10 Site ID: 122392 Spill Date: 1990-08-02				
PRIMETIME RESTAURANT	***42 BROADWAY STREET***	***N 1/8 - 1/4 (0.189 mi.)***	***K73***	***147***

Spill Number/Closed Date: 9810147 / 1998-11-12
Site ID: 238171
Spill Date: 1998-11-11

TRUDEAU INSTITUTE — 15 WOODRUFF STREET — NNE 1/8 - 1/4 (0.218 mi.) — N84 — 174
Spill Number/Closed Date: 8702601 / 1987-07-27
Site ID: 148841
Spill Date: 1987-06-30

DR. BALKIEWICZ — WOODRUFF STREET — NNE 1/8 - 1/4 (0.223 mi.) — N86 — 177
Spill Number/Closed Date: 9708228 / 1997-10-15
Site ID: 316552
Spill Date: 1997-10-14

PMS OUTFALL INTO SAR — WOODRUFF ST. — NNE 1/4 - 1/2 (0.279 mi.) — 97 — 209
Spill Number/Closed Date: 0345071 / 2006-10-17
Site ID: 134045
Spill Date: 2003-09-03

Lists of state and tribal registered storage tanks

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the UST list, as provided by EDR, has revealed that there are 16 UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
TOWN HALL	***30 MAIN ST***	***NE 0 - 1/8 (0.046 mi.)***	***C34***	***57***
Database: UST, Date of Government Version: 02/14/2023				
ATLANTIC REF. & MKTG	14 RIVER ST	ENE 0 - 1/8 (0.056 mi.)	E40	67
Database: UST, Date of Government Version: 02/14/2023				
ADIRONDACK BANK, FSB	60 MAIN ST	NNE 0 - 1/8 (0.105 mi.)	F58	97
Database: UST, Date of Government Version: 02/14/2023				
MARINE MIDLAND BANK	***70 MAIN ST***	***NNE 0 - 1/8 (0.118 mi.)***	***62***	***107***
Database: UST, Date of Government Version: 02/14/2023				
ST BERNARD'S CHURCH	***27 ST. BERNARD STREE***	***ENE 1/8 - 1/4 (0.156 mi.)***	***H63***	***110***
Database: UST, Date of Government Version: 02/14/2023				
RIVER STREET NICE N	***111 RIVER STREET***	***E 1/8 - 1/4 (0.164 mi.)***	***64***	***119***
Database: UST, Date of Government Version: 02/14/2023				
MAURICES BUILDING	10 BROADWAY	NNE 1/8 - 1/4 (0.168 mi.)	I67	132
Database: UST, Date of Government Version: 02/14/2023				
HOTEL SARANAC	100 MAIN ST	NE 1/8 - 1/4 (0.177 mi.)	J71	142
Database: UST, Date of Government Version: 02/14/2023				
SARANAC LAKE CENTRAL	141 PETROVA AVENUE	W 1/8 - 1/4 (0.200 mi.)	L78	160
Database: UST, Date of Government Version: 02/14/2023				
TRUDEAU INSTITUTE IN	18-22 WOODRUFF ST	NNE 1/8 - 1/4 (0.212 mi.)	N81	168
Database: UST, Date of Government Version: 02/14/2023				
DECHANTAL APARTMENTS	60 CHURCH ST	ENE 1/8 - 1/4 (0.213 mi.)	O82	171
Database: UST, Date of Government Version: 02/14/2023				
BURNS NEWS AGENCY IN	***28 WOODRUFF ST***	***NNE 1/8 - 1/4 (0.230 mi.)***	***N88***	***183***
Database: UST, Date of Government Version: 02/14/2023				

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
RIVERSIDE PROPERTIES	28-30 WOODRUFF STREE	NNE 1/8 - 1/4 (0.230 mi.)	N89	191
Database: UST, Date of Government Version: 02/14/2023				

Lower Elevation	Address	Direction / Distance	Map ID	Page
VILLAGE SARANAC LAKE	***3 MAIN STREET***	***ESE 0 - 1/8 (0.008 mi.)***	***A10***	***23***
Database: UST, Date of Government Version: 02/14/2023				
WILSON FARMS XPRESS	***25 MAIN STREET***	***ENE 0 - 1/8 (0.020 mi.)***	***A20***	***37***
Database: UST, Date of Government Version: 02/14/2023				
KEY BANK OF NEW YORK	55 BROADWAY STREET	N 1/8 - 1/4 (0.220 mi.)	K85	175
Database: UST, Date of Government Version: 02/14/2023				

AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the AST list, as provided by EDR, has revealed that there are 6 AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ADIRONDACK BANK	***60 MAIN STREET***	***NNE 0 - 1/8 (0.105 mi.)***	***F59***	***99***
Database: AST, Date of Government Version: 02/14/2023				
Facility Id: 5-231029				
ST BERNARD'S CHURCH	***27 ST. BERNARD STREE***	***ENE 1/8 - 1/4 (0.156 mi.)***	***H63***	***110***
Database: AST, Date of Government Version: 02/14/2023				
Facility Id: 5-422134				
HOTEL SARANAC	100 MAIN ST	NE 1/8 - 1/4 (0.177 mi.)	J70	138
Database: AST, Date of Government Version: 02/14/2023				
Facility Id: 5-422452				
SARANAC LAKE CENTRAL	141 PETROVA AVENUE	W 1/8 - 1/4 (0.200 mi.)	L76	153
Database: AST, Date of Government Version: 02/14/2023				
Facility Id: 5-230006				

Lower Elevation	Address	Direction / Distance	Map ID	Page
VILLAGE SARANAC LAKE	3 MAIN STREET	N 0 - 1/8 (0.113 mi.)	61	104
Database: AST, Date of Government Version: 02/14/2023				
Facility Id: 5-416703				
28 BROADWAY	28 BROADWAY	NNE 1/8 - 1/4 (0.211 mi.)	I80	166
Database: AST, Date of Government Version: 02/14/2023				
Facility Id: 5-515027				

TANKS: This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

A review of the TANKS list, as provided by EDR, has revealed that there is 1 TANKS site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
VERIZON NEW YORK INC	48 CHURCH STREET	ENE 1/8 - 1/4 (0.216 mi.)	O83	173
Database: TANKS, Date of Government Version: 02/14/2023				
Facility Id: 5-416371				
Site Status: Active				

Lists of state and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the VCP list, as provided by EDR, has revealed that there is 1 VCP site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
RIVER STREET NICE N	***111 RIVER STREET***	***E 1/8 - 1/4 (0.164 mi.)***	***64***	***119***
Database: VCP, Date of Government Version: 02/06/2023				
Site Code: 57893				

Lists of state and tribal brownfield sites

BROWNFIELDS: Brownfields Site List

A review of the BROWNFIELDS list, as provided by EDR, and dated 02/06/2023 has revealed that there is 1 BROWNFIELDS site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SARANAC LOFTS	120 BROADWAY	N 1/4 - 1/2 (0.401 mi.)	112	232
Site Code: 623777				

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

ODI: An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

A review of the ODI list, as provided by EDR, and dated 06/30/1985 has revealed that there is 1 ODI site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SARANAC LAKE VILLAGE	MCKENZIE POND RD	N 1/4 - 1/2 (0.349 mi.)	S107	223

EXECUTIVE SUMMARY

Local Lists of Hazardous waste / Contaminated Sites

DEL SHWS: A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

A review of the DEL SHWS list, as provided by EDR, and dated 02/06/2023 has revealed that there is 1 DEL SHWS site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SARANAC LAKE GAS CO. Site Code Id: 57075	PAYVILLE ROAD	ESE 1/2 - 1 (0.772 mi.)	121	264

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 02/06/2023 has revealed that there are 42 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SARANAC RIVER Spill Number/Closed Date: 0145138 / 2002-02-19 Site ID: 256431 Spill Date: 2002-02-15	RT. 3	NNW 0 - 1/8 (0.015 mi.)	B11	28
PUMP STATION @ NIMO Spill Number/Closed Date: 9111614 / 1992-02-11 Site ID: 331103 Spill Date: 1992-02-10	ROUTE 86	NNW 0 - 1/8 (0.015 mi.)	B12	29
SARANAC RIVER Spill Number/Closed Date: 9801448 / 1998-12-01 Site ID: 144144 Spill Date: 1998-05-03	RT 3, TOWARD BOOMING	NNW 0 - 1/8 (0.015 mi.)	B13	30
STORM SEWER OUTFALL Spill Number/Closed Date: 9310574 / 1999-04-23 Site ID: 114418 Spill Date: 1993-11-29	LAPAN HWY, RT. 3	NNW 0 - 1/8 (0.015 mi.)	B14	31
BEHIND PUMP STATION Spill Number/Closed Date: 9705049 / 1998-09-18 Site ID: 233127 Spill Date: 1997-07-27	RIVER ST.	NNW 0 - 1/8 (0.015 mi.)	B15	32
LAPAN HIGHWAY BRIDGE Spill Number/Closed Date: 9202680 / 1992-06-03 Site ID: 267743 Spill Date: 1992-06-03	LAPAN HIGHWAY	NNW 0 - 1/8 (0.015 mi.)	B16	33
SARANAC RIVER Spill Number/Closed Date: 9514240 / 1996-02-07 Site ID: 318773	RT 3	NNW 0 - 1/8 (0.015 mi.)	B17	34

Spill Date: 1996-02-05				
SARANAC RIVER Spill Number/Closed Date: 8803487 / 1988-07-21 Site ID: 217674 Spill Date: 1988-07-21	SARANAC LAKE	E 0 - 1/8 (0.025 mi.)	A22	44
SARANAC LAKE OFF DOR Spill Number/Closed Date: 0300692 / 2003-04-21 Site ID: 73494 Spill Date: 2003-04-19	ST BRIDGE-MUNICIPAL	NNW 0 - 1/8 (0.027 mi.)	B23	45
7-ELEVEN 35225 (WILS Spill Number/Closed Date: 1002076 / 2014-07-16 Site ID: 435173 Spill Date: 2010-04-23	MAIN AND RIVER ST	NE 0 - 1/8 (0.035 mi.)	A28	50
IN LAKE FLOWER OFF Spill Number/Closed Date: 1009429 / 2010-12-03 Site ID: 442965 Spill Date: 2010-12-03	14 KIWASSA RD	SE 0 - 1/8 (0.036 mi.)	D29	51
IN LAKE FLOWER Spill Number/Closed Date: 9603199 / 1996-06-07 Site ID: 221834 Spill Date: 1996-06-06	OFF RIVERSIDE DRIVE	ESE 0 - 1/8 (0.041 mi.)	D30	52
STORM SEWER OUTFALL Spill Number/Closed Date: 9606113 / 1996-08-13 Site ID: 189176 Spill Date: 1996-08-12	RIVER ST & ST BERNAR	ENE 0 - 1/8 (0.045 mi.)	E32	55
ST BERNARD'S CHURCH Spill Number/Closed Date: 9603678 / 1996-06-17 Site ID: 331023 Spill Date: 1996-06-17	***ST BERNARD ST***	***ENE 0 - 1/8 (0.046 mi.)***	***C35***	***60***
ST BERNARD CHURCH Spill Number/Closed Date: 9602812 / 1996-08-26 Site ID: 331022 Spill Date: 1996-05-20	ST BERNARD ST	ENE 0 - 1/8 (0.046 mi.)	C36	63
@ SARANAC LAKE TOWN Spill Number/Closed Date: 9205695 / 1992-08-17 Site ID: 310214 Spill Date: 1992-08-17	MAIN STREET	NNE 0 - 1/8 (0.053 mi.)	C38	65
ATLANTIC STATION Spill Number/Closed Date: 9408644 / 2002-09-03 Site ID: 149236 Spill Date: 1994-09-28	14 RIVER ST/ST. BERN	ENE 0 - 1/8 (0.056 mi.)	E39	66
BETWEEN T HALL/RICE Spill Number/Closed Date: 9009495 / 1990-11-30 Site ID: 310208 Spill Date: 1990-11-30	MAIN STREET	NNE 0 - 1/8 (0.057 mi.)	C42	75
COMMERCIAL BLDG Spill Number/Closed Date: 0211415 / 2003-02-16 Site ID: 60658 Spill Date: 2003-02-15	47 MAIN ST	NNE 0 - 1/8 (0.060 mi.)	C43	76
PARKING LOT BETWEEN	42 MAIN ST	NE 0 - 1/8 (0.069 mi.)	C44	77

Spill Number/Closed Date: 1811553 / 2019-02-20
Site ID: 582500
Spill Date: 2019-02-19

87 LAKE STREET | 87 LAKE STREET | WSW 0 - 1/8 (0.103 mi.) | 51 | 87
Spill Number/Closed Date: 1400270 / 2015-05-20
Site ID: 493505
Spill Date: 2014-04-08

ST. BERNARD'S CHURCH | ST. BERNARD ST | ENE 0 - 1/8 (0.104 mi.) | G52 | 88
Spill Number/Closed Date: 8912039 / 1990-03-21
Spill Number/Closed Date: 9108504 / 1991-11-08
Spill Number/Closed Date: 9207267 / 1993-06-10
Site ID: 261477
Site ID: 261478
Site ID: 261479
Spill Date: 1990-03-19
Spill Date: 1991-11-07
Spill Date: 1992-09-23

ST. BERNARD CHURCH | BERNARD ST. | ENE 0 - 1/8 (0.104 mi.) | G53 | 92
Spill Number/Closed Date: 8601987 / 1986-06-23
Site ID: 77431
Spill Date: 1986-06-23

ST. BERNARD'S CHURCH | CHURCH ST.(PRES.CHUR | ENE 0 - 1/8 (0.104 mi.) | G54 | 93
Spill Number/Closed Date: 8604804 / 2013-04-26
Site ID: 179985
Spill Date: 1986-10-25

ST. BERNARD'S CHURCH | BERNARD STREET | ENE 0 - 1/8 (0.104 mi.) | G56 | 95
Spill Number/Closed Date: 8605259 / 1986-11-18
Site ID: 132918
Spill Date: 1986-11-18

ST BERNARD'S CHURCH | ST BERNARDS STREET | ENE 0 - 1/8 (0.104 mi.) | G57 | 96
Spill Number/Closed Date: 9800404 / 1998-07-16
Site ID: 137660
Spill Date: 1998-04-09

MEYER'S HALLMARK (AL | 69 MAIN STREET | NNE 0 - 1/8 (0.109 mi.) | F60 | 103
Spill Number/Closed Date: 0145009 / 2001-08-20
Site ID: 213904
Spill Date: 2001-03-01

MARINE MIDLAND BANK | 70 MAIN ST | NNE 0 - 1/8 (0.118 mi.) | 62 | 107
Spill Number/Closed Date: 0202668 / 2002-07-08
Site ID: 155144
Spill Date: 2002-05-23

Lower Elevation	Address	Direction / Distance	Map ID	Page

SARANAC RIVER FROM D | MAIN ST. | 0 - 1/8 (0.000 mi.) | A1 | 8
Spill Number/Closed Date: 9945094 / 1999-08-04
Site ID: 77613
Spill Date: 1999-08-04

TOWN HALL | MAIN STREET | 0 - 1/8 (0.000 mi.) | A2 | 9
Spill Number/Closed Date: 8909365 / 1989-12-27
Site ID: 310203
Spill Date: 1989-12-27

PARNELL SHOE SALON | MAIN STREET | 0 - 1/8 (0.000 mi.) | A3 | 10

Spill Number/Closed Date: 0345061 / 2003-12-22
Spill Number/Closed Date: 0345082 / 2003-10-14
Site ID: 310195
Site ID: 310196
Spill Date: 2003-08-20
Spill Date: 2003-10-13

LAKE FLOWER BRIDGE	MAIN STREET	0 - 1/8 (0.000 mi.)	A4	13
Spill Number/Closed Date: 9011046 / 1991-05-29				
Site ID: 310209				
Spill Date: 1991-01-16				
SARANAC RIVER S.L.	MAIN ST.(QUONSET HUT	0 - 1/8 (0.000 mi.)	A5	14
Spill Number/Closed Date: 9402274 / 1994-05-16				
Site ID: 66307				
Spill Date: 1994-05-15				
METH LAB CLEAN UP	1 MAIN STREET	0 - 1/8 (0.001 mi.)	A7	15
Spill Number/Closed Date: 1305742 / 2013-12-13				
Site ID: 486322				
Spill Date: 2013-08-29				
SARANAC LAKE VILLAGE	10 MAIN ST.	E 0 - 1/8 (0.008 mi.)	A9	20
Spill Number/Closed Date: 9411066 / 1994-11-18				
Spill Number/Closed Date: 8808379 / 1989-01-25				
Site ID: 252206				
Site ID: 274408				
Spill Date: 1994-11-18				
Spill Date: 1989-01-20				
VILLAGE SARANAC LAKE	***3 MAIN STREET***	***ESE 0 - 1/8 (0.008 mi.)***	***A10***	***23***
Spill Number/Closed Date: 9802463 / 1998-05-26				
Spill Number/Closed Date: 9210815 / 1992-12-17				
Site ID: 162308				
Site ID: 163349				
Spill Date: 1998-05-26				
Spill Date: 1992-12-17				
AMERIGAS TRUCK	23 MAIN STREET	ENE 0 - 1/8 (0.019 mi.)	A18	36
Spill Number/Closed Date: 2203128 / 2022-07-15				
Site ID: 639229				
Spill Date: 2022-07-12				
WILSON FARMS XPRESS	***25 MAIN STREET***	***ENE 0 - 1/8 (0.020 mi.)***	***A20***	***37***
Spill Number/Closed Date: 1008012 / 2011-02-18				
Spill Number/Closed Date: 1007948 / 2011-02-18				
Spill Number/Closed Date: 0611041 / 2007-01-04				
Site ID: 441468				
Site ID: 441400				
Site ID: 375610				
Spill Date: 2010-09-17				
Spill Date: 2010-09-28				
Spill Date: 2007-01-03				
SARANAC RIVER OUTFAL	RT 3/MAIN ST.	NE 0 - 1/8 (0.027 mi.)	C24	46
Spill Number/Closed Date: 0108954 / 2001-12-10				
Site ID: 135291				
Spill Date: 2001-12-08				
OUTFALL BHND LITTLE	MAIN ST.	NE 0 - 1/8 (0.027 mi.)	C25	47
Spill Number/Closed Date: 9945202 / 2006-09-25				

Site ID: 77614 Spill Date: 2000-01-03				
TOWN OF HARRIETSTOWN Spill Number/Closed Date: 1409941 / 2017-10-05 Site ID: 503595 Spill Date: 2015-01-09	39 MAIN ST	NE 0 - 1/8 (0.035 mi.)	A27	49
BEHIND THE WATER HOL Spill Number/Closed Date: 9600492 / 1996-04-10 Site ID: 310221 Spill Date: 1996-04-10	MAIN STREET	NNE 0 - 1/8 (0.046 mi.)	C33	56

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 03/06/2023 has revealed that there are 5 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ATLANTIC SERVICE STA EPA ID:: NYD986960706	***14 RIVER ST***	***ENE 0 - 1/8 (0.056 mi.)***	***E41***	***71***
SIR SPEEDY PRINTING EPA ID:: NYN008014185	42 MAIN ST	NE 0 - 1/8 (0.069 mi.)	C45	79
NYNEX EPA ID:: NYD981129729	***26 CHURCH ST***	***ENE 1/8 - 1/4 (0.228 mi.)***	***M87***	***178***
ADIRONDACK DAILY ENT EPA ID:: NYN008014193	61 BROADWAY	N 1/8 - 1/4 (0.245 mi.)	P92	197

Lower Elevation	Address	Direction / Distance	Map ID	Page
SARANAC LAKE VILLAGE EPA ID:: NYR000114025	***10 MAIN ST***	***E 0 - 1/8 (0.008 mi.)***	***A8***	***16***

FINDS: The Facility Index System contains both facility information and "pointers" to other sources of information that contain more detail. These include: RCRIS; Permit Compliance System (PCS); Aerometric Information Retrieval System (AIRS); FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]; CERCLIS; DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes); Federal Underground Injection Control (FURS); Federal Reporting Data System (FRDS); Surface Impoundments (SIA); TSCA Chemicals in Commerce Information System (CICS); PADS; RCRA-J (medical waste transporters/disposers); TRIS; and TSCA. The source of this database is the U.S. EPA/NTIS.

A review of the FINDS list, as provided by EDR, and dated 02/02/2023 has revealed that there is 1 FINDS site within approximately 0.001 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LALANDE PROPERTY - D Registry ID:: 110019596800	4 DORSEY ST	0 - 1/8 (0.000 mi.)	6	15

PFAS ECHO: Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

A review of the PFAS ECHO list, as provided by EDR, and dated 03/30/2023 has revealed that there is 1 PFAS ECHO site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HARRIETSTOWN SANITAR		NE 0 - 1/8 (0.045 mi.)	C31	54

MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the MANIFEST list, as provided by EDR, and dated 01/01/2019 has revealed that there are 4 MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ATLANTIC SERVICE STA EPA ID: NYD986960706	***14 RIVER ST***	***ENE 0 - 1/8 (0.056 mi.)***	***E41***	***71***
SARANAC LAKE CSD - P EPA ID: NYD987014651	***141 PETROVA AVE***	***W 1/8 - 1/4 (0.200 mi.)***	***L75***	***151***
NYNEX EPA ID: NYD981129729	***26 CHURCH ST***	***ENE 1/8 - 1/4 (0.228 mi.)***	***M87***	***178***

Lower Elevation	Address	Direction / Distance	Map ID	Page
SARANAC LAKE VILLAGE EPA ID: NYR000114025	***10 MAIN ST***	***E 0 - 1/8 (0.008 mi.)***	***A8***	***16***

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past

sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 3 EDR Hist Auto sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HOYT TAXI SERVICE	53 MAIN ST	NNE 0 - 1/8 (0.070 mi.)	F46	82


Lower Elevation	Address	Direction / Distance	Map ID	Page
NONNA FINA	23 MAIN ST	ENE 0 - 1/8 (0.019 mi.)	A19	37
CASSIDY GERALD F	27 MAIN ST	ENE 0 - 1/8 (0.021 mi.)	A21	43

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 6 records.

Site Name	Database(s)
SARANAC QUARRY	LTANKS
SARANAC LAKE BUS GARAGE	LTANKS
TRUDEAU BUILDING	LTANKS, NY Spills
ADELPHIA CABLE	LTANKS
NIAGARA MOHAWK	LTANKS
SARANAC LAKE	LTANKS

OVERVIEW MAP - 7391856.2S



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- County Boundary
- Power transmission lines
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	APA HQ - Phase I ESA	CLIENT:	Bergmann Associates
ADDRESS:	13 Main Street Saranac Lake NY 12983	CONTACT:	Mary K Legawiec
LAT/LONG:	44.324429 / 74.132928	INQUIRY #:	7391856.2s
		DATE:	July 17, 2023 3:47 pm

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 7391856.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

Sensitive Receptors

National Priority List Sites

Dept. Defense Sites

0 1/16 1/8 1/4 Miles

Indian Reservations BIA

County Boundary

National Wetland Inventory

State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	APA HQ - Phase I ESA	CLIENT:	Bergmann Associates
ADDRESS:	13 Main Street Saranac Lake NY 12983	CONTACT:	Mary K Legawiec
LAT/LONG:	44.324429 / 74.132928	INQUIRY #:	7391856.2s
		DATE:	July 17, 2023 3:50 pm

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Lists of Federal NPL (Superfund) sites								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Lists of Federal Delisted NPL sites								
Delisted NPL	1.000		0	0	0	0	NR	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Lists of Federal CERCLA sites with NFRAP								
SEMS-ARCHIVE	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA facilities undergoing Corrective Action								
CORRACTS	1.000		0	0	0	0	NR	0
Lists of Federal RCRA TSD facilities								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA generators								
RCRA-LQG	0.250		0	0	NR	NR	NR	0
RCRA-SQG	0.250		0	0	NR	NR	NR	0
RCRA-VSQG	0.250		0	1	NR	NR	NR	1
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	0.001		0	NR	NR	NR	NR	0
Lists of state- and tribal hazardous waste facilities								
SHWS	1.000		0	0	0	0	NR	0
Lists of state and tribal landfills and solid waste disposal facilities								
SWF/LF	0.500		1	0	0	NR	NR	1
Lists of state and tribal leaking storage tanks								
INDIAN LUST	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
LTANKS	0.500		11	13	26	NR	NR	50
HIST LTANKS	0.500		0	0	0	NR	NR	0
Lists of state and tribal registered storage tanks								
FEMA UST	0.250		0	0	NR	NR	NR	0
UST	0.250		6	10	NR	NR	NR	16
CBS UST	0.250		0	0	NR	NR	NR	0
MOSF UST	0.500		0	0	0	NR	NR	0
MOSF	0.500		0	0	0	NR	NR	0
CBS	0.250		0	0	NR	NR	NR	0
AST	0.250		2	4	NR	NR	NR	6
CBS AST	0.250		0	0	NR	NR	NR	0
MOSF AST	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
TANKS	0.250		0	1	NR	NR	NR	1
State and tribal institutional control / engineering control registries								
RES DECL	0.125		0	NR	NR	NR	NR	0
ENG CONTROLS	0.500		0	0	0	NR	NR	0
INST CONTROL	0.500		0	0	0	NR	NR	0
Lists of state and tribal voluntary cleanup sites								
VCP	0.500		0	1	0	NR	NR	1
INDIAN VCP	0.500		0	0	0	NR	NR	0
Lists of state and tribal brownfield sites								
BROWNFIELDS	0.500		0	0	1	NR	NR	1
ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
SWTIRE	0.500		0	0	0	NR	NR	0
SWRCY	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	1	NR	NR	1
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	0.001		0	NR	NR	NR	NR	0
DEL SHWS	1.000		0	0	0	1	NR	1
US CDL	0.001		0	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
HIST UST	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
HIST AST	0.001		0	NR	NR	NR	NR	0
Local Land Records								
LIENS	0.001		0	NR	NR	NR	NR	0
LIENS 2	0.001		0	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	0.001		0	NR	NR	NR	NR	0
NY Spills	0.125		42	NR	NR	NR	NR	42
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
SPILLS 90	0.125		0	NR	NR	NR	NR	0
SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		3	2	NR	NR	NR	5
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	0.001		0	NR	NR	NR	NR	0
EPA WATCH LIST	0.001		0	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	0.001		0	NR	NR	NR	NR	0
TRIS	0.001		0	NR	NR	NR	NR	0
SSTS	0.001		0	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	0.001		0	NR	NR	NR	NR	0
RAATS	0.001		0	NR	NR	NR	NR	0
PRP	0.001		0	NR	NR	NR	NR	0
PADS	0.001		0	NR	NR	NR	NR	0
ICIS	0.001		0	NR	NR	NR	NR	0
FTTS	0.001		0	NR	NR	NR	NR	0
MLTS	0.001		0	NR	NR	NR	NR	0
COAL ASH DOE	0.001		0	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	0.001		0	NR	NR	NR	NR	0
RADINFO	0.001		0	NR	NR	NR	NR	0
HIST FTTS	0.001		0	NR	NR	NR	NR	0
DOT OPS	0.001		0	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	0.001		0	NR	NR	NR	NR	0
US AIRS	0.001		0	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	0.001		1	NR	NR	NR	NR	1
ECHO	0.001		0	NR	NR	NR	NR	0
DOCKET HWC	0.001		0	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
PFAS NPL	0.250		0	0	NR	NR	NR	0
PFAS FEDERAL SITES	0.250		0	0	NR	NR	NR	0
PFAS TSCA	0.250		0	0	NR	NR	NR	0
PFAS RCRA MANIFEST	0.250		0	0	NR	NR	NR	0
PFAS ATSDR	0.250		0	0	NR	NR	NR	0
PFAS WQP	0.250		0	0	NR	NR	NR	0
PFAS NPDES	0.250		0	0	NR	NR	NR	0
PFAS ECHO	0.250		1	0	NR	NR	NR	1
PFAS ECHO FIRE TRAINING	0.250		0	0	NR	NR	NR	0
PFAS PART 139 AIRPORT	0.250		0	0	NR	NR	NR	0
AQUEOUS FOAM NRC	0.250		0	0	NR	NR	NR	0
PFAS	0.250		0	0	NR	NR	NR	0
AIRS	0.001		0	NR	NR	NR	NR	0
COAL ASH	0.500		0	0	0	NR	NR	0
DRYCLEANERS	0.250		0	0	NR	NR	NR	0
E DESIGNATION	0.125		0	NR	NR	NR	NR	0
Financial Assurance	0.001		0	NR	NR	NR	NR	0
HSWDS	0.500		0	0	0	NR	NR	0
LEAD	0.001		0	NR	NR	NR	NR	0
MANIFEST	0.250		2	2	NR	NR	NR	4
SPDES	0.001		0	NR	NR	NR	NR	0
VAPOR REOPENED	0.500		0	0	0	NR	NR	0
UIC	0.001		0	NR	NR	NR	NR	0
COOLING TOWERS	0.001		0	NR	NR	NR	NR	0
MINES MRDS	0.001		0	NR	NR	NR	NR	0
PFAS TRIS	0.250		0	0	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	0	NR	0
EDR Hist Auto	0.125		3	NR	NR	NR	NR	3
EDR Hist Cleaner	0.125		0	NR	NR	NR	NR	0
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
RGA HWS	0.001		0	NR	NR	NR	NR	0
RGA LF	0.001		0	NR	NR	NR	NR	0
- Totals --		0	72	34	28	1	0	135

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1 **SARANAC RIVER FROM DRAIN** **NY Spills** **S104193663**
MAIN ST. **N/A**
< 1/8 **SARANAC LAKE, NY**
1 ft.

Site 1 of 17 in cluster A

Relative: SPILLS:
Lower

Actual:
1509 ft.

Name:	SARANAC RIVER FROM DRAIN
Address:	MAIN ST.
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9945094 / 1999-08-04
Facility ID:	9945094
Facility Type:	ER
DER Facility ID:	275064
Site ID:	77613
DEC Region:	5
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	1700
Spill Date:	1999-08-04
Investigator:	RDHUYCK
Referred To:	Not reported
Reported to Dept:	1999-08-04
CID:	Not reported
Water Affected:	SARANAC RIVER
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-08-04
Spill Record Last Update:	1999-08-04
Spiller Name:	DICK LUCEY
Spiller Company:	NORTHERN TECHNICAL SERVIC
Spiller Address:	MAIN ST.
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RH RFC: Source identified and discharge ceased. "
Remarks:	"Caller reports sheen/odors entering river through 48 storm drain behind Little Italy. RH investigated, determined NTS pumping contaminated water into storm drain versus sanitary, RH corrected situation."

All Materials:

Site ID:	77613
Operable Unit ID:	1090052
Operable Unit:	01
Material ID:	566191
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

SARANAC RIVER FROM DRAIN (Continued) **S104193663**

Resource Affected: Surface Water
Oxygenate: Not reported

A2 **TOWN HALL** **NY Spills** **S102118691**
MAIN STREET **N/A**
< 1/8 **SARANAC LAKE, NY**
1 ft.

Site 2 of 17 in cluster A

Relative: SPILLS:
Lower
Name: TOWN HALL
Actual: Address: MAIN STREET
1509 ft. City,State,Zip: SARANAC LAKE, NY
Spill Number/Closed Date: 8909365 / 1989-12-27
Facility ID: 8909365
Facility Type: ER
DER Facility ID: 284751
Site ID: 310203
DEC Region: 5
Spill Cause: Unknown
Spill Class: Not reported
SWIS: 1700
Spill Date: 1989-12-27
Investigator: MPMCLEAN
Referred To: Not reported
Reported to Dept: 1989-12-17
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: 1989-12-27
Cleanup Meets Std: True
Last Inspection: 1989-12-27
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1989-12-27
Spill Record Last Update: 1998-03-27
Spiller Name: Not reported
Spiller Company: UNKNOWN/NONE
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM
"
Remarks: "REPORT OF GAS ODORS/PETRO IN BOILER ROOM. MM ON SITE, HNU NEGATIVE, NO PETRO ON FLOOR, APPEARS TO BE WATER AND COAL DUST. NO ACTION TAKEN."

All Materials:
Site ID: 310203
Operable Unit ID: 936534
Operable Unit: 01
Material ID: 442527
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported

TOWN HALL (Continued) **S102118691**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Air
Oxygenate:	Not reported

A3 **PARNELL SHOE SALON** **LTANKS S100495005**
MAIN STREET **NY Spills N/A**
< 1/8 **SARANAC LAKE, NY**
1 ft.

Site 3 of 17 in cluster A

Relative: LTANKS:
Lower

Actual: Name:	PARNELL SHOE SALON
1509 ft. Address:	MAIN STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9300339 / 1993-04-07
Facility ID:	9300339
Site ID:	310219
Spill Date:	1993-04-07
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	1993-04-07
SWIS:	1700
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1993-04-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-04-07
Spill Record Last Update:	1995-12-21
Spiller Name:	Not reported
Spiller Company:	PARNELL SHOE SALON
Spiller Address:	MAIN STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	284751
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM 04/07/93: BUCKET PLACED UNDER TANK. CONTACTED OWNER AND ADVISED TO EMPTY TANK ASAP. NO FURTHER DEC ACTION UNLESS TANK FAILS IN INTERIM. TANK HAS BEEN LEAKING FOR OVER 5 DAYS. RFC: Minor spill, owner to clean up, pump out tank. "
Remarks:	"STORE CLERK NOTICED OIL ODOR. FULL TANK, NOT USED - ALL ELECTRIC HEATTANK,WEEPING. OWNER DOES NOT WANT IT PUMPED OUT UNTIL HE ARRIVES ON SITE AT SOME TIME NEXT WEEK. MM ON SITE 4/7/93, SLOW DRIP."

PARNELL SHOE SALON (Continued) **S100495005**

All Materials:

Site ID:	310219
Operable Unit ID:	982241
Operable Unit:	01
Material ID:	557022
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

SPILLS:

Name:	SARANAC RIVER
Address:	MAIN STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	0345061 / 2003-12-22
Facility ID:	0345061
Facility Type:	ER
DER Facility ID:	284751
Site ID:	310195
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	1700
Spill Date:	2003-08-20
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	2003-08-20
CID:	Not reported
Water Affected:	SARANAC RIVER
Spill Source:	Unknown
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-08-21
Spill Record Last Update:	2004-01-06
Spiller Name:	Not reported
Spiller Company:	UNDETERMINABLE/SEVERAL
Spiller Address:	RESIDENCES
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM MM to check outfall periodically. 12/22/03: Site work completed, no further monitoring required. RFC: Site work complete, no further sheens expected. "
Remarks:	"DOT upgrading storm sewer lines and disturbing outfall behind Little

PARNELL SHOE SALON (Continued) **S100495005**

Italy. Material being collected/contained as possible but minor sheen is escaping. Advised caller of situation, contractor preventing release as possible."

All Materials:

Site ID:	310195
Operable Unit ID:	881512
Operable Unit:	01
Material ID:	496693
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

Name:	OUTFALL BHND LITTLE ITALY
Address:	MAIN STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	0345082 / 2003-10-14
Facility ID:	0345082
Facility Type:	ER
DER Facility ID:	284751
Site ID:	310196
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	1700
Spill Date:	2003-10-13
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	2003-10-13
CID:	Not reported
Water Affected:	SARANAC RIVER
Spill Source:	Unknown
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-10-14
Spill Record Last Update:	2003-10-14
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM 10/14/03: MM checked area 0800 hrs, pad/boom still inplace, same odors. RFC: No evidence of new release. "
Remarks:	"Continuing calls on odors/sheen at outfall. "

PARNELL SHOE SALON (Continued) **S100495005**

All Materials:

Site ID:	310196
Operable Unit ID:	881525
Operable Unit:	01
Material ID:	496715
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

A4 **LAKE FLOWER BRIDGE** **NY Spills** **S102119105**
MAIN STREET **N/A**
< 1/8 **SARANAC LAKE, NY**
1 ft.

Site 4 of 17 in cluster A

Relative: **Lower**
Actual: **1509 ft.**

SPILLS:

Name:	LAKE FLOWER BRIDGE
Address:	MAIN STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9011046 / 1991-05-29
Facility ID:	9011046
Facility Type:	ER
DER Facility ID:	284751
Site ID:	310209
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	1700
Spill Date:	1991-01-16
Investigator:	AWStemp
Referred To:	Not reported
Reported to Dept:	1991-01-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	DEC
Cleanup Ceased:	1991-05-29
Cleanup Meets Std:	True
Last Inspection:	1991-05-01
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1991-01-18
Spill Record Last Update:	1991-05-29
Spiller Name:	C: TOM ROTH
Spiller Company:	SHICKEL???
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was

LAKE FLOWER BRIDGE (Continued) **S102119105**

Remarks: AS/MM 05/29/91: CLEANUP
ADEQUATE, CONTRACTOR REIMBURSED DEPARTMENT FOR PADS. "
"OIL ON WATER SURFACE, ALONG SHORELINE ON RIVERSIDE DRIVE. SORBENTS GIVEN TO CONTRACTOR, TOLD TO CLEAN UP. 1/17-MM/AS ON SITE, FREE PRODUCT STILL IN LAKE, CONTRACTOR GIVEN MORE PADS, TO CLEANUP."

All Materials:

Site ID:	310209
Operable Unit ID:	951244
Operable Unit:	01
Material ID:	431140
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

A5 **SARANAC RIVER S.L.** **NY Spills** **S102119789**
MAIN ST.(QUONSET HUT BLD) **N/A**
< 1/8 **SARANAC LAKE, NY**
1 ft.

Site 5 of 17 in cluster A

Relative: Lower
Actual: 1509 ft.

SPILLS:

Name:	SARANAC RIVER S.L.
Address:	MAIN ST.(QUONSET HUT BLD)
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9402274 / 1994-05-16
Facility ID:	9402274
Facility Type:	ER
DER Facility ID:	63515
Site ID:	66307
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	D3
SWIS:	1700
Spill Date:	1994-05-15
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1994-05-15
CID:	Not reported
Water Affected:	SARANAC RIVER
Spill Source:	Unknown
Spill Notifier:	Citizen
Cleanup Ceased:	1994-05-16
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-05-16
Spill Record Last Update:	1996-01-24
Spiller Name:	Not reported

SARANAC RIVER S.L. (Continued) **S102119789**

Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM RFC: Sheen in parking lot. No action taken. "
Remarks:	"FISHERMAN OBSERBED OIL IN RIVER COMING FROM STORM SEWER SYSTEM. MM CHECKED AREA @ 1100 HRS 5/16/94. MINOR SHEEN ENTERING INTO STORM CULVERT FROM PARKING AREA, NO OTHER PROBLEMS FOUND."

All Materials:

Site ID:	66307
Operable Unit ID:	995959
Operable Unit:	01
Material ID:	386015
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

---

6 **LALANDE PROPERTY - DORSEY ST** **FINDS** **1016326638**
4 DORSEY ST **N/A**
< 1/8 **SARANAC LAKE, NY 12983**
1 ft.

Relative: Higher
Actual: 1579 ft.

FINDS:
Registry ID: 110019596800

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

A7 **METH LAB CLEAN UP** **NY Spills** **S113915566**
1 MAIN STREET **N/A**
< 1/8 **SARANAC LAKE, NY**
0.001 mi.
3 ft. **Site 6 of 17 in cluster A**

Relative: Lower
Actual: 1511 ft.

SPILLS:

Name:	METH LAB CLEAN UP
Address:	1 MAIN STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	1305742 / 2013-12-13
Facility ID:	1305742
Facility Type:	ER

METH LAB CLEAN UP (Continued) **S113915566**

DER Facility ID:	441434
Site ID:	486322
DEC Region:	5
Spill Cause:	Deliberate
Spill Class:	C3
SWIS:	1746
Spill Date:	2013-08-29
Investigator:	BXHANKIN
Referred To:	Not reported
Reported to Dept:	2013-08-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-08-29
Spill Record Last Update:	2013-12-16
Spiller Name:	INVEST. LEANNE COLBY
Spiller Company:	JOSEPH D. WILLIAMS
Spiller Address:	155 BROADWAY APT 3
Spiller Company:	999
Contact Name:	INVEST. LEANNE COLBY
DEC Memo:	"12/13/13: final bill recieved. NFA required."
Remarks:	"Meth lab cleanup."

All Materials:

Site ID:	486322
Operable Unit ID:	1235969
Operable Unit:	01
Material ID:	2235267
Material Code:	0063A
Material Name:	unknown hazardous material
Case No.:	Not reported
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

A8 **SARANAC LAKE VILLAGE OF WATER PLANT** **RCRA NonGen / NLR** **1006810591**
East **10 MAIN ST** **MANIFEST** **NYR000114025**
< 1/8 **SARANAC LAKE, NY 12983**
0.008 mi.
42 ft. **Site 7 of 17 in cluster A**

Relative: **Lower**
Actual: **1515 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Saranac Lake Village Of Water Plant
Handler Address:	10 MAIN ST
Handler City,State,Zip:	SARANAC LAKE, NY 12983
EPA ID:	NYR000114025

SARANAC LAKE VILLAGE OF WATER PLANT (Continued) **1006810591**

Contact Name:	ROBERT MARTIN
Contact Address:	MAIN ST
Contact City,State,Zip:	SARANAC LAKE, NY 12983
Contact Telephone:	518-891-4160
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R5
Mailing Address:	MAIN ST
Mailing City,State,Zip:	SARANAC LAKE, NY 12983
Owner Name:	Village Of Saranac Lake
Owner Type:	Municipal
Operator Name:	Saranac Lake Water Plant
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No

SARANAC LAKE VILLAGE OF WATER PLANT (Continued) **1006810591**

Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	VILLAGE OF SARANAC LAKE
Legal Status:	Municipal
Date Became Current:	20030219
Date Ended Current:	Not reported
Owner/Operator Address:	2 MAIN ST
Owner/Operator City,State,Zip:	SARANAC LAKE, NY 12983
Owner/Operator Telephone:	518-891-4150
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	SARANAC LAKE WATER PLANT
Legal Status:	Municipal
Date Became Current:	20030219
Date Ended Current:	Not reported
Owner/Operator Address:	10 MAIN ST
Owner/Operator City,State,Zip:	SARANAC LAKE, NY 12983
Owner/Operator Telephone:	518-891-4160
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	VILLAGE OF SARANAC LAKE
Legal Status:	Municipal
Date Became Current:	20030219
Date Ended Current:	Not reported
Owner/Operator Address:	2 MAIN ST
Owner/Operator City,State,Zip:	SARANAC LAKE, NY 12983
Owner/Operator Telephone:	518-891-4150
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	SARANAC LAKE WATER PLANT
Legal Status:	Municipal
Date Became Current:	20030219
Date Ended Current:	Not reported

SARANAC LAKE VILLAGE OF WATER PLANT (Continued) **1006810591**

Owner/Operator Address: 10 MAIN ST
Owner/Operator City,State,Zip: SARANAC LAKE, NY 12983
Owner/Operator Telephone: 518-891-4160
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20060101
Handler Name: SARANAC LAKE VILLAGE OF WATER PLANT
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: SARANAC LAKE VILLAGE OF WATER PLANT
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20030219
Handler Name: SARANAC LAKE VILLAGE OF WATER PLANT
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:

NAICS Code: 22131
NAICS Description: WATER SUPPLY AND IRRIGATION SYSTEMS

Facility Has Received Notices of Violations:

Violations: No Violations Found

Evaluation Action Summary:

SARANAC LAKE VILLAGE OF WATER PLANT (Continued) **1006810591**

Evaluations: No Evaluations Found

NY MANIFEST:

Name:	VILLAGE OF SARANAC LAKE
Address:	10 MAIN ST
City,State,Zip:	SARANAC LAKE, NY 12983
Country:	USA
EPA ID:	NYR000114025
Facility Status:	Not reported
Location Address 1:	10 MAIN STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	SARANAC LAKE
Location State:	NY
Location Zip:	12983
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000114025
Mailing Name:	VILLAGE OF SARANAC LAKE
Mailing Contact:	DAN EVANS
Mailing Address 1:	10 MAIN STREET
Mailing Address 2:	Not reported
Mailing City:	SARANAC LAKE
Mailing State:	NY
Mailing Zip:	12983
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5188914257

A9 **SARANAC LAKE VILLAGE** **NY Spills** **S103561844**
East **10 MAIN ST.** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.008 mi.
42 ft. **Site 8 of 17 in cluster A**

Relative:
Lower

Actual:
1515 ft.

SPILLS:

Name:	SARANAC LAKE VILLAGE
Address:	10 MAIN ST.
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9411066 / 1994-11-18
Facility ID:	9411066
Facility Type:	ER
DER Facility ID:	206671
Site ID:	252206
DEC Region:	5
Spill Cause:	Other
Spill Class:	C3
SWIS:	1700
Spill Date:	1994-11-18
Investigator:	LJMILLIO
Referred To:	Not reported
Reported to Dept:	1994-11-18
CID:	Not reported
Water Affected:	Not reported

SARANAC LAKE VILLAGE (Continued) **S103561844**

Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	1994-11-18
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-11-18
Spill Record Last Update:	1996-03-19
Spiller Name:	Not reported
Spiller Company:	SARANAC LAKE VILLAGE
Spiller Address:	10 MAIN ST.
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was LM RFC: No contamination evident after tank was pulled. "
Remarks:	"8,000 G UST REMOVED, NO CONTAMINATION EVIDENT, REPLACING TANK. LUCK BROS. DOING REMOVAL. HYDE'S WILL OPEN AND CLEAN, LB WILL REMOVE UST."

All Materials:

Site ID:	252206
Operable Unit ID:	1004943
Operable Unit:	01
Material ID:	376924
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

Name:	TOWN HALL
Address:	10 MAIN STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	8808379 / 1989-01-25
Facility ID:	8808379
Facility Type:	ER
DER Facility ID:	223196
Site ID:	274408
DEC Region:	5
Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	1700
Spill Date:	1989-01-20
Investigator:	AWStemp
Referred To:	Not reported
Reported to Dept:	1989-01-20
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Affected Persons
Cleanup Ceased:	1989-01-25

SARANAC LAKE VILLAGE (Continued) **S103561844**

Cleanup Meets Std:	True
Last Inspection:	1989-01-25
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1989-01-20
Spill Record Last Update:	1989-01-25
Spiller Name:	Not reported
Spiller Company:	GETTY/GRIFFITH OIL
Spiller Address:	JOHN MUNN ROAD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AS/MM 01/25/89: GRIFFITH HIRED FOURTH COAST TO PUMP OUT CULVERT OF WASTE OIL, ALSO DRAIN AT STATION. 550 GALLON TANK OF WASTE OIL ALSO EMPTIED. SPILL CLEANED ADEQUATELY. "
Remarks:	"GASOLINE ODORS IN TOWN HALL. POSSIBLE SLUG FROM VEHICLE. WASTE OIL ALSO NOTICED IN SEWER. TRACED TO FLOOR DRAINS AT GETTY.GETTY/GRIFFITH OIL COMPANY TO CLEAN UP."

All Materials:

Site ID:	274408
Operable Unit ID:	924789
Operable Unit:	01
Material ID:	453139
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Site ID:	274408
Operable Unit ID:	924789
Operable Unit:	01
Material ID:	453140
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

A10
ESE
< 1/8
0.008 mi.
43 ft.

VILLAGE SARANAC LAKE
3 MAIN STREET
SARANAC LAKE, NY 12983

Site 9 of 17 in cluster A

Relative:
Lower

Actual:
1509 ft.

UST **U001846604**
NY Spills **N/A**

UST:

Name:	VILLAGE SARANAC LAKE
Address:	3 MAIN STREET
City,State,Zip:	SARANAC LAKE, NY 12983
Id/Status:	5-416703 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	5
Expiration Date:	10/02/2027
UTM X:	569212.17405
UTM Y:	4908242.59861
Site Type:	Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)

Affiliation Records:

Site Id:	39482
Affiliation Type:	Mail Contact
Company Name:	VILLAGE SARANAC LAKE
Contact Type:	Not reported
Contact Name:	VILLAGE MANAGER
Address1:	39 MAIN STREET
Address2:	2ND FLOOR, SUITE 9
City:	SARANAC LAKE
State:	NY
Zip Code:	12983
Country Code:	001
Phone:	(518) 891-4150
EMail:	MANAGER@SARANACLAKENY.GOV
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2013-01-04

Site Id:	39482
Affiliation Type:	Facility Owner
Company Name:	VILLAGE SARANAC LAKE
Contact Type:	DPW SUPERINTENDENT
Contact Name:	DUSTIN MARTIN
Address1:	39 MAIN STREET
Address2:	Not reported
City:	SARANAC LAKE
State:	NY
Zip Code:	12983
Country Code:	001
Phone:	(518) 891-4150
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BXHANKIN
Date Last Modified:	2019-12-27

Site Id:	39482
Affiliation Type:	Emergency Contact
Company Name:	VILLAGE SARANAC LAKE
Contact Type:	Not reported
Contact Name:	DUSTIN MARTIN
Address1:	Not reported

VILLAGE SARANAC LAKE (Continued) **U001846604**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(518) 354-0595
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BXHANKIN
Date Last Modified:	2019-12-27

Site Id:	39482
Affiliation Type:	Facility Operator
Company Name:	VILLAGE SARANAC LAKE
Contact Type:	Not reported
Contact Name:	DUSTIN MARTIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 891-4160
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BXHANKIN
Date Last Modified:	2019-12-27

Tank Info:

Tank Number:	001
Tank ID:	104248
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	8000
Install Date:	Not reported
Date Tank Closed:	11/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None

VILLAGE SARANAC LAKE (Continued) **U001846604**

C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 002
Tank ID: 104249
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 2000
Install Date: 12/01/1967
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 003
Tank ID: 109435
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 2000
Install Date: 11/01/1994
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 06/15/2015
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

VILLAGE SARANAC LAKE (Continued) **U001846604**

I05 - Overfill - Vent Whistle
G04 - Tank Secondary Containment - Double-Walled (Underground)
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
D10 - Pipe Type - Copper
F05 - Pipe External Protection - Jacketed
J05 - Dispenser - On Site Heating System (Supply/Return)
C03 - Pipe Location - Aboveground/Underground Combination
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
E00 - Piping Secondary Containment - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
B02 - Tank External Protection - Original Sacrificial Anode

SPILLS:

Name:	SARANAC RIVER
Address:	2 MAIN ST
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9802463 / 1998-05-26
Facility ID:	9802463
Facility Type:	ER
DER Facility ID:	136958
Site ID:	162308
DEC Region:	5
Spill Cause:	Traffic Accident
Spill Class:	C4
SWIS:	1700
Spill Date:	1998-05-26
Investigator:	SELALOND
Referred To:	Not reported
Reported to Dept:	1998-05-26
CID:	233
Water Affected:	SARANAC LAKE
Spill Source:	Passenger Vehicle
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1998-05-26
Spill Record Last Update:	1998-05-28
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SL RFC: Truck removed, no spillage occurred. "
Remarks:	"PU truck went into river spilling gas into water."

All Materials:

Site ID:	162308
Operable Unit ID:	1062999
Operable Unit:	01

VILLAGE SARANAC LAKE (Continued) **U001846604**

Material ID:	320792
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

Name:	HYDE'S FUEL
Address:	2 MAIN STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9210815 / 1992-12-17
Facility ID:	9210815
Facility Type:	ER
DER Facility ID:	137779
Site ID:	163349
DEC Region:	5
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1700
Spill Date:	1992-12-17
Investigator:	RLWAGNER
Referred To:	Not reported
Reported to Dept:	1992-12-17
CID:	Not reported
Water Affected:	SARANAC RIVER
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	1992-12-17
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-12-18
Spill Record Last Update:	1995-12-11
Spiller Name:	Not reported
Spiller Company:	VILLAGE OFFICES
Spiller Address:	2 MAIN ST.
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RW RFC: Cleanup complete, was fully contained. "
Remarks:	"RW INVESTIGATED SMALL SPILL. NO DISCHARGE TO RIVER. NO FURTHER ACTION."

All Materials:

Site ID:	163349
Operable Unit ID:	977454
Operable Unit:	01
Material ID:	404256
Material Code:	0001A
Material Name:	#2 fuel oil

VILLAGE SARANAC LAKE (Continued) **U001846604**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	13.00
Units:	G
Recovered:	13.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

B11 **SARANAC RIVER** **NY Spills** **S107410122**
NNW **RT. 3** **N/A**
< 1/8 **SARANAC RIVER, NY**
0.015 mi.
81 ft. **Site 1 of 8 in cluster B**

Relative:
Higher

Actual:
1536 ft.

SPILLS:

Name:	SARANAC RIVER
Address:	RT. 3
City,State,Zip:	SARANAC RIVER, NY
Spill Number/Closed Date:	0145138 / 2002-02-19
Facility ID:	0145138
Facility Type:	ER
DER Facility ID:	280321
Site ID:	256431
DEC Region:	5
Spill Cause:	Deliberate
Spill Class:	C4
SWIS:	1700
Spill Date:	2002-02-15
Investigator:	LJMILLIO
Referred To:	Not reported
Reported to Dept:	2002-02-15
CID:	Not reported
Water Affected:	SARANAC RIVER
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-02-19
Spill Record Last Update:	2002-02-19
Spiller Name:	Not reported
Spiller Company:	VILLAGE OF SARANAC LAKE
Spiller Address:	VAN BUREN ST.
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was LM 02/15/02: LM spoke with Lt. Bill Crain regarding concerns of snow being dumped into river. Lt. found out that VK was on site during day. Village had a water main break, no dumping of snow occured. RFC: No dumping occurred."
Remarks:	"Caller watched Village of Saranac Lake dump snow into the Saranac River."

SARANAC RIVER (Continued) **S107410122**

All Materials:

Site ID:	256431
Operable Unit ID:	851808
Operable Unit:	01
Material ID:	526984
Material Code:	1629A
Material Name:	sand
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

B12 **PUMP STATION @ NIMO** **NY Spills** **S102116976**
NNW **ROUTE 86** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.015 mi.
81 ft. **Site 2 of 8 in cluster B**

Relative: **Higher**

Actual: **1536 ft.**

SPILLS:

Name:	PUMP STATION @ NIMO
Address:	ROUTE 86
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9111614 / 1992-02-11
Facility ID:	9111614
Facility Type:	ER
DER Facility ID:	278491
Site ID:	331103
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	1700
Spill Date:	1992-02-10
Investigator:	RDHUYCK
Referred To:	Not reported
Reported to Dept:	1992-02-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Affected Persons
Cleanup Ceased:	1992-02-11
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-02-11
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	VILLAGE OF SARANAC LAKE
Spiller Address:	MAIN STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RH

PUMP STATION @ NIMO (Continued) **S102116976**

"

Remarks: "SAWAGE OVERFLOWING PUMP STATION, RUNNING ACROSS ROAD AND INTO LAKE, RESPONCE TAKEN BY DOW, NO ACTION BY SPILL RESPONSE."

All Materials:

Site ID:	331103
Operable Unit ID:	961913
Operable Unit:	01
Material ID:	416636
Material Code:	0062A
Material Name:	raw sewage
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

B13 **SARANAC RIVER** **NY Spills** **S102242880**
NNW **RT 3, TOWARD BOOMINGDALE** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.015 mi.
81 ft. **Site 3 of 8 in cluster B**

Relative:
Higher

Actual:
1536 ft.

SPILLS:

Name:	SARANAC RIVER
Address:	RT 3, TOWARD BOOMINGDALE
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9801448 / 1998-12-01
Facility ID:	9801448
Facility Type:	ER
DER Facility ID:	122886
Site ID:	144144
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	A1
SWIS:	1600
Spill Date:	1998-05-03
Investigator:	SELALOND
Referred To:	Not reported
Reported to Dept:	1998-05-03
CID:	323
Water Affected:	SARANAC RIVER
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-05-03
Spill Record Last Update:	1998-12-22
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported

SARANAC RIVER (Continued) **S102242880**

Spiller Company:	999
Contact Name:	STEVEN PAYE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SL 12/22/98: Final ISR sent to Albany. RFC: Unable to locate source; cleanup complete. "
Remarks:	"SHEEN ON THE RIVER, UNKNOWN WHERE IT IS COMING FROM. INVESTIGATING AT THIS TIME."

All Materials:

Site ID:	144144
Operable Unit ID:	1059083
Operable Unit:	01
Material ID:	323386
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

B14 **STORM SEWER OUTFALL** **NY Spills** **S102119567**
NNW **LAPAN HWY, RT. 3** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.015 mi.
81 ft. **Site 4 of 8 in cluster B**

Relative: **Higher**

Actual: **1536 ft.**

SPILLS:

Name:	STORM SEWER OUTFALL
Address:	LAPAN HWY, RT. 3
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9310574 / 1999-04-23
Facility ID:	9310574
Facility Type:	ER
DER Facility ID:	99785
Site ID:	114418
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	C1
SWIS:	1700
Spill Date:	1993-11-29
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1993-11-29
CID:	Not reported
Water Affected:	L FLOWER,SARANAC R
Spill Source:	Unknown
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-12-01

STORM SEWER OUTFALL (Continued) **S102119567**

Spill Record Last Update:	1999-04-30
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM RFC: Sheen has not be evident for a few months. "
Remarks:	"STRONG PETROLEUM ODORS COMING FROM STORM SEWER AT THE NEW HYDRAULIC JUMP STORM SEWER OUTFALL. UNKNOWN SOURCE."

All Materials:

Site ID:	114418
Operable Unit ID:	992295
Operable Unit:	01
Material ID:	389665
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

B15 **BEHIND PUMP STATION** **NY Spills** **S102665943**
NNW **RIVER ST.** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.015 mi.
81 ft. **Site 5 of 8 in cluster B**

Relative: Higher
Actual: 1536 ft.

SPILLS:

Name:	BEHIND PUMP STATION
Address:	RIVER ST.
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9705049 / 1998-09-18
Facility ID:	9705049
Facility Type:	ER
DER Facility ID:	192081
Site ID:	233127
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	A1
SWIS:	1700
Spill Date:	1997-07-27
Investigator:	SELALOND
Referred To:	Not reported
Reported to Dept:	1997-07-28
CID:	999
Water Affected:	SARANAC RIVER
Spill Source:	Unknown
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported

BEHIND PUMP STATION (Continued) **S102665943**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-07-28
Spill Record Last Update:	1998-09-18
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	SARANAC LAKE FIRE DEPT
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SL RFC: Unable to locate source. "
Remarks:	"SHEEN IN RIVER - FIRE DEPT ON SCENE - REQUESTING DEC RESPONSE."

All Materials:

Site ID:	233127
Operable Unit ID:	1050923
Operable Unit:	01
Material ID:	334272
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

B16 **LAPAN HIGHWAY BRIDGE** **NY Spills** **S102117130**
NNW **LAPAN HIGHWAY** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.015 mi.
81 ft. **Site 6 of 8 in cluster B**

Relative: **Higher**
Actual: **1536 ft.**

SPILLS:

Name:	LAPAN HIGHWAY BRIDGE
Address:	LAPAN HIGHWAY
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9202680 / 1992-06-03
Facility ID:	9202680
Facility Type:	ER
DER Facility ID:	218112
Site ID:	267743
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	D6
SWIS:	1700
Spill Date:	1992-06-03
Investigator:	RLWAGNER
Referred To:	Not reported
Reported to Dept:	1992-06-03
CID:	Not reported
Water Affected:	SARANAC RIVER
Spill Source:	Unknown
Spill Notifier:	Citizen

LAPAN HIGHWAY BRIDGE (Continued) **S102117130**

Cleanup Ceased:	1992-06-03
Cleanup Meets Std:	True
Last Inspection:	1992-06-03
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-06-11
Spill Record Last Update:	1995-11-17
Spiller Name:	Not reported
Spiller Company:	UNKNOWN/NONE
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RW RFC: Material determined to be pine pollen and foam from upstream dam. No further action needed. "
Remarks:	"REPORT OF OIL SHEEN PRESENT IN RIVER FOR SEVERAL DAYS. RW INVESTIGATED 6/3-NO OIL, POLLEN AND FOAM FROM DAM NOTED ONLY."

All Materials:

Site ID:	267743
Operable Unit ID:	966758
Operable Unit:	01
Material ID:	413914
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

B17 **SARANAC RIVER** **NY Spills** **S107408085**
NNW **RT 3** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.015 mi.
81 ft. **Site 7 of 8 in cluster B**

Relative: **Higher**

Actual: **1536 ft.**

SPILLS:

Name:	SARANAC RIVER
Address:	RT 3
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9514240 / 1996-02-07
Facility ID:	9514240
Facility Type:	ER
DER Facility ID:	256957
Site ID:	318773
DEC Region:	5
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	1700
Spill Date:	1996-02-05
Investigator:	LJMILLIO
Referred To:	Not reported
Reported to Dept:	1996-02-07

SARANAC RIVER (Continued) **S107408085**

CID:	351
Water Affected:	SARANAC RIVER
Spill Source:	Passenger Vehicle
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-02-08
Spill Record Last Update:	1996-06-03
Spiller Name:	Not reported
Spiller Company:	TONY BROOKS
Spiller Address:	PO BOX
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was LM 02/07/96: Tony parks his car at friends house - to a message to him, call Nick Cole 891-3351. Owner of sled - Eric Poole, Neill St., Saranac Lake, NY 891-1514. "
Remarks:	"Snowmobile went through ice 1/2 mi north of Saranac Lake F & G Club in 7ft of water. Call faxed from region 5 on 02/07/96."

All Materials:

Site ID:	318773
Operable Unit ID:	1028781
Operable Unit:	01
Material ID:	354373
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

Site ID:	318773
Operable Unit ID:	1028781
Operable Unit:	01
Material ID:	354372
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

A18 **AMERIGAS TRUCK** **NY Spills** **S128912863**
ENE **23 MAIN STREET** **N/A**
< 1/8 **SARANAC LAKE, NY 12983**
0.019 mi.
102 ft. **Site 10 of 17 in cluster A**

Relative: **Lower**

Actual: **1520 ft.**

SPILLS:

Name:	AMERIGAS TRUCK
Address:	23 MAIN STREET
City,State,Zip:	SARANAC LAKE, NY 12983
Spill Number/Closed Date:	2203128 / 2022-07-15
Facility ID:	2203128
Facility Type:	ER
DER Facility ID:	585823
Site ID:	639229
DEC Region:	5
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1746
Spill Date:	2022-07-12
Investigator:	KMZAPPIA
Referred To:	Not reported
Reported to Dept:	2022-07-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2022-07-12
Spill Record Last Update:	2022-07-15
Spiller Name:	Not reported
Spiller Company:	AMERA GAS
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	RICK
DEC Memo:	"7/12/2022: AmeriGas was collecting a propane tank at the corner of Main Street and Route 3 in Saranac Lake (Little Italy) when the hydraulic line on their truck blew causing a release of approx. 8-10 gallons of hydraulic oil. The Saranac Lake fire dept. was onsite and remediated the area using speedy dry. The speedy dry was put down until it was no longer absorbing product. There is staining left on the sidewalk, but no free product visible. The release was contained to the sidewalk and road, no other resources affected. MSDS Sheet obtained and filed in D2. RFC: NFA are needed at this time."
Remarks:	"Truck lost fluid, contained. no impacts to water"

All Materials:

Site ID:	639229
Operable Unit ID:	1386280
Operable Unit:	01
Material ID:	2401040

AMERIGAS TRUCK (Continued) **S128912863**

Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	8.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

A19 **NONNA FINA** **EDR Hist Auto** **1021638713**
ENE **23 MAIN ST** **N/A**
< 1/8 **SARANAC LAKE, NY 12983**
0.019 mi.
102 ft. **Site 11 of 17 in cluster A**

Relative: EDR Hist Auto
Lower

Actual: **1520 ft.**

Year:	Name:	Type:
2010	NONNA FINA	Gasoline Service Stations, NEC

A20 **WILSON FARMS XPRESS #591** **UST** **U000385364**
ENE **25 MAIN STREET** **NY Spills** **N/A**
< 1/8 **SARANAC LAKE, NY 12983**
0.020 mi.
105 ft. **Site 12 of 17 in cluster A**

Relative: UST:
Lower

Actual: **1520 ft.**

Name:	WILSON FARMS XPRESS #591
Address:	25 MAIN STREET
City,State,Zip:	SARANAC LAKE, NY 12983
Id/Status:	5-507520 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	5
Expiration Date:	N/A
UTM X:	569217.74434
UTM Y:	4908356.58860
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	40200
Affiliation Type:	Emergency Contact
Company Name:	WILSON FARMS, INC.
Contact Type:	Not reported
Contact Name:	RICHARD HALL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(716) 204-4333
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI

WILSON FARMS XPRESS #591 (Continued) **U000385364**

Date Last Modified: 2019-12-27

Site Id: 40200
Affiliation Type: Facility Operator
Company Name: WILSON FARMS XPRESS #591
Contact Type: Not reported
Contact Name: WILSON FARMS,INC.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NY
Zip Code: Not reported
Country Code: 001
Phone: (518) 891-6590
EMail: Not reported
Fax Number: Not reported
Modified By: bxhankin
Date Last Modified: 2008-05-16

Site Id: 40200
Affiliation Type: Facility Owner
Company Name: WILSON FARMS, INC.
Contact Type: COMPLIANCE SPECIALIST
Contact Name: MARK BECKER
Address1: 1780 WEHRLE DRIVE
Address2: Not reported
City: WILLIAMSVILLE
State: NY
Zip Code: 14221
Country Code: 001
Phone: (716) 204-4333
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2022-08-19

Site Id: 40200
Affiliation Type: Mail Contact
Company Name: 7-ELEVEN, INC
Contact Type: Not reported
Contact Name: MARK BECKER
Address1: 1780 WEHRLE DRIVE
Address2: Not reported
City: WILLIAMSVILLE
State: NY
Zip Code: 14221
Country Code: 001
Phone: (716) 830-9807
EMail: MARKBECKER@7-11.COM
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2022-04-08

Tank Info:

Tank Number: 006
Tank ID: 106712

WILSON FARMS XPRESS #591 (Continued) **U000385364**

Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	10/01/1990
Date Tank Closed:	06/04/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2722
Common Name of Substance:	Kerosene [#1 Fuel Oil] (Resale/Redistribute)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	C
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E00 - Piping Secondary Containment - None
I00 - Overfill - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	007
Tank ID:	106713
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	8000
Install Date:	10/01/1990
Date Tank Closed:	06/04/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	D
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

L99 - Piping Leak Detection - Other
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
F04 - Pipe External Protection - Fiberglass

WILSON FARMS XPRESS #591 (Continued) **U000385364**

C02 - Pipe Location - Underground/On-ground
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	008
Tank ID:	106714
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	10000
Install Date:	10/01/1990
Date Tank Closed:	06/04/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	D
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

L99 - Piping Leak Detection - Other
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
G04 - Tank Secondary Containment - Double-Walled (Underground)

SPILLS:

Name:	UNKNOWN
Address:	25 MAIN STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	1008012 / 2011-02-18
Facility ID:	1008012
Facility Type:	ER
DER Facility ID:	325229
Site ID:	441468
DEC Region:	5
Spill Cause:	Other

WILSON FARMS XPRESS #591 (Continued) **U000385364**

Spill Class:	C4
SWIS:	1746
Spill Date:	2010-09-17
Investigator:	BXHANKIN
Referred To:	Not reported
Reported to Dept:	2010-10-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-10-29
Spill Record Last Update:	2011-03-10
Spiller Name:	DIANE
Spiller Company:	UNKNOWN
Spiller Address:	25 MAIN STREET
Spiller Company:	999
Contact Name:	DIANE
DEC Memo:	"see spill 1007948"
Remarks:	"Caller stated there is a discrepnancy in fuel logs."

All Materials:

Site ID:	441468
Operable Unit ID:	1192030
Operable Unit:	01
Material ID:	2187250
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Name:	WILSON FARMS 591
Address:	25 MAIN ST
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	1007948 / 2011-02-18
Facility ID:	1007948
Facility Type:	ER
DER Facility ID:	396436
Site ID:	441400
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	1746
Spill Date:	2010-09-28
Investigator:	BXHANKIN
Referred To:	Not reported
Reported to Dept:	2010-10-27

WILSON FARMS XPRESS #591 (Continued) **U000385364**

CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-10-27
Spill Record Last Update:	2011-03-10
Spiller Name:	Not reported
Spiller Company:	WILSON FARMS
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	STAN MCGRAIN
DEC Memo:	"10-day inventory investigation sent in 2/18/11. NFA required."
Remarks:	"cleanup done"

All Materials:

Site ID:	441400
Operable Unit ID:	1191964
Operable Unit:	01
Material ID:	2187182
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Name:	WILSON FARMS
Address:	25 MAIN STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	0611041 / 2007-01-04
Facility ID:	0611041
Facility Type:	ER
DER Facility ID:	325229
Site ID:	375610
DEC Region:	5
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	1746
Spill Date:	2007-01-03
Investigator:	GJHANDLY
Referred To:	Not reported
Reported to Dept:	2007-01-03
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True

WILSON FARMS XPRESS #591 (Continued) **U000385364**

Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-01-03
Spill Record Last Update:	2007-01-04
Spiller Name:	KIRK DADGE
Spiller Company:	WILSON FARMS
Spiller Address:	25 MAIN STREET
Spiller Company:	001
Contact Name:	KIRK DADGE
DEC Memo:	"GH inspected location. Gasoline confined to onsite pavement and concrete pad. No impact to soil or surface water. OpTech called for cleanup. Cleanup was completed using sorbants. No further action required."
Remarks:	"customer overfilled his tank and in process of cleaning up: dec on site"

All Materials:

Site ID:	375610
Operable Unit ID:	1133231
Operable Unit:	01
Material ID:	2123034
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Resource Affected:	Soil
Oxygenate:	Not reported

A21 **CASSIDY GERALD F** **EDR Hist Auto** **1021010596**
ENE **27 MAIN ST** **N/A**
< 1/8 **SARANAC LAKE, NY 12983**
0.021 mi.
109 ft. **Site 13 of 17 in cluster A**

Relative: EDR Hist Auto
Lower

Actual:
1520 ft.

Year:	Name:	Type:
1974	CASSIDY GERALD F	Gasoline Service Stations
1975	CASSIDY GERALD F	Gasoline Service Stations
1976	CASSIDY GERALD F	Gasoline Service Stations
1977	CASSIDY GERALD F	Gasoline Service Stations
1978	CASSIDY GERALD F	Gasoline Service Stations
1979	CASSIDY GERALD F	Gasoline Service Stations
1980	CASSIDY GERALD F	Gasoline Service Stations
1982	CASSIDY GERALD F	Gasoline Service Stations
1983	CASSIDY GERALD F	Gasoline Service Stations

A22 **SARANAC RIVER** **NY Spills** **S102118228**
East **SARANAC LAKE** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.025 mi.
132 ft. **Site 14 of 17 in cluster A**

Relative:
Higher

Actual:
1530 ft.

SPILLS:

Name:	SARANAC RIVER
Address:	SARANAC LAKE
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	8803487 / 1988-07-21
Facility ID:	8803487
Facility Type:	ER
DER Facility ID:	180102
Site ID:	217674
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	1700
Spill Date:	1988-07-21
Investigator:	RDHUYCK
Referred To:	Not reported
Reported to Dept:	1988-07-21
CID:	Not reported
Water Affected:	SARANAC RIVER
Spill Source:	Unknown
Spill Notifier:	Citizen
Cleanup Ceased:	1988-07-21
Cleanup Meets Std:	True
Last Inspection:	1988-07-21
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1988-07-22
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RH "
Remarks:	"CITIZEN REPORTED OILY SHEEN ON WATER NEAR CHURCH STREET BRIDGE. RH INVESTIGATED, UNABLE TO LOCATE ANYTHING."

All Materials:

Site ID:	217674
Operable Unit ID:	920654
Operable Unit:	01
Material ID:	562354
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

B23
NNW
< 1/8
0.027 mi.
141 ft.

SARANAC LAKE OFF DORSEY
ST BRIDGE-MUNICIPAL LOT
SARANAC LAKE, NY

Site 8 of 8 in cluster B

NY Spills **S106013311**
N/A

Relative:
Higher

Actual:
1559 ft.

SPILLS:

Name:	SARANAC LAKE OFF DORSEY
Address:	ST BRIDGE-MUNICIPAL LOT
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	0300692 / 2003-04-21
Facility ID:	0300692
Facility Type:	ER
DER Facility ID:	69171
Site ID:	73494
DEC Region:	5
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	1700
Spill Date:	2003-04-19
Investigator:	RBMULVEY
Referred To:	Not reported
Reported to Dept:	2003-04-19
CID:	199
Water Affected:	SARANAC LAKE
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-04-19
Spill Record Last Update:	2003-04-21
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	RANDALL ROBERSON
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RM 04/21/03: RM on site - confirms a red fire extinguisher in river. Called Robert Martin 891-4160 Village DPW and informed him. Village will recover. RFC: Not a spill, more a litter issue.o"
Remarks:	"Caller states there is a fire extinguisher in the river at location - appears to have been dropped - unk if it is leaking or not. "

All Materials:

Site ID:	73494
Operable Unit ID:	868881
Operable Unit:	01
Material ID:	508768
Material Code:	0063A
Material Name:	unknown hazardous material
Case No.:	Not reported
Material FA:	Hazardous Material
Quantity:	.00
Units:	G
Recovered:	.00

SARANAC LAKE OFF DORSEY (Continued) **S106013311**

Resource Affected:	Surface Water
Oxygenate:	Not reported

C24 **SARANAC RIVER OUTFALL** **NY Spills** **S105236505**
NE **RT 3/MAIN ST.** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.027 mi.
144 ft. **Site 1 of 13 in cluster C**

Relative: **Lower**

Actual: **1522 ft.**

SPILLS:

Name:	SARANAC RIVER OUTFALL
Address:	RT 3/MAIN ST.
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	0108954 / 2001-12-10
Facility ID:	0108954
Facility Type:	ER
DER Facility ID:	116166
Site ID:	135291
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	A2
SWIS:	1700
Spill Date:	2001-12-08
Investigator:	GJHANDLY
Referred To:	Not reported
Reported to Dept:	2001-12-08
CID:	281
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-12-08
Spill Record Last Update:	2001-12-11
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	DAVE CILLEY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GH Known source of odor. NYSDEC will continue to monitor. 12/09/01: LM on site to check if outfall has additional problems other than what is currently being monitored. RFC: Active under spill # 9945202."
Remarks:	"CALLER REPORTS THAT THERE IS A DRAIN PIPE IN REAR OF RESTAURANT AND THERE IS AN ODOR COMMING FROM PIPE. CALLER IS REQUESTING CALLBACK FROM DEC REGIONAL OFFICE."

All Materials:

Site ID:	135291
Operable Unit ID:	846341
Operable Unit:	01

SARANAC RIVER OUTFALL (Continued) **S105236505**

Material ID:	530163
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Air
Oxygenate:	Not reported

C25 **OUTFALL BHND LITTLE ITALY** **NY Spills** **S104509281**
NE **MAIN ST.** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.027 mi.
144 ft. **Site 2 of 13 in cluster C**

Relative: **Lower**

Actual: **1522 ft.**

SPILLS:

Name:	OUTFALL BHND LITTLE ITALY
Address:	MAIN ST.
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9945202 / 2006-09-25
Facility ID:	9945202
Facility Type:	ER
DER Facility ID:	270944
Site ID:	77614
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	B1
SWIS:	1746
Spill Date:	2000-01-03
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	2000-01-03
CID:	Not reported
Water Affected:	SARANAC RIVER
Spill Source:	Unknown
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-01-20
Spill Record Last Update:	2006-09-27
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"09/25/06: Outfall sampled for several years, dissolved levels of contaminants decreasing with time, no further sampling pursued, no source ID possible. RFC: No further sampling. 09/27/06: Final ISR sent to Albany."
Remarks:	"Odors in outfall reported, additional samples to be collected by

OUTFALL BHND LITTLE ITALY (Continued) **S104509281**

Life Science Lab. River Walk now adjacent to outfall."

All Materials:

Site ID:	77614
Operable Unit ID:	1090170
Operable Unit:	01
Material ID:	290452
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Resource Affected:	Air, Surface Water
Oxygenate:	Not reported

A26 **SARANAC LAKE LF (V)** **SWF/LF** **S127086646**
NE **881 MCKENZIE ROAD 89 MAIN STREET 39 MAIN STREET** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.035 mi.
184 ft. **Site 15 of 17 in cluster A**

Relative: **Lower**
Actual: **1527 ft.**

SWF/LF:

Name:	SARANAC LAKE LF (V)
Address:	881 MCKENZIE ROAD 89 MAIN STREET 39 MAIN STREET
City,State,Zip:	SARANAC LAKE, NY
Flag:	INACTIVE
Region Code:	5
Phone Number:	Not reported
Owner Name:	Sullivan, William & Mary Village of Saranac Lake Village of Saranac Lake
Owner Type:	Private Municipal Municipal
Owner Address:	881 McKenzie Pond Rd
Owner Addr2:	Not reported
Owner City,St,Zip:	Saranac Lake, NY 12983
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	MSW
Activity Number:	Not reported
Active:	Not reported
East Coordinate:	Not reported
North Coordinate:	Not reported
Accuracy Code:	1: Good; Perimeter clear
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

A27
NE
< 1/8
0.035 mi.
184 ft.

TOWN OF HARRIETSTOWN TOWN HALL
39 MAIN ST
SARANAC LAKE, NY

Site 16 of 17 in cluster A

NY Spills **S117394360**
N/A

Relative:
Lower

Actual:
1527 ft.

SPILLS:

Name:	TOWN OF HARRIETSTOWN TOWN HALL
Address:	39 MAIN ST
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	1409941 / 2017-10-05
Facility ID:	1409941
Facility Type:	ER
DER Facility ID:	458523
Site ID:	503595
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	B1
SWIS:	1746
Spill Date:	2015-01-09
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	2015-01-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-01-09
Spill Record Last Update:	2017-10-05
Spiller Name:	Not reported
Spiller Company:	UNABLE TO DETERMINE
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	EDWARD RANDIG 524-0487 CELL
DEC Memo:	"01/20/15: Soil and GW samples collected by Op-Tech identified gasoline contamination. DEC to further investigate source, install treatment of GW and soil vapor extraction as practical. 07/14/15: Aztech completes summary report. Sub-slab depressuration system (SSDS) installed. Boiler room sump being treated thru carbon filtration. Quarterly monitoring ongoing. 04/06/17: Updated Aztech report received, SSDS working properly, contaminants in sump minimal and do not require carbon treatment. RFC: Harrietstown to maintain SSDS, No further sampling or monitoring is necessary by the Department."
Remarks:	"During excavation a fuel spill was found in soil and gw. Op-Tech is on scene. Unknown source, gas station nearby is undergoing remediation."

All Materials:

Site ID:	503595
Operable Unit ID:	1252948

TOWN OF HARRIETSTOWN TOWN HALL (Continued) **S117394360**

Operable Unit:	01
Material ID:	2255111
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil, Groundwater
Oxygenate:	Not reported

Site ID:	503595
Operable Unit ID:	1252948
Operable Unit:	01
Material ID:	2255110
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil, Groundwater
Oxygenate:	Not reported

A28 **7-ELEVEN 35225 (WILSON FARMS 591)** **NY Spills** **S110490637**
NE **MAIN AND RIVER ST** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.035 mi.
184 ft. **Site 17 of 17 in cluster A**

Relative: **Higher**

Actual: **1528 ft.**

SPILLS:

Name:	7-ELEVEN 35225 (WILSON FARMS 591)
Address:	MAIN AND RIVER ST
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	1002076 / 2014-07-16
Facility ID:	1002076
Facility Type:	ER
DER Facility ID:	390071
Site ID:	435173
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	1746
Spill Date:	2010-04-23
Investigator:	BXHANKIN
Referred To:	Not reported
Reported to Dept:	2010-05-24
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False

7-ELEVEN 35225 (WILSON FARMS 591) (Continued) **S110490637**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-05-24
Spill Record Last Update:	2014-07-22
Spiller Name:	Not reported
Spiller Company:	WILSON FARMS 591
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	RICH HALL
DEC Memo:	"4/13/12: Recieved quarterly report. 03/22/12: Recieved annual report. Contamination still exist. 7/16/14: Closure report received showing majority of contamination excavated onsite. Closed as not meeting standards as contamination still exist under roadway. See PBS 5-507520 for closure report."
Remarks:	"testing shows contamination"

All Materials:

Site ID:	435173
Operable Unit ID:	1185965
Operable Unit:	01
Material ID:	2180731
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Resource Affected:	Soil, Groundwater
Oxygenate:	Not reported

D29 **IN LAKE FLOWER OFF** **NY Spills** **S110750790**
SE **14 KIWASSA RD** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.036 mi.
188 ft. **Site 1 of 2 in cluster D**

Relative: Higher
Actual: 1542 ft.

SPILLS:

Name:	IN LAKE FLOWER OFF
Address:	14 KIWASSA RD
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	1009429 / 2010-12-03
Facility ID:	1009429
Facility Type:	ER
DER Facility ID:	397920
Site ID:	442965
DEC Region:	5
Spill Cause:	Traffic Accident
Spill Class:	C4
SWIS:	1746
Spill Date:	2010-12-03
Investigator:	BXHANKIN
Referred To:	Not reported
Reported to Dept:	2010-12-03
CID:	Not reported
Water Affected:	LAKE FLOWER

IN LAKE FLOWER OFF (Continued) **S110750790**

Spill Source:	Passenger Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-12-03
Spill Record Last Update:	2010-12-28
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	OFFICER SWAIN
DEC Memo:	"car removed, no spill. NFA required"
Remarks:	"car drove off rd and into lake flower vehicle is completly submerged, unk if any fluids have been released. Request call back. **0420 Officer Swain called to advise the vehicle has been removed from the water, no fluids appear to have been released.**"

All Materials:

Site ID:	442965
Operable Unit ID:	1193459
Operable Unit:	01
Material ID:	2188845
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Surface Water
Oxygenate:	Not reported

D30 **IN LAKE FLOWER** **NY Spills** **S102243123**
ESE **OFF RIVERSIDE DRIVE** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.041 mi.
219 ft. **Site 2 of 2 in cluster D**

Relative: **Higher**
Actual: **1529 ft.**

SPILLS:

Name:	IN LAKE FLOWER
Address:	OFF RIVERSIDE DRIVE
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9603199 / 1996-06-07
Facility ID:	9603199
Facility Type:	ER
DER Facility ID:	183470
Site ID:	221834
DEC Region:	5
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	1700
Spill Date:	1996-06-06
Investigator:	MPMCLEAN

IN LAKE FLOWER (Continued) **S102243123**

Referred To:	Not reported
Reported to Dept:	1996-06-06
CID:	322
Water Affected:	LAKE FLOWER
Spill Source:	Passenger Vehicle
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-06-07
Spill Record Last Update:	1996-06-13
Spiller Name:	Not reported
Spiller Company:	UNK PASSENGER TRUCK
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM RFC: Minor spill, no cleanup necessary. "
Remarks:	"Unattended vehicle rolled down driveway, roadway, submerged in lake. SLPD, tow truck, divers on site are removing vehicle asap. Quanity released insignificant for recovery. "

All Materials:

Site ID:	221834
Operable Unit ID:	1030758
Operable Unit:	01
Material ID:	561200
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

Site ID:	221834
Operable Unit ID:	1030758
Operable Unit:	01
Material ID:	561199
Material Code:	0005A
Material Name:	auto waste fluids
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

C31 **HARRIETSTOWN SANITARY LANDFILL** **PFAS ECHO** **1027366925**
NE **N/A**
< 1/8 **SARANAC LAKE, NY**
0.045 mi.
239 ft. **Site 3 of 13 in cluster C**

Relative:
Higher

Actual:
1534 ft.

PFAS ECHO:

Name:	HARRIETSTOWN SANITARY LANDFILL
Address:	Not reported
City,State,Zip:	SARANAC LAKE, NY
Latitude:	44.325212
Longitude:	-74.131784
Count:	1
County:	FRANKLIN
Status:	Unknown
Region:	02
Industry:	Waste Management
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110014016466
Facility Percent Minority:	18.222
Facility Derived Tribes:	-
Facility Population:	334.83
EPA Programs:	-
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	36033
Facility Indian Country Flag:	N
Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	02010006
Facility Derived WBD:	-
Facility Derived CD113:	21
Facility Derived CB2010:	360339510001013
Facility Major Flag:	-
Facility Active Flag:	-
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	-
Facility Programs With SNC:	0
Facility Compliance Status:	-
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	N
SDWIS Flag:	N
RCRA Flag:	N
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	-

HARRIETSTOWN SANITARY LANDFILL (Continued) **1027366925**

CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDS:	-
RCRA Permit Types:	-
RCRA NAICS:	-
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	Y
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-74.131784,%22y%22:44.325212,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

E32 **STORM SEWER OUTFALL** **NY Spills** **S102401336**
ENE **RIVER ST & ST BERNARD'S S** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.045 mi.
240 ft. **Site 1 of 5 in cluster E**

Relative: **Higher**

Actual: **1534 ft.**

SPILLS:

Name:	STORM SEWER OUTFALL
Address:	RIVER ST & ST BERNARD'S S
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9606113 / 1996-08-13
Facility ID:	9606113
Facility Type:	ER
DER Facility ID:	157948
Site ID:	189176
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	B2
SWIS:	1700
Spill Date:	1996-08-12
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1996-08-12
CID:	266
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-08-12
Spill Record Last Update:	1996-08-15
Spiller Name:	Not reported

STORM SEWER OUTFALL (Continued) **S102401336**

Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM 08/12/96: DEC aware of problem, quarterly sampling being performed @ outfall. RFC: Refer to spill # 9310574."
Remarks:	"CALLER NOTICES SMELL OF OIL EVERY MORNING FROM THE STORM SEWERS. "

All Materials:

Site ID:	189176
Operable Unit ID:	1033647
Operable Unit:	01
Material ID:	348845
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Sewer
Oxygenate:	Not reported

C33 **BEHIND THE WATER HOLE** **NY Spills** **S102243005**
NNE **MAIN STREET** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.046 mi.
242 ft. **Site 4 of 13 in cluster C**

Relative: **Lower**

Actual: **1522 ft.**

SPILLS:

Name:	BEHIND THE WATER HOLE
Address:	MAIN STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9600492 / 1996-04-10
Facility ID:	9600492
Facility Type:	ER
DER Facility ID:	284751
Site ID:	310221
DEC Region:	5
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	1700
Spill Date:	1996-04-10
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1996-04-11
CID:	267
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

BEHIND THE WATER HOLE (Continued) **S102243005**

Remediation Phase:	0
Date Entered In Computer:	1996-04-11
Spill Record Last Update:	1996-04-11
Spiller Name:	BOB JONES
Spiller Company:	HYDE FUEL COMPANY
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	BOB JONES
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM RFC: Minor spill, Hyde Fuel cleaned up. "
Remarks:	"hose failure 2 gallons spill onto ground surface and 3 vehicles hyde fuel cleaning up with speedi dri/pads owner award of situation"

All Materials:

Site ID:	310221
Operable Unit ID:	1028173
Operable Unit:	01
Material ID:	353887
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	2.00
Resource Affected:	Soil
Oxygenate:	Not reported

C34 **TOWN HALL** **LTANKS U001846096**
NE **30 MAIN ST** **UST N/A**
< 1/8 **SARANAC LAKE, NY 12983**
0.046 mi.
243 ft. **Site 5 of 13 in cluster C**

Relative: Higher

Actual: 1537 ft.

LTANKS:

Name:	HARRIESTOWN TOWN HALL
Address:	30 MAIN STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9706973 / 1997-11-05
Facility ID:	9706973
Site ID:	186709
Spill Date:	1997-09-11
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	1700
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1997-09-11
CID:	999
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False

TOWN HALL (Continued) **U001846096**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-09-11
Spill Record Last Update:	1997-11-10
Spiller Name:	KEN DEMARS
Spiller Company:	TOWN OF HARRISTSTOWN
Spiller Address:	30 MAIN STREET
Spiller County:	001
Spiller Contact:	KEN DEMARS
Spiller Phone:	(518) 891-1470
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	156050
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM 11/05/97: MM on site, tank removed, problem noted with vent pipe, tank in good shape, no holes in tank, no contaminated soil in tank pit, no further action necessary. RFC: Tank removed, no significant contamination encountered. "
Remarks:	"SUBSTANTIAL LOSS RATE (VALVTEST) FROM 15 YEAR OLD FUEL OIL TANK. TOWN TO MEET AND DISCUSS FUTURE ACTIONS, WILL RECONTACT MM 9/12."

All Materials:

Site ID:	186709
Operable Unit ID:	1050339
Operable Unit:	01
Material ID:	553439
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

UST:

Name:	TOWN HALL
Address:	30 MAIN ST
City,State,Zip:	SARANAC LAKE, NY 12983
Id/Status:	5-007447 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	5
Expiration Date:	N/A
UTM X:	569231.05958
UTM Y:	4908511.92273
Site Type:	Other

Affiliation Records:

Site Id:	38314
Affiliation Type:	Facility Owner
Company Name:	TOWN HARRIETSTOWN
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	30 MAIN ST
Address2:	Not reported

TOWN HALL (Continued) **U001846096**

City:	SARANAC LAKE
State:	NY
Zip Code:	12983
Country Code:	001
Phone:	(518) 891-1470
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	38314
Affiliation Type:	Mail Contact
Company Name:	TOWN HARRIETSTOWN
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	30 MAIN ST
Address2:	Not reported
City:	SARANAC LAKE
State:	NY
Zip Code:	12983
Country Code:	001
Phone:	(518) 891-1470
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	38314
Affiliation Type:	Facility Operator
Company Name:	TOWN HALL
Contact Type:	Not reported
Contact Name:	KEN DEMARS/JOHN WHEELER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 891-1470
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	38314
Affiliation Type:	Emergency Contact
Company Name:	TOWN HARRIETSTOWN
Contact Type:	Not reported
Contact Name:	KEN DEMARS/JOHN WHEELER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 891-1537
EMail:	Not reported

TOWN HALL (Continued) **U001846096**

Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	100211
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	07/01/1982
Date Tank Closed:	11/01/1997
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	05
Date Test:	10/01/1992
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None

C35 **ST BERNARD'S CHURCH** **LTANKS** **S102233843**
ENE **ST BERNARD ST** **NY Spills** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.046 mi.
244 ft. **Site 6 of 13 in cluster C**

Relative:
Higher

Actual:
1535 ft.

LTANKS:

Name:	ST BERNARD'S CHURCH
Address:	ST BERNARD ST
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9604012 / 1996-08-27
Facility ID:	9604012
Site ID:	331024
Spill Date:	1996-06-17
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	1700
Investigator:	MPMCLEAN
Referred To:	Not reported

ST BERNARD'S CHURCH (Continued) **S102233843**

Reported to Dept:	1996-06-17
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-06-24
Spill Record Last Update:	1997-09-25
Spiller Name:	FATHER SOUCY
Spiller Company:	ST BERNARD'S CHURCH
Spiller Address:	ST BERNARD ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	266229
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM 08/27/96: Contacted by Dan Unwin, Petro-Chem Tank Testing. Tank-piping passed system test, loose bushing(s) reason for failure. Mr. Unwin indicated inner wall definitely not leaking. Reason for product in interstitial space is due to thinness between inner/outer walls and slight tank slope toward interstitial monitor. Lead wires for cathodic protection found disconnected during tank excavation. Amount of free product in interstitial space should eventually remain consistent. Letter to be sent to church regarding findings. RFC: Tank passed retest. No release to environment. "
Remarks:	"TANK FAILED SYSTEM TEST, PETRO-CHEM TO RETURN TO DO TANK ONLY TEST, E,I,&R PRODUCT NOTED IN INTERSTIAL SPACE, 41 INITIALLY, 3-4 DURING TEST, 71 AFTER TEST. TESTER UNSURE OF HAPPENINGS 78 PRODUCT IN INNER TANK."

All Materials:

Site ID:	331024
Operable Unit ID:	1031671
Operable Unit:	01
Material ID:	350291
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

SPILLS:

Name:	ST BERNARD'S CHURCH
Address:	ST BERNARD ST
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9603678 / 1996-06-17
Facility ID:	9603678

ST BERNARD'S CHURCH (Continued) **S102233843**

Facility Type:	ER
DER Facility ID:	266229
Site ID:	331023
DEC Region:	5
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1700
Spill Date:	1996-06-17
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1996-06-17
CID:	312
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-06-17
Spill Record Last Update:	1997-09-25
Spiller Name:	Not reported
Spiller Company:	ST BERNARD'S CHURCH
Spiller Address:	ST BERNARD ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM RFC: Minor spill, Church cleaning up. "
Remarks:	"After testing tank and turning system back on - 5 gal lost out of valve in garage onto garage floor - church cleaning up."

All Materials:

Site ID:	331023
Operable Unit ID:	1031333
Operable Unit:	01
Material ID:	349952
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Resource Affected:	Soil
Oxygenate:	Not reported

C36 **ST BERNARD CHURCH** **NY Spills** **S102243098**
ENE **ST BERNARD ST** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.046 mi.
244 ft. **Site 7 of 13 in cluster C**

Relative:
Higher

Actual:
1535 ft.

SPILLS:

Name:	ST BERNARD CHURCH
Address:	ST BERNARD ST
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9602812 / 1996-08-26
Facility ID:	9602812
Facility Type:	ER
DER Facility ID:	266229
Site ID:	331022
DEC Region:	5
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	1700
Spill Date:	1996-05-20
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1996-05-28
CID:	270
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-05-29
Spill Record Last Update:	1997-09-25
Spiller Name:	DAVE GOKEY
Spiller Company:	AGWAY ENERGY
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM 05/28/96: Delivery to tank interstitial space. Agway contacted, to pump out space and retest tank for soundness. 08/26/96: Tank failed initial test, please refer to Spill Number 9604012. RFC: Refer to Spill Number 9604012 for further information."
Remarks:	"groundwater cleanup is ongoing agway contacted to pump out"

All Materials:

Site ID:	331022
Operable Unit ID:	1034114
Operable Unit:	01
Material ID:	349051
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G

ST BERNARD CHURCH (Continued) **S102243098**

Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

C37 **HARRIETSTOWN TOWN HALL** **LTANKS** **S106471481**
NNE **MAIN ST** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.053 mi.
282 ft. **Site 8 of 13 in cluster C**

Relative:
Higher

Actual:
1534 ft.

LTANKS:

Name:	HARRIETSTOWN TOWN HALL
Address:	MAIN ST
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	0245048 / 2002-06-21
Facility ID:	0245048
Site ID:	232048
Spill Date:	2002-06-21
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	1700
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	2002-06-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-06-21
Spill Record Last Update:	2002-06-21
Spiller Name:	DAN RILEY
Spiller Company:	HOME ENERGY
Spiller Address:	DEPOT STREET
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	(518) 891-1616
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	275645
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM "
Remarks:	"Driver filling tank could not hear whistle due to heavy traffic. Tank overfilled less than two gallons on driveway. Speedi Dri applied, material picked up. Line to tank drained to top of tank. No oil in building. No impacts. NFA."

All Materials:

Site ID:	232048
Operable Unit ID:	866885
Operable Unit:	01
Material ID:	509853

HARRIETSTOWN TOWN HALL (Continued) **S106471481**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	2.00
Resource Affected:	Soil
Oxygenate:	Not reported

C38 **@ SARANAC LAKE TOWN HALL** **NY Spills** **S102117251**
NNE **MAIN STREET** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.053 mi.
282 ft. **Site 9 of 13 in cluster C**

Relative: **Higher**
Actual: **1534 ft.**

SPILLS:

Name:	@ SARANAC LAKE TOWN HALL
Address:	MAIN STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9205695 / 1992-08-17
Facility ID:	9205695
Facility Type:	ER
DER Facility ID:	284751
Site ID:	310214
DEC Region:	5
Spill Cause:	Human Error
Spill Class:	D4
SWIS:	1700
Spill Date:	1992-08-17
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1992-08-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	1992-08-17
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-08-19
Spill Record Last Update:	1995-11-30
Spiller Name:	Not reported
Spiller Company:	BIG-D FUEL
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM RFC: Minor spill, Big D performed cleanup from asphalt. "
Remarks:	"BIG-D FILLING TANK IN PREPARATION FOR TANK TEST, SLIGHT OVERFILL RESULTED. BIG-D CLEANED USING SPEEDI-DRY. NO RESPONSE, NO FURTHER ACTION NEEDED."

@ SARANAC LAKE TOWN HALL (Continued) **S102117251**

All Materials:

Site ID:	310214
Operable Unit ID:	973084
Operable Unit:	01
Material ID:	409895
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

E39 **ATLANTIC STATION** **NY Spills** **S102120036**
ENE **14 RIVER ST/ST. BERNARD** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.056 mi.
297 ft. **Site 2 of 5 in cluster E**

Relative: **Higher**

Actual: **1537 ft.**

SPILLS:

Name:	ATLANTIC STATION
Address:	14 RIVER ST/ST. BERNARD
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9408644 / 2002-09-03
Facility ID:	9408644
Facility Type:	ER
DER Facility ID:	126974
Site ID:	149236
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	1746
Spill Date:	1994-09-28
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1994-09-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1994-09-29
Spill Record Last Update:	2002-09-03
Spiller Name:	BILL BROCHO
Spiller Company:	SUN COMPANY
Spiller Address:	PO BOX 1262
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM

ATLANTIC STATION (Continued) **S102120036**

09/19/94: RESULTS OF
INVESTIGATION WILL BE SENT TO DEC, MAY BE RESIDUAL FROM 1985-1986
SPILL. 12/28/94: SITE ASSESSMENT
REVIEWED BY DEC, LETTER SENT TO SUN REQUESTING ADDITIONAL ACTION.
02/02/95: TANKS REMOVED, GASOLINE
CONTAMINATED SOIL EXCAVATED TO EXTENT PRACTICAL (~280 CUBIC YARDS) AND
DISPOSED OF. SOME MW'S
REMAIN ON SITE. 12/12/95: SPARGE/SVEs INSTALLED AND OPERATING AT THE
SITE. 01/18/98: REMEDIATION
SYSTEM SHUT DOWN; SEMI-ANNUAL SAMPLING ONGOING 04/15/02: EXTENT OF
DISSOLVED CONTAMINANTS
DECREASING. NO FURTHER SAMPLING OR CLEANUP PURSUED BY THE DEPARTMENT.
RFC: SUNOCO PERFORMED
ADEQUATE CLEANUP, NO FURTHER ACTION NECESSARY. "

Remarks: "SOIL BORING SHOWED HNU READING OF >100 PPM. 1 OF 3 BORINGS. MM CONTACTED BRIAN IRVING, HANDEX. 1 SOIL BORING, 2 MW'S INSTALLED, WELLS SAMPLED. REPORT TO BE FORWARDED TO DEC."

All Materials:

Site ID:	149236
Operable Unit ID:	1002774
Operable Unit:	01
Material ID:	573199
Material Code:	1213A
Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	True

Site ID:	149236
Operable Unit ID:	1002774
Operable Unit:	01
Material ID:	378075
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	True

E40 **ATLANTIC REF. & MKTG. #0364-0554** **UST** **1000553645**
ENE **14 RIVER ST** **N/A**
< 1/8 **SARANAC LAKE, NY 12983**
0.056 mi.
297 ft. **Site 3 of 5 in cluster E**

Relative: UST:
Higher

Name:	ATLANTIC REF. & MKTG. #0364-0554
Address:	14 RIVER ST
City,State,Zip:	SARANAC LAKE, NY 12983

Actual:
1537 ft.

ATLANTIC REF. & MKTG. #0364-0554 (Continued) **1000553645**

Id/Status:	5-464392 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	5
Expiration Date:	N/A
UTM X:	572611.55835
UTM Y:	4975295.66967
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	39849
Affiliation Type:	Emergency Contact
Company Name:	ATLANTIC REF. & MKTG. CORP.
Contact Type:	Not reported
Contact Name:	LARRY BALLAY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(800) 786-9494
EMail:	Not reported
Fax Number:	Not reported
Modified By:	RBMULVEY
Date Last Modified:	2004-09-01

Site Id:	39849
Affiliation Type:	Facility Owner
Company Name:	ATLANTIC REF. & MKTG. CORP.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1801 MARKET ST. - 13/10 PC
Address2:	Not reported
City:	PHILADELPHIA
State:	PA
Zip Code:	19103
Country Code:	001
Phone:	(215) 977-6337
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	39849
Affiliation Type:	Mail Contact
Company Name:	ATLANTIC REF. & MKTG. CORP.
Contact Type:	Not reported
Contact Name:	UST COORDINATOR
Address1:	1801 MARKET ST. - 13/10 PC
Address2:	Not reported
City:	PHILADELPHIA
State:	PA
Zip Code:	19103
Country Code:	001
Phone:	(215) 977-6337
EMail:	Not reported
Fax Number:	Not reported

ATLANTIC REF. & MKTG. #0364-0554 (Continued) **1000553645**

Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	39849
Affiliation Type:	Facility Operator
Company Name:	ATLANTIC REF. & MKTG. #0364-0554
Contact Type:	Not reported
Contact Name:	COOP 5011
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 891-0350
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	105640
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	10000
Install Date:	09/01/1977
Date Tank Closed:	01/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	20
Date Test:	07/01/1994
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	002
Tank ID:	105641
Tank Status:	Closed - Removed

ATLANTIC REF. & MKTG. #0364-0554 (Continued) **1000553645**

Material Name: Closed - Removed
Capacity Gallons: 8000
Install Date: 10/01/1984
Date Tank Closed: 01/01/1995
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 20
Date Test: 07/01/1994
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I00 - Overfill - None

Tank Number: 003
Tank ID: 105642
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 10000
Install Date: 10/01/1984
Date Tank Closed: 01/01/1995
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 20
Date Test: 07/01/1994
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I00 - Overfill - None
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well

ATLANTIC REF. & MKTG. #0364-0554 (Continued) **1000553645**

J01 - Dispenser - Pressurized Dispenser

Tank Number:	004
Tank ID:	105643
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	11/01/1984
Date Tank Closed:	01/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	20
Date Test:	07/01/1994
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I00 - Overfill - None

E41 **ATLANTIC SERVICE STATION** **RCRA NonGen / NLR** **1004757884**
ENE **14 RIVER ST** **FINDS** **NYD986960706**
< 1/8 **SARANAC LAKE, NY 12983** **ECHO**
0.056 mi. **MANIFEST**
297 ft. **Site 4 of 5 in cluster E**

Relative: **Higher**
Actual: **1537 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Atlantic Service Station
Handler Address:	14 RIVER ST
Handler City,State,Zip:	SARANAC LAKE, NY 12983
EPA ID:	NYD986960706
Contact Name:	WILLIAM DELAUGHTER
Contact Address:	MARKET ST - MKT RISK MGMT
Contact City,State,Zip:	PHILADELPHIA, NY 19103
Contact Telephone:	215-977-6108
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported

ATLANTIC SERVICE STATION (Continued) **1004757884**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R5
Mailing Address:	MARKET ST - MKT RISK MGMT
Mailing City,State,Zip:	PHILADELPHIA, NY 19103
Owner Name:	Atlantic Refining & Marketing
Owner Type:	Private
Operator Name:	Atlantic Refining & Marketing
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018

ATLANTIC SERVICE STATION (Continued) **1004757884**

Waste Description: Benzene

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: ATLANTIC REFINING & MARKETING
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1801 MARKET ST
Owner/Operator City,State,Zip: PHILADELPHIA, PA 19103
Owner/Operator Telephone: 215-977-6108
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ATLANTIC REFINING & MARKETING
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1801 MARKET ST
Owner/Operator City,State,Zip: PHILADELPHIA, PA 19103
Owner/Operator Telephone: 215-977-6108
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ATLANTIC REFINING & MARKETING
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1801 MARKET ST
Owner/Operator City,State,Zip: PHILADELPHIA, PA 19103
Owner/Operator Telephone: 215-977-6108
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ATLANTIC REFINING & MARKETING
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1801 MARKET ST
Owner/Operator City,State,Zip: PHILADELPHIA, PA 19103
Owner/Operator Telephone: 215-977-6108
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: ATLANTIC SERVICE STATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny

ATLANTIC SERVICE STATION (Continued) **1004757884**

Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: ATLANTIC SERVICE STATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19910621
Handler Name: ATLANTIC SERVICE STATION
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004471170

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

ATLANTIC SERVICE STATION (Continued) **1004757884**

corrective action activities required under RCRA.

~~Click this hyperlink~~ while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004757884
Registry ID:	110004471170
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004471170
Name:	ATLANTIC SERVICE STATION
Address:	14 RIVER ST
City,State,Zip:	SARANAC LAKE, NY 12983

NY MANIFEST:

Name:	SUN COMPANY/ATLANTIC MAINTENANCE
Address:	14 RIVER ST
City,State,Zip:	SARANAC LAKE, NY 12983
Country:	USA
EPA ID:	NYD986960706
Facility Status:	Not reported
Location Address 1:	RIVER ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	SARANAC LAKE
Location State:	NY
Location Zip:	12983
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986960706
Mailing Name:	SUN COMPANY/ATLANTIC MAINTENANCE
Mailing Contact:	LINDA ST AMAND
Mailing Address 1:	RIVER ST
Mailing Address 2:	Not reported
Mailing City:	SARANAC LAKE
Mailing State:	NY
Mailing Zip:	12983
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5188910350

C42 **BETWEEN T HALL/RICE FURN.** **NY Spills** **S102119064**
NNE **MAIN STREET** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.057 mi.
301 ft. **Site 10 of 13 in cluster C**

Relative:
Higher

Actual:
1534 ft.

SPILLS:

Name:	BETWEEN T HALL/RICE FURN.
Address:	MAIN STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9009495 / 1990-11-30
Facility ID:	9009495
Facility Type:	ER
DER Facility ID:	284751
Site ID:	310208

BETWEEN T HALL/RICE FURN. (Continued) **S102119064**

DEC Region:	5
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	1700
Spill Date:	1990-11-30
Investigator:	AWSTEMP
Referred To:	Not reported
Reported to Dept:	1990-11-30
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	1990-11-30
Cleanup Meets Std:	True
Last Inspection:	1990-11-30
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-12-03
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	HYDE FUEL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"LEAK FROM DOME OF TRUCK (TRUCK ON SLANT, TANK FULL). HYDE PLACED SPEEDI-DRY AND SWEPT UP. AS ON SITE 11/30-CLEANUP COMPLETE."

All Materials:

Site ID:	310208
Operable Unit ID:	946583
Operable Unit:	01
Material ID:	429708
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

C43 **COMMERCIAL BLDG** **NY Spills** **S106011507**
NNE **47 MAIN ST** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.060 mi.
317 ft. **Site 11 of 13 in cluster C**

Relative: **Higher**

Actual: **1533 ft.**

SPILLS:

Name:	COMMERCIAL BLDG
Address:	47 MAIN ST
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	0211415 / 2003-02-16
Facility ID:	0211415
Facility Type:	ER

COMMERCIAL BLDG (Continued) **S106011507**

DER Facility ID:	59180
Site ID:	60658
DEC Region:	5
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1700
Spill Date:	2003-02-15
Investigator:	LJMILLIO
Referred To:	Not reported
Reported to Dept:	2003-02-15
CID:	390
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-02-15
Spill Record Last Update:	2003-02-20
Spiller Name:	BILL DECKER
Spiller Company:	BIG D FUEL
Spiller Address:	200 BROADWAY
Spiller Company:	001
Contact Name:	BARBARA DARRING
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was LM RFC: Cleanup completed. "
Remarks:	"Nozzle failed - spilled fuel - all material has been cleaned up."

All Materials:

Site ID:	60658
Operable Unit ID:	864743
Operable Unit:	01
Material ID:	511203
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Resource Affected:	Soil
Oxygenate:	Not reported

C44 **PARKING LOT BETWEEN COMPASS PRINTING AND WATERHOLE** **NY Spills** **S123661183**
NE **42 MAIN ST** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.069 mi.
365 ft. **Site 12 of 13 in cluster C**

Relative:
Higher

Actual:
1544 ft.

SPILLS:

Name:	PARKING LOT BETWEEN COMPASS PRINTING AND WATERHOLE
Address:	42 MAIN ST
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	1811553 / 2019-02-20

PARKING LOT BETWEEN COMPASS PRINTING AND WATERHOLE (Continued) **S123661183**

Facility ID:	1811553
Facility Type:	ER
DER Facility ID:	534983
Site ID:	582500
DEC Region:	5
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1746
Spill Date:	2019-02-19
Investigator:	BXHANKIN
Referred To:	Not reported
Reported to Dept:	2019-02-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2019-02-19
Spill Record Last Update:	2019-02-20
Spiller Name:	RICHARD MARTIN
Spiller Company:	MARTIN'S EXCAVATION
Spiller Address:	42 MAIN ST
Spiller Company:	999
Contact Name:	RICHARD MARTIN
DEC Memo:	"2/20/19: BH back onsite. Cleanup completed, photos in DecDocs. <5 gallons was released. 2/19/19: BH went to site. Found spill and put pads down. Martin's Excavation was the owner of the equipment. Worker was working on fixing bobcat. Explained that the spill needs to be cleaned up. He was going to Homenergy to get some spill pads. Martin's Excavation called and told them to help clean up spill. Please send photos when completed."
Remarks:	"Caller works at Compass Printing; states that unk individuals clearing snow from their parking area have a piece of heavy equipment with a broken hydraulic line which is putting an awful lot of hydraulic oil really close to the storm drains."

All Materials:

Site ID:	582500
Operable Unit ID:	1330180
Operable Unit:	01
Material ID:	2339328
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

C45 **SIR SPEEDY PRINTING** **RCRA NonGen / NLR** **1008374386**
NE **42 MAIN ST** **NYN008014185**
< 1/8 **SARANAC LAKE, NY 12983**
0.069 mi.
365 ft. **Site 13 of 13 in cluster C**

Relative: **Higher**

Actual: **1544 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Sir Speedy Printing
Handler Address:	42 MAIN ST
Handler City,State,Zip:	SARANAC LAKE, NY 12983
EPA ID:	NYN008014185
Contact Name:	BONNIE BREWER
Contact Address:	MAIN ST
Contact City,State,Zip:	SARANAC LAKE, NY 12983
Contact Telephone:	518-891-7050
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R5
Mailing Address:	MAIN ST
Mailing City,State,Zip:	SARANAC LAKE, NY 12983
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

SIR SPEEDY PRINTING (Continued) **1008374386**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20050512
Handler Name: SIR SPEEDY PRINTING	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: SIR SPEEDY PRINTING	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: SIR SPEEDY PRINTING	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

SIR SPEEDY PRINTING (Continued) **1008374386**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20041209
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYKWD
Evaluation Responsible Sub-Organization: R5
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

F46 **HOYT TAXI SERVICE** **EDR Hist Auto** **1020378612**
NNE **53 MAIN ST** **N/A**
< 1/8 **SARANAC LAKE, NY 12983**
0.070 mi.
370 ft. **Site 1 of 5 in cluster F**

Relative: EDR Hist Auto
Higher

Actual: Year: Name: Type:
1535 ft. 1969 HOYT TAXI SERVICE Gasoline Service Stations
1970 HOYT TAXI SERVICE Gasoline Service Stations
1971 HOYT TAXI SERVICE Gasoline Service Stations

E47 **ATLANTIC GAS STATION** **LTANKS** **S100159462**
ENE **RIVER ST.** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.077 mi.
409 ft. **Site 5 of 5 in cluster E**

Relative: LTANKS:
Higher

Actual:
1543 ft.

Name:	ATLANTIC GAS STATION
Address:	RIVER ST.
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	8805328 / 1988-09-28
Facility ID:	8805328
Site ID:	221831
Spill Date:	1988-09-20
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	1988-09-28
SWIS:	1746
Investigator:	rdhuyck
Referred To:	Not reported
Reported to Dept:	1988-09-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-09-21
Spill Record Last Update:	2007-02-28
Spiller Name:	Not reported
Spiller Company:	ATLANTIC GAS STATION
Spiller Address:	RIVER ST.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	183468
DEC Memo:	""
Remarks:	"EXCAVATION AND RETESTING. TRAPPED AIR IN THE TANK, RETESTED ON 9/28, PASSED."

All TTF:

Facility ID:	8805328

ATLANTIC GAS STATION (Continued) **S100159462**

Spill Number:	8805328
Spill Tank Test:	1534645
Site ID:	221831
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	221831
Operable Unit ID:	922380
Operable Unit:	01
Material ID:	457236
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

48
ESE
< 1/8
0.080 mi.
421 ft.

CHAPIN RESIDENCE
22 KIWASSA RD
SARANAC LAKE, NY

LTANKS **S106124316**
N/A

Relative:
Higher

Actual:
1538 ft.

LTANKS:

Name:	CHAPIN RESIDENCE
Address:	22 KIWASSA RD
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	0308360 / 2003-12-03
Facility ID:	0308360
Site ID:	299941
Spill Date:	2003-11-07
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	1600
Investigator:	GJHANDLY
Referred To:	Not reported
Reported to Dept:	2003-11-07
CID:	205
Water Affected:	Not reported

CHAPIN RESIDENCE (Continued) **S106124316**

Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-11-07
Spill Record Last Update:	2003-12-03
Spiller Name:	DANIEL SHERWOOD
Spiller Company:	CHAPIN RESIDENCE
Spiller Address:	22 KIWASSA RD
Spiller County:	001
Spiller Contact:	DANIEL SHERWOOD
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	242647
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GH GH inspected tank and escavation. Instructed OpTech to excavate small amount of contaminated soil and close excavation. 10 tons of contaminated soil is stockpiled and scheduled for disposal at ESMI. RFC: No further action is required."
Remarks:	"Pulled tank and found contamination."

All Materials:

Site ID:	299941
Operable Unit ID:	876860
Operable Unit:	01
Material ID:	501871
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

49
NNW
< 1/8
0.094 mi.
494 ft.

SARANAC RIVER **LTANKS** **S100161481**
DORSEY STREET **N/A**
SARANAC LAKE, NY

Relative:
Higher

Actual:
1584 ft.

LTANKS:

Name:	SARANAC RIVER
Address:	DORSEY STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	8605567 / 1988-08-01
Facility ID:	8605567
Site ID:	139351
Spill Date:	1986-12-02
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	1988-08-01

SARANAC RIVER (Continued) **S100161481**

SWIS:	1700
Investigator:	RLWAGNER
Referred To:	Not reported
Reported to Dept:	1986-12-02
CID:	Not reported
Water Affected:	SARANAC RIVER
Spill Notifier:	Federal Government
Last Inspection:	1988-04-08
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1986-12-04
Spill Record Last Update:	2000-12-21
Spiller Name:	Not reported
Spiller Company:	DAVID DAY
Spiller Address:	80 SCOTCH RIDGE ROAD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	119044
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RW/MM 12/03/86: R. WAGNER INSTALLED BOOM 12/3/86 IN RIVER. 03/02/88: SHEEN IN RIVER AGAIN REPORTED ON 02/12/88. RW AND MM INVESTIGATED. SOURCE AGAIN ACROSS STREET FROM GENDRONS. OWNER SENT LETTER TO TEST TANKS. 04/08/88: TANK REMOVED BY SPILLER, NEW TANK INSTALLED IN BASEMENT. AS INVESTIGATED REMOVAL, OIL EVIDENT IN PIT, BUT NO FURTHER ACTION TAKEN. NO LONGER PRESENT IN RIVER. RFC: TANK FOUND TO BE LEAKING AND REMOVED, NO FURTHER IMPACT TO RIVER."
Remarks:	"SHEEN IN RIVER, OIL & RUST COMING OUT OF STORMLINE NEXT TO BANK OFFICE BLDG. DETERMINED TO BE LEAKING UST AT ABOVE FACILITY. TANK REPLACED WITH NEW ONE."

All Materials:

Site ID:	139351
Operable Unit ID:	902516
Operable Unit:	01
Material ID:	474743
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

F50 **CHINA JADE** **LTANKS** **S102676599**
NNE **58 MAIN STREET** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.102 mi.
541 ft. **Site 2 of 5 in cluster F**

Relative:
Higher

Actual:
1545 ft.

LTANKS:

Name:	CHINA JADE
Address:	58 MAIN STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9304928 / 1993-07-15
Facility ID:	9304928
Site ID:	160821
Spill Date:	1993-07-15
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1993-07-15
SWIS:	1600
Investigator:	RLWAGNER
Referred To:	Not reported
Reported to Dept:	1993-07-15
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-07-20
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	HYDE FUELS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	135787
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RW "
Remarks:	"SPILLED ON SIDEWALK, SPEEDY DRY APPLIED AND CLEANED UP."

All Materials:

Site ID:	160821
Operable Unit ID:	983203
Operable Unit:	01
Material ID:	398401
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

51
WSW
< 1/8
0.103 mi.
546 ft.

87 LAKE STREET
87 LAKE STREET
SARANAC LAKE, NY 12953

NY Spills **S116554286**
N/A

Relative:
Higher

Actual:
1630 ft.

SPILLS:

Name:	87 LAKE STREET
Address:	87 LAKE STREET
City,State,Zip:	SARANAC LAKE, NY 12953
Spill Number/Closed Date:	1400270 / 2015-05-20
Facility ID:	1400270
Facility Type:	ER
DER Facility ID:	448386
Site ID:	493505
DEC Region:	5
Spill Cause:	Housekeeping
Spill Class:	D3
SWIS:	1746
Spill Date:	2014-04-08
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	2014-04-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2014-04-08
Spill Record Last Update:	2015-05-20
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	Not reported
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"Report of stained soils as a result of auto repair business operating on premises."

All Materials:

Site ID:	493505
Operable Unit ID:	1243008
Operable Unit:	01
Material ID:	2243628
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

G52 **ST. BERNARD'S CHURCH** **LTANKS** **S102117308**
ENE **ST. BERNARD ST** **NY Spills** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.104 mi.
549 ft. **Site 1 of 6 in cluster G**

Relative:
Higher

Actual:
1549 ft.

LTANKS:

Name:	ST. BERNARD'S CHURCH
Address:	ST. BERNARD ST
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9700694 / 1998-07-16
Facility ID:	9700694
Site ID:	145119
Spill Date:	1997-04-16
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	A1
Cleanup Ceased:	Not reported
SWIS:	1700
Investigator:	RDHUYCK
Referred To:	Not reported
Reported to Dept:	1997-04-16
CID:	257
Water Affected:	SARANAC RIVER
Spill Notifier:	Police Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-04-16
Spill Record Last Update:	1998-07-16
Spiller Name:	Not reported
Spiller Company:	AGWAY/3 J FUEL/CHURCH
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	SARANAC LAKE FD
Spiller Phone:	(518) 891-2211
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	123672
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RH 04/16/97: RH/MM/LM on scene. Product entered storm drain and into the Saranac River. Excavation work being done at Church by Whiteface Construction. Village workers built dam at river and flushed storm drain. Evergreen on scene to continue cleanup. An estimated minimum of 500 gallons was released (Department est). Soil excavated from tank to sidewalk. Soil samples indicate that material was satisfactorily removed in that area."
Remarks:	"TRUCK IS LEAKING UNKNOWN CAUSE AT THIS TIME SPILL IS GOING INTO SEWER AND THEN INTO THE LAKE"

All Materials:

Site ID:	145119
Operable Unit ID:	1043378
Operable Unit:	01
Material ID:	337284
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

ST. BERNARD'S CHURCH (Continued) **S102117308**

Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

SPILLS:

Name:	ST. BERNARDS CHURCH
Address:	ST. BERNARD STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	8912039 / 1990-03-21
Facility ID:	8912039
Facility Type:	ER
DER Facility ID:	213544
Site ID:	261477
DEC Region:	5
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	1700
Spill Date:	1990-03-19
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1990-03-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	DEC
Cleanup Ceased:	1990-03-21
Cleanup Meets Std:	False
Last Inspection:	1990-03-21
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-03-20
Spill Record Last Update:	1997-09-25
Spiller Name:	Not reported
Spiller Company:	CHET FOBARE & SONS
Spiller Address:	6 JAMES STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM "
Remarks:	"FOBARE ATTEMPTING TO PUMP PRODUCT FORM RECOVERY TANK TO REMOTE FILL LINE FOR FURNACE, SPILLED 2-3 G DUE TO CHECK VALVE. FOBARE TO CLEAN UP. TO CHECK NEXT VISIT. MM ON SITE 3/21/90-CLEANUP OK."

All Materials:

Site ID:	261477
Operable Unit ID:	937796
Operable Unit:	01
Material ID:	441520
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

ST. BERNARD'S CHURCH (Continued) **S102117308**

Quantity:	3.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	ST. BERNARD'S CHURCH
Address:	ST. BERNARD STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9108504 / 1991-11-08
Facility ID:	9108504
Facility Type:	ER
DER Facility ID:	213544
Site ID:	261478
DEC Region:	5
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1700
Spill Date:	1991-11-07
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1991-11-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	DEC
Cleanup Ceased:	1991-11-08
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1991-11-12
Spill Record Last Update:	1997-09-25
Spiller Name:	Not reported
Spiller Company:	CHET FOBARE & SONS
Spiller Address:	6 JAMES STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM "
Remarks:	"NOTICED STAINED AREA WHILE GAUGING MONITOR WELLS. 11/8-AL BONADUC CALLED, SPILL OCCURRED WHILE PUMPING OUT 275 IN RECOVERY SYSTEM APPROX. 1 MONTH AGO, ADVISED TO REPORT ANY FURTHER SPILLS."

All Materials:

Site ID:	261478
Operable Unit ID:	958810
Operable Unit:	01
Material ID:	420653
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00

ST. BERNARD'S CHURCH (Continued) **S102117308**

Resource Affected:	Soil
Oxygenate:	Not reported

Name:	ST. BERNARDS CHURCH
Address:	ST. BERNARD STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9207267 / 1993-06-10
Facility ID:	9207267
Facility Type:	ER
DER Facility ID:	213544
Site ID:	261479
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	E6
SWIS:	1700
Spill Date:	1992-09-23
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1992-09-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	1993-06-10
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-09-23
Spill Record Last Update:	1997-09-25
Spiller Name:	Not reported
Spiller Company:	CHET FOBARE & SONS
Spiller Address:	6 JAMES STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM RFC: Tank properly cleaned out, no further action pursued. "
Remarks:	"2-K TANK REMOVED FROM CHURCH, DEPARTMENT NOT NOTIFIED. FOBARE AND SONS TO CLOSE OUT TANK. DEC TO INSURE PROPER PROCEDURE, ETC."

All Materials:

Site ID:	261479
Operable Unit ID:	970904
Operable Unit:	01
Material ID:	407914
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

G53 **ST. BERNARD CHURCH** **NY Spills** **S102117973**
ENE **BERNARD ST.** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.104 mi.
549 ft. **Site 2 of 6 in cluster G**

Relative:
Higher

Actual:
1549 ft.

SPILLS:

Name:	ST. BERNARD CHURCH
Address:	BERNARD ST.
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	8601987 / 1986-06-23
Facility ID:	8601987
Facility Type:	ER
DER Facility ID:	72257
Site ID:	77431
DEC Region:	5
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1700
Spill Date:	1986-06-23
Investigator:	AWSTEMP
Referred To:	Not reported
Reported to Dept:	1986-06-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	1986-06-23
Cleanup Meets Std:	False
Last Inspection:	1986-06-23
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1986-12-04
Spill Record Last Update:	1998-07-30
Spiller Name:	Not reported
Spiller Company:	ULTRAMAR PETROLEUM
Spiller Address:	LAKESHORE RD.
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AS "
Remarks:	"SPILLER CLEANED UP. BLOWN GASKET ON PUMP DURING DELIVERY TO CHURCH."

All Materials:

Site ID:	77431
Operable Unit ID:	898214
Operable Unit:	01
Material ID:	478445
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

G54 **ST. BERNARD'S CHURCH** **NY Spills** **S102116380**
ENE **CHURCH ST.(PRES.CHURCH)** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.104 mi.
549 ft. **Site 3 of 6 in cluster G**

Relative:
Higher

Actual:
1549 ft.

SPILLS:

Name:	ST. BERNARD'S CHURCH
Address:	CHURCH ST.(PRES.CHURCH)
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	8604804 / 2013-04-26
Facility ID:	8604804
Facility Type:	ER
DER Facility ID:	151050
Site ID:	179985
DEC Region:	5
Spill Cause:	Equipment Failure
Spill Class:	A1
SWIS:	1746
Spill Date:	1986-10-25
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1986-10-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Local Agency
Cleanup Ceased:	1990-03-14
Cleanup Meets Std:	False
Last Inspection:	1989-10-01
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1986-10-30
Spill Record Last Update:	2016-09-21
Spiller Name:	Not reported
Spiller Company:	ST. BERNARD'S CHURCH
Spiller Address:	19 ST. BERNARDS STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"10/28/86: Groundwater Technologies installed recovery well, testing tanks and lines, drilling scheduled for 11/3/86 to locate source. 10/01/89: Groundwater pump and treat ongoing. 03/01/90 :Church takes over clean-up. 12/15/93: System modified to total fluids pumping and oil/water separator. 01/03/94: Clean-up ongoing by church, to date approx. 8800 gallons of fuel oil recovered from subsurface. 04/26/13: Church performed cleanup. Site monitoring wells have shown no signs of product for several years. No further action or monitoring needed. RFC: State performed initial investigation and clean-up, RP took over clean-up and completed the clean-up to a satisfactory extent."
Remarks:	"Oil noted in excavation at Presbyterian Church. Traced to leak in remote fill piping for fuel oil tank at church."

All Materials:

Site ID:	179985

ST. BERNARD'S CHURCH (Continued) **S102116380**

Operable Unit ID:	902017
Operable Unit:	01
Material ID:	474036
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	11000.00
Resource Affected:	Soil, Groundwater
Oxygenate:	Not reported

G55 **ST BERNARDS CHURCH** **LTANKS** **S102243155**
ENE **ST BERNARD ST** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.104 mi.
549 ft. **Site 4 of 6 in cluster G**

Relative: LTANKS:
Higher

Name:	ST BERNARDS CHURCH
Address:	ST BERNARD ST
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9701419 / 1997-05-01
Facility ID:	9701419
Site ID:	331025
Spill Date:	1997-05-01
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	1700
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1997-05-01
CID:	211
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-05-01
Spill Record Last Update:	1997-05-05
Spiller Name:	Not reported
Spiller Company:	ST BERNARDS CHURCH
Spiller Address:	ST. BERNARD ST.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	(518) 891-4616
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	266229
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM RFC: Being handled under spill # 9700694."
Remarks:	"RECENT TANK OVERFILL AT CHURCH - RECENT CHECK OF TANK INTERSTITIAL

Actual:
1549 ft.

ST BERNARDS CHURCH (Continued) **S102243155**

SPACE FOUND 101 INCHES OF PRODUCT - CHURCH SEEKING BIDS FOR TANK REMOVAL - REFER TO SPILL 97-00694."

All Materials:

Site ID:	331025
Operable Unit ID:	1044059
Operable Unit:	01
Material ID:	337974
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

G56 **ST. BERNARD'S CHURCH** **NY Spills** **S102117999**
ENE **BERNARD STREET** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.104 mi.
549 ft. **Site 5 of 6 in cluster G**

Relative:
Higher

Actual:
1549 ft.

SPILLS:

Name:	ST. BERNARD'S CHURCH
Address:	BERNARD STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	8605259 / 1986-11-18
Facility ID:	8605259
Facility Type:	ER
DER Facility ID:	114393
Site ID:	132918
DEC Region:	5
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1700
Spill Date:	1986-11-18
Investigator:	RLWAGNER
Referred To:	Not reported
Reported to Dept:	1986-11-18
CID:	Not reported
Water Affected:	SARANAC RIVER
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Affected Persons
Cleanup Ceased:	1986-11-18
Cleanup Meets Std:	False
Last Inspection:	1986-11-18
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1986-11-21
Spill Record Last Update:	2004-02-19
Spiller Name:	Not reported
Spiller Company:	GROUNDWATER TECHNOLOGY
Spiller Address:	Not reported
Spiller Company:	001

ST. BERNARD'S CHURCH (Continued) **S102117999**

Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was RW "
Remarks: "OIL SHOWING UP IN PUMP STATION & STP."

All Materials:
Site ID: 132918
Operable Unit ID: 902458
Operable Unit: 01
Material ID: 474459
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Resource Affected: Surface Water
Oxygenate: Not reported

G57 **ST BERNARD'S CHURCH** **NY Spills** **S103571949**
ENE **ST BERNARDS STREET** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.104 mi.
549 ft. **Site 6 of 6 in cluster G**

Relative:
Higher

Actual:
1549 ft.

SPILLS:
Name: ST BERNARD'S CHURCH
Address: ST BERNARDS STREET
City,State,Zip: SARANAC LAKE, NY
Spill Number/Closed Date: 9800404 / 1998-07-16
Facility ID: 9800404
Facility Type: ER
DER Facility ID: 117752
Site ID: 137660
DEC Region: 5
Spill Cause: Other
Spill Class: C3
SWIS: 1700
Spill Date: 1998-04-09
Investigator: RDHUYCK
Referred To: Not reported
Reported to Dept: 1998-04-09
CID: 999
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-04-09
Spill Record Last Update: 1999-07-23
Spiller Name: Not reported
Spiller Company: ROBERT LECLAIR

ST BERNARD'S CHURCH (Continued) **S103571949**

Spiller Address: Not reported
Spiller Company: 001
Contact Name: UNK
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was RH "
Remarks: "C & S ENGINEERS INSTALLING REMEDIAL SYSTEM AT SITE. ACCIDENTALLY SEVERED UNDERGROUND PIPING NEAR REAR AREA OF CHURCH. PIPING INSTALLED LESS THAN 12 INCHES BELOW GRADE AND SURROUNDED BY ROCKS AND ASPHALT."

All Materials:
Site ID: 137660
Operable Unit ID: 1060978
Operable Unit: 01
Material ID: 322377
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 2.00
Units: G
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

F58 **ADIRONDACK BANK, FSB** **UST** **U004079500**
NNE **60 MAIN ST** **N/A**
< 1/8 **SARANAC LAKE, NY 12983**
0.105 mi.
556 ft. **Site 3 of 5 in cluster F**

Relative: **Higher**
Actual: **1545 ft.**

UST:
Name: ADIRONDACK BANK, FSB
Address: 60 MAIN ST
City,State,Zip: SARANAC LAKE, NY 12983-0750
Id/Status: 5-231029 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 5
Expiration Date: N/A
UTM X: 569227.75095
UTM Y: 4908479.27068
Site Type: Other

Affiliation Records:
Site Id: 39135
Affiliation Type: Facility Owner
Company Name: ADIRONDACK BANK, FSB
Contact Type: Not reported
Contact Name: Not reported
Address1: 60 MAIN ST
Address2: Not reported
City: SARANAC LAKE
State: NY
Zip Code: 12983-0750
Country Code: 001
Phone: (518) 891-2323
EMail: Not reported
Fax Number: Not reported

ADIRONDACK BANK, FSB (Continued) **U004079500**

Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 39135
Affiliation Type: Mail Contact
Company Name: ADIRONDACK BANK, FSB
Contact Type: Not reported
Contact Name: MR. PHILLIP W. NEWCOMB
Address1: P.O. BOX 250
Address2: Not reported
City: SARANAC LAKE
State: NY
Zip Code: 12983-0750
Country Code: 001
Phone: (518) 891-2323
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 39135
Affiliation Type: Facility Operator
Company Name: ADIRONDACK BANK, FSB
Contact Type: Not reported
Contact Name: F. GREGG THALMANN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (518) 891-2323
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 39135
Affiliation Type: Emergency Contact
Company Name: ADIRONDACK BANK, FSB
Contact Type: Not reported
Contact Name: PHILLIP W. NEWCOMB
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (518) 891-5724
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001

ADIRONDACK BANK, FSB (Continued) **U004079500**

Tank ID:	102252
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	08/01/1986
Date Tank Closed:	05/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G04 - Tank Secondary Containment - Double-Walled (Underground)
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None

F59 **ADIRONDACK BANK** **LTANKS** **U003080443**
NNE **60 MAIN STREET** **AST** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.105 mi.
556 ft. **Site 4 of 5 in cluster F**

Relative:
Higher

Actual:
1545 ft.

LTANKS:

Name:	ADIRONDACK BANK
Address:	60 MAIN STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9601460 / 1996-05-03
Facility ID:	9601460
Site ID:	62244
Spill Date:	1996-04-29
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	1700
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1996-04-29
CID:	275
Water Affected:	SARANAC RIVER
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False

ADIRONDACK BANK (Continued) **U003080443**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-04-29
Spill Record Last Update:	1996-05-03
Spiller Name:	Not reported
Spiller Company:	ADIRONDACK BANK
Spiller Address:	60 MAIN STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	60371
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM 05/02/96: Tank removed from ground by Sheefer Plumbing and Heating. No evidence of leakage from outer wall, hole clean. RFC: No release to the environment. "
Remarks:	"SYSTEM TEST FAILURE - DOUBLE WALL TANK - INNER TANK FAILED, OUTSIDE HOLDING. CONTAINED SPILL, WILL PUMP OUT HOOK UP TEMP TANK"

All TTF:

Facility ID:	9601460
Spill Number:	9601460
Spill Tank Test:	1544501
Site ID:	62244
Tank Number:	001
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	62244
Operable Unit ID:	1033029
Operable Unit:	01
Material ID:	351264
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

AST:

Name:	ADIRONDACK BANK, FSB

ADIRONDACK BANK (Continued) **U003080443**

Address:	60 MAIN ST
City,State,Zip:	SARANAC LAKE, NY 12983-0750
Region:	STATE
DEC Region:	5
Site Status:	Unregulated/Closed
Facility Id:	5-231029
Program Type:	PBS
UTM X:	569227.75095
UTM Y:	4908479.27068
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	39135
Affiliation Type:	Facility Owner
Company Name:	ADIRONDACK BANK, FSB
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	60 MAIN ST
Address2:	Not reported
City:	SARANAC LAKE
State:	NY
Zip Code:	12983-0750
Country Code:	001
Phone:	(518) 891-2323
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	39135
Affiliation Type:	Mail Contact
Company Name:	ADIRONDACK BANK, FSB
Contact Type:	Not reported
Contact Name:	MR. PHILLIP W. NEWCOMB
Address1:	P.O. BOX 250
Address2:	Not reported
City:	SARANAC LAKE
State:	NY
Zip Code:	12983-0750
Country Code:	001
Phone:	(518) 891-2323
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	39135
Affiliation Type:	Facility Operator
Company Name:	ADIRONDACK BANK, FSB
Contact Type:	Not reported
Contact Name:	F. GREGG THALMANN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001

ADIRONDACK BANK (Continued) **U003080443**

Phone:	(518) 891-2323
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04
Site Id:	39135
Affiliation Type:	Emergency Contact
Company Name:	ADIRONDACK BANK, FSB
Contact Type:	Not reported
Contact Name:	PHILLIP W. NEWCOMB
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 891-5724
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	002
Tank Id:	109908
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	C01 - Pipe Location - Aboveground
	D10 - Pipe Type - Copper
	I04 - Overfill - Product Level Gauge (A/G)
	F00 - Pipe External Protection - None
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
	L09 - Piping Leak Detection - Exempt Suction Piping
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	H99 - Tank Leak Detection - Other
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/01/1996
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

ADIRONDACK BANK (Continued) **U003080443**

Tank Number:	003
Tank Id:	109909
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
D10 - Pipe Type - Copper
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H99 - Tank Leak Detection - Other

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/01/1996
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

F60 **MEYER'S HALLMARK (ALLEY)** **NY Spills** **S105056445**
NNE **69 MAIN STREET** **N/A**
< 1/8 **SARANAC LAKE, NY**
0.109 mi.
573 ft. **Site 5 of 5 in cluster F**

Relative:
Higher

Actual:
1542 ft.

SPILLS:

Name:	MEYER'S HALLMARK (ALLEY)
Address:	69 MAIN STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	0145009 / 2001-08-20
Facility ID:	0145009
Facility Type:	ER
DER Facility ID:	177220
Site ID:	213904
DEC Region:	5
Spill Cause:	Housekeeping
Spill Class:	C3
SWIS:	1700
Spill Date:	2001-03-01
Investigator:	GJHANDLY
Referred To:	Not reported
Reported to Dept:	2001-04-06
CID:	Not reported
Water Affected:	Not reported

MEYER'S HALLMARK (ALLEY) (Continued) **S105056445**

Spill Source:	Passenger Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-04-10
Spill Record Last Update:	2001-08-20
Spiller Name:	NANCY BUTCHINO
Spiller Company:	NANCY BUTCHINO
Spiller Address:	MAIN ST. (FLEECE SHOP)
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GH/RM 1200 hrs, GH/RM responded, put pads over affected area. Informed spiller that gasoline contaminated pavement and soil should be excavated properly, disposed of, and replaced. Will check pads and replace as necessary until removal. 04/08/01: Blacktop and soil cleaned by spiller. No further action. "
Remarks:	"Car in alleyway consistently leaking causing tracking of contamination into nearby business. "

All Materials:

Site ID:	213904
Operable Unit ID:	851750
Operable Unit:	01
Material ID:	526837
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

61
North
< 1/8
0.113 mi.
597 ft.

Relative:
Lower

Actual:
1520 ft.

VILLAGE SARANAC LAKE **AST** **A100366203**
3 MAIN STREET **N/A**
SARANAC LAKE, NY 12983

AST:

Name:	VILLAGE SARANAC LAKE
Address:	3 MAIN STREET
City,State,Zip:	SARANAC LAKE, NY 12983
Region:	STATE
DEC Region:	5
Site Status:	Active
Facility Id:	5-416703
Program Type:	PBS
UTM X:	569212.17405

VILLAGE SARANAC LAKE (Continued) **A100366203**

UTM Y: 4908242.59861
Expiration Date: 10/02/2027
Site Type: Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)

Affiliation Records:

Site Id: 39482
Affiliation Type: Mail Contact
Company Name: VILLAGE SARANAC LAKE
Contact Type: Not reported
Contact Name: VILLAGE MANAGER
Address1: 39 MAIN STREET
Address2: 2ND FLOOR, SUITE 9
City: SARANAC LAKE
State: NY
Zip Code: 12983
Country Code: 001
Phone: (518) 891-4150
EMail: MANAGER@SARANACLAKENY.GOV
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2013-01-04

Site Id: 39482
Affiliation Type: Facility Owner
Company Name: VILLAGE SARANAC LAKE
Contact Type: DPW SUPERINTENDENT
Contact Name: DUSTIN MARTIN
Address1: 39 MAIN STREET
Address2: Not reported
City: SARANAC LAKE
State: NY
Zip Code: 12983
Country Code: 001
Phone: (518) 891-4150
EMail: Not reported
Fax Number: Not reported
Modified By: BXHANKIN
Date Last Modified: 2019-12-27

Site Id: 39482
Affiliation Type: Emergency Contact
Company Name: VILLAGE SARANAC LAKE
Contact Type: Not reported
Contact Name: DUSTIN MARTIN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (518) 354-0595
EMail: Not reported
Fax Number: Not reported
Modified By: BXHANKIN
Date Last Modified: 2019-12-27

Site Id: 39482
Affiliation Type: Facility Operator

VILLAGE SARANAC LAKE (Continued) **A100366203**

Company Name:	VILLAGE SARANAC LAKE
Contact Type:	Not reported
Contact Name:	DUSTIN MARTIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 891-4160
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BXHANKIN
Date Last Modified:	2019-12-27

Tank Info:

Tank Number:	004
Tank Id:	246846
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	I05 - Overfill - Vent Whistle
	B05 - Tank External Protection - Jacketed
	L00 - Piping Leak Detection - None
	K00 - Spill Prevention - None
	A00 - Tank Internal Protection - None
	D10 - Pipe Type - Copper
	C01 - Pipe Location - Aboveground
	I04 - Overfill - Product Level Gauge (A/G)
	J02 - Dispenser - Suction Dispenser
	G12 - Tank Secondary Containment - Double-Walled (AG only)
	E00 - Piping Secondary Containment - None
	F00 - Pipe External Protection - None
	H02 - Tank Leak Detection - Interstitial - Manual Monitoring
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Plastic
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/30/2012
Capacity Gallons:	165
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

62
NNE
< 1/8
0.118 mi.
622 ft.

MARINE MIDLAND BANK SARANAC
70 MAIN ST
SARANAC LAKE, NY 12983

UST **U000384636**
NY Spills **N/A**

Relative:
Higher

Actual:
1548 ft.

UST:

Name:	MARINE MIDLAND BANK SARANAC
Address:	70 MAIN ST
City,State,Zip:	SARANAC LAKE, NY 12983
Id/Status:	5-393932 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	5
Expiration Date:	N/A
UTM X:	569223.45845
UTM Y:	4908420.89442
Site Type:	Other

Affiliation Records:

Site Id:	39423
Affiliation Type:	Facility Owner
Company Name:	MARINE MIDLAND BANK NA
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1 MARINE MIDLAND CEN. 9TH FL.
Address2:	Not reported
City:	SAFETY OFF., BUFFALO
State:	NY
Zip Code:	14240
Country Code:	001
Phone:	(716) 843-2322
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	39423
Affiliation Type:	Mail Contact
Company Name:	MARINE MIDLAND BANK NA
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1 MARINE MIDLAND CEN. 9TH FL.
Address2:	SAFETY OFF.
City:	BUFFALO
State:	NY
Zip Code:	14240
Country Code:	001
Phone:	(716) 843-2322
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	39423
Affiliation Type:	Facility Operator
Company Name:	MARINE MIDLAND BANK SARANAC
Contact Type:	Not reported
Contact Name:	GARY SEERY
Address1:	Not reported

MARINE MIDLAND BANK SARANAC (Continued) **U000384636**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 891-3711
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	39423
Affiliation Type:	Emergency Contact
Company Name:	MARINE MIDLAND BANK NA
Contact Type:	Not reported
Contact Name:	GARY SEERY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 788-1576
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	103911
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	05/16/2002
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	03
Date Test:	09/01/1999
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
H04 - Tank Leak Detection - Groundwater Well
B00 - Tank External Protection - None

MARINE MIDLAND BANK SARANAC (Continued) **U000384636**

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

SPILLS:

Name:	HSBC BANK USA
Address:	70 MAIN STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	0202668 / 2002-07-08
Facility ID:	0202668
Facility Type:	ER
DER Facility ID:	131492
Site ID:	155144
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	1700
Spill Date:	2002-05-23
Investigator:	GJHANDLY
Referred To:	Not reported
Reported to Dept:	2002-06-12
CID:	266
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-06-12
Spill Record Last Update:	2004-02-19
Spiller Name:	CLAIRE QUADRI
Spiller Company:	HSBC BANK USA
Spiller Address:	1 HSBC CENTER, 15TH FLOOR
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GH 06/12/02 - GH spoke to Tina Dorrance of S&W. Pointed out that DEC was not notified of the tank removal and the Bulk Storage registration for the new owner HSBC and the closure form were not completed or forwarded to the region 5 office. S&W assured GH that the necessary bulk storage forms with fees will be submitted by the owner soon. Advised her also that the indicated semi-volatile levels do not require additional remedial action at this time. 08/15/02 - revised closure report received by GH. Bulk Storage file contains closure report."
Remarks:	"SOIL SAMPLES TAKEN DURING REMOVAL OF A 2000 GALLON UNDERGROUND STORAGE TANK. TEST RESULTS WERE RECEIVED LAST WEEK. TEST RESULTS INDICATE THAT THERE WAS SOIL CONTAMINATION. CALLER SPOKE TO GREG HANDLY IN THE RAYBROOK OFFICE. NO FURTHER ACTION NECESSARY DUE TO LOW LEVELS."

MARINE MIDLAND BANK SARANAC (Continued) **U000384636**

All Materials:

Site ID:	155144
Operable Unit ID:	855769
Operable Unit:	01
Material ID:	520514
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

H63 **ST BERNARD'S CHURCH** **UST U000384809**
ENE **27 ST. BERNARD STREET** **AST N/A**
1/8-1/4 **SARANAC LAKE, NY 12983**
0.156 mi.
826 ft. **Site 1 of 2 in cluster H**

Relative:
Higher

Actual:
1557 ft.

UST:

Name:	ST BERNARD'S CHURCH
Address:	27 ST. BERNARD STREET
City,State,Zip:	SARANAC LAKE, NY 12983-1834
Id/Status:	5-422134 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	5
Expiration Date:	N/A
UTM X:	569308.95856
UTM Y:	4908401.25937
Site Type:	Religious Building (Church, Synagogue, Mosque, Temple, etc.)

Affiliation Records:

Site Id:	39519
Affiliation Type:	Facility Owner
Company Name:	ST BERNARDS CHURCH
Contact Type:	PASTOR
Contact Name:	FR. MARK REILLY
Address1:	27 ST. BERNAD STREET
Address2:	Not reported
City:	SARANAC LAKE
State:	NY
Zip Code:	12983-1834
Country Code:	001
Phone:	(518) 891-4616
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BXHANKIN
Date Last Modified:	2011-10-18

Site Id:	39519
Affiliation Type:	Mail Contact
Company Name:	ST BERNARDS CHURCH
Contact Type:	Not reported
Contact Name:	FR. MARK REILLY

ST BERNARD'S CHURCH (Continued) **U000384809**

Address1:	27 ST. BERNARD STREET
Address2:	Not reported
City:	SARANAC LAKE
State:	NY
Zip Code:	12983-1834
Country Code:	001
Phone:	(518) 891-4616
EMail:	STBERNARD@ROADRUNNER.COM
Fax Number:	Not reported
Modified By:	BXHANKIN
Date Last Modified:	2011-10-18

Site Id:	39519
Affiliation Type:	Facility Operator
Company Name:	ST BERNARDS CHURCH
Contact Type:	Not reported
Contact Name:	FATHER MARK REILLY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(518) 891-4616
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BXHANKIN
Date Last Modified:	2011-10-18

Site Id:	39519
Affiliation Type:	Emergency Contact
Company Name:	ST BERNARDS CHURCH
Contact Type:	Not reported
Contact Name:	FATHER MARK REILLY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(518) 891-4616
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BXHANKIN
Date Last Modified:	2011-10-18

Tank Info:

Tank Number:	001
Tank ID:	104807
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	10000
Install Date:	07/01/1987
Date Tank Closed:	08/01/1997
Registered:	True
Tank Location:	Underground

ST BERNARD'S CHURCH (Continued) **U000384809**

Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 03
Date Test: 08/01/1996
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
I04 - Overfill - Product Level Gauge (A/G)
D10 - Pipe Type - Copper
B02 - Tank External Protection - Original Sacrificial Anode
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None

Tank Number: 002
Tank ID: 104808
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: Not reported
Date Tank Closed: 09/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 01
Date Test: 12/01/1986
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
F02 - Pipe External Protection - Original Sacrificial Anode
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number: 003
Tank ID: 110583
Tank Status: Closed - Removed

ST BERNARD'S CHURCH (Continued) **U000384809**

Material Name:	Closed - Removed
Capacity Gallons:	6000
Install Date:	11/01/1997
Date Tank Closed:	07/11/2012
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	08/13/2002
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
D11 - Pipe Type - Flexible Piping
B02 - Tank External Protection - Original Sacrificial Anode
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
B04 - Tank External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None

AST:

Name:	ST BERNARD'S CHURCH
Address:	27 ST. BERNARD STREET
City,State,Zip:	SARANAC LAKE, NY 12983-1834
Region:	STATE
DEC Region:	5
Site Status:	Unregulated/Closed
Facility Id:	5-422134
Program Type:	PBS
UTM X:	569308.95856
UTM Y:	4908401.25937
Expiration Date:	N/A
Site Type:	Religious Building (Church, Synagogue, Mosque, Temple, etc.)

Affiliation Records:

Site Id:	39519
Affiliation Type:	Facility Owner
Company Name:	ST BERNARDS CHURCH
Contact Type:	PASTOR
Contact Name:	FR. MARK REILLY
Address1:	27 ST. BERNAD STREET
Address2:	Not reported
City:	SARANAC LAKE
State:	NY
Zip Code:	12983-1834
Country Code:	001

ST BERNARD'S CHURCH (Continued) **U000384809**

Phone:	(518) 891-4616
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BXHANKIN
Date Last Modified:	2011-10-18

Site Id:	39519
Affiliation Type:	Mail Contact
Company Name:	ST BERNARDS CHURCH
Contact Type:	Not reported
Contact Name:	FR. MARK REILLY
Address1:	27 ST. BERNARD STREET
Address2:	Not reported
City:	SARANAC LAKE
State:	NY
Zip Code:	12983-1834
Country Code:	001
Phone:	(518) 891-4616
EMail:	STBERNARD@ROADRUNNER.COM
Fax Number:	Not reported
Modified By:	BXHANKIN
Date Last Modified:	2011-10-18

Site Id:	39519
Affiliation Type:	Facility Operator
Company Name:	ST BERNARDS CHURCH
Contact Type:	Not reported
Contact Name:	FATHER MARK REILLY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(518) 891-4616
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BXHANKIN
Date Last Modified:	2011-10-18

Site Id:	39519
Affiliation Type:	Emergency Contact
Company Name:	ST BERNARDS CHURCH
Contact Type:	Not reported
Contact Name:	FATHER MARK REILLY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(518) 891-4616
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BXHANKIN
Date Last Modified:	2011-10-18

ST BERNARD'S CHURCH (Continued) **U000384809**

Tank Info:

Tank Number:	004
Tank Id:	244820
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I05 - Overfill - Vent Whistle
D99 - Pipe Type - Other
C01 - Pipe Location - Aboveground
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
F00 - Pipe External Protection - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
J02 - Dispenser - Suction Dispenser
K00 - Spill Prevention - None
G10 - Tank Secondary Containment - Impervious Underlayment
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/01/2012
Capacity Gallons:	660
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	005
Tank Id:	244821
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I05 - Overfill - Vent Whistle
D99 - Pipe Type - Other
C01 - Pipe Location - Aboveground
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
G01 - Tank Secondary Containment - Diking (Aboveground)
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
F00 - Pipe External Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
J02 - Dispenser - Suction Dispenser
K00 - Spill Prevention - None

ST BERNARD'S CHURCH (Continued) **U000384809**

G10 - Tank Secondary Containment - Impervious Underlayment
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/01/2012
Capacity Gallons:	0
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	006
Tank Id:	244822
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I05 - Overfill - Vent Whistle
D99 - Pipe Type - Other
C01 - Pipe Location - Aboveground
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
F00 - Pipe External Protection - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
J02 - Dispenser - Suction Dispenser
G10 - Tank Secondary Containment - Impervious Underlayment
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/01/2012
Capacity Gallons:	660
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

ST BERNARD'S CHURCH (Continued) **U000384809**

Tank Number:	007
Tank Id:	244823
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I05 - Overfill - Vent Whistle
D99 - Pipe Type - Other
C01 - Pipe Location - Aboveground
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
F00 - Pipe External Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
J02 - Dispenser - Suction Dispenser
K00 - Spill Prevention - None
G10 - Tank Secondary Containment - Impervious Underlayment
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/01/2012
Capacity Gallons:	0
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	008
Tank Id:	244824
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I05 - Overfill - Vent Whistle
D99 - Pipe Type - Other
C01 - Pipe Location - Aboveground
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
G01 - Tank Secondary Containment - Diking (Aboveground)
F00 - Pipe External Protection - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
J02 - Dispenser - Suction Dispenser
K00 - Spill Prevention - None
G10 - Tank Secondary Containment - Impervious Underlayment
A00 - Tank Internal Protection - None

ST BERNARD'S CHURCH (Continued) **U000384809**

	B01 - Tank External Protection - Painted/Asphalt Coating
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/01/2012
Capacity Gallons:	660
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)
Tank Number:	009
Tank Id:	244825
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	D99 - Pipe Type - Other
	I05 - Overfill - Vent Whistle
	C01 - Pipe Location - Aboveground
	G01 - Tank Secondary Containment - Diking (Aboveground)
	H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
	F00 - Pipe External Protection - None
	H02 - Tank Leak Detection - Interstitial - Manual Monitoring
	L09 - Piping Leak Detection - Exempt Suction Piping
	E00 - Piping Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
	K00 - Spill Prevention - None
	G10 - Tank Secondary Containment - Impervious Underlayment
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/01/2012
Capacity Gallons:	0
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)
Tank Number:	010
Tank Id:	244826

ST BERNARD'S CHURCH (Continued) **U000384809**

Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I05 - Overfill - Vent Whistle
D99 - Pipe Type - Other
C01 - Pipe Location - Aboveground
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
G01 - Tank Secondary Containment - Diking (Aboveground)
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
F00 - Pipe External Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
J02 - Dispenser - Suction Dispenser
K00 - Spill Prevention - None
G10 - Tank Secondary Containment - Impervious Underlayment
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/01/2012
Capacity Gallons:	330
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

---

64 **RIVER STREET NICE N EASY** **UST** **U001846304**
East **111 RIVER STREET** **VCP** **N/A**
1/8-1/4 **SARANAC LAKE, NY 12983** **NY Spills**
0.164 mi.
864 ft.

Relative:
Higher

Actual:
1537 ft.

UST:

Name:	RIVER STREET NICE N EASY
Address:	111 RIVER STREET
City,State,Zip:	SARANAC LAKE, NY 12983
Id/Status:	5-136050 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	5
Expiration Date:	N/A
UTM X:	569660.24481
UTM Y:	4908271.99751
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	38829
Affiliation Type:	Mail Contact
Company Name:	HYDE FUEL CO.
Contact Type:	Not reported

RIVER STREET NICE N EASY (Continued) **U001846304**

Contact Name:	TOM HYDE
Address1:	196 BROADWAY
Address2:	PO BOX 349
City:	SARANAC LAKE
State:	NY
Zip Code:	12983
Country Code:	001
Phone:	(518) 891-3151
EMail:	Not reported
Fax Number:	Not reported
Modified By:	rbmulvey
Date Last Modified:	2009-07-22

Site Id:	38829
Affiliation Type:	Facility Operator
Company Name:	RIVER STREET NICE N EASY
Contact Type:	Not reported
Contact Name:	HYDE FUEL CO.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 891-5614
EMail:	Not reported
Fax Number:	Not reported
Modified By:	bxhankin
Date Last Modified:	2008-10-02

Site Id:	38829
Affiliation Type:	Emergency Contact
Company Name:	ALASKAN OIL, INC.
Contact Type:	Not reported
Contact Name:	TOM HYDE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(518) 891-3151
EMail:	Not reported
Fax Number:	Not reported
Modified By:	bxhankin
Date Last Modified:	2008-10-02

Site Id:	38829
Affiliation Type:	Facility Owner
Company Name:	P.J. HYDE & SON INC.
Contact Type:	VICE PRESIDENT
Contact Name:	TERRY COOK
Address1:	196 BROADWAY - P.O. BOX 349
Address2:	Not reported
City:	SARANAC LAKE
State:	NY
Zip Code:	12983

RIVER STREET NICE N EASY (Continued) **U001846304**

Country Code:	001
Phone:	(518) 891-3151
EMail:	Not reported
Fax Number:	Not reported
Modified By:	rbmulvey
Date Last Modified:	2009-07-22

Tank Info:

Tank Number:	001
Tank ID:	101967
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	4000
Install Date:	10/01/1972
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number:	002
Tank ID:	101968
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	4000
Install Date:	10/01/1972
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

RIVER STREET NICE N EASY (Continued) **U001846304**

Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 003
Tank ID: 101969
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 4000
Install Date: 10/01/1972
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 004
Tank ID: 101970
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 4000
Install Date: 10/01/1972
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel

RIVER STREET NICE N EASY (Continued) **U001846304**

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number: 005
Tank ID: 101971
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 4000
Install Date: 10/01/1972
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 006
Tank ID: 101972
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91

RIVER STREET NICE N EASY (Continued) **U001846304**

Capacity Gallons:	4000
Install Date:	10/01/1972
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	007
Tank ID:	101973
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	8000
Install Date:	05/01/1989
Date Tank Closed:	04/14/2009
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	01
Date Test:	06/01/1989
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
G04 - Tank Secondary Containment - Double-Walled (Underground)
B02 - Tank External Protection - Original Sacrificial Anode
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser

RIVER STREET NICE N EASY (Continued) **U001846304**

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
C02 - Pipe Location - Underground/On-ground

Tank Number: 008
Tank ID: 101974
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 8000
Install Date: 05/01/1989
Date Tank Closed: 04/14/2009
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 01
Date Test: 06/01/1989
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
J01 - Dispenser - Pressurized Dispenser
F00 - Pipe External Protection - None
B02 - Tank External Protection - Original Sacrificial Anode
I01 - Overfill - Float Vent Valve
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E00 - Piping Secondary Containment - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: 009
Tank ID: 111548
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 03/23/2000
Date Tank Closed: 04/14/2009
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: NN

RIVER STREET NICE N EASY (Continued) **U001846304**

Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
G04 - Tank Secondary Containment - Double-Walled (Underground)
B02 - Tank External Protection - Original Sacrificial Anode
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin

VCP:

Name: 70 RIVER STREET (ALASKAN OIL)
Address: 70 RIVER STREET
City,State,Zip: SARANAC LAKE, NY 12983-
Program Type: VCP
Site Code: 57893
HW Code: V00017
Site Class: N
SWIS: 1746
Region: 5
Town: Harrietstown
Acres: Not reported
Date Record Added: 11/30/2000
Date Record Updated: 04/01/2009
Updated By: MOBARRIE
Site Description: "Site Description The Parish Energy/Alaskan Oil nice and easy gas station is located at 70 River Street in the Village of Saranac Lake, Franklin County. The main site feature is the gasoline convenience store building with fuel dispensers and canopies. The site is still currently being used as a gasoline retail facility. Surrounding properties are currently being used as residential, commercial and a village park on Saranac Lake. Underground fuel storage tanks and dispensers are the historical sources of contamination. Original subsurface investigation was performed in November 1995 and a supplementary investigation was performed off site. The sites current activities are limited to groundwater monitoring The VCA was terminated on September 15, 2007. As of that date, remedial work at the site reverted to the spill response program and is being managed under Spill Number 98-00441."
Env Problem: "Environmental Assessment The primary contaminants of concern at this site are Benzene, toluene, ethylbenzene, xylene(BTEX) and MTBE resulting from the underground petroleum storage tanks. Investigations indicate that a groundwater plume extends to the southeast underneath River Street toward but not to Saranac Lake. Groundwater standard exceedances have occurred for Benzene,

RIVER STREET NICE N EASY (Continued) **U001846304**

ethylbenzene and mtbe. There does not appear to be resource or significant environmental threat at this site. While the plume extends toward Saranac Lake, several years have monitoring have indicated that it is not expanding to the lake."

Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	6
Sub Type:	ZZZ
Owner Name:	RICHARD A. NEUGEBAUER,PRES.
Owner Company:	Alaskan Oil, Inc.
Owner Address:	500 SOLAR ST.
Owner Addr2:	Not reported
Owner City,St,Zip:	SYRACUSE, NY 13204
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	NICE AND EASY
Address:	70 RIVER ST
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9800441 / 2010-08-02
Facility ID:	9800441
Facility Type:	ER
DER Facility ID:	115423
Site ID:	134326
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	1746
Spill Date:	1998-04-10
Investigator:	rbmulvey
Referred To:	Not reported
Reported to Dept:	1998-04-10
CID:	281
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other

RIVER STREET NICE N EASY (Continued) **U001846304**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-04-10
Spill Record Last Update:	2010-08-02
Spiller Name:	Not reported
Spiller Company:	NICE AND EASY
Spiller Address:	70 RIVER ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"08/02/10: Russ Mulvey reviewed the CT Male report concerning the site remediation. Approximately 2,700 tons of contaminated soil and 100,000 gallons of contaminated water were removed from the site. There are remnant contamination spots left under the adjacent side walk and roadways (River Street and Shepard Ave.) There is also a small isolated hot spot near the northeast corner of the former pump island concrete mat. These spots are not believed to be significant amounts, and are isolated from direct contact, and the area is served by public water. This spill is therefore closed as not meeting standards. Russ sent Tom Hyde a letter stating this via e-mail at tom@hydefuel.com. RFC- Spill has been remediated to the extent feasible at this time."
Remarks:	"DURING A SCHEDULED SUB-SURFACE INVESTIGATION AN UNKNOWN AMOUNT OF MATERIAL BELIEVED TO BE GASOLINE WAS DISCOVERED. FURTHER TESTING AT LOCATION WILL BE DONE AT A LATER TIME. NO CALL BACK REQUESTED AT TIME OF CALL."

All Materials:

Site ID:	134326
Operable Unit ID:	1057799
Operable Unit:	01
Material ID:	566535
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

I65 **CLUB SARANAC** **LTANKS** **S107417362**
NNE **BROADWAY ST** **N/A**
1/8-1/4 **SARANAC LAKE, NY**
0.166 mi.
879 ft. **Site 1 of 5 in cluster I**

Relative:
Higher

Actual:
1531 ft.

LTANKS:

Name:	CLUB SARANAC
Address:	BROADWAY ST
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9515930 / 1996-05-31
Facility ID:	9515930
Site ID:	312196
Spill Date:	1996-03-05
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	1700
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1996-03-12
CID:	312
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-03-12
Spill Record Last Update:	1996-06-03
Spiller Name:	Not reported
Spiller Company:	ALICE'S RESTAURANT
Spiller Address:	BROADWAY ST.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	251754
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM 05/31/96: No oil in sump noted. EP&S to survey in elevation of sump in relation to Alice's Restaurant. RFC: No spill noted, refer to spill # 9506484 for more information."
Remarks:	"CALLER INDICATED FUEL OIL EVIDENT IN SUMP OF CLUB SARANAC - MM TO INVESTIGATE"

All Materials:

Site ID:	312196
Operable Unit ID:	1026904
Operable Unit:	01
Material ID:	352474
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

CLUB SARANAC (Continued) **S107417362**

Resource Affected: Groundwater
Oxygenate: Not reported

I66 **FORMER ALICE'S REST.** **LTANKS** **S102233797**
NNE **BROADWAY STREET** **NY Spills** **N/A**
1/8-1/4 **SARANAC LAKE, NY**
0.168 mi.
886 ft. **Site 2 of 5 in cluster I**

Relative: **Higher**

Actual: **1537 ft.**

LTANKS:

Name:	FORMER ALICE'S REST.
Address:	BROADWAY STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9506484 / 2006-02-15
Facility ID:	9506484
Site ID:	122398
Spill Date:	1995-05-01
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	A1
Cleanup Ceased:	Not reported
SWIS:	1746
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1995-08-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-08-25
Spill Record Last Update:	2006-02-17
Spiller Name:	Not reported
Spiller Company:	ALICE CARTER (DECEASED)
Spiller Address:	2 BROADWAY STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	309664
DEC Memo:	"08/24/95: 2K tank outside building. Not in use. Unsure of source. Further investigation to be pursued. 09/21/95: Significant oil noted pooling in Piro basement. EP&S hired to perform cleanup. 10/02/95: Piro 2K UST removed, not source. 10/03/95: Tank at Alice's fails tank test, oil noted entering into tank from subsurface during test/closeout procedures. 10/10/95: Nine monitor wells installed by EP&S, 2 feet of oil present in one well. Vent and recovery system in Piro basement operating fine. Awaiting EP&P investigation before recovery system design. 12/05/95: Interim ISR sent to Albany. 06/08/96: Dual phase vapor extraction system operating at location to recover free product. SVES/free product in sump pit ongoing in Piro basement. 11/29/96: Dual phase system removed, over 700 gallons oil removed from ground via system. 07/03/98: Free product appearing in

FORMER ALICE'S REST. (Continued) **S102233797**

MW's and in sump pit in Piro basement, Adirondack Associates hired to collect product bimonthly. 02/14/03: Free product recovery ongoing, soil vapor extraction system still operating in Piro basement. 02/15/06: Free product still in monitoring wells and in Piro basement, unsure of source, area may act as a low collection point for the village. To close this spill out and monitor select wells for free product using Spill # 0551598. No further costs under this spill. RFC: Spill remediated to the extent practical. No further DEC action required. 02/17/06: Final ISR sent to Albany."

Remarks: "FURTHER INVESTIGATION INTO DR. NEILL SPILL FOUND LINDA PIRO BASEMENT WITH SIGNIFICANT AREA OF OIL CONTAMINATION. OLD SPEEDY DRY STILL THROUGHOUT BASEMENT. OWNER INDICATES SPILL HAPPENED IN SPRING."

All Materials:

Site ID:	122398
Operable Unit ID:	1021257
Operable Unit:	01
Material ID:	364449
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	800.00
Resource Affected:	Soil, Indoor Air, Groundwater
Oxygenate:	Not reported

SPILLS:

Name:	MAURICE'S BEAUTY SALON
Address:	10 BROADWAY
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9705846 / 1997-08-14
Facility ID:	9705846
Facility Type:	ER
DER Facility ID:	61744
Site ID:	64010
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	1700
Spill Date:	1997-08-14
Investigator:	RDHUYCK
Referred To:	Not reported
Reported to Dept:	1997-08-14
CID:	369
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-08-14

FORMER ALICE'S REST. (Continued) **S102233797**

Spill Record Last Update:	1997-08-15
Spiller Name:	LINDA PIRO
Spiller Company:	ALICE'S RESTAURANT
Spiller Address:	4-6 BROADWAY
Spiller Company:	001
Contact Name:	LINDA PIRO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RH/LM RFC: See spill # 9506484. Vent system was unplugged from power source. System is now working again. "
Remarks:	"TANK FROM CALLERS NEXT DOOR NEIGHBOR IS LEAKING INTO THE BASEMENT. MICHAEL MCLEAN IS AWARE OF SITUATION. CALLER SAYS EQUIP NOT WORKING. PUMP NOT PUMPING, ODORS BUILDING UP IN BASEMENT."

All Materials:

Site ID:	64010
Operable Unit ID:	1049121
Operable Unit:	01
Material ID:	331463
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

I67 **MAURICES BUILDING** **UST** **U000384659**
NNE **10 BROADWAY** **N/A**
1/8-1/4 **SARANAC LAKE, NY 12983**
0.168 mi.
886 ft. **Site 3 of 5 in cluster I**

Relative: Higher
Actual: 1537 ft.

UST:

Name:	MAURICES BUILDING
Address:	10 BROADWAY
City,State,Zip:	SARANAC LAKE, NY 12983
Id/Status:	5-229326 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	5
Expiration Date:	N/A
UTM X:	569234.72914
UTM Y:	4908580.55088
Site Type:	Other

Affiliation Records:

Site Id:	38989
Affiliation Type:	Facility Owner
Company Name:	LINDA PIRO
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	4 MARSHALL
Address2:	Not reported
City:	SARANAC LAKE
State:	NY

MAURICES BUILDING (Continued) **U000384659**

Zip Code:	12983
Country Code:	001
Phone:	(518) 891-4760
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	38989
Affiliation Type:	Mail Contact
Company Name:	LINDA PIRO
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	4 MARSHALL
Address2:	Not reported
City:	SARANAC LAKE
State:	NY
Zip Code:	12983
Country Code:	001
Phone:	(518) 891-4760
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	38989
Affiliation Type:	Facility Operator
Company Name:	MAURICES BUILDING
Contact Type:	Not reported
Contact Name:	LINDA PIRO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 891-1555
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	38989
Affiliation Type:	Emergency Contact
Company Name:	LINDA PIRO
Contact Type:	Not reported
Contact Name:	MILES VAN NORTWICK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 891-2445
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT

MAURICES BUILDING (Continued) **U000384659**

Date Last Modified: 2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	104086
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	10/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
H00 - Tank Leak Detection - None
I00 - Overfill - None

H68 **NY TELEPHONE COMPANY** **LTANKS** **S103478107**
ENE **CHURCH STREET** **N/A**
1/8-1/4 **SARANAC LAKE, NY**
0.175 mi.
925 ft. **Site 2 of 2 in cluster H**

Relative: LTANKS:
Higher

Actual: Name:	NY TELEPHONE COMPANY
1555 ft. Address:	CHURCH STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9107797 / 1991-11-01
Facility ID:	9107797
Site ID:	318731
Spill Date:	1991-10-22
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1991-11-01
SWIS:	1700
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1991-10-22
CID:	Not reported

NY TELEPHONE COMPANY (Continued) **S103478107**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1991-10-23
Spill Record Last Update:	1998-07-21
Spiller Name:	Not reported
Spiller Company:	NY TELEPHONE COMPANY
Spiller Address:	CHURCH STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	278171
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM "
Remarks:	"6K TANK FAILED PETRO-TITE @ -.443. TO EXCAVATE, ISOLATE AND RETEST EITHER TUESDAY OR WEDNESDAY. 10/31-TANK RETESTED AND PASSED, FAILED DUE TO AIR POCKETS IN TANK, NO CONT. NOTED ANR. EXCAVATED PIPING."

All TTF:

Facility ID:	9107797
Spill Number:	9107797
Spill Tank Test:	1539199
Site ID:	318731
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	318731
Operable Unit ID:	961872
Operable Unit:	01
Material ID:	419982
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

I69 **OXFORD MARKET BLDG** **LTANKS** **S100162037**
NNE **BROADWAY ST** **NY Spills** **N/A**
1/8-1/4 **SARANAC LAKE, NY**
0.177 mi.
932 ft. **Site 4 of 5 in cluster I**

Relative: **Lower**

Actual: **1518 ft.**

LTANKS:

Name:	OXFORD MARKET BLDG
Address:	BROADWAY STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9004926 / 1994-01-10
Facility ID:	9004926
Site ID:	122392
Spill Date:	1990-08-02
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C3
Cleanup Ceased:	1994-01-10
SWIS:	1700
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1990-08-02
CID:	Not reported
Water Affected:	SARANAC RIVER
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-08-07
Spill Record Last Update:	1995-11-09
Spiller Name:	BILL DECKER
Spiller Company:	BIG D
Spiller Address:	188 BROADWAY STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	106117
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM RFC: Minimal amount of contaminated soil remediated on sie. No further action. "
Remarks:	"TANKER OVERFILLED TANK BY APPROX. 50-100 GALLONS, FUEL INTO DIRT DRIVEWAY, DOWN SIDEWALK, INTO STORM SEWER, INTO SARANAC RIVER. BIG D TO PERFORM CLEANUP (SOIL REMOVAL, BOOM/SORBENT MAINTENANCE)"

All Materials:

Site ID:	122392
Operable Unit ID:	942570
Operable Unit:	01
Material ID:	436001
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00

OXFORD MARKET BLDG (Continued) **S100162037**

Resource Affected:	Surface Water
Oxygenate:	Not reported

SPILLS:

Name:	OXFORD MARKET BLDG
Address:	BROADWAY ST
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9508695 / 1995-10-17
Facility ID:	9508695
Facility Type:	ER
DER Facility ID:	251754
Site ID:	312193
DEC Region:	5
Spill Cause:	Equipment Failure
Spill Class:	D3
SWIS:	1700
Spill Date:	1995-10-16
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1995-10-16
CID:	365
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	1995-10-17
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-10-16
Spill Record Last Update:	1995-11-06
Spiller Name:	Not reported
Spiller Company:	BIG-D-FUEL
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM/LM RFC: MM/LM checked area 10/17/95, minor spill, cleanup adequate. "
Remarks:	"problems w/ vent line resulted in oil blowing out vent into wall - <2 gallons lost - spill cleaned up - big d to excavate & repair vent line - tank not over filled - mm will check 10/16 **faxed over from region 5r**"

All Materials:

Site ID:	312193
Operable Unit ID:	1019280
Operable Unit:	01
Material ID:	359659
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	22.00
Units:	G

OXFORD MARKET BLDG (Continued) **S100162037**

Recovered: .00
Resource Affected: Groundwater
Oxygenate: Not reported

J70 **HOTEL SARANAC** **AST** **U003076832**
NE **100 MAIN ST** **N/A**
1/8-1/4 **SARANAC LAKE, NY 12983**
0.177 mi.
932 ft. **Site 1 of 3 in cluster J**

Relative:
Higher

Actual:
1552 ft.

AST:
Name: HOTEL SARANAC
Address: 100 MAIN ST
City,State,Zip: SARANAC LAKE, NY 12983
Region: STATE
DEC Region: 5
Site Status: Unregulated/Closed
Facility Id: 5-422452
Program Type: PBS
UTM X: 569336.69592
UTM Y: 4908592.04733
Expiration Date: N/A
Site Type: Other

Affiliation Records:
Site Id: 39530
Affiliation Type: Facility Operator
Company Name: HOTEL SARANAC
Contact Type: Not reported
Contact Name: SARDESHWARI ENT., INC.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NY
Zip Code: Not reported
Country Code: 001
Phone: (518) 891-2200
EMail: Not reported
Fax Number: Not reported
Modified By: BXHANKIN
Date Last Modified: 2010-12-03

Site Id: 39530
Affiliation Type: Emergency Contact
Company Name: SARDESHWARI ENT., INC.
Contact Type: Not reported
Contact Name: HOTEL SARANAC MAIN DESK
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (518) 891-2200
EMail: Not reported
Fax Number: Not reported
Modified By: BXHANKIN

HOTEL SARANAC (Continued) **U003076832**

Date Last Modified: 2010-12-03

Site Id: 39530
Affiliation Type: Facility Owner
Company Name: SARDESHWARI ENT., INC.
Contact Type: MANAGER
Contact Name: SEWA R. ARORA
Address1: 100 MAIN STREET
Address2: Not reported
City: SARANAC LAKE
State: NY
Zip Code: 12983
Country Code: 001
Phone: (518) 891-2200
EMail: SESAR@AOL.COM
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2013-10-28

Site Id: 39530
Affiliation Type: Mail Contact
Company Name: SARDESHWARI ENT., INC.
Contact Type: MANAGER
Contact Name: SEWA R. ARORA
Address1: 100 MAIN STREET
Address2: Not reported
City: SARANAC LAKE
State: NY
Zip Code: 12983
Country Code: 001
Phone: (518) 891-2200
EMail: SESAR@AOL.COM
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2013-10-28

Tank Info:

Tank Number: 001A
Tank Id: 111779
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.

HOTEL SARANAC (Continued) **U003076832**

Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	330
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	11/01/2007
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	001B
Tank Id:	111780
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	330
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	11/01/2007
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	040
Tank Id:	104795
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

HOTEL SARANAC (Continued) **U003076832**

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/01/1988
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	042
Tank Id:	104796
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/01/1988
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

J71 **HOTEL SARANAC** **UST** **U004063994**
NE **100 MAIN ST** **N/A**
1/8-1/4 **SARANAC LAKE, NY 12983**
0.177 mi.
932 ft. **Site 2 of 3 in cluster J**

Relative:
Higher

Actual:
1552 ft.

UST:

Name:	HOTEL SARANAC
Address:	100 MAIN ST
City,State,Zip:	SARANAC LAKE, NY 12983
Id/Status:	5-422452 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	5
Expiration Date:	N/A
UTM X:	569336.69592
UTM Y:	4908592.04733
Site Type:	Other

Affiliation Records:

Site Id:	39530
Affiliation Type:	Facility Operator
Company Name:	HOTEL SARANAC
Contact Type:	Not reported
Contact Name:	SARDESHWARI ENT., INC.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 891-2200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BXHANKIN
Date Last Modified:	2010-12-03

Site Id:	39530
Affiliation Type:	Emergency Contact
Company Name:	SARDESHWARI ENT., INC.
Contact Type:	Not reported
Contact Name:	HOTEL SARANAC MAIN DESK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(518) 891-2200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BXHANKIN
Date Last Modified:	2010-12-03

Site Id:	39530
Affiliation Type:	Facility Owner
Company Name:	SARDESHWARI ENT., INC.
Contact Type:	MANAGER
Contact Name:	SEWA R. ARORA
Address1:	100 MAIN STREET

HOTEL SARANAC (Continued) **U004063994**

Address2:	Not reported
City:	SARANAC LAKE
State:	NY
Zip Code:	12983
Country Code:	001
Phone:	(518) 891-2200
EMail:	SESAR@AOL.COM
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2013-10-28

Site Id:	39530
Affiliation Type:	Mail Contact
Company Name:	SARDESHWARI ENT., INC.
Contact Type:	MANAGER
Contact Name:	SEWA R. ARORA
Address1:	100 MAIN STREET
Address2:	Not reported
City:	SARANAC LAKE
State:	NY
Zip Code:	12983
Country Code:	001
Phone:	(518) 891-2200
EMail:	SESAR@AOL.COM
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2013-10-28

Tank Info:

Tank Number:	038
Tank ID:	104793
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	4000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

HOTEL SARANAC (Continued) **U004063994**

F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	039
Tank ID:	104794
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	4000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	044
Tank ID:	104797
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	10000
Install Date:	10/01/1988
Date Tank Closed:	10/30/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	09/02/2003
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

HOTEL SARANAC (Continued) **U004063994**

A00 - Tank Internal Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
C00 - Pipe Location - No Piping
B00 - Tank External Protection - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
F02 - Pipe External Protection - Original Sacrificial Anode

J72 **MORGAN RESIDENCE** **LTANKS** **S102119612**
NE **104 MAIN STREET** **NY Spills** **N/A**
1/8-1/4 **SARANAC LAKE, NY**
0.184 mi.
974 ft. **Site 3 of 3 in cluster J**

Relative: **Higher**
Actual: **1551 ft.**

LTANKS:

Name:	104 MAIN STREET
Address:	104 MAIN ST
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	0208796 / 2002-12-03
Facility ID:	0208796
Site ID:	168485
Spill Date:	2002-11-25
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	1600
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	2002-11-25
CID:	270
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-11-25
Spill Record Last Update:	2002-12-03
Spiller Name:	MORGAN
Spiller Company:	ELIZABETH VIEIROS
Spiller Address:	104 MAIN ST
Spiller County:	001
Spiller Contact:	ELIZABETH VIEIROS
Spiller Phone:	(518) 891-4295
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	141939
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM RFC: No apparent environmental or health impact from release, further investigation or cleanup not practical or pursued."
Remarks:	"Contaminated soil discovered during tank removal. MM on site 11/25/02 @ 1410 hours, tank has not been used for several years, in bad shape, fuel oil contaminated soil noted beneath tank but unable

MORGAN RESIDENCE (Continued) **S102119612**

to remove soil, determine contamination extent due to site conditions (water line, cedar hedge, tight conditions, slope)."

All Materials:

Site ID:	168485
Operable Unit ID:	860215
Operable Unit:	01
Material ID:	515790
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

SPILLS:

Name:	MORGAN RESIDENCE
Address:	104 MAIN STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9312250 / 1994-01-14
Facility ID:	9312250
Facility Type:	ER
DER Facility ID:	195134
Site ID:	236867
DEC Region:	5
Spill Cause:	Human Error
Spill Class:	D4
SWIS:	1700
Spill Date:	1994-01-14
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1994-01-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party
Cleanup Ceased:	1994-01-14
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-01-19
Spill Record Last Update:	1996-01-22
Spiller Name:	Not reported
Spiller Company:	BIG D
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM RFC: Minor spill, no response taken. "
Remarks:	"MINOR QUANTITY OF OIL SPILLED DUE TO OVERFILL ON GROUND OUTSIDE.

MORGAN RESIDENCE (Continued) **S102119612**

SHOVELED INTO DRUM FOR MELT/SEPARATION."

All Materials:

Site ID:	236867
Operable Unit ID:	990876
Operable Unit:	01
Material ID:	391241
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

K73 **PRIMETIME RESTAURANT** **LTANKS** **S103558378**
North **42 BROADWAY STREET** **NY Spills** **N/A**
1/8-1/4 **SARANAC LAKE, NY**
0.189 mi.
999 ft. **Site 1 of 2 in cluster K**

Relative: **Lower**

Actual: **1514 ft.**

LTANKS:

Name:	RAINDANCER
Address:	42 BROADWAY
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9810147 / 1998-11-12
Facility ID:	9810147
Site ID:	238171
Spill Date:	1998-11-11
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	1700
Investigator:	LJMILLIO
Referred To:	Not reported
Reported to Dept:	1998-11-11
CID:	233
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-11-11
Spill Record Last Update:	1998-11-12
Spiller Name:	BILL DECKER
Spiller Company:	BIG D FUEL
Spiller Address:	200 BROADWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5

PRIMETIME RESTAURANT (Continued) **S103558378**

DER Facility ID: 196167
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was LM RFC: Spill adequately cleaned up. "
Remarks: "1 QUART OF OIL SPILLED DUE TO TANK OVERFILL. SPILL TO SOIL AND CONCRETE. CLEAN UP IS UNDERWAY. ALSO SOME FUEL BEING REMOVED FROM TANK TO PREVENT MORE SPILLAGE. "

All Materials:
Site ID: 238171
Operable Unit ID: 1067423
Operable Unit: 01
Material ID: 314026
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: 1.00
Resource Affected: Soil
Oxygenate: Not reported

SPILLS:
Name: PRIMETIME RESTAURANT
Address: 42 BROADWAY STREET
City,State,Zip: SARANAC LAKE, NY
Spill Number/Closed Date: 9010686 / 1991-01-07
Facility ID: 9010686
Facility Type: ER
DER Facility ID: 63584
Site ID: 66395
DEC Region: 5
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 1700
Spill Date: 1991-01-04
Investigator: MPMCLEAN
Referred To: Not reported
Reported to Dept: 1991-01-04
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: 1991-01-07
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1991-01-07
Spill Record Last Update: 1999-02-22
Spiller Name: Not reported
Spiller Company: BIG D
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported

PRIMETIME RESTAURANT (Continued) **S103558378**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM
"

Remarks: "DRIVER ATTEMPTED TO DELIVER FUEL, FUEL BACKED UP INTO FILL PIPE. MOST OF FUEL SPILLED ONTO DRIVERS CLOTHES, REST CLEANED UP WOTH ABSORBENT PAD. NO ACTION BY SPILL RESPONSE."

All Materials:

Site ID:	66395
Operable Unit ID:	950914
Operable Unit:	01
Material ID:	430818
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	SARANAC RIVER SHEEN
Address:	42 BROADWAY
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9609165 / 1996-10-23
Facility ID:	9609165
Facility Type:	ER
DER Facility ID:	196167
Site ID:	238170
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	A1
SWIS:	1700
Spill Date:	1996-10-22
Investigator:	LJMILLIO
Referred To:	Not reported
Reported to Dept:	1996-10-22
CID:	233
Water Affected:	SARANAC RIVER
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-10-22
Spill Record Last Update:	1996-10-24
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was LM 10/22/96: LM on site at approximately 1730 hrs. Minor sheen on river, appears to be hydraulic

PRIMETIME RESTAURANT (Continued) **S103558378**

oil coming from construction
site at Rt. 3 bridge. Mike will check on 10/23/96. RFC: Mike checked site, sheen gone. "

Remarks: "Caller sees oil of some type on the surface of river."

All Materials:

Site ID:	238170
Operable Unit ID:	1037248
Operable Unit:	01
Material ID:	344894
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

74
North
1/8-1/4
0.198 mi.
1043 ft.

DARING RESIDENCE **LTANKS** **S103824225**
5 SUMNER PLACE **N/A**
SARANAC LAKE, NY

Relative:
Higher

Actual:
1540 ft.

LTANKS:

Name:	DARING RESIDENCE
Address:	5 SUMNER PLACE
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9845097 / 1999-04-19
Facility ID:	9845097
Site ID:	251141
Spill Date:	1999-03-12
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	1700
Investigator:	SELALOND
Referred To:	Not reported
Reported to Dept:	1999-03-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-03-15
Spill Record Last Update:	2000-01-04
Spiller Name:	Not reported
Spiller Company:	BARB DARING
Spiller Address:	PO BOX 1295
Spiller County:	001
Spiller Contact:	BILL DECKER

DARING RESIDENCE (Continued) **S103824225**

Spiller Phone: (518) 891-1900
Spiller Extention: Not reported
DEC Region: 5
DER Facility ID: 205831
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was SL RFC: Cleanup complete. "
Remarks: "2-275 g AST's in basement. One tank found to be leaking. Tanks being pumped out and replaced. Cleanup being completed by fuel supplier."

All Materials:
Site ID: 251141
Operable Unit ID: 1074067
Operable Unit: 01
Material ID: 309233
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

L75 **SARANAC LAKE CSD - PETROVA MIDDLE SCHOOL** **AIRS S121491052**
West **141 PETROVA AVE** **MANIFEST N/A**
1/8-1/4 **SARANAC LAKE, NY 12983**
0.200 mi.
1054 ft. **Site 1 of 4 in cluster L**

Relative: **Higher**
Actual: **1566 ft.**

AIRS:
Name: PETROVA ELEMENTARY SCHOOL
Address: 141 PETROVA AVE
City,State,Zip: SARANAC LAKE, NY 12983
DECID: 5164600348
Process ID: Not reported
Latitude: Not reported
Longitude: Not reported
FIPS Code: Not reported
Auth Type Code: AFR

Permit Status: Issued
Auth Status Code: 2
Emissions: Not reported
Issue date: 10/15/2015
Expired Date: 10/14/2025
Emission Unit date: Not reported
Contamination: Not reported
EPA Control Code: Not reported
Control Eff: Not reported
Unit: Not reported

Permit Status: Expired
Auth Status Code: 7
Emissions: Not reported
Issue date: 08/24/2011
Expired Date: 10/14/2015

SARANAC LAKE CSD - PETROVA MIDDLE SCHOOL (Continued) **S121491052**

Emission Unit date:	Not reported
Contamination:	Not reported
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	Not reported

NY MANIFEST:

Name:	SARANAC LAKE CSD - PETROVA MIDDLE SCHOOL
Address:	141 PETROVA AVE
City,State,Zip:	SARANAC LAKE, NY 12983
Country:	USA
EPA ID:	NYD987014651
Facility Status:	Not reported
Location Address 1:	141 PETROVA AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	SARANAC LAKE
Location State:	NY
Location Zip:	12983
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD987014651
Mailing Name:	SARANAC LAKE CSD - PETROVA MIDDLE SCHOOL
Mailing Contact:	DICK MOSE
Mailing Address 1:	141 PETROVA AVE
Mailing Address 2:	Not reported
Mailing City:	SARANAC LAKE
Mailing State:	NY
Mailing Zip:	12983
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5188915460

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD986980753
Trans2 State ID:	NJ0000027193
Generator Ship Date:	12/03/2009
Trans1 Recv Date:	12/03/2009
Trans2 Recv Date:	12/11/2009
TSD Site Recv Date:	12/14/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987014651
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	001055119JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N

SARANAC LAKE CSD - PETROVA MIDDLE SCHOOL (Continued) **S121491052**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	275
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	4
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	P005
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L76 **SARANAC LAKE CENTRAL SCHOOL DIST.** **AST** **U003153271**
West **141 PETROVA AVENUE** **N/A**
1/8-1/4 **SARANAC LAKE, NY 12983**
0.200 mi.
1054 ft. **Site 2 of 4 in cluster L**

Relative:
Higher

Actual:
1566 ft.

AST:

Name:	SARANAC LAKE CENTRAL SCHOOL DIST.
Address:	141 PETROVA AVENUE
City,State,Zip:	SARANAC LAKE, NY 12983
Region:	STATE
DEC Region:	5
Site Status:	Active
Facility Id:	5-230006
Program Type:	PBS
UTM X:	568899.09787
UTM Y:	4908315.46942
Expiration Date:	07/10/2027
Site Type:	School

Affiliation Records:

Site Id:	39048
Affiliation Type:	Facility Operator
Company Name:	SARANAC LAKE CENTRAL SCHOOL DIST.
Contact Type:	Not reported
Contact Name:	VERNON JAMES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

SARANAC LAKE CENTRAL SCHOOL DIST. (Continued) **U003153271**

Zip Code:	Not reported
Country Code:	001
Phone:	(518) 897-1726
EMail:	Not reported
Fax Number:	Not reported
Modified By:	RBMULVEY
Date Last Modified:	2017-06-12

Site Id:	39048
Affiliation Type:	Emergency Contact
Company Name:	SARANAC LAKE CENTRAL SCHOOL DIST.
Contact Type:	Not reported
Contact Name:	VERNON JAMES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(518) 637-2653
EMail:	Not reported
Fax Number:	Not reported
Modified By:	RBMULVEY
Date Last Modified:	2017-06-12

Site Id:	39048
Affiliation Type:	Mail Contact
Company Name:	SARANAC LAKE CENTRAL SCHOOL DIST.
Contact Type:	Not reported
Contact Name:	VERNON JAMES
Address1:	79 CANARAS AVE
Address2:	Not reported
City:	SARANAC LAKE
State:	NY
Zip Code:	12983
Country Code:	001
Phone:	(518) 897-1726
EMail:	JAMESVER@SLCS.ORG
Fax Number:	Not reported
Modified By:	BXHANKIN
Date Last Modified:	2013-09-05

Site Id:	39048
Affiliation Type:	Facility Owner
Company Name:	SARANAC LAKE CENTRAL SCHOOL DIST.
Contact Type:	DIRECTOR OF FACILITIES II
Contact Name:	VERNON P JAMES
Address1:	79 CANARAS AVE
Address2:	Not reported
City:	SARANAC LAKE
State:	NY
Zip Code:	12983
Country Code:	001
Phone:	(518) 891-5460
EMail:	JAMESVER@SLCS.ORG
Fax Number:	Not reported
Modified By:	KBSWEET

SARANAC LAKE CENTRAL SCHOOL DIST. (Continued) **U003153271**

Date Last Modified: 2022-07-21

Tank Info:

Tank Number: 005
Tank Id: 110134
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
F00 - Pipe External Protection - None
J06 - Dispenser - Tank Mounted Dispenser
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
G12 - Tank Secondary Containment - Double-Walled (AG only)
D99 - Pipe Type - Other

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 08/01/1996
Capacity Gallons: 500
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: gasoline/ethanol

Tank Number: 007
Tank Id: 235131
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

J05 - Dispenser - On Site Heating System (Supply/Return)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G10 - Tank Secondary Containment - Impervious Underlayment
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None

SARANAC LAKE CENTRAL SCHOOL DIST. (Continued) **U003153271**

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/1996
Capacity Gallons:	10
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/12/2018
Register:	True
Modified By:	KBSWEET
Last Modified:	07/21/2022
Material Name:	#2 fuel oil (on-site consumption)

L77 **SARANAC LAKE CSD - PETROVA MIDDLE SCHOOL** **RCRA-VSQG** **1004758654**
West **141 PETROVA AVE** **FINDS** **NYD987014651**
1/8-1/4 **SARANAC LAKE, NY 12983** **ECHO**
0.200 mi.
1054 ft. **Site 3 of 4 in cluster L**

Relative: **Higher**
Actual: **1566 ft.**

RCRA Listings:

Date Form Received by Agency:	20090714
Handler Name:	Saranac Lake Csd - Petrova Middle School
Handler Address:	141 PETROVA AVE
Handler City,State,Zip:	SARANAC LAKE, NY 12983
EPA ID:	NYD987014651
Contact Name:	SCOTT P PRUE
Contact Address:	CANARAS AVE
Contact City,State,Zip:	SARANAC LAKE, NY 12983
Contact Telephone:	518-897-1572
Contact Fax:	Not reported
Contact Email:	PRUESCO@SICS.ORG
Contact Title:	Not reported
EPA Region:	02
Land Type:	Other
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R5
Mailing Address:	CANARAS AVE
Mailing City,State,Zip:	SARANAC LAKE, NY 12983
Owner Name:	Saranac Lake Central School
Owner Type:	Other
Operator Name:	Lee Daunais
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No

SARANAC LAKE CSD - PETROVA MIDDLE SCHOOL (Continued) **1004758654**

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018
Waste Description:	Benzene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SARANAC LAKE CENTRAL SCHOOL
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	99 LAPAN HWY
Owner/Operator City,State,Zip:	SARANAC LAKE, NY 12983
Owner/Operator Telephone:	518-891-4221
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

SARANAC LAKE CSD - PETROVA MIDDLE SCHOOL (Continued) **1004758654**

Owner/Operator Indicator: Operator
Owner/Operator Name: SARANAC LAKE CENTRAL SCHOOL
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 99 LAPAN HWY
Owner/Operator City,State,Zip: SARANAC LAKE, NY 12983
Owner/Operator Telephone: 518-891-4221
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: LEE DAUNAIS
Legal Status: Other
Date Became Current: 20070901
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SARANAC LAKE CENTRAL SCHOOL
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 99 LAPAN HWY
Owner/Operator City,State,Zip: SARANAC LAKE, NY 12983
Owner/Operator Telephone: 518-891-4221
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SARANAC LAKE CENTRAL SCHOOL
Legal Status: Other
Date Became Current: 19240101
Date Ended Current: Not reported
Owner/Operator Address: 79 CANARAS AVE
Owner/Operator City,State,Zip: SARANAC LAKE, NY 12983
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: SARANAC LAKE CENTRAL SCHOOL
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

SARANAC LAKE CSD - PETROVA MIDDLE SCHOOL (Continued) **1004758654**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: SARANAC LAKE CENTRAL SCHOOL
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920918
Handler Name: SARANAC LAKE CENTRAL SCHOOL
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090714
Handler Name: SARANAC LAKE CSD - PETROVA MIDDLE SCHOOL
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 61111
NAICS Description: ELEMENTARY AND SECONDARY SCHOOLS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

SARANAC LAKE CSD - PETROVA MIDDLE SCHOOL (Continued) **1004758654**

FINDS:
Registry ID: 110008079079

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004758654
Registry ID:	110008079079
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110008079079
Name:	SARANAC LAKE CSD - PETROVA MIDDLE SCHOOL
Address:	141 PETROVA AVE
City,State,Zip:	SARANAC LAKE, NY 12983

L78 **SARANAC LAKE CENTRAL SCHOOL DIST.** **UST** **U004064297**
West **141 PETROVA AVENUE** **N/A**
1/8-1/4 **SARANAC LAKE, NY 12983**
0.200 mi.
1054 ft. **Site 4 of 4 in cluster L**

Relative:
Higher

Actual:
1566 ft.

UST:

Name:	SARANAC LAKE CENTRAL SCHOOL DIST.
Address:	141 PETROVA AVENUE
City,State,Zip:	SARANAC LAKE, NY 12983
Id/Status:	5-230006 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	5
Expiration Date:	07/10/2027
UTM X:	568899.09787
UTM Y:	4908315.46942
Site Type:	School

Affiliation Records:

Site Id:	39048
Affiliation Type:	Facility Operator
Company Name:	SARANAC LAKE CENTRAL SCHOOL DIST.
Contact Type:	Not reported
Contact Name:	VERNON JAMES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 897-1726
EMail:	Not reported
Fax Number:	Not reported
Modified By:	RBMULVEY

SARANAC LAKE CENTRAL SCHOOL DIST. (Continued) **U004064297**

Date Last Modified: 2017-06-12

Site Id: 39048
Affiliation Type: Emergency Contact
Company Name: SARANAC LAKE CENTRAL SCHOOL DIST.
Contact Type: Not reported
Contact Name: VERNON JAMES
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (518) 637-2653
EMail: Not reported
Fax Number: Not reported
Modified By: RBMULVEY
Date Last Modified: 2017-06-12

Site Id: 39048
Affiliation Type: Mail Contact
Company Name: SARANAC LAKE CENTRAL SCHOOL DIST.
Contact Type: Not reported
Contact Name: VERNON JAMES
Address1: 79 CANARAS AVE
Address2: Not reported
City: SARANAC LAKE
State: NY
Zip Code: 12983
Country Code: 001
Phone: (518) 897-1726
EMail: JAMESVER@SLCS.ORG
Fax Number: Not reported
Modified By: BXHANKIN
Date Last Modified: 2013-09-05

Site Id: 39048
Affiliation Type: Facility Owner
Company Name: SARANAC LAKE CENTRAL SCHOOL DIST.
Contact Type: DIRECTOR OF FACILITIES II
Contact Name: VERNON P JAMES
Address1: 79 CANARAS AVE
Address2: Not reported
City: SARANAC LAKE
State: NY
Zip Code: 12983
Country Code: 001
Phone: (518) 891-5460
EMail: JAMESVER@SLCS.ORG
Fax Number: Not reported
Modified By: KBSWEET
Date Last Modified: 2022-07-21

Tank Info:

Tank Number: 001
Tank ID: 102685

SARANAC LAKE CENTRAL SCHOOL DIST. (Continued) **U004064297**

Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 3000
Install Date: Not reported
Date Tank Closed: 08/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 01
Date Test: 07/01/1987
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 002
Tank ID: 102686
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 12/01/1979
Date Tank Closed: 08/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 08/01/1992
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

SARANAC LAKE CENTRAL SCHOOL DIST. (Continued) **U004064297**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	003
Tank ID:	102684
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	15000
Install Date:	12/01/1969
Date Tank Closed:	08/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	03
Date Test:	08/01/1992
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)

Tank Number:	004
Tank ID:	102687
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	12/01/1969
Date Tank Closed:	08/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	03
Date Test:	08/01/1992
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

F00 - Pipe External Protection - None

SARANAC LAKE CENTRAL SCHOOL DIST. (Continued) **U004064297**

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	006
Tank ID:	110135
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	12000
Install Date:	08/01/1996
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	07/23/2010
Next Test Date:	Not reported
Pipe Model:	D
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG
K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
J05 - Dispenser - On Site Heating System (Supply/Return)
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground

M79 **NORTH COUNTRY HOME SERV.** **LTANKS** **S102676304**
East **37 CHURCH STREET** **N/A**
1/8-1/4 **SARANAC LAKE, NY**
0.209 mi.
1101 ft. **Site 1 of 4 in cluster M**

Relative: **Higher**

Actual: **1540 ft.**

LTANKS:

Name:	NORTH COUNTRY HOME SERV.
Address:	37 CHURCH STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	8710155 / 1988-03-09
Facility ID:	8710155
Site ID:	67978

NORTH COUNTRY HOME SERV. (Continued) **S102676304**

Spill Date:	1988-03-03
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1988-03-09
SWIS:	1700
Investigator:	RLWAGNER
Referred To:	Not reported
Reported to Dept:	1988-03-03
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	Affected Persons
Last Inspection:	1988-03-09
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-03-07
Spill Record Last Update:	1988-09-08
Spiller Name:	Not reported
Spiller Company:	D. M. AGWAY
Spiller Address:	JOHN MUNN ROAD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	64880
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RW 03/09/88: 4TH COAST HIRED BY SPILLER TO DO CLEANUP. "
Remarks:	"FUEL DELIVERY 2/28, FUEL SPILLED ON GROUND AROUND FILL PIPE & RESIDENCE. ODORS IN WORKING & LIVING QUARTERS. D & M WILL CLEAN UP."

All Materials:

Site ID:	67978
Operable Unit ID:	915851
Operable Unit:	01
Material ID:	461936
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	20.00
Resource Affected:	Soil
Oxygenate:	Not reported

I80 **28 BROADWAY** **AST** **U003398487**
NNE **28 BROADWAY** **N/A**
1/8-1/4 **SARANAC LAKE, NY 12983**
0.211 mi.
1115 ft. **Site 5 of 5 in cluster I**

Relative:
Lower

Actual:
1510 ft.

AST:

Name:	28 BROADWAY
Address:	28 BROADWAY
City,State,Zip:	SARANAC LAKE, NY 12983
Region:	STATE
DEC Region:	5
Site Status:	Active
Facility Id:	5-515027
Program Type:	PBS
UTM X:	569252.81040
UTM Y:	4908659.04328
Expiration Date:	11/02/2027
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	40225
Affiliation Type:	Facility Owner
Company Name:	COMMUNITY LOAN SERVICING
Contact Type:	ASSET PRESERVATION COORDINATOR
Contact Name:	PAMELA MAZZA / AGENT FOR OWNER
Address1:	4425 PONCE DE LEON BLVD., 5TH FLOOR
Address2:	Not reported
City:	CORAL GABLES
State:	FL
Zip Code:	33146
Country Code:	001
Phone:	(305) 341-5603
EMail:	Not reported
Fax Number:	Not reported
Modified By:	RXMULVEY
Date Last Modified:	2023-01-10

Site Id:	40225
Affiliation Type:	Facility Operator
Company Name:	28 BROADWAY
Contact Type:	Not reported
Contact Name:	COMMUNITY LOAN SERVICING
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 524-2883
EMail:	Not reported
Fax Number:	Not reported
Modified By:	RXMULVEY
Date Last Modified:	2023-01-10

Site Id:	40225
Affiliation Type:	Mail Contact
Company Name:	MORTGAGE CONTRACTING SERVICES
Contact Type:	Not reported
Contact Name:	CODE COMPLIANCE

28 BROADWAY (Continued) **U003398487**

Address1:	350 HIGHLAND DR., #100
Address2:	Not reported
City:	LEWISVILLE
State:	TX
Zip Code:	75067
Country Code:	001
Phone:	(866) 563-1100
EMail:	PRSREQUEST@MCS360.COM
Fax Number:	Not reported
Modified By:	RXMULVEY
Date Last Modified:	2023-01-10

Site Id:	40225
Affiliation Type:	Emergency Contact
Company Name:	COMMUNITY LOAN SERVICING
Contact Type:	Not reported
Contact Name:	JD PROPERTY SERVICES, LLC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(717) 873-3668
EMail:	Not reported
Fax Number:	Not reported
Modified By:	RXMULVEY
Date Last Modified:	2023-01-10

Tank Info:

Tank Number:	001
Tank Id:	106788
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
D10 - Pipe Type - Copper
I05 - Overfill - Vent Whistle
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J05 - Dispenser - On Site Heating System (Supply/Return)
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
G10 - Tank Secondary Containment - Impervious Underlayment
A00 - Tank Internal Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1991

28 BROADWAY (Continued) **U003398487**

Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	RXMULVEY
Last Modified:	01/10/2023
Material Name:	#2 fuel oil (on-site consumption)

N81 **TRUDEAU INSTITUTE INC** **UST** **U001846563**
NNE **18-22 WOODRUFF ST** **N/A**
1/8-1/4 **SARANAC LAKE, NY 12983**
0.212 mi.
1119 ft. **Site 1 of 5 in cluster N**

Relative:
Higher

Actual:
1529 ft.

UST:

Name:	TRUDEAU INSTITUTE INC
Address:	18-22 WOODRUFF ST
City,State,Zip:	SARANAC LAKE, NY 12983
Id/Status:	5-393983 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	5
Expiration Date:	N/A
UTM X:	569314.72386
UTM Y:	4908681.65660
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	39426
Affiliation Type:	Mail Contact
Company Name:	TRUDEAU INSTITUTE INC
Contact Type:	Not reported
Contact Name:	JON LAW
Address1:	154 ALGONQUIN AVE
Address2:	Not reported
City:	SARANAC LAKE
State:	NY
Zip Code:	12983
Country Code:	001
Phone:	(518) 891-3080
EMail:	JLAW@TRUDEAUINSTITUTE.ORG
Fax Number:	Not reported
Modified By:	rbmulvey
Date Last Modified:	2013-09-09

Site Id:	39426
Affiliation Type:	Facility Operator
Company Name:	TRUDEAU INSTITUTE INC
Contact Type:	Not reported
Contact Name:	TRUDEAU INSTITUTE INC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001

TRUDEAU INSTITUTE INC (Continued) **U001846563**

Phone:	(518) 891-3080
EMail:	Not reported
Fax Number:	Not reported
Modified By:	RLREYELL
Date Last Modified:	2007-07-18

Site Id:	39426
Affiliation Type:	Emergency Contact
Company Name:	TRUDEAU INSTITUTE INC
Contact Type:	Not reported
Contact Name:	BRIAN WATERS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(518) 524-3081
EMail:	Not reported
Fax Number:	Not reported
Modified By:	RBMULVEY
Date Last Modified:	2007-07-23

Site Id:	39426
Affiliation Type:	Facility Owner
Company Name:	TRUDEAU INSTITUTE INC
Contact Type:	MECH., ELECT., PLUMBING SUPERVISOR
Contact Name:	JON LAW
Address1:	154 ALGONQUIN AVE.
Address2:	Not reported
City:	SARANAC LAKE
State:	NY
Zip Code:	12983
Country Code:	001
Phone:	(518) 891-3080
EMail:	Not reported
Fax Number:	Not reported
Modified By:	rbmulvey
Date Last Modified:	2013-09-09

Tank Info:

Tank Number:	001
Tank ID:	103923
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	3000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported

TRUDEAU INSTITUTE INC (Continued) **U001846563**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 002
Tank ID: 103924
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 07/01/1987
Date Tank Closed: 09/09/2013
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
I04 - Overfill - Product Level Gauge (A/G)
D10 - Pipe Type - Copper
F00 - Pipe External Protection - None
B02 - Tank External Protection - Original Sacrificial Anode
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

O82 **DECHANTAL APARTMENTS INC** **UST** **U001846583**
ENE **60 CHURCH ST** **N/A**
1/8-1/4 **SARANAC LAKE, NY 12983**
0.213 mi.
1125 ft. **Site 1 of 2 in cluster O**

Relative:
Higher

Actual:
1565 ft.

UST:

Name:	DECHANTAL APARTMENTS INC
Address:	60 CHURCH ST
City,State,Zip:	SARANAC LAKE, NY 12983
Id/Status:	5-392456 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	5
Expiration Date:	07/10/2022
UTM X:	569531.78441
UTM Y:	4908488.55625
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	39412
Affiliation Type:	Facility Operator
Company Name:	DECHANTAL APARTMENTS INC
Contact Type:	Not reported
Contact Name:	S CURTIS HAYES INC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 891-4004
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BXHANKIN
Date Last Modified:	2010-12-03

Site Id:	39412
Affiliation Type:	Mail Contact
Company Name:	DECHANTAL APARTMENTS INC
Contact Type:	MANAGING AGENT
Contact Name:	WAYNE FEINBERG
Address1:	60 CHURCH STREET
Address2:	Not reported
City:	SARANAC LAKE
State:	NY
Zip Code:	12983
Country Code:	001
Phone:	(518) 891-2020
EMail:	TOPBROKER@ROADRUNNER.COM
Fax Number:	Not reported
Modified By:	BXHANKIN
Date Last Modified:	2019-01-10

Site Id:	39412
Affiliation Type:	Emergency Contact
Company Name:	DECHANTAL APARTMENTS INC
Contact Type:	Not reported
Contact Name:	WAYNE FEINBERG
Address1:	Not reported

DECHANTAL APARTMENTS INC (Continued) **U001846583**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(518) 891-2020
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BXHANKIN
Date Last Modified:	2013-10-31

Site Id:	39412
Affiliation Type:	Facility Owner
Company Name:	DECHANTAL APARTMENTS INC
Contact Type:	MANAGING AGENT
Contact Name:	WAYNE FEINBERG
Address1:	60 CHURCH STREET
Address2:	Not reported
City:	SARANAC LAKE
State:	NY
Zip Code:	12983
Country Code:	001
Phone:	(518) 891-4004
EMail:	TOPBROKER@ROADRUNNER.COM
Fax Number:	Not reported
Modified By:	BXHANKIN
Date Last Modified:	2013-10-31

Tank Info:

Tank Number:	001
Tank ID:	104076
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	15000
Install Date:	09/01/1971
Date Tank Closed:	08/01/2002
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	03
Date Test:	11/01/1996
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

DECHANTAL APARTMENTS INC (Continued) **U001846583**

G00 - Tank Secondary Containment - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None

Tank Number:	002
Tank ID:	112185
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	10000
Install Date:	09/17/2002
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	04/11/2013
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
F05 - Pipe External Protection - Jacketed
D10 - Pipe Type - Copper
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
E04 - Piping Secondary Containment - Double walled UG
B02 - Tank External Protection - Original Sacrificial Anode
K01 - Spill Prevention - Catch Basin
J05 - Dispenser - On Site Heating System (Supply/Return)
C02 - Pipe Location - Underground/On-ground
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
L02 - Piping Leak Detection - Interstitial - Manual Monitoring

---

O83 **VERIZON NEW YORK INC-NY-83215** **TANKS** **S116349495**
ENE **48 CHURCH STREET** **N/A**
1/8-1/4 **SARANAC LAKE, NY 12983**
0.216 mi.
1139 ft. **Site 2 of 2 in cluster O**

Relative: **Higher**
Actual: **1558 ft.**

TANKS:

Name:	VERIZON NEW YORK INC-NY-83215
Address:	48 CHURCH STREET
City,State,Zip:	SARANAC LAKE, NY 12983
Facility Id:	5-416371
Region:	STATE
DEC Region:	5
Site Status:	Active
Program Type:	PBS
Expiration Date:	06/30/2027
UTM X:	569559.84638
UTM Y:	4908462.72440

N84 **TRUDEAU INSTITUTE** **LTANKS** **S100346765**
NNE **15 WOODRUFF STREET** **N/A**
1/8-1/4 **SARANAC LAKE, NY**
0.218 mi.
1152 ft. **Site 2 of 5 in cluster N**

Relative: **Lower**

Actual: **1515 ft.**

LTANKS:

Name:	TRUDEAU INSTITUTE
Address:	15 WOODRUFF STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	8702601 / 1987-07-27
Facility ID:	8702601
Site ID:	148841
Spill Date:	1987-06-30
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	1987-07-27
SWIS:	1746
Investigator:	RLWAGNER
Referred To:	Not reported
Reported to Dept:	1987-07-01
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	Tank Tester
Last Inspection:	1987-07-27
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-07-01
Spill Record Last Update:	2013-07-05
Spiller Name:	Not reported
Spiller Company:	TRUDEAU INSTITUTE
Spiller Address:	15 WOODRUFF STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	126650
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RW "
Remarks:	"TANK PUMPED OUT - WILL REPLACE (TANK # 3, 3,000 GALLON) TANK PULLED 7/27/87. R. WAGNER @ SITE - NO CLEANUP NEEDED. NEW DOUBLE WALL INSTALLED."

All TTF:

Facility ID:	8702601
Spill Number:	8702601
Spill Tank Test:	1531041
Site ID:	148841
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00

TRUDEAU INSTITUTE (Continued) **S100346765**

Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 148841
Operable Unit ID: 909107
Operable Unit: 01
Material ID: 559656
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 3000.00
Units: G
Recovered: .00
Resource Affected: Groundwater
Oxygenate: Not reported

K85 **KEY BANK OF NEW YORK** **UST** **U001847114**
North **55 BROADWAY STREET** **N/A**
1/8-1/4 **SARANAC LAKE, NY 12983**
0.220 mi.
1164 ft. **Site 2 of 2 in cluster K**

Relative:
Lower

Actual:
1519 ft.

UST:
Name: KEY BANK OF NEW YORK
Address: 55 BROADWAY STREET
City,State,Zip: SARANAC LAKE, NY 12983
Id/Status: 5-600238 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 5
Expiration Date: N/A
UTM X: 569173.79831
UTM Y: 4908714.78231
Site Type: Other

Affiliation Records:
Site Id: 40468
Affiliation Type: Facility Operator
Company Name: KEY BANK OF NEW YORK
Contact Type: Not reported
Contact Name: MS. SUSAN M. GOETZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (518) 891-2900
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

KEY BANK OF NEW YORK (Continued) **U001847114**

Site Id:	40468
Affiliation Type:	Emergency Contact
Company Name:	KEY BANK OF NEW YORK
Contact Type:	Not reported
Contact Name:	MS. SUSAN M. GOETZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 891-2900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	40468
Affiliation Type:	Facility Owner
Company Name:	KEY BANK OF NEW YORK
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	201 SOUTH WARREN STREET
Address2:	Not reported
City:	SYRACUSE
State:	NY
Zip Code:	13202
Country Code:	001
Phone:	(315) 470-5151
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	40468
Affiliation Type:	Mail Contact
Company Name:	KEY BANK OF NEW YORK
Contact Type:	Not reported
Contact Name:	MR. AL MONROE
Address1:	201 SOUTH WARREN STREET
Address2:	Not reported
City:	SYRACUSE
State:	NY
Zip Code:	13202
Country Code:	001
Phone:	(315) 470-5151
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	109063
Tank Status:	Closed - In Place
Material Name:	Closed - In Place

KEY BANK OF NEW YORK (Continued) **U001847114**

Capacity Gallons:	8000
Install Date:	Not reported
Date Tank Closed:	09/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D10 - Pipe Type - Copper
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

N86 **DR. BALKIEWICZ** **LTANKS** **S102660299**
NNE **WOODRUFF STREET** **N/A**
1/8-1/4 **SARANAC LAKE, NY**
0.223 mi.
1177 ft. **Site 3 of 5 in cluster N**

Relative: LTANKS:
Lower

Actual:
1509 ft.

Name:	DR. BALKIEWICZ
Address:	WOODRUFF STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9708228 / 1997-10-15
Facility ID:	9708228
Site ID:	316552
Spill Date:	1997-10-14
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	1700
Investigator:	LJMILLIO
Referred To:	Not reported
Reported to Dept:	1997-10-14
CID:	999
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-10-14

DR. BALKIEWICZ (Continued) **S102660299**

Spill Record Last Update:	1997-10-15
Spiller Name:	Not reported
Spiller Company:	DR. BALKIEWICZ
Spiller Address:	WOODRUFF STREET
Spiller County:	001
Spiller Contact:	JAN BALDIEWICZ
Spiller Phone:	(518) 891-2276
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	255225
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was LM RFC: No contamination evident. "
Remarks:	"REMOVING 1000 GALLON TANK AT BUSINESS."

All Materials:

Site ID:	316552
Operable Unit ID:	1051454
Operable Unit:	01
Material ID:	330211
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

M87 **NYNEX** **NY Spills** **1000983619**
ENE **26 CHURCH ST** **RCRA NonGen / NLR** **NYD981129729**
1/8-1/4 **SARANAC LAKE, NY 12983** **FINDS**
0.228 mi. **ECHO**
1203 ft. **Site 2 of 4 in cluster M** **MANIFEST**

Relative:
Higher

Actual:
1545 ft.

SPILLS:

Name:	NYNEX
Address:	26 CHURCH ST
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9613169 / 1997-08-20
Facility ID:	9613169
Facility Type:	ER
DER Facility ID:	152559
Site ID:	181949
DEC Region:	5
Spill Cause:	Other
Spill Class:	C4
SWIS:	1600
Spill Date:	1996-09-24
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1997-02-06
CID:	366
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported

NYNEX (Continued) **1000983619**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-02-06
Spill Record Last Update:	1997-08-21
Spiller Name:	Not reported
Spiller Company:	NYNEX
Spiller Address:	26 CHRUCH STREET
Spiller Company:	001
Contact Name:	TOM O'BRIEN
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM 02/06/97: Tanks were closed in place. Sterns and Wheeler. To obtain more information, provide report. 07/31/97: S&W Services, Inc. - tank closure report received, minor soil contamination, no environmental impact, no further action necessary. RFC: Minor loss, no environmental impact. "
Remarks:	"FOUND CONTAMINATION WHILE ABANDONING TANKS. "

All Materials:

Site ID:	181949
Operable Unit ID:	1040783
Operable Unit:	01
Material ID:	341814
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Nynex
Handler Address:	26 CHURCH ST
Handler City,State,Zip:	SARANAC LAKE, NY 12983-1815
EPA ID:	NYD981129729
Contact Name:	Not reported
Contact Address:	E 37TH ST
Contact City,State,Zip:	NEW YORK, NY 10016
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported

NYNEX (Continued) **1000983619**

State District Owner:	Ny
State District:	NYSDEC R5
Mailing Address:	E 37TH ST
Mailing City,State,Zip:	NEW YORK, NY 10016
Owner Name:	Nynex
Owner Type:	Private
Operator Name:	Nynex
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	NONE
Waste Description:	Not Defined
Waste Code:	X002
Waste Description:	Not Defined

NYNEX (Continued) **1000983619**

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: NYNEX	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	26 CHURCH ST
Owner/Operator City,State,Zip:	SARANAC LAKE, NY 12983
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: NYNEX	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	26 CHURCH ST
Owner/Operator City,State,Zip:	SARANAC LAKE, NY 12983
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: NYNEX	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	26 CHURCH ST
Owner/Operator City,State,Zip:	SARANAC LAKE, NY 12983
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: NYNEX	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: NYNEX	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No

NYNEX (Continued) **1000983619**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYNEX
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19950117
Handler Name: NYNEX
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004398161

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NYNEX (Continued) **1000983619**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000983619
Registry ID:	110004398161
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004398161
Name:	NYNEX
Address:	26 CHURCH ST
City,State,Zip:	SARANAC LAKE, NY 12983

NY MANIFEST:

Name:	NEW YORK TELEPHONE CO
Address:	26 CHURCH ST
City,State,Zip:	SARANAC LAKE, NY 12983-1815
Country:	USA
EPA ID:	NYD981129729
Facility Status:	Not reported
Location Address 1:	76-15 JAMAICA AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WOODHAVEN
Location State:	NY
Location Zip:	11421
Location Zip 4:	1851

NY MANIFEST:

EPAID:	NYD981129729
Mailing Name:	NEW YORK TELEPHONE CO
Mailing Contact:	NEW YORK TELEPHONE CO
Mailing Address 1:	26 CHURCH ST
Mailing Address 2:	Not reported
Mailing City:	SARANAC LAKE
Mailing State:	NY
Mailing Zip:	12983
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183308387

N88 **BURNS NEWS AGENCY INC** **LTANKS** **U001846363**
NNE **28 WOODRUFF ST** **UST** **N/A**
1/8-1/4 **SARANAC LAKE, NY 12983** **NY Spills**
0.230 mi.
1217 ft. **Site 4 of 5 in cluster N**

Relative:
Higher

Actual:
1528 ft.

LTANKS:

Name:	BURNS NEWS AGENCY
Address:	28 WOODRUFF STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	8702320 / 1992-10-01
Facility ID:	8702320
Site ID:	219812
Spill Date:	1987-06-22
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial

BURNS NEWS AGENCY INC (Continued) **U001846363**

Spill Class:	B2
Cleanup Ceased:	1992-10-01
SWIS:	1700
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1987-06-22
CID:	Not reported
Water Affected:	SARANAC RIVER
Spill Notifier:	Other
Last Inspection:	1989-10-01
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1980-01-01
Spill Record Last Update:	1998-10-02
Spiller Name:	Not reported
Spiller Company:	BURNS NEWS AGENCY, INC.
Spiller Address:	28 WOODRUFF STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	181798
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM RFC: Material no longer leaching into river. No further action needed. "
Remarks:	"OIL FROM CULVERT ADJACENT TO BURNS NEWS AGENCY; FOURTH COAST TO INSTALL SORBENT. RECOVERY WELL INTALLED SUMMER OF 1987. PRODUCT STILL IN WELL AS OF 5/1/89."

All Materials:

Site ID:	219812
Operable Unit ID:	908829
Operable Unit:	01
Material ID:	568106
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

Name:	BURNS NEWS AGENCY
Address:	28 WOODRUFF ST.
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	8603923 / 1986-11-01
Facility ID:	8603923
Site ID:	59704
Spill Date:	1986-09-16
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	A1

BURNS NEWS AGENCY INC (Continued) **U001846363**

Cleanup Ceased:	1986-11-01
SWIS:	1746
Investigator:	AWSTEMP
Referred To:	Not reported
Reported to Dept:	1986-09-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1986-09-16
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1986-09-22
Spill Record Last Update:	2016-06-21
Spiller Name:	Not reported
Spiller Company:	BURNS NEWS AGENCY
Spiller Address:	28 WOODRUFF ST.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	483377
DEC Memo:	"TANK ISOLATED, FAILED. SCHEDULED FOR REMOVAL AND SOIL EXCAVATION."
Remarks:	"TANK TEST FAILURE BY M.J.BRUSONE 899-2007, 0.1195 GPH."

All TTF:

Facility ID:	8603923
Spill Number:	8603923
Spill Tank Test:	1530225
Site ID:	59704
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	59704
Operable Unit ID:	900851
Operable Unit:	01
Material ID:	476735
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G

BURNS NEWS AGENCY INC (Continued) **U001846363**

Recovered: .00
Resource Affected: Surface Water
Oxygenate: Not reported

UST:
Name: BURNS NEWS AGENCY INC
Address: 28 WOODRUFF ST
City,State,Zip: SARANAC LAKE, NY 12983
Id/Status: 5-229113 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 5
Expiration Date: N/A
UTM X: 569387.54019
UTM Y: 4908713.58091
Site Type: Trucking/Transportation/Fleet Operation

Affiliation Records:
Site Id: 38974
Affiliation Type: Facility Owner
Company Name: BURNS NEWS AGENCY INC
Contact Type: Not reported
Contact Name: Not reported
Address1: 84 GLEN ST
Address2: Not reported
City: GLENS FALLS
State: NY
Zip Code: 12801
Country Code: 001
Phone: (518) 792-5138
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 38974
Affiliation Type: Mail Contact
Company Name: BURNS NEWS AGENCY INC
Contact Type: Not reported
Contact Name: Not reported
Address1: 84 GLEN ST
Address2: Not reported
City: GLENS FALLS
State: NY
Zip Code: 12801
Country Code: 001
Phone: (518) 792-5138
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 38974
Affiliation Type: Facility Operator
Company Name: BURNS NEWS AGENCY INC
Contact Type: Not reported

BURNS NEWS AGENCY INC (Continued) **U001846363**

Contact Name:	CARLTON A KING
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 891-0610
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	38974
Affiliation Type:	Emergency Contact
Company Name:	BURNS NEWS AGENCY INC
Contact Type:	Not reported
Contact Name:	CARLTON A KING
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 891-0610
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	102503
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	06/01/1985
Date Tank Closed:	11/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	01
Date Test:	09/01/1992
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B02 - Tank External Protection - Original Sacrificial Anode
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None

BURNS NEWS AGENCY INC (Continued) **U001846363**

I00 - Overfill - None
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
A99 - Tank Internal Protection - Other

Tank Number:	002
Tank ID:	102504
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	10/01/1986
Date Tank Closed:	11/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	01
Date Test:	10/01/1992
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B02 - Tank External Protection - Original Sacrificial Anode
A99 - Tank Internal Protection - Other
K01 - Spill Prevention - Catch Basin
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	003
Tank ID:	102505
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	500
Install Date:	10/01/1986
Date Tank Closed:	11/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	01
Date Test:	09/01/1992

BURNS NEWS AGENCY INC (Continued) **U001846363**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A99 - Tank Internal Protection - Other
B01 - Tank External Protection - Painted/Asphalt Coating
B02 - Tank External Protection - Original Sacrificial Anode
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

SPILLS:

Name: BURNS NEWS
Address: 28 WOODRUFF ST.
City,State,Zip: SARANAC LAKE, NY
Spill Number/Closed Date: 9207362 / 1992-12-21
Facility ID: 9207362
Facility Type: ER
DER Facility ID: 483377
Site ID: 59705
DEC Region: 5
Spill Cause: Equipment Failure
Spill Class: B3
SWIS: 1746
Spill Date: 1992-09-24
Investigator: MPMCLEAN
Referred To: Not reported
Reported to Dept: 1992-09-24
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Tank Tester
Cleanup Ceased: 1992-12-21
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1992-09-25
Spill Record Last Update: 2016-06-21
Spiller Name: Not reported
Spiller Company: BURNS NEWS
Spiller Address: 28 WOODRUFF STREET
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "12/21/92: Tank test results received, tank and piping retested tight.
RFC: Line repaired, retest
tight, no further action."
Remarks: "2K FUEL OIL TANK FAILED TANK TEST @ -.19GPH. CONTACTED BURNS NEWS, N.A. UNTIL 9/28, CONTACTED VALLEY EQUIPMENT, ARE PLANNING ON

BURNS NEWS AGENCY INC (Continued) **U001846363**

RETESTING TANK IN IMMEDIATE FUTURE."

All Materials:

Site ID:	59705
Operable Unit ID:	971002
Operable Unit:	01
Material ID:	408002
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

Name:	BURNS NEWS AGENCY INC.
Address:	28 WOODRUFF STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9845042 / 2003-08-19
Facility ID:	9845042
Facility Type:	ER
DER Facility ID:	483378
Site ID:	219813
DEC Region:	5
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1746
Spill Date:	1998-11-01
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1998-11-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-11-19
Spill Record Last Update:	2016-06-21
Spiller Name:	Not reported
Spiller Company:	BURNS NEWS AGENCY
Spiller Address:	28 WOODRUFF STREET
Spiller Company:	001
Contact Name:	CARLTON KING
DEC Memo:	"08/21/00: MM met with Pat Stratton, Stratton Plumbing and Heating. Pile of excavated, stockpiled contaminated soil checked, no PID readings, ok given to dispose of material. Stratton interested in purchasing property, provided copy of tank closure report. 08/19/03: LM checked location. Contaminated soil pile removed. Subsurface gasoline contamination

BURNS NEWS AGENCY INC (Continued) **U001846363**

remains at site but poses no
apparent environmental impact. RFC: No environmental impact noted from excavated contaminated soil,
soil disposed of."

Remarks: "Removal of UST's at site found contaminated soil from leak reported in 1987. Existing USTs being removed in excellent shape. Contaminated soil old, not impacting river, excavation of soil besides in immediate tank removal area recommended."

All Materials:

Site ID:	219813
Operable Unit ID:	1077047
Operable Unit:	01
Material ID:	309172
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

N89 NNE 1/8-1/4 0.230 mi. 1217 ft. **RIVERSIDE PROPERTIES** **UST** **U003128650**
28-30 WOODRUFF STREET **N/A**
SARANAC LAKE, NY 12983

Site 5 of 5 in cluster N

Relative: Higher

Actual: 1528 ft.

UST:

Name:	RIVERSIDE PROPERTIES
Address:	28-30 WOODRUFF STREET
City,State,Zip:	SARANAC LAKE, NY 12983
Id/Status:	5-600020 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	5
Expiration Date:	N/A
UTM X:	569387.54019
UTM Y:	4908713.58091
Site Type:	Other

Affiliation Records:

Site Id:	40254
Affiliation Type:	Facility Owner
Company Name:	WM. KINVILLE/PHIL LALANDE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	42-44 WOODRUFF STREET
Address2:	Not reported
City:	SARANAC LAKE
State:	NY
Zip Code:	12983
Country Code:	001
Phone:	(518) 891-0997
EMail:	Not reported
Fax Number:	Not reported

RIVERSIDE PROPERTIES (Continued) **U003128650**

Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 40254
Affiliation Type: Mail Contact
Company Name: WM. KINVILLE/PHIL LALANDE
Contact Type: Not reported
Contact Name: WM. KINVILLE/PHIL LALANDE
Address1: 42-44 WOODRUFF STREET
Address2: Not reported
City: SARANAC LAKE
State: NY
Zip Code: 12983
Country Code: 001
Phone: (518) 891-0997
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 40254
Affiliation Type: Facility Operator
Company Name: RIVERSIDE PROPERTIES
Contact Type: Not reported
Contact Name: WM. KINVILLE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (518) 891-0997
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 40254
Affiliation Type: Emergency Contact
Company Name: WM. KINVILLE/PHIL LALANDE
Contact Type: Not reported
Contact Name: PHIL LALANDE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (518) 891-0997
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001

RIVERSIDE PROPERTIES (Continued) **U003128650**

Tank ID:	107457
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	08/01/1991
Date Tank Closed:	08/01/1991
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

D10 - Pipe Type - Copper
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Number:	002
Tank ID:	107458
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	08/01/1991
Date Tank Closed:	08/01/1991
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

RIVERSIDE PROPERTIES (Continued) **U003128650**

F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

M90 **DECHANTAL APARTMENTS** **LTANKS** **S118953738**
East **20 CHURCH STREET** **N/A**
1/8-1/4 **SARANAC LAKE, NY**
0.235 mi.
1243 ft. **Site 3 of 4 in cluster M**

Relative:
Higher

Actual:
1546 ft.

LTANKS:

Name:	DECHANTAL APARTMENTS
Address:	20 CHURCH STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9110179 / 1992-02-04
Facility ID:	9110179
Site ID:	174072
Spill Date:	1991-12-27
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1992-02-04
SWIS:	1700
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1991-12-27
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-12-27
Spill Record Last Update:	1992-02-04
Spiller Name:	C: PHIL FEINBURG
Spiller Company:	S. CURTIS HAYES
Spiller Address:	25 BROADWAY STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	146425
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM "
Remarks:	"15K TANK FAILED PETROTITE @ GROSS LEAK, TEST ABORTED, EIR TO BE SCHEDULED. TANK RETESTED ON 1/7/92 AND PASSED."

All TTF:

Facility ID:	9110179
Spill Number:	9110179
Spill Tank Test:	1539472
Site ID:	174072
Tank Number:	Not reported
Tank Size:	0
Material:	0001

DECHANTAL APARTMENTS (Continued) **S118953738**

EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 174072
Operable Unit ID: 963791
Operable Unit: 01
Material ID: 418741
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

M91 **DECHANTAL APTS. INC.** **LTANKS** **S118953472**
East **20 CHURCH STREET** **N/A**
1/8-1/4 **SARANAC LAKE, NY**
0.235 mi.
1243 ft. **Site 4 of 4 in cluster M**

Relative: **Higher**
Actual: **1546 ft.**

LTANKS:
Name: DECHANTAL APTS. INC.
Address: 20 CHURCH STREET
City,State,Zip: SARANAC LAKE, NY
Spill Number/Closed Date: 0245039 / 2003-04-09
Facility ID: 0245039
Site ID: 174071
Spill Date: 2002-06-11
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 1700
Investigator: RBMULVEY
Referred To: Not reported
Reported to Dept: 2002-06-11
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0

DECHANTAL APTS. INC. (Continued) **S118953472**

Date Entered In Computer:	2002-06-12
Spill Record Last Update:	2003-04-09
Spiller Name:	Not reported
Spiller Company:	DECHANTAL APARTMENTS, INC
Spiller Address:	20 CHURCH ST.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	146425
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RM 04/09/03: Russ Mulvey closed this psill out. The tank in question was closed in place and a site assessment done. No further work is necessary."
Remarks:	"Failed tant test. Probably pump tank out."

All TTF:

Facility ID:	0245039
Spill Number:	0245039
Spill Tank Test:	1528199
Site ID:	174071
Tank Number:	01
Tank Size:	15000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	174071
Operable Unit ID:	866880
Operable Unit:	01
Material ID:	509843
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

P92 **ADIRONDACK DAILY ENTERPRISE** **RCRA NonGen / NLR** **1008374387**
North **61 BROADWAY** **NYN008014193**
1/8-1/4 **SARANAC LAKE, NY 12983**
0.245 mi.
1294 ft. **Site 1 of 2 in cluster P**

Relative: **Higher**

Actual: **1545 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Adirondack Daily Enterprise
Handler Address:	61 BROADWAY
Handler City,State,Zip:	SARANAC LAKE, NY 12983
EPA ID:	NYN008014193
Contact Name:	DON HARE
Contact Address:	BROADWAY
Contact City,State,Zip:	SARANAC LAKE, NY 12983
Contact Telephone:	518-891-2600
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R5
Mailing Address:	BROADWAY
Mailing City,State,Zip:	SARANAC LAKE, NY 12983
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

ADIRONDACK DAILY ENTERPRISE (Continued) **1008374387**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20050512
Handler Name:	ADIRONDACK DAILY ENTERPRISE
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name:	ADIRONDACK DAILY ENTERPRISE
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	ADIRONDACK DAILY ENTERPRISE
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

ADIRONDACK DAILY ENTERPRISE (Continued) **1008374387**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20041209
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYKWD
Evaluation Responsible Sub-Organization: R5
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Q93 **NORTH STAR INDUSTRIES** **LTANKS** **S118953821**
West **71 PETROVA AVENUE** **N/A**
1/4-1/2 **SARANAC LAKE, NY**
0.250 mi.
1321 ft. **Site 1 of 2 in cluster Q**

Relative:
Higher

Actual:
1567 ft.

LTANKS:

Name:	NORTH STAR INDUSTRIES
Address:	71 PETROVA AVENUE
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9608722 / 1996-10-16
Facility ID:	9608722
Site ID:	274677
Spill Date:	1996-10-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	1700
Investigator:	LJMILLIO
Referred To:	Not reported
Reported to Dept:	1996-10-14
CID:	266
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-10-14
Spill Record Last Update:	1996-10-17
Spiller Name:	BUCK WILLETTE
Spiller Company:	NORTH STAR INDUSTRIES
Spiller Address:	71 PETROVA AVENUE
Spiller County:	001
Spiller Contact:	BUCK WILLETTE
Spiller Phone:	(518) 891-2590
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	223412
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was LM 10/14/96: LM spoke with North Star Industries. Will retest 10/16/96 and call with results. RFC: Passed retest 10/16/96. "
Remarks:	"CALLER IS CERTAIN THAT IT'S A BAD GUAGE LINE (GUAGE DOESN'T WORK). TANK BEING EXCAVATED. TO BE RETESTED ON 10/16/96."

All TTF:

Facility ID:	9608722
Spill Number:	9608722
Spill Tank Test:	1544811
Site ID:	274677
Tank Number:	3
Tank Size:	4000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03

NORTH STAR INDUSTRIES (Continued) **S118953821**

Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	274677
Operable Unit ID:	1036925
Operable Unit:	01
Material ID:	344450
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

94
NNW
1/4-1/2
0.251 mi.
1327 ft.

29 WILLIAMS STREET **LTANKS** **S104951038**
29 WILLIAMS ST **N/A**
SARANAC LAKE, NY

Relative:
Higher

Actual:
1627 ft.

LTANKS:

Name:	29 WILLIAMS STREET
Address:	29 WILLIAMS ST
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	0012844 / 2001-03-06
Facility ID:	0012844
Site ID:	145443
Spill Date:	2001-03-05
Spill Cause:	Tank Overfill
Spill Source:	Commercial Vehicle
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	1700
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	2001-03-05
CID:	322
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-03-05
Spill Record Last Update:	2001-03-08
Spiller Name:	BILL DECKER
Spiller Company:	BIG D FUEL
Spiller Address:	200 BROADWAY

29 WILLIAMS STREET (Continued) **S104951038**

Spiller County:	001
Spiller Contact:	JANET SWENTUSKY
Spiller Phone:	(518) 891-0277
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	123939
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM RFC: Minor spill, RP performed adequate cleanup."
Remarks:	"DRIVER OVERFILLED TANK - SPILL HAS BEEN CLEANED UP "

All Materials:

Site ID:	145443
Operable Unit ID:	834781
Operable Unit:	01
Material ID:	539569
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Resource Affected:	Soil
Oxygenate:	Not reported

P95 **BROADWAY PROPERTIES** **LTANKS U003070072**
North **60-62 BROADWAY** **UST N/A**
1/4-1/2 **SARANAC LAKE, NY 12983** **NY Spills**
0.251 mi.
1327 ft. **Site 2 of 2 in cluster P**

Relative: LTANKS:
Higher

Actual: Name:	OXFORD MARKET
1549 ft. Address:	73 BROADWAY STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9007621 / 1990-12-04
Facility ID:	9007621
Site ID:	235125
Spill Date:	1990-10-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1990-12-04
SWIS:	1700
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1990-10-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1990-11-15
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-10-18
Spill Record Last Update:	1990-12-04

BROADWAY PROPERTIES (Continued) **U003070072**

Spiller Name: C: RUTH EPGENBACH
Spiller Company: OXFORD MARKET
Spiller Address: 73 BROADWAY STREET
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 5
DER Facility ID: 193660
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM 11/08/90: MM/AS ON SITE, PADS PLACED IN HOLE TO REMOVE, PRODUCT, HIGH GW LEVELS, RECOVERY WELL INSTALLED TO CATCH ANY RESIDUAL. NEGLIGIBLE AMOUNTS CONT. SOIL. 11/15/90: MM ON SITE, HOLE DUG DEEPER TO INSTALL NEW 6K TANK, GW IN HOLE FREE OF PRODUCT, GAVE PERMISSION TO REMOVE RECOVERY WELL. NO FURTHER ACTION NEEDED. "
Remarks: "8000G TANK FAILED PETRO-TITE , RESULTS INCONCLUSIVE. SUSPECT LEAK IN PIPING, WILL EXCAVATE AND RETEST NEXT WEEK. RETEST FAILED. 11/8-TANK REMOVED, ENCOUNTERED 1K ABANDONED, LEAKING INTO HOLE."

All TTF:
Facility ID: 9007621
Spill Number: 9007621
Spill Tank Test: 1537694
Site ID: 235125
Tank Number: Not reported
Tank Size: 0
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 235125
Operable Unit ID: 944958
Operable Unit: 01
Material ID: 431467
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Resource Affected: Groundwater
Oxygenate: Not reported

UST:
Name: BROADWAY PROPERTIES
Address: 60-62 BROADWAY

BROADWAY PROPERTIES (Continued) **U003070072**

City,State,Zip: SARANAC LAKE, NY 12983
Id/Status: 5-506273 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 5
Expiration Date: N/A
UTM X: 569143.09071
UTM Y: 4908777.87343
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 40192
Affiliation Type: Facility Owner
Company Name: EARL & VICTORIA HITCHCOCK
Contact Type: OWNER
Contact Name: EARL S. HITCHCOCK
Address1: 6 MOWRY AVE
Address2: Not reported
City: GREENWICH
State: NY
Zip Code: 12834
Country Code: 001
Phone: (518) 692-7721
EMail: Not reported
Fax Number: Not reported
Modified By: rbmulvey
Date Last Modified: 2009-01-14

Site Id: 40192
Affiliation Type: Mail Contact
Company Name: BROADWAY PROPERTIES
Contact Type: Not reported
Contact Name: EARL S. HITCHCOCK JR
Address1: 6 MOWRY AVE
Address2: Not reported
City: GREENWICH
State: NY
Zip Code: 12834
Country Code: 001
Phone: (518) 692-7721
EMail: Not reported
Fax Number: Not reported
Modified By: BXHANKIN
Date Last Modified: 2011-10-26

Site Id: 40192
Affiliation Type: Facility Operator
Company Name: BROADWAY PROPERTIES
Contact Type: Not reported
Contact Name: EARL S. HITCHCOCK JR
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (518) 891-2816
EMail: Not reported

BROADWAY PROPERTIES (Continued) **U003070072**

Fax Number:	Not reported
Modified By:	BXHANKIN
Date Last Modified:	2011-10-26
Site Id:	40192
Affiliation Type:	Emergency Contact
Company Name:	EARL & VICTORIA HITCHCOCK
Contact Type:	Not reported
Contact Name:	BIG D FUEL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(518) 891-1900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	106696
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	8000
Install Date:	Not reported
Date Tank Closed:	11/01/1990
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	002
Tank ID:	112622

BROADWAY PROPERTIES (Continued) **U003070072**

Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	8000
Install Date:	11/01/1990
Date Tank Closed:	12/15/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	10/23/2013
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
D10 - Pipe Type - Copper
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
B02 - Tank External Protection - Original Sacrificial Anode
F00 - Pipe External Protection - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
I00 - Overfill - None
K01 - Spill Prevention - Catch Basin
G04 - Tank Secondary Containment - Double-Walled (Underground)

SPILLS:

Name:	BUSINESS
Address:	73 BROADWAY
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	0704009 / 2007-07-16
Facility ID:	0704009
Facility Type:	ER
DER Facility ID:	333498
Site ID:	384082
DEC Region:	5
Spill Cause:	Other
Spill Class:	C3
SWIS:	1746
Spill Date:	2007-07-10
Investigator:	gjhandly
Referred To:	Not reported
Reported to Dept:	2007-07-10
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported

BROADWAY PROPERTIES (Continued) **U003070072**

Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-07-10
Spill Record Last Update:	2007-07-16
Spiller Name:	EARL HITCHCOCK
Spiller Company:	BUSINESS
Spiller Address:	73 BROADWAY
Spiller Company:	001
Contact Name:	EARL HITCHCOCK
DEC Memo:	"All cleaned up by Big D. No further action required."
Remarks:	"TANK BLEW BACK A MIST OF OIL AND LANDED ON THE CEMENT ABOUT 2 CUPS AND IS ALL CLEANED UP: PIPING ON TRUCK ALSO HAD A LEAK IN IT:"

All Materials:

Site ID:	384082
Operable Unit ID:	1141392
Operable Unit:	01
Material ID:	2131606
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Resource Affected:	Soil
Oxygenate:	Not reported

Q96 **NORTH STAR INDUSTRIES** **LTANKS** **S102676400**
West **PETROVA AVE** **N/A**
1/4-1/2 **SARANAC LAKE, NY**
0.255 mi.
1349 ft. **Site 2 of 2 in cluster Q**

Relative:
Higher

Actual:
1568 ft.

LTANKS:

Name:	NORTH STAR INDUSTRIES
Address:	PETROVA AVE
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	8911602 / 1990-03-07
Facility ID:	8911602
Site ID:	238818
Spill Date:	1990-03-07
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1990-03-07
SWIS:	1700
Investigator:	AWSTEMP
Referred To:	Not reported
Reported to Dept:	1990-03-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	1990-03-07
Recommended Penalty:	False
Meets Standard:	True

NORTH STAR INDUSTRIES (Continued) **S102676400**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-03-09
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	HYDE FUEL COMPANY
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	196558
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AS "
Remarks:	"TANK CONTENTS MISGAUGED DURING DELIVERY, OVERFILL ON BLACKTOP AT REAR OF BUILDING. SPEEDI-DRY APPLIED. AS ON SITE 3/7-CLEANUP OK."

All Materials:

Site ID:	238818
Operable Unit ID:	937291
Operable Unit:	01
Material ID:	441111
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	NORTH STAR INDUSTRIES
Address:	PETROVA AVE
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9712367 / 1998-02-05
Facility ID:	9712367
Site ID:	238820
Spill Date:	1998-02-04
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	1700
Investigator:	LJMILLIO
Referred To:	Not reported
Reported to Dept:	1998-02-04
CID:	999
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-02-05

NORTH STAR INDUSTRIES (Continued) **S102676400**

Spill Record Last Update:	2001-05-16
Spiller Name:	DAN RILEY
Spiller Company:	HOME ENERGY
Spiller Address:	DEPOT STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	196558
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was LM 02/04/98: LM spoke with Dan Riley. Cleanup complete. FO sprayed in snow. Contaminated snow shoveled up and removed. 02/05/98: MM/LM checked site. No sign of overfill. RFC: Cleanup complete."
Remarks:	"UST (4000 GAL) OVERFILLED. ABOUT 1 GAL SPRAYED OVER SNOW DURING AN OVERFILL."

All Materials:

Site ID:	238820
Operable Unit ID:	1055126
Operable Unit:	01
Material ID:	326976
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Resource Affected:	Soil
Oxygenate:	Not reported

---

97 **PMS OUTFALL INTO SARANAC** **LTANKS** **S102118933**
NNE **WOODRUFF ST.** **NY Spills** **N/A**
1/4-1/2 **SARANAC LAKE, NY 12983**
0.279 mi.
1472 ft.

Relative:
Lower

Actual:
1509 ft.

LTANKS:

Name:	PMS OUTFALL INTO SARANAC
Address:	WOODRUFF ST.
City,State,Zip:	SARANAC LAKE, NY 12983
Spill Number/Closed Date:	0345071 / 2006-10-17
Facility ID:	0345071
Site ID:	134045
Spill Date:	2003-09-03
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	1746
Investigator:	GJHANDLY
Referred To:	Not reported
Reported to Dept:	2003-09-03
CID:	Not reported
Water Affected:	SARANAC RIVER
Spill Notifier:	DEC

PMS OUTFALL INTO SARANAC (Continued) **S102118933**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-09-04
Spill Record Last Update:	2006-10-18
Spiller Name:	WALTER CHURCH
Spiller Company:	PMOSE CO. INC.
Spiller Address:	PO BOX 159
Spiller County:	001
Spiller Contact:	DON CALDERA
Spiller Phone:	(518) 523-9953
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	115177
DEC Memo:	"2 UST's found along side of bldg. Op-Tech called in and UST's excavated. Impacted soil evident around tanks. Analytical results of 5 soil samples and 1 GW sample taken from the UST excavation indicate petroleum contamination. 11/12/04 - 2 additional UST's found to the rear of the bldg. Both tanks removed by Op-Tech and both excavations indicate petroleum contamination. 1,000 gal. UST furthest from bldg stored gasoline in the past. This tank was found to be highly corroded with gasoline impact to the soil and groundwater. About 100 tons of contaminated soil is stockpiled on site. Op-Tech will produce report and recommend additional site investigation work. Copy of letter report from Op-Tech reviewed and indicates significant contamination. 12/16/04 - Walter Church called Greg Handly to talk about DEC letter requiring full investigation. Mr. Church indicated that he was unable to continue the investigation work. Greg informed Mr. Church the DEC was required to move forward with the investigation and that access to the property was needed. He agreed to access by DEC and it's contractor. Greg will proceed with call-out of contractor and obtain signed access agreement. 2/10/05 - Greg Handly (GH) received tank closure report from Op-Tech. Copy forwarded to Precision Environmental for review before mobilizing for MW installation. 7/2005 - Investigation completed by Precision. Excavation of comtaminated soil is the selected remedy. 11/2005 - Excavation of 971 tons of contaminated soil is complete. GW monitoring will continue. 3/2006 - GW monitoring indicates low levels of VOC contamination remain. Contaminated soil excavated to extent practical. RFC: No further action required. 08/18/05: Russ Mulvey on site at 08:40 am, excavator, backhoe, low boy trailer, operator and supervisor on site. John Johnson on site at 9:00 am. John is operating excavator, started at 9:10 am. Add one van and one carry all type trailer on site at 9:00 am. Excavating and staging contaminated soils from between PMS and adjacent property's house. Russ Mulvey off site at 9:30 am. 08/19/05: Russ Mulvey on site at 8:30 am. Work was ongoing when he arrived. They are backfilling the excavation between PMS and the adjacent house. Russ Mulvey off site at 9:50 am. Russ back on site at 2:10 pm, no one on site. The equipment is staged on site, but no one is here. 10/18/06: Final ISR sent to Albany."
Remarks:	"Sheen and petroleum odors present in corner of property near Woodruff Street bridge."

All Materials:

Site ID:	134045

PMS OUTFALL INTO SARANAC (Continued) **S102118933**

Operable Unit ID: 881518
Operable Unit: 01
Material ID: 496703
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 100.00
Units: G
Recovered: .00
Resource Affected: Soil, Groundwater, Surface Water
Oxygenate: Not reported

Site ID: 134045
Operable Unit ID: 881518
Operable Unit: 01
Material ID: 2119127
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 50.00
Units: G
Recovered: .00
Resource Affected: Soil, Groundwater, Surface Water
Oxygenate: Not reported

SPILLS:
Name: WAREHOUSE COIN WASH
Address: WOODRUFF AVE
City,State,Zip: SARANAC LAKE, NY
Spill Number/Closed Date: 9004730 / 1990-08-01
Facility ID: 9004730
Facility Type: ER
DER Facility ID: 111541
Site ID: 129392
DEC Region: 5
Spill Cause: Housekeeping
Spill Class: Not reported
SWIS: 1700
Spill Date: 1990-07-27
Investigator: MPMCLEAN
Referred To: Not reported
Reported to Dept: 1990-07-27
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Citizen
Cleanup Ceased: 1990-08-01
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1990-07-30
Spill Record Last Update: 1990-08-02

PMS OUTFALL INTO SARANAC (Continued) **S102118933**

Spiller Name:	Not reported
Spiller Company:	WAREHOUSE COIN WASH
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM "
Remarks:	"WASTE OIL FROM OIL CHANGE LEAKING OUT OF OIL PAN, CONTACTED OWNER TO CLEAN UP. 8/1-CLEANUP ADEQUATE"

All Materials:

Site ID:	129392
Operable Unit ID:	942475
Operable Unit:	01
Material ID:	435812
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

98
ENE
1/4-1/2
0.308 mi.
1628 ft.

TISSOT CONSTRUCTION **LTANKS** **S105055072**
RT. 86 **N/A**
SARANAC LAKE, NY

Relative:
Higher

Actual:
1601 ft.

LTANKS:

Name:	TISSOT CONSTRUCTION
Address:	RT. 86
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	0145038 / 2001-06-12
Facility ID:	0145038
Site ID:	120228
Spill Date:	2001-06-11
Spill Cause:	Tank Overfill
Spill Source:	Commercial Vehicle
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	1700
Investigator:	LJMILLIO
Referred To:	Not reported
Reported to Dept:	2001-06-11
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-06-12
Spill Record Last Update:	2001-06-14

TISSOT CONSTRUCTION (Continued) **S105055072**

Spiller Name:	Not reported
Spiller Company:	TISSOT CONSTRUCTION
Spiller Address:	RT. 86
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	(518) -
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	104407
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was LM RFC: Minor spill. "
Remarks:	"2' diameter stain near truck where it was overfilled, at southerly end of property."

All Materials:

Site ID:	120228
Operable Unit ID:	849733
Operable Unit:	01
Material ID:	526870
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

R99 **CASIER'S - OLD TANK** **LTANKS** **S103941013**
North **BLOOMINGDALE ST** **N/A**
1/4-1/2 **SARANAC LAKE, NY**
0.309 mi.
1633 ft. **Site 1 of 3 in cluster R**

Relative:
Higher

Actual:
1551 ft.

LTANKS:

Name:	CASIER'S - OLD TANK
Address:	BLOOMINGDALE ST
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9901135 / 1999-05-17
Facility ID:	9901135
Site ID:	76576
Spill Date:	1999-04-29
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	1700
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1999-04-29
CID:	211
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False

CASIER'S - OLD TANK (Continued) **S103941013**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-04-29
Spill Record Last Update:	1999-05-17
Spiller Name:	Not reported
Spiller Company:	CASIER FURNITURE
Spiller Address:	BLOOMINGDALE ST
Spiller County:	001
Spiller Contact:	JOHN STEITZ
Spiller Phone:	(518) 891-2540
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	71572
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM 05/03/99: MM on site, 1000 gallon tank at location removed, several holes noted. McEnvironmental on site to close out. Luck Brothers to excavate contaminated soil to extent possible. 05/17/99: Minor amount of contaminated soil removed, excavation limited due to several utilities in area. RFC: Contaminated soil excavated to extent practical, no further action required. "
Remarks:	"CALLER EXCAVATING AND FOUND UNDERGROUND STORAGE TANK THAT APPEARS TO BE LEAKING - DEC REP HAS BEEN ON SCENE."

All Materials:

Site ID:	76576
Operable Unit ID:	1075910
Operable Unit:	01
Material ID:	304684
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

R100 **STEWARTS** **LTANKS** **S102676659**
North **BLOOMINGDALE ROAD & DEPOT** **N/A**
1/4-1/2 **SARANAC LAKE, NY**
0.317 mi.
1675 ft. **Site 2 of 3 in cluster R**

Relative: **Higher**

Actual: **1548 ft.**

LTANKS:

Name:	STEWARTS
Address:	BLOOMINGDALE ROAD & DEPOT
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9312279 / 1994-01-19
Facility ID:	9312279
Site ID:	319324
Spill Date:	1994-01-19
Spill Cause:	Tank Overfill
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3
Cleanup Ceased:	1994-01-19
SWIS:	1700

STEWARTS (Continued) **S102676659**

Investigator:	SELALOND
Referred To:	Not reported
Reported to Dept:	1994-01-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-01-19
Spill Record Last Update:	1998-03-27
Spiller Name:	Not reported
Spiller Company:	CUSTOMER
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	257260
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SL RFC: Speedy dry applied and picked up. "
Remarks:	"FIRE DEPT. ON SCENE AND LEFT. SPILL CONTAINED ON PAVEMENT."

All Materials:

Site ID:	319324
Operable Unit ID:	990910
Operable Unit:	01
Material ID:	391267
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	8.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

R101 **STEWARTS SHOP # 242** **LTANKS** **S100964842**
North **BLOOMINGDALE AVE** **N/A**
1/4-1/2 **SARANAC LAKE, NY**
0.319 mi.
1685 ft. **Site 3 of 3 in cluster R**

Relative:
Higher

Actual:
1551 ft.

LTANKS:

Name:	STEWARTS SHOP # 242
Address:	BLOOMINGDALE AVE
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9112342 / 2002-09-11
Facility ID:	9112342
Site ID:	182693
Spill Date:	1992-03-04
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility

STEWARTS SHOP # 242 (Continued) **S100964842**

Spill Class:	A3
Cleanup Ceased:	Not reported
SWIS:	1746
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1992-03-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1993-04-05
Spill Record Last Update:	2004-10-04
Spiller Name:	CHAD FOWLER
Spiller Company:	STEWART'S
Spiller Address:	PO BOX 435
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	310895
DEC Memo:	"03/05/92: Groundwater investigation to begin Monday March 9,1992. 05/06/92: Groundwater treatment/soil vapor extraction system installed and operating at site. Passaretti Geological maintaining system, performing system and monitoring well sampling. 05/22/92: Initial GW investigation report received, additional offsite wells requested. 07/10/92: Additional wells installed, Sturdy Supply across Bloomingdale Avenue has petroleum contaminatin from source on their property. Additional offsite investigation not purused. 02/23/97: SVS system still operating on site. Groundwater treatment system has been down for some time. Contamination levels in monitoring wells have been decreasing. 01/04/00: MW sampling, SVES monitoring being conducted by Precision Environmental groundwater treatment system no longer operating. 09/11/02: MW reviews site status report submitted by Precision (9/6/02). Site closed out, no further cleanup/investigation/sampling necessary. RFC: RP performed satisfactory cleanup. "
Remarks:	"4K SUPER UNLEADED TANK FAILED, GROSS LEAK, TANK PUMPED OUT. ODORS NOTICED IN ADIRONDACK DAILY ENTERPRISE, JC PENNY, AND SANITARY SEWER. STEWART'S INSTALLING EXHAUST FANS IN ADIRONDACK DAILY ENTERPRISE, JC PENNEY & STORM SEWER."

All TTF:

Facility ID:	9112342
Spill Number:	9112342
Spill Tank Test:	1539686
Site ID:	182693
Tank Number:	Not reported
Tank Size:	0
Material:	1213A
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported

STEWARTS SHOP # 242 (Continued) **S100964842**

Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	182693
Operable Unit ID:	965944
Operable Unit:	01
Material ID:	572805
Material Code:	1213A
Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	True

Site ID:	182693
Operable Unit ID:	965944
Operable Unit:	01
Material ID:	417322
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	True

---

102 West 1/4-1/2 0.323 mi. 1706 ft.

PETROVA AVE SCHOOL
PETROVA AVE
SARANAC LAKE, NY

LTANKS **S102676494**
N/A

Relative: Higher

Actual: 1571 ft.

LTANKS:

Name:	PETROVA AVE SCHOOL
Address:	PETROVA AVE
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9107092 / 1991-10-02
Facility ID:	9107092
Site ID:	238819
Spill Date:	1991-10-02
Spill Cause:	Tank Overfill
Spill Source:	Unknown
Spill Class:	Not reported
Cleanup Ceased:	1991-10-02
SWIS:	1700
Investigator:	RLWAGNER

PETROVA AVE SCHOOL (Continued) **S102676494**

Referred To:	Not reported
Reported to Dept:	1991-10-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-10-03
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	196558
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RW "
Remarks:	"GAUGE HAD FAULTY READING OR HAULER OVERFILLED 7500G TANK, SPILL ON GRASS NEAR VENT PIPE. RW ON SITE, VERY SMALL SPILL, WILL DIG UP AND SPREAD UNTIL CLEAN. NO POTENTIAL FOR ANY IMPACTS."

All Materials:

Site ID:	238819
Operable Unit ID:	961336
Operable Unit:	01
Material ID:	419323
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

---

103 **MRS KELTING** **LTANKS** **S102676834**
WSW **174 LAKE ST** **N/A**
1/4-1/2 **SARANAC LAKE, NY**
0.325 mi.
1714 ft.

Relative:
Higher

Actual:
1613 ft.

LTANKS:

Name:	MRS KELTING
Address:	174 LAKE ST
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9509800 / 1995-11-07
Facility ID:	9509800
Site ID:	181770
Spill Date:	1995-11-07
Spill Cause:	Tank Overfill

MRS KELTING (Continued) **S102676834**

Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	1700
Investigator:	LJMILLIO
Referred To:	Not reported
Reported to Dept:	1995-11-07
CID:	351
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-11-07
Spill Record Last Update:	1996-04-01
Spiller Name:	Not reported
Spiller Company:	BIG D
Spiller Address:	188 BROADWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	( ) 891-6344
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	152418
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was LM RFC: Big D cleaned up, homeowner satisfied. "
Remarks:	"ON CEMENT FLOOR, CLEANED WITH SPEEDY DRY, REPLACED WHISTLE HOME OWNER SATISFIED W/ CLEANUP CALL FAXED FROM REGION 5R ON 11/07/95"

All Materials:

Site ID:	181770
Operable Unit ID:	1024134
Operable Unit:	01
Material ID:	360734
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

---

104 East 1/4-1/2 0.332 mi. 1754 ft. **SCHNECK RESIDENCE** **LTANKS** **S102676851**
FRANKLIN AVE. **N/A**
SARANAC LAKE, NY

Relative: Higher

Actual: 1565 ft.

LTANKS:

Name:	SCHNECK RESIDENCE
Address:	FRANKLIN AVE.
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9515925 / 1996-03-04

SCHNECK RESIDENCE (Continued) **S102676851**

Facility ID:	9515925
Site ID:	243136
Spill Date:	1996-02-26
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	1700
Investigator:	LJMILLIO
Referred To:	Not reported
Reported to Dept:	1996-03-12
CID:	312
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-03-12
Spill Record Last Update:	1996-03-15
Spiller Name:	Not reported
Spiller Company:	HYDE FUEL
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	KATHY SCHNECK
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	199724
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was LM RFC: Odors dissipated. "
Remarks:	"small amount in basement - speedy-dri applied - did not think it necessary for hyde fuel to come back and look at it"

All Materials:

Site ID:	243136
Operable Unit ID:	1030578
Operable Unit:	01
Material ID:	352469
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

105
ENE
1/4-1/2
0.346 mi.
1827 ft.

45 FRANKLIN AVE
45 FRANLKIN AVE
SARANAC LAKE, NY

LTANKS **S102660804**
N/A

Relative:
Higher

Actual:
1622 ft.

LTANKS:

Name:	45 FRANKLIN AVE
Address:	45 FRANLKIN AVE
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	8808981 / 1989-10-04
Facility ID:	8808981
Site ID:	327366
Spill Date:	1989-02-14
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	1989-10-04
SWIS:	1600
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1989-02-14
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	1989-10-04
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-02-17
Spill Record Last Update:	1992-08-26
Spiller Name:	Not reported
Spiller Company:	DAN FINLAYSON
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	263517
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM 10/04/89: MW HAS BEEN DRY FOR OVER 1/2 YEAR, NO SIGN OF ANY IMPACT NEAR NEIGHBORS, NO SURFACE WATER IN IMMEDIATE AREA. NO FURTHER ACTION WARRENTED. "
Remarks:	"UST DEVELOPED HOLE, LOSING +-1000 GALLONS OF FUEL OIL. TANK REMOVED, PIT DUG UNDER TANK, GROSSLY CONTAMINATED SOIL REMOVED, TO LANDFILL. MW INSTALLED, DRILLED TO 55, NO GW, SOIL AT BOTTOM CLEAN."

All Materials:

Site ID:	327366
Operable Unit ID:	924897
Operable Unit:	01
Material ID:	453738
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1000.00
Units:	G

45 FRANKLIN AVE (Continued) **S102660804**

Recovered: .00
Resource Affected: Groundwater
Oxygenate: Not reported

S106 **IN FRONT OF RUSTY NAIL** **LTANKS** **S103941146**
NNW **BROADWAY** **N/A**
1/4-1/2 **SARANAC LAKE, NY**
0.348 mi.
1840 ft. **Site 1 of 4 in cluster S**

Relative: **Higher**
Actual: **1572 ft.**

LTANKS:
Name: IN FRONT OF RUSTY NAIL
Address: BROADWAY
City,State,Zip: SARANAC LAKE, NY
Spill Number/Closed Date: 9945033 / 1999-05-14
Facility ID: 9945033
Site ID: 61852
Spill Date: 1999-05-13
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 1700
Investigator: MPMCLEAN
Referred To: Not reported
Reported to Dept: 1999-05-13
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1999-05-14
Spill Record Last Update: 1999-05-17
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller County: 999
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 5
DER Facility ID: 60042
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM 05/14/99: LM on site. Two tanks found and removed. 1 - 1000 gallon and 1 - 500 gallon. RFC: Minor contamination found. "
Remarks: "Tank and contaminated soil encountered while DOT excavating in front of Rusty Nail, McEnvironmental to remove tank afternoon of 5/14/99. "

All Materials:
Site ID: 61852
Operable Unit ID: 1090004
Operable Unit: 01
Material ID: 293814
Material Code: 0001A

IN FRONT OF RUSTY NAIL (Continued) **S103941146**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

S107 **SARANAC LAKE VILLAGE LANDFILL** **ODI** **1007444964**
North **MCKENZIE POND RD** **N/A**
1/4-1/2 **SARANAC LAKE, NY**
0.349 mi.
1843 ft. **Site 2 of 4 in cluster S**

Relative: **Higher**
Actual: **1557 ft.**

ODI:

Non Compliance Category:	03 06
Latitude:	44 18 30
Longitude:	074 06 30

S108 **SARANAC LAKE LANDFILL** **LTANKS** **S100560434**
North **MCKENZIE POND ROAD** **NY Spills** **N/A**
1/4-1/2 **SARANAC LAKE, NY**
0.349 mi.
1843 ft. **Site 3 of 4 in cluster S**

Relative: **Higher**
Actual: **1557 ft.**

LTANKS:

Name:	SARANAC LAKE LANDFILL
Address:	MCKENZIE POND ROAD
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9305475 / 1993-08-17
Facility ID:	9305475
Site ID:	193220
Spill Date:	1993-07-31
Spill Cause:	Tank Failure
Spill Source:	Commercial Vehicle
Spill Class:	C3
Cleanup Ceased:	1993-08-17
SWIS:	1600
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1993-08-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-08-10
Spill Record Last Update:	1996-01-03
Spiller Name:	Not reported
Spiller Company:	METALS UNLIMITED
Spiller Address:	PO BOX 470

SARANAC LAKE LANDFILL (Continued) **S100560434**

Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	161108
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM 08/02/93: 3:00 PM TANK PRESENTLY A LITTLE OVER 1/2 FULL. 08/02/93: MM CONTACTED AMY AND ADVISED TO EMPTY TANK TO STOP LEAK. EXCAVATE CONT. SOIL. SHE INDICATED SOMEONE WOULD PUMP OUT TANK THAT EVENING. ASKED HER TO DETERM. HOW MUCH FUEL WAS IN TANK BEFORE DELIVERY. 08/04/93: 10:40 AM INSPECTED SITE, CONT. SOIL NOT EXCAVATED AS OF YET. INSPECTION OF EQUIPMENT FOUND SAME TANK WITH SAME AMOUNT OF FUEL. PAN PLACED UNDER EQUIPMENT TO CATCH LEAK. 08/04/93: 2:15 PM ADVISED VILLAGE MANAGER PAT FITZGERALD OF SITUATION. WOULD BE WILLING TO HELP IN CLEANUP, SPREAD CONT. SOIL ON SITE, ETC. 08/04/93: 2:30 PM, REINSPECTED SITE, METALS UNLIMITED NOT ON SITE, TANK STILL DRIPPING. CONVERS. W/WORKER AT LANDFILL INDICATED THAT THE EQUIP. BROKE TUESDAY AM, LEFT SITE TO OBTAIN PART, HAVE NOT RETURNED. 08/04/93: WORKER ALSO INDICATED THAT METALS UNLIMITED STATED THAT TANK HAS BEEN LEAKING FOR SOME TIME, THEY FORGOT TO PLACE CATCH PAN UNDER TANK WHEN TRAILER PARKED 7/31/93. 08/04/93: UNABLE TO CONTACT METALS UNLIMITED BY PHONE. 08/05/93: RW/ECO FLYNN ON SITE 8/5/93, OPERATOR OF CRUSHER VERY COOPERATIVE, TO EXCAVATE CONT. SOIL, ADD BLACK DIRT/COMPST, TREAT ON SITE, TO REPLACE TANK. RFC: Minimum contaminated soil bioremediated on site. No further action needed."
Remarks:	"CAR CRUSHER ON-SITE TO CRUSH METAL. 275G DIESEL TANK ON CRUSHER LEAKING. MM/SL INVESTIGATED. MM SPOKE W/METALS UNLIMITED, TANK TO BE EMPTIED, CONT. SOIL TO BE ADDRESSED."

All Materials:

Site ID:	193220
Operable Unit ID:	986984
Operable Unit:	01
Material ID:	395390
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

SPILLS:

Name:	SARANAC LAKE LANDFILL
Address:	MCKENZIE POND ROAD
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	8909907 / 1990-02-01
Facility ID:	8909907
Facility Type:	ER
DER Facility ID:	161108
Site ID:	193217
DEC Region:	5
Spill Cause:	Deliberate

SARANAC LAKE LANDFILL (Continued) **S100560434**

Spill Class:	Not reported
SWIS:	1600
Spill Date:	1989-06-01
Investigator:	RLWAGNER
Referred To:	Not reported
Reported to Dept:	1990-01-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	1990-02-01
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-03-02
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	GLENEAGLES CORP??
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RW "
Remarks:	"REPORT OF ASBESTOS DUMPING IN SARANAC LANDFILL. NO ACTION TAKEN AS PERWL MEMO TO TM DATED 1/17/90."

All Materials:

Site ID:	193217
Operable Unit ID:	936916
Operable Unit:	01
Material ID:	443048
Material Code:	0026A
Material Name:	asbestos
Case No.:	01332214
Material FA:	Hazardous Material
Quantity:	600000.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

S109 **RUSTY NAIL** **LTANKS** **S100494861**
NNW **BROADWAY STREET** **NY Spills** **N/A**
1/4-1/2 **SARANAC LAKE, NY**
0.349 mi.
1845 ft. **Site 4 of 4 in cluster S**

Relative:
Higher

Actual:
1566 ft.

LTANKS:

Name:	RUSTY NAIL
Address:	BROADWAY STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	8910180 / 1990-01-24
Facility ID:	8910180
Site ID:	122388
Spill Date:	1990-01-22

RUSTY NAIL (Continued) **S100494861**

Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1990-01-24
SWIS:	1700
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1990-01-22
CID:	Not reported
Water Affected:	SARANAC RIVER
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-01-24
Spill Record Last Update:	1990-05-23
Spiller Name:	Not reported
Spiller Company:	RUSTY NAIL
Spiller Address:	C: CINDY THOMPSON
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	106117
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM 01/24/90: SPILL CLEANUP ADEQUATE, MATERIAL ON FLOOR CLEANED WITH SPEEDI-DRY, ETC. DYE TESTED DRAIN, APPARENTLY RUNS TO STP, NO DYE DETECTIBLE IN RIVER. "
Remarks:	"275 ABOVEGROUND TANK RUPTURED SEAM, SPILLING FUEL TO BASEMENT FLOOR, EXITING OUT FLOOR DRAIN, SHEEN IN SARANAC RIVER, TO DYE TEST DRAIN TO DETERMINE EXIT."

All Materials:

Site ID:	122388
Operable Unit ID:	937204
Operable Unit:	01
Material ID:	443298
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

SPILLS:

Name:	ALICE'S RESTAURANT
Address:	BROADWAY ST
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9513071 / 1996-01-19
Facility ID:	9513071

RUSTY NAIL (Continued) **S100494861**

Facility Type:	ER
DER Facility ID:	251754
Site ID:	312195
DEC Region:	5
Spill Cause:	Other
Spill Class:	D4
SWIS:	1700
Spill Date:	1996-01-19
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1996-01-19
CID:	365
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-01-19
Spill Record Last Update:	1996-01-22
Spiller Name:	Not reported
Spiller Company:	HYDE FUEL COMPANY
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM RFC: Minor sheen, no cleanup needed. "
Remarks:	"alice reported spill to hyde as a result of a recent delivery. mm was on site during delivery, most of sheen due to meltoff of parking area alley - no response taken"

All Materials:

Site ID:	312195
Operable Unit ID:	1024062
Operable Unit:	01
Material ID:	356801
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

Name:	ALICE'S RESTAURANT
Address:	BROADWAY
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9400157 / 1994-04-04
Facility ID:	9400157
Facility Type:	ER
DER Facility ID:	60042

RUSTY NAIL (Continued) **S100494861**

Site ID:	61848
DEC Region:	5
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	1700
Spill Date:	1994-04-04
Investigator:	AWSTEMP
Referred To:	Not reported
Reported to Dept:	1994-04-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	1994-04-04
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-04-05
Spill Record Last Update:	1996-01-22
Spiller Name:	Not reported
Spiller Company:	HYDE'S FUEL
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AS RFC: Speedy dry applied and cleaned up. "
Remarks:	"NOZZLE BROKE DURING DELIVERY. 1-2G SPILLED, SPEEDY DRY APPLIED AND REMOVED."

All Materials:

Site ID:	61848
Operable Unit ID:	993890
Operable Unit:	01
Material ID:	387483
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

---

110 East 1/4-1/2 0.369 mi. 1946 ft.

MAINLINE GARAGE
LAKE FLOWER AVENUE
SARANAC LAKE, NY

LTANKS **S100160994**
NY Spills **N/A**

Relative: Higher

Actual: 1538 ft.

LTANKS:

Name:	MAINLINE GARAGE
Address:	LAKE FLOWER AVENUE
City,State,Zip:	SARANAC LAKE, NY

MAINLINE GARAGE (Continued) **S100160994**

Spill Number/Closed Date:	8706905 / 1987-11-24
Facility ID:	8706905
Site ID:	287325
Spill Date:	1987-06-10
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	1987-11-24
SWIS:	1600
Investigator:	AWSTEMP
Referred To:	Not reported
Reported to Dept:	1987-11-13
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	DEC
Last Inspection:	1987-11-13
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-11-13
Spill Record Last Update:	1998-10-16
Spiller Name:	Not reported
Spiller Company:	HYDE FUEL COMPANY
Spiller Address:	171 BROADWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	232754
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AS 11/24/87: TANK EXCAVATED AND REMOVED. "
Remarks:	"3,000 GALLON TANK - DIESEL LEAKING - ABANDONED ON SITE."

All Materials:

Site ID:	287325
Operable Unit ID:	910777
Operable Unit:	01
Material ID:	465893
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

SPILLS:

Name:	BEHIND LAKE VIEW DELI
Address:	LAKE FLOWER AVENUE
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	0345088 / 2003-10-31
Facility ID:	0345088

MAINLINE GARAGE (Continued) **S100160994**

Facility Type:	ER
DER Facility ID:	91310
Site ID:	103220
DEC Region:	5
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1700
Spill Date:	2003-10-23
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	2003-10-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-10-28
Spill Record Last Update:	2003-11-04
Spiller Name:	ANN MARIE TROMBLEY
Spiller Company:	LAKE PLACID DISPOSAL CO
Spiller Address:	22 OLD MILITARY ROAD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM 10/27/03 - BD on site at 1545. Spill being cleaned up with bobcat and workers with shovels. Instructed workers to remove soils until oil sheens were no longer evident. 10/28/03 - BD on site at 1045. Spill cleaned up. RFC: No further action necessary."
Remarks:	"Leak of hydraulic oil due to equipment failure. Oil running with storm runoff. RM inspected location, WSM/LPD to return to location and cleanup contaminated soil area, significant quantity running off lot."

All Materials:

Site ID:	103220
Operable Unit ID:	881527
Operable Unit:	01
Material ID:	496722
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

111
NW
1/4-1/2
0.380 mi.
2007 ft.

DURFEE RESIDENCE
2 FAIRVIEW AVENUE
SARANAC LAKE, NY

LTANKS **S100493895**
N/A

Relative:
Higher

Actual:
1641 ft.

LTANKS:

Name:	DURFEE RESIDENCE
Address:	2 FAIRVIEW AVENUE
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9205763 / 1992-08-19
Facility ID:	9205763
Site ID:	329037
Spill Date:	1992-08-18
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	1992-08-19
SWIS:	1700
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1992-08-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-08-19
Spill Record Last Update:	1995-11-30
Spiller Name:	Not reported
Spiller Company:	ROBERT DURFEE
Spiller Address:	2 FAIRVIEW AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	264792
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM RFC: Minor spill, contained to basement area. Cleaned up by Agway. "
Remarks:	"LEAK OCCURRED IN BOTTOM OF TANK DUE TO CORROSION, RESIDENCE NOTICED ODORS AND CONTACTED AGWAY. AGWAY RESPONDED, PUMPED OUT TANK, WIPED PRODUCT OFF CEMENT. TO REPLACE TANK. NO DEC RESPONSE."

All Materials:

Site ID:	329037
Operable Unit ID:	969529
Operable Unit:	01
Material ID:	559027
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

DURFEE RESIDENCE (Continued) **S100493895**

Resource Affected: Soil
Oxygenate: Not reported

---

112 **SARANAC LOFTS** **BROWNFIELDS** **S127990278**
North **120 BROADWAY** **N/A**
1/4-1/2 **SARANAC LAKE, NY 12983**
0.401 mi.
2115 ft.

Relative:
Higher

Actual:
1562 ft.

BROWNFIELDS:

Name:	SARANAC LOFTS
Address:	120 BROADWAY
City,State,Zip:	SARANAC LAKE, NY 12983
Program:	BCP
Site Code:	623777
Acres:	1.100
HW Code:	C517015
SWIS:	1744
Town:	Franklin
Record Added Date:	08/24/2021
Record Updated Date:	01/24/2023
Update By:	BDHUYCK
Site Description:	"Location: The 1.11-acre mixed-use (small commercial and vacant) parcel is located at 120 Broadway in a well-developed village area of Saranac Lake, Franklin County. Site Features: A tire shop (a former filling station) is located at the southern portion of Lot 12 on Broadway. The site is significantly sloped with an approximately 15-foot drop in elevation from the front of the tire shop to the rear of the building with a walkout basement. The remainder of the property is relatively flat and is comprised of a gravel parking lot at the rear of the building and a maintained yard (entirety of Lot 11). Portions of the eastern and western borders at Lot 12 are defined by the extent of the on-site building. Portions of the northern border at Lot 11 are defined by a concrete retaining wall. Current Zoning and Land Use: The site is partially occupied and is located in a E-1 commercial and residential zoning district. Uses at adjoining properties include the Adirondack Rail Trail (a 119-mile walking/biking corridor to the north), the Saranac Lake Volunteer Rescue Squad to the east, multi-family residential developments to the west of Lot 12 (south of Lot 11), a bookstore and and a children s museum and family resource center to the south, and a propane storage facility (Hyde Fuel) to the west of Lot 11. Past Uses of the Site: The southern portion of the subject property (Lot 12) was in use for commercial purposes as a filling station and automotive maintenance facility sometime between 1916 and 1924. This portion of the property contains a small structure that has been used as a tire shop since circa 1969. The northern portion of the property (Lot 11) contained a woodworking factory from at least 1916 through 1965 (remaining portions of these buildings were present on the property as late as 1977). Site Geology and Hydrogeology: Soils in the vicinity of the subject property are likely to be derived from glaciolacustrine deposits, which overlie hard crystalline bedrock. Soils recovered during the combined Phase I & II subsurface investigation generally consisted of loamy, fine to medium sands. Likely fill material containing sandy loams or variable-texture sand with coal fragments and/or ash was observed in several borings during the remedial investigation ranging in depth from several inches to up

SARANAC LOFTS (Continued) **S127990278**

to ten feet below grade surface (bgs). Boring refusal (likely on bedrock) was encountered at depths ranging from seven feet bgs at the southern end of Lot 12, ten to 13.5 feet bgs at the northern half of Lot 12 and nine to 13.5 feet bgs at Lot 11. Bedrock outcrops were observed on the opposite site of Broadway, but not on the property. Saturated soils were encountered at the surface to ten feet bgs at Lot 11 and approximately 15 feet bgs at the southern end of Lot 12 to five feet bgs at the northern half of Lot 12. Overall groundwater flow at the site is southerly at Lot 11 and north-northeasterly at Lot 12, toward a low-lying area at the northern half of Lot 12, from which it flows southeasterly toward the Saranac River (located approximately 0.2-mile from the property)."

Env Problem:

"Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), per- and polyfluoroalkyl substances (PFAS), pesticides and herbicides. Based upon investigations conducted to date, the primary contaminants of concern for the site include VOCs, SVOCs, such as polycyclic aromatic hydrocarbons (PAHs; ex: benzo(a)anthracene, benzo(a)pyrene and benzo(b)fluoranthene), and metals. Soils: Contaminated soils are likely due to historic repair activities and releases from former gasoline underground storage tanks (USTs) at the site. VOCs, PAHs, and metals were detected in soils above restricted-residential use soils cleanup objectives (RRU SCOs). PFAS impacts were limited to one exceedance above NYSDEC soil cleanup guidance values. No pesticides, PCBs or herbicides were detected in soil samples (with the exception of endosulfan sulfate detection in a duplicate sample). Groundwater: VOC and SVOC contaminates were detected in groundwater above groundwater standards. Site groundwater is also characterized by low grade metal and PFAS contamination. Pesticides, PCBs and herbicides were not detected in any groundwater samples. Soil Vapor: Gasoline constituents are present in soil vapor. This is likely due to the field evidence of petroleum contamination documented in both soil and groundwater. Nature and Extent of Contamination: Soil: VOCs are above RRU SCOs and/or protection of groundwater (POG) SCOs in soil near the tank location, and north-northeast of the site building. Concentrations detected above RRU SCOs in sample 2SB-05 5 include 1,2,4-trimethylbenzene (320 ppm; RRU SCO 52 ppm); 1,3,5-trimethylbenzene (100 ppm; RRU SCO 52 ppm); and xylenes (210 ppm; RRU SCO 100 ppm). Total xylene was reported above the POG SCO in sample 2SB-07 7 northeast of the building (3.4 ppm; POG 1.6 ppm). 2SB-05 5 contained high levels of total tentatively identified compounds (TICs; 777 ppm). No other VOCs were reported above RRU SCOs, and no other VOCs found in groundwater above standards were also detected in soil above POG SCOs. PAHs were detected above RRU SCOs in sample 2SB-13 2-5, 2SB-23 0-5 and 2SB-24 0-5. Which include maximum reported values of benzo(a)anthracene (4.38 ppm; RRU SCO 1 ppm), benzo(a)pyrene (3 ppm; RRU SCO 1 ppm); and benzo(b)fluoranthene (6.11 ppm; RRU SCO 1 ppm). All SVOCs detected above SCOs, and all TICs, were located in the upper 0 to 5 feet interval of soil. TAL metals were detected above RRU SCOs in sample 2SB-06 5 and 2SB-08 0-5, including maximum reported values for: barium (3,780 ppm; RRU SCO 400 ppm); cadmium (6.48 ppm; RRU SCO 4.3 ppm); copper (429 ppm; RRU SCO 270 ppm); and lead (1,010 ppm; RRU SCO 400 ppm). No other sampling locations contained metals above RRU SCOs. UU SCOs were exceeded in twelve other samples collected. No pesticides, PCBs, and herbicides were detected above unrestricted use SCO in soil samples.

SARANAC LOFTS (Continued) **S127990278**

The detections of PFAS compounds PFOS and PFOA were not above the restricted residential use guidance values. Groundwater: VOCs above groundwater standards were detected in MW-01 and MW-04. Concentrations detected above AWQS (5 ppb) at MW-01: 1,2,4-trimethylbenzene (1,440 ppb), 1,3,5-trimethylbenzene (352 ppb), ethyl benzene (1,280 ppb), toluene (707 ppb), and total xylenes (1,196 ppb). Similar contamination was found at MW-04 at lower levels. Cyclohexane and methylcyclohexane (AWQS not established) were detected at elevated levels in both wells (as high as 112 ppb). Chlorinated VOCs were detected at MW-01: 1,2-dichloropropane at 2.3 ppb, (AWQS 1 ppb) and MW-04: 1,1,2-trichloroethane, at 32.3 ppb (AWQS 1 ppb). VOC TICs were detected: 737 ppb at MW-04, 299 ppb at MW-01, and 1 ppb at MW-03 (no TICs were found in other wells). The detection of these TICs could be indicative of natural degradation of petroleum. Trace to low levels of one or more SVOCs, primarily PAHs, were reported in all wells. Naphthalene was detected above its AWQS of 10 in MW-01 (179 ppb) and MW-04 (14.2 ppb). SVOC TICs were detected: 5,978 ppb at MW-01 and 1079 ppb at MW-04. Multiple metals were reported in all groundwater samples, with elevated levels of both total and dissolved cobalt, iron, manganese, and/or sodium in all wells except MW-05. MW-01 detected a concentration of cobalt above AWQS. Dissolved metal concentrations did not exceed AWQS or were significantly lower than total metals concentrations in groundwater for the metals cobalt and iron. This indicates that these metals are not migrating through the water column. The data is indicative of ubiquitous and/or naturally occurring metals in groundwater upgradient and across the site. PFOS and PFOA were detected in two samples (MW-04, MW-09), below the maximum contaminant level, or drinking water standard, which is 10 ppt for both substances. Soil Vapor: SV-06 indicates VOC gasoline constituents (cyclohexane (1,700,000 ug/m3); n-heptane (4,300,000 ug/m3); n-hexane (7,700,000 ug/m3); and, BTEX and related VOCs (up to 95,000 ug/m3). Nine soil vapor samples reported concentrations of solvent 2-butanone between 1,400 to 3,400 ug/m3. Most of the soil vapor detections were located on Lot 12 with the solvent 2-butanone present throughout the Site. "

Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2021-11-16 10:40:00
Record Upd:	2023-01-04 14:46:00
Updated By:	KMZAPPIA
Own Op:	4
Sub Type:	NNN
Owner Name:	Adirondack Tire Co.
Owner Company:	Adirondack Tire Co.
Owner Address:	117 Broadway
Owner Addr2:	Not reported

SARANAC LOFTS (Continued) **S127990278**

Owner City,St,Zip:	Saranac Lake, NY 12983
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Gregory Mace
Owner Address:	120 Broadway
Owner Addr2:	Not reported
Owner City,St,Zip:	Saranac Lake, NY 12983
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Kenneth Kearney
Owner Company:	Parkview Development & Construction, LLC
Owner Address:	57 Route 6, Suite 207
Owner Addr2:	Not reported
Owner City,St,Zip:	Baldwin Place, NY 10505
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Peter Benson
Owner Company:	Saranac Lake Free Library
Owner Address:	109 Main Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Saranac Lake, NY 12983
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	2103108
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2023-01-06 10:39:00
Record Updated:	2023-01-06 10:39:00
Updated By:	KMZAPPIA

---

113 South 1/4-1/2 0.408 mi. 2153 ft. **SHELLY VANCOUR RESIDENCE** **LTANKS** **S106971490**
340 GLENWOOD DRIVE **N/A**
SARANAC LAKE, NY 12983

Relative: Higher

Actual: 1608 ft.

LTANKS:

Name:	SHELLY VANCOUR RESIDENCE
Address:	340 GLENWOOD DRIVE
City,State,Zip:	SARANAC LAKE, NY 12983
Spill Number/Closed Date:	0485104 / 2004-11-05
Facility ID:	0485104
Site ID:	333221
Spill Date:	2004-11-01
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	B2
Cleanup Ceased:	Not reported
SWIS:	1746
Investigator:	LJMILLIO
Referred To:	Not reported

SHELLY VANCOUR RESIDENCE (Continued) **S106971490**

Reported to Dept:	2004-11-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-11-02
Spill Record Last Update:	2004-11-05
Spiller Name:	Not reported
Spiller Company:	GRIFFITH ENERGY
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	(518) 891-2939
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	268471
DEC Memo:	"RFC: Minor release. Cleanup complete. Close. "
Remarks:	"Overfilled tank, fuel came out vent pipe into basement. Scott cleaned up with speedy dry. Left absorbent on concrete, will pick up today."

All Materials:

Site ID:	333221
Operable Unit ID:	1095396
Operable Unit:	01
Material ID:	575534
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Resource Affected:	Soil
Oxygenate:	False

T114 **PJ HYDE & SON** **LTANKS S103824449**
NNW **171 BROADWAY** **NY Spills N/A**
1/4-1/2 **SARANAC LAKE, NY 12983**
0.435 mi.
2297 ft. **Site 1 of 2 in cluster T**

Relative:
Higher

Actual:
1565 ft.

LTANKS:

Name:	HYDE FUELS
Address:	171 BROADWAY
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9209709 / 1995-12-18
Facility ID:	9209709
Site ID:	74229
Spill Date:	1992-11-19
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3

PJ HYDE & SON (Continued) **S103824449**

Cleanup Ceased:	1995-12-18
SWIS:	1700
Investigator:	RDHUYCK
Referred To:	Not reported
Reported to Dept:	1992-11-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-11-20
Spill Record Last Update:	1998-02-23
Spiller Name:	Not reported
Spiller Company:	HYDE FUELS
Spiller Address:	171 BROADWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	69718
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RH 12/18/95: SOIL VAPOR EXTRACTION SYSTEM INSTALLED AND OPERATED FOR SEVERAL YEARS. SYSTEM CURRENTLY INACTIVE. WILL CONFIRM RELEASE WAS ADEQUATELY CLEANED UP AT THE TIME OF UST UPGRADE/REPLACEMENT. "
Remarks:	"TANK TEST FAILURE AT STATION. PIPING TO DISPENSER ISOLATED. SUSPECT PROBLEM WITH MANIFOLD. TO EXCAVATE ISOLATE AND RETEST MONDAY. CONT. ENCOUNTERED IN SOILS SVES INSTALLED AND OPERATING."

All TTF:

Facility ID:	9209709
Spill Number:	9209709
Spill Tank Test:	1540873
Site ID:	74229
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	74229
Operable Unit ID:	976299
Operable Unit:	01
Material ID:	406755
Material Code:	0009

PJ HYDE & SON (Continued) **S103824449**

Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

Name:	HYDE FUEL
Address:	171 BROADWAY
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9406734 / 1994-08-17
Facility ID:	9406734
Site ID:	74233
Spill Date:	1994-08-17
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C4
Cleanup Ceased:	1994-08-17
SWIS:	1700
Investigator:	RDHUYCK
Referred To:	Not reported
Reported to Dept:	1994-08-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1994-08-18
Spill Record Last Update:	1994-12-16
Spiller Name:	Not reported
Spiller Company:	HYDE FUELS
Spiller Address:	171 BROADWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	69718
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RH "
Remarks:	"DRIVER OVERFILLED UST DIESEL TANK AT FACILITY. RP IN PROCESS OF CLEANING UP RELEASE."

All Materials:

Site ID:	74233
Operable Unit ID:	1001136
Operable Unit:	01
Material ID:	558698
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum

PJ HYDE & SON (Continued) **S103824449**

Quantity:	2.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	HYDE FUELS
Address:	171 BROADWAY
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9407184 / 1994-08-26
Facility ID:	9407184
Site ID:	74234
Spill Date:	1994-08-26
Spill Cause:	Tank Overfill
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C4
Cleanup Ceased:	1994-08-26
SWIS:	1700
Investigator:	RDHUYCK
Referred To:	Not reported
Reported to Dept:	1994-08-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-08-29
Spill Record Last Update:	1994-12-16
Spiller Name:	Not reported
Spiller Company:	HYDE FUEL
Spiller Address:	171 BROADWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	69718
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RH "
Remarks:	"LOADING RACK - OVERFILL, SPEEDY DRY APPLIED AND CLEANED UP."

All Materials:

Site ID:	74234
Operable Unit ID:	1004624
Operable Unit:	01
Material ID:	380198
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Resource Affected:	Soil

PJ HYDE & SON (Continued) **S103824449**

Oxygenate:	Not reported
Name:	PASSENGER VEHICLE OVERFIL
Address:	171 BROADWAY
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9814305 / 1999-03-01
Facility ID:	9814305
Site ID:	74240
Spill Date:	1999-02-28
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	1700
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1999-02-28
CID:	382
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1999-02-28
Spill Record Last Update:	1999-03-04
Spiller Name:	TOM HYDE
Spiller Company:	HYDE FUEL
Spiller Address:	BROADWAY
Spiller County:	001
Spiller Contact:	TOM HYDE
Spiller Phone:	(518) 871-3151
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	69718
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM 02/28/99: Spill from overfill of passenger vehicle. Minor amound made it to catch basin. RFC: Minor spill, Hyde Fuel performed cleanup. "
Remarks:	"TRUCK TANK OVERFILLED WHILE FILLING IT FOR A DELIVERY. CLEANED UP BY HYDE FUEL CREWS."

All Materials:

Site ID:	74240
Operable Unit ID:	1075349
Operable Unit:	01
Material ID:	311002
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Resource Affected:	Soil
Oxygenate:	Not reported

PJ HYDE & SON (Continued) **S103824449**

Name:	HYDE MOBIL MART
Address:	171 BROADWAY
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9903373 / 1999-07-08
Facility ID:	9903373
Site ID:	74241
Spill Date:	1999-06-23
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	1700
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1999-06-23
CID:	371
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1999-06-23
Spill Record Last Update:	2000-01-19
Spiller Name:	Not reported
Spiller Company:	DRIVER - NIAGARA MOHAWK
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	TERRY COOK
Spiller Phone:	(518) 891-3151
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	69718
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM RFC: Minor spill, Hyde Fuel performed cleanup. "
Remarks:	"Customer overfilled tank of van -- clean up complete."

All Materials:

Site ID:	74241
Operable Unit ID:	1082300
Operable Unit:	01
Material ID:	303297
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	HYDE FUEL COMPANY
Address:	171 BROADWAY STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	8908152 / 1989-11-16

PJ HYDE & SON (Continued) **S103824449**

Facility ID:	8908152
Site ID:	157113
Spill Date:	1989-11-16
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	Not reported
Cleanup Ceased:	1989-11-16
SWIS:	1700
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1989-11-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-11-16
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	HYDE FUEL
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	132878
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM "
Remarks:	"TRUCK OVERFILL, USED SPEEDI-DRY FOR CLEANUP. MM-SPILL CONTAINED ON PAVEMENT, HYDE TO STORE SPEEDI-DRY IN 55 GALLON DRUM UNTIL PROPER DISPOSAL ARRANGED."

All Materials:

Site ID:	157113
Operable Unit ID:	935613
Operable Unit:	01
Material ID:	444913
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Resource Affected:	Soil
Oxygenate:	Not reported

SPILLS:

Name:	HYDE MOBIL
Address:	171 BROADWAY STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9002192 / 1990-05-25

PJ HYDE & SON (Continued) **S103824449**

Facility ID:	9002192
Facility Type:	ER
DER Facility ID:	132878
Site ID:	157114
DEC Region:	5
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	1700
Spill Date:	1990-05-25
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1990-05-25
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	1990-05-25
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1990-05-29
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	HYDE FUEL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM "
Remarks:	"NOZZLE AND HOSE SEPARATED WHILE CUSTOMER PUMPING. CLEANED UP WITH SPEEDI-DRY, DID NOT LEAVE PUMP ISLAND AREA. REPLACED HOSE, NO FURTHER ACTION NEEDED."

All Materials:

Site ID:	157114
Operable Unit ID:	942051
Operable Unit:	01
Material ID:	436950
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	2.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	HYDE FUEL TERMINAL
Address:	171 BROADWAY STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9100001 / 1991-04-09
Facility ID:	9100001
Facility Type:	ER
DER Facility ID:	132878

PJ HYDE & SON (Continued) **S103824449**

Site ID:	157115
DEC Region:	5
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	1700
Spill Date:	1991-03-31
Investigator:	RDHUYCK
Referred To:	Not reported
Reported to Dept:	1991-03-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	1991-04-09
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1991-04-09
Spill Record Last Update:	1992-09-02
Spiller Name:	C: BOB JONES
Spiller Company:	HYDE FUEL COMPANY
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RH/MM "
Remarks:	"HOSE BLEW OFF TRUCK, FUEL SPILLED ONTO GROUND, SPEEDI-DRY APPLIED. 4/1-RH ON SITE TO INSPECT, SPEEDI-DRY PICKED UP, SOME CONTAMINATED SOIL LOCATED, ADVISED TO SCRAPE AND PICK UP."

All Materials:

Site ID:	157115
Operable Unit ID:	950555
Operable Unit:	01
Material ID:	426214
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	AT TERMINAL
Address:	171 BROADWAY STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9100542 / 1991-04-14
Facility ID:	9100542
Facility Type:	ER
DER Facility ID:	132878
Site ID:	157116
DEC Region:	5
Spill Cause:	Equipment Failure

PJ HYDE & SON (Continued) **S103824449**

Spill Class:	Not reported
SWIS:	1700
Spill Date:	1991-04-14
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1991-04-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	1991-04-14
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1991-04-18
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	HYDE FUEL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM "
Remarks:	"GASGET ON PIPELINE BROKE, SPEEDI DRY APPLIED, WOULD LIKE CALLBACK. MM CONTACTED BJ @ 1630, PIPELINE FROM AST, DELIVERY TRUCK LUCKILY NOTICED PROBLEM, 25G SPILLED/CONTAINED/CLEANED UP IN DIKE."

All Materials:

Site ID:	157116
Operable Unit ID:	954074
Operable Unit:	01
Material ID:	426730
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	HYDE FUEL-BROADWAY
Address:	171 BROADWAY STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9112241 / 1992-03-03
Facility ID:	9112241
Facility Type:	ER
DER Facility ID:	132878
Site ID:	157117
DEC Region:	5
Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	1700
Spill Date:	1992-02-29

PJ HYDE & SON (Continued) **S103824449**

Investigator:	RBMULVEY
Referred To:	Not reported
Reported to Dept:	1992-02-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	1992-03-03
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-04-03
Spill Record Last Update:	1993-04-03
Spiller Name:	Not reported
Spiller Company:	HYDE FUEL COMPANY
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RM "
Remarks:	"CUSTOMER DROVE OVER HOSE, APPLIED SPEEDI-DRY, PICKED UP CONTAMINATED SNOW. 3/2-RM ON SITE, PROBLEM PICKED UP, NO FURTHER ACTION NECESSARY." Not reported

All Materials:

Site ID:	157117
Operable Unit ID:	965845
Operable Unit:	01
Material ID:	417222
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	HYDE FUEL
Address:	171 BROADWAY STREET
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9112914 / 1992-03-19
Facility ID:	9112914
Facility Type:	ER
DER Facility ID:	132878
Site ID:	157118
DEC Region:	5
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	1700
Spill Date:	1992-03-19
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1992-03-19

PJ HYDE & SON (Continued) **S103824449**

CID:	Not reported
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	1992-03-19
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-03-24
Spill Record Last Update:	1998-03-27
Spiller Name:	Not reported
Spiller Company:	UNKNOWN CUSTOMER
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM "
Remarks:	"CUSTOMER FILLED CAR WITH $5 GAS, PROMPTLY LEAKED OUT, SPEEDI-DRY APPLIED AND PICKED UP, ON PAVEMENT ONLY."

All Materials:

Site ID:	157118
Operable Unit ID:	963529
Operable Unit:	01
Material ID:	414459
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	PJ HYDE & SON
Address:	171 BROADWAY
City,State,Zip:	SARANAC LAKE, NY 12983
Spill Number/Closed Date:	0550330 / 2017-02-27
Facility ID:	0550330
Facility Type:	ER
DER Facility ID:	38859
Site ID:	346504
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	1746
Spill Date:	2005-05-24
Investigator:	BXHANKIN
Referred To:	Not reported
Reported to Dept:	2005-05-24
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	Responsible Party

PJ HYDE & SON (Continued) **S103824449**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2005-05-24
Spill Record Last Update:	2017-03-23
Spiller Name:	THOMAS HYDE
Spiller Company:	PJ HYDE & SON
Spiller Address:	171 BROADWAY
Spiller Company:	001
Contact Name:	THOMAS HYDE
DEC Memo:	"2/27/17: closure report received. NFA required. 4/28/06: BH contacted NTS to find out what is happening. System has not been started up yet."
Remarks:	"Routine site assessment performed at the facility. Laboratory analysis results identified petroleum contamination in excess of standards in groundwater."

All Materials:

Site ID:	346504
Operable Unit ID:	1104276
Operable Unit:	01
Material ID:	584448
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Resource Affected:	Soil, Groundwater
Oxygenate:	Not reported

Site ID:	346504
Operable Unit ID:	1104276
Operable Unit:	01
Material ID:	584447
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Resource Affected:	Soil, Groundwater
Oxygenate:	Not reported

Name:	HYDE FUEL
Address:	171 BROADWAY
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	8802920 / 1988-07-01
Facility ID:	8802920
Facility Type:	ER
DER Facility ID:	305761
Site ID:	74226

PJ HYDE & SON (Continued) **S103824449**

DEC Region:	5
Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	1746
Spill Date:	1988-07-01
Investigator:	RDHUYCK
Referred To:	Not reported
Reported to Dept:	1988-07-01
CID:	Not reported
Water Affected:	SARANAC RIVER
Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	Responsible Party
Cleanup Ceased:	1988-07-01
Cleanup Meets Std:	True
Last Inspection:	1988-07-01
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1988-07-05
Spill Record Last Update:	2005-11-17
Spiller Name:	Not reported
Spiller Company:	HYDE FUEL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"OVERFILL AT FUEL TRANSFER TO TANK TRUCK, INITAILLY ON PAVEMENT, SOME WASHED DOWN SEWER DURING RAINSTORM."

All Materials:

Site ID:	74226
Operable Unit ID:	920124
Operable Unit:	01
Material ID:	458481
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

Name:	HYDE FUEL COMPANY
Address:	171 BROADWAY
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	8809659 / 1989-07-19
Facility ID:	8809659
Facility Type:	ER
DER Facility ID:	69718
Site ID:	74227
DEC Region:	5
Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	1700
Spill Date:	1989-03-15

PJ HYDE & SON (Continued) **S103824449**

Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1989-03-15
CID:	Not reported
Water Affected:	SARANAC RIVER
Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	DEC
Cleanup Ceased:	1989-07-19
Cleanup Meets Std:	True
Last Inspection:	1989-07-19
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1989-03-16
Spill Record Last Update:	1989-07-28
Spiller Name:	C: TOM HYDE
Spiller Company:	HYDE FUEL COMAPNY
Spiller Address:	171 BROADWAY STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM/AS 03/15/89: SPILLER CLEANING WITH BOOMS. NUMEROUS AREAS NOTED WHERE CONTAMINATED SOIL EVIDENT. 07/19/89: NO SIGN OF ANY PROBLEM IN OR AROUND DIKE AREA. NO FURTHER ACTION NEEDED. 10/03/95: This is additional information about material spilled from the translation of the old spill file: ANTI-FREEZE, PETRO."
Remarks:	"CONTAMINATION EVIDENT THROUGHTOUT AREA DUE TO SPRING THAW. (WASTE OIL FLOATING IN WATER IN DIKE AREA, WASTE OIL & ANTIFREEZE LEAKING FROM 55 GAL. DRUMS, SHEEN APPARENT THROUGHOUT FACILITY."

All Materials:

Site ID:	74227
Operable Unit ID:	925921
Operable Unit:	01
Material ID:	450841
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

Name:	HYDE FUEL COMPANY
Address:	171 BROADWAY
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	8904835 / 1989-08-07
Facility ID:	8904835
Facility Type:	ER
DER Facility ID:	69718
Site ID:	74228
DEC Region:	5
Spill Cause:	Human Error

PJ HYDE & SON (Continued) **S103824449**

Spill Class:	Not reported
SWIS:	1700
Spill Date:	1989-08-07
Investigator:	RDHUYCK
Referred To:	Not reported
Reported to Dept:	1989-08-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	1989-08-07
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1989-08-15
Spill Record Last Update:	1998-03-27
Spiller Name:	Not reported
Spiller Company:	BAY VIEW DAIRY
Spiller Address:	CUMBERLAND HEAD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RH "
Remarks:	"DRIVER LEFT HYDE FEUL WITHOUT SECURING FUEL CAP. SEVERAL GALLONS SPILLED ONTO PARKING LOT. HYDE FUEL CLEANED UP."

All Materials:

Site ID:	74228
Operable Unit ID:	932589
Operable Unit:	01
Material ID:	448865
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	HYDE FUEL
Address:	171 BROADWAY
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9302220 / 1994-11-04
Facility ID:	9302220
Facility Type:	ER
DER Facility ID:	69718
Site ID:	74230
DEC Region:	5
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1700
Spill Date:	1993-05-17
Investigator:	MPMCLEAN

PJ HYDE & SON (Continued) **S103824449**

Referred To:	Not reported
Reported to Dept:	1993-05-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	Responsible Party
Cleanup Ceased:	1993-05-17
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-05-26
Spill Record Last Update:	1996-06-03
Spiller Name:	Not reported
Spiller Company:	HYDE FUEL STORAGE TERMIN
Spiller Address:	171 BROADWAY
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM 5/17/93: FURTHER CONTAMINATED SOIL IS ALSO STOCKPILED ON SITE. TO SEND LETTER REGARDING TREATING CONTAMINATED SOIL - PREVENTING FUTURE SPILL INCIDENTS/REPLACING CRUSHER RUN WITH CEMENT, ETC. RFC: Small surface spill adequately cleaned up. "
Remarks:	"SUCTION HOSE RUPTURED DURING OFF LOADING. USED ABSORBENTS DRUMMED UP. SPILLED ON CRUSHER RUN. MM ON SITE 5/18 @ 1000, MET WITH TOM HYDE, TERRY COOK."

All Materials:

Site ID:	74230
Operable Unit ID:	980656
Operable Unit:	01
Material ID:	399356
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	HYDE FUEL
Address:	171 BROADWAY
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9306247 / 1993-08-23
Facility ID:	9306247
Facility Type:	ER
DER Facility ID:	69718
Site ID:	74231
DEC Region:	5
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	1700

PJ HYDE & SON (Continued) **S103824449**

Spill Date:	1993-08-21
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1993-08-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	1993-08-23
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-08-24
Spill Record Last Update:	1996-01-09
Spiller Name:	Not reported
Spiller Company:	MR. BILLS TRANSIT
Spiller Address:	640 E 55TH STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM RFC: 8/23/93 - Site adequately cleaned up."
Remarks:	"DRIVER WAS FILLING UP BUS UNATTENDED AND OVERFILLED. THEY CONTAINED BY SPEEDY DRY AND WILL CLEAN UP AND DISPOSE OF."

All Materials:

Site ID:	74231
Operable Unit ID:	984394
Operable Unit:	01
Material ID:	396132
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Click this hyperlink while viewing on your computer to access
8 additional NY SPILL: record(s) in the EDR Site Report.

T115 **JOHN'S SUNOCO - FORMER** **LTANKS** **S100160941**
NNW **172 BROADWAY ST.** **NY Spills** **N/A**
1/4-1/2 **SARANAC LAKE, NY**
0.446 mi.
2355 ft. **Site 2 of 2 in cluster T**

Relative: LTANKS:
Higher

Name:	PARISH ENERGY CORP.
Address:	172 BROADWAY
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	8705769 / 1988-12-14
Facility ID:	8705769

Actual:
1562 ft.

JOHN'S SUNOCO - FORMER (Continued) **S100160941**

Site ID:	157299
Spill Date:	1987-10-08
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	1988-12-14
SWIS:	1700
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1987-10-08
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	Tank Tester
Last Inspection:	1987-11-23
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1980-01-01
Spill Record Last Update:	1998-10-13
Spiller Name:	Not reported
Spiller Company:	PARISH ENERGY CORP.
Spiller Address:	172 BROADWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	133033
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM / / : THEY WANTED TO LEAVE TANK IN GROUND UNTIL SPRING, BUT RW TOLD HIM TO REMOVE IT. HE WILL CALL 11/30 IF HE FINDS SOMEONE TO REMOVE IT. "
Remarks:	"4 K TANK SYSTEM FAILED PETRO TITE AT APP. 1 GPH (POSSIBLE VAPOR POCKET) OR GROSS LEAK - TO REMOVE PRODUCT AND INVESTIGATE FURTHER. TANK REMOVED AS PER AS."

All TTF:

Facility ID:	8705769
Spill Number:	8705769
Spill Tank Test:	1531863
Site ID:	157299
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

JOHN'S SUNOCO - FORMER (Continued) **S100160941**

Site ID:	157299
Operable Unit ID:	909607
Operable Unit:	01
Material ID:	468345
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

SPILLS:

Name:	JOHN'S SUNOCO - FORMER
Address:	172 BROADWAY ST.
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9207184 / 1994-06-21
Facility ID:	9207184
Facility Type:	ER
DER Facility ID:	133953
Site ID:	158520
DEC Region:	5
Spill Cause:	Unknown
Spill Class:	D3
SWIS:	1700
Spill Date:	1992-09-21
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1992-09-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	DEC
Cleanup Ceased:	1994-06-21
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1992-09-22
Spill Record Last Update:	1995-12-01
Spiller Name:	Not reported
Spiller Company:	PARISH ENERGY FUEL INC.
Spiller Address:	4254 NO. RAILROAD ST.
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM/SL 11/12/93: GWI RECEIVED FROM OPTEC. QUARTERLY SAMPLING OF MONITORING WELLS TO BE PERFORMED. 04/30/94: LETTER SENT TO PARISH FUELS REQUESTING ADDITIONAL INVESTIGATION (GWI). 06/21/94: LOW LEVELS ONLY PRESENT IN MONITORING WELLS, NO FURTHER ACTION NEEDED. RFC: GWI found low level contaminants. No further action

JOHN'S SUNOCO - FORMER (Continued) **S100160941**

necessary. "
Remarks: "CONTAMINATED SOIL ENCOUNTERED DURING TANK REMOVAL (3-4K, 2-1K), SOME SPILLAGE ALSO AS RESULT OF PIPING, PARISH IS TANKING SAMPLES FROM TANK HOLES."

All TTF:
Facility ID: 9207184
Spill Number: 9207184
Spill Tank Test: 1540599
Site ID: 158520
Tank Number: 004
Tank Size: 0
Material: Not reported
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

Facility ID: 9207184
Spill Number: 9207184
Spill Tank Test: 1540600
Site ID: 158520
Tank Number: 002
Tank Size: 0
Material: Not reported
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

Facility ID: 9207184
Spill Number: 9207184
Spill Tank Test: 1540601
Site ID: 158520
Tank Number: 003
Tank Size: 0
Material: Not reported
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills

JOHN'S SUNOCO - FORMER (Continued) **S100160941**

Last Modified Date: Not reported

All Materials:
Site ID: 158520
Operable Unit ID: 974175
Operable Unit: 01
Material ID: 407843
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

---

116 **DUPREE RESIDENCE** **LTANKS** **S103558392**
ESE **LAKE FLOWER AVE** **N/A**
1/4-1/2 **SARANAC LAKE, NY**
0.465 mi.
2457 ft.

Relative:
Higher

Actual:
1535 ft.

LTANKS:
Name: DUPREE RESIDENCE
Address: LAKE FLOWER AVE
City,State,Zip: SARANAC LAKE, NY
Spill Number/Closed Date: 9845038 / 1998-12-16
Facility ID: 9845038
Site ID: 130116
Spill Date: 1998-10-01
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: A1
Cleanup Ceased: Not reported
SWIS: 1600
Investigator: MPMCLEAN
Referred To: Not reported
Reported to Dept: 1998-11-11
CID: Not reported
Water Affected: LAKE FLOWER
Spill Notifier: Citizen
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1998-11-12
Spill Record Last Update: 1998-12-16
Spiller Name: Not reported
Spiller Company: MILDRED DUPREE
Spiller Address: 5 WINONA
Spiller County: 001
Spiller Contact: MILDRED DUPREE
Spiller Phone: (518) 891-2441
Spiller Extention: Not reported

DUPREE RESIDENCE (Continued) **S103558392**

DEC Region: 5
DER Facility ID: 112123
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM 11/12/98: DOW notified regarding sanitary sewage flowing into Lake Flower. 11/13/98: MM checked location, no evidence of sheen/product in lake. Sewage also not evident. MM will recheck location. 12/15/98: No further complaints at location. RFC: Investigation found no spill. "
Remarks: "Caller advises that the 275 UST in the garage of the residence failed. Tank was filled in October and a short time later the tank was empty. Oil now showing up in Lake Flower. Also, sanitary sewage is flowing out from vent pipe behind residence and flowing into the lake. "

All Materials:
Site ID: 130116
Operable Unit ID: 1074011
Operable Unit: 01
Material ID: 309169
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 275.00
Units: G
Recovered: .00
Resource Affected: Surface Water
Oxygenate: Not reported

U117 **NO COUNTRY CHRISTIAN CTR** **LTANKS** **S103238437**
ESE **212 LAKE FLOWER AV** **N/A**
1/4-1/2 **SARANAC LAKE, NY**
0.468 mi.
2470 ft. **Site 1 of 3 in cluster U**

Relative:
Higher

Actual:
1531 ft.

LTANKS:
Name: NO COUNTRY CHRISTIAN CTR
Address: 212 LAKE FLOWER AV
City,State,Zip: SARANAC LAKE, NY
Spill Number/Closed Date: 9803041 / 1998-06-22
Facility ID: 9803041
Site ID: 271172
Spill Date: 1998-06-08
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 1600
Investigator: RDHUYCK
Referred To: Not reported
Reported to Dept: 1998-06-08
CID: 211
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True

NO COUNTRY CHRISTIAN CTR (Continued) **S103238437**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-06-08
Spill Record Last Update:	1999-07-27
Spiller Name:	FACILITY MANAGER
Spiller Company:	NO COUNTRY CHRISTIAN CTR
Spiller Address:	212 LAKE FLOWER AV
Spiller County:	001
Spiller Contact:	FACILITY MANAGER
Spiller Phone:	(518) 891-3255
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	220719
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RH 06/10/98: Letter sent to facility advising them to repair and retest or close. 06/16/98: RH onsite approximately 1pm following removal of UST. Two soil samples were collected from beneath the storage tank. Samples screened with HNu and exhibited no response. No contamination encountered. Closed."
Remarks:	"2500 GAL FAILED TIGHTNESS TEST."

All TTF:

Facility ID:	9803041
Spill Number:	9803041
Spill Tank Test:	1545961
Site ID:	271172
Tank Number:	003
Tank Size:	2500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	271172
Operable Unit ID:	1060865
Operable Unit:	01
Material ID:	321367
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	WILL RODGERS CHRST. CENTR

NO COUNTRY CHRISTIAN CTR (Continued) **S103238437**

Address:	212 LAKE FLOWER AVE
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9100066 / 1991-04-02
Facility ID:	9100066
Site ID:	176313
Spill Date:	1991-04-01
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1991-04-02
SWIS:	1700
Investigator:	RBMULVEY
Referred To:	Not reported
Reported to Dept:	1991-04-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	1991-04-02
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-04-09
Spill Record Last Update:	1991-04-09
Spiller Name:	C: NEIL SECOR
Spiller Company:	CHRISTIAN CENTER
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	148187
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RM "
Remarks:	"UNCOVERING VENT LINES TO UPGRADE, DISCOVERED ODORS AND DISCOLORED SOIL, WOULD LIKE DEC TO LOOK AT AND ADVISE. RM ON SITE, NO CONTAMINATION EVIDENT, NO CLEANUP NEEDED."

All Materials:

Site ID:	176313
Operable Unit ID:	953594
Operable Unit:	01
Material ID:	426281
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

U118 **MAIN LINE GARAGE** **LTANKS** **S101174604**
ESE **26 LAKE FLOWER AVENUE** **N/A**
1/4-1/2 **SARANAC LAKE, NY**
0.471 mi.
2488 ft. **Site 2 of 3 in cluster U**

Relative:
Higher

Actual:
1530 ft.

LTANKS:

Name:	MAIN LINE GARAGE
Address:	26 LAKE FLOWER AVENUE
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9406571 / 1996-08-22
Facility ID:	9406571
Site ID:	106092
Spill Date:	1994-08-08
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	1700
Investigator:	RDHUYCK
Referred To:	Not reported
Reported to Dept:	1994-08-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1994-08-16
Spill Record Last Update:	1996-08-22
Spiller Name:	Not reported
Spiller Company:	PJ HYDE & SON INC.
Spiller Address:	171 BROADWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	93515
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RH 8/22/96: Site does not meet standards. However, concentrations are such that additional impacts are not likely. Further remediation may occur during future site development."
Remarks:	"ROUTINE TANK CLOSURE AT FACILITY. EXCAVATED SOILS HIGHLY CONT. (100-300 PPM HNU). SOME FREE PRODUCT DISCOVERED ON GROUNDWATER SURFACE."

All Materials:

Site ID:	106092
Operable Unit ID:	1003947
Operable Unit:	01
Material ID:	379607
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L

MAIN LINE GARAGE (Continued) **S101174604**

Recovered: .00
Resource Affected: Groundwater
Oxygenate: Not reported

U119 **MADDENS RENTAL PROPERTY** **LTANKS** **S102233833**
ESE **8 LAKE FLOWER AVE** **N/A**
1/4-1/2 **SARANAC LAKE, NY**
0.475 mi.
2509 ft. **Site 3 of 3 in cluster U**

Relative: **Higher**
Actual: **1532 ft.**

LTANKS:

Name:	MADDENS RENTAL PROPERTY
Address:	8 LAKE FLOWER AVE
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9601576 / 1996-04-30
Facility ID:	9601576
Site ID:	194449
Spill Date:	1996-04-30
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	1600
Investigator:	MPMCLEAN
Referred To:	Not reported
Reported to Dept:	1996-04-30
CID:	349
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-05-01
Spill Record Last Update:	1996-05-03
Spiller Name:	Not reported
Spiller Company:	BILL MADDEN
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	162046
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MM RFC: Minor spill, Hyde Fuel cleaning up. "
Remarks:	"odors noted in residence, discovery that 275g abt in basement leaking, hyde fuel cleaning up. mm on site@ 1415, tank pumped out 15 gal lost out tank bottom. concrete floor, most of oil soaked into couch adjacent to tank. speedy dry being used to clean up remaining.house being ventilated. no dec action needed"

All Materials:

Site ID:	194449
Operable Unit ID:	1033133
Operable Unit:	01

MADDENS RENTAL PROPERTY (Continued) **S102233833**

Material ID:	351380
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	15.00
Resource Affected:	Soil
Oxygenate:	Not reported

---

120 SE 1/4-1/2 0.477 mi. 2519 ft. **BIG D** **LTANKS** **S102676658**
87 RIVERSIDE DRIVE **N/A**
SARANAC LAKE, NY

Relative: Higher

Actual: 1555 ft.

LTANKS:

Name:	BIG D
Address:	87 RIVERSIDE DRIVE
City,State,Zip:	SARANAC LAKE, NY
Spill Number/Closed Date:	9311945 / 1994-04-29
Facility ID:	9311945
Site ID:	219724
Spill Date:	1994-01-04
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	1994-04-29
SWIS:	1700
Investigator:	RDHUYCK
Referred To:	Not reported
Reported to Dept:	1994-01-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-01-11
Spill Record Last Update:	1996-01-19
Spiller Name:	Not reported
Spiller Company:	BIG D
Spiller Address:	200 BROADWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	5
DER Facility ID:	181718
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RH RFC: RH investigated 1/4/94. Spill contained at loading rack. No offsite impact. Contaminated material satisfactorily excavated. "
Remarks:	"SHOVELED CONTAM. SNOW, PUT IN GARBAGE CAN. SIPHONED OFF."

BIG D (Continued) **S102676658**

All Materials:

Site ID:	219724
Operable Unit ID:	990561
Operable Unit:	01
Material ID:	390955
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

121
ESE
1/2-1
0.772 mi.
4078 ft.

SARANAC LAKE GAS CO. INC.
PAYVILLE ROAD
SARANAC LAKE, NY 12783

DEL SHWS **S108061175**
N/A

Relative:
Higher

Actual:
1555 ft.

DEL SHWS:

Name:	SARANAC LAKE GAS CO. INC.
Address:	PAYVILLE ROAD
City,State,Zip:	SARANAC LAKE, NY 12783-
Year:	Not reported
Site Code Id:	57075
Site Classification:	Not reported
Region:	5
Epa Id Number:	Not reported
Site Type - Dump:	No
Site Type - Structure:	No
Site Type - Lagoon:	No
Site Type - Landfill:	No
Site Type - Treat Pond:	No
Site Size (Acres):	Not reported
Site Size Comment:	Not reported
Period Assoc/HW Start:	Not reported
Period Assoc/HW End:	Not reported
Lat/Long:	Not reported
Lat/Long Decimal:	Not reported
Lat/Long (dms):	Not reported
Hazardous Waste Code:	516008
Hazard Waste Disposed:	Not reported
Quantity:	Not reported
Air Data Available:	No
SW Std Contravention:	No
GW Std Contravention:	No
Soil Type:	Not reported
Sediment Data Available:	No
GW Std Contravention:	No
DW Std Contravention:	No
SW Std Contravention:	No
Air Stand Contraventions:	No
Legal Action Type:	Not reported
State Legal Action:	No

SARANAC LAKE GAS CO. INC. (Continued) **S108061175**

Federal Legal Action:	No
Enforce Status Code:	Not reported
Remedial Act Proposed:	No
Rem Act Under Design:	No
Rem Act In Progress:	No
Rem Act Completed:	No
Remedial Action Type:	Not reported
Soil Type:	Not reported
Depth To Groundwater:	Not reported
Owner Name:	Not reported
Owner Address:	Not reported
Owner City,St,Zip:	Not reported
Owner Phone:	Not reported
Owner Contact Name:	Not reported
Owner During Disposal:	Not reported
Owner During Use:	Not reported
Operator Name:	Not reported
Operator Address:	Not reported
Operator City,St,Zip:	Not reported
Operator Phone:	Not reported
Operator Contact Name:	Not reported
Oper During Disposal:	Not reported
Site Type:	Not reported
HW Disposal Period:	Not reported
Analytical Data Available:	Not reported
Applicable Std Exceeded:	Not reported
Geotech Info:	Not reported
Depth To Groundwater:	Not reported
Status:	Not reported
Nature Of Action:	Not reported
Env Prob Assessment:	Not reported
Site Description:	Not reported
Confirmed HW:	Not reported
Environment Assesment:	Not reported
Health Assesment:	Not reported
Disposal Start Date:	Not reported
Disposal Term Date:	Not reported
Air Violation:	Not reported
Groundwater Violation:	Not reported
Drink Water Violation:	Not reported
Surface Water Violation:	Not reported
Legal New York State:	Not reported
Legal Federal:	Not reported
Legal State:	Not reported
Remedial Action Active:	Not reported
Remedial Action Done:	Not reported
NPL Status:	Not reported
Count Operator:	Not reported
Count Owner:	Not reported
NYTM X:	Not reported
NYTM Y:	Not reported
Co Name:	Not reported
Co Addr:	Not reported
Operator Addr:	Not reported
Operator Addr 2:	Not reported
Operator Addr 3:	Not reported
Operator Addr 4:	Not reported

SARANAC LAKE GAS CO. INC. (Continued) **S108061175**

HWDP From:	Not reported
From To:	Not reported
Assessment of Health:	Not reported
Description:	This former MGP facility was used for manufacturing lighting gas for the Village of Saranac Lake. There are MGP wastes confirmed in Brandy Brook and Pontiac Bay (downstram of this site) which most likely originated at this site. The site is currently a propane gas site and is in a residential setting. It is included in the inventory of hazardous substance waste disposal sites (ID # HS5006). Investigation is needed.
Record Added Date:	2002-02-21 11:39:00
Record Updated Date:	2007-05-11 12:04:00
Env Assessment:	Elevated levels of PAHs have been found in the nearby Brandy Brook and Pontiac Bay.
HW Disposed/Quantity:	Not reported
Assess/Env Prog:	Not reported
Assess/Health Prob:	Not reported
Site Description:	Not reported

Count: 6 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
SARANAC LAKE	S106471486	SARANAC QUARRY	BLOOMINGDALE ROAD		LTANKS
SARANAC LAKE	S102676575	SARANAC LAKE BUS GARAGE	BUS GARG, BLOOMINGDALE RD		LTANKS
SARANAC LAKE	S102118367	TRUDEAU BUILDING	CHURCH STREET		LTANKS, NY Spills
SARANAC LAKE	S100494937	ADELPHIA CABLE	LAKE COLBY DRIVE		LTANKS
SARANAC LAKE	S100161110	NIAGARA MOHAWK	LAKE COLBY DR.		LTANKS
SARANAC LAKE	S100161463	SARANAC LAKE	RIVER STREET		LTANKS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/02/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 15

Source: EPA
Telephone: N/A
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 5
Telephone 312-886-6686

EPA Region 10
Telephone 206-553-8665

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6774

EPA Region 9
Telephone: 415-947-4246

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/02/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 15

Source: EPA
Telephone: N/A
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Lists of Federal Delisted NPL sites

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/02/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 15

Source: EPA
Telephone: N/A
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 03/26/2023
Date Data Arrived at EDR: 03/28/2023
Date Made Active in Reports: 05/30/2023
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 06/23/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/02/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 15

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Quarterly

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/02/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 15

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Quarterly

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 03/06/2023
Date Data Arrived at EDR: 03/09/2023
Date Made Active in Reports: 03/20/2023
Number of Days to Update: 11

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

Lists of Federal RCRA TSD facilities

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 03/06/2023
Date Data Arrived at EDR: 03/09/2023
Date Made Active in Reports: 03/20/2023
Number of Days to Update: 11

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

Lists of Federal RCRA generators

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/06/2023
Date Data Arrived at EDR: 03/09/2023
Date Made Active in Reports: 03/20/2023
Number of Days to Update: 11

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 03/06/2023
Date Data Arrived at EDR: 03/09/2023
Date Made Active in Reports: 03/20/2023
Number of Days to Update: 11

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/06/2023
Date Data Arrived at EDR: 03/09/2023
Date Made Active in Reports: 03/20/2023
Number of Days to Update: 11

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 02/08/2023
Date Data Arrived at EDR: 02/09/2023
Date Made Active in Reports: 05/02/2023
Number of Days to Update: 82

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 05/23/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 02/20/2023
Date Data Arrived at EDR: 02/21/2023
Date Made Active in Reports: 05/02/2023
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/23/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 02/20/2023
Date Data Arrived at EDR: 02/21/2023
Date Made Active in Reports: 05/02/2023
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/23/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 03/20/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 05/30/2023
Number of Days to Update: 70

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

Lists of state- and tribal hazardous waste facilities

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 02/06/2023
Date Data Arrived at EDR: 02/07/2023
Date Made Active in Reports: 04/24/2023
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/05/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Annually

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 03/31/2023
Date Data Arrived at EDR: 04/04/2023
Date Made Active in Reports: 06/21/2023
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

Lists of state and tribal leaking storage tanks

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land

A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 04/19/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 05/08/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 04/25/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 04/19/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/14/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 02/06/2023
Date Data Arrived at EDR: 02/07/2023
Date Made Active in Reports: 02/09/2023
Number of Days to Update: 2

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 05/05/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Lists of state and tribal registered storage tanks

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 03/08/2023
Date Data Arrived at EDR: 03/09/2023
Date Made Active in Reports: 05/30/2023
Number of Days to Update: 82

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 02/14/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 06/02/2023
Number of Days to Update: 73

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 02/14/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 06/02/2023
Number of Days to Update: 73

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 02/14/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 06/02/2023
Number of Days to Update: 73

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 02/14/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 06/02/2023
Number of Days to Update: 73

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 04/19/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 04/25/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/14/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

TANKS: Storage Tank Faciliy Listing
This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 02/14/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 06/02/2023
Number of Days to Update: 73
Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

RES DECL: Restrictive Declarations Listing
A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 09/27/2022
Date Data Arrived at EDR: 12/12/2022
Date Made Active in Reports: 03/06/2023
Number of Days to Update: 84
Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 06/14/2023
Next Scheduled EDR Contact: 09/25/2023
Data Release Frequency: Varies

ENV RES DECL: Environmental Restrictive Declarations
The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 09/27/2022
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 06/02/2023
Number of Days to Update: 73
Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 06/12/2023
Next Scheduled EDR Contact: 09/25/2023
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls
Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 02/06/2023
Date Data Arrived at EDR: 02/07/2023
Date Made Active in Reports: 04/24/2023
Number of Days to Update: 76
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 05/05/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls
Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 02/06/2023
Date Data Arrived at EDR: 02/07/2023
Date Made Active in Reports: 04/24/2023
Number of Days to Update: 76
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 05/05/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Quarterly

Lists of state and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Agreements
New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 02/06/2023
Date Data Arrived at EDR: 02/07/2023
Date Made Active in Reports: 04/24/2023
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 05/05/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Semi-Annually

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 06/13/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

VCP NYC: Voluntary Cleanup Program Listing NYC
New York City voluntary cleanup program sites.

Date of Government Version: 03/06/2023
Date Data Arrived at EDR: 03/08/2023
Date Made Active in Reports: 05/25/2023
Number of Days to Update: 78

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 06/06/2023
Next Scheduled EDR Contact: 09/18/2023
Data Release Frequency: Varies

Lists of state and tribal brownfield sites

BROWNFIELDS: Brownfields Site List
A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 02/06/2023
Date Data Arrived at EDR: 02/07/2023
Date Made Active in Reports: 04/24/2023
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 05/05/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing
In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 02/06/2023
Date Data Arrived at EDR: 02/07/2023
Date Made Active in Reports: 04/24/2023
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/05/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 04/06/2023
Date Data Arrived at EDR: 04/13/2023
Date Made Active in Reports: 04/19/2023
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 06/08/2023
Next Scheduled EDR Contact: 09/25/2023
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 03/31/2023
Date Data Arrived at EDR: 04/04/2023
Date Made Active in Reports: 06/21/2023
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 02/27/2018
Date Data Arrived at EDR: 04/06/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 06/05/2023
Next Scheduled EDR Contact: 09/18/2023
Data Release Frequency: No Update Planned

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 04/19/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 07/11/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 04/27/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 05/22/2023
Date Data Arrived at EDR: 05/23/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 48

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 05/23/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 02/06/2023
Date Data Arrived at EDR: 02/07/2023
Date Made Active in Reports: 04/24/2023
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/05/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 05/22/2023
Date Data Arrived at EDR: 05/23/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 48

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 05/23/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Quarterly

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information

Lien information from the Oil Spill Fund.

Date of Government Version: 02/01/2023
Date Data Arrived at EDR: 02/02/2023
Date Made Active in Reports: 04/25/2023
Number of Days to Update: 82

Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 04/27/2023
Next Scheduled EDR Contact: 08/14/2023
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/02/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 03/19/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 05/30/2023
Number of Days to Update: 70

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 02/06/2023
Date Data Arrived at EDR: 02/07/2023
Date Made Active in Reports: 02/09/2023
Number of Days to Update: 2

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 05/05/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 03/06/2023
Date Data Arrived at EDR: 03/09/2023
Date Made Active in Reports: 03/20/2023
Number of Days to Update: 11

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 05/08/2023
Date Data Arrived at EDR: 05/16/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 55

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 05/16/2023
Next Scheduled EDR Contact: 08/28/2023
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 06/07/2021
Date Data Arrived at EDR: 07/13/2021
Date Made Active in Reports: 03/09/2022
Number of Days to Update: 239

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 07/10/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 07/30/2021
Date Data Arrived at EDR: 02/03/2023
Date Made Active in Reports: 02/10/2023
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 05/11/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 03/13/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 05/30/2023
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 05/01/2023
Next Scheduled EDR Contact: 08/14/2023
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 05/04/2023
Next Scheduled EDR Contact: 08/14/2023
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 06/14/2022
Date Made Active in Reports: 03/24/2023
Number of Days to Update: 283

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 06/16/2023
Next Scheduled EDR Contact: 09/25/2023
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 02/16/2023
Date Made Active in Reports: 05/02/2023
Number of Days to Update: 75

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 05/19/2023
Next Scheduled EDR Contact: 08/28/2023
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 04/17/2023
Date Data Arrived at EDR: 04/18/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 83

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 04/18/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/02/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 15

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 04/27/2022
Date Data Arrived at EDR: 05/04/2022
Date Made Active in Reports: 05/10/2022
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 06/12/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/02/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 15

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 08/14/2023
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 03/20/2023
Date Data Arrived at EDR: 04/04/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 66

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 07/07/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 03/15/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 05/30/2023
Number of Days to Update: 70
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 07/12/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 04/14/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 87
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 05/25/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 05/25/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 05/04/2023
Next Scheduled EDR Contact: 08/14/2023
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 01/02/2020
Date Data Arrived at EDR: 01/28/2020
Date Made Active in Reports: 04/17/2020
Number of Days to Update: 80

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 04/25/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 03/31/2023
Date Data Arrived at EDR: 04/20/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 81

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 03/09/2023
Date Made Active in Reports: 03/20/2023
Number of Days to Update: 11

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 03/03/2023
Date Data Arrived at EDR: 03/03/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 98

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 04/26/2023
Next Scheduled EDR Contact: 08/14/2023
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 08/30/2019
Date Data Arrived at EDR: 11/15/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 74

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 05/24/2023
Next Scheduled EDR Contact: 08/28/2023
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/02/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data
A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

MINES VIOLATIONS: MSHA Violation Assessment Data
Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 04/03/2023
Date Data Arrived at EDR: 04/04/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 66

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Quarterly

US MINES: Mines Master Index File
Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 02/02/2023
Date Data Arrived at EDR: 02/22/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 84

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 05/24/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing
This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 01/07/2022
Date Data Arrived at EDR: 02/24/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 82

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 05/25/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing
Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 05/25/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines
An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 03/17/2023
Date Data Arrived at EDR: 03/17/2023
Date Made Active in Reports: 05/30/2023
Number of Days to Update: 74
Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 06/13/2023
Next Scheduled EDR Contact: 09/18/2023
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 02/02/2023
Date Data Arrived at EDR: 02/28/2023
Date Made Active in Reports: 03/24/2023
Number of Days to Update: 24
Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 05/25/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Quarterly

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 03/25/2023
Date Data Arrived at EDR: 03/31/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 70
Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 06/29/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82
Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 05/17/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Varies

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 11/09/2021
Date Data Arrived at EDR: 10/20/2022
Date Made Active in Reports: 01/10/2023
Number of Days to Update: 82
Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 05/15/2023
Date Data Arrived at EDR: 05/17/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 54
Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 05/17/2023
Next Scheduled EDR Contact: 08/28/2023
Data Release Frequency: Quarterly

PFAS NPL: Superfund Sites with PFAS Detections Information

EPA's Office of Land and Emergency Management and EPA Regional Offices maintain data describing what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment.

Date of Government Version: 06/07/2023
Date Data Arrived at EDR: 06/08/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 1

Source: Environmental Protection Agency
Telephone: 703-603-8895
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS FEDERAL SITES: Federal Sites PFAS Information

Several federal entities, such as the federal Superfund program, Department of Defense, National Aeronautics and Space Administration, Department of Transportation, and Department of Energy provided information for sites with known or suspected detections at federal facilities.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 04/07/2023
Number of Days to Update: 8

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS TSCA: PFAS Manufacture and Imports Information

EPA issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. EPA publishes non-confidential business information (non-CBI) and includes descriptive information about each site, corporate parent, production volume, other manufacturing information, and processing and use information.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 71

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS RCRA MANIFEST: PFAS Transfers Identified In the RCRA Database Listing

To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: PFAS, PFOA, PFOS, PERFL, AFFF, GENX, GEN-X (plus the VT waste codes). These keywords were searched for in the following text fields: Manifest handling instructions (MANIFEST_HANDLING_INSTR), Non-hazardous waste description (NON_HAZ_WASTE_DESCRIPTION), DOT printed information (DOT_PRINTED_INFORMATION), Waste line handling instructions (WASTE_LINE_HANDLING_INSTR), Waste residue comments (WASTE_RESIDUE_COMMENTS).

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 05/02/2023
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS ATSDR: PFAS Contamination Site Location Listing

PFAS contamination site locations from the Department of Health & Human Services, Center for Disease Control & Prevention. ATSDR is involved at a number of PFAS-related sites, either directly or through assisting state and federal partners. As of now, most sites are related to drinking water contamination connected with PFAS production facilities or fire training areas where aqueous film-forming firefighting foam (AFFF) was regularly used.

Date of Government Version: 06/24/2020
Date Data Arrived at EDR: 03/17/2021
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 601

Source: Department of Health & Human Services
Telephone: 202-741-5770
Last EDR Contact: 04/20/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Varies

PFAS WQP: Ambient Environmental Sampling for PFAS

The Water Quality Portal (WQP) is a part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations and individuals submit project details and sampling results to this public repository. The information is commonly used for research and assessments of environmental quality.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 05/02/2023
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS NPDES: Clean Water Act Discharge Monitoring Information

Any discharger of pollutants to waters of the United States from a point source must have a National Pollutant Discharge Elimination System (NPDES) permit. The process for obtaining limits involves the regulated entity (permittee) disclosing releases in a NPDES permit application and the permitting authority (typically the state but sometimes EPA) deciding whether to require monitoring or monitoring with limits.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 04/07/2023
Number of Days to Update: 8

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS ECHO: Facilities in Industries that May Be Handling PFAS Listing

Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 04/03/2023
Number of Days to Update: 4

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS ECHO FIRE TRAINING: Facilities in Industries that May Be Handling PFAS Listing

A list of fire training sites was added to the Industry Sectors dataset using a keyword search on the permitted facilitys name to identify sites where fire-fighting foam may have been used in training exercises. Additionally, you may view an example spreadsheet of the subset of fire training facility data, as well as the keywords used in selecting or deselecting a facility for the subset. as well as the keywords used in selecting or deselecting a facility for the subset. These keywords were tested to maximize accuracy in selecting facilities that may use fire-fighting foam in training exercises, however, due to the lack of a required reporting field in the data systems for designating fire training sites, this methodology may not identify all fire training sites or may potentially misidentify them.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 04/03/2023
Number of Days to Update: 4

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS PART 139 AIRPORT: All Certified Part 139 Airports PFAS Information Listing

Since July 1, 2006, all certified part 139 airports are required to have fire-fighting foam onsite that meet military specifications (MIL-F-24385) (14 CFR 139.317). To date, these military specification fire-fighting foams are fluorinated and have been historically used for training and extinguishing. The 2018 FAA Reauthorization Act has a provision stating that no later than October 2021, FAA shall not require the use of fluorinated AFFF. This provision does not prohibit the use of fluorinated AFFF at Part 139 civilian airports; it only prohibits FAA from mandating its use. The Federal Aviation Administration?s document AC 150/5210-6D - Aircraft Fire Extinguishing Agents provides guidance on Aircraft Fire Extinguishing Agents, which includes Aqueous Film Forming Foam (AFFF).

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 04/03/2023
Number of Days to Update: 4

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

AQUEOUS FOAM NRC: Aqueous Foam Related Incidents Listing

The National Response Center (NRC) serves as an emergency call center that fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. The spreadsheets posted to the NRC website contain initial incident data that has not been validated or investigated by a federal/state response agency. Response center calls from 1990 to the most recent complete calendar year where there was indication of Aqueous Film Forming Foam (AFFF) usage are included in this dataset. NRC calls may reference AFFF usage in the ?Material Involved? or ?Incident Description? fields.

Date of Government Version: 04/27/2023
Date Data Arrived at EDR: 04/27/2023
Date Made Active in Reports: 05/02/2023
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS 2: New York State Inactive Landfill Initiative

A list of landfills that were investigated and the analytical results for PFOA and PFOS for those landfills. These data represent the landfills from the ILI database that were investigated.

Date of Government Version: 11/14/2022
Date Data Arrived at EDR: 01/12/2023
Date Made Active in Reports: 01/23/2023
Number of Days to Update: 11

Source: Department of Environmental Conservation
Telephone: 518-402-9662
Last EDR Contact: 04/27/2023
Next Scheduled EDR Contact: 08/14/2023
Data Release Frequency: Varies

PFAS: PFAS Contamination Site Location Listing

DEC surveyed select businesses, fire departments, fire training centers, bulk storage facilities, airports, and Department of Defense (DoD) facilities. The responses to the survey have helped to determine if these entities used or stored materials containing PFOA/PFOS including AFFF and dispersants used in Teflon coating operations. The results of this survey will be updated periodically as additional responses are received..

Date of Government Version: 01/16/2019
Date Data Arrived at EDR: 05/08/2019
Date Made Active in Reports: 06/24/2019
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9020
Last EDR Contact: 05/04/2023
Next Scheduled EDR Contact: 08/14/2023
Data Release Frequency: Varies

PFAS 3: PFAS Environmental Site Remediation List

Per- and Polyfluoroalkyl Substances (PFAS) are a group of chemicals used to make fluoropolymer coatings and products that resist heat, oil, stains, grease, and water. Fluoropolymer coatings are blends of resins and lubricants used in products such as water-repellent clothing, furniture, adhesives, paint and varnish, food packaging, heat-resistant non-stick cooking surfaces and insulation of electrical wires. Chemicals in this group include perfluorooctanoic acid (PFOA) and perfluorooctane sulfonic acid (PFOS).

Date of Government Version: 02/06/2023
Date Data Arrived at EDR: 02/07/2023
Date Made Active in Reports: 04/25/2023
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9759
Last EDR Contact: 05/05/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Varies

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 02/14/2023
Date Data Arrived at EDR: 02/15/2023
Date Made Active in Reports: 05/09/2023
Number of Days to Update: 83

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 07/12/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing

A listing of coal ash disposal site locations.

Date of Government Version: 03/22/2023
Date Data Arrived at EDR: 03/24/2023
Date Made Active in Reports: 06/07/2023
Number of Days to Update: 75

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 03/06/2023
Date Data Arrived at EDR: 03/08/2023
Date Made Active in Reports: 05/25/2023
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 05/31/2023
Next Scheduled EDR Contact: 09/18/2023
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 12/12/2022
Date Made Active in Reports: 03/07/2023
Number of Days to Update: 85

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 06/13/2023
Next Scheduled EDR Contact: 09/25/2023
Data Release Frequency: Semi-Annually

Financial Assurance 1: Financial Assurance Information Listing

Financial assurance information.

Date of Government Version: 03/27/2023
Date Data Arrived at EDR: 03/29/2023
Date Made Active in Reports: 06/13/2023
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing

A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 07/31/2021
Date Data Arrived at EDR: 01/05/2023
Date Made Active in Reports: 03/24/2023
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 05/31/2023
Next Scheduled EDR Contact: 09/18/2023
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NYC LEAD: Lead-based Paint Testing Results

The results of the inspections for all classrooms serving students under six in applicable buildings. Identifies all classrooms, whether there was observation of peeling paint, and if there was, standard response protocol was followed.

Date of Government Version: 12/31/2022
Date Data Arrived at EDR: 02/01/2023
Date Made Active in Reports: 04/25/2023
Number of Days to Update: 83

Source: New York City Department of Education
Telephone: 212-374-5141
Last EDR Contact: 05/04/2023
Next Scheduled EDR Contact: 08/14/2023
Data Release Frequency: Varies

NYC LEAD 2: Recent Lead Paint Violations

Pursuant to New York City?s Housing Maintenance Code, the Department of Housing Preservation and Development (HPD) issues violations against conditions in rental dwelling units that have been verified to violate the New York City Housing Maintenance Code (HMC) or the New York State Multiple Dwelling Law (MDL). Violations are issued when an inspection verifies that a violation of the HMC or MDL exists. It is closed when the violation is corrected, as observed/verified by HPD or as certified by the landlord.

Date of Government Version: 01/30/2023
Date Data Arrived at EDR: 02/01/2023
Date Made Active in Reports: 04/25/2023
Number of Days to Update: 83

Source: New York City Department of Housing Preservation & Development
Telephone: 212-863-8200
Last EDR Contact: 05/03/2023
Next Scheduled EDR Contact: 08/14/2023
Data Release Frequency: Varies

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/01/2019
Date Data Arrived at EDR: 10/29/2021
Date Made Active in Reports: 01/19/2022
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 04/27/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Quarterly

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 10/20/2022
Date Data Arrived at EDR: 11/09/2022
Date Made Active in Reports: 01/30/2023
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 07/12/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: No Update Planned

VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 01/01/2022
Date Data Arrived at EDR: 02/08/2022
Date Made Active in Reports: 05/06/2022
Number of Days to Update: 87

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 05/11/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Varies

UIC: Underground Injection Control Wells
A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 02/26/2023
Date Data Arrived at EDR: 03/01/2023
Date Made Active in Reports: 05/19/2023
Number of Days to Update: 79

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 05/30/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Quarterly

COOLING TOWERS: Registered Cooling Towers
This data includes the location of cooling towers registered with New York State. The data is self-reported by owners/property managers of cooling towers in service in New York State. In August 2015, the New York State Department of Health released emergency regulations requiring the owners of cooling towers to register them with New York State.

Date of Government Version: 04/04/2023
Date Data Arrived at EDR: 04/12/2023
Date Made Active in Reports: 06/28/2023
Number of Days to Update: 77

Source: Department of Health
Telephone: 518-402-7650
Last EDR Contact: 07/12/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Varies

PCS: Permit Compliance System
PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 07/14/2011
Date Data Arrived at EDR: 08/05/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 55

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: No Update Planned

PCS ENF: Enforcement data
No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

MINES MRDS: Mineral Resources Data System
Mineral Resources Data System

Date of Government Version: 08/23/2022
Date Data Arrived at EDR: 11/22/2022
Date Made Active in Reports: 02/28/2023
Number of Days to Update: 98

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 05/25/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Varies

PFAS TRIS: List of PFAS Added to the TRI
Section 7321 of the National Defense Authorization Act for Fiscal Year 2020 (NDAA) immediately added certain per- and polyfluoroalkyl substances (PFAS) to the list of chemicals covered by the Toxics Release Inventory (TRI) under Section 313 of the Emergency Planning and Community Right-to-Know Act (EPCRA) and provided a framework for additional PFAS to be added to TRI on an annual basis.

Date of Government Version: 06/07/2023
Date Data Arrived at EDR: 06/08/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 1

Source: Environmental Protection Agency
Telephone: 202-566-0250
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

CORTLAND COUNTY:

AST - CORTLAND: Cortland County Storage Tank Listing

A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 04/20/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Quarterly

UST - CORTLAND: Cortland County Storage Tank Listing

A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 04/20/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Quarterly

NASSAU COUNTY:

AST - NASSAU: Registered Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 04/20/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: No Update Planned

AST NCFM: Storage Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 04/20/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Varies

TANKS NASSAU: Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35
Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 04/20/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Varies

UST - NASSAU: Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35
Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 04/20/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: No Update Planned

UST NCFM: Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34
Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 04/20/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Varies

ROCKLAND COUNTY:

AST - ROCKLAND: Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 05/23/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: No Update Planned

UST - ROCKLAND: Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 05/23/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: No Update Planned

SUFFOLK COUNTY:

AST - SUFFOLK: Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 04/20/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: No Update Planned

TANKS SUFFOLK: Storage Tank Database

This county is not included in the state?s database. These are facilities that have no tank information in the storage tank database.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 02/05/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 31

Source: Department of Health Services
Telephone: 631-854-2516
Last EDR Contact: 04/20/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Varies

UST - SUFFOLK: Storage Tank Database

A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 04/20/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

AST - WESTCHESTER: Listing of Storage Tanks

A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 02/09/2023
Date Data Arrived at EDR: 02/16/2023
Date Made Active in Reports: 02/28/2023
Number of Days to Update: 12

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 04/26/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Semi-Annually

UST - WESTCHESTER: Listing of Storage Tanks

A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 02/09/2023
Date Data Arrived at EDR: 02/16/2023
Date Made Active in Reports: 02/28/2023
Number of Days to Update: 12

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 04/26/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Semi-Annually

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 11/16/2022
Date Data Arrived at EDR: 11/16/2022
Date Made Active in Reports: 02/06/2023
Number of Days to Update: 82

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 05/11/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/18/2022
Number of Days to Update: 80

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 05/10/2022
Next Scheduled EDR Contact: 08/28/2023
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 10/28/2019
Date Data Arrived at EDR: 10/29/2019
Date Made Active in Reports: 01/09/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 06/01/2023
Next Scheduled EDR Contact: 09/18/2023
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

APA HQ - PHASE I ESA
13 MAIN STREET
SARANAC LAKE, NY 12983

TARGET PROPERTY COORDINATES

Latitude (North):	44.324429 - 44° 19' 27.94''
Longitude (West):	74.132928 - 74° 7' 58.54''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	569138.9
UTM Y (Meters):	4908056.5
Elevation:	1528 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	14115916 SARANAC LAKE, NY
Version Date:	2019
East Map:	14115876 MCKENZIE MOUNTAIN, NY
Version Date:	2019

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General North

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 1528 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
Not Reported	

Additional Panels in search area:	FEMA Source Type
Not Reported	

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
NOT AVAILABLE	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Precambrian
System:	Precambrian
Series:	Anorthosite
Code:	Ya *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Plutonic and Intrusive Rocks

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name:	BECKET
Soil Surface Texture:	very stony - fine sandy loam
Hydrologic Group:	Class C - Slow infiltration rates. Soils with layers impeding downward movement of water, or soils with moderately fine or fine textures.
Soil Drainage Class:	Well drained. Soils have intermediate water holding capacity. Depth to water table is more than 6 feet.

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: LOW

Depth to Bedrock Min: > 60 inches

Depth to Bedrock Max: > 60 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	2 inches	very stony - fine sandy loam	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 2.00 Min: 0.60	Max: 6.50 Min: 3.60
2	2 inches	31 inches	fine sandy loam	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 2.00 Min: 0.60	Max: 6.50 Min: 3.60
3	31 inches	65 inches	sandy loam	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 0.60 Min: 0.06	Max: 7.30 Min: 5.10

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: mucky-peat
unweathered bedrock
very stony - muck

Surficial Soil Types: mucky-peat
unweathered bedrock
very stony - muck

Shallow Soil Types: muck

Deeper Soil Types: unweathered bedrock
gravelly - loamy sand
fine sandy loam
loam
silt loam

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
2	USGS40000878653	1/4 - 1/2 Mile SSE
6	USGS40000878652	1/2 - 1 Mile South
B12	USGS40000878687	1/2 - 1 Mile North
13	USGS40000878685	1/2 - 1 Mile NNW
14	USGS40000878672	1/2 - 1 Mile WNW
D16	USGS40000878648	1/2 - 1 Mile South
D17	USGS40000878649	1/2 - 1 Mile South

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
1	NY0002610	1/4 - 1/2 Mile NNE

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
3	NYWS40000035316	1/2 - 1 Mile NNE
4	NYWS40000036556	1/2 - 1 Mile SW
5	NYWS40000036048	1/2 - 1 Mile NE
7	NYWS40000036589	1/2 - 1 Mile SW
A8	NYWS40000038334	1/2 - 1 Mile SSW
A9	NYWS40000038399	1/2 - 1 Mile SSW
10	NYWS40000038160	1/2 - 1 Mile North
B11	NYWS40000038790	1/2 - 1 Mile North
C15	NYWS40000035433	1/2 - 1 Mile NE
18	NYWS40000038912	1/2 - 1 Mile South
E19	NYWS40000037445	1/2 - 1 Mile NNE
E20	NYWS40000035678	1/2 - 1 Mile North
C21	NYWS40000037688	1/2 - 1 Mile ENE
22	NYWS40000038587	1/2 - 1 Mile SSE

PHYSICAL SETTING SOURCE MAP - 7391856.2s



- County Boundary
- Major Roads
- Contour Lines
- Airports
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- GI Indeterminate Groundwater Flow at Location
- GV Groundwater Flow Varies at Location
- HD Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	APA HQ - Phase I ESA	CLIENT:	Bergmann Associates
ADDRESS:	13 Main Street Saranac Lake NY 12983	CONTACT:	Mary K Legawiec
LAT/LONG:	44.324429 / 74.132928	INQUIRY #:	7391856.2s
		DATE:	July 17, 2023 3:51 pm

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
NNE **FRDS PWS** **NY0002610**
1/4 - 1/2 Mile
Higher

PWS ID:	NY0002610	PWS type:	System Owner/Responsible Party
PWS name:	SYMONDS ROGER	PWS address:	SARANAC LAKE CENTRAL SCH DIS#1
PWS city:	SARANAC LAKE	PWS state:	NY
PWS zip:	12982	PWS ID:	NY0002610
PWS type:	System Owner/Responsible Party		
PWS name:	SYMONDS ROGER	PWS address:	SARANAC LAKE CENTRAL SCH DIS#1
PWS city:	SARANAC LAKE	PWS state:	NY
PWS zip:	12982	PWS ID:	NY0002610
Activity status:	Active	Date system activated:	Not Reported
Date system deactivated:	Not Reported	Retail population:	00000083
System name:	LAKE CLEAR SCHOOL	System address:	Not Reported
System city:	LAKE CLEARKE	System state:	NY
System zip:	12945		
County FIPS:	016	City served:	HARRIETSTOWN (T)
Latitude:	441945	Longitude:	0740754

2
SSE **FED USGS** **USGS40000878653**
1/4 - 1/2 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	F 579	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Basement Complex
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	400	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

3
NNE **NY WELLS** **NYWS40000035316**
1/2 - 1 Mile
Higher

DEC Well #:	EX1015	Well Depth (ft):	375
Bedrock Depth (ft):	Not Reported	Groundwater Depth (ft):	0
Casing Depth (ft):	Not Reported	Casing 1 Diameter (in):	6
Casing 1 Length (ft):	50	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	3
Well Purpose:	Domestic	Driller Registration #:	NYRD10579

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

4
SW
1/2 - 1 Mile
Higher

NY WELLS **NYWS40000036556**

DEC Well #:	EX2298	Well Depth (ft):	605
Bedrock Depth (ft):	9	Groundwater Depth (ft):	40
Casing Depth (ft):	Not Reported	Casing 1 Diameter (in):	6
Casing 1 Length (ft):	20	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	.5
Well Purpose:	Domestic	Driller Registration #:	NYRD10181

5
NE
1/2 - 1 Mile
Higher

NY WELLS **NYWS40000036048**

DEC Well #:	EX1772	Well Depth (ft):	361
Bedrock Depth (ft):	49	Groundwater Depth (ft):	50
Casing Depth (ft):	Not Reported	Casing 1 Diameter (in):	6
Casing 1 Length (ft):	56	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	8
Well Purpose:	Domestic	Driller Registration #:	NYRD10037

6
South
1/2 - 1 Mile
Higher

FED USGS **USGS40000878652**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	F 582	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Basement Complex
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	200	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

7
SW
1/2 - 1 Mile
Higher

NY WELLS **NYWS40000036589**

DEC Well #:	EX2332	Well Depth (ft):	665
Bedrock Depth (ft):	4	Groundwater Depth (ft):	30
Casing Depth (ft):	Not Reported	Casing 1 Diameter (in):	6
Casing 1 Length (ft):	40	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	2
Well Purpose:	Domestic	Driller Registration #:	NYRD10181

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database | EDR ID Number

A8
SSW
1/2 - 1 Mile
Higher

NY WELLS **NYWS40000038334**

DEC Well #:	F2067	Well Depth (ft):	505
Bedrock Depth (ft):	5	Groundwater Depth (ft):	60
Casing Depth (ft):	Not Reported	Casing 1 Diameter (in):	6
Casing 1 Length (ft):	20	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	1.25
Well Purpose:	Domestic	Driller Registration #:	NYRD10181

A9
SSW
1/2 - 1 Mile
Higher

NY WELLS **NYWS40000038399**

DEC Well #:	F2127	Well Depth (ft):	605
Bedrock Depth (ft):	10	Groundwater Depth (ft):	0
Casing Depth (ft):	Not Reported	Casing 1 Diameter (in):	6
Casing 1 Length (ft):	20	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	5
Well Purpose:	Domestic	Driller Registration #:	NYRD10181

10
North
1/2 - 1 Mile
Higher

NY WELLS **NYWS40000038160**

DEC Well #:	F1896	Well Depth (ft):	420
Bedrock Depth (ft):	6	Groundwater Depth (ft):	0
Casing Depth (ft):	Not Reported	Casing 1 Diameter (in):	6
Casing 1 Length (ft):	22	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	3
Well Purpose:	Domestic	Driller Registration #:	NYRD10037

B11
North
1/2 - 1 Mile
Higher

NY WELLS **NYWS40000038790**

DEC Well #:	F577	Well Depth (ft):	200
Bedrock Depth (ft):	Not Reported	Groundwater Depth (ft):	0
Casing Depth (ft):	Not Reported	Casing 1 Diameter (in):	6
Casing 1 Length (ft):	20	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	4
Well Purpose:	Domestic	Driller Registration #:	NYRD10212

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

B12
North
1/2 - 1 Mile
Higher | **FED USGS** | **USGS40000878687**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	F 577	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Basement Complex
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	200	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

13
NNW
1/2 - 1 Mile
Higher | **FED USGS** | **USGS40000878685**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	F 355	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Basement Complex
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	247	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

14
WNW
1/2 - 1 Mile
Higher | **FED USGS** | **USGS40000878672**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	F 1	Type:	Well
Description:	Not Reported	HUC:	02010006
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand and Gravel	Aquifer Type:	Not Reported
Construction Date:	1964	Well Depth:	50
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

C15
NE
1/2 - 1 Mile
Higher | **NY WELLS** | **NYWS40000035433**

DEC Well #:	EX1138	Well Depth (ft):	500
Bedrock Depth (ft):	12	Groundwater Depth (ft):	0
Casing Depth (ft):	24	Casing 1 Diameter (in):	6

Casing 1 Length (ft):	26	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	0
Well Purpose:	Domestic	Driller Registration #:	NYRD10579

D16
South
1/2 - 1 Mile
Higher

FED USGS **USGS40000878648**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	F 346	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	300	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

D17
South
1/2 - 1 Mile
Higher

FED USGS **USGS40000878649**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	F 702	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Basement Complex
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	500	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

18
South
1/2 - 1 Mile
Higher

NY WELLS **NYWS40000038912**

DEC Well #:	F702	Well Depth (ft):	500
Bedrock Depth (ft):	Not Reported	Groundwater Depth (ft):	0
Casing Depth (ft):	Not Reported	Casing 1 Diameter (in):	6
Casing 1 Length (ft):	60	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	0
Well Purpose:	Domestic	Driller Registration #:	NYRD10153

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

E19
NNE
1/2 - 1 Mile
Higher

NY WELLS **NYWS40000037445**

DEC Well #:	F1154	Well Depth (ft):	300
Bedrock Depth (ft):	6	Groundwater Depth (ft):	0
Casing Depth (ft):	22	Casing 1 Diameter (in):	6
Casing 1 Length (ft):	22	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	1
Well Purpose:	Domestic	Driller Registration #:	NYRD10212

E20
North
1/2 - 1 Mile
Higher

NY WELLS **NYWS40000035678**

DEC Well #:	EX1390	Well Depth (ft):	540
Bedrock Depth (ft):	Not Reported	Groundwater Depth (ft):	0
Casing Depth (ft):	Not Reported	Casing 1 Diameter (in):	6
Casing 1 Length (ft):	40	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	4.5
Well Purpose:	Domestic	Driller Registration #:	NYRD10037

C21
ENE
1/2 - 1 Mile
Higher

NY WELLS **NYWS40000037688**

DEC Well #:	F1415	Well Depth (ft):	320
Bedrock Depth (ft):	22	Groundwater Depth (ft):	0
Casing Depth (ft):	Not Reported	Casing 1 Diameter (in):	6
Casing 1 Length (ft):	36	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	2.5
Well Purpose:	Domestic	Driller Registration #:	NYRD10153

22
SSE
1/2 - 1 Mile
Higher

NY WELLS **NYWS40000038587**

DEC Well #:	F367	Well Depth (ft):	180
Bedrock Depth (ft):	Not Reported	Groundwater Depth (ft):	0
Casing Depth (ft):	Not Reported	Casing 1 Diameter (in):	6
Casing 1 Length (ft):	77	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	N
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	7
Well Purpose:	Domestic	Driller Registration #:	NYRD10153

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: NY Radon

Radon Test Results

County	Town	Num Tests	Avg Result	Geo Mean	Max Result
FRANKLIN	ALTAMONT	11	1.41	0.7	6.1
FRANKLIN	BANGOR	3	1.37	1.1	2.2
FRANKLIN	BELLMONT	3	1.8	1.61	2.9
FRANKLIN	BOMBAY	2	2.65	2.51	3.5
FRANKLIN	BRIGHTON	3	2.07	1.88	2.9
FRANKLIN	CHATEAUGAY	3	0.93	0.8	1.6
FRANKLIN	CONSTABLE	5	0.8	0.6	2.1
FRANKLIN	DICKINSON	4	2.48	1.84	6.2
FRANKLIN	FORT COVINGTON	4	2.05	1.47	3.8
FRANKLIN	FRANKLIN	8	0.63	0.55	1.4
FRANKLIN	HARRIETSTOWN	25	0.78	0.61	2.6
FRANKLIN	MALONE	20	1.5	1.17	3.9
FRANKLIN	MOIRA	4	1.23	0.89	2.2
FRANKLIN	WAVERLY	2	1.45	1.17	2.3
FRANKLIN	WESTVILLE	2	3	2.89	3.8

Federal EPA Radon Zone for FRANKLIN County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Not Reported

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Source: Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APA HQ - PHASE I ESA
13 MAIN STREET
SARANAC LAKE, NY 12983

Inquiry Number: 7391856.7S
JULY 22, 2023

EDR Environmental Lien and AUL Search

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Environmental Lien and AUL Search

The EDR Environmental Lien Search Report provides results from a search of available current land title records for environmental cleanup liens and other activity and use limitations, such as engineering controls and institutional controls.

A network of professional, trained researchers, following established procedures, uses client supplied address information to:

- search for parcel information and/or legal description;
- search for ownership information;
- research official land title documents recorded at jurisdictional agencies such as recorders' offices, registries of deeds, county clerks' offices, etc.;
- access a copy of the deed;
- search for environmental encumbering instrument(s) associated with the deed;
- provide a copy of any environmental encumbrance(s) based upon a review of key words in the instrument(s) (title, parties involved, and description); and
- provide a copy of the deed or cite documents reviewed.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This report was prepared for the use of Environmental Data Resources, Inc., and AFX Research, LLC. (AFX) exclusively. This report is neither a guarantee of title, a commitment to insure, or a policy of title insurance. **NO WARRANTY, EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WTH THIS REPORT**. Environmental Data Resources, Inc. (EDR) and AFX exclusively specifically disclaim the making of any such warranties, including without limitation, merchantability or fitness for a particular use or purpose. The information contained in this report is retrieved as it is recorded from the various agencies that make it available. The total liability is limited to the fee paid for this report.

Copyright 2023 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EDR Environmental Lien and AUL Search

TARGET PROPERTY INFORMATION

ADDRESS

APA HQ - PHASE I ESA

13 MAIN STREET

SARANAC LAKE, NY 12983

RESEARCH SOURCE

JUDICIAL RECORDS ***NOT*** SEARCHED. BASED ON AVAILABLE INFORMATION EVALUATED BY THE TITLE SEARCH PROFESSIONAL, THE JURISDICTION ***DOES NOT*** REQUIRE A SEARCH OF JUDICIAL RECORDS IN ORDER TO IDENTIFY ENVIRONMENTAL LIENS.

Source 1: FRANKLIN COUNTY RECORDER'S OFFICE

Source 2: NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

Source 3: UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

PROPERTY INFORMATION

Legal Description:	45821 0002001000 SARANAC LAKE OFFICE BLDG
Current Owner:	VILLAGE OF SARANAC LAKE
Property Identifiers:	164601-458-021-0002-001-000-0000
Comments:	NO DEED FOUND 1980 - PRESENT.

EDR Environmental Lien and AUL Search

ENVIRONMENTAL LIEN

Environmental Lien: Found ☐ Not Found ☒

Comments: NONE IDENTIFIED.

OTHER ACTIVITY AND USE LIMITATIONS (AULS)

Other AUL's: Found ☐ Not Found ☒

Comments: NONE IDENTIFIED.

EDR Environmental Lien and AUL Search

MISCELLANEOUS

Comments: NONE IDENTIFIED.

APPENDIX H:

ADDITIONAL DOCUMENTATION

NPS Form 10-900
(3-82)

OMB No. 1024-0018
Expires 10-31-87

United States Department of the Interior
National Park Service

National Register of Historic Places Inventory—Nomination Form

For NPS use only
received SEP 30 1987
date entered NOV -2 1987

See instructions in *How to Complete National Register Forms*
Type all entries—complete applicable sections

1. Name

historic Paul Smith's Electric Light and Power and Railroad Company Complex

and or common

2. Location

street & number 2 Main Street ___ not for publication

city, town Saranac Lake ___ vicinity of

state New York code 036 county Franklin code 033

3. Classification

Category	Ownership	Status	Present Use	
___ district	X public	X occupied	___ agriculture	___ museum
X building(s)	___ private	___ unoccupied	___ commercial	___ park
X structure	___ both	___ work in progress	___ educational	___ private residence
___ site	**Public Acquisition**	**Accessible**	___ entertainment	___ religious
___ object	NA in process	X yes: restricted	X government	___ scientific
	NA being considered	___ yes: unrestricted	___ industrial	___ transportation
		___ no	___ military	___ other:

4. Owner of Property

name Village of Saranac Lake (buildings and dam); County of Franklin (bridge)

street & number 2 Main Street

city, town Saranac Lake ___ vicinity of state New York

5. Location of Legal Description

courthouse, registry of deeds, etc. Franklin County Courthouse

street & number Main Street

city, town Malone state New York

6. Representation in Existing Surveys

title Village of Saranac Lake Historic Resources Survey has this property been determined eligible? ___ yes X no

date 1984 ___ federal ___ state ___ county X local

depository for survey records Historic Saranac Lake, 132 River Street

city, town Saranac Lake state New York 12983

7. Description

Condition		Check one	Check one
___ excellent	___ deteriorated	___ unaltered	_x_ original site
_x_ good	___ ruins	_x_ altered	___ moved date NA
___ fair	___ unexposed		

Describe the present and original (if known) physical appearance

The Paul Smith's Electric Light and Power and Railroad Company complex is located in southern Franklin County on the Saranac River in the village of Saranac Lake. The nominated property is approximately two acres in extent and incorporates four principal elements: two structures (a dam and a bridge) and two buildings (a powerhouse and an office building). The dam and the bridge span the Saranac River, and the two buildings line the south bank, forming an interdependent complex. The waters thus impounded form Lake Flower upstream. All four of these interconnected elements contribute to the significance of the property.

Powerhouse

The powerhouse at the rear of 2 Main Street is a single story, one room brick building measuring 40 feet by 55 feet in plan, completed in 1909 for Paul Smith's Power and Light Company. Its battered stone foundation walls, since clad in concrete, are three feet thick at the top and flare to nearly six feet at the base. In places this foundation forms a part of the dam and in other places a part of the riverbank. When the powerhouse was built, head gates were installed at the Main Street bridge with a flume running underneath the street to carry the water to the two turbines approximately eight feet in diameter then located beneath the powerhouse. Three Rodney Hunt iron gates and controls, still operable, remain in place on the lake side of the bridge. The basement of the powerhouse contains three octagonal turbine pits along the north, riverbank, wall. All the original generating equipment was scrapped during World War II, with the metal going to the war effort.

The building is constructed of load-bearing brick walls with wood roof trusses that allowed the unobstructed space necessary to accommodate the original power generation equipment. Until the mid-1940's, this room housed a pair of dynamos and the distributing switchboard for Saranac Lake's electricity. A large cupola with metal pan sheathing rises in the center of the ridge of the gable roof, its east wall perforated with porcelain-lined orifices from which power lines once emerged.

Office Building

The Paul Smith's Electric Light and Power and Railroad Company office building at 2 Main Street is the most visible element of the complex. Built in 1927 at a cost of approximately $275,000, it is a three-story steel and masonry building with a terra-cotta exterior, located at the south side of the flume. While the name of construction engineer John Sweeney, a close associate of Phelps Smith, appears on some drawings, it has not been determined if he was

the architect of the building. The building has a great subterranean chamber below the first floor (once part of the flume), but this space can only be reached through the powerhouse. Placed squarely against the powerhouse in the rear, the new building was designed with an angled facade which parallels Main Street, thus forming a trapezoidal shape. The office building is 66 feet long, east to west, and 40 feet wide. (At the facade it measures 41'7½".) It has twelve-foot ceilings and rectangular steel framed windows on the first two floors and a fifteen-foot ceiling with original steel framed windows capped by arches on the third floor. The windows have operable lights which open in canopy fashion to provide fresh air.

The structural brick is clad in terra cotta on all but the rear of the building, which abuts the powerhouse; on the new wall above this junction, the brick is covered with a thin cementitious parge coat. The terra-cotta cladding is coarsely textured and colored a pale gray, so that it resembles granite. The first story is separated from the second and third stories by a classical entablature which is supported at the facade by fluted pilasters with Corinthian capitals. The third story is capped by a larger entablature with a modillion supported cornice, followed by a short parapet wall at the perimeter of the flat roof. Both upper and lower entablatures continue around the building the full length of both north and south facades.

The Main Street facade is composed of three bays. Each end of the façade has an entry door, with a display window placed symmetrically between them. Decorative, colored ceramic tiles line the street level show window, originally used to display appliances for sale. The facade features a variety of colors, including touches of blue and green glazed terra cotta on the six street-level pilasters framing the two entrances and the display window. Four of the pilasters support intact original lantern-style light fixtures. The frieze above the storefront carries the name "PAUL SMITH'S ELECTRIC LIGHT AND POWER AND RAILROAD CO." in incised capital letters.

The second floor of the Main Street facade features windows with triangular pediments in corresponding positions above the entry doors and paired rectangular windows without trim in the center. Above the paired window is a framed terra-cotta tablet bearing the inscription "POWER AND LIGHT." The third floor features windows on each end of the facade with round arched heads and fanlight muntins. At the center, paired rectangular windows are present, surmounted by a decorative glazed terra-cotta panel consisting of a shield with swags of drapery and ribbons in blue and gold in raised relief.

Above the third story entablature in the center section of the facade is a bracketed portion of the parapet wall raised to allow space for a polychrome glazed frieze depicting a city, with utility poles, powerlines, and buildings beneath a sky full of clouds and lightning bolts in raised relief.

The south facade is composed of four bays. The first floor has four rectangular openings; three of them contain paired windows, whereas the second from the left contains a doorway. They are framed by narrow terra-cotta moldings in an egg and dart design. The second floor windows repeat the design of those below. The third floor window openings contain paired sash and are headed by round arches with fanlight muntins. The arches are detailed with prominent keystones. The parapet above the third story entablature on the south facade incorporates a raised center tablet, similar to that of the east facade but without decoration.

The north facade fronts upon the Saranac River and is similar in fenestration to the south facade. A four-foot-wide iron balcony projects across the full length of the elevation at the first floor level overlooking the river. Again, the second opening from the left is an entry, in this instance providing access to the balcony. The balcony includes a decorative iron balustrade and is floored in red quarry tiles.

The back of the building, or west elevation, butts up against the powerhouse. Above the roof of the powerhouse, the brick wall of the office building is parged with concrete. Again, the parapet has a plain, raised center section. The west facade has an iron fire escape, with a door to the third floor, and two unadorned windows.

The office building roof is flat and is encircled by a short parapet wall. A terra-cotta clad elevator penthouse with an L-shaped plan rises above the roof in the southeast corner of the building. The penthouse has tall vertical proportions accentuated by pilasters at each of its corners. The penthouse is also detailed with a classical entablature cornice and parapet and decorated with tablets in raised relief which are detailed with swags and wreaths. Small steel sash casement windows are let into its south and east elevations. The 1000 pound capacity Otis elevator is still in place.

The interior of the building is quite plain, though little alteration appears to have occurred. The sub-grade level contains a great, plain, concrete chamber which originally carried water to the

adjacent powerhouse. The east face, which once opened to the flume, has been blocked off with a concrete wall. The west wall is completely open to the basement of the powerhouse, which originally contained the equipment for generating power.

The first floor interior is simple in finish and open in plan. A display area designed to showcase appliances is located at the east side of the room and includes a large window with tiled surrounds. The floor is finished in terrazzo, currently covered with carpeting. A lightweight interior wall system which allowed for changes in the partitions is apparently original, and one room of this kind on the first floor remains. For the building's new use as municipal offices, a system of freestanding dividers was introduced. A permanent wall along the rear of the main room divides a lavatory and a walk-in safe from the open area. Several original wall sconce lighting fixtures remain in place. Other than the southeast corner of the building (set aside for the accommodation of the stairwell and elevator tower), the interior of the building on all three main floors is free of structural columns and permanent partitions, leaving floor spaces open.

The second floor has a twelve-foot ceiling, a terrazzo floor, and one office set aside by the lightweight partition system. A storage room and two separate, white tiled toilet rooms occupy the back section.

The third floor has a fifteen-foot ceiling and terrazzo floors, here partially carpeted. Two offices are set off with original partitions; there is a single toilet room and a fire door giving access to the fire escape.

Original uses of these interior spaces are not fully understood; however, it would appear that all three floors were used for general office activities in which many employees shared a very large room and were overseen by a floor supervisor with a private office.

Main Street Bridge over the Lake Flower Outlet

The Main Street Bridge over the Lake Flower outlet is a concrete slab bridge built between 1924 and 1931. This bridge replaced an iron bridge on the same site that existed as early as 1895. The existing bridge is a two-span structure with a concrete deck supported by steel beam stringers. The north span crosses the outlet of Lake Flower. The south span crosses the abandoned intake

flume to a former hydroelectric power plant located to the west of the bridge. The flume has been sealed at the upstream and downstream faces of the bridge. The flume and the south abutment of the bridge are structurally connected to the Power and Light building, and it therefore seems reasonable to assume that the bridge itself was built in conjunction with the office building and new flume during 1927.

The total bridge length is 83 feet with an overall width of 47.2' and a curb-to-curb width of 35.2'. There is an asphalt overlay on the bridge deck. On each side of the bridge there is a five-foot-wide sidewalk with a four-foot-high reinforced concrete balustrade assembled of pre-cast concrete parts painted white. The balustrades at the east and west sides of the bridge each consist of eight panels with pierced openings separated by simple, undecorated plinths and capped by pre-cast railing sections.

Concrete lighting standards, located at each post on the east and west sides of the bridge, were originally part of the bridge design. One standard on the west side remains substantially intact; the riser from another on the east side is also extant.

The abutments and the center pier are built of concrete and appear to have been reinforced with sheet piling. Four telephone cable conduits are buried in the concrete deck and two water mains are located in the stream bed underneath the bridge. The bridge has a posted load limit of 15 tons.

Lake Flower Dam and Power Flume

The Lake Flower Dam is currently impounded by a concrete dam constructed with Works Progress Administration assistance between 1936 and 1938. The dam is tied into the office building foundation and extends approximately 70 feet across the Saranac River in a north-south alignment, maintaining a 13.5-foot gross head. A 40-foot wide spillway is located at the south side of the structure and two buttressed floodgate structures are located at the north side. The gates themselves have been modified with modern electrical controls installed during the rehabilitation of the dam in 1986-1987. Water impounded by the Lake Flower Dam was originally diverted for use in the powerhouse through a concrete flume originating east of the 1927 office building. The original Rodney Hunt Co. headgates remain in place and are located on the east side of Main Street just south of the Main Street Bridge. Although temporarily sealed off, the power flume extends west beneath Main Street and passes beneath the office building into the former turbine chamber of the powerhouse. Water

was returned to the river through three partially submerged parts in the north foundation of the powerhouse. Due to deterioration and a lack of conformance with current flood safety standards, the dam was rehabilitated by the village of Saranac Lake in 1986-1987 and provided with upgraded discharge capacity. The basic design of the dam, however, remains unaltered.

8. Significance

Period	Areas of Significance—Check and justify below				
___ prehistoric	___ archeology-prehistoric	___ community planning	___ landscape architecture	___ religion	
___ 1400–1499	___ archeology-historic	___ conservation	___ law	___ science	
___ 1500–1599	___ agriculture	___ economics	___ literature	___ sculpture	
___ 1600–1699	x architecture	___ education	___ military	___ social/ humanitarian	
___ 1700–1799	___ art	___ engineering	___ music	___ theater	
___ 1800–1899	___ commerce	___ exploration/settlement	___ philosophy	___ transportation	
x 1900–1938	___ communications	x industry	___ politics/government	___ other (specify)	
		___ invention			

Specific dates 1908–c. 1937 **Builder/Architect** undetermined

Statement of Significance (in one paragraph)

The Paul Smith's Power and Light Company complex in Saranac Lake is historically significant in illustrating the development of one of the Adirondack region's earliest electric utility companies and architecturally significant for the outstanding Neoclassical design of its principal building. Built on the site of an earlier water power facility completed in 1827, the existing plant complex includes an intact 1908 powerhouse building, a stylish 1927 terra-cotta powerhouse annex and office building, a c. 1927 steel and concrete bridge designed to complement the design of the office building, and a reinforced concrete dam and flume constructed in 1936-c.1937 with W.P.A. funding. The components of the nominated property illustrate a continuing process of adaptation and improvement during the 1908-c.1937 period of significance and attest to the progressive role of this important and influential private utility in the development of Saranac Lake.

The site was first developed by Captain Pliny Miller, Saranac Lake's second recorded settler, who had established a dam and a sawmill at a waterfall on the Saranac River by 1827. After his death in 1859, his son John built a hotel nearby.

> In 1888, a new owner (Wallace Murray) took over and changed the name to the "Riverside Inn"... Since his rooms and new porches overlooked the mill pond, Murray was concerned with the vista. Ever since the original flooding the pond was infested with a mess of ugly stumps which protruded above the water line.

After wining and dining Governor Roswell P. Flower at a grand ball in his honor, Murray approached him for state funds to eliminate the navigational hazards and beautify the mill pond. The funds were made available, and henceforth the mill pond was known as "Lake Flower."

On September 20, 1894, the Saranac Lake Electric Company was formed. The basis of its physical plant was the dam and sawmill that Captain Pliny Miller had built in 1827.

In 1905, Paul Smith and his two sons formed the Paul Smith's Electric Light and Power Company, with generating capacity from Franklin Falls and Union Falls much greater than the 290 kilowatt capacity at the Lake Flower site. On January 16, 1907, Paul Smith bought the Saranac Lake Electric Company for $125,000. Captain Miller's timber built mill was replaced in 1908 with the existing

9. Major Bibliographical References

SEE CONTINUATION SHEET

10. Geographical Data

Acreage of nominated property Approximately 2 acres

Quadrangle name Saranac Lake **Quadrangle scale** 1:25 000

UTM References

	Zone	Easting	Northing		Zone	Easting	Northing
A	18	569170	4908040	B			
C				D			
E				F			
G				H			

Verbal boundary description and justification

Refer to Item 7 and attached site map.

List all states and counties for properties overlapping state or county boundaries

state	N/A	**code**	**county**	**code**
state	N/A	**code**	**county**	**code**

11. Form Prepared By

name/title Mark Peckham

organization NYS Parks, Recreation, Historic Preservation **date** September, 1987

street & number Agency Building] **telephone** 518-474-0479

city or town Albany **state** New York 12238

12. State Historic Preservation Officer Certification

The evaluated significance of this property within the state is:

___ national ___ state X local

As the designated State Historic Preservation Officer for the National Historic Preservation Act of 1966 (Public Law 89-665), I hereby nominate this property for inclusion in the National Register and certify that it has been evaluated according to the criteria and procedures set forth by the National Park Service.

State Historic Preservation Officer signature Orin Lehman

title Commissioner **date** 9/14/87

For NPS use only

I hereby certify that this property is included in the National Register

Entered in the National Register

Keeper of the National Register **date** 11-2-87

Attest: **date**

Chief of Registration

substantial brick structure built to house the electrical generators. Head gates were installed at the Main Street Bridge, then an iron bridge, with a flume running under the street to carry the water to the two Lefell water turbines beneath the plant. Drive belts conveyed power from the turbines to a pair of Stanley dynamos on the floor above. Paul Smith died in 1912, and his son, Phelps Smith, became president of the electric company. The Saranac Lake facility was run from rented offices until Phelps Smith decided to build his own office building. In 1927 the new Paul Smith's office building was erected directly astride the old flume which ran beneath the new building to connect with the 1908 plant at the rear. The office building was handsomely constructed of steel and terra cotta to a height of three stories complete with an electric elevator.

Phelps Smith died in 1937. The proceeds of his estate were left to support the formation of Paul Smith's College, with Paul Smith's Hotel to be the basis of its physical plant. Therefore, from 1937 to 1966, the college owned and operated the power company. Because of the very limited supply of water in Lake Flower and particularly the inability to control the flow of water due to restricted water rights, power generation at this site was abandoned by the company. The old machinery was scrapped in late 1941 or 1942 during World War II, with the metal going to the war effort. The Paul Smith's Company merged into Niagara Mohawk Power Corporation in 1966, and they used the office building until recent years. The village acquired the buildings and part interest in the bridge in 1986.

The 1927 Power and Light Company Office Building at 2 Main Street is architecturally significant in the context of Saranac Lake's architectural development as a rare and distinctive example of Neoclassical architecture and as one of only two examples in the village of the historic use of architectural terra-cotta as an exterior cladding material. Built during the prosperous years which preceded the Great Depression, the stylish design of the building and its extravagant use of terra-cotta projected an image of optimism and confidence in the future. The design of the office building is consistent with the national popularity of the Neoclassical style during the 1920's and is characterized by its symmetrical facades and vocabulary of richly detailed Neoclassical architectural elements including round-arched and pedimented window openings, fluted pilasters with Corinthian capitals and fully developed entablatures with denticulated cornices. Only one other major example of Neoclassical design is present within the village core, the 1928 Harrietstown Town

Hall at 30 Main Street, built of brick and distinguished by a multi-staged domed clock tower.

The use of terra-cotta in the design and construction of the office building is rare in the context of Saranac Lake's architectural development and is illustrated by only one other example in the village, the 1924 Tousley Building at 38-40 Main Street. Although widely used in American urban areas during the first three decades of the twentieth century, its rarity in Saranac Lake was probably explained by the village's remote location and the difficulty and expense of importing the material and obtaining experienced workmen qualified to handle it. The artistic properties and versatility of this ceramic material are fully exploited in this example and demonstrate the ability of this material to articulate the complex forms and details characteristic of the Neoclassical style. The surface finish of the terra-cotta in the office building varies from a granular and slightly speckled texture suggestive of granite to glazed polychromatic details evident in the plaques which embellish the facade.

The powerhouse is the only building in Saranac Lake known to have been built during the ownership of Apollos "Paul" Smith, a famous Adirondack guide, hotelier, raconteur and developer. Most of his working life was spent at the hotel in the little community named for him, Paul Smiths, about 10 miles northwest of Saranac Lake. In the latter part of his life he developed an interest in hydroelectric power, which then led to his acquisition of the old Saranac Lake plant. This facility had preceded Smith's hydroelectric development at Franklin Falls and Union Falls but was much smaller in its generating capacity. Smith is important for his lifelong friendship with Dr. E.L. Trudeau, whose Adirondack destination when he was dying of tuberculosis was Paul Smith's Hotel. These two individuals were major figures in Saranac Lake's late nineteenth and early twentieth century economic development.

The period of time in which the 1927 office building was built was a time in which several other large-scale public and commercial buildings were constructed in the village. The Harrietstown Town Hall, the Hotel Saranac, Petrova School, the U.S. Post Office and the Tousley Building were all constructed in the period from 1923-1927. These buildings also illustrate an emphasis on the use of permanent materials and Neoclassical styling and together with the office building represent the climax of architectural development in Saranac Lake.

In 1936-c.]977 a new concrete dam integral to the complex was built by the village with W.P.A. funds, replacing a previous wooden dam a few yards upstream. Construction is well documented in historic photographs of each stage of the work. The Paul Smith's Company donated $10,000 toward the cost of the new dam, which was fastened to the north wall of the office building. Because the concrete from this dam had badly deteriorated from freezing and thawing, especially at the waterline, a rehabilitation of the dam and spillway was undertaken in 1986-1987.

The concrete Main Street Bridge that exists today replaced an iron span and was constructed sometime between December 1924 and January 1931, according to Sanborn maps. Though no specific date of construction can be found, it appears likely that it was built at the same time as the office building since extensive alterations to the site required during the construction of the office building probably required changes to the configuration of the earlier bridge. Phelps Smith's considerable influence may well have been a factor in causing a new bridge to be built which complemented his fine new building. The design of the pre-cast concrete balustrades, detailed with pierced openings and originally carrying light standards is distinctive within the village for its degree of formality and concern for design.


Donaldson, Alfred L.. A History of the Adirondacks. 2 vols. n.p.: The Century Company, 1921.

Duquette, John. "Electric History of Saranac Lake." Adirondack Daily Enterprise, Friday, October 31, 1986.

Insurance Maps of Saranac Lake, New York. 7 editions: Sanborn-Perris Map Co., New York, 1895 to 1931 inclusive.

Preliminary research and documentation provided by:

Mary B. Hotaling, Executive Director
Historic Saranac Lake
132 River Street, P.O. Box 1030
Saranac Lake, New York 12983



NOMINATED PROPERTY: PAUL SMITH'S ELECTRIC AND POWER AND RAILROAD COMPANY COMPLEX

ADDRESS: 2 MAIN STREET

VILLAGE: SARANAC LAKE

COUNTY: FRANKLIN

STATE: NEW YORK

PROBLEM DESCRIPTION SHEET

State Name New York County Name Franklin

Resource Name Smith's, Paul, Electric Light & Power & RR Co. Complex

Data Collector's Surname MacPherson Today's Date 10/8/87

Federal Register List ___/___/___ Cert. Date ___/___/___

Reference No. 87001898

Describe Problem:

Nomination has bldgs & structure checked as resource type. Entered Dist.

Team Leader _____ Date ___/___/___ N R Staff _____ Date ___/___/___

Problem Team _____ Date ___/___/___

Form WASO - 6
03/27/85

8700 1898

WASO Form - 177
("R" June 1984)

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES
EVALUATION/RETURN SHEET

Smith's, Paul, Electric Light and Power and
Railroad Company Complex
Franklin County
NEW YORK

SEP 30 1987

Working No. _____
Fed. Reg. Date: 2/7/89
Date Due: 10/30/87 - 11/14/87
Action: ACCEPT 11-2-87
___ RETURN _____
___ REJECT _____
Federal Agency: _____

☐ resubmission
☐ nomination by person or local government
☐ owner objection
☐ appeal

Entered in the National Register

Substantive Review: ☐ sample ☐ request ☐ appeal ☐ NR decision

Reviewer's comments:

Recom./Criteria _____
Reviewer _____
Discipline _____
Date _____
_____ see continuation sheet

Nomination returned for: _____ technical corrections cited below
_____ substantive reasons discussed below

1. Name

2. Location

3. Classification

Category	Ownership	Status	Present Use
	Public Acquisition	Accessible	

4. Owner of Property

5. Location of Legal Description

6. Representation in Existing Surveys

Has this property been determined eligible? ☐ yes ☐ no

7. Description

Condition		Check one	Check one
☐ excellent	☐ deteriorated	☐ unaltered	☐ original site
☐ good	☐ ruins	☐ altered	☐ moved date _____
☐ fair	☐ unexposed		

Describe the present and original (if known) physical appearance

☐ summary paragraph
☐ completeness
☐ clarity
☐ alterations/integrity
☐ dates
☐ boundary selection

8. Significance

Period Areas of Significance—Check and justify below

Specific dates Builder/Architect

Statement of Significance *(in one paragraph)*

- ☐ summary paragraph
- ☐ completeness
- ☐ clarity
- ☐ applicable criteria
- ☐ justification of areas checked
- ☐ relating significance to the resource
- ☐ context
- ☐ relationship of integrity to significance
- ☐ justification of exception
- ☐ other

9. Major Bibliographical References

10. Geographical Data

Acreage of nominated property _____

Quadrangle name _____

UTM References

Verbal boundary description and justification

11. Form Prepared By

12. State Historic Preservation Officer Certification

The evaluated significance of this property within the state is:

____ national ____ state ____ local

State Historic Preservation Officer signature

title date

13. Other

- ☐ Maps
- ☐ Photographs
- ☐ Other

Questions concerning this nomination may be directed to _____

Signed _____ Date _____ Phone: _____

GPO 918-450

Comments for any item may be continued on an attached sheet



Paul Smith's Electric Light & Power & Railroad Co. complex
2 Main St. Saranac Lake
Franklin Co. N.Y.
Photo by: Barbara Parnass, 1987.
Neg. at: Parnass neg. file, S.h.
HSh nomination

Photo No. 1: 1927 office building & bridge
looking WSW from Riverside Park



Paul Smith's Electric Light
+ Power + Railroad Co. Complex
2 Main St. Saranac Lake
Franklin Co. NY.
Photo by: Barbara Parnass, 1987.
Neg. at: Parnass neg. file, S.L.
HSL nomination

Photo No. 2: looking WNW
1927 office building



3

Paul Smith's Electric Light + Power + Railroad Co Complex
2 Main St, Saranac Lake
Franklin Co. N.Y.
Photo by: Barbara Parnass, 1987.
Neg. at: Parnass neg. file, S.L.
HSL nomination

Photo No. 3: North elevation of office building and powerhouse showing dam in foreground.



4

Paul Smith's Electric Light
& Power & Rail road Co. Complex
2 Main St. Saranac Lake
Franklin Co. N.Y.


Photo by: Barbara Parnass, 1987.
Neg. at: Parnass neg. file, S.L.
HSL nomination

Photo No. 4: East facade detail
terra cotta pilaster
& metal lantern



5


Paul Smith's Electric Light & Power & Railroad Co. Complex
2 Main St. Saranac Lake
Franklin Co. NY
Photo by: Barbara Parnass, 1987.
Neg. at: Parnass neg. file, S.H. HSH nomination
Photo No. 5: Cupola of 1909 power house looking north by NW



6.

Paul Smith's Electric Light & Power & Rail road Co. complex
2 Main St. Saranac Lake
Franklin Co. N.Y.
Photo by Barbara Parnass, 1987.
Neg at: Parnass neg. file, S.h.
HSh nomination

Photo No. 6 - 1909 Power House river level showing turbine pits.




7.

Paul Smith's Electric Light & Power & Rail road Co. complex
2 Main St. Saranac Lake
Franklin Co. NY
Photo by Barbara Parnass, 1987.
Neg. at: Parnass neg. file, S.H.
HSH nomination

Photo No. 7: Main Floor, Power House
Showing NE corner

SARANAC LAKE, NEW YORK

7.5X15 MINUTE SERIES (TOPOGRAPHIC)



11 KM. TO N.Y. 30
TUPPER LAKE 19 KM.

LAKE PLACID 14 KM.

AVERYVILLE 9.8 KM.

LAKE PLACID 24 KM.

11 KM. TO N.Y. 86
LAKE PLACID 14 KM.

1 590 000 FEET

1 550 000 FEET

580 000 FEET

530 000 FEET

KILOMETERS 0 .5 1 2 3 4 5

MILES 0 .5 1 2 3

SCALE 1:25 000

1 CENTIMETER TO 250 METERS

0 500 1000 2000 3000 4000 5000 METERS

0 1000 2000 4000 6000 8000 10 000 12 000 14 000 16 000 FEET

© INTERIOR—GEOLOGICAL SURVEY, RESTON, VIRGINIA—1978

SARANAC LAKE, NEW YORK
4474–141–T25
1978

4474–141–T25

1:25 000-scale *metric* topographic map of

Saranac Lake

NEW YORK



SHOWING

- Contours and elevations in meters
- Highways, roads and other manmade structures
- Water features
- Woodland areas
- Geographic names

U.S. DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

1978

Produced by the United States Geological Survey

Control by USGS and NOS/NOAA

Compiled by photogrammetric methods from aerial photographs taken 1976. Field checked 1976
Map edited 1978

Projection and 1000-meter grid, zone 18: Universal Transverse Mercator
10,000-foot grid ticks based on New York coordinate system, east zone. 1927 North American datum

To place on the projected North American datum 1983 move the projection lines 2.1 meters south and 31.2 meters west as shown by dashed corner ticks

This area also covered by 1:25 000-scale orthophotoquad

CONTOUR INTERVAL 10 METERS
SUPPLEMENTARY CONTOUR INTERVAL 5 METERS
NATIONAL GEODETIC VERTICAL DATUM OF 1929

CONTROL ELEVATIONS SHOWN TO THE NEAREST 0.1 METER
OTHER ELEVATIONS SHOWN TO THE NEAREST METER

THIS MAP COMPLIES WITH NATIONAL MAP ACCURACY STANDARDS

CONVERSION TABLE

Meters	Feet
1	3.2808
2	6.5617
3	9.8425
4	13.1234
5	16.4042
6	19.6850
7	22.9659
8	26.2467
9	29.5276
10	32.8084

To convert meters to feet multiply by 3.2808
To convert feet to meters multiply by .3048

DECLINATION DIAGRAM



UTM grid convergence (GN) and 1978 magnetic declination (MN) at center of map
Diagram is approximate

ADJOINING MAPS

1	2	3
4		5
6	7	8

1 Saint Regis Mtn
2 Bloomingdale
3 Wilmington
4 Lake Saranac Lake
5 Upper Lake
6 Tupper Lake
7 Ampersand Lake
8 Keene Valley

FOR SALE BY U. S. GEOLOGICAL SURVEY
RESTON, VIRGINIA 22092

Topographic Map Symbols

- Primary highway, hard surface
- Secondary highway, hard surface
- Light-duty road, hard or improved surface
- Unimproved road; trail
- Route marker: Interstate; U. S.; State
- Railroad: standard gage; narrow gage
- Bridge; drawbridge
- Footbridge; overpass; underpass
- Built-up area; only selected landmark buildings shown
- House; barn; church; school; large structure
- Boundary:
  - National; with monument
  - State
  - County, parish
  - Civil township, precinct, district
  - Incorporated city, village, town
  - National or State reservation; small park
  - Land grant with monument; found section corner
  - U. S. public lands survey: range, township; section
  - Range, township; section line: location approximate
- Fence or field line
- Power transmission line, located tower
- Dam; dam with lock
- Cemetery; grave
- Campground; picnic area; U. S. location monument
- Windmill; water well; spring
- Mine shaft; prospect; adit or cave
- Control: horizontal station; vertical station; spot elevation
- Contours: index; intermediate; supplementary; depression
- Distorted surface: strip mine, lava; sand
- Bathymetric contours: index; intermediate
- Perennial lake and stream; intermittent lake and stream
- Rapids, large and small; falls, large and small
- Swamp; marsh
- Submerged marsh; land subject to controlled inundation
- Woodland; scattered trees
- Scrub; mangrove
- Orchard; vineyard

A pamphlet describing topographic maps is available on request

Criteria | Spatial | Results

1. Navigate to your area of interest

Option A: Zoom to a County or Municipality

Select County... | Select Municipality... | Zoom

Option B: Find an Address Location

3 main street, Saranac Lake, New York | Find Address

2. Define or refine the location/area for your search


Click a button below to activate the draw tool and draw the shape on the map

Point | Line | Rectangle | Circle | Polygon

3. Generate a search radius around your graphic (Optional)

Generate a [ ] Foot buffer | Generate Buffer

Search | Reset



U.S. Fish and Wildlife Service
National Wetlands Inventory

3 Main St, Saranac Lake, New York



August 3, 2023

Wetlands

- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland
- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond
- Lake
- Other
- Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.

Soil Map—Franklin County, New York
(3 Main Street, Saranac Lake, New York)



Map Scale: 1:1,190 if printed on A landscape (11" x 8.5") sheet.

N

Meters
0 15 30 60 90

Feet
0 50 100 200 300

Map projection: Web Mercator Corner coordinates: WGS84 Edge tics: UTM Zone 18N WGS84

MAP LEGEND

Area of Interest (AOI)
- Area of Interest (AOI)

Soils
- Soil Map Unit Polygons
- Soil Map Unit Lines
- Soil Map Unit Points

Special Point Features
- Blowout
- Borrow Pit
- Clay Spot
- Closed Depression
- Gravel Pit
- Gravelly Spot
- Landfill
- Lava Flow
- Marsh or swamp
- Mine or Quarry
- Miscellaneous Water
- Perennial Water
- Rock Outcrop
- Saline Spot
- Sandy Spot
- Severely Eroded Spot
- Sinkhole
- Slide or Slip
- Sodic Spot
- Spoil Area
- Stony Spot
- Very Stony Spot
- Wet Spot
- Other
- Special Line Features

Water Features
- Streams and Canals

Transportation
- Rails
- Interstate Highways
- US Routes
- Major Roads
- Local Roads

Background
- Aerial Photography

MAP INFORMATION

The soil surveys that comprise your AOI were mapped at 1:24,000.

Warning: Soil Map may not be valid at this scale.

Enlargement of maps beyond the scale of mapping can cause misunderstanding of the detail of mapping and accuracy of soil line placement. The maps do not show the small areas of contrasting soils that could have been shown at a more detailed scale.

Please rely on the bar scale on each map sheet for map measurements.

Source of Map: Natural Resources Conservation Service
Web Soil Survey URL:
Coordinate System: Web Mercator (EPSG:3857)

Maps from the Web Soil Survey are based on the Web Mercator projection, which preserves direction and shape but distorts distance and area. A projection that preserves area, such as the Albers equal-area conic projection, should be used if more accurate calculations of distance or area are required.

This product is generated from the USDA-NRCS certified data as of the version date(s) listed below.

Soil Survey Area: Franklin County, New York
Survey Area Data: Version 6, Sep 10, 2022

Soil map units are labeled (as space allows) for map scales 1:50,000 or larger.

Date(s) aerial images were photographed: Jun 20, 2020—Jun 22, 2020

The orthophoto or other base map on which the soil lines were compiled and digitized probably differs from the background imagery displayed on these maps. As a result, some minor shifting of map unit boundaries may be evident.

Map Unit Legend

Map Unit Symbol	Map Unit Name	Acres in AOI	Percent of AOI
AnA	Adams loamy fine sand, 0 to 3 percent slopes	3.2	100.0%
Totals for Area of Interest		**3.2**	**100.0%**

United States Department of the Interior

FISH AND WILDLIFE SERVICE
New York Ecological Services Field Office
3817 Luker Road
Cortland, NY 13045-9385
Phone: (607) 753-9334 Fax: (607) 753-9699
Email Address: fw5es_nyfo@fws.gov

In Reply Refer To: August 03, 2023
Project Code: 2023-0112510
Project Name: Adirondack Park Agency Head Quarters Phase I ESA

Subject: List of threatened and endangered species that may occur in your proposed project location or may be affected by your proposed project

To Whom It May Concern:

The enclosed species list identifies threatened, endangered, proposed and candidate species, as well as proposed and final designated critical habitat, that may occur within the boundary of your proposed project and/or may be affected by your proposed project. The species list fulfills the requirements of the U.S. Fish and Wildlife Service (Service) under section 7(c) of the Endangered Species Act (Act) of 1973, as amended (16 U.S.C. 1531 *et seq.*).

New information based on updated surveys, changes in the abundance and distribution of species, changed habitat conditions, or other factors could change this list. Please feel free to contact us if you need more current information or assistance regarding the potential impacts to federally proposed, listed, and candidate species and federally designated and proposed critical habitat. Please note that under 50 CFR 402.12(e) of the regulations implementing section 7 of the Act, the accuracy of this species list should be verified after 90 days. This verification can be completed formally or informally as desired. The Service recommends that verification be completed by visiting the ECOS-IPaC website at regular intervals during project planning and implementation for updates to species lists and information. An updated list may be requested through the ECOS-IPaC system by completing the same process used to receive the enclosed list.

The purpose of the Act is to provide a means whereby threatened and endangered species and the ecosystems upon which they depend may be conserved. Under sections 7(a)(1) and 7(a)(2) of the Act and its implementing regulations (50 CFR 402 *et seq.*), Federal agencies are required to utilize their authorities to carry out programs for the conservation of threatened and endangered species and to determine whether projects may affect threatened and endangered species and/or designated critical habitat.

A Biological Assessment is required for construction projects (or other undertakings having similar physical impacts) that are major Federal actions significantly affecting the quality of the human environment as defined in the National Environmental Policy Act (42 U.S.C. 4332(2)

(c)). For projects other than major construction activities, the Service suggests that a biological evaluation similar to a Biological Assessment be prepared to determine whether the project may affect listed or proposed species and/or designated or proposed critical habitat. Recommended contents of a Biological Assessment are described at 50 CFR 402.12.

If a Federal agency determines, based on the Biological Assessment or biological evaluation, that listed species and/or designated critical habitat may be affected by the proposed project, the agency is required to consult with the Service pursuant to 50 CFR 402. In addition, the Service recommends that candidate species, proposed species and proposed critical habitat be addressed within the consultation. More information on the regulations and procedures for section 7 consultation, including the role of permit or license applicants, can be found in the "Endangered Species Consultation Handbook" at:

http://www.fws.gov/endangered/esa-library/pdf/TOC-GLOS.PDF

Migratory Birds: In addition to responsibilities to protect threatened and endangered species under the Endangered Species Act (ESA), there are additional responsibilities under the Migratory Bird Treaty Act (MBTA) and the Bald and Golden Eagle Protection Act (BGEPA) to protect native birds from project-related impacts. Any activity, intentional or unintentional, resulting in take of migratory birds, including eagles, is prohibited unless otherwise permitted by the U.S. Fish and Wildlife Service (50 C.F.R. Sec. 10.12 and 16 U.S.C. Sec. 668(a)). For more information regarding these Acts see https://www.fws.gov/birds/policies-and-regulations.php.

The MBTA has no provision for allowing take of migratory birds that may be unintentionally killed or injured by otherwise lawful activities. It is the responsibility of the project proponent to comply with these Acts by identifying potential impacts to migratory birds and eagles within applicable NEPA documents (when there is a federal nexus) or a Bird/Eagle Conservation Plan (when there is no federal nexus). Proponents should implement conservation measures to avoid or minimize the production of project-related stressors or minimize the exposure of birds and their resources to the project-related stressors. For more information on avian stressors and recommended conservation measures see https://www.fws.gov/birds/bird-enthusiasts/threats-to-birds.php.

In addition to MBTA and BGEPA, Executive Order 13186: *Responsibilities of Federal Agencies to Protect Migratory Birds*, obligates all Federal agencies that engage in or authorize activities that might affect migratory birds, to minimize those effects and encourage conservation measures that will improve bird populations. Executive Order 13186 provides for the protection of both migratory birds and migratory bird habitat. For information regarding the implementation of Executive Order 13186, please visit https://www.fws.gov/birds/policies-and-regulations/executive-orders/e0-13186.php.

We appreciate your concern for threatened and endangered species. The Service encourages Federal agencies to include conservation of threatened and endangered species into their project planning to further the purposes of the Act. **Please include the Consultation Code in the header of this letter with any request for consultation or correspondence about your project that you submit to our office.**

Attachment(s):

- Official Species List

OFFICIAL SPECIES LIST

This list is provided pursuant to Section 7 of the Endangered Species Act, and fulfills the requirement for Federal agencies to "request of the Secretary of the Interior information whether any species which is listed or proposed to be listed may be present in the area of a proposed action".

This species list is provided by:

New York Ecological Services Field Office
3817 Luker Road
Cortland, NY 13045-9385
(607) 753-9334

PROJECT SUMMARY

Project Code: 2023-0112510
Project Name: Adirondack Park Agency Head Quarters Phase I ESA
Project Type: Commercial Development
Project Description: potential purchase and relocation of the APA HQ to Saranac Lake. Would be building a new building.
Project Location:

The approximate location of the project can be viewed in Google Maps: https://www.google.com/maps/@44.32460115,-74.1326413507371,14z



Counties: Franklin County, New York

ENDANGERED SPECIES ACT SPECIES

There is a total of 2 threatened, endangered, or candidate species on this species list.

Species on this list should be considered in an effects analysis for your project and could include species that exist in another geographic area. For example, certain fish may appear on the species list because a project could affect downstream species.

IPaC does not display listed species or critical habitats under the sole jurisdiction of NOAA Fisheries[1], as USFWS does not have the authority to speak on behalf of NOAA and the Department of Commerce.

See the "Critical habitats" section below for those critical habitats that lie wholly or partially within your project area under this office's jurisdiction. Please contact the designated FWS office if you have questions.

---

1. NOAA Fisheries, also known as the National Marine Fisheries Service (NMFS), is an office of the National Oceanic and Atmospheric Administration within the Department of Commerce.

MAMMALS

NAME	STATUS
Northern Long-eared Bat *Myotis septentrionalis* No critical habitat has been designated for this species. Species profile: https://ecos.fws.gov/ecp/species/9045	Endangered

INSECTS

NAME	STATUS
Monarch Butterfly *Danaus plexippus* No critical habitat has been designated for this species. Species profile: https://ecos.fws.gov/ecp/species/9743	Candidate

CRITICAL HABITATS

THERE ARE NO CRITICAL HABITATS WITHIN YOUR PROJECT AREA UNDER THIS OFFICE'S JURISDICTION.

YOU ARE STILL REQUIRED TO DETERMINE IF YOUR PROJECT(S) MAY HAVE EFFECTS ON ALL ABOVE LISTED SPECIES.

IPAC USER CONTACT INFORMATION

Agency:	Bergmann
Name:	Mary Legawiec
Address:	280 East Broad Street
Address Line 2:	Suite #200
City:	Rochester
State:	NY
Zip:	14604
Email	mlegawiec@bergmannpc.com
Phone:	5854987820

APPENDIX I:

RESUMES OF AUTHORS

BERGMANN
ARCHITECTS ENGINEERS PLANNERS



EXPERIENCE:

Total: 2.5 Years
Bergmann: 2.5 Years

EDUCATION:

- BA, Geological Sciences, State University of New York at Geneseo
- MSc, Integrated Management of Freshwater Environments, Queen Mary University of London

CERTIFICATIONS

- OSHA 40 Hour Hazardous Waste Operations and Emergency Response
- NYSDOL-certified Mold Assessor
- NYSDEC 4-Hour Erosion and Sediment Control Training

PROFESSIONAL AFFILIATIONS

- Genesee Finger Lakes Chapter Air & Waste Management Association
- National Association of Environmental Professionals
- American Institute for Professional Geologists

CERTIFICATIONS

- Legawiec, Mary & MacKenzie, Lindsay. (2017) Influence of Microbial Biofilms on The Preservation of Soft Tissues in Snails.

Mary Legawiec

ENVIRONMENTAL SCIENTIST, MSC

Mary Legawiec responsible for conducting fieldwork, including soil, groundwater, air, mold, and soil vapor sampling, responsible for the preparation of all appropriate inquiries-compliant Phase I Environmental Site Assessment (ESA) reports and Phase II ESAs, and environmental construction oversight.

Project Experience

WaWa | Phase I and Phase II ESA | Ruckersville, VA

Performed as an Environmental Scientist for a Phase II ESA subsurface investigation on behalf of WaWa as part of the due diligence in the redevelopment of a historic gas station into a WaWa gas station. Collected and logged subsurface samples that were field screened for the presence of volatile organic compounds (VOCs). Selected samples submitted for laboratory analysis to assess potential releases from previous on-site operations. Prepared report comparing analytical results to WaWa for future redevelopment of the Property.

Providence Housing | Brownfield Cleanup Investigation (BCPi) | Rochester, New York

Performed as an Environmental Scientist for a BCPi supplemental subsurface investigation on behalf of Providence Housing as part of the due diligence/at the request of New York State Department of Environmental Conservation (NYSDEC) in the redevelopment of a site with historic contamination into affordable housing. Collected and logged subsurface samples that were field screened for the presence of volatile organic compounds (VOCs). Selected samples submitted for laboratory analysis to assess potential releases from previous on-site operations. Prepared report comparing analytical results to Providence Housing for future redevelopment of the Property.

ALDI | Phase II ESA | Grand Island, New York

Performed as a Environmental Scientist for a Phase II ESA subsurface investigation on behalf of ALDI as part of the due diligence in the redevelopment of a historic gas station into an ALDI grocery store. Collected and logged subsurface samples that were field screened for the presence of volatile organic compounds (VOCs). Selected samples submitted for laboratory analysis to assess potential releases from previous on-site operations. Prepared report comparing analytical results to ALDI for future redevelopment of the Property.

Monroe County DOT | Phase II ESA | Pittsford, New York

Performed as a Environmental Scientist for a Phase II ESA subsurface investigation on behalf of Monroe County DOT as part of the due diligence in the removal of historic culverts. Collected and logged subsurface samples that were field screened for the presence of volatile organic compounds (VOCs). Selected samples submitted for laboratory analysis to assess potential releases from previous on-site operations. Prepared report comparing analytical results to Monroe County DOT for future removal and redevelopment of culverts.

University of Rochester | Environment Construction Oversight | Rochester, New York

Environmental Scientist responsible for environmental oversight and hazardous waste characterization during the construction of the emergency room. Responsibilities include air quality monitoring via dust monitors to ensure dust is properly maintained during site construction; identification and sampling of potential PCB impacted soil monitored by means of visual, olfactory, and instrument (Photoionization Detector [PID]) recognition; and environmental oversight during excavation/removal of impacted soil, verification of proper handling, transportation, and disposal of impacted soil to predetermined and approved landfill facility.

Client | Phase II ESA | Marietta, Georgia

Environmental Scientist responsible for a Phase II ESA subsurface investigation on behalf of Client as part of the due diligence in the development of a Commercial Use Property. Collected and logged subsurface samples that were field screened for the presence of volatile organic compounds (VOCs). Selected samples submitted for laboratory analysis to assess potential releases from previous on-site operations. Prepared report comparing analytical results to Client for future development.

Christa Construction | Mold Assessments | Various Locations

Environmental Scientist responsible for coordinating/performing mold assessments and provide remediation recommendations Pursuant of NYSDOL Article 32 designs for various multi-family housing development projects throughout New York State. Ongoing.

Christa Construction | Soil Vapor Intrusion Sampling | Amsterdam, New York

Environmental Scientist responsible for soil vapor intrusion sampling, and subsequent reporting for one (1) residential property.

True Green Capital | Landfill Inspections | Auburn and Elbridge, New York

Environmental Scientist responsible for weekly landfill inspections during the construction of solar array facilities on capped landfills. Responsibilities include weekly inspections to confirm no damage to the landfill caps, piping, excessive erosion during construction activities. Weekly photologs, inspection checklists, and reports provided to the Client within 24 hours of the landfill inspections.

EDF Renewables | Phase I ESA | Verona, New York

Environmental Scientist responsible for coordinating and performing a Phase I ESA to characterize site conditions and prepare an all-appropriate inquiries compliant Phase I ESA report for future development of a solar array on the project site. Report included the review of relevant available historical literature, maps, atlases, and environmental database information relating to environmental quality.

CBREE HEERY | Phase I ESA | Henrietta, New York

Environmental Scientist responsible for coordinating and performing a Phase I ESA to characterize site conditions and prepare an all-appropriate inquiries compliant Phase I ESA report for future development of a solar array on the project site. Report included the review of relevant available historical literature, maps, atlases, and environmental database information relating to environmental quality.

Delaware River Solar | SWPPP and EM Inspections | Troupsburg, New York

Environmental Scientist responsible for coordinating and performing a Storm Water Pollution Protection Plan and Environmental Monitoring Site Visits to ensure that erosional control and SWPPP measures are in proper working order and abiding by guidelines. Also responsible for preparing a compliant SWPPP and EM reports of the subject property. Reports include Erosional control/design deficiencies, soil disturbance documentation, and overall site progress.

Empire Valorize | SWPPP Inspection | Benton, New York

Environmental Scientist responsible for coordinating and performing a Storm Water Pollution Protection Plan and Environmental Monitoring Site Visits to ensure that erosional control and SWPPP measures are in proper working order and abiding by guidelines. Also responsible for preparing a compliant SWPPP and EM reports of the subject property. Reports include Erosional control/design deficiencies, soil disturbance documentation, and overall site progress.

DePaul Properties | Environmental Monitoring | Amsterdam, New York

Environmental Scientist responsible for monitoring air quality via dust monitors to ensure dust is properly maintained during site construction. Excavated/disturbed soil were monitored by means of visual, olfactory, and instrument (Photoionization Detector [PID]) recognition.

Client | Periodic Review Report | Rochester, New York

Environmental Professional responsible for the collection, analysis, and tabulation of water sample quality. Performed as the Environmental Scientist responsible for data submission to the NYSDEC Equis database and report submission to the Client and NYSDEC.

Culligan | Phase II ESA | Rochester, New York

Environmental Scientist responsible for a Phase II ESA subsurface investigation on behalf of Client as part of the due diligence of Property redevelopment. Collected and logged subsurface samples that were field screened for the presence of volatile organic compounds (VOCs). Selected samples submitted for laboratory analysis to assess potential releases from previous on-site operations. Prepared report comparing analytical results to Culligan for future development.

City of Rochester | Dust Monitoring, Disturbance Activity Monitoring | Rochester, New York

Environmental scientist responsible for collecting and recording dust levels during construction activities. PID, olfactory, and visual observations were used during any disturbance activities to ensure no impacted sediment was encountered.

Buckeye Partners, LP | Water sampling for Pipeline Discharge | Pittsburg, Pennsylvania

Environmental Specialist responsible for collecting discharge water samples.

DePaul Properties | Environmental Management Plan and Soil Management Plan | Dansville, New York

Evaluated media analytical findings to identify removal areas to incorporate during site redevelopment. Developed an Environmental Management Plan (EMP) and Soil Management Plan (SMP). The EMP and SMP outlined procedures and regulations to follow during the project based on known and unknown site conditions and environmental impacts.

DePaul Properties | Phase II ESA | Rochester, New York

Performed as a Field Environmental Professional Environmental Scientist for a Phase II ESA subsurface investigation on behalf of DePaul Properties as part of the due diligence in the re-development of vacant land into affordable housing. Environmental Professional that monitored advancement of soil borings using

Geoprobe® direct-push technology. Collected and logged subsurface samples that were field screened for the presence of volatile organic compounds. Selected samples submitted for laboratory analysis to assess potential releases from previous on-site operations. Prepared report comparing analytical results to DePaul for future expansion development.

URMC | Phase II ESA | Rochester, New York

Performed as a Environmental Scientist for a Phase II ESA subsurface investigation on behalf of University of Rochester Medical Center (URMC) as part of the due diligence in the expansion of the Emergency Room Tower. Monitored advancement of soil borings using Geoprobe® direct-push technology. Collected and logged subsurface samples that were field screened for the presence of volatile organic compounds. Selected samples submitted for laboratory analysis to assess potential releases from previous on-site operations. Prepared report comparing analytical results to URMC for future expansion development.

BERGMANN
ARCHITECTS ENGINEERS PLANNERS



Ariadna Cheremeteff

ENVIRONMENTAL REGIONAL DISCIPLINE LEADER, ENVIRONMENTAL

Ariadna has been working in the environmental remediation field for over a decade specializing in Brownfield and Voluntary Cleanup Program investigations and projects, obtaining Certificate of Completion for several of those projects, Phase I and Phase II Site assessments, hazardous waste remediation, construction oversight, project management, asbestos and mold building inspections, and regulatory compliance. She has provided her expertise for site renovation, remediation, residential redevelopment, municipal and industrial projects. She is currently the Environmental Discipline Leader for the Energy + Environment Practice at Bergmann. Ari has extensive experience managing projects that require a variety of different components including: soil, air, and groundwater sampling, data interpretation, analysis, permitting, and reporting, development of Site and Environmental Management Plans, and preparation of detailed project-related specifications.

EXPERIENCE:

Total: 16 Years
Bergmann: >4 Year

EDUCATION:

- Bachelor of Science in Environmental Management and Technology, Rochester Institute of Technology
- Associate of Science in Liberal Arts, Monroe Community College

CERTIFICATIONS

- OSHA 40 Hour Hazardous Waste Operations and Emergency Response
- NYSDOL-licensed Project Designer
- NYSDOL-certified Building Inspector
- NYDOL-certified Mold Assessor

PROFESSIONAL AFFILIATIONS

- Genesee Finger Lakes Chapter Air & Waste Management Association
- Women of Wastewater, Rochester, New York

Project Experience

Dormitory Authority of the State of New York | NYSDEC VCP Site No. V-00463-9 | Groundwater Monitoring, Groundwater Treatment System Operation & Maintenance | Gowanda, NY | Environmental Discipline Leader Responsible for coordinating and scheduling quarterly groundwater sampling and monthly monitoring of a soil vapor extraction system and groundwater treatment system. Review of monthly submissions, quarterly reports, and annual Periodic Review Report. Coordination with DASNY, OPWDD, NYSDEC, and NYSDOH regarding preparation and additional remedial activities towards Site Closure. Preparation, scheduling, and oversight of additional investigative activities.

City of Rochester | Final Engineering Report and Site Management Plan | NYSDEC Site B-00129-8 1200 East Main Street | Rochester, New York | Environmental Discipline Leader Responsible for coordination between stamping professional engineers, communication with the NYSDEC and the City, addressing revisions and comments and ultimately final submittal packages of the Final Engineering Report (FER) and Site Management Plan (SMP) for the City of Rochester 1200 East Main Street Environmental Restoration Project. Due to these efforts, the property has received an executed Certificate of Completion from the NYSDEC.

City of Rochester | Scio Street Brownfield Cleanup | Environmental Remediation and Project Planning | Rochester, New York | Senior Environmental Scientist and Project Planning Responsible for project planning and support for a bioremediation implementation project on a former petroleum spill site. Performed calculations for radius of influence, communicated with injection material supplier to obtain the most effective

product for the Site. Worked in conjunction with company GIS specialist to map out injection program maximizing material impact on the petroleum plume. Coordinated bioremediation injections with the City, company personnel, and subcontractor. Coordinated subsequent groundwater sampling, provided data analysis, and summary report of findings.

DePaul Properties | Environmental Remediation and Management Planning | Upper Falls Site and Housing Redevelopment Project | Rochester, New York | Environmental Project Manager Provided project management, budgeting, staff planning, and frequent communication with the Client, construction contractors, and representatives from the City of Rochester, Monroe County, and State Agencies. Responsible for planning and implementing Phase II assessments for the housing development project on 21 parcels prior to construction. Subsequently prepared an Environmental Management Plan (EMP) to address site conditions throughout all phases of the construction and redevelopment. Responsible for appropriate coordination and approves for disposal of petroleum-impacted and reworked native soil. Provided project oversight to confirm EMP specifications and guidelines were adhered to throughout intrusive work during the Site redevelopment. Planned and executed a bioremediation application to petroleum-impacted area along bedrock in concurrence with the NYSDEC. Attend bi-monthly meetings during peak construction and intrusive activities. Prepared and submitted required monthly project update reports and the Final EMP Progress Report.

Home Leasing | Environmental Remediation and Management Planning | Warfield Square/The Community on East Main Street Site Redevelopment | Rochester, New York | Environmental Project Manager. Provided project management, staff planning, and communication with the Client, and representatives from the City of Rochester, County of Monroe, and State Agencies. Prior to construction conducted Phase II assessments for the housing development project that included six parcels including an on-site HUD lead surface soil survey and submittal of required reports including recommendations for the Site. Prepared the Environmental Management Plan (EMP) in accordance with City requirements to address site conditions throughout all phases of the construction and redevelopment. Responsible for appropriate coordination and approves for disposal of petroleum-impacted and reworked native soil. Project oversight to confirm EMP specifications and guidelines were adhered to throughout intrusive work during the Site redevelopment. Attend bi-monthly meetings during peak construction and intrusive activities. Prepared and submitted required monthly project update reports and the Final EMP Progress Report.

DePaul Properties | Packet Boat Landing Site Redevelopment | Environmental Site Assessments and UST Removal | Lockport, New York | Environmental Project Lead. Responsible for project management of Phase II Environmental site investigative work in preparation for site redevelopment of vacant over 5-acres of land in Lockport, New York. Provided project field support during geoprobe investigation as well as joint soil sampling and oversight during the foundation engineering exploratory test pit excavations. Provided on call Environmental oversight and support during several emergency petroleum tank removals encountered during site redevelopment. Including subcontractor communication and direction, composite sampling for petroleum-impacted soil disposal, contact with disposal facility, confirmatory sampling and appropriate air monitoring and field screening. Responsible for spill reporting, communication with the NSYDEC Region 9 Spills Division, appropriate permitting, required reporting and successful spill closure.

DePaul Properties | Joseph L. Allen Apartments | Environmental Site Assessments and UST Removals | Schenectady, New York | Environmental Project Lead. Responsible for project management of Phase II Environmental site investigative work in preparation for site redevelopment of nine (9) adjoining commercial properties in the City of Schenectady, New York. Provided project field support during several geoprobe investigations including soil and groundwater sampling. Provided on call Environmental oversight and support during several emergency petroleum tank removals encountered during site redevelopment.