Australian Government

Civil Aviation Safety Authority

Aircraft Maintenance Certification Log

VH- CAK

Serial No. 74078

Book No. 1

Date	Aircraft		Maintenance Details and Certifications
	TTIS	Landings or Cycles	
10/8/17	0		CAO 100.5. ANT TRANSPONDOR CHECK. CARRIED OUT ALL S/K.
			.057 FOR AND ON BEHALF OF SMART GROUP A/Asia P/L T/as A.C.S. Certificate of Approval No.C536148 PERSUANT TO CAR 42 ZE
10/8/17	0		AD RAD 47 CARRIED OUT. .057536.
10/8/17	0		CAO 100.5. AIRSPEED / ALT CHECKS CARRIED OUT. 54913
2/8/2018	47,5	163	* Annual inspection C/O as per Casa checklist and Superior M/S.
			* oil drained and replenished with 7 quarts 20W x 50
			* Oil filter replaced, no contamination found in old filter.
			* Seavage filter checked, no debris
			* Spark plugs cleaned, gapped checked, refitted.
			* Compression check C/O satisfactory 75/80 76/80 76/80 76/80.
			* Fire wall fuel gascolator quick drain assy replaced due leaking.
			* Scuff marks on prop. face from spinner removed less than 0.020. Scuff
			marks sanded and blended, anodised and painted as per Whitcoast

Date	Aircraft		Maintenance Details and Certifications
	TTIS	Landings or Cycles	
			props recomendations. Spinner blade openings reworked to clear blades.
			when feathering / cycling prop.
			* Spinner bulk head bolt torqued correctly.
			* Brake actuators removed and air fittings cleaned and refitted assmy.
			567 aerlant: Brake actuators refitted.
			* One new brake pad fitted to L/H brake assembly.
			* Complete brake system bled from bottom up, no leaks evident.
			* All wheel bearings cleaned inspected regreased with mobil 28.
			* 90° angle vent tube fabricated and fitted to solve fuel venting issues.
			* Prop greased with Aeroshell 6
			* SB. 14-01-31 Cracking in bend of Horizontal stab Rear spar C/O no defect
			* SB 16-03-28 Cracking inboard rear spar Aileron web. C/O no defects.
			* SB 14-02-03 Cracking Elevator spar web attachment. C/O no defects.
			* AP./Eng L/H Continuity Airworthiness C/O no defects.

Date	Aircraft		Maintenance Details and Certifications
	TTIS	Landings or Cycles	
			* Engine Air filter cleaned, inspected, recharged with KEW mileage kit.
			* Wing fuel drain orings replaced due to perished and leaking.
			* Aircraft panels and interior refitted as removed.
			* Aircraft found to be serviceable and Airworthy for a period of 12 month, or 100h which ever first.
			* Rec. MR. A 207538 issued.
11/7/18	~~220.7~~ 780140	~~207~~	FITTED BRAKE PADS MAIN WHEELS ONLY SY9113

FOR AND BEHALF OF
OUR ATTICUS
TRADING AS CHOICE
AVIATION SERVICES
1-F771S-2

Date	Aircraft		Maintenance Details and Certifications
	TTIS	Landings or Cycles	
28/2/2019	116,2.	254	* Annual inspection carried out as per Casa checklist 5 and Superior M/S.
			* Oil drained, filter replaced, no debris in old filter, Tgauge A100 uplifted
			* Sparkplugs cleaned, gapped, checked, refitted.
			* Compression check c/o ① 75/80 ② 76/80 ③ 75/80 ④ 75/80.
			* Air filter cleaned and recharged with KEN recharge kit.
			* Prop regreased with Aeroshell 6
			* Prop stone nicks removed from leading edges.
			* Prop CSU adjusted 2 turns in Maintaining 2600 rpm full power
			* Alternator wiring checked, could not fault for alternator dropping off line
			* All wheel bearings cleaned, checked, regreased mobil 28
			* New 500x5 Main wheel Tires fitted P/n 072-312-0. ARC 18/789/NKE/10/18
			ARC 17/106765/NKE/10/B. Inflated to 40 psi
			* Brake system bled from bottom up.
			* Elevator pivot bolts loose at control, washers added and grand, and b

Date	Aircraft		Maintenance Details and Certifications
	TTIS	Landings or Cycles	
			Tightened and play removed from pivot bushes.
			* Two wing spar bolts retorqued and secured.
			* Two wing root bolts Tightened and Torqued as required.
			* Horizontal stabilizer / Vertical fin attachment bolts Torqued checked.
			* OAT probe check carried out, could not fault against motor Temp. gauge.
			* RO/Eng 4th Continuing Airworthiness. C/O no defects
			* SB 14-01-31 Cracks in bend of Horizontal Stab. Fwd spar C/O no defects
			* SB 16-03-28 Cracks inboard rear spar Aileron reb C/O no defects
			* SB 14-02-03 Crack Elevator spar reb attachments C/O no defects
			* Cowlings fasteners adjusted Tighter to suit flush.
			* All removed panels and interior furnishings refitted as removed.
			* Rec MR issued A206476 valid for a year or 100h, which ever first.
			FOR AND BEHALF OF OUR ATTICUS TRADING AS CHOICE AVIATION SERVICES 1-F771S-2 780140

Date	Aircraft		Maintenance Details and Certifications
	TTIS	Landings or Cycles	
23-6-19			ALL PITOT STATIC INSTRUMENTS AND TRANSPONDER SYSTEM TESTED
			SERVICABLE IAW CAO 100.5 AND AD/RAD/47. IFR6000
			S/N 104005033 DUE CAL 19th MARCH 2020. P/S T/S S/N 2133
			DUE CAL 3RD MAY 2020. 527605
28/2/2020	187.2.	321	*Annual inspection C/O as per Casa obedients and Superior Engine M/S.
			*oil drained and replenished with 7 quarts phillips 20w50
			*Compression check C/O satisfactory ① 74/80 ② 75/80 ③ 75/80 ④ 76/80
			*SB 14-01-31 Horizontal Stab RWD. Spar cracks C/O no defects
			*SB 16-05-28 inboard rear spar cracks Ailerons spar C/O no defects
			*SB 14-02-03. Elevator spar web attach point cracks C/O no defects
			*AD/Eng/4 4th Continuing Airworthiness C/O no defects.
			*oil filter changed, no debris in old filter
			*New Brake pads fitted to R/H side

Date	Aircraft		Maintenance Details and Certifications
	TTIS	Landings or Cycles	
			* Air filter cleaned, and recharged KEN. FOR AND BEHALF OF OUR ATTICUS TRADING AS CHOICE AVIATION SERVICES 1-F771S-2
			* Tires inflate 40 psi main and 30 psi nose
			* New MR. issued A250803. 780140.
12/7/20			SLICK MAGS SERVICE BULLETIN, CHANGE GEAR KITS
			S/N 5000703 x (2.) 599113
23/11/20			REPLACE EGT PROBE ON CYC 2 599113
1/12/20			REPLACE FUEL TRANSDUCER. 599113
31/12/20			NEW BATTERY 599113
8/11/21			NEW BACKUP BATTERY FOR DYNON SCREEN 599113

Date	Aircraft		Maintenance Details and Certifications
	TTIS	Landings or Cycles	
2-3-21	267.2		

This Constitutes a Final Certification in Accordance with CAR42ZE as a Loose Leaf Log Book Entry

VH-CAK	Vans RV-7A	AFTIS	267.2	SABC Job #	806
Expired MR # A250803				Issued MR #	66427

Task	Code	Description	Action Taken
1		Periodic inspection	Periodic inspection carried out IAW CASA Schedule 5 and log book statement
2	SB-14-01-31	Horizonal Stabilizer cracks	Carried out - Nil Defects
3	SB-16-03-28	I/B Aileron hinge bracket cracking	Carried out - Nil Defects
4	SB-14-02-03	Elevator Spar cracks	Carried out - Nil Defects
5	AD/Eng 4/A11	Engine Continued Airworthiness	Carried out - Nil Defects

Cylinder Compression Test / 80 psi - Cyl 1 - 77, Cyl 2 - 78, Cyl 3 - 78, Cyl 4 - 78

LAME	Luke Gallin
Licence	527605
Signature	
Date	2nd March 2021

For & on behalf of SABC Maintenance PTY LTD Cert. Of Approval No. C513121

Date	Aircraft		Maintenance Details and Certifications
	TTIS	Landings or Cycles	
24·6·21			ALL PITOT STATIC INSTRUMENTS AND SYSTEMS TESTED SERVICABLE AND
			TRANSPONDER AND ENCODER TESTED SERVICABLE IAW CAO 100·5
			AND AD/RAD/47. OPS450 S/N 50501226 DUE CAL 2/7/21. IFR6000 S/N 104005033
			DUE CAL 8/4/22. 527605
22/7/21			REPLACED PUSH TO TALK BUTTONS/SWITCHES 599113
6/12/21			NOSE BRAKE PADS 599113
1-3-22	326.2		

Date - 1st March 2022 **Aircraft - VH-CAK** **S/N - 74078** **AFTTIS - 326.2**

Annual Inspection carried out IAW CASA Schedule 5.
AD/Eng/4A11 , Carried out servicable - Form 728 attached in Engine logbook
The following vans SB's carried out with nil defects noted....
SB-00006 - Kavlico pressure sensors
SB 16-03-28 - Aft wing web inspection
SB 14-02-05 FWD elevator spar inspection
SB 14-01-31 - Horizontal stabilizer Has been Modified IAW SB 14-01-31

Engine compressions
1 - 78 , 2 - 77 , 3 - 78 , 4 - 78

FOR AND ON BEHALF OF
SABC MAINTENANCE PTY LTD
CERT. OF APPROVAL NO. C513121

Maintenance Release # issued - A165051

Name - Luke Gallin **Signature -** **License** 527605

For and on behalf of SABC Certificate of approval # C513121- Job number 860

Date	Aircraft		Maintenance Details and Certifications
	TTIS	Landings or Cycles	
8-3-22	326.2		PROPELLER BALANCE CARRIED SERVICABLE IAW DYNAVIBE
			USER MANUAL VERSION 1-09. RESULTS 0.08 IPS @ 56° @2470RPM.
			527605
8-3-22	326.2		SERVICE WHEEL BEARINGS (MAIN WHEELS)
			599113
12/1/23	363.2		

Date - 12th Jan 2023 **Aircraft - VH-CAK** **S/N - 74078** **AFTTIS - 363.2**

Annual Inspection carried out IAW CASA Schedule 5.
The following vans SB's carried out with nil defects noted....
SB-00006 - Kavlico pressure sensors
SB 16-03-28 - Aft wing web inspection
SB 14-02-05 FWD elevator spar inspection
SB 14-01-31 - Horizontal stabilizer Has been Modified IAW SB 14-01-31

Engine compressions
1 - 77 , 2 - 79 , 3 - 76 , 4 - 78

Maintenance Release # issued - A165052

FOR AND ON BEHALF OF SABC MAINTENANCE PTY LTD CERT. OF APPROVAL NO. C513121

Name - Luke Gallin **Signature -** **License -** 527605

For and on behalf of SABC Certificate of approval # C513121- Job number 907

Date	Aircraft		Maintenance Details and Certifications
	TTIS	Landings or Cycles	

This Constitutes a Final Certification in Accordance with CAR42ZE as a Loose Leaf Log Book Entry

VH-CAK Model: RV7A AF Serial #: 74078 **Job No:** CAK29924

AF TTIS: 378.00 AF Cycles: AF Landings: **Maintenance Release No:**

Expired M/Release No:

Avionics & IFR Upgrade

The following additional work carried out:

Garmin GMA245 Audio Panel Installed GMS245 IM PN: 190-01879-11
Garmin GNS355 GPS/COM installed IAW Garmin STC SA02636SE
CAO100.5 App1 Para 14, Transponder Periodic Tests Carried out satisfactory
CAO100.5 App1 Para 3, Pitot-static system test Carried out satisfactory
CAO100.5 App1 Para 4,Altimeters & Airdata test Carried out satisfactory
CAO100.5 App1 Para 5, Airspeed indicator test Carried out satisfactory
CAO100.5 App 1 Para 4.6, Automatic Alt. encoders test Carried out satisfactory
Instrument Electrical & Radio Inspections carried out IAW CASA Maint sched IFR.

The following relevant parts were used:

Part #	Description	GRN	Task	Quantity
010-01318-01	GMA 245 Audio Panel With Installation Kit Serial # - 3YL004456	FAV16526		1
010-02232-60	Kit, GNC 355A, w/ GA 35, STC Product Registration 2" GPS/COM Navigator, install rack Serial # -5YS000781	FAV16410		1

For and on behalf of Flight Avionics C of A Number C569309

Co-ordinator's Name: James McDonald **Signature:** ..... **Licence:** **440791** **Date:** 18/07/2023

Date	Aircraft	
	TTIS	Landings or Cycles
1/2/24	405.6	

Maintenance Details and Certifications

This Constitutes a Final Certification in Accordance with CAR42ZE as a Loose Leaf Log Book Entry

VH-CAK Model: VAN'S RV-7A AF Serial #: 74078

AF TTIS: 405.60 AF Cycles: AF Landings:

Job No: CAK-11149

Maintenance Release No: A299734

Expired M/Release No: A165052

BAM Burgess Aircraft Maintenance

Annual

The following maintenance tasks carried out:

Task	Code	Description	Action Taken
001	PERIODIC AIRFRAME	100 Hour / 12 Month Inspection as per CAAP42B-1(2.3)	Carried out law CAAP42B-1(2.3)
002	PERIODIC ENGINE	100 Hour / 12 Month Inspection as per CAAP42B-1	Carried out law CAAP42B-1(2.3)
003	AD/ENG/4 Amdt 11	Piston Engine Continuing Airworthiness Requirements	Carried out law AD/ENG/4 AMDT 11
004	AD/LYC/78 Amdt 6	Thermostatic Oil Cooler Bypass Valve	Carried out law AD/LYC/78 AMDT 6 - nil defects evident
005	SB-00036	O/B elevator hinge on hori stab rear spar inspection	Carried out law SB-00036 - nil defects evident.
006	SB 16-03-28	Aft wing spar web inspection	Carried out law SB 16-03-28 - nil defects evident.
007	SB 14-02-05	FWD elevator spar inspection	Carried out law SB 14-02-05 - nil defects evident
008	SB 14-01-31	Horizontal stabilizer	Carried out law SB 14-01-31 - nil defects evident.
009	SB 00080	Oil cooler inspection (Check for relvance)	N/A - not in serial number range. Complied with SB0001 - Nil defects evident
010	SB 00090	Dynon SV-AP-PANEL runaway trim (Check for relevance)	N/A due serial number range.
011	SB-0006	Kavlico pressure sensors	Carried out law SB-0006- nil deects evident
012	PERIODIC PROPELLER	100 Hour / 12 Month Inspection as per CAAP42B-1	Carried out law CAAP42B-1(2.3).
013	Additional Work	RH rudder cable rubbing full lock on rib.	Filed rib to required clearance law RV-7A Builders Manual.
014	Additional Work	Floor support rib cracked.	Rib repaired law RV-7A Builders Manual and AC43.13-1B Section 4 Para 4-58.
015	Additional Work	Worn brake pads on main wheels	Both main wheel brake pads replaced law RV-7A Builders Manual.
016	Additional Work	Rivet defects found fuselage and longeron rear section.	Rivets either drilled out and replaced or re-riveted law AC43.13-1B Section 4 Para 4-50 to 57.

The following relevant parts were used:

Part #	Description	GRN	Task	Quantity
D-436-37	ENVIRO Splice Blue	S220724-43		1
MS24693-C028	SS Machine Screw [6-32 x 1/2"]	S230615-13	001	1
AA48108-2	Oil Filter thread 3/4-16	S231108-04	002	1
MS35769-21	Copper Gasket - Crush Washer	S190804-2	002	1
SOS3	Oil Analysis Kit	S230925-01	002	1
W100PLUS	W100 Plus Oil - Owner Supplied	S250124-1	002	6
MS20470AD4-3	ALUM RIVET	S160208-1	014	4
APS66-10600	APS Brake Lining	S230905-05	015	4
RA105-002	Rivet - Brake lining	S220428-21	015	12
10P8-11 EPOXY A PRIMER	Epoxy Primer Base Component A	S230912-01	016	10
10P8-11 EPOXY B PRIMER	Epoxy Primer Component B	S230912-02	016	10

For and on behalf of Burgess Aircraft Maintenance Pty Ltd C of A Number 0777

Co-ordinator's Name: Frank Ragonese **Signature:** ..... **Licence:** 511650 **Date:** 01/02/2024

Date	Aircraft		Maintenance Details and Certifications
	TTIS	Landings or Cycles	
23/4/24	405.6		**This Constitutes a Final Certification in Accordance with CAR42ZE as a Loose Leaf Log Book Entry** VH-CAK Model: VAN'S RV-7A AF Serial #: 74078 **Job No:** CAK-11188 AF TTIS: 405.60 AF Cycles: AF Landings: **Maintenance Release No:** **Expired M/Release No:** BAM Burgess Aircraft Maintenance **Leak in Both Fuel Tanks** **The following maintenance tasks carried out:** **Task** **Code** **Description** **Action Taken** 001 Additional Work Leak in both LH and RH fuel tanks Both LH and RH fuel tanks drained, removed from aircraft and rebuilt. Tanks refitted and leak checked ok. All law Vans Build Manual. 002 Additional Work Spark Plugs U/S All spark plugs replaced and tested ok as per Lycoming OHM. **For and on behalf of Burgess Aircraft Maintenance Pty Ltd C of A Number 0777** **Co-ordinator's Name:** James Veall **Signature:**..... **Licence:** 130053 **Date:** 23/04/2024
			This Constitutes a Final Certification in Accordance with CAR42ZE as a Loose Leaf Log Book Entry VH-CAK Model: VAN'S RV-7A AF Serial #: 74078 **Job No:** CAK-11531 AF TTIS: 444.60 AF Cycles: AF Landings: **Maintenance Release No:** **Expired M/Release No:** BAM Burgess Aircraft Maintenance **Non-standard riveting - Engineering Order.** **The following maintenance tasks carried out:** **Task** **Code** **Description** **Action Taken** 001 Additional Work Carry out continuing airworthiness requirements law EO# 240821-1. EO# 240821-1 complied with for poor riveting standards on VH-CAK. **For and on behalf of Burgess Aircraft Maintenance Pty Ltd C of A Number 0777** **Co-ordinator's Name:** James Veall **Signature:**..... **Licence:** 130053 **Date:** 31/01/2025
31/1/25	444.60		

Date	Aircraft		Maintenance Details and Certifications
	TTIS	Landings or Cycles	
11/2/25	445.10	10	

This Constitutes a Final Certification in Accordance with CAR42ZE as a Loose Leaf Log Book Entry

BAM Burgess Aircraft Maintenance

VH-CAK Model: VAN'S RV-7A AF Serial #: 74078

AF TTIS: 445.10 AF Cycles: AF Landings:

Job No: CAK-11570

Maintenance Release No: A334665

Expired M/Release No: A299734

Annual

The following maintenance tasks carried out:

Task	Code	Description	Action Taken
001	PERIODIC AIRFRAME	100 Hour / 12 Month Inspection as per CAAP42B-1	Carried out iaw CAAP42B.1.
002	PERIODIC ENGINE	100 Hour / 12 Month Inspection as per CAAP42B-1	Carried out iaw CAAP42B.1.
003	AD/ENG/4 Amdt 11	Piston Engine Continuing Airworthiness Requirements	Carried out iaw AD/ENG/4 AMDT 11 - NDE
004	AD/LYC/78 Amdt 6	Thermostatic Oil Cooler Bypass Valve (Check for relevance)	Carried out previously at 378 TTIS - Not due until 1003hrs
005	SB480F	50 hour oil and filter	Carried out iaw SB480F - NDE
006	SB-00080 REV 2	Inspection of EA-00002 Oil Cooler for Possible Leaks - Check for compliance	SB-00080 REV 2 not relevant to this aircraft.
007	SB 16-03-28	Aft wing spar web inspection	Carried out iaw SB 16-03-28 - NDE.a
008	SB 14-02-05	FWD elevator spar inspection	Carried out iaw SB 14-02-05 - NDE
009	SB-00036	O/B elevator hinge on hori stab rear spar inspection	Carried out iaw SB-00036 - NDE.
010	PERIODIC PROPELLER	100 Hour / 12 Month Inspection as per CAAP42B-1	Carried out iaw CAAP42B-1.
011	SB-00103	Dynon Canopy Warning Software/Settings - Check for Compliance	N/A - Not fitted to aircraft.
012	SB-0006	Kavlico pressure sensors	Carried out iaw SB-0006 - NDE.
013	EO 240821-1	Inspection of Non-standard riveting.	Carried out iaw EO 240821-1 - NDE
014	Additional Work	Fuel leaks near aux fuel pump.	Fittings cleaned and refitted iaw AC43.13 Section 2 P8-31.
015	Additional Work	RH brake slave cylinder leaking.	Seal replaced iaw Matco WE51H Manual.
016	Additional Work	Nosewheel bearing U/S	Bearing replaced iaw RV7 Build manual.
017	Additional Work	Both LH and RH tanks leaking fuel.	Resealed iaw RV7 Builders Manual.
018	Additional Work	Flap motor continues to run past bottom stop.	Flap microswitch control rod adjusted iaw RV7 Build Manual.

For and on behalf of Burgess Aircraft Maintenance Pty Ltd C of A Number 0777

Co-ordinator's Name: Alastair Hall **Signature:**..... **Licence:** 435034 **Date:** 11/02/2025

Date	Aircraft		Maintenance Details and Certifications
	TTIS	Landings or Cycles	
9/4/26	456.7		

This Constitutes a Final Certification in Accordance with CAR42ZE as a Loose Leaf Log Book Entry

BAM Burgess Aircraft Maintenance

VH-CAK Model: VAN'S RV-7A AF Serial #: 74078 Job #: CAK-11947

AF TTIS: 456.70 AF Cycles: AF Landings: M/R #:

Expired M/R #: A334665

Periodic Airframe and Engine

The following maintenance tasks carried out:

Task	Code	Description	Action Taken
001	PERIODIC AIRFRAME	100 Hour / 12 Month Inspection as per CAAP42B-1	C/O IAW CAAP42B-1 v2.3.
002	PERIODIC ENGINE	100 Hour / 12 Month Inspection as per CAAP42B-1	C/O IAW CAAP42B-1 v2.3.
003	PERIODIC PROPELLER	100 Hour / 12 Month Inspection as per CAAP42B-1	C/O IAW CAAP42B-1 v2.3.
004	AD/ENG/4 Amdt 11	Piston Engine Continuing Airworthiness Requirements	C/O IAW AD/ENG/4 AMDT 11, NDE.
005	AD/LYC/78 AMDT 6	Thermostatic Oil Cooler Bypass Valve (Check for relevance)	N/A Due P/N starts with (SL). Locking nut is held in position with roll pin. NOT crimped as per AD/LYC/78 AMDT 6.
006	SB-0006	Kavlico pressure sensors	C/O IAWSB-0006, NDE.
007	SB 16-03-28	Aft wing spar web inspection	C/O IAW SB 16-03-28 AFT, NDE.
008	SB 14-02-05	FWD elevator spar inspection	C/O IAW SB 14-02-05 FWD, NDE.
009	SB-00036	O/B elevator hinge on hori stab rear spar inspection	C/O IAW SB-00036 O/B, NDE.
010	SB480F	50 hour oil and filter	C/O IAW SB480F, NDE.
011	EO 240821-1	Inspection of Non-standard riveting.	C/O IAWEO 240821-1, NDE.
012	CAO100.5 APP1 PARA 3, 4, 4.6 & 14	Pitot/static leak test, altimeter calibration, encoder calibration and transponder test.	C/O IAW CAO100.5 APP1 PARA 3, 4, 4.6 & 14, NDE.
013	AWB34-008	Compass Calibration	C/O IAW AWB34-008, all errors within 2%. FOR: N 30 60 E 120 150 STR: 001 032 061 090 121 152 FOR: 180 210 240 W 300 330 STR: 179 210 240 271 300 329
014	Additional Work	LH Tyre Low PSI	Pumped up as required, C/O IAW Rv-7A Builders Manual, NDE.
015	Additional Work	Wheel Spat Brackets Loose Both Wheels.	Main bolts tightened, IAW Rv-7A Builders Manual.

The following compass swing(s) carried out:

Compass Name	0 N	030	060	090 E	120	150	180 S	210	240	270 W	300	330
Magnetic	001	032	061	090	121	152	179	210	240	271	300	329

The following relevant parts were used:

Part #	Description	GRN	Task	Quantity
AA48108-2	Oil Filter thread 3/4-16	2178	002	1
W100PLUS	W100 Plus Oil	2209	002	8

For and on behalf of Burgess Aircraft Maintenance Pty Ltd C of A Number 0

Co-ordinator's Name: James Veall **Signature:**..... **Licence:** 130053 **Date:** 09/04/2026