⊕ Trimble

What's New April 2024
Contents

This document contains a full record of all content revisions contained within the April 2024 Design Suite content update. To apply content updates to your application follow the below instructions.

Automatic data updates are user defined within the 'Check for Updates' tab under 'Application Settings'. Once applied, a check will be made for a new package upon every launch of the application. If a new package is found, you will be prompted to install it now or later. Once installed, the application will be restarted.

Manual data updates are run at users' discretion. If your application is not set to automatically check for data updates, you can manually check by going to the 'Check for Updates' tab under 'Application Settings' and clicking 'Check Now'. If a new package is found, you will be prompted to install it now or later. Once installed, the application will be restarted.

Section 1	Summary
Modified Content	Protective Devices: Proteus (MEPED-726) Schneider (MEPED-752) *See Section 2 for details*

Section 2	Detailed Content Changes

Protective Devices

Proteus

Modified content

- o MEPED-726 – MC MCCB update.

  The MC MCCB range has had the following updates:
  - o The time/current curves have been updated in accordance with Proteus's latest datasheets. The device will need to be reselected to see the update changes.
  - o The layout in the Protective Devices Selector has been simplified, all devices are now covered under the MC MCCB family.
  - o Addition of MC MCCB devices with earth leakage protection, Type A and B.

Schneider

Modified content

- o MEPED-752 – Bug fix affecting the MasterPacT MTZ ACB devices, which only allowed the overload to be set to a maximum value of 400A, regardless of device rating. The device will need to be reselected to see the update changes.