APPENDIX A. Finish Codes

SECTION A. ALUMINUM ALLOYS

CODE	APPLICABLE FINISH

A797 **CHEMICAL FILM**
ALL ALUMINUM ALLOYS

A CLEAN AND BRUSH CHEM FILM ALL SURFACES PER 168.
B TOUCH UP AS REQUIRED PER 354.
C (INACTIVE FOR NEW DESIGN).

A798 **PRIMER, WHITE URETHANE, AND 16NXXXX FINISH**
BARE 2000 AND 7000 SERIES ALUMINUM ALLOYS

A ANODIZE ALL SURFACES PER 111.
B PRIME 2 COATS ALL SURFACES PER 204.
C PAINT INTERIOR SURFACES WITH WHITE URETHANE COATING PER 222 (OR 274).
D FINISH EXTERIOR EXPOSED SURFACE AFTER ASSEMBLY PER 16N0001.
E TOUCH UP AS REQUIRED PER 236, 242 OR 237.

A799 **SOLID FILM LUBRICANT**
CLAD OR 1000, 3000, 5000, OR 6000 SERIES ALUMINUM ALLOYS AND ALUMINUM CASTINGS

A CHEM FILM ALL SURFACES PER 105.
B APPLY SOLID FILM LUBRICANT TO ALL SURFACES PER 228.

A800 **FMS-3014 FORM 2 ADHESIVE PRIMER**
BARE 2000 AND 7000 SERIES ALUMINUM ALLOYS

A ANODIZE ALL SURFACES PER 111.
B APPLY FMS-3014 FORM 2 ADHESIVE PRIMER TO ALL SURFACES PER 400.
C TOUCH UP AS REQUIRED PER 401 (OR 402 AS APPLICABLE).

A801 **FMS-3014 FORM 2 ADHESIVE PRIMER AND WHITE URETHANE**
BARE 2000 AND 7000 SERIES ALUMINUM ALLOYS

A ANODIZE ALL SURFACES PER 111.
B APPLY FMS-3014 FORM 2 ADHESIVE PRIMER TO ALL SURFACES PER 400.
C PAINT SPECIFIED SURFACES WITH URETHANE COATING;
WHITE COLOR NUMBER 17875 OR WHITE COLOR NUMBER 17925 PER 406
D TOUCH UP AS REQUIRED PER 237, 401 (OR 402 AS APPLICABLE), AND 404.

A802 **FMS-3014 FORM 2 ADHESIVE PRIMER**
BARE 2000 AND 7000 SERIES ALUMINUM ALLOYS

A ANODIZE ALL SURFACES PER 111.
B APPLY FMS-3014 FORM 2 ADHESIVE PRIMER TO ALL SURFACES PER 400.
C TOUCH UP AS REQUIRED PER 401 (OR 402 AS APPLICABLE).
D (SEE A800 FOR PREFERRED CODE).

NOTE: A802 IS DUPLICATE CODE OF A800. DO NOT USE A802 FOR NEW DESIGN.

A803 **FMS-3014 FORM 2 ADHESIVE PRIMER AND 16NXXXX FINISH**
BARE 2000 AND 7000 SERIES ALUMINUM ALLOYS

A ANODIZE ALL SURFACES PER 111.
B APPLY FMS-3014 FORM 2 ADHESIVE PRIMER TO SPECIFIED SURFACES AND SURFACES EXPOSED TO FUEL PER 403.
C PRIME EXTERIOR EXPOSED SURFACES WITH ONE COAT OF PRIMER PER 202.
D FINISH EXTERIOR EXPOSED SURFACES AFTER ASSEMBLY PER DRAWING 16NXXXX.
E TOUCH UP AS REQUIRED PER 235 AND 401 (OR 402 AS APPLICABLE).