APPENDIX A. Finish Codes

SECTION A. ALUMINUM ALLOYS

CODE	APPLICABLE FINISH
A804	**PRIMER, FMS-3014 FORM 2 ADHESIVE PRIMER, AND 16NXXXX FINISH. BARE 2000 & 7000 SERIES ALLOYS (WITH PART OF EXTERIOR SURFACE COVERED).**
	A ANODIZE ALL SURFACES PER 111.
	B APPLY FMS-3014 FORM 2 ADHESIVE PRIMER TO SPECIFIED INTERIOR SURFACES AND SURFACES EXPOSED TO FUEL PER 403.
	C PRIME EXTERIOR COVERED SURFACE (AS NOTED ON DRAWING) WITH TWO COATS OF PRIMER PER 205 (OR 245).
	D PRIME REMAINING EXTERIOR EXPOSED SURFACES WITH ONE COAT OF PRIMER PER 202.
	E FINISH EXTERIOR EXPOSED SURFACE AFTER ASSEMBLY PER DRAWING 16NXXXX.
	F TOUCH UP AS REQUIRED PER 235,236,242,& 401 (OR 402 AS APPLICABLE.
A805	**FMS-3014 FORM 2 ADHESIVE PRIMER CLAD OR 1000, 3000, 5000, OR 6000 SERIES ALUMINUM ALLOYS AND ALUMINUM CASTINGS (EXCEPT TUBING)**
	A CHEM FILM ALL SURFACES PER 105.
	B APPLY FMS-3014 FORM 2 ADHESIVE PRIMER TO ALL SURFACES PER 400.
	C TOUCH UP AS REQUIRED PER 401 (OR 402 AS APPLICABLE).
A806	**FMS-3014 FORM 2 ADHESIVE PRIMER BARE 2000 AND 7000 SERIES ALUMINUM ALLOYS**
	A ANODIZE ALL SURFACES PER 111.
	B APPLY FMS-3014 FORM 2 ADHESIVE PRIMER TO ALL SURFACES PER 400.
	C TOUCH UP AS REQUIRED PER 401 (OR 402 AS APPLICABLE).
	D (SEE A800 FOR PREFERRED CODE).
	NOTE: A806 IS DUPLICATE CODE OF A800. DO NOT USE A806 FOR NEW DESIGN.
A807	**FMS-3014 FORM 2 ADHESIVE PRIMER, WHITE URETHANE, AND 16NXXXX FINISH BARE 2000 AND 7000 SERIES ALUMINUM ALLOYS**
	A ANODIZE ALL SURFACES PER 111.
	B APPLY FMS-3014 FORM 2 ADHESIVE PRIMER TO SPECIFIED SURFACES AND SURFACES EXPOSED TO FUEL PER 403.
	C PAINT SPECIFIED SURFACES WITH WHITE URETHANE; COLOR NO.17875 OR COLOR NO. 17925 PER 406.
	D PRIME EXTERIOR EXPOSED SURFACES WITH ONE COAT OF PRIMER PER 202.
	E FINISH EXTERIOR EXPOSED SURFACES AFTER ASSEMBLY PER DRAWING 16NXXXX.
	F TOUCH UP AS REQUIRED PER 235, 236, 242,(CONT'D IN NEXT STEP)
	G (CONT'D FROM PREV STEP) 401, (OR 402 AS APPLICABLE), & 404.