APPENDIX A. Finish Codes

SECTION A. ALUMINUM ALLOYS

CODE	APPLICABLE FINISH
A808	**PRIMER, FMS-3014 FORM TWO ADHESIVE PRIMER, WHITE URETHANE, & 16NXXXX FINISH. BARE 2000 OR 7000 SERIES AL ALLOYS USED FOR LOWER WING SKINS**
	A ANODIZE NOTED SURFACES PER 114.
	B CHEM FILM REMAINING SURFACES PER 134.
	C APPLY FMS-3014 FORM 2 ADHESIVE PRIMER TO INTERIOR SURFACES AND SURFACES EXPOSED TO FUEL PER 403.
	D PRIME EXTERIOR COVERED SURFACES (AS NOTED ON DRAWING) WITH TWO COATS OF PRIMER PER 205 (OR 245).
	E APPLY TEFLON-URETHANE COATING TO THE SPECIFIED PRIMED AREA AS SPECIFIED ON APPLICABLE 16NXXXX AIRCRAFT PAINTING DRAWING
	F PRIME EXTERIOR SURFACES EXPOSED IN COVE AREAS AND EXTERIOR NON-COVERED SURFACES WITH ONE COAT OF PRIMER PER 202.
	G APPLY WHITE URETHANE COATING TO EXTERIOR SURFACES EXPOSED IN COVE AREAS PER 222 (OR 274).
	H FINISH EXTERIOR EXPOSED SURFACE AFTER ASSEMBLY PER DRAWING 16NXXXX.
	I TOUCH UP AS REQUIRED PER 235, 236, 237,(CONT'D IN NEXT STEP)
	J (CONT'D FROM PREV STEP) 242, 298, AND 401 (OR 402 AS APPLICABLE).
A809	**FMS-3014 FORM 2 ADHESIVE PRIMER AND GRAY URETHANE BARE 2000 AND 7000 SERIES ALUMINUM ALLOYS**
	A ANODIZE ALL SURFACES PER 111.
	B APPLY FMS-3014 FORM 2 ADHESIVE PRIMER TO SPECIFIED SURFACES AND SURFACES EXPOSED TO FUEL PER 403.
	C PRIME EXTERIOR SURFACES REQUIRING GRAY COLOR WITH ONE COAT OF PRIME PER 202.
	D PAINT SPECIFIED EXTERIOR SURFACES WITH GRAY COLOR NUMBER 36270 URETHANE COATING PER 290.
	E TOUCH UP AS REQUIRED PER 291 AND 401 (OR 402 AS APPLICABLE).
A810	**FMS-3014 FORM 2 ADHESIVE PRIMER AND WHITE URETHANE BARE 2000 AND 7000 SERIES ALUMINUM ALLOYS**
	A ANODIZE ALL SURFACES PER 111.
	B APPLY FMS-3014 FORM 2 ADHESIVE PRIMER TO ALL SURFACES PER 400.
	C PAINT SPECIFIED SURFACES WITH WHITE URETHANE; COLOR NO.17875 OR COLOR NO. 17925 PER 406.
	D TOUCH UP AS REQUIRED PER 236, 401 (OR 402 AS APPLICABLE), AND 404.