APPENDIX A. Finish Codes

SECTION A. ALUMINUM ALLOYS

CODE	APPLICABLE FINISH
A811	**FMS-3014 FORM 2 ADHESIVE PRIMER AND 16NXXXX FINISH BARE 2000 AND 7000 SERIES ALUMINUM ALLOYS**
	A ANODIZE ALL SURFACES PER 111.
	B APPLY FMS-3014 FORM 2 ADHESIVE PRIMER TO SPECIFIED INTERIOR SURFACES AND SURFACES EXPOSED TO FUEL PER 403.
	C PRIME REMAINING EXTERIOR SURFACES WITH ONE COAT OF PRIMER PER 202.
	D PAINT SPECIFIED EXTERIOR SURFACES WITH TEFLON-URETHANE COATING AS SPECIFIED ON APPLICABLE 16NXXXX AIRCRAFT PAINTING DRAWING. (OVERSPRAY ONTO FAYING SURFACES IS NOT PERMITTED).
	E FINISH REMAINING EXTERIOR SURFACES AFTER ASSEMBLY PER DRAWING 16NXXXX.
	F TOUCH UP AS REQUIRED PER 235, 236, 242,(CONT'D IN NEXT STEP)
	G (CONT'D FROM PREV STEP) 298, AND 401 (OR 402 AS APPLICABLE)
A812	**FMS-3014 FORM 2 ADHESIVE PRIMER AND 16NXXXX FINISH BARE 2000 AND 7000 SERIES ALUMINUM ALLOYS (FINISH INACTIVE FOR NEW DESIGN; USE A811.)**
	A ANODIZE ALL SURFACES PER 111.
	B APPLY FMS-3014 FORM 2 ADHESIVE PRIMER TO SPECIFIED INTERIOR SURFACES AND SURFACES EXPOSED TO FUEL PER 403.
	C PRIME REMAINING EXTERIOR SURFACES WITH ONE COAT OF PRIMER PER 202.
	D PAINT SPECIFIED EXTERIOR SURFACES WITH TEFLON-URETHANE COATING AS SPECIFIED ON APPLICABLE 16NXXXX AIRCRAFT PAINTING DRAWING. (OVERSPRAY ONTO FAYING SURFACE IS NOT PERMITTED).
	E FINISH SPECIFIED EXTERIOR SURFACES AFTER ASSEMBLY PER DRAWING 16N0001.
	F TOUCH UP AS REQUIRED PER 235, 236, 242,(CONT'D IN NEXT STEP)
	G (CONT'D FROM PREV STEP) 298, AND 401 (OR 402 AS APPLICABLE).
A813	**FMS-3014 FORM 2 ADHESIVE PRIMER, WHITE ACRYLIC LACQUER/WHITE URETHANE, AND 16NXXXX FINISH BARE 2000 AND 7000 SERIES ALUMINUM ALLOYS**
	A ANODIZE ALL SURFACES PER 111.
	B APPLY FMS-3014 FORM 2 ADHESIVE PRIMER TO SPECIFIED INTERIOR SURFACES AND SURFACES EXPOSED TO FUEL PER 403.
	C PRIME REMAINING SURFACES WITH ONE COAT OF PRIMER PER 202.
	D PAINT SPECIFIED SURFACES WITH EITHER WHITE ACRYLIC LACQUER OR WHITE URETHANE COATING PER 407.
	E FINISH EXTERIOR EXPOSED SURFACES AFTER ASSEMBLY PER DRAWING 16N0001.
	F TOUCH UP AS REQUIRED PER 235, 242, 401 (OR 402 AS APPLICABLE), AND 405.
A814	**FMS-3014 FORM 2 ADHESIVE PRIMER AND 16NXXXX FINISH BARE 2000 AND 7000 SERIES ALUMINUM ALLOYS**
	A ANODIZE ALL SURFACES PER 111.
	B APPLY FMS-3014 FORM 2 ADHESIVE PRIMER TO INTERIOR SURFACES AND SURFACES EXPOSED TO FUEL AS NOTED ON THE DRAWING PER 403
	C PRIME EXTERIOR EXPOSED SURFACES WITH ONE COAT OF PRIMER PER 202.
	D FINISH EXTERIOR EXPOSED SURFACES AFTER ASSEMBLY PER DRAWING 16N0001.
	E TOUCH UP AS REQUIRED PER 235, 236, 242, AND 401 (OR 402 AS APPLICABLE).