APPENDIX A. Finish Codes

SECTION A. ALUMINUM ALLOYS

CODE	APPLICABLE FINISH
A815	**PRIMER, FMS-3014 FORM 2 ADHESIVE PRIMER, AND WHITE URETHANE BARE 2000 AND 7000 SERIES ALUMINUM ALLOYS**
	A ANODIZE ALL SURFACES PER 111.
	B APPLY FMS-3014 FORM 2 ADHESIVE PRIMER TO SPECIFIED SURFACES AND SURFACES EXPOSED TO FUEL PER 403.
	C PAINT SPECIFIED SURFACES WITH WHITE URETHANE COATING; COLOR NO. 17875 OR COLOR NO. 17925 PER 406.
	D PRIME EXTERIOR EXPOSED SURFACES WITH ONE COAT OF PRIMER PER 202.
	E TOUCH UP AS REQUIRED PER 235, 236, 242,(CONT'D IN NEXT STEP)
	F (CONT'D FROM PREV STEP) 401 (OR 402 AS APPLICABLE) AND 404.
A816	**PRIMER AND FMS-3014 FORM 2 ADHESIVE PRIMER BARE 2000 AND 7000 SERIES ALUMINUM ALLOYS**
	A ANODIZE ALL SURFACES PER 111.
	B APPLY FMS-3014 FORM 2 ADHESIVE PRIMER TO SPECIFIED SURFACES AND SURFACES EXPOSED TO FUEL PER 403.
	C PRIME EXTERIOR EXPOSED SURFACES WITH ONE COAT OF PRIMER PER 202.
	D TOUCH-UP AS REQUIRED PER 242 AND 401 (OR 402 AS APPLICABLE).
A817	**FMS-3014 FORM 2 ADHESIVE PRIMER CLAD OR 1000, 3000, 5000, OR 6000 SERIES ALUMINUM ALLOYS AND ALUMINUM CASTINGS (EXCEPT TUBING).**
	A CHEM FILM ALL SURFACES PER 105.
	B APPLY FMS-3014 FORM 2 ADHESIVE PRIMER TO ALL SURFACES PER 400.
	C TOUCH UP AS REQUIRED PER 401 (OR 402 AS APPLICABLE).
	D (SEE A805 FOR PREFERRED CODE).
	NOTE: A817 IS DUPLICATE CODE OF A805. DO NOT USE A817 FOR NEW DESIGN.
A818	**FMS-3014 FORM 2 ADHESIVE PRIMER AND HARD ANODIZE BARE 2000 AND 7000 SERIES ALUMINUM ALLOYS**
	A HARD ANODIZE SPECIFIED SURFACES PER 115.
	B ANODIZE REMAINING SURFACES PER 114.
	C APPLY FMS-3014 FORM 2 ADHESIVE PRIMER TO SPECIFIED SURFACES PER 403.
	D TOUCH UP AS REQUIRED PER 401 (OR 402 AS APPLICABLE).
A819	**FMS-3014 FORM 2 ADHESIVE PRIMER AND HARD ANODIZE CLAD OR 1000, 3000, 5000, OR 6000 SERIES ALUMINUM ALLOYS AND CASTINGS**
	A HARD ANODIZE SPECIFIED SURFACES PER 115.
	B CHEM FILM REMAINING SURFACES PER 134.
	C APPLY FMS-3014 FORM 2 ADHESIVE PRIMER TO SPECIFIED SURFACES PER 403.
	D TOUCH UP AS REQUIRED PER 401 (OR 402 AS APPLICABLE).
A820	**FMS-3014 FORM 2 ADHESIVE PRIMER BARE 2000 AND 7000 SERIES ALUMINUM ALLOYS**
	A ANODIZE ALL SURFACES PER 111.
	B APPLY FMS-3014 FORM 2 ADHESIVE PRIMER TO SPECIFIED SURFACES PER 403.
	C TOUCH UP AS REQUIRED PER 401 (OR 402 AS APPLICABLE).