APPENDIX A. Finish Codes

SECTION T. TITANIUM AND TITANIUM ALLOYS

CODE	APPLICABLE FINISH
T406	**PRIMER AND 16NXXXX FINISH.** **ALL TITANIUM ALLOYS.** A CLEAN AND APPLY CONVERSION TREATMENT TO ALL SURFACES PER 151 B PRIME SPECIFIED SURFACES ONE COAT PER 202. C FINISH EXTERIOR EXPOSED SURFACES AFTER ASSEMBLY PER DRAWING 16N0001. D TOUCH UP AS REQUIRED PER 342.
T407	**PRIMER AND BLACK EPOXY ENAMEL/BLACK URETHANE.** **ALL TITANIUM ALLOYS.** A CLEAN PER 145. B PRIME ONE COAT ALL SURFACES PER 201. C PAINT SPECIFIED SURFACES WITH BLACK EPOXY ENAMEL OR BLACK URETHANE PER 213. D TOUCH UP AS REQUIRED PER 323.
T408	**PRIMER AND DARK GRAY URETHANE. TITANIUM ALLOYS.** A CLEAN AND APPLY CONVERSION TREATMENT TO ALL SURFACES PER 151 B PRIME SPECIFIED SURFACES ONE COAT PER 202. C PAINT PRIMED SURACES WITH DARK GRAY URETHANE COATING PER 527. D TOUCH UP AS REQUIRED PER 528.
T409	**PRIMER AND DARK GRAY URETHANE. TITANIUM ALLOYS.** A CLEAN AND APPLY CONVERSION TREATMENT TO ALL SURFACES PER 151 B PRIME ALL SURFACES ONE COAT PER 201. C PAINT ALL SURACES WITH DARK GRAY URETHANE COATING PER 529. D TOUCH UP AS REQUIRED PER 528.
T410	**WHITE ACRYLIC LACQUER/WHITE URETHANE AND 16NXXXX FINISH TITANIUM ALLOYS.** A CLEAN PER 145. B PRIME ONE COAT SPECIFIED SURFACES PER 202. C PAINT INTERIOR SURFACES WITH EITHER WHIT ACRYLIC LACQUER OR WHITE URETHANE COATING PER 294 (OR 296). D FINISH EXTERIOR EXPOSED SURFACE AFTER ASSEMBLY PER DRAWING 16N0001. E TOUCH UP AS REQUIRED PER 341, 343, AND 345.
T411	**WHITE URETHANE AND 16NXXXX FINISH TITANIUM ALLOYS** A CLEAN AND APPLY CONVERSION TREATMENT TO ALL SURFACES PER 151 OR CLEAN AND ABRADE ALL SURFACES PER 183. B PRIME ONE COAT ALL SURFACES PER 531. C PAINT INTERIOR SURFACES WITH WHITE URETHANE COATING PER 222 (OR 274). D FINISH EXTERIOR EXPOSED SURFACE AFTER ASSEMBLY PER THE APPLICABLE 16NXXXX PAINTING DRAWING. E TOUCH UP AS REQUIRED PER 341 AND 342. F NOTE: FOR APPLICATION OF FMS-3049 COATING; SEE MATERIALS AND PROCESSES ENGINEERING FOR USE.