APPENDIX B. Basic Elements

Basic Element	Basic Element Step(s)
381	THE APPLICATION OF BLUE PAINT MAY BE DELAYED TO A SUBSEQUENT ASSEMBLY LEVEL. IF BLUE PAINT IS APPLIED AT A LATER TIME, PREVIOUSLY PRIMED SURFACES SHALL BE SOLVENT CLEANED (MIL-C-38736* OR FMS-2004), SCUFFED TO REMOVE GLOSS WITH 320 GRIT SANDPAPER OR "SCOTCHBRITE", RE-WIPED WITH SOLVENT CLEANER, THEN MIST COATED WITH FMS-3027, MIL-PRF-23377, OR MIL-PRF-85582 PRIMER, FOLLOWED BY TWO COATS OF URETHANE, BLUE COLOR 35109, PER MIL-C-83286 OR MIL-C-85285 APPLIED TO ALL EXPOSED SURFACES. *NOTE: P6174 NON-AROMATIC CLEANER MAY BE USED IN LIEU OF MIL-C-38736 CLEANER. (REFERENCE CR 1345 FOR COPRODUCER USE.)
382	RESTORE CORROSION PROTECTION TO EDGES AND SURFACES (E.G., HOLES, COUNTERSINKS, SPOTFACES, ETC.) OF CORROSION RESISTANT STEEL ALLOYS THAT HAVE BEEN MACHINED AFTER INITIAL CORROSION PROTECTION HAS BEEN APPLIED. FOR PAINTED SURFACES, CLEAN PER FPS-3001, PARA. 3.1.3(A). TOUCH UP WITH ONE COAT OF FMS-3027, MIL-PRF-23377, MIL-PRF-85582, OR FMS-1058-1 PRIMER, FOLLOWED BY TWO COATS OF MIL-C-83286 OR MIL-C-85285 BLUE URETHANE COATING, COLOR 35109.
400	APPLY FMS-3014 FORM 2 ADHESIVE PRIMER TO ALL SURFACES PER FPS-3035.