6. CERTIFICATION

6.1 Producer: With each shipment of raw material (including extrusions and rolled rings), the producer shall furnish a certified report (in triplicate) stating the specific results of the acceptance tests required in paragraph 4.2. This report shall also include the purchase order numbr, heat number, size and quantity from each heat, and this specification number.

6.2 Subcontractor: When raw material for subcontract parts is purchased directly by a part subcontractor, the subcontractor shall be responsible for determining that each lot of material meets all requirements of this specification. With each part shipment, the subcontractor shall submit a copy of the report required in Paragraph 6.1.

NOTE: For the purpose of this specification, the term "subcontractor" applies to the company under contract directly to the Fort Worth Division to design and provide certain components or systems, to provide service, and/or to fabricate individual parts to Fort Worth Division specifications.