5.13 Address Requirements - Label and mark shipments in accordance with the following:

FROM: (Shipper) TO: GENERAL DYNAMICS
Fort Worth Division
(Address) Fort Worth, Texas

P.O.# B.L.# CASE # LOT # (Pieces)

5.13.1 Rail - Less Than Carload (LCL) and Carload (CL) freight must be consigned to Benbrook, Texas.

5.13.2 Air - Air Freight or Air Freight Forwarder will be marked "HOLD AT AIRPORT FOR PICK-UP BY CONSIGNEE" on both label and bill of lading.

5.13.3 Motor - All Motor Freight must be consigned to Fort Worth, Texas.

5.13.4 Indicate Purchase Order and Case Number on all bills of lading, airbills, and receipts. Air mail all original Commercial Bills of Lading, airbills, and receipts to the attention of the General Dynamics' Traffic Department, P.O. Box 748, Fort Worth, Texas 76101.

5.14 Notice of Shipment - The Seller shall give notice of shipment when and as instructed by the Buyer. This notice shall include date shipped, flight number or routing, carrier, waybill number, material shipped, pieces, weight, and estimated time of arrival. Notice shall be sent in such a manner as to insure receipt by the Buyer in advance of material receipt.