ELEMNTS	CHANGE	PAGE
120	Corrected a typo error by adding "less than symbol" omitted on E revision.	25
152	Corrected a typo error by adding "less than symbol" omitted on E revision.	28
155	Corrected a typo error by adding "greater than symbol" omitted on E revision.	28
165	Corrected a typo error by adding "greater symbol" omitted on E revision.	29
236	Corrected a typo error by adding the word "AT" in third line that was omitted on E revision.	37
273	Corrected a typo error by changing "3" to "B" in first line.	42
280	In next to last line, added "per MIL-C-83286" for clarification and in fourth line corrected "MIL-C-78766" to read "MIL-C-38736".	43
281	In next to last line, added "per MIL-C-83286" for clarification.	44
302	Corrected a typo error from E revision by changing "FPS-004" to FPS-0004".	48
342	Corrected a typo error from E revision by changing "16N000L" to "16N0001".	56
357	In last sentence, added primer reference on touch up prior to applying white top coat touch up, in accordance with shop practice and FPS-3001 requirements.	60
361	Corrected an E revision error by changing "PARA. 3.1.5." to "PARA. 3.1.1(A)" to correctly match FPS-3001.	60
366	Added word "WITH" in first line for better understanding.	61