



791 STRIKE DETAIL



Inside Face
of Door


Section Thru Cutouts Center
Reinforcement
for 791 Strike
(See Note 6)

791 Strike




NOTES:


1. Do not scale drawing.
2. Dimensions are in inches (mm).
3. LHR door shown. Preparation is typical for both door hands.
4. Minimum door stile width: 3-1/2 (89).
5. Prepare mounting holes when installing the device.
6. Unreinforced frames require blind rivet nuts (by others) to mount the strike.
7. This hole MUST be field located using physical part as template, after installation is complete and device is fully operational.
8. For recommended door reinforcements see template 7400-0000. Unreinforced doors require SNB option to mount the device components.
9. Holes for optional SNB: 9/32 (7.00) dia., inside door face; 3/8 (9.50) dia., outside door face.
10. Provide door stiffeners, as needed to prevent door collapse due to installation with power tools, door use, or abuse.
11. Device mount to hinge stile (not shown) requires hole location and preparation during device installation.
12. For outside trim preparation see appropriate trim template.
13. For electrical devices (suffixes "B", "G", "O", "P", "S") also see template 7477-0001.
14. Bottom bolt will retract to 1/8 (3.2) above floor strike. Floor coverings in the door path must be laid accordingly.



794 STRIKE DETAIL



Typical Top & Bottom Door Detail (Door Face Cutout Top Only, As Shown)



RESPONSIBILITY
DOOR AND FRAME MANUFACTURERS ARE
RESPONSIBLE FOR PROVIDING ADEQUATE
CONSTRUCTION OR REINFORCEMENTS FOR
PROPER INSTALLATION OF HARDWARE SHOWN.
ALL ARCHITECTURAL BUILDERS HARDWARE MUST
BE INSTALLED ON PROPERLY REINFORCED
DOORS AND FRAMES, REGARDLESS OF TYPE,
MATERIAL, OR METHOD OF CONSTRUCTION.

**7220M, 7225M & 7220MF Concealed Vertical Rod
Exit Devices for Narrow Escutcheon Trim,
Application for Metal Door and Frame With
Optional 794 Strike**

Contact us for support at 1-855-557-5078.

ASSA ABLOY

SUPERSEDES	4/01	DO NOT SCALE DRAWING
TEMPLATE NUMBER	7473-0022	DATE 01-24