















QUINNIE L






nr	L[mm]	B[mm]	T[mm]	Menge	Colli
1	920	770	19	1	1/2



U8



ø10x60

x...(2)

U7S



x...(2)

W4



x...(2)


G46



6x8

x...(4)

W10



1350mm

x...(1)



I







G46



6x8

x...(4)






II

W4






2x






III







IV




1




2






3








4












5




 $A = A$




QUINNIE P





0,5h






nr	L[mm]	B[mm]	T[mm]	Menge	Colli
1	920	770	19	1	1/2




U8



ø10x60

x...(2)

U7S



x...(2)

W4



x...(2)


G46



6x8

x...(4)

W10



1350mm

x...(1)



I







G46



6x8

x...(4)






II

W4






2x






III







IV




1




2





3



4



5

 $A = A$ 