


Instrukcja Obsługi

Szklarnia ogrodowa



































Liczba modułów: 6








































*Heavy Duty Machinery*



# PARTS LIST A










#		MM	#x	#		MM	#x
1		1214 mm	4x	17a		1310 mm	1x
2		1132 mm	1x	18			8x
3		1132 mm	1x	19		380 mm	1x
4		1132 mm	1x	20		1586 mm	2x
5		1132 mm	1x	21a		1235 mm	2x
6		1639 mm	1x	22		1302 mm	6x
7		1639 mm	1x	23		595 mm	2x
8		1665 mm	1x	24		616 mm	1x
9		1665 mm	1x	25		1292 mm	2x
10		1214 mm	10x	26		616 mm	2x
11		1115 mm	10x	27		616 mm	1x
12		618 mm	1x	28		M6x10	246x
13			4x	29		M6 mm	247x
14		1255 mm	1x	30		522 mm	8x
15		635 mm	4x	31		609 mm	1x
16a		1310 mm	1x	32		595 mm	4x

# PARTS LIST B






#		MM	#x	#		MM	#x
33		598 mm	4x	52		M6x30 mm	1x
34a		1350 mm	2x	53			6x
35a		1350 mm	2x	54			4x
36a		1357.5 mm	2x	55			2x
37		1640 mm	4x	56		1235 mm	2x
38a		1350 mm	2x	57		1235 mm	2x
39a		1357.5 mm	2x	58		1235 mm	2x
40a		960 mm	1x	59		1235 mm	2x
41		605 mm	5x	60			
42			8x	61		580 mm	1x
43			4x	62		580 mm	1x
44			1x	63		625 mm	2x
45			1x	64			3x
46			2x	65		1240 mm	2x
47		M4.5x19 mm	16x	66		1240 mm	2x
48		M4x7.5	24x	67		1080 mm	2x
49			250x	68		960 mm	2x
50			1x				
51			4x				




①




2



3




④-1





7


④-2




8







11



12

### Podstawa:

8

CLIP (#49)

Numer	Miara	Menge
1	605x1210	17PCS
2	605x1130	8PCS
3	605x450	2PCS
4	605x590	4PCS
5	605x549	4PCS
6	605x662	1PCS
7	610x234	1PCS
8	015x232	1PCS
9	010x602	2PCS
10	605x460	2PCS

- 1 ————— 4PCS
- 2 ————— 4PCS
- 3 ————— 2PCS
- 4 ————— 4PCS
- 5 ————— 6PCS
- 6 ————— 18PCS
- 7 ————— 40PCS
- 8 ————— 40PCS
- 9 ————— 12PCS

