

# **XPA12-75**












"STATUS" DARIA PINTAK

Address: ul. Georga Philippa Telemanna 5, 68-200 Żary

NIP: 9282107735 REGON: 525760316 VAT: PL9282107735

E-mail: disposers.com.pl@gmail.com Telefon kontaktowy: +48 786 153 207



## **INTENDED USE**

This polisher is designed for commercial use in industry and trade, for all types of polishing work with polishing sponges, lambskins and woolskins, felt plate, buffing di .

# **GENERAL SAFETY RULES**

#### **WORK AREA**

- **Keep work area clean and well lit.** *Cluttered and dark areas invite accidents.*
- Do not operate power tools in explosive atmospheres, such as in the presence of flammable liquids, gases or dust. Power tools create sparks which may ignite the dust or fumes.
- Keep children and bystanders away while operating a power tool. Distractions can cause you to lose control.

#### **ELECTRICAL SAFETY**

- Power tool plugs must match the outlet. Never modify the plug in any way. Do not use any adapter plugs with earthed (grounded) power tools. Unmodified plugs and matching outlets will reduce risk of electric shock.
- Avoid body contact with earthed or grounded surfaces such as pipes, radiators, ranges and refrigerators. There is an increased risk of electric shock if your body is earthed or grounded.
- Do not expose power tools to rain or wet conditions. Water entering a power tool will increase the risk of electric shock.
- Do not abuse the cord. Never use the cord for carrying, pulling or unplugging the power tool. Keep cord away from heat, oil, sharp edges or moving parts. Damaged or entangled cords increase the risk of electric shock.
- When operating a power tool outdoors, use an extension cord suitable for outdoor use. Use of a cord suitable for outdoor use reduces the risk of electric shock.
- Connect the electric power tool to electricity, using a 16 A maximum secure contact protected outlet (220-240V~, 50 Hz). We recommend you to attach a residual current circuit-breaker (RCD) that does not exceed 30mA.

#### **PERSONAL SAFETY**

- Stay alert, watch what you are doing and use common sense when operating a power tool. Do not use a power tool while you are tired or under the influence of drugs, alcohol or medication. A moment of inattention while operating power tools may result in serious personal injury.
- **Use safety equipment. Always wear eye protection.** Safety equipment such as dust mask, non-skid safety shoes, hard hat, or hearing protection used for appropriate conditions will reduce personal injuries.

3

## **DANE TECHNICZNE**

Model XPA12-75 Napiecie zasilania 220-240 B~ 50 Hz Moc 750 W Częstotliwość obrotów bez obciążenia 2000-5500 obr./min. Średnica podstawy 50 и 75 mm Masa 2,3 kg Okres gwarancji 5 lat 77.6 db(A), blad 3 dB(A) 88.6 Poziom ciśnienia akustycznego LpA dB(A), błąd 3 dB(A) 5.99 m/s<sup>2</sup> Poziom mocy akustycznej LwA Wartość drgań ahb/ahm ahb/ahm Klasa ochrony

## Wyposażenie:

Polerski krążek 75 mm, polerski krążek 125 mm, dodatkowa rękojeść (2), zestaw narzędzi do polerowania, klucz.

Producent zastrzega sobie prawo do zmiany parametrów technicznych produktu i jego wyposażenia bez uprzedniego powiadomienia.

# **DEKLARACJE ZGODNOŚCI**

STATUS ITALIA S.R.L. oświadcza, że produkt marki STATUS polerka **XPA12-75** został wyprodukowany zgodnie z następującymi dyrektywami UE: **2006/42/EC, 2014/30/EU**.

Odpowiada również następującym normom: EN 60745-1:2009+A11:2010, EN 60745-2-3:2011+A2:2013+A11:2014+A12:2014+A13:2015, EN 55014-1:2017, EN 55014-2:2015, EN IEC 61000-3-2:2019, EN 61000-3-3:2013+A1:2019, AfPS GS 2019:01 PAK. Dokumentacja techniczna znajduje się u producenta: STATUS ITALIA S.R.L., via Aldo Moro, 14/A, 36060 - Pianezze (VI), WŁOCHY.

Karon Giacinto Dyrektor STATUS Italia S.r.l.

## **GENERAL SAFETY RULES**

- UWAGA: Należy używać wyłącznie osprzętu roboczego ze sprawnym systemem chwytania. Po wymianie tarczy należy wyłączyć maszynę na co najmniej 30 sekund.
- UWAGA: Wibrujące lub nierównomiernie obracające się tarcze należy natychmiast wymienić.

# **OBSŁUGA**

#### **OGÓLNA INSPEKCJA**

Regularnie sprawdzaj wszystkie elementy mocowania i upewnij się, że są one dobrze dokręcone. W przypadku luźnego śruby, natychmiast go dokręć, aby uniknąć sytuacji związanych z ryzykiem. W przypadku uszkodzenia przewodu zasilającego, jego wymiana powinna być przeprowadzona przez producenta lub jego specjalistę serwisowego, aby uniknąć zagrożeń związanych z wymianą.

#### **CZYSZCZENIE**

Regularnie sprawdzaj, czy do otworów wentylacyjnych silnika elektrycznego nie dostały się kurz i obce ciała. Po każdym użyciu czyść urządzenie z kurzu, wiórów i trocin. Użyj miękkiej szczotki lub strumienia sprężonego powietrza, aby usunąć nagromadzony kurz. Do czyszczenia używaj wilgotnej szmatki z niewielką ilością mydła.

#### **UWAGA!**

Nie używaj detergentów ani rozpuszczalników do czyszczenia - mogą one spowodować uszkodzenie plastikowych elementów urządzenia. Upewnij się, że woda nie dostanie się do wnętrza urządzenia.

#### WYMIANA CZŚ CI ZAMIENNYCH

Używanie części zamiennych innych producentów podczas naprawy może spowodować uszkodzenie urządzenia i poważne obrażenia. Tylko oryginalne części zamiennych, zamontowane w autoryzowanym serwisie, gwarantują niezawodną i bezpieczną pracę urządzenia.

15

- Avoid accidental starting. Ensure the switch is in the off position before plugging in.
   Carrying power tools with your finger on the switch or plugging in power tools that have the switch on invites accidents.
- Remove any adjusting key or wrench before turning the power tool on. A wrench or a key left attached to a rotating part of the power tool may result in personal injury.
- **Do not overreach. Keep proper footing and balance at all times.** This enables better control of the power tool in unexpected situations.
- Dress properly. Do not wear loose clothing or jewellery. Keep your hair, clothing and gloves away from moving parts. Loose clothes, jewellery or long hair can be caught in moving parts.
- If devices are provided for the connection of dust extraction and collection facilities, ensure these are connected and properly used. Use of these devices can reduce dust related hazards.

#### **POWER TOOL USE AND CARE**

- Do not force the power tool. Use the correct power tool for your application. The correct power tool will do the job better and safer at the rate for which it was designed.
- Do not use the power tool if the switch does not turn it on and off. Any power tool that cannot be controlled with the switch is dangerous and must be repaired.
- Disconnect the plug from the power source before making any adjustments, changing accessories, or storing power tools. Such preventive safety measures reduce the risk of starting the power tool accidentally.
- Store idle power tools out of the reach of children and do not allow persons unfamiliar with the power tool or these instructions to operate the power tool. Power tools are dangerous in the hands of untrained users.
- Maintain power tools. Check for misalignment or binding of moving parts, breakage of parts and any other condition that may affect the power tools operation. If damaged, have the power tool repaired before use. Many accidents are caused by poorly maintained power tools.
- **Keep cutting tools sharp and clean.** Properly maintained cutting tools with sharp cutting edges are less likely to bind and are easier to control.
- Use the power tool, accessories and tool bits etc. in accordance with these
  instructions, taking into account the working conditions and the work to be
  performed. Use of the power tool for op-erations different from those intended could
  result in a hazardous situation.

#### **SERVICE**

 Have your power tool serviced by a qualified repair person using only identical replacement parts. This will ensure that the safety of the power tool is maintained.

# **POLISHER SAFETY WARNINGS**

- This power tool is intended to function as a polisher or machine for cleaning surfaces
  with a wire brush. Read all safety warnings, instructions, illustrations and specifications
  provided with this power tool. Failure to follow all instructions listed below may result
  in electric shock, fi e and/or serious injury.
- Operations such as grinding or cutting-off a e not recommended to be performed with this power tool. This power tool is not recommended for polishing. Operations for which the power tool was not designed may create a hazard and cause personal injury.
- Do not use accessories which are not specifcally designed and recommended by the tool manufacturer. Just because the accessory can be attached to your power tool, it does not assure safe operation.
- Never mount circular blades or grinding wheels for angle grinders.
- Use only accessories appropriate for the processed material and the rotation speed.
- The rated speed of the accessory must be at least equal to the maximum speed marked on the power tool. Accessories running faster than their rated speed can break and fly apart.
- The outside diameter and the thickness of your accessory must be within the capacity rating of your power tool. Incorrectly sized accessories cannot be adequately guarded or controlled.
- The arbour size of flange, backing pads or any other accessory must properly fit the spindle of the power tool. Accessories with arbour holes that do not match the mounting hardware of the power tool will run out of balance, vibrate excessively and may cause loss of control.
- Do not use a damaged accessory. Before each use inspect the accessory such as backing pad for cracks, tear or excess wear, wire brush for loose or cracked wires. If power tool or accessory is dropped, inspect for damage or install an undamaged accessory. After inspecting and installing an accessory, position yourself and bystanders away from the plane of the rotating accessory and run the power tool at maximum no load speed for one minute. Damaged accessories will normally break apart during this test time.
- Wear personal protective equipment. Depending on application, use face shield, safety
  goggles or safety glasses. As appropriate, wear dust mask, hearing protectors, gloves
  and workshop apron capable of stopping small abrasive or workpiece fragments.
  The eye protection must be capable of stopping flying deb is generated by various
  operations. The dust mask or respirator must be capable of filt ating particles
  generated by your operation. Prolonged exposure to high intensity noise may cause
  hearing loss.
- Keep bystanders a safe distance away from work area. Anyone entering the work area must wear personal protective equipment. Fragments of workpiece or of a broken accessory may fly way and cause injury beyond immediate area of operation.

5

# **OPIS**

- 1. Przełącznik
- 2. Regulator prędkości obrotowej
- 3. Zamknięta dodatkowa rączka
- 4. Prosty uchwyt pomocniczy
- 5. Elastyczny krążek polerski
- 6. Osprzęt polerski z mocowaniem na rzep (miękka dysk pośrednia, arkusz ścierny, gąbka, dysk filcowy, pokrywa z wełny owczej)

# **INSTRUKCJE ROBOCZE**

## Włączanie/Wyłączanie

- Włączanie: Naciśnij tylną część przełącznika 1 i przesuń go do przodu, aż się zatrzyma.
- Wyłączanie: Naciśnij tylną część przełącznika 1 i pozwól mu powrócić do pozycji wyjściowej.

# Ustawianie prędkości obrotowej

• Prędkość obrotowa jest regulowana za pomocą regulatora 2 do odpowiedniej pozycji.

# Montaż dodatkowej rękojeści

- Zamknięta rękojeść 3 jest montowana na obudowie przekładni za pomocą dwóch śrub i sześciokąta.
- Dodatkowa rękojeść 4 może być zamontowana po lewej lub prawej stronie obudowy przekładni. Montuje się go poprzez wkręcenie w otwory w obudowie przekładni.

# Tarcza polerska

- Tarcza polerska 5 jest nakręcana na wrzeciono polerki. Osprzęt jest bezpośrednio mocowany do tarczy polerskiej za pomocą rzepów (VECRO).
- Do montażu/demontażu tarczy polerskiej może być konieczne zablokowanie wrzeciona za pomocą klucza lub przycisku blokady wrzeciona.

# Mocowanie narzędzia roboczego na talerzu polerskim

 Dysza montowana na tarczy musi mieć średnicę Ømin148. Musi ona ściśle przylegać do tarczy, a osie dyszy i tarczy muszą być wyrównane podczas montażu.
 Nieprawidłowo zamontowane dysze powodują szarpanie i wibracje.

# ZASADY BEZPIECZEŃSTWA DLA MASZYNY POLERSKIEJ

- Średnica otworu montażowego tarcz szlifierskich, tarcz szlifierskich, talerzowych tarcz szlifierskich i innych urządzeń pomocniczych musi zapewniać mocne, szczelne mocowanie na wrzecionie ręcznej maszyny. Narzędzie robocze i urządzenia z otworami montażowymi zamontowane na wrzecionie maszyny z luzem będą niezrównoważone, powodować zwiększone drgania i prowadzić do utraty kontroli nad maszyną podczas pracy.
- Nie używaj uszkodzonego narzędzia roboczego. Przed każdym użyciem sprawdź narzędzie robocze, takie jak tarcze szlifierskie, pod kątem obtłuczeń i pęknięć; tarcze szlifierskie pod kątem pęknięć, rozerwań lub nadmiernego zużycia; szczotki druciane pod kątem luźnych lub złamanych drutów. Po upadku ręcznej maszyny lub narzędzia roboczego dokonaj inspekcji w celu wykrycia uszkodzeń. Po inspekcji i zamontowaniu narzędzia roboczego operator oraz wszyscy obecni w pobliżu powinni zająć pozycję poza płaszczyzną obrotu narzędzia roboczego, a następnie włączyć ręczną maszynę do pracy na maksymalnej prędkości obrotowej bez obciążenia przez 1 minutę. W większości przypadków w trakcie kontroli dochodzi do rozerwania uszkodzonego narzędzia roboczego.
- Używaj środków ochrony indywidualnej. W zależności od wykonywanej pracy używaj osłony twarzy, zasłon ochronnych na oczy. W razie potrzeby korzystaj z maski przeciwpyłowej, ochrony słuchu, rękawic i fartucha ochronnego zdolnego utrzymać drobne cząstki ścierne i cząstki materiału obrabianego. Środki ochrony wzroku powinny być zdolne do zatrzymywania rozpryskujących się cząstek powstających podczas różnych prac. Maska przeciwpyłowa lub respirator powinny odfiltrowywać cząstki powstające podczas prac.
- Nie dopuszczaj osób trzecich bezpośrednio w pobliże strefy roboczej. Wszystkie osoby wchodzące w strefę roboczą powinny nosić środki ochrony indywidualnej. Fragmenty obrabianego przedmiotu lub uszkodzonego narzędzia roboczego mogą rozpryskiwać się i powodować uszkodzenia ciała w bezpośrednim sąsiedztwie miejsca wykonywania pracy.
- Należy regularnie czyścić otwory wentylacyjne elektronarzędzia. Wentylator silnika zasysa kurz do obudowy, a nadmierna ilość metalowego pyłu może spowodować ryzyko porażenia prądem elektrycznym.
- Nie pracuj ręczną maszyną w pobliżu łatwopalnych materiałów. Te materiały mogą zapalić się od iskier powstających podczas pracy.
- Nie używaj narzędzi roboczych, które wymagają stosowania chłodziw. Użycie wody lub innych chłodziw może prowadzić do porażenia prądem elektrycznym.
- Podczas pracy w zapylonym środowisku otwory wentylacyjne urządzenia muszą być utrzymywane w czystości. Elektronarzędzie przegrzeje się, jeśli chłodzenie będzie utrudnione z powodu zatkania otworów wentylacyjnych przez pył.

# POLISHER SAFETY WARNINGS TOOL PARTS OVERVIEW

- Use clamps or a vice to secure your work whenever possible.
- Do not apply side pressure to stop the pad rotation after switching the machine off.
- Guide the machine towards the processed material only if the machine is switched on.
- Position the cord clear of the spinning accessory. If you lose control, the cord may be cut or snagged and your hand or arm may be pulled into the spinning accessory.
- Never lay the power tool down until the accessory has come to a complete stop. The spinning accessory may grab the surface and pull the power tool out of your control.
- Do not run the power tool while carrying it at your side. Accidental contact with the spinning accessory could snag your clothing, pulling the accessory into your body.
- Regularly clean the power tool's air vents. The motor's fan will draw the dust inside the
  housing and excessive accumulation of powdered metal may cause electrical hazards.
- Do not operate the power tool near flammable m terials. Sparks could ignite these materials.
- Do not use accessories that require liquid coolants. Using water or other liquid coolants may result in electrocution or shock.
- This power tool is designed for dry sanding only.
- The tool must be used only for its prescribed purpose. Any use other use than those mentioned in this Instruction will be considered a case of misuse. The user and not the manufacturer shall be liable for any damage or injury resulting from such cases of misuse.
- The manufacturer shall not be liable for any changes made to the tool nor for any damage resulting from such changes.
- When operating in dusty environment, the ventilation slots must be kept clean. If it should become necessary to clear dust, first dis onnect the tool from the mains supply (use non metallic objects to clean the dust) and avoid damaging internal parts. The power tool will overheat under deteriorated cooling due to the clogged with dust ventilation slots.

# **TOOL PARTS OVERVIEW**

- On/off swi ch
- 2. Electronic speed preselection wheel
- 3. D-shape auxiliary handle
- 4. Auxiliary handle
- 5. Hook-and-loop fl xible backing pad
- 6. Hook-and-loop operating tool (soft intermediate disc, abrasive sheet, sponge, felt wheel, lambswool polishing bonnet)

# **OPERATION**

#### **SWITCHING ON - SWITCHING OFF**

- Switching on: Push the back end of the ON/OFF switch 1 down and then forward in the direction of the arrow until its front end will sag, thus fixing itsel .
- Switching off: Press the back, lifted end of switch 1 and release it to return in its initial position.

## Preselecting the speed

• To set the operating speed, move the dial 2 to the required value.

#### MOUNTING THE AUXILIARY HANDLE

- The auxiliary handle 3 is fastened to the gear box by two bolts under the bolt heads. Screwing and unscrewing the bolts is performed by an open end spanner.
- The auxiliary handle 4 can be mounted alternatively to the right or left side of the gear box. It is screwed directly to the machine gear box.

#### **BACKING PAD**

- The backing pad 5 can be screwed directly onto the spindle. The hook-and-loop operating tools 6 (sandpaper, polishing sponge, felt wheel, lambswool bonnet, etc.) can be fi ed directly onto the backing pad.
- To dismount (unscrew) the backing pad use a spanner when necessary.

### FIXING THE OPERATING TOOL TO THE HOOK-AND-LOOP (VELCRO) BACKING PAD

- The operating tool fastened to the backing pad shall be Ømin148. The operating tool shall be aligned with the backing pad and care shall be taken to ensure their coaxiality. Eccentrically mounted operating tools cause wobbling and vibrations.
- WARNING: Use only pads with un-damaged hook-and-loop system. Perform a trial test for at least 30 sec at no load after replacing the backing pad.
- WARNING: Vibrating or otherwise improperly rotating backing pads must be re-placed immediately!

# **MAINTENANCE**

#### **GENERAL INSPECTION**

Regularly inspect all fasteners and ensure they are properly tightened. Should any of the screws be loose, retighten it immediately to avoid hazards.

If the replacement of the supply cord is necessary, this has to be done by the manufacturer or his agent in order to avoid a safety hazard.

7

- Przed rozpoczęciem pracy należy dokładnie sprawdzić stan produktu: łatwość poruszania ruchomymi częściami, brak uszkodzeń części obudowy i wyposażenia. Wszelkie uszkodzone części produktu lub wyposażenia należy wymienić przed rozpoczeciem pracy.
- Sprzęt tnący należy utrzymywać w czystości, dobrze naostrzony i nasmarowany. Narzędzi i wyposażenia dodatkowego należy używać wyłącznie do prac określonych w instrukcji obsługi tego produktu. Używanie produktu niezgodnie z jego przeznaczeniem może spowodować uszkodzenia i obrażenia ciała.

#### **OBSŁUGA SERWISOWA**

Maszyna wymagająca naprawy musi zostać naprawiona przez wykwalifikowany
personel, który używa oryginalnych części zamiennych do wymiany. zamiennych
niecertyfikowanych przez producenta tego produktu może spowodować jego awarię i
naruszenie norm bezpieczeństwa elektrycznego produktu.

# ZASADY BEZPIECZEŃSTWA DLA MASZYNY POLERSKIEJ

- Ta ręczna maszyna przeznaczona jest do użytku jako maszyna polerska. Zapoznaj się ze wszystkimi ostrzeżeniami dotyczącymi bezpieczeństwa, instrukcjami, ilustracjami i parametrami technicznymi dostarczonymi wraz z tą ręczną maszyną. Nieprzestrzeganie wszystkich poniższych wskazówek może prowadzić do porażenia prądem elektrycznym, pożaru i/lub poważnego uszkodzenia ciała.
- Nie wykonuj prac przy użyciu tej ręcznej maszyny, takich jak szlifowanie, struganie lub cięcie. Wykonywanie prac, dla których ręczna maszyna nie jest przeznaczona, może stanowić zagrożenie i prowadzić do uszkodzeń ciała.
- Nie używaj narzędzia roboczego i innych urządzeń pomocniczych, które nie są specjalnie przeznaczone dla tej maszyny i nie są zalecane przez producenta maszyny.
   Samo możliwe ich zamocowanie do tej ręcznej maszyny nie gwarantuje jej bezpiecznej pracy.
- Nominalna częstotliwość narzędzia roboczego, podana na nim, musi być nie mniejsza niż maksymalna prędkość obrotowa podana na maszynie. Praca narzędziem obrotowym z prędkością większą niż jego nominalna prędkość obrotowa może prowadzić do jego rozerwania się i rozrzucenia odłamków.
- Zewnętrzna średnica i grubość narzędzia roboczego muszą odpowiadać możliwościom funkcjonalnym maszyny. Nieproporcjonalne narzędzia robocze nie mogą być odpowiednio osłonięte i podczas pracy mogą prowadzić do utraty kontroli nad maszyną.

# PODSTAWOWE WYMAGANIA BEZPIECZEŃSTWA

# BEZPIECZEŃSTWO OSOBISTE

- Nie pracuj z maszyną na pełne zmęczenie ani pod wpływem narkotyków, alkoholu lub leków. Chwila nieuwagi podczas pracy z maszyną może prowadzić do poważnych obrażeń.
- Używaj indywidualnego sprzętu ochronnego (okulary ochronne, maska przeciwpyłowa, solidny kask, nauszniki przeciwhałasowe, buty antypoślizgowe).
   Stosowanie sprzętu ochronnego sprawi, że praca będzie wygodniejsza i bezpieczniejsza.
- Przed podłączeniem do sieci upewnij się, że przełącznik znajduje się w pozycji
   "wyłączony". Pomoże to zapobiec przypadkowemu włączeniu produktu.
- Nie włączaj maszyny, nie usuwając klucza regulacyjnego lub klucza uchwytu maszyny itp. Jeśli narzędzie dostanie się do ruchomych części produktu po jego włączeniu, może spowodować obrażenia ciała i uszkodzenie produktu.
- **Podczas pracy należy przyjmować stabilną pozycję.** *Należy zawsze stać na stabilnym podłożu. Utrata równowagi podczas pracy może spowodować poważne obrażenia.*
- Nie nosić niepotrzebnie luźnej odzieży do pracy. Przed rozpoczęciem pracy należy zdjąć biżuterię. Jeśli masz długie włosy, ukryj je pod czapką. Jeśli krawędzie odzieży, biżuterii lub włosów zostaną przytrzaśnięte przez ruchome części produktu, może dojść do obrażeń.
- Jeśli produkt jest wyposażony w złącze odkurzacza, przed użyciem należy
  podłączyć odkurzacz. Skuteczne usuwanie kurzu z obszaru roboczego sprawi, że praca
  będzie bardziej komfortowa i ochroni zdrowie.

#### EZPIECZNE UŻYTKOWANIE I PRZECHOWYWANIE PRODUKTU

- Nie przeciążać produktu. Do każdego rodzaju pracy należy używać wyłącznie przeznaczonych do tego narzędzi lub sprzętu.
- **Nie należy używać produktu z uszkodzonym przełącznikiem.** Jeśli przełącznik nie działa wyraźnie, a produkt jest trudny do włączenia/wyłączenia, należy go natychmiast wymienić.
- Przed przystąpieniem do regulacji produktu lub wymiany akcesoriów należy zawsze odłączyć urządzenie od zasilania. Pomoże to zapobiec przypadkowemu włączeniu produktu podczas prac konserwacyjnych.
- Produkt należy przechowywać w miejscu niedostępnym dla dzieci i osób niezaznajomionych z produktem. Każda osoba, która nie korzystała wcześniej z tego typu narzędzia, musi uważnie i w całości przeczytać niniejszą instrukcję przed rozpoczęciem pracy.

# MAINTENANCE TECHNICAL SPECIFICATIONS

#### **CLEANING**

For safe operation always keep the machine and its ventilation slots clean.

Regularly check to see if any dust or foreign matter has entered the ventilation slots and the grills around the switches. Use a soft brush and/or air jet to remove any accumulated dust. Wear safety glasses to protect your eyes whilst cleaning.

Exterior plastic parts may be cleaned with a damp cloth and mild detergent if necessary.

#### WARNING!

Never use alcohol, petrol or other cleaning agent. Never use caustic agents to clean plastic parts. Water must never come into contact with the tool.

#### REPLACEMENT PARTS

To assure product safety and reliability, repairs, maintenance and adjustment (including brush inspection and replacement) should be performed by authorised service centres always using genuine replacement parts.

# **TECHNICAL SPECIFICATIONS**

Model	XPA12-75
Voltage	220-240 V~ 50 Hz
Input power	750 W
No load speed	2000-5500/min.
Backing pad Ø	50 and 75 mm
Weight	2,3 kg
A-weighted sound pressure level LpA	77.6 db(A), uncertainty 3 dB(A)
A-weighted sound power level LwA	88.6 dB(A), uncertainty 3 dB(A)
Vibration emission value ahb/ahm	5.99 m/s <sup>2,</sup> uncertainty 1,5 m/s <sup>2</sup>
Protection class	II

#### Includes:

Backing pad 75 mm, Backing pad 50 mm, auxilliary handle (2), spongle set.

The manufacturer reserves the right to make changes and improvements to the products and to alter specifications without prior notice.

# PRZEZNACZENIE PRODUKTU. GŁÓWNE WYMAGANIA DOTYCZĄCE BEZPIECZEŃSTWA

# **CE DECLARATION OF CONFORMITY**

We STATUS ITALIA S.R.L. as the responsible manufacturer declare that the following STATUS machine(s): Polisher Model No./ Type: XPA12-75.

are of series production and conforms to the following European Directives: **2006/42/EC, 2014/30/EU**.

And are manufactured in accordance with the following standards or standardised documents: EN 60745-1:2009+A11:2010, EN 60745-2-3:2011+A2:2013+A11:2014+A12:2014+A13:2015, EN 55014-1:2017, EN 55014-2:2015, EN IEC 61000-3-2:2019, EN 61000-3-3:2013+A1:2019, AfPS GS 2019:01 PAK.

9

The technical documentation kept by the manufacturer: STATUS ITALIA S.R.L., via Aldo Moro, 14/A, 36060 - Pianezze (VI), ITALY

Caron Giacinto Director

## PRZEZNACZENIE PRODUKTU

Ta maszyna polerska przeznaczona jest do wykonywania prac polerskich wszelkiego rodzaju z użyciem miękkich gąbek polerskich, skór owczych i wełnianych, filcowych i tkaninowych kół polerskich.

# **GŁÓWNE WYMAGANIA DOTYCZĄCE BEZPIECZEŃSTWA**

#### PRZESTRZEŃ ROBOCZA

- Zachowaj porządek i odpowiednie oświetlenie w miejscu pracy.
- Przestrzeń robocza musi być dobrze oświetlona, aby uniknąć wypaфdków.
- Nie pracuj elektryczną maszynką w środowisku wybuchowym, gdzie są łatwopalne ciecze. Silnik elektryczny produktu iskrzy podczas pracy i może spowodować pożar.
- Nie dopuszczaj do obecności dzieci i osób trzecich podczas pracy z maszyną.

#### BEZPIECZEŃSTWO ELEKTRYCZNE

- Elektryczne maszyny ręczne powinny być wyposażone w wtyczkę. Niedozwolone jest używanie nie standardowego wtyku ani innych metod podłączania do źródła zasilania.
- Unikaj kontaktu ciała z uziemieniem i uziemionymi powierzchniami, takimi jak rury, kaloryfery, baterie itp. Kontakt z uziemionymi przedmiotami znacznie zwiększa ryzyko porażenia prądem.
- Zakazane jest używanie maszyny w warunkach niechronionych przed deszczem, w wilgotnych i mokrych pomieszczeniach. Wilgoć dostająca się do maszyny zwiększa ryzyko porażenia prądem elektrycznym.
- Nie traktuj zaniedbane zasilającego przewodu (sznura); nie używaj go do
  przenoszenia maszyny ani do odłączania jej od zasilania. Chronić przewód zasilający
  przed ciepłem, olejami, ostrymi krawędziami (przedmiotami), ruchomymi częściami
  maszyny. Uszkodzony przewód może spowodować porażenie prądem.
- Podczas korzystania z produktu na zewnątrz należy używać przedłużacza przeznaczonego specjalnie do użytku na zewnątrz. Użycie specjalnego przedłużacza znacznie zmniejsza ryzyko porażenia prądem.
- - Parametry sieci zasilającej do podłączenia produktu muszą być zgodne z parametrami określonymi na tabliczce znamionowej produktu. (220-240 V, 50 Hz)

10