



$$\frac{1}{8}$$




1

	ø8x30mm 		L-450 	ø5.0x13mm 	ø15/12mm 		ø3.0x16mm 	ø3.5x16mm 
8	16	12	2SET	4	5	2	2	3



2

ø8x30mm 	ø15/12mm 
8	8



3

Ø8x30mm




A

4



D1

5



PUSH
TO
OPEN

PR3




2SET

Ø5.0x13mm



P9

4





4



E



4



5



4



6

$\varnothing 6,4 \times 60 \text{ mm}$
 B1




6

$\varnothing 9,0 \text{ mm}$
 E1




6



4mm



O




E1

7



Z1

1




8

$\varnothing 6,4 \times 60 \text{ mm}$	$\varnothing 9,0 \text{ mm}$
	
B1	E1
6	6

4mm

O







	
B1	E1

9

$\varnothing 3,0 \times 16 \text{ mm}$


P1
20

L
12






10




$\varnothing 4,0 \times 25 \text{ mm}$	
	F4
P12	F4
5	5








11



12




13




14

$\varnothing 8 \times 30 \text{ mm}$  A	$\varnothing 15 / 12 \text{ mm}$  C	 D1
8	4	4


2x




15





2x




16




4




2x




17



10



2x








18








ø3.0x20mm

P7


4



19



PUSH TO OPEN



WALL DRILL

Ø3.5x16mm

P4

N

