












1,5h









G56 4x16 x...(48)	G57 3,5x16 x...(4)			
F15 x...(8)	P25 x...(2)	A1 ø7x50 x...(8)		
G50 6x13 x...(4)	F12 x...(4)	I1 x...(8)	M8 350mm x...(1)	
W1 x...(1)	A6 ø7x40 x...(4)	H4 350mm x...(2)	W2 x...(1)	
K1 ø15x12 x...(12)	P4 x...(8)	C3 Z35PR x...(4)	D3 H=2 PZ35PR x...(4)	G34 3,5x16 x...(22)
K10 x...(12)	B1 ø8x35 x...(20)	I7 x...(12)	L13 x...(2)	N1 M4x9 x...(2)














I








II






IV







V




VI




1.




2.







VII




1.





2.




P25










VIII









IX




 $a=b$ 





XI





XII




XIII









XIV








XV





XVI






G34



3,5x16

x...(4)


G3



4x30

x...(16)

P19



x...(1)

P44



x...(4)

I

