




Typ	A mm	B mm	H mm	H1 mm	W mm	D mm	D1 mm
A	30	35	19	12	14	5	4,2
B	35	40	26	17	18	6	4,2
C	40	50	33	22	20	8	5,2