































PL Instrukcja montażu
EN Assembly instruction

WN100




Promis Sp. z o.o.

ul. Sobieskiego 14 • 40-082 Katowice • tel. 032 206 84 11 • fax 032 253 98 12


www.promis.pl • promis@promis.pl

1  1PCS	2  1PCS	3  1PCS	4  1PCS	5  1PCS									
6  1PCS	7  1PCS	8  2PCS	9  1PCS	10  1PCS									
11  1PCS	12  1PCS	13  1PCS	14  1PCS	15  1PCS									
16  1PCS	17  1PCS	18  1PCS	19  2PCS	20  1PCS	21  1PCS	22  1PCS							
23  2PCS	24  1PCS	25  1PCS	26  1PCS	27  1PCS	28  1PCS								
29  1PCS	30  1PCS	31  2PCS	32  1PCS	33  1PCS	34  1PCS	35  2PCS	36  1PCS	37  1PCS					
38  1PCS	39  4PCS	40  1PCS	41  1PCS	42  4PCS	43  4PCS	44  4PCS	45  4PCS	46  2PCS	47  2PCS	48  6PCS	49  6PCS	50  12PCS	51  3PCS


Ax32	Bx9	Cx21	Dx4	Ex3	Fx1	Gx1	Hx1	Ix1	Jx4	Kx2	Lx1
											




4




5




6




7




8




9




10




11




12




13




14




15



16



17



18

