


KOC GAŚNICZY

EN 1869:2019

Wykonany w 100% z włókna szklanego
1,2 m x 1,8 m

**UWAGA! PO UŻYCIU NALEŻY WYRZUCIĆ KOC.
PRODUKT JEDNORAZOWEGO UŻYTKU.
PO UŻYCIU WYMIENIĆ NA NOWY.**



Chwyć taśmy dłońmi, pociągnij je do siebie i w dół wyjmując koc z pojemnika.




Trzymając za taśmy, całkowicie przykryj płomienie kocem odcinając dopływ tlenu. Wyłącz dopływ energii. Pozostaw koc na gaszonej powierzchni aż do ostygnięcia.



POŻAR ODZIEŻY
Jeśli wystąpił pożar odzieży, zmusь poszkodowanego do położenia się na ziemi. Owiń go kocem gaśniczym, by stłumić ogień. Zadzwoń po pomoc medyczną.

POCIĄGNIJ TAŚMY ABY WYJĄĆ




Wyprodukowano w CHRL dla Grupa Topex Sp. z o.o. Sp. k.

FIRE BLANKET

EN 1869:2019

Made of 100% glass fibre
1,2 m x 1,8 m

**ATTENTION! THROW AWAY THE BLANKET
AFTER USE. DISPOSABLE PRODUCT.
REPLACE WITH A NEW ONE AFTER USE.**



Grasp the straps with your hands, pulling them towards you and down removing the blanket from the container.




Holding the straps, completely cover the flames with a blanket cutting off the oxygen supply. Turn off the energy supply. Leave the blanket on the extinguished area until it has cooled down.



CLOTHING FIRE If a clothing fire has occurred, force the casualty to the ground. Wrap him or her with a fire blanket to smother the fire. Call for medical assistance

PULL THE STRAPS TO REMOVE



Manufactured in the PRC for Grupa Topex Sp. z o.o. Sp. k.